



地平线
Horizon Robotics

Sunrise 3.0E (X3E)

Errata

Rev. 1.0

April 2021

© 2020 Horizon Robotics. All rights reserved.

Important Notice and Disclaimer

Information in this document is provided solely to enable system and software implementers to use Horizon products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document.

The information in this document is subject to change without notice. Every effort has been made in the preparation of this document to ensure accuracy of the contents, but all statements, information, and recommendations in this document do not constitute a warranty of any kind, express or implied.

All statements, information and recommendations in this document are provided "AS IS". Horizon makes no warranty, representation or guarantee of any kind, express or implied, regarding the merchantability, fitness or suitability of its products for any particular purpose, and non-infringement of any third party intellectual property rights, nor does Horizon assume any liability arising out of the application or use of any product, and specifically disclaims any and all liability, including without limitation consequential or incidental damages.

"Typical" parameters that may be provided in Horizon datasheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals", must be validated for each customer application by customer's technical experts. Buyers and others who are developing systems that incorporate Horizon products (collectively, "Users") understand and agree that Users shall remain responsible for using independent analysis, evaluation and judgment in designing their applications and that Users have full and exclusive responsibility to assure the safety of Users' applications and compliance of their applications (and of all Horizon products used in or for Users' applications) with all applicable regulations, laws and other applicable requirements.

User agrees to fully indemnify Horizon and its representatives against any claims, damages, costs, losses and/or liabilities arising out of User's unauthorized application of Horizon products and non-compliance with any terms of this notice.

© 2020 Horizon Robotics. All rights reserved.

Horizon Robotics, Inc.

<https://www.horizon.ai>

Revision History

This section tracks the significant documentation changes that occur from release-to-release. The following table lists the technical content changes for each revision.

Revision	Date	Description
1.0	April 2021	Initial release

Contents

Important Notice and Disclaimer	i
Revision History	ii
Contents.....	iii
Tables	iv
1 Introduction.....	5
1.1 Scope	5
1.2 Errata Summary.....	5
2 Errata.....	6
2.1 ERR0001	6
2.2 ERR0002	7
2.3 ERR0003	8
2.4 ERR0004	9

Tables

Table 1-1 Summary of Silicon Errata	5
---	---

1 Introduction

This document contains the silicon errata known at the time of publication for the X3E artificial intelligence processor in supported releases up to.

1.1 Scope

This document describes the errata by Errata ID. Each description includes:

- A unique defect tracking identifier and the current status of the errata.
- Where the implementation deviates from the specification and the conditions under which erroneous behavior occurs.
- The implications of the erratum with respect to typical applications.
- The application and limitations of a workaround where possible.

This document describes errata information that may impact anyone who is developing software that will run on implementations of this X3E product.

1.2 Errata Summary

Table 1-1 below gives a quick reference to all documented device errata of the X3E and their status:

- A = workaround available
- N = no workaround available
- P = partial workaround available

Table 1-1 Summary of Silicon Errata

Errata ID	Errata	Solution	Status
IPU			
ERR0001	IPU configuration failed about ddr_en of DS2 channel.	No fix scheduled	A
ERR0002	Bus hang up during frame drop operation.	No fix scheduled	A
PYM			
ERR0003	Bus hang up during frame drop operation.	No fix scheduled	P
USB			
ERR0004	USB hot plug failed.	No fix scheduled	A

2 Errata

2.1 ERR0001

IPU: IPU configuration failed about ddr_en of DS2 channel

Description

IPU configuration is failed about ddr_en of DS2 channel with shadow register group 2 and 3 selected when the current shadow ready 2 and 3 set.

The ddr_en for shadow register group 2 and 3 selection map wrong ready flag.

Workarounds

Have to set the shadow ready 1 to instead the shadow ready 2 and 3 for ddr_en.

Proposed Solution

No fix scheduled.

2.2 ERR0002

IPU: Bus hang up during frame drop operation

Description

There is a bus write FIFO control bug occurred with corner bus response during frame drop operation.

This bug will stop the write data transfer after write command, and then make stall inside the DDR controller.

Implications

This bug make bus hang up with frame drop operation when the DDR bandwidth is over 65% usage.

Workarounds

To avoid frame drop in busy DDR usage, perform the following procedures:

1. Set bus write FIFO thread pointer to 0x0.
2. Use the safe output image width (buffer depth – 256 pixels) for the down scaler 0/1/3/4 as below:
 - Upscale: (buffer depth 2688): 2688x1944.
 - Down scale 0: (buffer depth 1280): 1024x720.
 - Down scale 1: (buffer depth 2048): 1792x1080.
 - Down scale 2: (buffer depth 2688): 2688x1944.
 - Down scale 3: (buffer depth 2048): 1792x1080.
 - Down scale 4: (buffer depth 1280): 1024x720.

Proposed Solution

No fix scheduled.

2.3 ERR0003

PYM: Bus hang up during frame drop operation

Description

There is a failed data transfer protection during frame drop operation. The bus response will hit the corner case when frame drop asserted from other scale channel.

Implications

This bug make bus hang up with frame drop operation when the DDR bandwidth is over 65% usage.

Workarounds

Have to use offline mode to instead online mode to avoid frame drop.

Proposed Solution

No fix scheduled.

2.4 ERR0004

USB: USB hot plug failed

Description

In USB device mode, there is no VBUS detection in current chip ball out to detect external VBUS connected.

Implications

The USB host can't detect the X3E USB device after hot plug.

Workarounds

Have to use a GPIO for the VBUS in detection in USB device mode.

Proposed Solution

No fix scheduled.