


ADVANCED SYSTEM ADMINISTRATION & NETWORK ENGINEERING CHALLENGE: SELF-HEALING, ZERO-DOWNTIME ENTERPRISE NETWORK



Explanation

Detailed Explanation of Your Network Setup

Your network is designed with **high availability, security, and scalability** in mind. Below is a structured explanation of each component and how they work together.

1. Network Design Overview

Your network follows a **three-layer architecture**, including:

1. **Core Layer:**
 - Two Cisco 2911 routers for **external connectivity and redundancy**

- Connected using a **cluster link** for failover
 - 2. **Firewall Layer:**
 - Two **ASA 5506-X** firewalls
 - Firewalls separate **internal, DMZ, and external networks**
 - Security levels are assigned to protect different network zones
 - 3. **Distribution Layer:**
 - Two **Cisco 3650 multilayer switches**
 - They handle **VLAN segmentation, InterVLAN routing, and redundancy (HSRP)**
 - Also responsible for **connecting to firewalls and core routers**
 - 4. **Access Layer:**
 - Three **Cisco 2960 switches**
 - Connect end devices such as **PCs, servers, and Wireless LAN Controller (WLC-2504)**
 - Implement **Spanning Tree Protocol (STP)** to prevent loops
-

2. Device Security & Management

- All devices have a **hostname** set for identification
 - **SSH** is configured for secure remote access instead of Telnet
 - **ACLs (Access Control Lists)** restrict unauthorized access to management interfaces
 - **Banner messages** warn unauthorized users
-

3. VLANs and Segmentation

The network uses **VLANs (Virtual LANs)** to separate traffic for security and efficiency:

- **VLAN - Management** (For network administrators and device management)
- **VLAN - Users** (For employees and workstation traffic)
- **VLAN - Servers** (For internal applications, database, and storage)

VLANs prevent **unnecessary traffic flow** between departments and improve security.

4. Redundancy & High Availability

- **HSRP (Hot Standby Router Protocol)** is implemented on the **two multilayer switches** to provide a **virtual IP address** for gateway redundancy
 - If one switch fails, the **other automatically takes over as the default gateway**
 - **EtherChannel** is used to bundle multiple links between switches, improving bandwidth and failover
-

5. Spanning Tree Protocol (STP) Implementation

- STP is enabled to **prevent network loops**, ensuring a stable network
 - **PortFast and BPDU Guard** are configured on **end-device ports** to protect against accidental loops
-

6. DHCP Server & IP Addressing

- The **DHCP server** dynamically assigns **IP addresses** to devices in the user VLAN
 - **DHCP Relay** is configured so that requests from other VLANs are forwarded to the DHCP server
 - **DMZ and Server VLANs** use **static IP addressing** for stability and security
-

7. OSPF Routing Protocol

- **OSPF (Open Shortest Path First)** is implemented across routers, firewalls, and switches to enable **dynamic routing**

- This ensures automatic route adjustments in case of **link failures**
 - The **firewall redistributes static routes** to OSPF to provide **external connectivity**
-

8. Firewall Security & ACLs

- The **firewall assigns different security levels** to interfaces:
 - **Inside (Highest Security)** → Used for internal users
 - **DMZ (Medium Security)** → Hosts publicly accessible servers
 - **Outside (Lowest Security)** → Connects to the internet
 - **ACLs are used** to control traffic between these zones:
 - **Restricting unauthorized external access**
 - **Allowing specific inbound connections** (e.g., web and mail servers)
 - **Blocking unnecessary internal-to-DMZ access**
-

9. Internet & External Connectivity

- The **firewall acts as the main security gateway** to filter and inspect traffic
 - A **static default route is configured** on the firewall to send all internet-bound traffic to the ISP router
 - **NAT (Network Address Translation) is enabled** to allow internal devices to access the internet securely
-

10. Final Testing & Troubleshooting

To ensure the network is working properly:

- **Ping between VLANs to test InterVLAN communication**
 - **Check HSRP status to confirm failover is active**
 - **Verify OSPF neighbor relationships to ensure proper routing**
 - **Review firewall logs to ensure correct security policies are applied**
 - **Test redundancy by shutting down one switch or router and observing failover behavior**
-

Conclusion

This setup provides:

High availability with HSRP, OSPF, and EtherChannel

Strong security with VLAN segmentation, ACLs, and Firewalls

Efficient traffic management using STP, DHCP, and OSPF

Network Devices

Firewall 1

Rom image verified correctly

Cisco Systems ROMMON, Version 1.1.8, RELEASE SOFTWARE

Copyright (c) 1994-2015 by Cisco Systems, Inc.

Compiled Thu 06/18/2015 12:15:56.43 by builders

Current image running: Boot ROM0

Last reset cause: PowerCycleRequest
DIMM Slot 0 : Present

Platform ASA5506 with 4096 Mbytes of main memory
MAC Address: 00D0.58D1.7A01

Use BREAK or ESC to interrupt boot.
Use SPACE to begin boot immediately.

LFBFF signature verified.
INIT: version 2.88 booting
Starting udev
Configuring network interfaces... done.
Populating dev cache
dosfsck 2.11, 12 Mar 2005, FAT32, LFN
There are differences between boot sector and its backup.
Differences: (offset:original/backup)
65:01/00
Not automatically fixing this.
Starting check/repair pass.
Starting verification pass.
/dev/sdb1: 110 files, 814352/1798211 clusters
dosfsck(/dev/sdb1) returned 0
IO Memory Nodes: 1
IO Memory Per Node: 205520896 bytes

Global Reserve Memory Per Node: 314572800 bytes Nodes=1

LCMB: got 205520896 bytes on numa-id=0, phys=0x10dc00000, virt=0x2aaaab000000
LCMB: HEAP-CACHE POOL got 314572800 bytes on numa-id=0, virt=0x7fea63e00000
Processor memory: 1502519902

Compiled on Fri 18-Mar-16 14:04 PDT by builders

Total NICs found: 13
i354 rev03 Gigabit Ethernet @ irq255 dev 20 index 08 MAC: 0060.2F99.4C01
ivshmem rev03 Backplane Data Interface @ index 09 MAC: 0000.0001.0002
en_vtun rev00 Backplane Control Interface @ index 10 MAC: 0000.0001.0001
en_vtun rev00 Backplane Int-Mgmt Interface @ index 11 MAC: 0000.0001.0003
en_vtun rev00 Backplane Ext-Mgmt Interface @ index 12 MAC: 0000.0000.0000
Verify the activation-key, it might take a while...
Running Permanent Activation Key: 0x8AAB4013 0xB23A93B2 0x8C87269C 0x9627792A 0xE283604C

Licensed features for this platform:
Maximum Physical Interfaces : 8 perpetual
Maximum VLANs : 30 perpetual

Inside Hosts : Unlimited perpetual
Failover : Active/Standby perpetual
Encryption-DES : Enabled perpetual
Encryption-3DES-AES : Enabled perpetual
Carrier : Disabled perpetual
AnyConnect Premium Peers : 4 perpetual
AnyConnect Essentials : Disabled perpetual
Other VPN Peers : 50 perpetual
Total VPN Peers : 50 perpetual
AnyConnect for Mobile : Disabled perpetual
AnyConnect for Cisco VPN Phone : Disabled perpetual
Advanced Endpoint Assessment : Disabled perpetual
Shared License : Disabled perpetual
Total UC Proxy Sessions : 160 perpetual
Botnet Traffic Filter : Disabled perpetual
Cluster : Disabled perpetual

This platform has an ASA 5506 Security Plus license.

Encryption hardware device : Cisco ASA Crypto on-board accelerator (revision 0x1)

Cisco Adaptive Security Appliance Software Version 9.6(1)

***** Warning *****

This product contains cryptographic features and is subject to United States and local country laws governing, import, export, transfer, and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute, or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return the enclosed items immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at:
<http://www.cisco.com/wwl/export/crypto/tool/stqrg.html>

If you require further assistance please contact us by sending email to export@cisco.com.

***** Warning *****

Cisco Adaptive Security Appliance Software, version 9.6
Copyright (c) 1996-2016 by Cisco Systems, Inc.

For licenses and notices for open source software used in this product, please visit

<http://www.cisco.com/go/asa-opensource>

Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) of the Commercial Computer Software - Restricted Rights clause at FAR sec. 52.227-19 and subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS sec. 252.227-7013.

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, California 95134-1706

Reading from flash...
!.

Cryptochecksum (unchanged): 53e564fb 7d6f3ddf 585849fd 748c6e59

INFO: Power-On Self-Test in process.

.....

INFO: Power-On Self-Test complete.

INFO: Starting HW-DRBG health test...

INFO: HW-DRBG health test passed.

INFO: Starting SW-DRBG health test...

INFO: SW-DRBG health test passed.

Type help or '?' for a list of available commands.

FWL1>

00:00:40: %OSPF-5-ADJCHG: Process 35, Nbr 1.1.3.3 on GigabitEthernet1/1 from LOADING to FULL, Loading Done

00:00:45: %OSPF-5-ADJCHG: Process 35, Nbr 1.1.4.4 on GigabitEthernet1/2 from LOADING to FULL, Loading Done

Firewall 2

Rom image verified correctly

Cisco Systems ROMMON, Version 1.1.8, RELEASE SOFTWARE

Copyright (c) 1994-2015 by Cisco Systems, Inc.
Compiled Thu 06/18/2015 12:15:56.43 by builders

Current image running: Boot ROM0
Last reset cause: PowerCycleRequest
DIMM Slot 0 : Present

Platform ASA5506 with 4096 Mbytes of main memory
MAC Address: 0001.631A.1901

Use BREAK or ESC to interrupt boot.
Use SPACE to begin boot immediately.

LFBFF signature verified.
INIT: version 2.88 booting
Starting udev
Configuring network interfaces... done.
Populating dev cache
dosfsck 2.11, 12 Mar 2005, FAT32, LFN
There are differences between boot sector and its backup.
Differences: (offset:original/backup)
65:01/00
Not automatically fixing this.
Starting check/repair pass.
Starting verification pass.
/dev/sdb1: 110 files, 814352/1798211 clusters
dosfsck(/dev/sdb1) returned 0
IO Memory Nodes: 1
IO Memory Per Node: 205520896 bytes

Global Reserve Memory Per Node: 314572800 bytes Nodes=1

LCMB: got 205520896 bytes on numa-id=0, phys=0x10dc00000, virt=0x2aaaab000000
LCMB: HEAP-CACHE POOL got 314572800 bytes on numa-id=0, virt=0x7fea63e00000
Processor memory: 1502519902

Compiled on Fri 18-Mar-16 14:04 PDT by builders

Total NICs found: 13
i354 rev03 Gigabit Ethernet @ irq255 dev 20 index 08 MAC: 00E0.F9D5.0701
ivshmem rev03 Backplane Data Interface @ index 09 MAC: 0000.0001.0002
en_vtun rev00 Backplane Control Interface @ index 10 MAC: 0000.0001.0001
en_vtun rev00 Backplane Int-Mgmt Interface @ index 11 MAC: 0000.0001.0003
en_vtun rev00 Backplane Ext-Mgmt Interface @ index 12 MAC: 0000.0000.0000
Verify the activation-key, it might take a while...

Running Permanent Activation Key: 0xE2E1C47B 0x594A9B77 0x34354936 0xEC5EDE66 0x06493C57

Licensed features for this platform:

Maximum Physical Interfaces : 8 perpetual
Maximum VLANs : 30 perpetual
Inside Hosts : Unlimited perpetual
Failover : Active/Standby perpetual
Encryption-DES : Enabled perpetual
Encryption-3DES-AES : Enabled perpetual
Carrier : Disabled perpetual
AnyConnect Premium Peers : 4 perpetual
AnyConnect Essentials : Disabled perpetual
Other VPN Peers : 50 perpetual
Total VPN Peers : 50 perpetual
AnyConnect for Mobile : Disabled perpetual
AnyConnect for Cisco VPN Phone : Disabled perpetual
Advanced Endpoint Assessment : Disabled perpetual
Shared License : Disabled perpetual
Total UC Proxy Sessions : 160 perpetual
Botnet Traffic Filter : Disabled perpetual
Cluster : Disabled perpetual

This platform has an ASA 5506 Security Plus license.

Encryption hardware device : Cisco ASA Crypto on-board accelerator (revision 0x1)

Cisco Adaptive Security Appliance Software Version 9.6(1)

***** Warning *****

This product contains cryptographic features and is subject to United States and local country laws governing, import, export, transfer, and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute, or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return the enclosed items immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at:
<http://www.cisco.com/wwl/export/crypto/tool/stqrg.html>

If you require further assistance please contact us by sending email to export@cisco.com.

***** Warning *****

Cisco Adaptive Security Appliance Software, version 9.6
Copyright (c) 1996-2016 by Cisco Systems, Inc.

For licenses and notices for open source software used in this product, please visit
<http://www.cisco.com/go/asa-opensource>

Restricted Rights Legend

Use, duplication, or disclosure by the Government is
subject to restrictions as set forth in subparagraph
(c) of the Commercial Computer Software - Restricted
Rights clause at FAR sec. 52.227-19 and subparagraph
(c) (1) (ii) of the Rights in Technical Data and Computer
Software clause at DFARS sec. 252.227-7013.

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, California 95134-1706

Reading from flash...
!.

Cryptochecksum (unchanged): 317f4cbd 7f631b85 27502e07 7b8d0e2d

INFO: Power-On Self-Test in process.

.....
INFO: Power-On Self-Test complete.

INFO: Starting HW-DRBG health test...
INFO: HW-DRBG health test passed.

INFO: Starting SW-DRBG health test...
INFO: SW-DRBG health test passed.

Type help or '?' for a list of available commands.

Multilayer Switch 3

Booting...
Interface GE 0 link down***ERROR: PHY link is down
Reading full image into memory
done
Bundle Image

Kernel Address : 0x5342e350
Kernel Size : 0x418a9b / 4295323
Initramfs Address : 0x53846dec
Initramfs Size : 0xe780c3 / 15171779
Compression Format : .mzip

Bootable image at @ ram : 0x5342e350
Bootable image segment 0 address range[0x81100000, 0x82140000] is in range[0x80180000, 0x90000000].
@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
File flash:/cat3k_caa-universalk9.16.03.02.SPA.bin uncompressed and installed, entry point :
0x81690280
Loading Linux kernel with entry point 0x8166a600 ...
Bootloader: Done loading app on core_mask : 0xf

Launching Linux Kernel (flags = 0x5)

%IOSXEBOOT-7474e1d3392fed124a6b809c1b351b29-new_cksum: (rp/0): 4
%IOSXEBOOT - 7474e1d3392fed124a6b809c1b351b29 - saved_cksum: (rp / 0) : 4
% IOSXEBOOT - Sat - ### : (rp / 0) : Feb 4 22 : 18 : 09 Universal 2017 PLEASE DO NOT POWER CYCLE
BOOT LOADER UPGRADING 4
% IOSXEBOOT - loader - boot: (rp / 0) : upgrade successful 4

Front - end Microcode IMG MGR : found 1 microcode images for 1 device.
Image for front - end 0 : / tmp / microcode_update / front_end / fe_type_8_1

--More-- Front - end Microcode IMG MGR : Preparing to program device microcode...
Front - end Microcode IMG MGR : Preparing to program device[0]...85504 bytes.
Front - end Microcode IMG MGR : Programming device
0...wRr0%.....10%.....20%.....30%.....40%.....50%.....60%.....70%....
.....80%.....90%.....!
Front - end Microcode IMG MGR : Microcode programming complete for device 0.
Front - end Microcode IMG MGR : Microcode programming complete in 43 seconds
1
Both links down, not waiting for other switches
Switch number is 1

Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) of the Commercial Computer Software - Restricted Rights clause at FAR sec. 52.227-19 and subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS sec. 252.227-7013.

cisco Systems, Inc.
170 West Tasman Drive
San Jose, California 95134-1706

Cisco IOS Software [Denali], Catalyst L3 Switch Software (CAT3K_CAA-UNIVERSALK9-M), Version 16.3.2, RELEASE SOFTWARE (fc4)

Technical Support : <http://www.cisco.com/techsupport>

Copyright(c) 1986 - 2016 by Cisco Systems, Inc.

Compiled Tue 08 - Nov - 16 17:31 by pt_team

Cisco IOS-XE software, Copyright(c) 2005 - 2016 by cisco Systems, Inc.
All rights reserved. Certain components of Cisco IOS - XE software are licensed under the GNU General Public License("GPL") Version 2.0. The software code licensed under GPL Version 2.0 is free software that comes with ABSOLUTELY NO WARRANTY. You can redistribute and / or modify such GPL code under the terms of GPL Version 2.0. For more details, see the documentation or "License Notice" file accompanying the IOS - XE software, or the applicable URL provided on the flyer accompanying the IOS - XE software.

FIPS: Flash Key Check : Begin

FIPS: Flash Key Check : End, Not Found, FIPS Mode Not Enabled

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at:
<http://www.cisco.com/wwl/export/crypto/tool/stqrg.html>

If you require further assistance please contact us by sending email to export@cisco.com.

cisco WS-C3650-24PS (MIPS) processor (revision N0) with 865815K/6147K bytes of memory.
Processor board ID FDO2031E1Q6
2048K bytes of non - volatile configuration memory.

4194304K bytes of physical memory.
250456K bytes of Crash Files at crashinfo : .
1609272K bytes of Flash at flash : .
0K bytes of at webui : .

Base ethernet MAC Address : 00:D0:BA:9C:5B:50
Motherboard assembly number : 73-15899-06
Motherboard serial number : FDO20311WHP
Model revision number : N0
Motherboard revision number : A0
Model number : WS-C3650-24PS
System serial number : FDO2031Q0TD

Press RETURN to get started!

%LINK-3-UPDOWN: Interface Vlan10, changed state to down

%LINK-3-UPDOWN: Interface Vlan20, changed state to down

%LINK-3-UPDOWN: Interface Vlan50, changed state to down

%LINK-3-UPDOWN: Interface Vlan90, changed state to down

%LINK-5-CHANGED: Interface Vlan10, changed state to up

%LINK-5-CHANGED: Interface Vlan20, changed state to up

%LINK-5-CHANGED: Interface Vlan50, changed state to up

%LINK-5-CHANGED: Interface Vlan90, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/1, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/1, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan1, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/2, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/2, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/3, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/3, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan10, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan20, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan50, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan90, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/4, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/4, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/6, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/6, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/7, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/7, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/8, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/8, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/9, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/9, changed state to up

%HSRP-6-STATECHANGE: Vlan10 Grp 10 state Speak -> Standby

%HSRP-6-STATECHANGE: Vlan10 Grp 10 state Standby -> Active

%HSRP-6-STATECHANGE: Vlan90 Grp 90 state Speak -> Standby

%HSRP-6-STATECHANGE: Vlan90 Grp 90 state Standby -> Active

%HSRP-6-STATECHANGE: Vlan20 Grp 20 state Speak -> Standby

%HSRP-6-STATECHANGE: Vlan20 Grp 20 state Standby -> Active

%HSRP-6-STATECHANGE: Vlan50 Grp 50 state Speak -> Standby

%HSRP-6-STATECHANGE: Vlan50 Grp 50 state Standby -> Active

Multilayer Switch 4

Booting...

Interface GE 0 link down***ERROR: PHY link is down

Reading full image into memory

done

Bundle Image

Kernel Address : 0x5342e350

Kernel Size : 0x418a9b / 4295323

Initramfs Address : 0x53846dec

Initramfs Size : 0xe780c3 / 15171779

Compression Format : .mzip

Bootable image at @ ram : 0x5342e350

Bootable image segment 0 address range[0x81100000, 0x82140000] is in range[0x80180000, 0x90000000].

@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@

File flash:/cat3k_caa-universalk9.16.03.02.SPA.bin uncompressed and installed, entry point :
0x81690280

Loading Linux kernel with entry point 0x8166a600 ...

Bootloader: Done loading app on core_mask : 0xf

Launching Linux Kernel (flags = 0x5)

%IOSXEBOOT-7474e1d3392fed124a6b809c1b351b29-new_cksum: (rp/0): 4

%IOSXEBOOT - 7474e1d3392fed124a6b809c1b351b29 - saved_cksum: (rp / 0) : 4

% IOSXEBOOT - Sat - ### : (rp / 0) : Feb 4 22 : 18 : 09 Universal 2017 PLEASE DO NOT POWER CYCLE

BOOT LOADER UPGRADING 4

% IOSXEBOOT - loader - boot: (rp / 0) : upgrade successful 4

Front - end Microcode IMG MGR : found 1 microcode images for 1 device.

Image for front - end 0 : / tmp / microcode_update / front_end / fe_type_8_1

--More-- Front - end Microcode IMG MGR : Preparing to program device microcode...

Front - end Microcode IMG MGR : Preparing to program device[0]...85504 bytes.

Front - end Microcode IMG MGR : Programming device

0...wRr0%.....10%.....20%.....30%.....40%.....50%.....60%.....70%....
.....80%.....90%.....!

Front - end Microcode IMG MGR : Microcode programming complete for device 0.

Front - end Microcode IMG MGR : Microcode programming complete in 43 seconds

1

Both links down, not waiting for other switches

Switch number is 1

Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) of the Commercial Computer Software - Restricted Rights clause at FAR sec. 52.227-19 and subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS sec. 252.227-7013.

cisco Systems, Inc.
170 West Tasman Drive
San Jose, California 95134-1706

Cisco IOS Software [Denali], Catalyst L3 Switch Software (CAT3K_CAA-UNIVERSALK9-M), Version 16.3.2, RELEASE SOFTWARE (fc4)
Technical Support : <http://www.cisco.com/techsupport>
Copyright(c) 1986 - 2016 by Cisco Systems, Inc.
Compiled Tue 08 - Nov - 16 17:31 by pt_team

Cisco IOS-XE software, Copyright(c) 2005 - 2016 by cisco Systems, Inc.
All rights reserved. Certain components of Cisco IOS - XE software are licensed under the GNU General Public License("GPL") Version 2.0. The software code licensed under GPL Version 2.0 is free software that comes with ABSOLUTELY NO WARRANTY. You can redistribute and / or modify such GPL code under the terms of GPL Version 2.0. For more details, see the documentation or "License Notice" file accompanying the IOS - XE software, or the applicable URL provided on the flyer accompanying the IOS - XE software.

FIPS: Flash Key Check : Begin
FIPS: Flash Key Check : End, Not Found, FIPS Mode Not Enabled

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at:
<http://www.cisco.com/wwl/export/crypto/tool/stqrg.html>

If you require further assistance please contact us by sending email to export@cisco.com.

cisco WS-C3650-24PS (MIPS) processor (revision N0) with 865815K/6147K bytes of memory.

Processor board ID FDO2031E1Q6

2048K bytes of non - volatile configuration memory.

4194304K bytes of physical memory.

250456K bytes of Crash Files at crashinfo : .

1609272K bytes of Flash at flash : .

0K bytes of at webui : .

Base ethernet MAC Address : 00:00:0C:17:40:04

Motherboard assembly number : 73-15899-06

Motherboard serial number : FDO20311WHP

Model revision number : N0

Motherboard revision number : A0

Model number : WS-C3650-24PS

System serial number : FDO2031Q0TD

Press RETURN to get started!

%LINK-3-UPDOWN: Interface Vlan10, changed state to down

%LINK-3-UPDOWN: Interface Vlan20, changed state to down

%LINK-3-UPDOWN: Interface Vlan50, changed state to down

%LINK-3-UPDOWN: Interface Vlan90, changed state to down

%LINK-5-CHANGED: Interface Vlan10, changed state to up

%LINK-5-CHANGED: Interface Vlan20, changed state to up

%LINK-5-CHANGED: Interface Vlan50, changed state to up

%LINK-5-CHANGED: Interface Vlan90, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/1, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/1, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan1, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/2, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/2, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/3, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/3, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan10, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan20, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan50, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan90, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/4, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/4, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/6, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/6, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/7, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/7, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/8, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/8, changed state to up

%LINK-5-CHANGED: Interface GigabitEthernet1/0/9, changed state to up

%LINEPROTO-5-UPDOWN: Line protocol on Interface GigabitEthernet1/0/9, changed state to up

%HSRP-6-STATECHANGE: Vlan50 Grp 50 state Speak -> Standby

%HSRP-6-STATECHANGE: Vlan50 Grp 50 state Standby -> Active

%HSRP-6-STATECHANGE: Vlan20 Grp 20 state Speak -> Standby

%HSRP-6-STATECHANGE: Vlan20 Grp 20 state Standby -> Active

%HSRP-6-STATECHANGE: Vlan10 Grp 10 state Speak -> Standby

%HSRP-6-STATECHANGE: Vlan10 Grp 10 state Standby -> Active

%HSRP-6-STATECHANGE: Vlan90 Grp 90 state Speak -> Standby
%HSRP-6-STATECHANGE: Vlan90 Grp 90 state Standby -> Active