


HMS DC Calibration: Oddities Observed in Residuals

Carlos Yero
July 3, 2018

1 PASS (2.2 GeV Beam):
HMS RUN 1267

DC RESIDUALS




Observed Bad Residuals
Corresponding to group of
Wires. ALL in TDC Slot 2

HMS Hut Crate, TDC SLOT2
Plane 1u1 (81-96)
Plane 1v2 (49-64)
Plane 2v1 (81-96)
Plane 2u2 (49-64)

**5 PASS (10.59 GeV Beam):
HMS RUN 1856**

DC RESIDUALS




**Observed Bad Residuals
Corresponding to group of
Wires. ALL in TDC Slot 2
(Edge wires are less obvious)**

**HMS Hut Crate, TDC SLOT2
Plane 1u1 (81-96)
Plane 1v2 (49-64)
Plane 2v1 (81-96)
Plane 2u2 (49-64)**


1 PASS (2.2 GeV Beam):
HMS RUN 1267

DC Drift Times vs. Wire

HMS Drift Time vs. Wire: Plane 2v1




HMS Drift Time vs. Wire: Plane 1u1




Odd Drift Times for the same groups that had bad residuals

HMS Drift Time vs. Wire: Plane 1v2




HMS Drift Time vs. Wire: Plane 2u2




**5 PASS (10.59 GeV Beam):
HMS RUN 1856**

HMS Drift Time vs. Wire: Plane 1v2




**Odd Drift Times for the
same groups that had bad
residuals**

HMS Drift Time vs. Wire: Plane 2u2



**The other groups of edge wires
From this run
were not that obvious,
And were not included**


1 PASS (2.2 GeV Beam):
HMS RUN 1267




It is as if SLOT 2 TDC, is
NOT determining the
Right reference time and so it appears to
be OUT of SYNC

NOTE: This was the slot that
Had an abnormal shift in time,
so the DC calibration
Need to correct for this.

ProjectionY of binx=46 [x=45.0..46.0]




ProjectionY of binx=54 [x=53.0..54.0]



5 PASS (10.59 GeV Beam):
HMS RUN 1856


HMS Drift Time vs. Wire: Plane 2u2




It is as if SLOT 2 TDC, is
NOT determining the
Right reference time and so it
appears to be **OUT of SYNC**

NOTE: This was the slot that
Had an abnormal shift in time,
so the DC calibration
Need to correct for this.

ProjectionY of binx=46 [x=45.0..46.0]



ProjectionY of binx=55 [x=54.0..55.0]



Conclusion

- 📌 The region of bad residuals is consistent between different runs, and seems to be coming from the same TDC SLOT 2, which has been known to have this Weird time offset.
- 📌 This problem observed in the residuals was hidden by another problem with The horoscope start-time being subtracted twice from the tdc time. But after this 'start-time' problem was solved, it uncovered, this other problem with the residuals.
- 📌 After discussing with Mark Jones, we came to the conclusion that these odd drift times observed stemming from the same tdc module, had to do with the module itself, and NOT the chamber.

The TDC Module in SLOT 2 of the HMS DC crate should be replaced before starting the FALL 2018 Run Period