


Statistical Process Control

Argon Chen (陳正剛)

Graduate Institute of Industrial Engineering
National Taiwan University

Impact of Variation on Quality Performance



Variation Causes and Behavior


- Shewhart's Variation Causes
 - Chance (Common) Causes
 - the variation sources are under the normal conditions that are commonly observed in processes.
 - Special (Assignable) Causes
 - some variation source(s) goes beyond the normal conditions
- Process shift
 - mean level shift
 - process variation shift
 - mean and variation shift

©Argon Chen

The Nature of Faults in the Process

Two fundamental types of faults or problems			
Faults	Local faults Special causes Sporadic problems Assignable causes :	versus	System faults Common causes Chronic problems Chance causes :
Examples	Broken tools Jammed machine Material contamination Human errors Accidents :	versus	Wrong specification Inappropriate method Poor supervision Poor training Poor design :
Action/ by Whom	Correctable locally (at the machine level) by the individual (operator or the first level of supervision)	versus	Requires a change in the system – only management can specify and implement the change


Behavior of Mean Level



5

©Argon Chen

Behavior of the Variation Level



6

©Argon Chen


Statistical Process Control

- A prime objective of a control chart is to detect special (assignable) causes of variation in a process.
- A control chart detects the presence of a special cause but does not "find" the cause.
- A process that is operating without special causes of variation (only under common causes of variation) is said to be "in a state of statistical control."

7

©Argon Chen

Classical Control System View of SPC Implementation




8

©Argon Chen

Moving from Instability to Control to Improvement

- SPC: detect and remove special cause of variation
- Process improvement: reduce common cause of variation



9

©Argon Chen


Statistical Process Control (SPC) Chart

- A scientific approach to detect process changes?
 - Hypothesis testing.....t-test? umh...too complicated...
 - Recall what hypothesis testing is
 - test statistic
 - rejection region
- SPC chart approach to detect process changes
 - sample statistic
 - out-of-control region
 - graphical trend chart

10

©Argon Chen

Hypothesis Testing vs. SPC Chart



- We need a model to describe the variability behavior
- Is there any universal mathematical model that can describe the behavior? Yes, normal distribution (Central Limit Theorem)!

11

©Argon Chen


Shewhart Control Chart

- Sample (Test) statistic (Y):
 - \bar{X} or R : variable characteristic (Ex: SiO_2 thickness, CD, etc.)
 - p : fraction defective (attribute characteristic) (Ex: number of defective wafers in a lot of wafers)
 - c : number of defects (attribute characteristic) (Ex: number of particles on a wafer)
- Out-of-control (Reject) region (Shewhart scheme):
 - outside (***Expected Value*** $\pm 3 \times$ ***Standard Deviation***)
- Shewhart Control Chart
 - Central Line (CL): mean of Y (or target T)
 - Upper Control Limit (UCL): $\text{CL} + 3 \hat{\sigma}_Y$
 - Lower Control Limit (LCL): $\text{CL} - 3 \hat{\sigma}_Y$

12

©Argon Chen

Control Chart for Central Tendency



$$\bar{Y} = \bar{X} = \sum_{i=1}^n X_i / n$$

n : sample size

$$CL = \bar{Y} = \bar{\bar{X}} \text{ (or } T \text{)}$$

$$UCL = \bar{\bar{X}} \text{ (or } T \text{)} + 3\hat{\sigma}_{\bar{X}}$$

$$LCL = \bar{\bar{X}} \text{ (or } T \text{)} - 3\hat{\sigma}_{\bar{X}}$$

13

©Argon Chen

Estimation of $\sigma_{\bar{X}}$

- Estimating $\sigma_{\bar{X}}$
sample standard deviation

$$\hat{\sigma}_{\bar{X}} = S_{\bar{X}} = \sqrt{\frac{\sum_i (\bar{X}_i - \bar{\bar{X}})^2}{k-1}}$$

- Do not use** $\sigma_{\bar{X}} = \frac{\sigma_X}{\sqrt{n}} \Rightarrow \hat{\sigma}_{\bar{X}} = \frac{S_X}{\sqrt{n}}$

(Variation sources of X and \bar{X} are different)

14

©Argon Chen

Control Chart for Dispersion

- Control chart (hypothesis test) for dispersion
 - test statistic: range (R)
 - rejection region: above or below 3 standard deviation of R

$$\bar{R} \pm 3 \cdot \hat{\sigma}_R$$

- Estimating σ_R :

$$\hat{\sigma}_R = S_R = \sqrt{\frac{\sum_i (R_i - \bar{R})^2}{k-1}}$$

Control Limit Calculations

Given $\hat{\sigma}_{\bar{x}} = S_{\bar{x}}$ and $\hat{\sigma}_R = S_R$

Average chart





$$UCL(LCL) = \bar{\bar{X}} + (-)3\hat{\sigma}_{\bar{x}} = \bar{\bar{X}} + (-)3S_{\bar{x}}$$

~~$$UCL(LCL) = \bar{\bar{X}} + (-)3\frac{\hat{\sigma}_x}{\sqrt{n}} = \bar{\bar{X}} + (-)3\frac{S_x}{\sqrt{n}}$$~~

Range chart

$$\begin{aligned} UCL(LCL) &= \bar{R} + (-)3\sigma_R = \bar{R} + (-)3S_R \\ &= \bar{R} + 3S_R(\max(0, \bar{R} - 3S)) \end{aligned}$$

\bar{X} -R Control Chart



$$Y = \bar{X} = \sum_{i=1}^n X_i / n$$

n : sample size

$$CL = \bar{Y} = \bar{\bar{X}} \text{ (or } T \text{)}$$

$$UCL = \bar{\bar{X}} \text{ (or } T \text{)} + 3S_{\bar{X}}$$

$$LCL = \bar{\bar{X}} \text{ (or } T \text{)} - 3S_{\bar{X}}$$

$$Y = R = X_{\max} - X_{\min}$$

$$CL = \bar{Y} = \bar{R}$$

$$UCL = \bar{R} + 3S_R$$

$$LCL = \max[0, \bar{R} - 3S_R]$$

17







©Argon Chen

Constructing \bar{X} and R Control Charts – making sure data used are under only common causes

initial

1st revision

2nd revision



18

©Argon Chen

Two Types of Errors and Chart Performance

- Two errors of \bar{X} hypothesis testing:
 - type I error?
chart signals but the process is still in control
 - type II error?
chart does not signal but the process is actually out of control
- Calculating the probabilities of type I and type II errors (α and β)
 - assumptions: normal and independence

Example: \bar{X} - R control chart

©Argon Chen


Two Types of Errors and Average Run Length

- Average Run Length (ARL): The average time length a control chart takes to give an alarm.
- ARL_0 : The average time length a control chart takes to give an false alarm when the process is actually in-control. (measuring Type I error probability, α)
- ARL_1 : The average time length a control chart takes to give an out-of-control alarm given the process is indeed out-of-control (measuring Type II error probability, β)

©Argon Chen


Average Run Length (ARL_0) under Control

- RL_0 : number of runs between false alarms (a random variable)
- Average run length (ARL_0)
 - Average of RL_0 (Geometric Distribution with $p=\alpha$)
 - Higher $ARL_0 \Rightarrow$ higher robustness
 - $ARL_0=1/\alpha$




Average Run Length (ARL_1) under Out-of-Control

- RL_1 : the number of runs it takes to detect a shift (a random variable)
- Average run length (ARL_1)
 - Average of RL_1 (Geometric Distribution with $p=1-\beta$)
 - Lower $ARL_1 \Rightarrow$ higher sensitivity
 - $ARL_1=1/(1-\beta)$ for Shewhart control chart



Type I Error Prob. of \bar{X} Chart




$$\alpha = 0.0027 \Rightarrow ARL_0 = \frac{1}{\alpha} = 370.37$$

23

©Argon Chen

Type II Error Prob. of \bar{X} Chart




$$\begin{aligned} \beta &= \text{Prob.}(T - 3\sigma_{\bar{x}} \leq \bar{x} \leq T + 3\sigma_{\bar{x}}) \\ &= \text{Prob.}\left(\frac{T - 3\sigma_{\bar{x}} - (T + 2\sigma_{\bar{x}})}{\sigma_{\bar{x}}} \leq \frac{\bar{x} - (T + 2\sigma_{\bar{x}})}{\sigma_{\bar{x}}} \leq \frac{T + 3\sigma_{\bar{x}} - (T + 2\sigma_{\bar{x}})}{\sigma_{\bar{x}}}\right) \\ &= \text{Prob.}(-5 \leq Z \leq 1) = ? \Rightarrow ARL_1 = 1/(1 - \beta) \end{aligned}$$

24

©Argon Chen

Control Chart Zones to Aid Control Chart Rules




- Western Electric Run Rules
- apply to \bar{X} and R control charts

25

©Argon Chen

Test 1: Extreme Points

- one point beyond the control limit
- apply to \bar{X} and R control charts
- Western Electric Rule 1




26

©Argon Chen

Test 2: Two-out-of-Three

- two out of three points in zone A or beyond
- apply to \bar{X} control chart (not to R since distribution of R is more likely asymmetric)
- Western Electric Rule 2




27

rgon Chen

Test 3: Four-out-of-Five

- four out of five points in zone B or beyond
- apply to \bar{X} control chart (not to R since distribution of R is more likely asymmetric)
- Western Electric Rule 3




28

©Argon Chen

Test 4: Runs above or below the Centerline

- eight points above or below the centerline
- apply to \bar{X} and R control charts
- Western Electric Rule 1




29

©Argon Chen

Test 5: Linear Trend Identification

- six points show a continuing increase or decrease
- apply to \bar{X} and R control charts




30

©Argon Chen

Test 6: Oscillatory Trend Identification

- 14 points oscillate up and down
- apply to \bar{X} and R control charts




31

©Argon Chen

Test 7: Avoidance of Zone C

- eight points avoid zone C
- apply to \bar{X} control chart




32

©Argon Chen

Test 8: Run in Zone C

- 15 points fall in zone C only
- apply to \bar{X} control chart




Notice: these tests do improve the sensitivity of the charts, but increase α -risk as well.

33

©Argon Chen

Control Chart for Attribute Variable

- Example: Defects on semiconductor wafer surface



34

Source: <https://www.rsipvision.com/automated-optical-inspection/>


©Argon Chen

Shewhart Attribute Control Chart

- p chart (fraction defective item)
- np (d) chart (number of defective item)
- c chart (number of defects)
- u chart (number of defects per unit)

Attribute Quality Characterization

- Example: defects of bearing cast



3 Cracks

6 Holes

1 Flash


1 Gate breakout

Number of defects = 11

Number of defectives = 6

Fraction defective = $\frac{6}{10} = 0.6$

Number of defects/unit = $\frac{11}{10} = 1.1$



Ideas of Number of Defectives np (d) Chart

- Number of Defectives: In a sample of n items, d is the number of bad items
- Assuming Binomial Distribution Model

$$P(d) = \binom{n}{d} p^d (1-p)^{n-d}$$

- Test statistic: d
- Control chart scheme: $E(d) \pm 3\sqrt{\text{Var}(d)}$
- Based on binomial model:

$$E(d) = np$$

$$\text{Var}(d) = np(1-p)$$

37

©Argon Chen

Number of Defectives (np) Chart

$$n\hat{p} \pm 3\sqrt{n\hat{p}(1-\hat{p})} \quad \text{where} \quad \hat{p} = \bar{p} = \frac{\sum_{i=1}^k d_i}{\sum_{i=1}^k n_i} \quad (\text{why not } \frac{\sum_{i=1}^k \frac{d_i}{n_i}}{k}?)$$

Average weighted by sample size

$$= \frac{n_1}{\sum_{i=1}^k n_i} \cdot \frac{d_1}{n_1} + \frac{n_2}{\sum_{i=1}^k n_i} \cdot \frac{d_2}{n_2} + \dots + \frac{n_k}{\sum_{i=1}^k n_i} \cdot \frac{d_k}{n_k} = \frac{\sum_{i=1}^k d_i}{\sum_{i=1}^k n_i}$$

38

©Argon Chen

- $n=100$
- $k=30$

Sample	Number Defective	Fraction Defective
1	7	0.07
2	8	0.08
3	6	0.06
4	8	0.08
5	6	0.06
6	8	0.08
7	3	0.03
8	5	0.05
9	9	0.09
10	7	0.07
11	7	0.07
12	9	0.09
13	8	0.08
14	7	0.07
15	8	0.08
16	10	0.10
17	10	0.10
18	5	0.05
19	12	0.12
20	11	0.11
21	8	0.08
22	10	0.10
23	4	0.04
24	10	0.10
25	7	0.07
26	7	0.07
27	9	0.09
28	8	0.08
29	10	0.10
30	10	0.10
	237	

39

©Argon Chen

Number of Defective (np) Chart

$$\begin{aligned}\bar{p} &= \frac{237}{3000} \\ &= 0.079\end{aligned}$$


$$\begin{aligned}n\bar{p} &= 100(0.079) \\ &= 7.9\end{aligned}$$

Control limits:

$$\begin{aligned}n\bar{p} \pm 3\sqrt{n\bar{p}(1-\bar{p})} \\ 7.9 \pm 3\sqrt{7.9(1-0.079)}\end{aligned}$$

$$UCL_{np} = 16.00$$

$$LCL_{np} = -0.20, \text{ so a lower limit of } 0.00 \text{ is used}$$



40

©Argon Chen

Ideas of Fraction Defectives (p) Chart

- Fraction Defectives: In a sample of n items, d is the number of bad items
- Assuming Binomial Distribution Model

$$P(d) = \binom{n}{d} p^d (1-p)^{n-d}$$

- Test statistic: d/n
- Control chart scheme: $E(d/n) \pm 3\sqrt{\text{Var}(d/n)}$
- Based on binomial model:

$$E(d/n) = E(d)/n = np/n = p$$

$$\text{Var}(d/n) = \text{Var}(d)/n^2 = [np(1-p)]/n^2 = [p(1-p)]/n$$

Fraction Defectives (p) Chart

$$\hat{p} \pm 3\sqrt{[\hat{p}(1-\hat{p})]/n}$$

$$\text{where } \hat{p} = \bar{p} = \frac{\sum_{i=1}^k d_i}{\sum_{i=1}^k n_i}$$

p Chart Example


Sample	Number Defective	Fraction Defective
1	7	0.07
2	8	0.08
3	6	0.06
4	8	0.08
5	6	0.06
6	8	0.08
7	3	0.03
8	5	0.05
9	9	0.09
10	7	0.07
11	7	0.07
12	9	0.09
13	8	0.08
14	7	0.07
15	8	0.08
16	10	0.10
17	10	0.10
18	5	0.05
19	12	0.12
20	11	0.11
21	8	0.08
22	10	0.10
23	4	0.04
24	10	0.10
25	7	0.07
26	7	0.07
27	9	0.09
28	8	0.08
29	10	0.10
30	10	0.10
237		

$$\begin{aligned}\bar{p} &= \frac{\text{sum of all defectives}}{\text{total number of units}} \\ &= \frac{237}{3000} \\ &= 0.0790\end{aligned}$$

For $\bar{p} = 0.0790$ and $n = 100$,

$$\begin{aligned}\hat{\sigma}_p &= \sqrt{\frac{\bar{p}(1-\bar{p})}{n}} \\ &= \sqrt{\frac{(0.0790)(1-0.0790)}{100}} \\ &= 0.0270\end{aligned}$$

$$\begin{aligned}\text{UCL} &= \bar{p} + 3\hat{\sigma}_p \\ &= 0.0790 + (3)(0.0270) \\ &= 0.1600 \\ \text{LCL} &= \bar{p} - 3\hat{\sigma}_p \\ &= 0.0790 - (3)(0.0270) \\ &= -0.002 \\ &= 0.0\end{aligned}$$



43

©Argon Chen

Variable-Sample-Size *p* Chart

- compute separate limits for each subgroup
- use an average sample size
- use standardized *p* values

$$Z_i = \frac{\frac{d_i}{n_i} - \bar{p}}{\sqrt{\bar{p}(1-\bar{p})/n_i}}$$


44

©Argon Chen

Variable-Sample-Size p Chart Example

Sample	n	d	p	LCL_p	UCL_p	z
1	238	11	0.046	0.026	0.131	-1.84
2	245	18	0.073	0.027	0.130	-0.28
3	270	17	0.063	0.029	0.127	-0.94
4	207	15	0.072	0.022	0.134	-0.31
5	251	11	0.044	0.027	0.129	-2.03
6	254	15	0.059	0.028	0.129	-1.14
7	236	19	0.081	0.026	0.131	0.13
8	245	20	0.082	0.027	0.130	0.19
9	246	35	0.142	0.027	0.130	3.74
10	269	14	0.052	0.029	0.127	-1.60
11	223	7	0.031	0.024	0.132	-2.61
12	246	42	0.171	0.027	0.130	5.40
13	262	14	0.053	0.029	0.128	-1.50
14	258	15	0.058	0.028	0.128	-1.21
15	232	20	0.086	0.025	0.131	0.45
16	219	9	0.041	0.024	0.133	-2.05
17	263	23	0.087	0.029	0.128	0.55
18	244	11	0.045	0.027	0.130	-1.93
19	274	21	0.077	0.030	0.127	-0.10
20	245	37	0.151	0.027	0.130	4.24
21	233	16	0.069	0.026	0.131	-0.55
22	267	18	0.067	0.029	0.128	-0.66
23	254	20	0.079	0.028	0.129	0.03
24	264	16	0.061	0.029	0.128	-1.07
25	253	34	0.134	0.028	0.129	3.32
26	290	22	0.076	0.031	0.126	-0.15
27	231	9	0.039	0.025	0.131	-2.23
28	227	40	0.176	0.025	0.132	5.49
29	234	18	0.077	0.026	0.131	-0.08
30	253	15	0.059	0.028	0.129	-1.13

Variable-Sample-Size p Chart Example



Ideas of Number of Defect Chart

- Assuming Poisson Distribution Model (why?)

$$P(\text{defect number} = c; \lambda) = \frac{e^{-\lambda} \lambda^c}{c!}$$

- Sample statistic: c
- Control chart scheme: $E(c) \pm 3\sqrt{\text{Var}(c)}$
- Base on Poisson model:

$$E(c) = \text{Var}(c) = \lambda$$

Number of Defect (c) Chart

$$\hat{\lambda} \pm 3\sqrt{\hat{\lambda}}$$

$$\text{where } \hat{\lambda} = \bar{c} = \frac{\sum_{i=1}^k c_i}{k}$$

Example of c Chart


Sample	Number of Defects
1	16
2	14
3	28
4	16
5	12
6	20
7	10
8	12
9	30
10	17
11	9
12	17
13	14
14	16
15	15
16	13
17	14
18	16
19	11
20	20
21	11
22	9
23	16
24	31
25	13

Centerline:

$$\begin{aligned}\bar{c} &= \frac{\text{total number of defects}}{\text{total number of samples}} \\ &= \frac{400}{25} \\ &= 16.\end{aligned}$$

Control limits:

$$\begin{aligned}UCL_c, LCL_c &= \bar{c} \pm 3\sqrt{\bar{c}} \\ &= 16 \pm 3\sqrt{16} \\ UCL_c &= 28 \\ LCL_c &= 4.\end{aligned}$$



49

©Argon Chen

Ideas of Number of Defects per Unit Chart

- Assuming Poisson Distribution Model again

$$P(\text{defect number/unit } b; \lambda) = \frac{e^{-\lambda} \lambda^b}{b!}$$

- Sample statistic: $u = \sum_{i=1}^n b_i / n = \frac{c}{n} = \bar{b}$

- Control chart scheme: $E(\bar{b}) \pm 3\sqrt{\text{Var}(\bar{b})}$
- Base on Poisson model:

$$E(\bar{b}) = E(b) = \lambda \quad \text{Var}(\bar{b}) = \text{Var}(b) / n = \lambda / n$$

50

©Argon Chen

Number of Defects per Unit (u) Chart

- Variable limits due to variable sample sizes

$$\hat{\lambda} \pm 3\sqrt{\hat{\lambda} / n}$$

$$\text{where } \hat{\lambda} = \frac{\sum_{i=1}^k c_i}{\sum_{i=1}^k n_i} \quad k : \text{number of samples (lots)}$$

Number of Defect per Unit (u) Chart Example

Sample	Sample Size, n	Number of Defects per Sample, c	Average Number of Defects per Unit, \bar{u}	LCL _{u_i}	UCL _{u_i}
1	16	23	1.44	0.49	2.25
2	20	30	1.50	0.59	2.16
3	26	35	1.35	0.68	2.06
4	8	12	1.50	0.13	2.61
5	22	29	1.32	0.62	2.12
6	29	35	1.21	0.72	2.02
7	31	50	1.61	0.74	2.00
8	13	15	1.15	0.40	2.35
9	28	36	1.29	0.71	2.04
10	23	38	1.65	0.64	2.10
11	19	24	1.26	0.57	2.18
12	23	32	1.39	0.64	2.10
13	14	24	1.71	0.43	2.31
14	29	34	1.17	0.72	2.02
15	27	38	1.41	0.70	2.05
16	15	25	1.67	0.46	2.28
17	22	26	1.18	0.62	2.12
18	22	24	1.09	0.62	2.12
19	14	22	1.57	0.43	2.31
20	16	17	1.06	0.49	2.25
21	22	33	1.50	0.62	2.12
22	16	21	1.31	0.49	2.25
23	14	18	1.29	0.43	2.31
24	5	9	1.80	0.00	2.94
25	13	18	1.38	0.40	2.35
26	19	26	1.37	0.57	2.18
27	10	12	1.20	0.26	2.48

An example calculation for control limits follows.

$$\begin{aligned} \text{control limits} &= \bar{u} \pm 3\sqrt{\frac{\bar{u}}{n}} \\ &= 1.37 \pm 3\sqrt{\frac{1.37}{n}} \end{aligned}$$

For sample 1, $n_1 = 16$, and therefore,

$$\text{LCL}_{u_1} = 0.49$$

$$\text{UCL}_{u_1} = 2.25.$$

