

# IC100

## CNC Machine

Dr. Purnendu Das (Presenter)

Dr Jose Immanuel R. (Owner)

Assistant Professor




Department of Mechanical Engineering

**Indian Institute of Technology Bhilai**

# Principle of cutting



# Principle of cutting



# Machining Centers - A bit of history

**1949**

US Air Force asks MIT to develop a "numerically controlled" machine.

**1952**

Prototype NC machine demonstrated (punched tape input)

**1980-**

CNC machines (computer used to link directly to controller)

**1990-**

DNC: external computer "drip feeds" control programmer to machine tool controller

# Conventional milling machines

Vertical milling machine




VICTOR JF-3VS

# Conventional milling machines

Horizontal Milling machine architecture

**How does the table move  
along X- Y- and Z- axes ?**





Conventi



# Introduction to CNC

- Numerical control (NC) is the automation of machine tools that are operated by precisely programmed commands encoded on a storage medium, as opposed to controlled manually.
- Most NC today is computer numerical control (CNC), in which computers play an integral part of the control.
- In modern CNC systems, end-to-end component design is highly automated using computer-aided design (CAD) and computer-aided manufacturing (CAM) programs.




# Advantages of CNC

- CNC machines can be used continuously
- Batch production with high accuracy
- Can be updated by improving the software
- Training in the use of CNCs is available through the use of 'virtual software'.
- Intricate detail machining
- No need to make a prototype or a model
- One person can supervise many CNC machines simultaneously – Economical and time saving

# Disadvantages

- Expensive than manually operated machines
- CNC machine operator only needs basic training and skills, enough to supervise several machines. In years gone by, engineers needed years of training to operate centre lathes, milling machines and other manually operated machines. This means many of the **old skills are been lost.**
- Investment in CNC machines can lead to unemployment

# Operations in CNC



CNC Milling



CNC Plasma Cutter




CNC Electric Discharge Machining

# Other CNC Operations

- CNC Water Jet Cutter
- Drilling
- Sheet metal works (Turret punch)
- Wire bending machines
- Surface grinders
- Cylindrical grinders


# Some principle components



# Elements of CNC Machine

**SIX** major elements:

- i. Input Device
- ii. Machine Control Unit
- iii. Machine Tool
- iv. Driving System
- v. Feedback Devices
- vi. Display Unit



# Types

*Based on **Motion Type:***

Point-to-Point      or      Continuous path

*Based on **Control Loops:***

Open loop      or      Closed loop

*Based on **Power Supply:***

Electric      or      Hydraulic      or      Pneumatic

*Based on **Positioning System***


Incremental      or      Absolute



# Motion Control Systems

## 1. Point-To-Point Control: CNC Drilling of Three Holes in **Flat Plate**


- System moves to a location and performs an operation at that location (e.g., drilling)
- Also applicable in robotics



# Motion Control Systems


## 2. Continuous Path Control in CNC Profile Milling of Part Outline

- System performs an operation during movement (e.g., milling and turning) - Contouring




# Open Loop Systems

Open loop systems have no access to the real time data about the performance of the system and therefore no immediate corrective action can be taken in case of system disturbance.




## Open loop system – An example




# Close Loop Systems

In a close loop system, feed back devices closely monitor the output and any disturbance will be corrected in the first instance. Therefore high system accuracy is achievable.




## Close loop system – An example



# Ball Lead Screws



- Ball lead screw is the heart of the drive system.
- Advantages of ball lead screw are:
- Precise position and repeatability
- High Speed capability
- Less Wear
- Longer life

## PITCH Vs LEAD





# Absolute and relative dimensioning






# CNC Programming Basics

- CNC instructions are called part program commands.
- When running, a part program is interpreted one command line at a time until all lines are completed.
- Commands, which are also referred to as blocks, are made up of words which each begin with a letter address and end with a numerical value.




# CNC programming – Things to know

- Coordinate System
- Units, incremental or absolute positioning
- Coordinates: X,Y,Z, RX,RY,RZ
- Feed rate and spindle speed
- Coolant Control: On/Off, Flood, Mist
- Tool Control: Tool and tool parameters

# Axes of CNC Machine Tool




# From 3-axis to 5-axis machining



- Not sufficient for the complete finishing process for very deep part and having narrow cavities
- Results in a bad surface quality and long machining times in Case of harder material
- dozens of views need to be defined
- more tool movements
- programming is quite difficult
- sum of all views does not cover the whole geometry
- overlapping views lead to surface quality problems
- More number of lead-in and out movements

# Five Axis CNC



# Application

- complex three dimensional profiles
- for impellers, turbine blades, and plastic mold tools




# ADVANTAGES OF 5 AXIS CNC

- to machine complex shapes in a single setup
- reduces the machinist setup time and increases production rates
- By eliminating multiple set-ups, time and errors are reduced
- the feature-to-features accuracy is improved because the same zero or datum reference frame is used throughout the manufacturing process
- since simultaneous movement is allowed along the X and Y axis, shorter and more rigid tools may be used
- higher spindle/cutting tool speeds may be achieved while reducing the load on the cutting tool
- Shorter and thicker cutters also reduce vibration when machining deep pockets or contoured features with three-axis machines.

# Programming the machines – G code

- Each line of program -> **Block**



# Programming Key Letters


- O - Program number (Used for program identification)
- N - Sequence number (Used for line identification)
- G - Preparatory function
- X - X axis designation
- Y - Y axis designation
- Z - Z axis designation
- R - Radius designation
- F - Feed rate designation
- S - Spindle speed designation
- H - Tool length offset designation
- D - Tool radius offset designation
- T - Tool Designation
- M - Miscellaneous function

# Some essential G-codes

- G00 Rapid traverse
- G01 Linear interpolation
- G02 Circular interpolation CW
- G03 Circular interpolation CCW
- G20 Imperial unit
- G21 Metric unit
- G90 Absolute system
- G91 Incremental system
- G94 Feed per minute
- G95 Feed per revolution


# Some essential M-codes

- M00 Program Stop
- M03 Spindle on CW
- M04 Spindle on CCW
- M05 Spindle stop
- M06 ATC
- M08/M09 Coolant on/off
- M10/M11 Vice Open/close
- M30 Program stop and rewind
- M98 Sub-program call
- M99 Sub-program end and return



# Example

- Feed: 30 mm/min
- Speed: 5000 rpm



# Primary Machining Parameters

- Cutting Speed – ( $v$ )
  - Primary motion
  - Peripheral speed

	m/s	ft/min
--	-----	--------
- Feed – ( $f$ )
  - Secondary motion
  - Turning:
  - Milling:

	mm/rev	in/rev
	mm/tooth	in/tooth
- Depth of Cut – ( $d$ )
  - Penetration of tool below original work surface
  - Single parameter

	mm	in
--	----	----
- Resulting in Material Removal Rate – ( $MRR$ )  
$$MRR^* = v f d$$

	mm <sup>3</sup> /s	in <sup>3</sup> /min
--	--------------------	----------------------

where  $v$  = cutting speed;  $f$  = feed;  $d$  = depth of cut

\* general model, only!

# Machining Operations & Parameters

<i>Operation Type</i>	<i>Speed</i>	<i>Feed</i>	<i>Depth of Cut</i>
Turning: workpiece rotates single point cutting	<b>Surface speed (periphery) of workpiece</b>	<b>Parallel to the workpiece axis*</b> (except parting/grooving)	<b>Tool penetration below original work surface</b>
Drilling: tool rotates single pass cutting	<b>Surface speed (periphery) of tool</b>	<b>Parallel to the tool axis</b>	<b>Tool penetration below original work surface (depth of hole)</b>
Milling: tool rotates multi-point cutting	<b>Surface speed (periphery) of tool</b>	<b>Perpendicular to the tool axis</b>	<b>Tool penetration below original work surface</b>



# Cut Types: Roughing & Finishing

<i>Cut Type</i>	<i>Number of Passes</i>	<i>Speed</i>	<i>Feed</i>	<i>Depth of Cut</i>
Roughing: removes large amounts to get close to shape	1 +	Low	High 0.4 - 1.25 mm/ .015 - .050 in/	High 2.5 - 20 mm .100 - .750 in
Finishing: achieves final dimensions, tolerances, and finish	1 - 2	High	Low 0.125 - 0.4 mm/ .005 - .015 in/	Low 0.75 - 2.0 mm .030 - .075 in

# Machining Calculations: Turning

- Spindle Speed -  $N$ 
  - $v$  = cutting speed
  - $D_o$  = outer diameter

$$N = \frac{v}{\pi D_o}$$

(rpm)

- Feed Rate -  $f_r$ 
  - $f$  = feed per rev

$$f_r = N f$$

(mm/min -or- in/min)

- Depth of Cut -  $d$ 
  - $D_o$  = outer diameter
  - $D_f$  = final diameter

$$d = \frac{D_o - D_f}{2}$$

(mm -or- in)

- Machining Time -  $T_m$ 
  - $L$  = length of cut

$$T_m = \frac{L}{f_r}$$

(min)

- Mat'l Removal Rate - MRR

$$MRR = v f d$$

(mm<sup>3</sup>/min -or- in<sup>3</sup>/min)\*

*\* This approximate equation assumes that  $f$  has units of mm or inches – in accordance with Groover and Rufe (SME) texts.*

- Mat'l Removal Rate - MRR

$$MRR = \pi D_{avg} d f N$$

(mm<sup>3</sup>/min -or- in<sup>3</sup>/min)\*

In this equation:  
 – in accordance with Kalpakjian, et. al. texts.

$$D_{avg} = \frac{D_o + D_i}{2}$$

IBNC 435 Computer Controlled

Mat'l Removal Rate - MRR  $MRR = \frac{\pi (D_o^2 - D_i^2) f N}{4}$  (mm<sup>3</sup>/min -or- in<sup>3</sup>/min)\*

*\*This equation is the SDSM&T form!*

$$MRR = v f d$$

# Machining Calculations: Drilling

- Spindle Speed -  $N$

- $v$  = cutting speed
- $D$  = tool diameter

$$N = \frac{v}{\pi D}$$

(rpm)

- Feed Rate -  $f_r$

- $f$  = feed per rev

$$f_r = Nf$$

(mm/min -or- in/min)

- Machining Time -  $T_m$

– Through Hole :

- $t$  = thickness
- $\theta$  = tip angle

$$T_m = \frac{t + \frac{1}{2}D[\tan(90 - \frac{\theta}{2})]}{f_r}$$

(min)

– Blind Hole :

- $d$  = depth

$$T_m = \frac{d}{f_r}$$

- Mat'l Removal Rate - MRR

$$MRR = \frac{\pi D^2 f_r}{4}$$

(mm<sup>3</sup>/min -or- in<sup>3</sup>/min)

Alternatively:  $MRR = \frac{\pi D^2 N f}{4}$

# Machining Calculations: Milling

- Spindle Speed -  $N$

- $v$  = cutting speed
- $D$  = cutter diameter

$$N = \frac{v}{\pi D} \quad (\text{rpm})$$

- Feed Rate -  $f_r$

- $f$  = feed per tooth
- $n_t$  = number of teeth

$$f_r = N n_t f$$

(mm/min -or- in/min)

- Machining Time -  $T_m$

- Slab Milling:

- $L$  = length of cut
- $d$  = depth of cut

$$T_m = \frac{L + \sqrt{d(D-d)}}{f_r}$$

(min)

- Face Milling:

- $w$  = width of cut
- 2<sup>nd</sup> form is multi-pass

$$T_m = \frac{L + D}{f_r} \quad \text{-or-} \quad T_m = \frac{L + 2\sqrt{w(D-w)}}{f_r}$$

- Mat'l Removal Rate - MRR

$$MRR = w d f_r \quad (\text{mm}^3/\text{min} \text{ -or- } \text{in}^3/\text{min})$$

# Power and Energy Relationships

- Power requirements to perform machining can be computed from:

$$P_c = F_c v \quad \text{N-m/s (W)} \quad \text{ft-lb/min}$$

where:  $P_c$  = cutting power;  
 $F_c$  = cutting force; and  
 $v$  = cutting speed

- Customary U.S. units for power are Horsepower  
(= 33000 ft-lb/min)

# Power and Energy Relationships

- The Gross machine power ( $P_g$ ) available is:

$$P_c = P_g \bullet E$$

where  $E$  = mechanical efficiency of machine tool

- Typical  $E$  for machine tools =  $\sim 80 - 90\%$

Note: Alternate relationships for the same -

$$P_g = \frac{P_c}{E}$$

$$HP_g = \frac{HP_c}{E}$$

# Unit Power in Machining

- Useful to convert power into power per unit volume rate of metal cut
- Called the *unit power*,  $P_u$  or *unit horsepower*,  $HP_u$

$$P_u = \frac{P_c}{MRR} \quad \text{or} \quad HP_u = \frac{HP_c}{MRR}$$

where  $MRR$  = material removal rate



# Specific Energy in Machining

- Unit power ( $P_u$ ) is also known as the *specific energy* ( $U$ ), or the power required to cut a unit volume of material:

$$U = P_u = \frac{P_c}{MRR} = \frac{F_c}{t_o w}$$

where  $t_o$  = un-deformed chip thickness;  
 $w$  = width of the chip; and  
 $F_c$  = cutting force

- Units for specific energy are typically N-m/mm<sup>3</sup> (*same as J/mm<sup>3</sup>*) or as in-lb/in<sup>3</sup>
- Table on Materials page approximates specific energy for several materials based on estimated hardness