

Micromouse Information packet:

You will have received:

## Mouse Contents

5x Printed Circuit Boards (Mother, Processor, Power, Sensing, Programming)

Pinheaders (2x **2x19**, 1x **2x14**, 1x **2x08** 1x **1x07** R/A)

Pinsockets (2x **2x19**, 2x **1x10**, 1x **2x14**)

2x Geared DC Motors

2x Wheels

2x Motor brackets (1x L, 1x R)


6x bolts

6x nuts



1x battery + connector



Battery




Motor brackets



Processor Board




Power Board



Programmer Adapter



Sensor Board



Power-pinheader



Sensing-pinheader



Processor-pinheaders



Sensing-pinsocket



Processor-pinsocket



Processor-pinsocket



Plus 2x jumper

Plus 2x 1x2 pinheader

Plus 4x header

Plus 6x header

Processor - programming



Adapter Connection



Adapter Connection





You will need:

Your programmer from your 2nd year STM Board


Soldering Iron


Solder

Some wire

## Initial Prep

Each of your boards will have a scored line on them. This is called a V-score and you can just snap off the extra pieces of fibreglass that are not needed.






Let's start with the base "aka" the motherboard.

## Motherboard

Before soldering the THT components

There are 8 resistors we need to short with solder.



R15, R13, R11, R9, R3, R1, R7, R5


Then if you feeling brave, you can ask Brendon for a SMD capacitor for C9 (10nF or 100nF would be fine)

Now you can solder the THT components;

The Processors 2x 2x19 pinsocket

The Sensorboards 1x 2x14 pinsocket






You still need to mount the motor, but we will do that a little later.

## Sensorboard

The sensor board needs jumpers soldered for the LED drive currents  
Each jumper pair has an L and an H. We want to solder the L current jumper.  
The 2x14 pinheader, **Note:** The board needs to face downward.  
The 2x 1x2 pinheaders. These are responsible for the downward LEDs power and signal.



## ProcessorBoard


The processor board needs:

Its 2x 2x19 pinheaders soldered

The pinsocket 1x7 for programming



## Powerboard

The battery connector - PAY careful attention to polarity...



The powerboard needs to 2x8 pinheader to be soldered onto it.





## Programmer

Break the pinsocket pieces to fit the programmer you need to cut it into 2 pieces 1x4 and 1x5 similar to what you did in your 2nd year STM kit.


Solder the R/A pinheader

Solder the pin sockets


Insert the Programmer

## Assembly

Cut the top off the motors



Before the motor cutout





After the motor cutaway

Clean the brackets

Remove the whiskers from the 3D prints and remove burrs








Solder wires to motors

Only 200mA - so I wouldn't worry about thickness

Insert motors into the bracket



Solder wires onto motherboard

Connect the Motors to the Motherboard.

Solder the power board onto the robot.

Plug in battery

Program the mouse



## Finished Images

