



8.10 Robot teaching for press down plate

Perform 8.2 Preparation for robot teaching before starting the procedure shown below.
Do not change T(Theta-axis) and R(R-axis) data for correct operation.



(1) Press [Q. STOP] key.




(2) Press [BUZZER STOP] key on MAIN SCREEN.





- (3) Connect the teach pendant with the machine, and press [TEACH MODE] key on the MAINSCREEN.
- (4) Press [MAINTENANCE] key on the teach pendant. "RANDOM" is displayed on the teach pendant screen. Press [BUZZER STOP] key on MAIN SCREEN.

8.10 Robot teaching for press down plate (Continued)




- (5) Press [SET] key on the MAIN SCREEN. "INDIVIDUAL OPERATION PANEL" is displayed.




- (6) Rotate the robot arm with teach pendant. T=1100, Z=1500
- (7) Press the display of "INDIVIDUAL OPERATION PANEL". The keyboard is displayed. Enter "762" (Press down plate forward), and press [ON] key.
- (8) Fine adjust the T-axis position so that the press down plate position is at the same position as the wafer chuck area.

8.10 Robot teaching for press down plate (Continued)



- (9) Moves the press down plate downward until it contacts the chuck table. (R-axis)
The value of Z at the position is Z_1 .



- (10) Moves the press down plate upward. (R-axis)
Place the wafer having warpage (maximum warpage in your wafer) on the chuck table.
- (11) Adjust the pressdown plate position so that it does not contact both peeling tape and wafer warpage. The value of Z at the position is Z_2

$$\text{Stroke} = Z_2 - Z_1$$

$$\text{Offset} = 100 \text{ (Fixed)}$$

$$Z = Z_2 - \text{Offset}$$

- (12) After positioning, press [READ POSITION] key. The current position of Z is displayed.
To save the value, press [TEMP] key holding down [SHIFT] key.