

**License Number**

CBD1601056

**Customer**

Nexteer Automotive Corporation  
Package: MSR\_Ford\_SLP1 - ECU product, "Steering Systems"

**Maintenance Expiry Date**

2018-03-01

**SIP Delivery Date**

2017-02-10

**SIP Version**

17.00.04

**SLP**

MSR\_Ford\_SLP1

**Delivery Number**

D00

**Report Creation Date**

2017-02-16

**Contact**

In case of questions or the need for an update of the basic software delivery, please contact [EmbeddedSupport@us.vector.com](mailto:EmbeddedSupport@us.vector.com) or your Vector contact person.

## Table of Contents

1. [Introduction](#)
  - [1.1 Resolving Issues](#)
  - [1.2 Issue Classification](#)
2. [New Issues](#)
  - [2.1 Safety Relevant Issues: 8](#)
  - [2.2 Runtime Issues without Workaround: 4](#)
  - [2.3 Runtime Issues with Workaround: 18](#)
  - [2.4 Not Released Functionality: 12](#)
  - [2.5 Apparent Issues: 88](#)
  - [2.6 Compiler Warnings: 44](#)
3. [New Issues for Information: 0](#)
4. [Report Legend](#)
5. [Quality Management Contact](#)

## 1. Introduction

### 1.1 Resolving Issues

Reported issues are not automatically fixed with the next update delivery.

If a reported issue shall be fixed, please contact Vector agree on the issues that can be fixed with upcoming deliveries.

Please note that Vector may fix issues without explicit request.

### 1.2 Issue Classification

This Issue Report provides issues that have been detected since the last report. The issues have been classified to facilitate the assessment of their impact:

The chapter 'New Issues' lists issues that have been detected since the last report and which could not be excluded based on the use-case defined in the questionnaire. The issues are classified as follows:

- **Safety Related Issues:** Safety related issues have impact on the functional safety of the software module. If this issue interferes with the functional safety concept of the ECU, this module (or module configuration) must not be used for serial production in a safety-related project. The effect of the issue to the ECU functionality and functional safety has to be analyzed by the user as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.
- **Runtime Issues without Workaround:** Runtime issues without a workaround require an update of the software delivery in case the issue affects the ECU overall functionality. The effect of an issue to the ECU functionality has to be analyzed by the customer as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.
- **Runtime Issues with Workaround:** It is not recommended to update a delivery due to a runtime issue with a documented workaround. The effect of an issue to the ECU functionality has to be analyzed by the user as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.
- **Not Released Functionality:** Not released functionalities (BETA) are either complete software modules or features in the software module that have not yet passed a complete development cycle (they are e.g. not or only partly tested). If a BETA issue ticket affects a complete software module, the software module must not be used for serial production. If a BETA issue ticket affects a feature in the software module, the user has to ensure that all BETA features are disabled as indicated for the serial production release of the ECU.
- **Apparent Issues:** Apparent issues are detected immediately when using the software module. If an issue does not show up while working with the software module, the ECU project is not affected by the issue. Apparent issues may or may not have workarounds.
- **Compiler Warnings:** As a service we also provide the known compiler warnings. The occurrence of a compiler warning may depend on the used software module configuration and compiler settings.

The chapter 'New Issues for Information' lists issues that are not relevant for the use-case that has been documented in the questionnaire provided to Vector. The issues may, however, be relevant for other use-cases. Additionally, issues that have been accepted or are tolerated by the OEM (as defined in the questionnaire) are reported here.

## 2. New Issues

### 2.1 Safety Relevant Issues

Safety related issues have impact on the functional safety of the software module. If this issue interferes with the functional safety concept of the ECU, this module (or module configuration) must not be used for serial production in a safety-related project.

The effect of the issue to the ECU functionality and functional safety has to be analyzed by the user as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.

#### Index

<a href="#">ESCAN00092747</a>	Mode Switch event in the wrong context leads to unexpected behavior SysService_Asr4EcuM@Implementation
<a href="#">ESCAN00093275</a>	ChainTask() returns to caller with disabled interrupts if the OS detects an error. Os_CoreGen7@Implementation
<a href="#">ESCAN00093505</a>	Automatic mode for calculating slave trigger pattern may expand time duration for reaching safe state or omit reaching safe state at all If_Asr4IfWd@Implementation
<a href="#">ESCAN00093570</a>	Data consistency problems due to usage of wrong interrupt lock APIs Rte_Core@Implementation
<a href="#">ESCAN00093734</a>	NvM allows to generate NULL_PTR for explicit synchronization callbacks for blocks with enabled NvMBlockUseSyncMechanism and NvMUseServicePorts MemService_AsrNvM@GenTool_GeneratorMsr
<a href="#">ESCAN00093745</a>	Data consistency problems because IOC API is called reentrantly in case of IOC queues with queue size 1 Rte_Core@Implementation
<a href="#">ESCAN00093787</a>	NvM GenTool_GeneratorMsr does not sync block length between NvM und underlying modules MemService_AsrNvM@GenTool_GeneratorMsr
<a href="#">ESCAN00093999</a>	API GetNumberOfActivatedCores() triggers kernel panic if caller is not trusted. Os_CoreGen7@Implementation

## ESCAN00092747 Mode Switch event in the wrong context leads to unexpected behavior

**Component@Subcomponent:** SysService\_Asr4EcuM@Implementation

**First affected version:** 5.00.00

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

-----  
The symptoms are highly dependent on the used ECU. It might happen that the OS error hook or the protection hook is called or the mode management behaves unexpectedly due to inconsistent internal data of the EcuM.

When does this happen:

-----  
This happens after calling the API EcuM\_SetState() (Used Rte Mode: EcuM\_CurrentMode) which can be called by application or by BswM.

In which configuration does this happen:

-----  
Only in configurations with EcuM/EcuMFlexGeneral/EcuMModeHandling is set to true

AND additional one of the following topics apply to your configuration.

- A non-MICROSAR RTE is used which provides memory protection
- The EcuM\_MainFunction and the application which calls EcuM\_SetState() belong to a different OS application

You are not affected if the EcuM\_MainFunction and the BswM action which triggers the EcuM\_SetState() are running in the same task context.

### Resolution Description:

Workaround:

-----  
In case that the EcuM\_SetState() API is called by application or by BswM (without using the ECU State Handling):

- The application or the BswM\_MainFunction() has to run in the same context task context as the EcuM\_MainFunction.

In case that the EcuM\_SetState() API is called by BswM (with using the ECU State Handling):

- No workaround for this use case.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

**ESCAN00093275 ChainTask() returns to caller with disabled interrupts if the OS detects an error.****Component@Subcomponent:** Os\_CoreGen7@Implementation**First affected version:** 1.00.00**Fixed in versions:** 1.09.00**Problem Description:**

What happens (symptoms):

-----  
Interrupts are disabled when function ChainTask() returns to calling task.

When does this happen:

-----  
- Task calls ChainTask and inter arrival time violation is detected and the ProtectionHook returns PRO\_IGNORE.  
- Task calls ChainTask with a TaskID which belongs on different core, and the X-Signal queue is already full.

In which configuration does this happen:

-----  
TimingProtection configured (SC2/SC4) and inter-arrival protection used.  
or  
Multi core task activation/chaining used.

Mind that this issue has been extended in:

ESCAN00093673: ChainTask() returns to caller with disabled interrupts if the OS detects an error.

**Resolution Description:**

Workaround:

-----  
Do not use ChainTask() for self chaining activation  
Instead call  
ActivateTask(<TaskID>);  
TerminateTask(<TaskID>);

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

## ESCAN00093505 Automatic mode for calculating slave trigger pattern may expand time duration for reaching safe state or omit reaching safe state at all

**Component@Subcomponent:** If\_Asr4IfWd@Implementation

**First affected version:** 5.00.00

**Fixed in versions:** 5.02.00

### Problem Description:

What happens (symptoms):

-----

In case of using the WdgIf with state combiner functionality (multi core) it is possible to configure a so called automatic mode for calculating the trigger pattern of the the slaves out of the given parameter from WdgM (configuration values WdgMTriggerWindowStart and WdgMTriggerConditionValue).

In that case the state combiner parameters WdgIfStateCombinerReferenceCycle, WdgIfStateCombinerSlaveIncrementsMin and WdgIfStateCombinerSlaveIncrementsMax can be left empty. The WdgM calls the WdgIf with API WdgIf\_SetTriggerWindow with parameters WdgMDeviceIndex, WdgMTriggerWindowStart and WdgMTriggerTimeout and calculates these values at runtime. However, both given parameters WdgMTriggerWindowStart and WdgMTriggerTimeout are senseless and can be configured arbitrary, because no underlying watchdog device is used - only the state combiner master is connect to a watdog device.

The result is that a necessary safe state is not reached at all or much later than expected.

Example:

-----

The master is configured as follows:  
WdgMTriggerWindowStart: 0ms / 1ms  
WdgMTriggerTimeout: 50ms

The slave is configured as follows:  
WdgMTriggerWindowStart: 0ms / 1ms  
WdgMTriggerTimeout: 20ms

Usually when analyzing these values somebody assume that within 50ms the slave gets 2 or 3 trigger requests. However, with the current implementation of the WdgIf the master checks the slave trigger pattern after 20 master cycles which is 1000ms and expects between 1 and 1000 trigger requests. So if the slave gets triggered once within 1s, the master does not detect any error and continues triggering the underlying watchdog

When does this happen:

-----

This happens if the WdgM detects errors for alive, deadline and / or logical supervision on a "slave core" and discontinues triggering temporarily.

In which configuration does this happen:

-----

This issues does only affect multi-core configurations where:

- /MICROSAR/WdgIf/WdgIfGeneral/WdgIfUseStateCombiner is enabled AND
- /MICROSAR/WdgIf/WdgIfStateCombiner is configured AND
- /MICROSAR/WdgIf/WdgIfStateCombiner/WdgIfStateCombinerGeneral/WdgIfStateCombinerUseManualMode is disabled

### Resolution Description:

<b>ESCAN00093505</b>	<b>Automatic mode for calculating slave trigger pattern may expand time duration for reaching safe state or omit reaching safe state at all</b>
----------------------	---

Workaround:

-----  
Do not use automatic mode. Enable the configuration switch /MICROSAR/WdgIf/WdgIfStateCombiner/WdgIfStateCombinerGeneral/WdgIfStateCombinerUseManualMode and configure all parameters within /MICROSAR/WdgIf/WdgIfStateCombiner/WdgIfStateCombinerSlave.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00093570 Data consistency problems due to usage of wrong interrupt lock APIs	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.07.00
<b>Fixed in versions:</b>	1.14.00, 1.13.01
<b>Problem Description:</b> What happens (symptoms): ----- RTE opens level interrupts within Rte_COMCbk and Rte_LdComCbkRxIndication signal reception callbacks.  If the OS locks the level interrupts for category 2 interrupts, the locking is no longer active during the remaining runtime of the RTE callback and other BSW and OS code that runs within the interrupt service routine that triggered the reception callback.  This means that other interrupts can interrupt the callback and other BSW and OS code, leading to misbehavior (e.g. data consistency problems) when the other modules do not support this use case.  When does this happen: ----- During runtime when a COM or LDCOM callback for queued data reception is called.  In which configuration does this happen: ----- This only happens when the OS provides the optimized MICROSAR APIs osDisableLevelKM/UM/AM. This happens when the configuration contains data elements with queued semantics that are mapped to COM signals or LDCOM PDUs. Moreover for COM signals, the handling of the COM signals needs to be configured to INTERRUPT (not DEFERRED).  Callbacks for which the issue can occur can be identified in the generated RTE code by searching for the string Rte_QAddElement in Rte_COMCbk* or Rte_LdComCbkRxIndication* functions.  The issue can only occur when the called Rte_QAddElement function calls Rte_EnableOSInterrupts() instead of ResumeOSInterrupts().	
<b>Resolution Description:</b> Workaround: ----- Set the preprocessor flag RTE_DISABLE_ENHANCED_INTERRUPT_LOCK_API  Resolution: ----- The described issue is corrected by modification of all affected work-products.	



## ESCAN00093734      **NvM allows to generate NULL\_PTR for explicit synchronization callbacks for blocks with enabled NvMBlockUseSyncMechanism and NvMUseServicePorts**

**Component@Subcomponent:** MemService\_AsrNvM@GenTool\_GeneratorMsr

**First affected version:** 4.02.00

**Fixed in versions:** 4.03.00

### **Problem Description:**

What happens (symptoms):

-----  
NvM accesses a function pointer with value NULL\_PTR. Bad pointer exception/ segmentation fault may occur.

When does this happen:

-----  
When a request accessing the block data is setup (multi or single block read or write request). Because of enabled explicit synchronization mechanism NvM want to invoke the callback from its function pointer which is actually NULL\_PTR.

In which configuration does this happen:

-----  
NvM block with enabled NvMUseServicePorts and enabled NvMBlockUseSyncMechanism but the callbacks NvMReadRamBlockFromNvCallback and NvMWriteRamBlockToNvCallback are still NULL\_PTR or empty. NvSwc is not configured to use explicit synchronization.

### **Resolution Description:**

Workaround:

-----  
If the Explicit Synchronization mechanism is enabled via NvMBlockUseSyncMechanism, both NvMWriteRamBlockToNvCallback and NvMReadRamBlockFromNvCallback has to be configured (!= NULL\_PTR). If NvMUseServicePorts is enabled, the block SWC shall be configured to configure the Explicit Synchronization Callbacks (via RTE). If this is not the case the block shall not use the Explicit Synchronization Mechanism!

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

<b>ESCAN00093745</b>	<b>Data consistency problems because IOC API is called reentrantly in case of IOC queues with queue size 1</b>
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.02.00
<b>Fixed in versions:</b>	1.14.00, 1.13.01
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The call to an IOC API in an Rte_Call API results in data consistency problems.	
When does this happen:	
-----	
During runtime when multiple clients for a server port operation call the server from concurrent tasks in the same partition.	
In which configuration does this happen:	
-----	
This happens when client and server are located in different partitions and when a server port is connected to multiple client ports.	
It happens when client and server are located on different cores and EnforceIOC is set or when the clients are located in multiple partitions.	
This will result in the generation of IocSend calls in the affected Rte_Call APIs.	
The problem only occurs when the server queue size is 1.	
Moreover, this only happens when an operating system is used that does not provide IocSend APIs that are reentrant.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Increase the queue size to 2.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093787      NvM GenTool_GeneratorMsr does not sync block length between NvM und underlying modules	
<b>Component@Subcomponent:</b>	MemService_AsrNvM@GenTool_GeneratorMsr
<b>First affected version:</b>	4.02.01
<b>Fixed in versions:</b>	4.03.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
NvM does not synchronize block length with underlying modules.	
When does this happen:	
-----	
When a NvM block is linked to a Fee/Ea block and its size changes.	
In which configuration does this happen:	
-----	
every	
<b>Resolution Description:</b>	
Workaround:	
-----	
User has to check all Fee/Ea blocks referenced by NvM to be configured correctly - size, priority, datasets.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093999 API GetNumberOfActivatedCores() triggers kernel panic if caller is not trusted.	
<b>Component@Subcomponent:</b>	Os_CoreGen7@Implementation
<b>First affected version:</b>	1.06.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The OS calls kernel panic, if the API GetNumberOfActivatedCores() is called.	
When does this happen:	
-----	
If the caller is not trusted.	
In which configuration does this happen:	
-----	
/MICROSAR/Os/OsOS/OsScalabilityClass = SC3 or SC4	
/MICROSAR/Os/OsOS/OsDebug/OsORTIDebugSupport = ORTI_22_ADDITIONAL or ORTI_23_ADDITIONAL	
<b>Resolution Description:</b>	
Workaround:	
-----	
Do not use ORTI_22_ADDITIONAL or ORTI_23_ADDITIONAL.	
Use ORTI_22_STANDARD or ORTI_23_STANDARD instead.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

## 2.2 Runtime Issues without Workaround

Runtime issues without a workaround require an update of the software delivery in case the issue affects the ECU overall functionality. The effect of an issue to the ECU functionality has to be analyzed by the customer as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.

### Index

<a href="#">ESCAN00087310</a>	P2 timings are not recovered on ECU Reset/Power On (Multi Protocol) Diag_Asr4Dcm@Implementation
<a href="#">ESCAN00091357</a>	EcuM detects the wrong Wakeup Source during startup as the reset reason SysService_Asr4EcuM@Implementation
<a href="#">ESCAN00092861</a>	Status of FeeInstance is determined incorrectly If_AsrIfFeeSmallSector@Implementation
<a href="#">ESCAN00092914</a>	Active protocol is not recovered on ECU Reset/Power On Diag_Asr4Dcm@Implementation

ESCAN00087310 P2 timings are not recovered on ECU Reset/Power On (Multi Protocol)	
<b>Component@Subcomponent:</b>	Diag_Asr4Dcm@Implementation
<b>First affected version:</b>	4.01.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b> What happens (symptoms): ----- ECU operates after reset with the correct session but with P2 timings of the default session.  When does this happen: ----- When a recovery info with a non-default target session is provided by the application during reset.  In which configuration does this happen: ----- - State recovery is supported (i.e. /Dcm/DcmConfigSet/DcmGeneral/DcmStateRecoveryAfterResetEnabled = TRUE) AND - Session specific P2 timings are configured AND - Multi Protocol is supported	
<b>Resolution Description:</b> Workaround: ----- No workaround available.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00091357 EcuM detects the wrong Wakeup Source during startup as the reset reason	
<b>Component@Subcomponent:</b>	SysService_Asr4EcuM@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b> What happens (symptoms): ----- As a consequence of the wrong detected Wakeup Source as reset reason the wrong channel might be woken up. Depending on the configuration it is also possible that no channel is woken up.  When does this happen: ----- At startup of the Ecu.  In which configuration does this happen: ----- Only in configurations with at least one wakeup source with configured parameter ResetReasonRef [EcuM/EcuMConfiguration/EcuMCommonConfiguration/EcuMWakeupSource/EcuMResetReasonRef] AND The Mcu data type Mcu_ResetType is bigger than uint8 (0xFF), e.g. uint16 or uint32.	
<b>Resolution Description:</b> Workaround: ----- No workaround available.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00092861      Status of FeeInstance is determined incorrectly	
<b>Component@Subcomponent:</b>	If_AsrIfFeeSmallSector@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	1.00.02
<b>Problem Description:</b> What happens (symptoms): ----- In some rare cases the content in flash related to a FeeInstance is interpreted incorrectly by SmallSectorFee. Consequently, further processing of this FeeInstance is incorrect. An inconsistent instance may be interpreted erroneously as valid.  When does this happen: ----- If a reset occurs while a FeeBlock is being erased in order to free space for a upcoming write request. This issue only occurs if erase direction of flash device is from back to front. Datasheet does not specify any details about erase direction.  In which configuration does this happen: ----- If FlsBlankCheck API is disabled for the corresponding FeePartitionConfiguration, which should not be the case in usual SmallSectorFee use case (RH850).	
<b>Resolution Description:</b> Workaround: ----- No workaround available.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00092914	Active protocol is not recovered on ECU Reset/ Power On
<b>Component@Subcomponent:</b>	Diag_Asr4Dcm@Implementation
<b>First affected version:</b>	4.01.00
<b>Fixed in versions:</b>	
<p><b>Problem Description:</b></p> <p>What happens (symptoms):</p> <p>-----</p> <p>ECU operates after reset with a wrong protocol ID which leads to one of the following effects:</p> <ul style="list-style-type: none"> <li>- A new request of the tester, which has initiated the reset, is unexpectedly not responded</li> </ul> <p>OR</p> <ul style="list-style-type: none"> <li>- A new request of the tester, which has initiated the reset, is responded with NRC 0x21 (BusyRepeatRequest)</li> </ul> <p>OR</p> <ul style="list-style-type: none"> <li>- A request of a different tester with higher priority does not cancel an ongoing diagnostic service processing</li> </ul> <p>When does this happen:</p> <p>-----</p> <p>At run time (power on/reset) when the API Dcm_GetRecoveryStates returns E_OK (i.e. pre-reset/power-down states of DCM shall be restored).</p> <p>In which configuration does this happen:</p> <p>-----</p> <ul style="list-style-type: none"> <li>- Feature "DCM state recovery on ECU power on/reset" is enabled (parameter "DcmStateRecoveryAfterResetEnabled" is TRUE).</li> </ul> <p>AND</p> <ul style="list-style-type: none"> <li>- More than one protocol is configured (more than one DcmDslProtocolRow is configured)</li> </ul>	
<p><b>Resolution Description:</b></p> <p>Workaround:</p> <p>-----</p> <p>No workaround available.</p> <p>Resolution:</p> <p>-----</p> <p>The described issue is corrected by modification of all affected work-products.</p>	



## 2.3 Runtime Issues with Workaround

It is not recommended to update a delivery due to a runtime issue with a documented workaround. The effect of an issue to the ECU functionality has to be analyzed by the user as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.

### Index

<a href="#">ESCAN00061207</a>	DaVinci Configurator 5: Issue Reporting Procedure GenTool_ConfiguratorCfg5@Application
<a href="#">ESCAN00076256</a>	BswM_CanSM_Indication called with locked interrupts - OS ErrorHook on Os API Invocation Ccl_Asr4SmCan@Implementation
<a href="#">ESCAN00089164</a>	The EcuM stays in RUN state even if EcuM_KillAllRunRequests has been called SysService_Asr4EcuM@Implementation
<a href="#">ESCAN00090885</a>	CAN-FD only: Use different Rx-PDUs with same CAN-ID in FullCAN mailboxes DrvCan__baseAsr@GenTool_GeneratorMsr
<a href="#">ESCAN00091305</a>	EcuM with fixed state machine causes a Det error in Dem_Init because this module has been initialized two times SysService_Asr4EcuM@Implementation
<a href="#">ESCAN00091550</a>	Service 0x27: Dcm allows seed/key attempt earlier as the configured security delay time Diag_Asr4Dcm@GenTool_GeneratorMsr
<a href="#">ESCAN00091756</a>	Random modification of memory Diag_Asr4Dem@GenTool_GeneratorMsr
<a href="#">ESCAN00092745</a>	Missing "if" statement DrvCan_Rh850McanAsr@Implementation
<a href="#">ESCAN00092880</a>	EcuM calls the Mcu_SetMode API with invalid mcu modes SysService_Asr4EcuM@Implementation
<a href="#">ESCAN00093001</a>	CanNm calls Det_ReportError cyclically when not active in a predefined variant (PB-S) Nm_Asr4NmCan@Implementation
<a href="#">ESCAN00093055</a>	Duplicate BlockNumbers are not detected in configuration If_AsrIfFeeSmallSector@GenTool_GeneratorMsr
<a href="#">ESCAN00093185</a>	Wrong behaviour of hierarchically ordered IPduGroups Il_AsrComCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00093263</a>	Missing "if" statement DrvCan_Mpc5700McanLI@Implementation
<a href="#">ESCAN00093335</a>	Service 0x10: Transition to/from FBL without final response Diag_Asr4Dcm@Implementation
<a href="#">ESCAN00093466</a>	Unexpected DET in Dem_DcmDisableDTCRecordUpdate Diag_Asr4Dem@Implementation
<a href="#">ESCAN00093886</a>	Service 0x28: Dcm performs Rte_Switch with a wrong mode from the corresponding CommunicationControl ModeDeclarationGroup Diag_Asr4Dcm@Implementation
<a href="#">ESCAN00093905</a>	Service 0x19: Sub-functions 0x04/0x06/0x10/0x18/0x19 report zero values for snapshot/extended data records Diag_Asr4Dcm@Implementation
<a href="#">ESCAN00093906</a>	ECU returns NRC 0x13 instead of 0x33 or other execution pre-condition related NRC for services with a sub-function parameter Diag_Asr4Dcm@Implementation

ESCAN00061207 DaVinci Configurator 5: Issue Reporting Procedure	
<b>Component@Subcomponent:</b>	GenTool_ConfiguratorCfg5@Application
<b>First affected version:</b>	5.00.01
<b>Fixed in versions:</b>	
<b>Problem Description:</b> This ticket describes the reporting of DaVinci Configurator 5 issues. This ticket is a general information and not an issue. ----- Issues of the DaVinci Configurator 5 tool are not part of the active issue reporting (i.e. this report). The DaVinci Configurator 5 issue list can be downloaded from our home page: DaVinci Developer OpenIssue Lists: <a href="https://portal.vector.com/web/davinci/shared-folder?t=c2b431ff-5dae-4a72-83ec-b9c8ca17561c">https://portal.vector.com/web/davinci/shared-folder?t=c2b431ff-5dae-4a72-83ec-b9c8ca17561c</a> DaVinci Configurator OpenIssue Lists: <a href="https://portal.vector.com/web/davinci/shared-folder?t=15d156f3-65d3-4b6e-8107-ec44051aebff">https://portal.vector.com/web/davinci/shared-folder?t=15d156f3-65d3-4b6e-8107-ec44051aebff</a>	
<b>Resolution Description:</b> Workaround: ----- This is not an issue but only a reference to the tool specific issue reporting. No changes to the delivery required.	

## ESCAN00076256 BswM\_CanSM\_Indication called with locked interrupts - OS ErrorHook on Os API Invocation

**Component@Subcomponent:** Ccl\_Asr4SmCan@Implementation

**First affected version:** 2.00.00

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

-----  
Symptom 1)

OS API Invocation ends up with a call to ErrorHook.

Error Cause of this ErrorHook is that OS API is called whereas Interrupts are locked.

Errorcodes would then be:

osdErrATIntAPIDisabled 0x1104U,  
osdErrHTMultipleActivation 0x1305U,  
osdErrSEIntAPIDisabled 0x4105U,  
osdErrSECallContext 0x4106U or  
osdErrWEInterruptsDisabled 0x4403U

Symptom 2)

Rte Runnable that is triggered on TxError will not be called when Communication is shut down and Sending Request is outstanding

When does this happen:

-----  
every time function "BswM\_CanSM\_Indication" ends up in an Os API Invocation (for example BswM Rule to stop Ipdu Groups AND a transmission is still ongoing AND TxError is configured to trigger a runnable in the Rte)

AND

the function "BswM\_CanSM\_Indication" is called with locked interrupts (Transition to NO\_COMMUNICATION)

In which configuration does this happen:

-----  
If any BswM rule (which belongs to a BswM\_CanSM\_Indication), is configured as immediate AND

an OS function is called within the call context of the BswM rule

AND

this OS function must not be called with locked interrupts.

e.g.

Std Rules in BswM are configured

AND

A Rte Runnable is triggered on Tx Error

AND

Osek OS which implements the requirement "If ActivateTask / SetEvent is called with locked Interrupts, reject the action and call an ErrorHook" is used (for example Vector Os)

### Resolution Description:

Workaround:

-----  
Configure the BswM Rule as deferred

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

<b>ESCAN00089164</b>	<b>The EcuM stays in RUN state even if EcuM_KillAllRunRequests has been called</b>
<b>Component@Subcomponent:</b>	SysService_Asr4EcuM@Implementation
<b>First affected version:</b>	3.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The ECU stays in RUN state, even if anyone has called the API EcuM_KillAllRunRequests.	
When does this happen:	
-----	
Always after EcuM_KillAllRunRequests() has been called and at least one channel is in a state unequal COMM_NO_COM_NO_PENDING_REQUEST.	
In which configuration does this happen:	
-----	
Only in configurations with ECUM_FIXED_BEHAVIOR is active (EcuM/EcuMGeneral/EcuMEnableFixBehavior).	
<b>Resolution Description:</b>	

## ESCAN00089164 The EcuM stays in RUN state even if EcuM\_KillAllRunRequests has been called

Workaround:

-----  
The following shows a possible workaround to ignore all ComM channel states in case of an active KillAllRunRequests.

Hint: EcuM\_SetWakeupEvent considers wakeup events even if EcuM\_KillAllRunRequests() was called. This might cause that the EcuM transits from PostRun to Run again, because of a new occurred wakeup event.

The call of the API ComM\_GetState() has to be mapped to an application function in case that it is called in context of EcuM.c. This can be done by configure the following header file as a User Configuration file in the EcuM configuration (EcuM/EcuMGeneral/EcuMUserConfigurationFile):

- Example Appl\_ComM\_EcuM.h:

```
#if defined (ECUM_SOURCE)
extern Std_ReturnType Appl_ComM_GetState(const NetworkHandleType Channel,
ComM_StateType* State);
```

```
# define ComM_GetState Appl_ComM_GetState
#endif
```

- Example Appl\_ComM\_EcuM.c:

```
#include "Std_Types.h"
#include "ComM.h"
```

```
#define ECUM_PRIVATE_CFG_INCLUDE
#include "EcuM_PrivateCfg.h"
#undef ECUM_PRIVATE_CFG_INCLUDE
```

```
Std_ReturnType Appl_ComM_GetState(const NetworkHandleType Channel, ComM_StateType*
State)
{
    Std_ReturnType retVal = E_OK;
    /* Verify that EcuM_KillAllRunRequests() was not called */
    if ((EcuM_GetKillAllInProgress() & (0x01u)) == 0u)
    {
        retVal = ComM_GetState(Channel, State);
    }
    else
    {
        /* In case of an active KillAllRunRequest, set the virtual ComM State to no communication and no
        request. */
        *State = COMM_NO_COM_NO_PENDING_REQUEST;
    }

    return retVal;
}
```

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00090885      CAN-FD only: Use different Rx-PDUs with same CAN-ID in FullCAN mailboxes	
<b>Component@Subcomponent:</b>	DrvCan__baseAsr@GenTool_GeneratorMsr
<b>First affected version:</b>	4.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b> What happens (symptoms): ----- Message will not be received (filtered by CanIf due to wrong CAN-FD type) --> This is an invalid configuration !!! (but currently not secured by validator)  When does this happen: ----- Always and immediately during runtime.  In which configuration does this happen: ----- CAN-FD messages are used AND two messages/PDUs with same CAN-ID are used (one Classic CAN and one CAN FD) AND these two or at least one of the messages are configured as FullCAN	
<b>Resolution Description:</b> Workaround: ----- do not use PDUs with same CAN-IDs as FullCAN  Resolution: ----- The described issue is corrected by modification of all affected work-products. - Add validator to avoid this invalid configuration	

## ESCAN00091305 EcuM with fixed state machine causes a Det error in Dem\_Init because this module has been initialized two times

**Component@Subcomponent:** SysService\_Asr4EcuM@Implementation

**First affected version:** 3.00.00

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

-----  
In some situations the EcuM with fixed state machine calls Dem\_Init() two times, this lead to a Det error thrown by the Dem with the message DEM\_E\_WRONG\_CONDITION,

When does this happen:

-----  
During runtime of the EcuM API EcuM\_StartupTwo().

In which configuration does this happen:

-----  
All of the following conditions have to be fulfilled to be affected by this issue:

- The Ecum with fixed state machine has to be active (EcuM/EcuMGeneral/EcuMEnableFixBehavior).
- The include Dem has to be active (EcuM/EcuMFixedGeneral/EcuMIncludeDem).
- At least one wakeup source has to be configured for wakeup validation (EcuM/EcuMConfiguration/EcuMCommonConfiguration/EcuMWakeupSource/EcuMValidationTimeout).
- At startup the standard wakeup source (ECUM\_WKSOURCE\_RESET) has to be cleared via the API EcuM\_ClearWakeupEvent() to force a wakeup validation after startup and to prevent a transition to RUN state until this wakeup source is validated.

### Resolution Description:

Workaround:

-----  
In case that the valid wakeup event during initialization (ECUM\_WKSOURCE\_RESET) is cleared in context of driver init list two or three and a wakeup event for validation is set the Dem\_Init call has to be avoided.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

**ESCAN00091550      Service 0x27: Dcm allows seed/key attempt earlier as the configured security delay time****Component@Subcomponent:** Diag\_Asr4Dcm@GenTool\_GeneratorMsr**First affected version:** 1.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----

A security delay time expires too early. Dcm accepts new seed requests before the configured delay time is expired.

When does this happen:

-----

If after last unsuccessful attempt responded with Nrc 0x36 (exceededNumberOfAttempts) a new seed request is sent before the expected delay time.

In which configuration does this happen:

-----

- Service 0x27 is supported

AND

- There is more than one security level configured

AND

- Any delay time is configured for any security level (in Dcm\_Cfg.h:

DCM\_STATE\_SEC\_RETRY\_ENABLED == STD\_ON or

DCM\_STATE\_SEC\_DELAY\_ON\_BOOT\_ENABLED == STD\_ON)

AND

- The dividend of a configured security delay time (in milliseconds) and the task cycle (also in milliseconds) is greater than 65535

**Resolution Description:**

Workaround:

-----

The equation shall become true: ( $\text{<TimeParameter>} / \text{DcmTaskTime}$ ) < 63535.

Therefore, the following workarounds are possible:

1) Increase the DcmTaskTime parameter value.

OR

2) Reduce the timeout value in the corresponding timing parameter.

Resolution:

-----

The described issue is corrected by modification of all affected work-products.



**ESCAN00091756 Random modification of memory****Component@Subcomponent:** Diag\_Asr4Dem@GenTool\_GeneratorMsr**First affected version:** 6.00.00**Fixed in versions:** 10.00.00**Problem Description:**

What happens (symptoms):

-----  
Memory corruption due to function argument mismatch.

The RTE port interface operation is defined incorrectly:

wrong: Std\_ReturnType &lt;&gt;(uint8\* data, Dem\_EventIdType EventId)

expected: Std\_ReturnType &lt;&gt;(Dem\_EventIdType EventId, uint8\* data)

Due to the switched argument position, the event ID is passed in place of the destination pointer, leading to random memory modification.

When does this happen:

-----  
Depending on configuration of Dem/DemGeneral/DemDataElement/  
DemExternalCSDataElementClass/DemDataElementStoreNonVolatile  
the issue will trigger when an event is stored in the event memory, or when a diagnostic service requests event data using service 19 04 or 19 06

In which configuration does this happen:

-----  
Dem/DemGeneral/DemUseRte == TRUE  
AND  
Dem/DemGeneral/DemDataElement/DemExternalCSDataElementClass/DemDataElementUsePort == TRUE  
AND  
Dem/DemGeneral/DemDataElement/DemExternalCSDataElementClass/  
DemUseEventIdArgumentForCallback == TRUE**Resolution Description:**

Workaround:

-----  
Set Dem/DemGeneral/DemDataElement/DemExternalCSDataElementClass/  
DemDataElementUsePort == FALSE and provide a wrapper function in Dem/DemGeneral/  
DemDataElement/DemExternalCSDataElementClass/DemDataElementReadFnc  
The wrapper function can call the application port interface with the correct order of arguments.

e.g.

Std\_ReturnType ApplWrapper(Dem\_EventIdType EventId, uint8\* Data)  
{  
  return Rte\_Call\_<ApplicationPortInterfaceName>(Data, EventId);  
}

Please note, the issue correction will change the port interface description as defined in the technical reference. The application SWC interface needs to be adapted accordingly.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

## ESCAN00092745 Missing "if" statement

**Component@Subcomponent:** DrvCan\_Rh850McanAsr@Implementation

**First affected version:** 2.09.00

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

-----  
The transition to "Start" or "Stop" Mode is returned erroneously as "Done" to upper layers.  
E.g. the MCAN can still be active with pending Tx requests although Stop Mode reached is notified.

When does this happen:

-----  
At run time.

In which configuration does this happen:

-----  
Only for AutoSar 4.x  
AND  
MCAN Revision 2.x, 3.0.0, 3.0.1  
AND  
CAN\_BOSCH\_ERRATUM\_008 == STD\_ON.

### Resolution Description:

Workaround:

-----  
Enable "Hardware Loop Check by application" and check for timeout notifications for  
"kCanLoopStart"/"kCanLoopStop".  
If a timeout appears the requested mode change must be repeated.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00092880 EcuM calls the Mcu_SetMode API with invalid mcu modes	
<b>Component@Subcomponent:</b>	SysService_Asr4EcuM@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The Mcu_SetMode API is called with a wrong mcu mode which can lead to an array out of bounds write access.	
When does this happen:	
-----	
During sleep phases.	
In which configuration does this happen:	
-----	
In configurations with at least one sleep mode [EcuM/EcuMConfiguration/ EcuMCommonConfiguration/EcuMSleepMode]	
AND	
The Mcu_ModeType values start with 0 instead of 1.	
<b>Resolution Description:</b>	

## ESCAN00092880 EcuM calls the Mcu\_SetMode API with invalid mcu modes

Workaround:

-----  
The Mcu\_SetMode API is called inside the callout EcuM\_McuSetMode with the passed (and potentially wrong) McuMode.

To avoid passing the wrong mode to the Mcu the callout EcuM\_McuSetMode can be adapted like the following:

```
FUNC(void, ECUM_CODE) EcuM_McuSetMode(Mcu_ModeType McuMode)
{
/
*****

* DO NOT CHANGE THIS COMMENT! <USERBLOCK EcuM_McuSetMode> DO NOT CHANGE THIS
COMMENT!

*****

/* Add implementation of EcuM_McuSetMode() */

if(McuMode == 0)
{
Mcu_SetMode(McuConf_McuModeSettingConf_McuModeSettingConf); // <=== Use symbolic
names provided by the Mcu here.
}

return;
/
*****

* DO NOT CHANGE THIS COMMENT! </USERBLOCK> DO NOT CHANGE THIS COMMENT!

*****

} /* End of EcuM_McuSetMode() */
```

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

## ESCAN00093001 CanNm calls Det\_ReportError cyclically when not active in a predefined variant (PB-S)

**Component@Subcomponent:** Nm\_Asr4NmCan@Implementation

**First affected version:** 5.00.00

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

-----  
CanNm calls Det\_ReportError() cyclically with the following parameters:

ModuleId 0x1f, InstanceId 0x0, ApiId 0x13, ErrorId 0x1  
(errorId = CANNM\_E\_NO\_INIT)

The ECU is not blocked.

The CanNm behaves properly according to the selected variant.

When does this happen:

-----  
Always during runtime every time the CanNm\_Mainfuncation is called by the OS.

In which configuration does this happen:

- - /MICROSAR/EcuC/EcucGeneral/EcuCSafeBswChecks == ON  
AND  
- In Postbuild-Selectable configurations, with at least two predefined variants  
AND  
- CanNm is not active in one variant  
AND  
- The predefined variant where the CanNm is not active, is the currently running one.

### Resolution Description:

Workaround:

-----  
This Det\_ReportError call can be ignored.

Permanently filter this Det\_ReportError call in the Det component.  
Refer to the Technical Reference of the Det for further information.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00093055 Duplicate BlockNumbers are not detected in configuration	
<b>Component@Subcomponent:</b>	If_AsrIfFeeSmallSector@GenTool_GeneratorMsr
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	1.01.00
<b>Problem Description:</b> What happens (symptoms): ----- A BlockNumber uniquely identifies a block in FeeBlockConfiguration. If a BlockNumber is duplicate, FEE may perform a requested job for the wrong block. In case both blocks have different block lengths, the job request will be declined due to failed development checks.  When does this happen: ----- When BlockNumbers are modified manually via "Set User Defined" attribute in configuration and two (or more) blocks share the same BlockNumber.  In which configuration does this happen: ----- Every configuration using CFG5 5.14.00 and later.	
<b>Resolution Description:</b> Workaround: ----- BlockNumbers can be modified manually via "Set User Defined" attribute. Make sure that no BlockNumber occurs twice.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

## ESCAN00093185 Wrong behaviour of hierarchically ordered IPduGroups

**Component@Subcomponent:** Il\_AsrComCfg5@GenTool\_GeneratorMsr

**First affected version:** 4.00.00

**Fixed in versions:** 12.00.00

### Problem Description:

What happens (symptoms):

-----  
 Activating/ deactivating a parent ComIPduGroup with Com\_IpduGroupStart, Com\_IpduGroupStop has no influence the ComIPdu of the sub I-PduGroups..  
 Starting/ stopping the reception deadline monitoring with Com\_EnableReceptionDM, Com\_DisableReceptionDM will not start/stop the reception deadline monitoring of ComIPdu's which are referred by the Sub-ComIPduGroups of a parent ComIPduGroup.

When does this happen:

-----  
 This issue will occur whenever Com\_IpduGroupStart, Com\_IpduGroupStop is called for a parent ComIPduGroup of hierarchically ordered IPduGroups at runtime.

OR

This issue will occur whenever Com\_EnableReceptionDM, Com\_DisableReceptionDM is called for a parent ComIPduGroup of hierarchically ordered IPduGroups at runtime.

In which configuration does this happen:

-----  
 ComOptimizedIPduGroupHandling == ON

AND

ComIPduGroups are hierarchically ordered (/MICROSAR/Com/ComConfig/ComIPduGroup/ComIPduGroupGroupRef is configured).

### Resolution Description:

Workaround:

-----  
 Deactivate /MICROSAR/Com/ComGeneral/ComOptimizedIPduGroupHandling .

Resolution:

-----  
 The described issue is corrected by modification of all affected work-products.

ESCAN00093263 Missing "if" statement	
<b>Component@Subcomponent:</b>	DrvCan_Mpc5700McanLI@Implementation
<b>First affected version:</b>	2.08.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The transition to "Start" or "Stop" Mode is returned erroneously as "Done" to upper layers. E.g. the MCAN can still be active with pending Tx requests although Stop Mode reached is notified.	
When does this happen:	
-----	
At run time.	
In which configuration does this happen:	
-----	
Only for AutoSar 4.x AND MCAN Revision 2.x, 3.0.0, 3.0.1 AND CAN_BOSCH_ERRATUM_008 == STD_ON.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Enable "Hardware Loop Check by application" and check for timeout notifications for "kCanLoopStart"/"kCanLoopStop". If a timeout appears the requested mode change must be repeated.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	



**ESCAN00093335      Service 0x10: Transition to/from FBL without final response****Component@Subcomponent:** Diag\_Asr4Dcm@Implementation**First affected version:** 1.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----

The ECU does not final positive response for diagnostic service 0x10 (DiagnosticSessionControl) after switching into or from the FBL software.

Note:

This could happen only very rarely or on each diagnostic request of the above described kind. It mainly depends on the Dcm\_MainFunction() scheduling.

When does this happen:

-----

At runtime when:

- Service 0x10 with FBL related diagnostic session is requested with set SPRMIB = TRUE (SuppressPositiveResponseMessageIndicationBit).

AND

- The Dcm\_MainFunction(Worker)() is not called within the P2server time (i.e. a RCR-RP could be sent prior execution of service 0x10 has started).

In which configuration does this happen:

-----

- DCM is configured to not send final response prior switching to/from FBL (DCM ECUC parameter of all DcmDslProtocolRows: DcmSendRespPendOnTransToBoot == FALSE, resp. in Dcm\_Cfg.h #define DCM\_DIAG\_RCRRP\_ON\_BOOT\_ENABLED == STD\_OFF)

- DCM is configured to not send any RCR-RP prior switching to/from FBL (DCM ECUC parameter DcmFinalResponseToFblEnabled == FALSE, resp. in Dcm\_Cfg.h #define DCM\_SVC\_10\_RST2BOOT\_HIS\_ENABLED == STD\_ON)

AND

- DCM is configured to have two main-functions (DCM ECUC parameter DcmSplitTasksEnabled == TRUE, resp. in Dcm\_Cfg.h #define DCM\_SPLIT\_TASKS\_ENABLED == STD\_ON)

AND

- The scheduling time of the Dcm\_MainFunctionWorker exceeds any P2server time.

(DCM ECUC parameters are in relation: DcmMainFunctionWorkerTaskTime >

(DcmDspSessionP2ServerMax - DcmTimStrP2ServerAdjust) for at least one session/diagnostic protocol combination)

OR

- Due to heavy CPU load, the execution of Dcm\_MainFunctionWorker() is delayed for a time exceeding the P2server for the current request.

**Resolution Description:**

## **ESCAN00093335      Service 0x10: Transition to/from FBL without final response**

Workaround:

-----  
Possible workarounds:

- 1) If there is a requirement to not send any RCR-RP prior FBL-application software switch, then assure (via task priorities, task cycle times) that DCM will never delay the service 0x10 processing prior resetting the ECU. In other words, the ECU shall be reset in any case within the P2server time.
- 2) If for some integration reasons this is not possible to guarantee the runtime needed till reset, then the configured option "DcmSendRespPendOnTransToBoot" obviously does not make any sense, since sometime there still will be a RCR-RP sent. To make the ECU behavior deterministic, do enable the RCR-RP prior reset option (DcmSendRespPendOnTransToBoot = TRUE).

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00093466	Unexpected DET in Dem_DcmDisableDTCRecordUpdate
<b>Component@Subcomponent:</b>	Diag_Asr4Dem@Implementation
<b>First affected version:</b>	7.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
DET call DEM_DCMDISABLEDTCRECORDUPDATE_APIID, error code DEM_E_WRONG_CONDITION	
Depending on DET configuration, the task calling Dem_DcmDisableDTCRecordUpdate will block	
due to an endless loop in the DET module.	
This can cause unrepsonsive diagnostics or ECU reset by watchdog.	
When does this happen:	
-----	
When processing a diagnostic service 19 04, 19 06, 19 11 or 19 12,	
such that Dem_DcmEnableDTCRecordUpdate is called after a call to	
Dem_DcmDisableDTCRecordUpdate, but before the Dem task was executed at least once.	
This can happen when the Dem task schedule is larger than the Dcm, or in multi-protocol use-	
cases where a high priority request cancels an ongoing diagnostic request before the Dem main	
function was called.	
In which configuration does this happen:	
-----	
The Dcm supports protocol cancellation	
OR	
The BSW task scheduling allows for a situation in which the Dcm will cancel a started request	
before the Dem task was executed.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Ignore the DET report	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

## ESCAN00093886 Service 0x28: Dcm performs Rte\_Switch with a wrong mode from the corresponding CommunicationControl ModeDeclarationGroup

**Component@Subcomponent:** Diag\_Asr4Dcm@Implementation

**First affected version:** 7.01.00

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

Depending on the application use of the CommunicationControl ModeDeclarationGroup, the result of the notification with an unexpected mode can vary. Here some examples:

- If the provided by DCM notification is not used by any SW-C, nothing happens (i.e. issue ticket can be ignored)

or

- If the application evaluates the new communication control mode, wrong action will be executed once the new communication control mode is received in the SW-C.

The following mapping applies here:

Value Expected (Correct) -> Received (Wrong)

0	ENABLE_RX_TX_NORM	DISABLE_RX_ENABLE_TX_NORM_NM
1	ENABLE_RX_DISABLE_TX_NORM	DISABLE_RX_TX_NM
2	DISABLE_RX_ENABLE_TX_NORM	ENABLE_RX_DISABLE_TX_NORM
3	DISABLE_RX_TX_NORMAL	ENABLE_RX_TX_NM
4	ENABLE_RX_TX_NM	ENABLE_RX_DISABLE_TX_NORM_NM
5	ENABLE_RX_DISABLE_TX_NM	DISABLE_RX_ENABLE_TX_NM
6	DISABLE_RX_ENABLE_TX_NM	ENABLE_RX_TX_NORM
7	DISABLE_RX_TX_NM	DISABLE_RX_TX_NORMAL
8	ENABLE_RX_TX_NORM_NM	DISABLE_RX_TX_NORM_NM
9	ENABLE_RX_DISABLE_TX_NORM_NM	ENABLE_RX_TX_NORM_NM
10	DISABLE_RX_ENABLE_TX_NORM_NM	DISABLE_RX_ENABLE_TX_NORM
11	DISABLE_RX_TX_NORM_NM	ENABLE_RX_DISABLE_TX_NM

When does this happen:

Each time one of the following events occurs:

- The ECU (re-)enters default diagnostic session: the application gets notified for entering mode DISABLE\_RX\_TX\_NORM\_NM instead of ENABLE\_RX\_TX\_NORM\_NM.
- Each time a valid request for diagnostic service 0x28 is received and processed without any detected errors, the new mode sent to the application will not match the requested new communication state. (see mapping table above)

In which configuration does this happen:

Service 0x28 is internally handled by DCM (in Dcm\_Cfg.h #define DCM\_SVC\_28\_SUPPORT\_ENABLED is generated to be STD\_ON)

### Resolution Description:

## **ESCAN00093886      Service 0x28: Dcm performs Rte\_Switch with a wrong mode from the corresponding CommunicationControl ModeDeclarationGroup**

Workaround:

-----  
Using the provided information on the main page, implement a mapping table to convert the wrong mode passed by DCM. Apply this mapping in all affected SW-Cs.

Example implementation:

```
#include Dcm.h
const Rte_ModeType_DcmCommunicationControl Dcm_ComCtrlModeMap_ESCAN00093886[] =
{
    RTE_MODE_DcmCommunicationControl_DCM_DISABLE_RX_ENABLE_TX_NM
    ,RTE_MODE_DcmCommunicationControl_DCM_DISABLE_RX_ENABLE_TX_NORM
    ,RTE_MODE_DcmCommunicationControl_DCM_DISABLE_RX_ENABLE_TX_NORM_NM
    ,RTE_MODE_DcmCommunicationControl_DCM_DISABLE_RX_TX_NM
    ,RTE_MODE_DcmCommunicationControl_DCM_DISABLE_RX_TX_NORMAL
    ,RTE_MODE_DcmCommunicationControl_DCM_DISABLE_RX_TX_NORM_NM
    ,RTE_MODE_DcmCommunicationControl_DCM_ENABLE_RX_DISABLE_TX_NM
    ,RTE_MODE_DcmCommunicationControl_DCM_ENABLE_RX_DISABLE_TX_NORM
    ,RTE_MODE_DcmCommunicationControl_DCM_ENABLE_RX_DISABLE_TX_NORM_NM
    ,RTE_MODE_DcmCommunicationControl_DCM_ENABLE_RX_TX_NM
    ,RTE_MODE_DcmCommunicationControl_DCM_ENABLE_RX_TX_NORM
    ,RTE_MODE_DcmCommunicationControl_DCM_ENABLE_RX_TX_NORM_NM
};
```

Usage:

```
void ApplFunctionUsingComControlModes(void)
{
    Rte_ModeType_DcmCommunicationControl newMode;

    Rte_Read_<SwcA>_CommControl_Can0(&newMode);

    DoSomethingWithNewMode(Dcm_ComCtrlModeMap_ESCAN00093886[newMode]);
}
```

Note:

Once this issue is resolved, this workaround mapping table can be removed for ROM/runtime efficiency, but even if left inside the code, will represent a 1:1 mapping, so it the adapted SW-C must not necessarily be adapted again.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

<b>ESCAN00093905</b>	<b>Service 0x19: Sub-functions 0x04/0x06/0x10/0x18/0x19 report zero values for snapshot/extended data records</b>
<b>Component@Subcomponent:</b>	Diag_Asr4Dcm@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Positive responses for diagnostic service 0x19 sub-functions 0x04/0x06/0x10/0x18/0x19 report zero values for snapshot/extended data records.	
The correct behavior of the ECU shall be to interrupt the response transmission for lack of further response data. The issue here is that the zero value might be interpreted as real EDR (ExtendedDataRecord) / SSR (SnapshotRecord) data and mislead the ECU's fault analysis.	
When does this happen:	
-----	
At runtime when	
- Requesting one of the above listed sub-functions	
AND	
- The DEM reports initially to DCM a size of the EDR/SSR to be reported different from the later reported actual EDR/SSR sizes. Note: This happens if the DEM implementation reports initially the record size without considering whether all data within the record is available, but takes the configured maximum possible EDR/SSR size.	
In which configuration does this happen:	
-----	
- Dcm is configured to use paged-buffer responses for service 0x19 (in Dcm_Cfg.h #define DCM_DEM_API_PAGED_BUFFER_ENABLED is set to STD_ON && #define DCM_PAGED_BUFFER_ENABLED is set to STD_ON) AND	
- Diagnostic service 0x19 with any of the sub-functions 0x04/0x06/0x10/0x18/0x19 is supported by the ECU. (in the Dcm_Cfg.h any of the #defines DCM_SVC_19_XX_SUPPORT_ENABLED (XX is the sub-function ID above) is generated to STD_ON)	
<b>Resolution Description:</b>	
Workaround:	
-----	
Switch back to linear buffer response transmission.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

## ESCAN00093906 ECU returns NRC 0x13 instead of 0x33 or other execution pre-condition related NRC for services with a sub-function parameter

**Component@Subcomponent:** Diag\_Asr4Dcm@Implementation

**First affected version:** 1.00.00

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

ECU returns NRC 0x13 instead of 0x33 or other execution pre-condition related NRC for services with a sub-function parameter.

When does this happen:

Each time a diagnostic client requests a service that:

- supports sub-function parameter (e.g. SID 0x10 (DiagnosticSessionControl) )

AND

- The requested sub-function is a valid one, but:

- not supported in the currently active security level

OR

- not allowed under currently active ECU project specific sub-function related pre-conditions (i.e. modeled via DcmModeRules)

AND

- the request length is not valid for the sub-function

In which configuration does this happen:

For any diagnostic service that has sub-functions supported in different security levels resp. different DcmModeRule pre-conditions.

Example:

- ECU is configured to support the following security levels: locked, level X.

- Service 0x10 has following sub-functions (SF): 0x01 and 0x02.

This issue will occur if:

- SF 0x01 is allowed in all security levels (locked one inclusively) i.e. has no security restrictions

- SF 0x02 is allowed only once security access level X is enabled

Any request for service 0x10 0x02 with any wrong length more than two bytes, while the ECU is locked, will result in NRC 0x13 (ICMLOF) instead of 0x33 (SAD).

Please note:

This issue will not occur if:

- All SID 0x10 sub-functions have the same diagnostic security access execution precondition dependency e.g. allowed only in the security level X. In this case not only the sub-functions but the SID 0x10 itself will not be supported in the security access locked level. This will result in NRC 0x33 (SAD), which is no deviation of the ISO specification.

### Resolution Description:

ESCAN00093906	ECU returns NRC 0x13 instead of 0x33 or other execution pre-condition related NRC for services with a sub-function parameter
<p>Workaround:</p> <p>-----</p> <p>Avoid sub-function related security level resp. DcmModeRule execution precondition dependencies. Let the complete service (at SID level) be restricted via security level resp. DcmModeRule execution pre-condition.</p>	
<p>Resolution:</p> <p>-----</p> <p>The described issue is corrected by modification of all affected work-products.</p>	

## 2.4 Not Released Functionality

Not released functionalities (BETA) are either complete software modules or features in the software module that have not yet passed a complete development cycle (they are e.g. not or only partly tested). If a BETA issue ticket affects a complete software module, the software module must not be used for serial production. If a BETA issue ticket affects a feature in the software module, the user has to ensure that all BETA features are disabled as indicated for the serial production release of the ECU.

### Index

<a href="#">ESCAN00084471</a>	BETA version - the BSW module has a feature with BETA state (FEAT-1093) Rte_Core@Implementation
<a href="#">ESCAN00087538</a>	BETA version - the module is in BETA state Rte_Analyzer@Application
<a href="#">ESCAN00088830</a>	BETA Feature - Memory Protection in trusted applications is only provided as a BETA feature Os_CoreGen7@Implementation
<a href="#">ESCAN00089701</a>	BETA Feature - Executing trusted applications in non privileged mode is only provided as a BETA feature. Os_CoreGen7@Implementation
<a href="#">ESCAN00090942</a>	BETA version - the BSW module has a feature with BETA state (FEAT-1914) If_AsrIfCan@Implementation
<a href="#">ESCAN00091204</a>	BETA version - the Nm module has a feature with BETA state (FEAT-1865) Nm_Asr4NmIf@Implementation
<a href="#">ESCAN00091210</a>	BETA version - the BSW module has a feature with BETA state (FEAT-1726) Rte_Core@Implementation
<a href="#">ESCAN00091218</a>	BETA version - the BSW module has a feature with BETA state (FEAT-371) Diag_Asr4Dcm@Implementation
<a href="#">ESCAN00091231</a>	BETA version - the BSW module has a feature with BETA state (FEAT-1899) Diag_Asr4Dcm@GenTool_GeneratorMsr
<a href="#">ESCAN00092471</a>	BETA version - the BSW module has a feature with BETA state (FEAT-1454) SysService_Asr4EcuM@GenTool_GeneratorMsr
<a href="#">ESCAN00092764</a>	BETA version - the BSW module has a feature with BETA state (FEAT-1454) Ccl_Asr4ComMCfg5@Implementation
<a href="#">ESCAN00092868</a>	BETA version - the BSW module is in BETA state DrvCry_Rh850Icum@Implementation



## ESCAN00084471 BETA version - the BSW module has a feature with BETA state (FEAT-1093)

**Component@Subcomponent:** Rte\_Core@Implementation

**First affected version:** 1.08.00

**Fixed in versions:**

### Problem Description:

What is the impact of BETA software:

-----  
BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

-----  
The following feature/function is in BETA state.

- FEAT-1093: Support of different strategies for writing NV data in Nv Block SWCs

To ensure that only productive code is used verify that:

- no cyclic or on data reception triggered runnables in a Nv Block SWC are used

### Resolution Description:

## ESCAN00087538 BETA version - the module is in BETA state

**Component@Subcomponent:** Rte\_Analyzer@Application

**First affected version:** 0.05.00

**Fixed in versions:**

### Problem Description:

What is the impact of BETA software:

-----  
BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

-----  
The complete module is in BETA state

### Resolution Description:

<b>ESCAN00088830      BETA Feature - Memory Protection in trusted applications is only provided as a BETA feature</b>	
<b>Component@Subcomponent:</b>	Os_CoreGen7@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b> What is the impact of BETA software: ----- BETA feature: - must not be used in productive projects as they may result in unpredictable ECU behavior - may not provide all features intended for the productive project - is not tested and not all quality measures have taken place  Which functionality is BETA: ----- The following feature/function is in BETA state. - Memory Protection in trusted applications.  To ensure that only productive code is used verify that: - OsTrustedApplicationWithProtection is false for all applications.	
<b>Resolution Description:</b> Workaround: ----- Do not use memory protection for trusted.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00089701</b>	<b>BETA Feature - Executing trusted applications in non privileged mode is only provided as a BETA feature.</b>
<b>Component@Subcomponent:</b>	Os_CoreGen7@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What is the impact of BETA software:	
-----	
BETA feature:	
<ul style="list-style-type: none"> <li>- must not be used in productive projects as they may result in unpredictable ECU behavior</li> <li>- may not provide all features intended for the productive project</li> <li>- is not tested and not all quality measures have taken place</li> </ul>	
Which functionality is BETA:	
-----	
The following feature/function is in BETA state.	
<ul style="list-style-type: none"> <li>- Executing trusted applications in non privileged mode is implemented as a BETA feature:</li> </ul>	
To ensure that only productive code is used verify that:	
<ul style="list-style-type: none"> <li>- IsPrivileged is TRUE for all trusted applications</li> </ul>	
<b>Resolution Description:</b>	
API Extensions:	
-----	
No extension of the API.	
API Changes:	
-----	
No modification of the API.	
Module handling changes:	
-----	
No modification of the module handling.	
For a detailed description of the API and the handling of the module refer to the Technical Reference.	

<b>ESCAN00090942      BETA version - the BSW module has a feature with BETA state (FEAT-1914)</b>	
<b>Component@Subcomponent:</b>	If_AsrIfCan@Implementation
<b>First affected version:</b>	6.11.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
<p>What is the impact of BETA software:</p> <p>-----</p> <p>BETA software</p> <ul style="list-style-type: none"> <li>- must not be used in productive projects as they may result in unpredictable ECU behavior</li> <li>- may not provide all features intended for the productive project</li> <li>- is not or only partly tested and not all quality measures have taken place</li> </ul> <p>Which functionality is BETA:</p> <p>-----</p> <p>The following feature/function is in BETA state.</p> <ul style="list-style-type: none"> <li>- Data checksum (Rx and Tx)</li> </ul> <p>To ensure that only productive code is used verify that:</p> <ul style="list-style-type: none"> <li>- Following parameters disabled in configuration tool:</li> </ul> <p>/MICROSAR/CanIf/CanIfPrivateCfg/CanIfDataChecksumTxSupport</p> <p>/MICROSAR/CanIf/CanIfPrivateCfg/CanIfDataChecksumRxSupport</p> <p>or CanIf_Cfg.h:</p> <ul style="list-style-type: none"> <li>- CANIF_DATA_CHECKSUM_RX_SUPPORT STD_OFF</li> <li>- CANIF_DATA_CHECKSUM_TX_SUPPORT STD_OFF</li> </ul>	
<b>Resolution Description:</b>	

## ESCAN00091204 BETA version - the Nm module has a feature with BETA state (FEAT-1865)

**Component@Subcomponent:** Nm\_Asr4NmIf@Implementation

**First affected version:** 10.00.00

**Fixed in versions:**

### Problem Description:

What is the impact of BETA software:

-----  
BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

-----  
The following feature/function is in BETA state.

The NmOsek has to support the specific coordination use cases:

- Use different intervals between the Nm\_SynchronizationPoint() function call and the expected NmOsek\_NetworkRelease() call in dependency of the state of NmOsek
- Use different shutdown times for CanNm and NmOsek on the same channel

To ensure that only productive code is used verify that:

- If Nm Coordination is active in Nm and NmOsek is used in the configuration, then check that in NmOsek the configuration parameter "Wait Bus Sleep Extensions" is inactive

-Nm\_Cfg.h contains the following line:

```
#define NM_WAIT_BUS_SLEEP_EXTENSIONS STD_OFF
```

### Resolution Description:

## ESCAN00091210 BETA version - the BSW module has a feature with BETA state (FEAT-1726)

**Component@Subcomponent:** Rte\_Core@Implementation

**First affected version:** 1.12.00

**Fixed in versions:**

### Problem Description:

What is the impact of BETA software:

-----  
BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

-----  
The following feature/function is in BETA state.

- This feature allows connection between Nv ports and S/R ports

To ensure that only productive code is used verify that:

- no Nv port is connected with a S/R port

### Resolution Description:

## ESCAN00091218 BETA version - the BSW module has a feature with BETA state (FEAT-371)

**Component@Subcomponent:** Diag\_Asr4Dcm@Implementation

**First affected version:** 7.00.00

**Fixed in versions:**

### Problem Description:

What is the impact of BETA software:

-----  
BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

-----  
The following feature/function is in BETA state.

- The sender/receiver access to the application data.

To ensure that only productive code is used verify that:

- Parameter DcmDspDataUsePort is not one of: USE\_DATA\_SENDER\_RECEIVER
- Parameter DcmDspDidUsePort is not one of: USE\_ATOMIC\_SENDER\_RECEIVER\_INTERFACE, USE\_ATOMIC\_NV\_DATA\_INTERFACE

### Resolution Description:

## ESCAN00091231 BETA version - the BSW module has a feature with BETA state (FEAT-1899)

**Component@Subcomponent:** Diag\_Asr4Dcm@GenTool\_GeneratorMsr

**First affected version:** 7.00.00

**Fixed in versions:**

### Problem Description:

What is the impact of BETA software:

-----  
BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

-----  
The following feature/function is in BETA state.

- Sender/Receiver Ports for NVM or complex types data.

To ensure that only productive code is used verify that:

- ECUC parameter /Dcm/DcmConfigSet/DcmDsp/DcmDspDid/DcmDspDidUsePort == USE\_DATA\_ELEMENT\_SPECIFIC\_INTERFACES

### Resolution Description:

## ESCAN00092471 BETA version - the BSW module has a feature with BETA state (FEAT-1454)

**Component@Subcomponent:** SysService\_Asr4EcuM@GenTool\_GeneratorMsr

**First affected version:** 8.00.00

**Fixed in versions:**

### Problem Description:

What is the impact of BETA software:

-----  
BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

-----  
The following feature/function is in BETA state.

- Configuration of PNC references for WakeupSources

HINT: Only Ethernet regarding PNCs might be references by WakeupSources, other busses are not supported!

### Resolution Description:

## ESCAN00092764 BETA version - the BSW module has a feature with BETA state (FEAT-1454)

**Component@Subcomponent:** Ccl\_Asr4ComMCfg5@Implementation

**First affected version:** 8.00.00

**Fixed in versions:**

### Problem Description:

What is the impact of BETA software:

-----  
BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

-----  
The following feature/function is in BETA state.

- FEAT-1454: Configuration of Switch Ports (switchable per PNC)

The above feature/function has following limitations:

- CFG5 do not provide any validations rules. A proper feature configuration has to be ensured manually.
- Use case PB-L is not supported.
- PNCs having at least one /MICROSAR/ComM/ComMConfigSet/ComMPnc/ComMPortGroupsPerPnc require a ComM user.

To ensure that only productive code is used verify that:

- /MICROSAR/ComM/ComMConfigSet/ComMPnc/ComMPortGroupsPerPnc does not exist.
- and

- ensure that COMM\_WAKEUPENABLEDOFPNC is defined to STD\_OFF in ComM\_Cfg.h.

Note: otherwise MSSV fails with error message 'assertion 'COMM\_WAKEUPENABLEDOFPNC: "STD\_ON" == "STD\_OFF" does not hold'.

### Resolution Description:

## ESCAN00092868 BETA version - the BSW module is in BETA state

**Component@Subcomponent:** DrvCry\_Rh850Icum@Implementation

**First affected version:** 1.00.00

**Fixed in versions:**

### Problem Description:

What is the impact of BETA software:

-----  
BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

-----  
The complete BSW module is in BETA state

### Resolution Description:



## 2.5 Apparent Issues

Apparent issues are detected immediately when using the software module. If an issue does not show up while working with the software module, the ECU project is not affected by the issue. Apparent issues may or may not have workarounds.

### Index

<a href="#">ESCAN00073545</a>	Final FBL response not cancelled on protocol preemption Diag_Asr4Dcm@Implementation
<a href="#">ESCAN00079399</a>	Linker error: '<Cdd>_Transmit' : undeclared identifier Cdd_AsrCddCfg5@Description
<a href="#">ESCAN00082111</a>	Data Type Truncation when using more than 255 Mailboxes DrvCan__baseAsr@GenTool_GeneratorMsr
<a href="#">ESCAN00082619</a>	Out of bounds exception DrvCan_Mpc5700McanAsr@GenTool_GeneratorMsr
<a href="#">ESCAN00082683</a>	Compiler Error: Datatype PduR__PBConfigIdType not defined by PduR Gw_AsrPduRCfg5@Implementation
<a href="#">ESCAN00082963</a>	IllegalStateException: The size of the keys: (..) of the ConstStruct: SIDFE/XIDFE does not match the size of the ConstStruct DrvCan_Mpc5700McanAsr@GenTool_GeneratorMsr
<a href="#">ESCAN00084949</a>	Validation error COM02411: solving action does not solve in post-build selectable projects. IL_AsrComCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00086253</a>	Validation message PDUR13006 is wrongly shown for N:1 transport protocol routing paths Gw_AsrPduRCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00087264</a>	VTT only: parameter settings from VttEcuC not used (EcuC used instead) DrvCan__base@GenTool_GeneratorMsr
<a href="#">ESCAN00087932</a>	ConsistencyRT00002 reports IllegalStateException: Optional.get() cannot be called on an absent value Cdd_AsrCddCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00087948</a>	Update Bits are not cleared if Com_IpduGroupControl is called with initialize = false IL_AsrComCfg5@Implementation
<a href="#">ESCAN00087958</a>	Wrong return value of GetTaskState when called from PostTaskHook Os_CoreGen7@Implementation
<a href="#">ESCAN00087977</a>	Compiler error: PduR_Lcfg.c: 'PDUR_FCT_IPDUMTX' : undeclared identifier Gw_AsrPduRCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00088524</a>	Compiler error: Undeclared identifier in the initialization structure CommonAsr_ComStackLib@GenTool_GeneratorMsr
<a href="#">ESCAN00089287</a>	Dem APIs are incompatible to the application Diag_Asr4Dem@GenTool_GeneratorMsr
<a href="#">ESCAN00089309</a>	Generation error PDUR10530 Handle Id parameter is missing Gw_AsrPduRCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00089580</a>	Solving action of validation PDUR10500 has not effect Gw_AsrPduRCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00089766</a>	CDD90025: Error at validator runtime Cdd_AsrCddCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00090253</a>	Communication interface PDU are misleading to a wrong destination Gw_AsrPduRCfg5@Implementation
<a href="#">ESCAN00090430</a>	Module initialization fails Diag_Asr4Dem@Implementation
<a href="#">ESCAN00090666</a>	Linker error caused by wrong memory section name SysService_AsrCryFord@Implementation

## Index

<a href="#">ESCAN00090998</a>	Configuration tool reports Rte90005 exception because of java.lang.IllegalArgumentException Rte_Asr4@GenTool_GeneratorMsr
<a href="#">ESCAN00091118</a>	EcuM causes a Rte Det error (RTE_E_DET_UNINIT) in the shutdown sequence while the Nvm write all is performed SysService_Asr4EcuM@Implementation
<a href="#">ESCAN00091322</a>	Validation error message cannot be solved: Error at validator runtime Consistency: an exception was caught while executing onModelEvent() of a validator. Configuration inconsistencies couldn't be reported by this validator.ModelView:UnfilteredInvariantProjectModelView Nm_Asr4NmIf@GenTool_GeneratorMsr
<a href="#">ESCAN00091373</a>	RTE01069 error in case a BSW module provides core service SWCs with mapped server runnables Rte_Asr4@GenTool_GeneratorMsr
<a href="#">ESCAN00091455</a>	A RuntimeException "unknown DataTapeRep enumeration" for sint64 is thrown CommonAsr_ComStackLib@GenTool_GeneratorMsr
<a href="#">ESCAN00091493</a>	An unnecessary DET error is reported when using extended or mixed addressing Tp_Asr4TpCan@Implementation
<a href="#">ESCAN00091624</a>	Using array types for unqueued IOC communication leads to compile error: array initialization needs curly braces Os_CoreGen7@GenTool_GeneratorMsr
<a href="#">ESCAN00091822</a>	Error message "The number of channels and/or BusNms on one channel inside one coordination cluster must be greater than '1'." is displayed at the wrong place Nm_Asr4NmIf@GenTool_GeneratorMsr
<a href="#">ESCAN00092001</a>	Compiler error: Undefined identifier *IterType with size relations CommonAsr_ComStackLib@GenTool_GeneratorMsr
<a href="#">ESCAN00092035</a>	BswM generator throws an exception in case of incorrect referenced SWC Modes SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00092058</a>	Inconsistent data types in interface DcmIf Diag_Asr4Dem@GenTool_GeneratorMsr
<a href="#">ESCAN00092064</a>	SwcTemplate: Missing back-references to Ecuc-Parameter in Port-Interfaces Diag_Asr4Dcm@GenTool_GeneratorMsr
<a href="#">ESCAN00092245</a>	TechRef: Integration of secret key is not correct Diag_AsrSwcSecAccess_Ford@Doc_TechRef
<a href="#">ESCAN00092505</a>	The start address for CAN Message RAM only works for 64KByte alignment. DrvCan_Mpc5700McanAsr@GenTool_GeneratorMsr
<a href="#">ESCAN00092569</a>	Compiler error: identifier "pduInfo_var_id" is undefined DrvCan_Mpc5700McanLI@Implementation
<a href="#">ESCAN00092571</a>	Compiler error: Undefined symbol is used If_AsrIfFeeSmallSector@GenTool_GeneratorMsr
<a href="#">ESCAN00092622</a>	A change of the main function period does not lead to a rebuild of the SWC description SysService_Asr4EcuM@GenTool_GeneratorMsr
<a href="#">ESCAN00092623</a>	Compiler error: fatal error: Nvm_Cfg.h: No such file or directory SysService_Asr4BswMCfg5@Implementation
<a href="#">ESCAN00092644</a>	ConsistencyRT00002 after adding multiple ComStackContributions of the same type Cdd_AsrCddCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00092718</a>	<MSN>90005 - Generator (<Generator Name>) failure, because of an exception "exception in <Msn> generator during Validation encountered: java.lang.NullPointerException" CommonAsr_ComGenericGenLib@GenTool_GeneratorMsr

## Index

<a href="#">ESCAN00092720</a>	DataRenamer not working for MICROSAR Define block CommonAsr_ComGenericGenLib@GenTool_GeneratorMsr
<a href="#">ESCAN00092756</a>	Name of OBD calibrateable configuration symbols are out of date Diag_Asr4Dcm@Doc_TechRef
<a href="#">ESCAN00092812</a>	Using trusted function stubs with user defined types may lead to compile error: left operand must be an l-value Os_CoreGen7@GenTool_GeneratorMsr
<a href="#">ESCAN00092839</a>	Linker include files are not generated for non-AUTOSAR cores. Os_CoreGen7@GenTool_GeneratorMsr
<a href="#">ESCAN00092892</a>	Compiler error: function "EcuM_BswErrorHook" has no prototype SysService_Asr4EcuM@Implementation
<a href="#">ESCAN00092955</a>	Compiler error: incompatible types - from 'const <MSN>_PCConfigType *' to 'const <MSN>ConfigType *const' SysService_Asr4EcuM@GenTool_GeneratorMsr
<a href="#">ESCAN00092986</a>	Compiler error: Error directive due to inconsistent configuration of Communication Mode Info Cp_AsrXcp@GenTool_GeneratorMsr
<a href="#">ESCAN00092995</a>	CAN-FD message without BRS will not be received DrvCan_Mpc5700McanLI@Implementation
<a href="#">ESCAN00093023</a>	RTE Analyzer sporadically triggers windows application crash dialog Rte_Analyzer@Application
<a href="#">ESCAN00093048</a>	RTE generator generates unused Rte_TrustedCom_SendSignal Rte_Core@Implementation
<a href="#">ESCAN00093079</a>	*_GLOBALSHARED_VAR_NOCACHE_* defines are used by Rte_MemMap.h but not generated by Os_MemMap.h. Os_CoreGen7@GenTool_GeneratorMsr
<a href="#">ESCAN00093109</a>	Missing Limitation for aggregated measurement data size of < 64KB Cp_AsrXcp@Doc_TechRef
<a href="#">ESCAN00093110</a>	Service 0x2F: ECU sends NRC 0x10 to a valid IO control DID request Diag_Asr4Dcm@GenTool_GeneratorMsr
<a href="#">ESCAN00093127</a>	RTE generator does not create IOCs in the OS configuration for single core systems Rte_Core@Implementation
<a href="#">ESCAN00093144</a>	Class cast exception when the configuration contains a subelement mapping for application datatypes Rte_Asr4@GenTool_GeneratorMsr
<a href="#">ESCAN00093236</a>	Compiler error: OS does not compile if only application specific hooks are configured. Os_CoreGen7@GenTool_GeneratorMsr
<a href="#">ESCAN00093294</a>	Invalid key accepted due to inconsistent Csm and CryFord job processing configuration Diag_AsrSwcSecAccess_Ford@Implementation
<a href="#">ESCAN00093309</a>	RTE Analyzer fails due to duplicated mainfunction Rte_Core@Implementation
<a href="#">ESCAN00093317</a>	Value Calculations does not act as expected CommonAsr_ComGenericGenLib@GenTool_GeneratorMsr
<a href="#">ESCAN00093405</a>	Auto Configuration - Invalid multiplicity after manual adaptations of container BswMAvailableActions SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00093413</a>	Auto Configuration Module Initialization - Changed User Include Files always restores SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00093449</a>	A2L compu method RTE_CM_BOOLEAN cannot be used to calibrate boolean values Rte_Core@Implementation

## Index

<a href="#">ESCAN00093455</a>	Compile error in PduR: <CDD>_Transmit is not defined Cdd_AsrCddCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00093463</a>	Wrong generated MemMap.h file for Gen7 Os Rte_Core@Implementation
<a href="#">ESCAN00093469</a>	Compiler error: 'retVal' undeclared identifier Ccl_Asr4ComMCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00093491</a>	Compiler error: identifier PduR_GetBmTxBufferIndRomStartIdxOfRmGDestRom is undefined Gw_AsrPduRCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00093494</a>	Compiler error: OS event not created for inactive/unconnected server runnables Rte_Core@Implementation
<a href="#">ESCAN00093502</a>	Technical Reference: Wrong API description for Csm_SymKeyExtractStart SysService_AsrCsm@Doc_TechRef
<a href="#">ESCAN00093539</a>	RTE49999 when SWC template generation tries to delete write protected files Rte_Core@Implementation
<a href="#">ESCAN00093569</a>	The IOC const WriteOutParameters causes error in build Rte_Core@Implementation
<a href="#">ESCAN00093579</a>	Incorrect usage of Det SysService_Asr4WdM@Implementation
<a href="#">ESCAN00093580</a>	Incorrect usage of Det If_Asr4IfWd@Implementation
<a href="#">ESCAN00093633</a>	Compiler error: Mismatch between expected and generated trusted function signature Os_CoreGen7@GenTool_GeneratorMsr
<a href="#">ESCAN00093634</a>	CAN-FD format (Bosch V1.0, ISO-11898) inconsistent DrvCan_Mpc5700McanAsr@GenTool_GeneratorMsr
<a href="#">ESCAN00093638</a>	Linking fails if the configuration contains many software components Rte_Analyzer@Application
<a href="#">ESCAN00093650</a>	Generation of RTE Analyzer stubs fails due to invalid characters in object descriptions Rte_Core@Implementation
<a href="#">ESCAN00093653</a>	Compiler error: CheckDetErrorContinue function call uses optimized away trigger disabling flag Rte_Core@Implementation
<a href="#">ESCAN00093654</a>	Compiler error: Redefinition of Sender/Receiver data element declaration Rte_Core@Implementation
<a href="#">ESCAN00093656</a>	Compiler error: Redefinition of enumeration data type Rte_Core@Implementation
<a href="#">ESCAN00093669</a>	Compiler error: Identifier OSErrors_GetScheduleTableStatus_ScheduleStatus not defined. Os_CoreGen7@Implementation
<a href="#">ESCAN00093692</a>	Auto Configuration dialog shows an empty message about "Manual Adaptations" after finishing the Auto Configuration. SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00093765</a>	Compiler error: Rte_ComSendSignalProxyPeriodic accesses missing variable Rte_Core@Implementation
<a href="#">ESCAN00093785</a>	Mirror component Transmission pathways are not detected correctly Gw_AsrPduRCfg5@GenTool_GeneratorMsr
<a href="#">ESCAN00093839</a>	CFG5 Exception in <MSN> generator during Generation encountered and no files are generated CommonAsr_ComStackLib@GenTool_GeneratorMsr
<a href="#">ESCAN00093969</a>	Missing Dem_[Dcm]ClearDTC in list of required DEM API Diag_Asr4Dcm@Doc_TechRef

## Index

- |                               |  |
|-------------------------------|--|
| <a href="#">ESCAN00094010</a> | Compiler error: Redefinition of data handle entry in component data structure for PR Ports using implicit communication<br>Rte_Core@Implementation |
| <a href="#">ESCAN00094026</a> | Compiler error: Missing extern declaration for Rte_InitState<br>Rte_Core@Implementation  |

ESCAN00073545 Final FBL response not cancelled on protocol preemption	
<b>Component@Subcomponent:</b>	Diag_Asr4Dcm@Implementation
<b>First affected version:</b>	1.05.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The ECU will process the FBL final response even if there is higher protocol request sent.	
When does this happen:	
-----	
When immediately after reprogramming of the ECU has ended, the very first request after ECU powers on in the application is a hi-priority one (i.e. OBD).	
In which configuration does this happen:	
-----	
- Any configuration where the ECU shall be able to send a final response without request after reset.	
AND	
- Protocol prioritisation is to be supported (i.e. OBD vs. UDS).	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

**ESCAN00079399      Linker error: '<Cdd>\_Transmit' : undeclared identifier****Component@Subcomponent:**      Cdd\_AsrCddCfg5@Description**First affected version:**          2.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
Linker error in PduR\_Lcfg.c: '<Cdd>\_Transmit' : undeclared identifier

The Cdd\_AsrCddCfg5 is not derived according to the ASR 4.0.3 rules and allows a LOWER-MULTIPLICITY of 0 for the CddPduRLowerLayerRxPdu and CddPduRLowerLayerTxPdu instead of the LOWER-MULTIPLICITY of 1.

The generic ASR PduR according to the ASR 4.0.3 Specification has no information to deactivate a communication direction (e.g. a Parameter in the PduRBswModules).

When does this happen:

-----  
The error is issued by the linker after compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
Rx only Cdd with a CddPduRLowerLayerContribution (just receive pathways exits)

The &lt;CddName&gt;.h file contains the following define:

&lt;CddName&gt;\_LOWERLAYERCOMIF\_TX is defined to STD\_OFF

**Resolution Description:**

Workaround:

-----  
Implement the not required '<Cdd>\_Transmit' API on your own in a c and h file of your choice and add the header file with a user config file to the PduR configuration that the compiler does not throw a warning.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00082111 Data Type Truncation when using more than 255 Mailboxes	
<b>Component@Subcomponent:</b>	DrvCan__baseAsr@GenTool_GeneratorMsr
<b>First affected version:</b>	1.05.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b> What happens (symptoms): ----- One or more CAN-busses quit transmitting frames or never start transmission. Another symptom which can occur are Det-Errors in CAN-Write  A reliable indicator for this issue are compiler warnings while compiling CanIf reporting data type truncation. e.g. "integer conversion resulted in truncation" in Table "CanControllerConfig[]"  When does this happen: ----- runtime effect: - Always respectively after a small period of time. compiler warning: - always while compile time.  In which configuration does this happen: ----- Whenever there are more than 255 mailboxes (LPDUs) configured in Can driver. Can_Mailbox[] table is bigger than 255.	
<b>Resolution Description:</b> Workaround: ----- Set Can/CanGeneral/CanHardwareHandleType to user defined 16 bit.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	



ESCAN00082619 Out of bounds exception	
<b>Component@Subcomponent:</b>	DrvCan_Mpc5700McanAsr@GenTool_GeneratorMsr
<b>First affected version:</b>	3.00.00
<b>Fixed in versions:</b>	3.00.02
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
During generation time an "illegal out of bounds" exception appears. This will result in inconsistent generation data.	
When does this happen:	
-----	
At generation time.	
In which configuration does this happen:	
-----	
This happens if a configuration with Variant PostBuild and Standard IDs or Extended IDs only is configured to support Mixed IDs as well.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Configure at least one Extended ID Filter entry when using Standard IDs. Configure at least one Standard ID Filter entry when using Extended IDs.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00082683      Compiler Error: Datatype PduR__PBConfigIdType not defined by PduR	
<b>Component@Subcomponent:</b>	Gw_AsrPduRCfg5@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	7.02.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Datatype PduR_PBConfigIdType isn't defined by the PduR as defined within AUTOSR_SWS_PDURouter within ASR4.2.1 Release and therefore not used as return value type of the PduR_GetConfigurationId API. Instead within the API a uint16 is used as return value type. Due to this there could be compilation issues if some other module or integration code is using this data type.	
When does this happen:	
-----	
When the API PduR_GetConfigurationId(void) is used	
In which configuration does this happen:	
-----	
All	
<b>Resolution Description:</b>	
Workaround:	
-----	
The problem can be solved by defining the datatype within a User Config File of the PduR.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00082963</b>	<b>IllegalStateException: The size of the keys: (..) of the ConstStruct: SIDFE/XIDFE does not match the size of the ConstStruct</b>
<b>Component@Subcomponent:</b>	DrvCan_Mpc5700McanAsr@GenTool_GeneratorMsr
<b>First affected version:</b>	3.00.00
<b>Fixed in versions:</b>	3.00.03
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Generation fails with an Exception similar to this:	
IllegalStateException: The size of the keys: (..) of the ConstStruct: SIDFE/XIDFE does not match the size of the ConstStruct	
When does this happen:	
-----	
During Generation / Validation.	
In which configuration does this happen:	
-----	
Mixed ID Configuration used	
AND	
At least one channel has only Standard / only Extended filters.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Ensure that all channels have standard and extended filters configured.	
Create a (closed) dummy filter with the missing id type if necessary.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00084949      Validation error COM02411: solving action does not solve in post-build selectable projects.</b>	
<b>Component@Subcomponent:</b>	Il_AsrComCfg5@GenTool_GeneratorMsr
<b>First affected version:</b>	4.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b> What happens (symptoms): ----- The solving action for COM02411, offering to delete the parameter /MICROSAR/EcuC/EcucPduCollection/Pdu/MetaDataLength does not delete it. The parameter can be deleted manually though.  When does this happen: ----- During execution of the solving action.  In which configuration does this happen: ----- Post-build selectable configurations which match all of the following criteria: - Contains at least one instance of /MICROSAR/EcuC/EcucPduCollection/Pdu that is not active in all variants. - Validator message COM02411 is issued in this PDU with the solving action to delete the parameter MetaDataLength.	
<b>Resolution Description:</b> Workaround: ----- Manually delete the parameter.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00086253      Validation message PDUR13006 is wrongly shown for N:1 transport protocol routing paths	
<b>Component@Subcomponent:</b>	Gw_AsrPduRCfg5@GenTool_GeneratorMsr
<b>First affected version:</b>	8.00.00
<b>Fixed in versions:</b>	8.01.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The validation message PDUR13006 is shown in the Configurator 5 validation window, if a N:1 transport protocol routing path is configured. The message should only appear for N:1 communication interface routing paths.	
When does this happen:	
-----	
The message is shown if N:1 transport protocol routing paths are configured.	
In which configuration does this happen:	
-----	
N:1 transport protocol routing paths may only be configured for single frame transport protocol messages (only single buffer call is supported). This is validated by another validator.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Ignore the validator message for N:1 transport protocol routing paths.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00087264 VTT only: parameter settings from VttEcuC not used (EcuC used instead)	
<b>Component@Subcomponent:</b>	DrvCan__base@GenTool_GeneratorMsr
<b>First affected version:</b>	3.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
VTT does not use the settings given in VttEcuC modul like:	
- SafeBswChecks (SafeBsw used but should not --> more runtime consumption)	
- DummyFunction (compiler warnings)	
- DummyStatement (compiler warnings)	
- OsType (same for Hardware)	
When does this happen:	
-----	
while compile time for DummyFunction and DummyStatement	
while runtime for SafeBswChecks	
In which configuration does this happen:	
-----	
VTT used	
and	
Platform settings in EcuC modul differ from settings in VttEcuC modul	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00087932 ConsistencyRT00002 reports IllegalStateException: Optional.get() cannot be called on an absent value	
<b>Component@Subcomponent:</b>	Cdd_AsrCddCfg5@GenTool_GeneratorMsr
<b>First affected version:</b>	5.00.00
<b>Fixed in versions:</b>	5.00.01
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The validation result with ID ConsistencyRT00002 is reported in the DaVinci Configurator. In the validation details contains the following info: Exception: java.lang.IllegalStateException: Optional.get() cannot be called on an absent value	
When does this happen:	
-----	
During live-validation of the EcuC model in the DaVinci Configurator	
In which configuration does this happen:	
-----	
This issue happens if no related /MICROSAR/PduR/PduRBswModules container(s), referencing the Cdd module(s) is existing AND In the Cdd module Rx/Tx Pdus routed via the PduR are configured	
<b>Resolution Description:</b>	
Workaround:	
-----	
Add the missing /MICROSAR/PduR/PduRBswModules referencing the existing Cdd module(s) and restart DaVinci Configurator.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00087948</b>	<b>Update Bits are not cleared if Com_IpduGroupControl is called with initialize = false</b>
<b>Component@Subcomponent:</b>	Il_AsrComCfg5@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
----- After a IpduGroup is started with initialize = false a Signal is transmitted with set Update Bit although signal was not updated since the IpduGroup was stopped.	
When does this happen:	
----- during the call of Com_IpduGroupControl.	
In which configuration does this happen:	
-----	
If Tx UpdateBits are used	
AND	
if Com_IpduGroupControl is used with initialize = false	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	



**ESCAN00087958      Wrong return value of GetTaskState when called from PostTaskHook****Component@Subcomponent:** Os\_CoreGen7@Implementation**First affected version:** 1.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----

GetTaskState returns SUSPENDED for current task when called from PostTaskHook.  
Return 'RUNNING' instead.

When does this happen:

-----

In PostTaskHook the task is still running.

In which configuration does this happen:

-----

Configuration invariant.

**Resolution Description:**

Workaround:

-----

Do not use the API GetTaskState for the current task in the PostTaskHook.

Resolution:

-----

The described issue is corrected by modification of all affected work-products.

**ESCAN00087977      Compiler error: PduR\_Lcfg.c:  
'PDUR\_FCT\_IPDUMTX' : undeclared identifier****Component@Subcomponent:** Gw\_AsrPduRCfg5@GenTool\_GeneratorMsr**First affected version:** 2.03.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
Compiler error: PduR\_Lcfg.c: 'PDUR\_FCT\_IPDUMTX' : undeclared identifier

Hint: If a module without routing paths is configured the validation can not determine the communication type.

Ensure that the /MICROSAR/PduR/PduRBswModules Parameter are configured suitable to the post- build scenario.

When does this happen:

-----  
The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
/ActiveEcuC/PduR/PduRGeneral[PduRDevErrorDetect] == true AND  
Impl. Config Variant == VARIANT-POST-BUILD-LOADABLE AND  
/ActiveEcuC/PduR/IpduM exists (/MICROSAR/PduR/PduRBswModules) AND  
No routing path for IpduM exists AND the /ActiveEcuC/PduR/IpduM[PduRCommunicationInterface]  
== false**Resolution Description:**

Workaround:

-----  
The communication type must be configured for BSW modules without routing paths.

Configure /ActiveEcuC/PduR/IpduM[PduRCommunicationInterface] to "true"

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00088524      Compiler error: Undeclared identifier in the initialization structure	
<b>Component@Subcomponent:</b>	CommonAsr_ComStackLib@GenTool_GeneratorMsr
<b>First affected version:</b>	7.00.00
<b>Fixed in versions:</b>	8.01.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compiler throws an error for an undeclared identifier used in the root initialization structure.	
When does this happen:	
-----	
The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
The configuration contains multiple predefined variants (selectable)	
AND	
array or struct symbols are generated to the configuration class precompile	
AND	
isReduceConstantData2Define() returns true	
AND	
isInterfacesForDeactivatedData() returns true	
<b>Resolution Description:</b>	
Workaround:	
-----	
if isInterfacesForDeactivatedData() is user configurable a workaround is available else not.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00089287      Dem APIs are incompatible to the application	
<b>Component@Subcomponent:</b>	Diag_Asr4Dem@GenTool_GeneratorMsr
<b>First affected version:</b>	3.00.00
<b>Fixed in versions:</b>	9.00.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Application interfaces cannot be connected to the Dem ports because of incompatible type definitions.	
The Dem APIs use Dem_ExtendedStatusByteType which uses an incompatible compu-method compared to Dem_UdsStatusType.	
When does this happen:	
-----	
Always when trying to connect an application software to the Dem	
In which configuration does this happen:	
-----	
Applications using port definitions according to Autosar 4.1.2	
<b>Resolution Description:</b>	
Workaround:	
-----	
Change the datatype used in the application SWC to enumeration instead of bitfield.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

## ESCAN00089309      Generation error PDUR10530 Handle Id parameter is missing

**Component@Subcomponent:** Gw\_AsrPduRCfg5@GenTool\_GeneratorMsr

**First affected version:** 9.00.00

**Fixed in versions:** 9.03.00

### Problem Description:

What happens (symptoms):

During code generation, the PduR generator throws error PDUR10530 and stops generation. Additionally, errors PDUR90001 and PDUR90005 are thrown for the same problem.

When does this happen:

During code generation.

In which configuration does this happen:

All configurations including the module:

Il\_AsrIpduMCfg5@root version 7.00.00 and higher

where the optional parameter

/MICROSAR/IpduM/IpduMConfig/IpduMTxPathway/IpduMTxRequest/IpduMTxConfirmationPduId does not exist

AND

/MICROSAR/PduR/PduRRoutingTables/PduRRoutingTable/PduRRoutingPath/PduRDestPdu/PduRTransmissionConfirmation == FALSE

AND

/MICROSAR/PduR/PduRRoutingTables/PduRRoutingTable/PduRRoutingPath/PduRDestPdu/PduRDestPduDataProvision == PDUR\_DIRECT

### Resolution Description:

Workaround:

Set /MICROSAR/IpduM/IpduMConfig/IpduMTxPathway/IpduMTxRequest/IpduMTxConfirmationPduId to any value (e.g. 0), a validator will then calculate the correct the value.

Resolution:

The described issue is corrected by modification of all affected work-products.

## ESCAN00089580 Solving action of validation PDUR10500 has not effect

**Component@Subcomponent:** Gw\_AsrPduRCfg5@GenTool\_GeneratorMsr

**First affected version:** 7.00.00

**Fixed in versions:** 9.03.00

### Problem Description:

What happens (symptoms):

-----  
The provided solving action of PduR validation result PDUR10500 has not effect. The validation error gets not resolved.

PDUR10500 PduRDestTxBufferRef parameter missing. (58 messages)  
PDUR10500 The parameter PduRDestTxBufferRef must be configured when  
PduRDestPduDataProvision(value=PDUR\_TRIGGERTRANSMIT) is set to PDUR\_TRIGGERTRANSMIT.  
Create the container DefinitionRef: /MICROSAR/PduR/PduRRoutingTables/PduRRoutingTable/  
PduRRoutingPath/PduRDestPdu/PduRDestTxBufferRef in

When does this happen:

-----  
During execution of the provided solving action:  
Create the container DefinitionRef: /MICROSAR/PduR/PduRRoutingTables/PduRRoutingTable/  
PduRRoutingPath/PduRDestPdu/PduRDestTxBufferRef in

In which configuration does this happen:

-----  
In case a validation result for PDUR10500 was found.

This happens for PDUS with the following criteria:  
Communication Interface Gateway Routing Paths are configured  
AND  
PduRDestPduDataProvision == PDUR\_TRIGGERTRANSMIT  
AND  
The parameter /MICROSAR/PduR/PduRRoutingTables/PduRRoutingTable/PduRRoutingPath/  
PduRDestPdu/PduRDestTxBufferRef does not reference any PduRTxBuffer

### Resolution Description:

Workaround:

-----  
The incorrect /MICROSAR/PduR/PduRRoutingTables/PduRRoutingTable/PduRRoutingPath/  
PduRDestPdu/PduRDestTxBufferRef parameter(s) needs to be configured manually.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00089766 CDD90025: Error at validator runtime	
<b>Component@Subcomponent:</b>	Cdd_AsrCddCfg5@GenTool_GeneratorMsr
<b>First affected version:</b>	3.01.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
An exception is thrown, if multiple CDDs with J1939RmContribution are configured.	
When does this happen:	
-----	
During validation.	
In which configuration does this happen:	
-----	
In configurations with multiple J1939RmContribution CDDs.	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work products.	

ESCAN00090253	Communication interface PDU are misleading to a wrong destination
<b>Component@Subcomponent:</b>	Gw_AsrPduRCfg5@Implementation
<b>First affected version:</b>	6.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
If Communication Interface and Transport Protocol routings are configured and the Communication Interface option in the PduR BSW module is disabled the SecOC communication interface PDU is misleading to a wrong destination.	
Hint: Missing validation for communication interface pathways.	
When does this happen:	
-----	
Always and immediately during runtime	
In which configuration does this happen:	
-----	
<ul style="list-style-type: none"> <li>- Configuration with SecOC and</li> <li>- If Communication Interface and Transport Protocol routings are configured for the SecOC and</li> <li>- Communication Interface option in the PduR BSW Modules is disabled</li> </ul>	
<b>Resolution Description:</b>	
Workaround:	
-----	
Enable the communication interface option in the PduR- BSW Modules for SecOC module	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	



ESCAN00090430      Module initialization fails	
<b>Component@Subcomponent:</b>	Diag_Asr4Dem@Implementation
<b>First affected version:</b>	5.00.00
<b>Fixed in versions:</b>	8.00.08, 12.00.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
In PostBuild Loadable configurations	
Initializing the Dem will result in EcuM_BswErrorHook	
In PostBuild Selectable configurations (only PB-S, no PB-L)	
The Dem will behave in a random way	
When does this happen:	
-----	
Always and immediately	
In which configuration does this happen:	
-----	
Postbuild Selectable and/or Postbuild Loadable configurations with module individual post-build enabled	
AND	
Segmented memory model, where memory mapping of DEM_PBCFG differs in pointer distance from DEM_PBCFG_ROOT and/or DEM_CONST	
PB-Loadable with Module individual PB: Affected if pointers to DEM_PBCFG_ROOT cannot be assigned to a pointer to DEM_PBCFG	
PB-Selectable without post-build loadable: Affected if pointers to DEM_CONST cannot be assigned to a pointer to DEM_PBCFG	
<b>Resolution Description:</b>	
Workaround:	
-----	
Change the memory mapping configuration such that pointers to DEM_PBCFG_ROOT / DEM_CONST can be assigned to a pointer variable defined for DEM_PBCFG	
e.g. use far pointers for both DEM_PBCFG_ROOT / DEM_CONST and DEM_PBCFG	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00090666 Linker error caused by wrong memory section name	
<b>Component@Subcomponent:</b>	SysService_AsrCryFord@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
A linker error occurs due to a missing memory section. E.g. OsAppBswNonTrusted	
When does this happen:	
-----	
If a special memory mapping configuration in MemMap.h was used to build the library. E.g. if memory protection is used and the BSW is mapped in the memory section of a special OS application.	
In which configuration does this happen:	
-----	
If the customer uses a different name for the related memory sections or OS applications.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Renaming the section due to the Vector Configuration	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00090998 Configuration tool reports Rte90005 exception because of java.lang.IllegalArgumentException	
<b>Component@Subcomponent:</b>	Rte_Asr4@GenTool_GeneratorMsr
<b>First affected version:</b>	4.08.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The configuration tool reports Rte90005 - Generator (MICROSAR RTE Generator) failure, because of an exception	
- Exception in Rte generator during Generation encountered: java.lang.IllegalArgumentException	
When does this happen:	
-----	
This happen during generation phase.	
In which configuration does this happen:	
-----	
This can happen sometimes in configurations that contain RTE errors found in calculation or validation phase.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Solving the reported RTE errors messages.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00091118</b>	<b>EcuM causes a Rte Det error (RTE_E_DET_UNINIT) in the shutdown sequence while the Nvm write all is performed</b>
<b>Component@Subcomponent:</b>	SysService_Asr4EcuM@Implementation
<b>First affected version:</b>	3.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
----- The Rte throws a Det error with the ID RTE_E_DET_UNINIT during the shutdown sequence.	
When does this happen:	
----- Always during the NvM_WriteAll() is performed.	
In which configuration does this happen:	
----- Only in configurations with all the following parameters are set to true:	
/ActiveEcuC/EcuM/EcuMGeneral/EcuMEnableFixBehavior /ActiveEcuC/EcuM/EcuMFixedGeneral/EcuMModeSwitchRteAck /ActiveEcuC/EcuM/EcuMFixedGeneral/EcuMIncludeNvramMgr /ActiveEcuC/Rte/RteGeneration/RteDevErrorDetect	
<b>Resolution Description:</b>	
Workaround:	
----- The only workaround is to filter this DET message.	
Resolution:	
----- The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00091322</b>	<b>Validation error message cannot be solved: Error at validator runtime Consistency: an exception was caught while executing onModelEvent() of a validator. Configuration inconsistencies couldn't be reported by this validator.ModelView:UnfilteredInvariantProjectModel</b>
<b>Component@Subcomponent:</b>	Nm_Asr4NmIf@GenTool_GeneratorMsr
<b>First affected version:</b>	9.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	

## ESCAN00091322 Validation error message cannot be solved: Error at validator runtime Consistency: an exception was caught while executing onModelEvent() of a validator. Configuration inconsistencies couldn't be reported by this validator.ModelView:UnfilteredInvariantProjectModel

What happens (symptoms):

The following validation error message appears in the Validation view in DaVinci Configurator:

ConsistencyRT00002 Error at validator runtime (1 message)

ConsistencyRT00002 Consistency: an exception was caught while executing onModelEvent() of a validator. Configuration inconsistencies couldn't be reported by this validator.ModelView:UnfilteredInvariantProjectModelView

This is not a configuration problem but an internal implementation error. Please contact Vector for support.

Validator-Class:

com.vector.cfg.gen.Nm\_Asr4NmIf.validation.NmGlobalCoordinatorTimeAllNmOsekInNormalValidator

Validator-Description: NmGlobalCoordinatorTimeAllNmOsekInNormalValidator validates that the setting NmGlobalCoordinatorTimeAllNmOsekInNormal is defined if it required.

Further runtime errors of this validator won't be reported in the UI.

Ex: com.vector.cfg.gen.core.moduleinterface.exceptions.ValidationFailedException: [Error]

NM01003 - A Specific Channel configuration is missing for the NmChannelConfig

- The corresponding CanNmChannelConfig is missing for this NmChannelConfig

We are sorry, but due to this internal error, code generation of /[ANY]/CanNm, /MICROSAR/NmOsek, /[ANY]/FrIf, /[ANY]/FrNm, /[ANY]/UdpNm, /[ANY]/ComM, /MICROSAR/Nm has to be blocked. As a workaround, you may try to restart DaVinci Configurator. Otherwise, please call Vector for support

/ActiveEcuC/ComM

FrIf

UdpNm

CanNm

/ActiveEcuC/Nm

FrNm

/ActiveEcuC/NmOsek

Apparently, the message cannot be resolved.

When does this happen:

During configuration with DaVinci Configurator.

In which configuration does this happen:

Any configuration with Nm where a NmChannelConfig container exists that does not have a correspondent BusNmChannelConfig container (e.g. CanNmChannelConfig, FrNmChannel, LinNmChannelConfig, UdpNmChannelConfig, J1939NmChannelConfig, NmOsekChannelConfig, ...)

AND

(  
'Coordinator Support Enabled' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalFeatures/  
NmCoordinatorSupportEnabled) is turned OFF in the NmGlobalFeatures container in Nm in the  
'Network Management General' / 'Basic Editor' in DaVinci Configurator-> Nm\_Cfg.h contains  
#define NM\_COORDINATOR\_SUPPORT\_ENABLED STD\_OFF)

AND/OR

('Wait Bus Sleep Extensions' (/MICROSAR/NmOsek/NmOsekGlobalConfig/  
NmOsekWaitBusSleepExtensions) is turned OFF or not defined or cannot be found in the

**ESCAN00091322**      **Validation error message cannot be solved: Error at validator runtime Consistency: an exception was caught while executing onModelEvent() of a validator. Configuration inconsistencies couldn't be reported by this validator.ModelView:UnfilteredInvariantProjectModel**

NmOsekGlobalConfig container in NmOsek in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator -> NmOsek\_Cfg.h does not contain #define NMOSEK\_WAIT\_BUS\_SLEEP\_EXTENSIONS)

AND/OR

('Synchronizing Network' (/MICROSAR/Nm/NmChannelConfig/NmSynchronizingNetwork) is turned OFF for at least one NmChannelConfig container in Nm in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator)

AND/OR

('Coord Cluster Index' (/MICROSAR/Nm/NmChannelConfig/NmCoordClusterIndex) is undefined or set to 255 for at least one NmChannelConfig container in Nm in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator)

)

Please note that this is an invalid configuration because either the NmChannelConfig container without a BusNmChannelConfig must be deleted or the corresponding BusNmChannelConfig container must be created.

#### **Resolution Description:**

Workaround:

-----  
In DaVinci Configurator:

1) Create the corresponding BusNmChannelConfig container and configure its parameters and sub-containers.

OR

2) Delete the NmChannelConfig container that lacks a corresponding BusNmChannelConfig container.

Afterwards (no matter whether 1) or 2) has been applied), save the configuration, close it and re-open it.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

## ESCAN00091373 RTE01069 error in case a BSW module provides core service SWCs with mapped server runnables

**Component@Subcomponent:** Rte\_Asr4@GenTool\_GeneratorMsr

**First affected version:** 4.09.00

**Fixed in versions:** 4.14.00

### Problem Description:

What happens (symptoms):

-----  
RTE generation is incorrectly aborted with an RTE01069 error message.

When does this happen:

-----  
During generation.

In which configuration does this happen:

-----  
This happens when the configuration contains multiple service SWCs for the same BSW module.

### Resolution Description:

Workaround:

-----  
Do not map the server runnable.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

## ESCAN00091455 A RuntimeException "unknown DataTapeRep enumeration" for sint64 is thrown

**Component@Subcomponent:** CommonAsr\_ComStackLib@GenTool\_GeneratorMsr

**First affected version:** 6.00.00

**Fixed in versions:** 8.03.01

### Problem Description:

What happens (symptoms):

-----  
A RuntimeException "unknown DataTapeRep enumeration" for sint64 is thrown at generation time.

When does this happen:

-----  
Always and immediately under specific circumstances. See in which configuration does this happen.

In which configuration does this happen:

-----  
Any configuration using the EComStackDataTypeRep sint64.

### Resolution Description:

Workaround:

-----  
No workaround available.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.



## ESCAN00091493 An unnecessary DET error is reported when using extended or mixed addressing

**Component@Subcomponent:** Tp\_Asr4TpCan@Implementation

**First affected version:** 3.01.00

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

1. A DET error is reported when receiving an Rx PDU containing a "Target Address" that doesn't match any of the Rx SDUs configured with "Extended Addressing" in the CanTp.
- AND/OR
2. A DET error is reported when receiving an Rx PDU containing an "Address Extension" that doesn't match any of the Rx SDUs configured with "Mixed Addressing" in the CanTp.

When does this happen:

This happens always when receiving an Rx PDU with an "unknown" address extension or target address (i.e., the ECU is not the intended addressee).

In which configuration does this happen:

This happens only in configurations where at least one Rx SDU is configured with extended addressing or mixed addressing:

(CanTp/CanTpConfig/CanTpChannel/CanTpRxNSdu/CanTpRxAddressingFormat == CANTP\_EXTENDED)

AND/OR

(CanTp/CanTpConfig/CanTpChannel/CanTpRxNSdu/CanTpRxAddressingFormat == CANTP\_MIXED)

DET error reporting must also be enabled (CANTP\_DEV\_ERROR\_REPORT == STD\_ON)

### Resolution Description:

Workaround:

No error is reported if DET error reporting is disabled.

In case DET error reporting is required, the error CANTP\_E\_INVALID\_RX\_ID could be filtered out when reported from CANTP\_SID\_RXINDICATION.

Resolution:

This issue hasn't been solved yet.

**ESCAN00091624      Using array types for unqueued IOC communication leads to compile error: array initialization needs curly braces****Component@Subcomponent:** Os\_CoreGen7@GenTool\_GeneratorMsr**First affected version:** 1.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
The compiler states: array initialization needs curly braces

When does this happen:

-----  
The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
This happens only when array types are used for unqueued IOC communication.**Resolution Description:**

Workaround:

-----  
Do not use array types for unqueued communication. If necessary put the array into a structure first.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

## ESCAN00091822 Error message "The number of channels and/or BusNms on one channel inside one coordination cluster must be greater than '1'." is displayed at the wrong place

**Component@Subcomponent:** Nm\_Asr4NmIf@GenTool\_GeneratorMsr

**First affected version:** 2.00.00

**Fixed in versions:** 9.00.01

### Problem Description:

What happens (symptoms):

-----  
The error message

NM02041 The Coordinator settings are configured incorrectly. (1 message)

NM02041 The number of channels and/or BusNms on one channel inside one coordination cluster must be greater than '1'.

/ActiveEcuC/Nm/NmChannelConfig\_001[NmCoordClusterIndex]

/ActiveEcuC/Nm/NmGlobalConfig/NmGlobalFeatures[NmCoordinatorSupportEnabled]

is displayed at a wrong place in DaVinci Configurator in the 'Network Management General' / 'Basic Editor' at some 'Coord Cluster Index' parameter that is actually configured correctly.

Example:

In a setup with three channels having each one of them a NmChannelConfig container, the Coord Cluster Index setting is set to 0 for the first and second NmChannelConfig container and set to 1 for the third NmChannelConfig container.

Then the error message might be displayed at the 'Coord Cluster Index' parameter of the first or second NmChannelConfig container.

When does this happen:

-----  
During configuration with DaVinci Configurator.

In which configuration does this happen:

-----  
In invalid configurations where

'Coordinator Support Enabled' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalFeatures/NmCoordinatorSupportEnabled) is turned ON in the NmGlobalFeature container in the Network Management General' / 'Basic Editor' in DaVinci Configurator

AND

a NmChannelConfig container exists that has the NmCoordClusterIndex (/MICROSAR/Nm/NmChannelConfig/NmCoordClusterIndex) defined to a value that no other NmChannelConfig container contains

AND

the aforementioned NmChannelConfig container has only one NmBusType (/MICROSAR/Nm/NmChannelConfig/NmBusType) subcontainer

Please note that this is an invalid configuration and only the error message is displayed at the wrong configuration item.

### Resolution Description:

## ESCAN00091822 Error message "The number of channels and/or BusNms on one channel inside one coordination cluster must be greater than '1'." is displayed at the wrong place

Workaround:

-----  
Locate the NmChannelConfig container that has the only unique value for 'Coord Cluster Index'.

If the channel that the NmChannelConfig container belongs to shall be coordinated:

Either

A) make sure that another NmBusType container exists below the NmChannelConfig container  
or

B) make sure that another NmChannelConfig container exists that has the same 'Coord Cluster Index' value

If the channel that the NmChannelConfig container belongs to shall not be coordinated: just delete the 'Coord Cluster Index' value

Please note that the workaround actually fixes the configuration to make it a valid one.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

## ESCAN00092001 Compiler error: Undefined identifier \*IterType with size relations

**Component@Subcomponent:** CommonAsr\_ComStackLib@GenTool\_GeneratorMsr

**First affected version:** 8.00.00

**Fixed in versions:** 8.03.01

### Problem Description:

What happens (symptoms):

-----  
Compile error occurs in the doxygen group \*IterableTypesWithSizeRelations. The type definition of the size relevant array \*IterType is undefined.

When does this happen:

-----  
The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
Any configuration with a ConstStruct containing only indirection, which is deactivated by a reason.

### Resolution Description:

Workaround:

-----  
No Workaround available.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

**ESCAN00092035 BswM generator throws an exception in case of incorrect referenced SWC Modes****Component@Subcomponent:** SysService\_Asr4BswMCfg5@GenTool\_GeneratorMsr**First affected version:** 2.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
An exception is thrown during SWC Template Generation similar to the following one:

48599 ERROR - Consistency: an exception was caught while executing onModelEvent() on rule "com.vector.cfg.gen.SysService\_Asr4BswMCfg5.validation.swc.BswMSwcModeNotificationValidation"

java.lang.IllegalStateException: An PreferredSolvingAction was already assign. Two PreferredSolvingActions are not allowed.

As a consequence, SWC Template Generation fails.

When does this happen:

-----  
During tool usage.

In which configuration does this happen:

-----  
Incorrect SWC Modes are referenced by /MICROSAR/BswM/BswMConfig/BswMArbitration/BswMModeRequestPort/BswMModeInitValue/BswMSwcModeInitValue/BswMSwcModeInitValueRef and other Swc Mode parameters.**Resolution Description:**

Workaround:

-----  
Invalid references to the SWC modes has to be resolved manually.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00092058 Inconsistent data types in interface DcmIf	
<b>Component@Subcomponent:</b>	Diag_Asr4Dem@GenTool_GeneratorMsr
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	10.00.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
SWC-Validation of Dcm and Dem generates inconsistent data types in interface DcmIf. Limits of the corresponding enumeration data types do not match.	
When does this happen:	
-----	
At Dem/Dcm SWC template import time in DaVinci Developer.	
In which configuration does this happen:	
-----	
/Dem/DemGeneral/DemDcmSupport = True within an AR 3.x RTE.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Import first the Dem_Swc.arxml file, then the Dcm_Swc.arxml file to override the Dem data types (imported through Dcm).	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00092064 SwcTemplate: Missing back-references to Ecuc-Parameter in Port-Interfaces	
<b>Component@Subcomponent:</b>	Diag_Asr4Dcm@GenTool_GeneratorMsr
<b>First affected version:</b>	7.01.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Tools that rely on back-references to Ecuc-Parameter such as BaseEcucGen will not be able to link the port interface to corresponding entry in DIAG-EX.	
When does this happen:	
-----	
Each time Dcm Swc is updated.	
In which configuration does this happen:	
-----	
For already existing Routine Service port interfaces that have been updated with DcmDspRoutineSystemTemplateDiagnosticRoutineRef.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Variant A) Delete Dcm Swc file and reopen and save Cfg5-project.	
Variant B) Temporarily deactivate affected Routine (toggle DcmDspRoutineUsed to False and True).	
Variant C) Use Cfg5.13 SP 3, Cfg5.14 SP1 or a newer version.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00092245    TechRef: Integration of secret key is not correct	
<b>Component@Subcomponent:</b>	Diag_AsrSwcSecAccess_Ford@Doc_TechRef
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The Technical Reference is slightly outdated. In Chapter 4.1.1 the TechRef states out: "SwcSecAccessFord_Cfg.c In this file the secret keys can be stored"	
This is no longer correct since the implementation version 1.00.00. The key data are now fetched by using the DCM service "GetSecurityLevelFixedBytes".	
When does this happen:	
-----	
Implementation version > 1.00.00	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	



ESCAN00092505      The start address for CAN Message RAM only works for 64KByte alignment.	
<b>Component@Subcomponent:</b>	DrvCan_Mpc5700McanAsr@GenTool_GeneratorMsr
<b>First affected version:</b>	3.00.01
<b>Fixed in versions:</b>	3.03.01
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
No CAN communication on CAN Bus. Just CAN ID "0" with dlc "0" is sent by the ECU.	
When does this happen:	
-----	
Always and immediately	
In which configuration does this happen:	
-----	
It happens when the start address is not aligned to a 64KByte block.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Do only configure Start Addresses for the CAN Message RAM which are aligned to 64KByte boundaries.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00092569 Compiler error: identifier "pduInfo_var_id" is undefined	
<b>Component@Subcomponent:</b>	DrvCan_Mpc5700McanLI@Implementation
<b>First affected version:</b>	2.08.00
<b>Fixed in versions:</b>	2.10.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compiler error: identifier "pduInfo_var_id" is undefined	
When does this happen:	
-----	
The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
Only if the MCAN Revision is less than 3.1.0 (CAN_MCAN_REVISION < 0x0310)	
AND	
CAN FD is activated (CAN_FD_SUPPORT != CAN_NONE).	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00092571 Compiler error: Undefined symbol is used	
<b>Component@Subcomponent:</b>	If_AsrIfFeeSmallSector@GenTool_GeneratorMsr
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	1.00.01
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
A compile error will occur because of using an undefined symbol: EA_PRIVATE_CONST	
When does this happen:	
-----	
The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
In every configuration.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Add #define EA_PRIVATE_CONST to compiler abstraction.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00092622      A change of the main function period does not lead to a rebuild of the SWC description</b>	
<b>Component@Subcomponent:</b>	SysService_Asr4EcuM@GenTool_GeneratorMsr
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b> What happens (symptoms): ----- The SWC description file is not updated after a change of the EcuM main function period.  When does this happen: ----- After change of the parameter /MICROSAR/EcuM/EcuMGeneral/EcuMMainFunctionPeriod.  In which configuration does this happen: ----- In all configurations.	
<b>Resolution Description:</b> Workaround: ----- Adapt another parameter which leads to a rebuild of the SWC description, e.g. rename of a sleepmode [/EcuM/EcuMConfiguration/EcuMCommonConfiguration/EcuMSleepMode].  After rebuild the name of this sleepmode can be switched back to the old name, the rename is only necessary to trigger a rebuild.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00092623	Compiler error: fatal error: Nvm_Cfg.h: No such file or directory
<b>Component@Subcomponent:</b>	SysService_Asr4BswMCfg5@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The compiler throws the following error:	
fatal error: Nvm_Cfg.h: No such file or directory	
When does this happen:	
-----	
During compilation.	
In which configuration does this happen:	
-----	
A compiler / operating system (Linux) is used which acts case sensitive.	
AND	
A NvM module is part of the configuration.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Provide a header file Nvm_Cfg.h which includes the original file NvM_Cfg.h.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00092644 ConsistencyRT00002 after adding multiple ComStackContributions of the same type	
<b>Component@Subcomponent:</b>	Cdd_AsrCddCfg5@GenTool_GeneratorMsr
<b>First affected version:</b>	2.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
ConsistencyRT00002 is thrown	
When does this happen:	
-----	
1) you add an unnecessary ComStackContribution that voids the allowed multiplicity	
2) you remove the unnecessary ComStackContribution by delete or undo to comply with the allowed multiplicity again	
3) the above exception is thrown	
In which configuration does this happen:	
-----	
Any configuration containing the module Cdd_AsrCddCfg5	
<b>Resolution Description:</b>	
Workaround:	
-----	
Restart CFG5 and the message is gone again.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

**ESCAN00092718**      **<MSN>90005 - Generator (<Generator Name>) failure, because of an exception "exception in <Msn> generator during Validation encountered: java.lang.NullPointerException"**

**Component@Subcomponent:**      CommonAsr\_ComGenericGenLib@GenTool\_GeneratorMsr

**First affected version:**      5.01.00

**Fixed in versions:**      5.02.00

**Problem Description:**

What happens (symptoms):

-----  
During code generation, an error message similar to the following one:

[Error] <MSN>90005 - Generator (<Generator Name>) failure, because of an exception  
- Exception in <Msn> generator during Validation encountered:  
java.lang.NullPointerException

-----  
Erroneous CEs:

[DefinitionRef: /MICROSAR/<Msn>]

-----  
CEs:

[DefinitionRef: /MICROSAR/<Msn>]

-----  
AutoSolvingAction: <none>

PreferredSolvingAction: <none>

SolvingActions: <none>

-----  
GeneratorPackage: <Generator Name>(<Generator version> - com.vector.cfg.gen.<module name>)

When does this happen:

-----  
During code generation with DaVinci Configurator.

In which configuration does this happen:

-----  
Any

**Resolution Description:**

Workaround:

-----  
Use

com.vector.cfg.gen.CommonAsr\_ComGenericGenLib.data.access.GenericGenAccess.getStruct(String  
instead

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00092720 DataRenamer not working for MICROSAR Define block	
<b>Component@Subcomponent:</b>	CommonAsr_ComGenericGenLib@GenTool_GeneratorMsr
<b>First affected version:</b>	5.01.00
<b>Fixed in versions:</b>	5.02.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The data renamer does not work for the MICROSAR define block.	
When does this happen:	
-----	
During code generation with DaVinci Configurator.	
In which configuration does this happen:	
-----	
Any	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	
ESCAN00092756 Name of OBD calibrateable configuration symbols are out of date	
<b>Component@Subcomponent:</b>	Diag_Asr4Dcm@Doc_TechRef
<b>First affected version:</b>	4.01.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Within chapter 9.11.1.2 "Calibration of Supported OBD Parameter Identifier" some calibratable symbols are listed with an obsolete naming convention:	
For example "dcmCfg_Svc01SupportedIdMask" should be "Dcm_CfgSvc01SupportedIdMask".	
When does this happen:	
-----	
At ECU project setup time.	
In which configuration does this happen:	
-----	
- Calibration of supported OBD parameter identifier is supported	
<b>Resolution Description:</b>	
Workaround:	
-----	
Read the cited global const table names as if prefixed with "DcmCfg_" instead of the printed "dcmCfg_".	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	



**ESCAN00092812      Using trusted function stubs with user defined types may lead to compile error: left operand must be an l-value****Component@Subcomponent:**      Os\_CoreGen7@GenTool\_GeneratorMsr**First affected version:**      1.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
The compiler states the error message: "left operand must be an l-value" (or a similar message).

When does this happen:

-----  
The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
This happens only in scalability classes SC3 and SC4 when trusted functions are configured with trusted function stub generation and one of the parameter types of a trusted function is an array type.**Resolution Description:**

Workaround:

-----  
Use a structure instead (which may contain an array).

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00092839 Linker include files are not generated for non-AUTOSAR cores.	
<b>Component@Subcomponent:</b>	Os_CoreGen7@GenTool_GeneratorMsr
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	1.08.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Linker reports an error.	
The following sections are not defined:	
- OS_NONAUTOSAR_CORE<x>_CONST	
- OS_CORESTATUS_CORE<x>_VAR_NOCACHE_NOINIT	
Where <x> is the core ID of the non-AUTOSAR core.	
For AUTOSAR cores there are linker include files (Os_Link_Core<x>.ld) generated, which shall be used in the main linker file.	
For non-AUTOSAR cores there are no such files generated.	
When does this happen:	
-----	
Always and immediately.	
In which configuration does this happen:	
-----	
There are cores which are configured as non-AUTOSAR.	
This is also the case, if a multi-core hardware is used as a single core system.	
<b>Resolution Description:</b>	

## ESCAN00092839 Linker include files are not generated for non-AUTOSAR cores.

Workaround:

For each non-AUTOSAR core create a linker include file (e.g. Os\_Link\_Core<x>.ld) with the following content:

```
--[ Os_Link_Core<x>.ld ]-----
#if defined ( OS_LINK_CONST ) || defined ( OS_LINK_CONST_KERNEL ) || defined
( OS_LINK_CONST_KERNEL_NEAR )
.OS_NONAUTOSAR_CORE<x>_CONST ALIGN(32) :> .
_OS_NONAUTOSAR_CORE<x>_CONST_START = ADDR(.OS_NONAUTOSAR_CORE<x>_CONST);
_OS_NONAUTOSAR_CORE<x>_CONST_END = ENDADDR(.OS_NONAUTOSAR_CORE<x>_CONST);
#endif

#if defined ( OS_LINK_VAR ) || defined ( OS_LINK_VAR_KERNEL ) || defined
( OS_LINK_VAR_KERNEL_FAR ) || defined ( OS_LINK_VAR_KERNEL_FAR_NOCACHE ) || defined
( OS_LINK_VAR_KERNEL_FAR_NOCACHE_NOINIT )
.OS_CORESTATUS_CORE<x>_VAR_NOCACHE_NOINIT ALIGN(32) :> .
_OS_CORESTATUS_CORE<x>_VAR_NOCACHE_NOINIT_START =
ADDR(.OS_CORESTATUS_CORE<x>_VAR_NOCACHE_NOINIT);
_OS_CORESTATUS_CORE<x>_VAR_NOCACHE_NOINIT_END =
ENDADDR(.OS_CORESTATUS_CORE<x>_VAR_NOCACHE_NOINIT);
#endif

#ifdef OS_LINK_CONST
# undef OS_LINK_CONST
#endif

#ifdef OS_LINK_VAR
# undef OS_LINK_VAR
#endif
-----
```

Use the appropriate syntax for your compiler. For correct syntax you can look at the generated files of AUTOSAR cores.

Use the manually created linker include file(s) in the main linker file.

Resolution:

The described issue is corrected by modification of the generator.

**ESCAN00092892      Compiler error: function "EcuM\_BswErrorHook" has no prototype****Component@Subcomponent:** SysService\_Asr4EcuM@Implementation**First affected version:** 2.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
Compiler throws the following error:

function "EcuM\_BswErrorHook" has no prototype

When does this happen:

-----  
The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
Only in configurations with any PB Modules but EcuM is not configured as PB

AND

The module which uses the API EcuM\_BswErrorHook() includes 'EcuM.h' instead of 'EcuM\_BswErrorHook.h'.

**Resolution Description:**

Workaround:

-----  
Include the file 'EcuM\_Error.h' additional to the include 'EcuM.h', e.g. via a user configuration file.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

<b>ESCAN00092955</b>	<b>Compiler error: incompatible types - from 'const &lt;MSN&gt;_PCConfigType *' to 'const &lt;MSN&gt;ConfigType *const'</b>
<b>Component@Subcomponent:</b>	SysService_Asr4EcuM@GenTool_GeneratorMsr
<b>First affected version:</b>	4.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	

## ESCAN00092955 Compiler error: incompatible types - from 'const <MSN>\_PCConfigType \*' to 'const <MSN>ConfigType \*const'

What happens (symptoms):

The compiler throws an error like the following:

```
1> EcuM_Init_Cfg.c
1>GenData/EcuM_Init_Cfg.c(86): error C4133: 'initializing' : incompatible types - from 'const CanNm_PCConfigType *' to 'const EcuM_PbConfigType *const '
1>GenData/EcuM_Init_Cfg.c(87): error C4133: 'initializing' : incompatible types - from 'const EcuM_PCConfigType *' to 'const SchM_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(88): error C4133: 'initializing' : incompatible types - from 'const SchM_ConfigType *' to 'const Can_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(89): error C4133: 'initializing' : incompatible types - from 'const Can_PCConfigType *' to 'const CanIf_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(90): error C4133: 'initializing' : incompatible types - from 'const CanIf_PCConfigType *' to 'const Com_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(91): error C4133: 'initializing' : incompatible types - from 'const Com_PCConfigType *' to 'const PduR_PBConfigType *const '
1>GenData/EcuM_Init_Cfg.c(92): error C4133: 'initializing' : incompatible types - from 'const PduR_PCConfigType *' to 'const CanSM_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(93): error C4133: 'initializing' : incompatible types - from 'const CanSM_PCConfigType *' to 'const CanNm_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(103): error C4133: 'initializing' : incompatible types - from 'const CanNm_PCConfigType *' to 'const EcuM_PbConfigType *const '
1>GenData/EcuM_Init_Cfg.c(104): error C4133: 'initializing' : incompatible types - from 'const EcuM_PCConfigType *' to 'const SchM_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(105): error C4133: 'initializing' : incompatible types - from 'const SchM_ConfigType *' to 'const Can_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(106): error C4133: 'initializing' : incompatible types - from 'const Can_PCConfigType *' to 'const CanIf_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(107): error C4133: 'initializing' : incompatible types - from 'const CanIf_PCConfigType *' to 'const Com_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(108): error C4133: 'initializing' : incompatible types - from 'const Com_PCConfigType *' to 'const PduR_PBConfigType *const '
1>GenData/EcuM_Init_Cfg.c(109): error C4133: 'initializing' : incompatible types - from 'const PduR_PCConfigType *' to 'const CanSM_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(110): error C4133: 'initializing' : incompatible types - from 'const CanSM_PCConfigType *' to 'const CanNm_ConfigType *const '
```

When does this happen:

The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

In variant configurations with modules which uses different EcuC init phases in different variants (/MICROSAR/EcuC/EcucGeneral/BswInitialization/InitFunction/InitPhase).

E.g.

VARIANT\_1: InitPhase = NO\_INIT

VARIANT\_2: InitPhase = INIT\_TWO\_MCAL

### Resolution Description:

## ESCAN00092955 Compiler error: incompatible types - from 'const <MSN>\_PCConfigType \*' to 'const <MSN>ConfigType \*const

Workaround:

To resolve this the content of the `CONT EcuM_GlobalConfigRoot` in `EcuM_Init_Cfg.c` has to be reordered to fit to the struct `EcuM_GlobalConfigRootType`.

e.g.

```
CONST(EcuM_GlobalConfigRootType, ECUM_CONST) EcuM_GlobalConfigRoot =
{
{
BswM_Config_CanNm_Ptr,
EcuM_Config_CanNm_Ptr,
CanNm_Config_CanNm_Ptr,
},
{
BswM_Config_ClassB_Ptr,
CanNm_Config_ClassB_Ptr, <===== Wrong position, must be the last one
EcuM_Config_ClassB_Ptr,
},
{
BswM_Config_ClassC_Ptr,
CanNm_Config_ClassC_Ptr, <===== Wrong position, must be the last one
EcuM_Config_ClassC_Ptr,
}
};
```

typedef struct

```
{
CONSTP2CONST(BswM_ConfigType, TYPEDEF, BSWM_INIT_DATA) CfgPtr_BswM_Init;
CONSTP2CONST(EcuM_PbConfigType, TYPEDEF, ECUM_INIT_DATA) CfgPtr_EcuM_Init;
CONSTP2CONST(CanNm_ConfigType, TYPEDEF, CANNM_INIT_DATA) CfgPtr_CanNm_Init;
} EcuM_GlobalPCConfigType;
```

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00092986	Compiler error: Error directive due to inconsistent configuration of Communication Mode Info
<b>Component@Subcomponent:</b>	Cp_AsrXcp@GenTool_GeneratorMsr
<b>First affected version:</b>	3.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
<p>The following error is shown by the compiler:</p> <pre>../../../../external/bsw/xcp/Xcp.h:2442: #error "XCP consistency error: Communication mode info should be enabled when using block download."</pre>	
When does this happen:	
-----	
<p>The error is issued by the compiler during compilation of the code in case the configuration is as described below.</p>	
In which configuration does this happen:	
-----	
<p>This happens in configurations where</p> <ul style="list-style-type: none"> <li>- Xcp Block Download (/MICROSAR/Xcp/XcpGeneral/XcpBlockDownload) is enabled</li> </ul> <p>AND</p> <ul style="list-style-type: none"> <li>- Xcp Communication Mode Info (/MICROSAR/Xcp/XcpGeneral/XcpCommunicationModeInfo) is disabled.</li> </ul>	
<b>Resolution Description:</b>	
Workaround:	
-----	
<p>Enable Xcp Communication Mode Info (/MICROSAR/Xcp/XcpGeneral/XcpCommunicationModeInfo)</p>	
Resolution:	
-----	
<p>The described issue is corrected by modification of all affected work-products.</p>	



ESCAN00092995 CAN-FD message without BRS will not be received	
<b>Component@Subcomponent:</b>	DrvCan_Mpc5700McanLI@Implementation
<b>First affected version:</b>	2.09.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
A CAN-FD message without Bitrate Switching will:	
- not be received by the upper layers.	
- produce a DET Error (CAN_E_PARAM_DLC) for messages with a DLC greater than 8 bytes.	
When does this happen:	
-----	
During runtime,	
always and immediately,	
when a CAN-FD message is received without Bitrate Switching (CAN-FD BRS bit) set.	
In which configuration does this happen:	
-----	
Only in configurations using CAN-FD Rx messages without Bitrate switching.	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093023 RTE Analyzer sporadically triggers windows application crash dialog	
<b>Component@Subcomponent:</b>	Rte_Analyzer@Application
<b>First affected version:</b>	0.07.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms): ----- Windows issues a message box MICROSAR RTE Analyzer (Beta) has stopped working.  If started on the console, the console might contain additional message "free from wrong pool during global destruction"	
When does this happen: ----- This happens after RTE Analyzer terminated itself.	
In which configuration does this happen: ----- This happens independent of the used configuration.	
<b>Resolution Description:</b>	
Workaround: ----- Set the environment variable KOMODO_VERSION to 1 before starting MicrosarRteAnalyzer Example:  set KOMODO_VERSION=1 MicrosarRteAnalyzer -c config.json -o outputDirectory	
Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00093048 RTE generator generates unused Rte_TrustedCom_SendSignal	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.06.00
<b>Fixed in versions:</b>	1.14.00, 1.13.01
<b>Problem Description:</b> What happens (symptoms): ----- RTE generator generates an API Rte_TrustedCom_SendSignal that is never called.  When does this happen: ----- During generation.  In which configuration does this happen: ----- This happens when memory protection is used and when the configuration contains sender-receiver communication with receiver components that do not have port accesses for the received data elements.	
<b>Resolution Description:</b> Workaround: ----- Configure read accesses in the receiver component.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00093079</b> <b>*_GLOBALSHARED_VAR_NOCACHE_* defines are used by Rte_MemMap.h but not generated by Os_MemMap.h.</b>	
<b>Component@Subcomponent:</b>	Os_CoreGen7@GenTool_GeneratorMsr
<b>First affected version:</b>	1.01.05
<b>Fixed in versions:</b>	1.08.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Sources do not compile, the MemMap defines *_GLOBALSHARED_VAR_NOCACHE_* are used by Rte_MemMap.h, but they are not provided by the Os_MemMap.h.	
When does this happen:	
-----	
During compile time.	
Always and immediately	
In which configuration does this happen:	
-----	
In every configuration where explicit linkage is used.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Use the OS generated define instead.	
Resolution:	
-----	
Provide compatibility define.	

ESCAN00093109 Missing Limitation for aggregated measurement data size of < 64KB	
<b>Component@Subcomponent:</b>	Cp_AsrXcp@Doc_TechRef
<b>First affected version:</b>	2.01.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The Xcp has a limitation that limits the aggregated data size during DAQ measurement to < 64KB. This is currently not documented and mostly relevant for Linux systems.	
When does this happen:	
-----	
Always and immediately	
In which configuration does this happen:	
-----	
all configurations	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093110      Service 0x2F: ECU sends NRC 0x10 to a valid IO control DID request	
<b>Component@Subcomponent:</b>	Diag_Asr4Dcm@GenTool_GeneratorMsr
<b>First affected version:</b>	7.01.00
<b>Fixed in versions:</b>	7.02.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The ECU sends NRC 0x10 (GeneralReject) on a validly formatted service 0x2F (IoControlByIdentifier).	
When does this happen:	
-----	
<ul style="list-style-type: none"> <li>- At runtime when a valid request to control an IO-DID is sent to the ECU</li> </ul> AND	
<ul style="list-style-type: none"> <li>- The requested IO-DID uses S/R (Sender/Receiver) communication</li> </ul> AND	
<ul style="list-style-type: none"> <li>- The application needs more time to prepare the final result of the requested operation (i.e. the IoControlResponse data of the corresponding S/R port is written at a later time)</li> </ul>	
In which configuration does this happen:	
-----	
Any configuration that specifies all IO-DIDs to use S/R communication.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Define at least one IO-DID to use application function call interface with asynchronous data access i.e. parameter /Dcm/DcmConfigSet/DcmDsp/DcmDspData/DcmDspDataUsePort == USE_DATA_ASYNCH_CLIENT_SERVER or USE_DATA_ASYNCH_FNC	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093127 RTE generator does not create IOCs in the OS configuration for single core systems	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	1.13.01, 1.14.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The RTE uses IOCs from the OS but the generator does not add the IOCs to the OS configuration.	
When does this happen:	
-----	
During generation.	
In which configuration does this happen:	
-----	
This happens when memory protection is used and when there are N:1 client-server or sender-receiver communication with multiple sending OS applications.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Manually configure the IOCs in the OS configuration.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

**ESCAN00093144      Class cast exception when the configuration contains a subelement mapping for application datatypes****Component@Subcomponent:**      Rte\_Asr4@GenTool\_GeneratorMsr**First affected version:**          4.09.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
RTE generator reports an error message Rte90005

Exception in Rte generator during Calculation encountered:

java.lang.ClassCastException:

com.vector.cfg.model.mdf.impl.ar4x.swcomponenttemplate.portinterface.VMApplicationComposition  
cannot be cast to

com.vector.cfg.model.mdf.ar4x.swcmponenttemplate.portinterface.MIImplementationDataTypeSubE

When does this happen:

-----  
During generation.

In which configuration does this happen:

-----  
This happens when the configuration contains a connection between a delegation port with  
application record type

and a component port with a primitive application datatype.

Moreover a subelement mapping needs to be configured for the connection.

**Resolution Description:**

Workaround:

-----  
Either use implementation datatypes for the subelement mapping

or

create a wrapper SWC that converts the data from the record type to a primitive type

or

receive the full record in the application SWC.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.



**ESCAN00093236      Compiler error: OS does not compile if only application specific hooks are configured.****Component@Subcomponent:**      Os\_CoreGen7@GenTool\_GeneratorMsr**First affected version:**          1.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
There are compilation error if only application specific hooks (no global hooks) are configured.

ctc E272: ["GenData/Os\_Hal\_Context\_Lcfg.c" 274/38] undeclared identifier

"OsCfg\_Stack\_OsCore0\_Startup\_Dyn"

1&gt; ctc E245: ["GenData/Os\_Hal\_Context\_Lcfg.c" 274/38] invalid type for left operand of subscript

1&gt; ctc E244: ["GenData/Os\_Hal\_Context\_Lcfg.c" 274/38] invalid operand types for + operator

1&gt; ctc E245: ["GenData/Os\_Hal\_Context\_Lcfg.c" 275/37] invalid type for left operand of subscript

1&gt; ctc E244: ["GenData/Os\_Hal\_Context\_Lcfg.c" 275/37] invalid operand types for + operator

1&gt; ctc E306: ["GenData/Os\_Hal\_Context\_Lcfg.c" 274/29] initializer must be constant

1&gt; ctc E306: ["GenData/Os\_Hal\_Context\_Lcfg.c" 275/29] initializer must be constant

When does this happen:

-----  
If only application specific hooks and no system hook is configured.

In which configuration does this happen:

-----  
SC3/SC4**Resolution Description:**

Workaround:

-----  
Configure dummy system hooks.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

<b>ESCAN00093294 Invalid key accepted due to inconsistent Csm and CryFord job processing configuration</b>	
<b>Component@Subcomponent:</b>	Diag_AsrSwcSecAccess_Ford@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
SecurityAccess_FunctionFinish() declares key as valid even if the verification has failed.	
When does this happen:	
-----	
While processing the security access key.	
In which configuration does this happen:	
-----	
If configured Csm job processing type and CryFord job processing type are inconsistent. E.g. Csm configured for sync job processing and CryFord for async processing.	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093309 RTE Analyzer fails due to duplicated mainfunction	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.13.00
<b>Fixed in versions:</b>	1.13.01, 1.14.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
RTE Analyzer aborts with an error message.	
Compiling...	
Linking...	
ERROR: Linking globals named 'WdgM_MainFunction': symbol multiply defined!	
When does this happen:	
-----	
The error is issued by RTE Analyzer during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
This happens when the configuration contains service components and BSW modules with different names and the same executable entity names.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Duplicate the RteAnalyzerConfiguration.json and remove the source file that contains the duplicated mainfunction from the SourceFileList (WdgM.c). Keep the source file of the service SWC (WdgM_OsApplicationTrustedC0).	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093317 Value Calculations does not act as expected	
<b>Component@Subcomponent:</b>	CommonAsr_ComGenericGenLib@GenTool_GeneratorMsr
<b>First affected version:</b>	2.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b> What happens (symptoms): ----- An Value Calculation has only influence to values which are added to the ComStackLib. The values of the Define Creator are directly taken from the corresponding EcuC parameter. Furthermore, Value Calculations for references (i.e convert a reference to an integer of the target) do not work either.  When does this happen: ----- Always during the generation  In which configuration does this happen: ----- Generators which uses ValueCalculators for parameters which are created by the Microsar Define creator. or Value calculation is used for a reference	
<b>Resolution Description:</b> Workaround: ----- Use a struct extender / custom #define for the DefRef and blacklist the DefRef instead  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

## ESCAN00093405 Auto Configuration - Invalid multiplicity after manual adaptations of container BswMAvailableActions

**Component@Subcomponent:** SysService\_Asr4BswMCfg5@GenTool\_GeneratorMsr

**First affected version:** 10.00.00

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

-----

User-modifications about a changed BswMAvailableActions subcontainer are recognized by the Auto Configuration assistant but even if they should be kept, the assistant will re-create the original action. This leads to an invalid model because the user modification is not removed by the assistant.

Example:

- Configure Communication Control is used and Reinitialize TX is turned ON, Finish is clicked.
- the /MICROSAR/BswM/BswMConfig/BswMModeControl/BswMAAction CC\_EnableDM\_<I-PDU-Group> has a BswMDeadlineMonitoringControl container which is deleted within the Basic Editor
- Instead another BswMAvailableActions subcontainer is created of another type, e.g.

BswMComMMModelimitation

- Configure Communication Control is used once again and Finish is clicked. An option is offered to either keep this modification or to restore it, but independent of the choice, the original BswMDeadlineMonitoringControl is restored without removing the user modification. Because the user modification is not removed the multiplicity of the container BswMAvailableActions[0...1] is violated.

When does this happen:

-----

During the configuration with DaVinci Configurator in the BSW Management Editor in the following sequence:

- Configure <Auto Configuration> is clicked
- Finish is clicked
- Some objects like a /MICROSAR/BswM/BswMConfig/BswMModeControl/BswMAAction/BswMAvailableActions/BswMDeadlineMonitoringControl container are deleted or changed
- Configure <Auto Configuration> is clicked once again
- Finish is clicked
- the dialog 'Manual Adaptions' does pop up
- Finish is clicked in the 'Manual Adaptions' dialog

In which configuration does this happen:

-----

Any configuration using one of the Auto Configurations in BSW Management in DaVinci Configurator

### Resolution Description:

Workaround:

-----

Redo the previously manual changes that have been overwritten.

Resolution:

-----

The described issue is corrected by modification of all affected work-products.

**ESCAN00093413      Auto Configuration Module Initialization - Changed User Include Files always restores****Component@Subcomponent:** SysService\_Asr4BswMCfg5@GenTool\_GeneratorMsr**First affected version:** 2.00.01**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----

If the EcuM\_Init\_PBCfg.h entry in the User Config File (/MICROSAR/BswM/BswMGeneral/BswMUserIncludeFiles/BswMUserIncludeFile) list is overwritten by some other value or being replaced, it is being restored after the Module Configuration Auto Configuration is applied again and the other value might be removed.

When does this happen:

-----

During the configuration with DaVinci Configurator in the BSW Management Editor in the following sequence:

- Configure Module Initialization is clicked
- Finish is clicked
- One of the /MICROSAR/BswM/BswMGeneral/BswMUserIncludeFiles/BswMUserIncludeFile has the value EcuM\_Init\_PBCfg.h, this one is being changed or deleted.
- Configure Module Initialization is clicked once again
- Finish is clicked
- the dialog 'Manual Adaptions' does not pop up or it pops up but the change is not displayed
- Finish is clicked in the 'Manual Adaptions' dialog if it is displayed

In which configuration does this happen:

-----

Any configuration using the Module Initialization Auto Configurations in BSW Management in DaVinci Configurator

AND

EcuM is configured as Postbuild Loadable or Postbuild Selectable

**Resolution Description:**

Workaround:

-----

Redo the previously manual changes that have been overwritten.

Resolution:

-----

The described issue is corrected by modification of all affected work-products.

<b>ESCAN00093449      A2L compu method RTE_CM_BOOLEAN cannot be used to calibrate boolean values</b>	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Only FALSE can be selected in calibration tools for boolean calibration values	
When does this happen:	
-----	
During calibration	
In which configuration does this happen:	
-----	
If calibration is configured for a boolean element	
<b>Resolution Description:</b>	
Workaround:	
-----	
Configure an integer element with a dedicated compu method instead of a boolean element.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093455      Compile error in PduR: <CDD>_Transmit is not defined	
<b>Component@Subcomponent:</b>	Cdd_AsrCddCfg5@GenTool_GeneratorMsr
<b>First affected version:</b>	2.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compile error in PduR: <CDD>_Transmit is not defined.	
This mandatory API is not defined by CDD	
When does this happen:	
-----	
compile time	
In which configuration does this happen:	
-----	
A CddPduRLowerLayerRxPdu but no CddPduRLowerLayerTxPdu is configured.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Define the missing API in memmap.h, the section for the define <CDD>_START_SEC_CODE	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	



ESCAN00093463 Wrong generated MemMap.h file for Gen7 Os	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.13.00
<b>Fixed in versions:</b>	1.13.01, 1.14.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The compiler reports #error "MemMap.h, wrong pragma command"	
When does this happen:	
-----	
The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
This happens in configurations with Gen7 OS.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Change the template content of the generated <Swc>_MemMap.h files.	
The changes will not be overwritten by a later generation step	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093469 Compiler error: 'retVal' undeclared identifier	
<b>Component@Subcomponent:</b>	Ccl_Asr4ComMCfg5@GenTool_GeneratorMsr
<b>First affected version:</b>	7.00.00
<b>Fixed in versions:</b>	8.01.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Functions ComM_RequestBusSMMode and ComM_GetCurrentBusSMMode in file ComM_Lcfg.c use an undeclared variable retVal.	
Typical compiler error explanations may be:	
..\comm_lcfg.c: error C2065: 'retVal' : undeclared identifier	
When does this happen:	
-----	
The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
1) Only one ComM channel exists and the channel has ComM/ComMConfigSet/ComMChannel/ComMBusType == COMM_BUS_TYPE_INTERNAL	
Note, this is an unusual use-case.	
AND	
2) ComM/ComMGeneral/ComMDevErrorDetect == true	
<b>Resolution Description:</b>	
Workaround:	
-----	
Set ComM/ComMGeneral/ComMDevErrorDetect to false if possible, otherwise no workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00093491</b>	<b>Compiler error: identifier PduR_GetBmTxBufferIndRomStartIdxOfRmGDestRon is undefined</b>
<b>Component@Subcomponent:</b>	Gw_AsrPduRCfg5@GenTool_GeneratorMsr
<b>First affected version:</b>	11.00.00
<b>Fixed in versions:</b>	11.01.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Missing validation of PduRDestPduQueueDepth in case of communication interface routing	
If a communication interface gateway routing path with a dedicated buffer reference is configured and the "PduRDestPduQueueDepth" parameter does not exist, no validation error is reported.	
When does this happen:	
-----	
The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
- Communication Interface gateway routings with TxBuffer References and the /MICROSAR/PduR/PduRRoutingTables/PduRRoutingTable/PduRRoutingPath/PduRDestPdu/PduRDestPduQueueDepth is not configured.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Create/Set the corresponding PduRDestPduQueueDepth parameter manually.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

## ESCAN00093494 Compiler error: OS event not created for inactive/unconnected server runnables

**Component@Subcomponent:** Rte\_Core@Implementation

**First affected version:** 1.00.00

**Fixed in versions:** 1.14.00

### Problem Description:

What happens (symptoms):

-----  
Compilation fails because an RTE TASK contains code that checks for an OS event

```
if ((ev & Rte_Ev_Run_XXXX) != (EventMaskType)0)
{
}
```

The OS event is not created by the RTE generator.

When does this happen:

-----  
The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
This happens when a mapped server runnable uses implicit APIs (e.g. has access to an IRV with buffered communication) and the corresponding server port is not connected or the server runnable is not active.

### Resolution Description:

Workaround:

-----  
Manually create the OS event in the OS configuration.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00093502      Technical Reference: Wrong API description for Csm_SymKeyExtractStart	
<b>Component@Subcomponent:</b>	SysService_AsrCsm@Doc_TechRef
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
On TechnicalReference_Csm, Csm_SymKeyExtractStart prototype is	
Csm_ReturnType Csm_SymKeyExtractStart (Csm_ConfigIdType cfgId, const Csm_SymKeyType	
*keyPtr)	
But has to be	
FUNC( Csm_ReturnType, CSM_CODE ) Csm_SymKeyExtractStart( Csm_ConfigIdType cfgId )	
There is no second parameter.	
When does this happen:	
-----	
-	
In which configuration does this happen:	
-----	
-	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093539 RTE49999 when SWC template generation tries to delete write protected files	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	1.14.00, 1.13.01
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
SWC template generation aborts with an error message RTE49999 An unexpected error occurred.	
When does this happen:	
-----	
This happens when SWC templates are generated and the templates are write protected.	
In which configuration does this happen:	
-----	
Always	
<b>Resolution Description:</b>	
Workaround:	
-----	
Remove the write protection from the SWC template files.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093569      The IOC const WriteOutParameters causes error in build	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.02.00
<b>Fixed in versions:</b>	1.13.01, 1.14.00
<b>Problem Description:</b> What happens (symptoms): ----- The IOC const WriteOutParameters causes error in build. Error: argument of type "<DataTypeName> *" is incompatible with parameter of type "const <DataTypeName> *"	
When does this happen: ----- The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen: ----- In configurations with Client/Server-Communication over processors cores with EnforceIOC enabled. OR In configurations with Client/Server-Communication with more than one Client on different OsApplications.	
<b>Resolution Description:</b> Workaround: ----- No workaround available.	
Resolution: ----- The described issue is corrected by modification of all affected work-products.	

## ESCAN00093579 Incorrect usage of Det

**Component@Subcomponent:** SysService\_Asr4WdM@Implementation

**First affected version:** 5.00.00

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

-----  
The component WdgM does not use the Det module as default. Instead of using Det a module Appl\_Det module must be integrated.

Furthermore the second parameter of API (Appl\_)Det\_ReportError uses vendor id instead of instance id according to AUTOSAR.

When does this happen:

-----  
Always if Det (Appl\_Det) is enabled and an error is reported

In which configuration does this happen:

-----  
If the following parameter is enabled and an runtime / Det error is detected:  
- /MICROSAR/WdgM/WdgMGeneral/WdgMDevErrorDetect == true

### Resolution Description:

Workaround:

-----  
Include the Det.h in customer / user file Appl\_Det.h

Redefine the API Appl\_Det\_ReportError to Det\_ReportError, do not use the second parameter and define the second parameter to 0.

Example:

```
#include "Det.h"
```

```
#define Det_Appl_Det_ReportError(ModuleId, VendorIf, ApiId, ErrorId)
DetStub_ReportError( ModuleId, InstanceID, ApiId, ErrorId) Det_ReportError(ModuleId, 0, ApiId,
ErrorId )
```

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.



ESCAN00093580 Incorrect usage of Det	
<b>Component@Subcomponent:</b>	If_Asr4IfWd@Implementation
<b>First affected version:</b>	5.00.00
<b>Fixed in versions:</b>	5.02.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The component WdgIf does not use the Det module as default. Instead of using Det a module Appl_Det module must be integrated.	
Furthermore the second parameter of API (Appl_)Det_ReportError uses vendor id instead of instance id according to AUTOSAR.	
When does this happen:	
-----	
Always if Det (Appl_Det) is enabled and an error is reported	
In which configuration does this happen:	
-----	
If the following parameter is enabled and an runtime / Det error is detected:	
- /MICROSAR/WdgIf/WdgIfGeneral/WdgIfDevErrorDetect == true	
<b>Resolution Description:</b>	
Workaround:	
-----	
Include the Det.h in customer / user file Appl_Det.h	
Redefine the API Appl_Det_ReportError to Det_ReportError, do not use the second parameter and define the second parameter to 0.	
Example:	
#include "Det.h"	
#define Det_Appl_Det_ReportError(ModuleId, VendorIf, ApiId, ErrorId)	
DetStub_ReportError( ModuleId, InstanceID, ApiId, ErrorId) Det_ReportError(ModuleId, 0, ApiId, ErrorId )	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

## ESCAN00093633 Compiler error: Mismatch between expected and generated trusted function signature

**Component@Subcomponent:** Os\_CoreGen7@GenTool\_GeneratorMsr

**First affected version:** 1.00.00

**Fixed in versions:** 1.08.01

### Problem Description:

What happens (symptoms):

-----  
A compiler error occurs if the user configures a trusted function 'IN' parameter with datatype like "const uint32\*".

An error message like the following is shown:

"argument of type "uint32 \*" is incompatible with parameter of type "uint32"".

When does this happen:

-----  
The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
If any /MICROSAR/Os/OsApplication/OsApplicationTrustedFunction/OsTrustedFunctionParam exists with

/MICROSAR/Os/OsApplication/OsApplicationTrustedFunction/OsTrustedFunctionParam/

OsTrustedFunctionParamDirection set to 'IN' and

/MICROSAR/Os/OsApplication/OsApplicationTrustedFunction/OsTrustedFunctionParam/

OsTrustedFunctionParamDataType with "const <type> \*".

### Resolution Description:

Workaround:

-----  
The issue can be circumvented by adding the "const" keyword for a second time.

E.g. instead of "const uint32 \*", configure OsTrustedFunctionParamDataType with "const const uint32 \*".

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00093634 CAN-FD format (Bosch V1.0, ISO-11898) inconsistent	
<b>Component@Subcomponent:</b>	DrvCan_Mpc5700McanAsr@GenTool_GeneratorMsr
<b>First affected version:</b>	3.00.01
<b>Fixed in versions:</b>	
<b>Problem Description:</b> What happens (symptoms): ----- After changing the Mcan Revision to M_CAN_REV_315 the parameter CanFd NISO is grey'ed and cannot be edited. This is not correct for M_CAN_REV_315 as for this revision both CAN-FD formats are available.  When does this happen: ----- During configuration time.  In which configuration does this happen: ----- In every configuration.	
<b>Resolution Description:</b> Workaround: ----- Mark CanFd NISO parameter as "Set user defined", configure the parameter as required, mark CanFd NISO parameter as "Set NOT user defined".  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00093638      Linking fails if the configuration contains many software components	
<b>Component@Subcomponent:</b>	Rte_Analyzer@Application
<b>First affected version:</b>	0.05.00
<b>Fixed in versions:</b>	0.09.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
RTE Analyzer aborts with a linking failed error message because the commandline is too long.	
When does this happen:	
-----	
During analysis with RTE Analyzer.	
In which configuration does this happen:	
-----	
When the configuration contains many software components.	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

## ESCAN00093650 Generation of RTE Analyzer stubs fails due to invalid characters in object descriptions

**Component@Subcomponent:** Rte\_Core@Implementation

**First affected version:** 1.09.00

**Fixed in versions:** 1.14.00, 1.13.01

### Problem Description:

What happens (symptoms):

-----  
RTE generator fails to generate the RTE Analyzer stubs.

When does this happen:

-----  
During generation.

In which configuration does this happen:

-----  
This happens when the description for configuration objects contain special characters like ", \$, %, @;

### Resolution Description:

Workaround:

-----  
Do not use the special characters ", @, %, \$ in descriptions.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

## ESCAN00093653 Compiler error: CheckDetErrorContinue function call uses optimized away trigger disabling flag

**Component@Subcomponent:** Rte\_Core@Implementation

**First affected version:** 1.13.00

**Fixed in versions:** 1.13.01, 1.14.00

### Problem Description:

What happens (symptoms):

-----  
The compiler reports undeclared identifier "Rte\_TriggerDisableMaxCount\_<Name>"

When does this happen:

-----  
The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
In configurations with ModeDisablings and active DET.

### Resolution Description:

Workaround:

-----  
No workaround available.

ESCAN00093654      Compiler error: Redefinition of Sender/Receiver data element declaration	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.07.00
<b>Fixed in versions:</b>	1.13.01, 1.14.00
<b>Problem Description:</b> What happens (symptoms): ----- The compiler reports redefinition of "Read_<PortName>_<DataElementName>" or "Receive_<PortName>_<DataElementName>" variable.  When does this happen: ----- The error is issued by the compiler during compilation of the code in case the configuration is as described below.  In which configuration does this happen: ----- This happens in configurations with Sender/Receiver communication where the PortName and DataElementName is used multiple times.	
<b>Resolution Description:</b> Workaround: ----- Rename the PortName of the ports involved in the Sender/Receiver communication.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00093656 Compiler error: Redefinition of enumeration data type	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.10.00
<b>Fixed in versions:</b>	1.13.01, 1.14.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The compiler reports redefinition of "<VariableName>_V_<Count>" variable.	
When does this happen:	
-----	
The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
This happens in configurations where the enumeration data type is used in different software components without LiteralPrefix.	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00093669</b>		<b>Compiler error: Identifier OSError_GetScheduleTableStatus_ScheduleStatus not defined.</b>
<b>Component@Subcomponent:</b>	Os_CoreGen7@Implementation	
<b>First affected version:</b>	1.00.00	
<b>Fixed in versions:</b>		
<b>Problem Description:</b>		
What happens (symptoms):		
-----		
The compiler states an error message like: Identifier OSError_GetScheduleTableStatus_ScheduleStatus not defined.		
When does this happen:		
-----		
The error is issued by the compiler during compilation of the code in case the API function OSError_GetScheduleTableStatus_ScheduleStatus shall be used.		
In which configuration does this happen:		
-----		
This happens only in configurations where schedule tables are used.		
<b>Resolution Description:</b>		
Workaround:		
-----		
No workaround available.		
Resolution:		
-----		
The described issue is corrected by modification of all affected work-products.		



<b>ESCAN00093692</b>	<b>Auto Configuration dialog shows an empty message about "Manual Adaptations" after finishing the Auto Configuration.</b>
<b>Component@Subcomponent:</b>	SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
<b>First affected version:</b>	10.00.00
<b>Fixed in versions:</b>	11.00.00
<b>Problem Description:</b>	
What happens (symptoms):	
----- The Auto Configuration dialog shows an empty message about "Manual Adaptations" after finishing the Auto Configuration.	
When does this happen:	
-----	
After finishing the Auto Configuration dialog and one feature (e.g. one specific channel in Auto Configuration Communication Control) is unselected.	
In which configuration does this happen:	
-----	
In all configurations which use an Auto Configuration.	
<b>Resolution Description:</b>	
Workaround:	
-----	
The manual change, e.g. switch from RefValueA to RefValueB has to be reverted manually.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093765 Compiler error: Rte_ComSendSignalProxyPeriodic accesses missing variable	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.03.00
<b>Fixed in versions:</b>	1.14.00, 1.13.01
<b>Problem Description:</b> What happens (symptoms): ----- Compilation fails because Rte_ComSendSignalProxyPeriodic accesses a variable that is not part of Rte.c  When does this happen: ----- The error is issued by the compiler during compilation of the code in case the configuration is as described below.  In which configuration does this happen: ----- This happens when the configuration contains senders that are not mapped to the partition that contains the BSW and when the configuration contains no internal sender-receiver connections.	
<b>Resolution Description:</b> Workaround: ----- Create an internal sender-receiver connection.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00093785 Mirror component Transmission pathways are not detected correctly	
<b>Component@Subcomponent:</b>	Gw_AsrPduRCfg5@GenTool_GeneratorMsr
<b>First affected version:</b>	10.01.00
<b>Fixed in versions:</b>	11.01.00
<b>Problem Description:</b> What happens (symptoms): ----- A Tx forwarding where the upper layer is a "/MICROSAR/Mirror" are not detected correctly and a routing is not created by a solving action. The validation reports an error that a routing path is incomplete. See workaround.  When does this happen: ----- Always and immediately during configuration  In which configuration does this happen: ----- Configuration where a "/MICROSAR/Mirror" upper layer is involved in a routing	
<b>Resolution Description:</b> Workaround: ----- Configure the routing path manually.  Refer the appropriate Pdu as source and destination Pdu to the routing. Set Dest Pdu direction to Transmit and the Data Provision to PDUR_DIRECT and the DestPduRoutingType to API_FORWARDING. This parameter must be defined via "user define"  see also TechnicalReference_Mirror.pdf Version 1.0.0 chapter "Configure the destination channel"  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00093839      CFG5 Exception in <MSN> generator during Generation encountered and no files are generated	
<b>Component@Subcomponent:</b>	CommonAsr_ComStackLib@GenTool_GeneratorMsr
<b>First affected version:</b>	4.00.00
<b>Fixed in versions:</b>	8.05.01, 8.06.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
CFG5 shows the following error message "Exception in <MSN> generator during Generation encountered" and no files are generated.	
The detailed error description is: java.lang.NullPointerException	
When does this happen:	
-----	
at generation time.	
In which configuration does this happen:	
-----	
Any configuration where the postbuild-selectable support is enabled for this module AND the generator uses the API setRequiresIndexUsedArray() with the parameter true.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Deactivate ComStackLib based optimizations if configurable and try to generate again.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00093969 Missing Dem_[Dcm]ClearDTC in list of required DEM API	
<b>Component@Subcomponent:</b>	Diag_Asr4Dcm@Doc_TechRef
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Missing information that Dem_[Dcm]ClearDTC is also a required API.	
When does this happen:	
-----	
Reading technical reference.	
In which configuration does this happen:	
-----	
N/A	
<b>Resolution Description:</b>	
Workaround:	
-----	
Consider Dem_[Dcm]ClearDTC() to be a required API by DCM.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00094010 Compiler error: Redefinition of data handle entry in component data structure for PR Ports using implicit communication	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.05.00
<b>Fixed in versions:</b>	1.13.01
<b>Problem Description:</b> What happens (symptoms): ----- A compiler error occurs due to a redefinition of a data handle entry in the component data structure for PR Ports using implicit communication  Typical compiler error explanations may be: 'struct' member redefinition  When does this happen: ----- The error is issued by the compiler during compilation of the code in case the configuration is as described below.  In which configuration does this happen: ----- This happens for configurations using - PR Ports - implicit read AND implicit write access - object code components OR multiple instantiated SWC leading to the usage of the component data structure	
<b>Resolution Description:</b> Workaround: ----- No workaround available.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00094026 Compiler error: Missing extern declaration for Rte_InitState	
<b>Component@Subcomponent:</b>	Rte_Core@Implementation
<b>First affected version:</b>	1.07.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compilation fails because Rte_InitState has no extern declaration.	
When does this happen:	
-----	
The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
This happens when a task contains schedulable entities and background triggered runnables.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Set the parameter /MICROSAR/Rte/RteGeneration/RteDevErrorDetectUninit to true.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

## 2.6 Compiler Warnings

As a service we also provide the known compiler warnings. The occurrence of a compiler warning may depend on the used software module configuration and compiler settings.

### Index

<a href="#">ESCAN00051574</a>	[MSR4 only] Compiler warning: statement is unreachable SysService_AsrDet@Implementation
<a href="#">ESCAN00055307</a>	Compiler warning: unused static function "XcpMemClr" Cp_AsrXcp@Implementation
<a href="#">ESCAN00065890</a>	Compiler warning: cast discards '___attribute__((noreturn))' qualifier from pointer target type DrvCan_Mpc5700McanLI@Implementation
<a href="#">ESCAN00065891</a>	Compiler warning: cast increases required alignment of target type DrvCan_Mpc5700McanLI@Implementation
<a href="#">ESCAN00067159</a>	Compiler warning: cast truncates constant value MemService_AsrNvM@Implementation
<a href="#">ESCAN00067161</a>	Compiler warning: conditional expression is constant IL_AsrComCfg5@Implementation
<a href="#">ESCAN00067237</a>	Compiler warning: large type was implicitly cast to small type If_AsrIfCan@Implementation
<a href="#">ESCAN00068402</a>	Compiler warning: conditional expression or part of it is always true/false DrvTrans_Tja1043CandioAsr@Implementation
<a href="#">ESCAN00068434</a>	Compiler warning: conditional expression or part of it is always true/false DrvCan__coreAsr@Implementation
<a href="#">ESCAN00068435</a>	Compiler warning: narrowing or signed-to-unsigned type conversion found: unsigned int to unsigned char MemService_AsrNvM@Implementation
<a href="#">ESCAN00068872</a>	Compiler warning: the order of volatile accesses is undefined in this statement DrvCan__coreAsr@Implementation
<a href="#">ESCAN00074793</a>	Compiler warning: Condition is always constant Diag_Asr4Dem@Implementation
<a href="#">ESCAN00076827</a>	Compiler warning: Prototypes for Sector Info not present Cp_AsrXcp@GenTool_GeneratorMsr
<a href="#">ESCAN00078543</a>	Compiler warning: statement is unreachable when Calibration is deactivated Cp_AsrXcp@Implementation
<a href="#">ESCAN00081459</a>	Compiler warning: function "ApplCanTimerLoop" was declared but never referenced DrvCan__coreAsr@Implementation
<a href="#">ESCAN00086596</a>	Compiler warning: used wrong Memory class qualifier in several functions Gw_AsrPduRCfg5@Implementation
<a href="#">ESCAN00086650</a>	Compiler warning: pointless comparison of unsigned integer with zero SysService_AsrCsm@Implementation
<a href="#">ESCAN00087235</a>	Compiler warning: variable "lErrorId" was declared but never referenced Tp_Asr4TpCan@Implementation
<a href="#">ESCAN00087501</a>	Compiler warning: "signed/unsigned mismatch" due to missing cast in 0:N or 1:N indirections CommonAsr_ComStackLib@GenTool_GeneratorMsr
<a href="#">ESCAN00087536</a>	Compiler warning: 'function' : conversion from 'const <SomeType>' to '<AnotherType>', possible loss of data CommonAsr_ComStackLib@GenTool_GeneratorMsr
<a href="#">ESCAN00088061</a>	BswM_Lcfg.c: warning: 'function' : conversion from 'const BswM_ImmediateUserStartIdxOfModeReqeustMappingType' to 'BswM_SizeOfImmediateUserType', possible loss of data SysService_Asr4BswMCfg5@GenTool_GeneratorMsr



## Index

<a href="#">ESCAN00088362</a>	Compiler warning: "cast truncates constant value" with signed data CommonAsr_ComStackLib@GenTool_GeneratorMsr
<a href="#">ESCAN00089241</a>	Compiler warning: multiple warnings SysService_CryptoCv@Impl_actCLib
<a href="#">ESCAN00089425</a>	Compiler warning: missing braces around initializer SysService_CryptoCv@Impl_ESLib
<a href="#">ESCAN00089543</a>	Compiler warning: dead assignment to "errorId" eliminated Nm_Asr4NmIf@Implementation
<a href="#">ESCAN00089544</a>	Compiler warning: conversion to 'uint8' from 'int' may alter its value Nm_Asr4NmIf@Implementation
<a href="#">ESCAN00089619</a>	Compiler warning: last line of file ends without a newline Diag_Asr4Dem@Implementation
<a href="#">ESCAN00090108</a>	Compiler warning: function "PduR_Init_Rpg" was declared but never referenced Gw_AsrPduRCfg5@Implementation
<a href="#">ESCAN00090113</a>	Compiler Warning: Result of function-call is ignored SysService_CryptoCv@Impl_ESLib
<a href="#">ESCAN00090114</a>	Compiler Warning: Assignment in condition SysService_CryptoCv@Impl_actCLib
<a href="#">ESCAN00090161</a>	Compiler warning: condition evaluates always to true/false Ccl_Asr4ComMCfg5@Implementation
<a href="#">ESCAN00090806</a>	Compiler warning: C4310: cast truncates constant value Gw_AsrPduRCfg5@Implementation
<a href="#">ESCAN00090831</a>	Compiler warning: integer conversion resulted in a change of sign Il_AsrComCfg5@Implementation
<a href="#">ESCAN00090874</a>	Compiler warning: DEM_CFG_SUPPORT_NVM_POLLING undefined Diag_Asr4Dem@Implementation
<a href="#">ESCAN00091295</a>	Compiler warning: dead assignment / variable set but not used Ccl_Asr4ComMCfg5@Implementation
<a href="#">ESCAN00091340</a>	Compiler warning: cast truncates constant value If_AsrIfCan@Implementation
<a href="#">ESCAN00091343</a>	Compiler warning: warning C4310: cast truncates constant value If_AsrIfCan@Implementation
<a href="#">ESCAN00091547</a>	Compiler warning: condition is always false Diag_Asr4Dem@Implementation
<a href="#">ESCAN00092315</a>	Compiler warning: function "CanLL_WakeUpHandling" was declared but never referenced DrvCan_Mpc5700McanLI@Implementation
<a href="#">ESCAN00092713</a>	Preprocessor parse error DrvCan_Mpc5700McanLI@Implementation
<a href="#">ESCAN00093058</a>	Compiler warning: conversion from 'PduIdType' to 'PduR_TxMulti2LoStateIterType', possible loss of data Gw_AsrPduRCfg5@Implementation
<a href="#">ESCAN00093096</a>	Compiler warning: truncating assignment Ccl_Asr4ComMCfg5@Implementation
<a href="#">ESCAN00093790</a>	Compiler warning: conversion from 'PduIdType' to 'PduR_TxMulti2LoStateIterType', possible loss of data Gw_AsrPduRCfg5@Implementation
<a href="#">ESCAN00093792</a>	Compiler warning: conversion from 'PduIdType' to 'PduR_RmSrcRomIterType', possible loss of data Gw_AsrPduRCfg5@Implementation

ESCAN00051574 [MSR4 only] Compiler warning: statement is unreachable	
<b>Component@Subcomponent:</b>	SysService_AsrDet@Implementation
<b>First affected version:</b>	5.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compiler warns for unreachable statement in API function Det_ReportError	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
Configurations with disabled "Enable Extended Debug Support" and DET_AUTOSARVERSION == 4	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is not resolved because there is no technical solution.	

<b>ESCAN00055307      Compiler warning: unused static function "XcpMemClr"</b>	
<b>Component@Subcomponent:</b>	Cp_AsrXcp@Implementation
<b>First affected version:</b>	1.03.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b> What happens (symptoms): ----- The following (or similar) warning occurs: ctc W536: ["../BSW/Xcp/XcpProf.c" 642/29] unused static function "XcpMemClr"  Compiler warns for an unused function: can be accepted - is usually because of specific configuration and not too complex \#ifdef usage  When does this happen: ----- The warning is issued by the compiler during compilation of the code in case the configuration is as described below.  In which configuration does this happen: ----- When DAQ measurement is deactivated.	
<b>Resolution Description:</b> Workaround: ----- The function XcpMemClr can be overwritten. Therefore a user config file can be used to set the define XcpMemClr. This will deactivate the function  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

**ESCAN00065890**      **Compiler warning: cast discards  
'\_\_attribute\_\_((noreturn))' qualifier from pointer  
target type****Component@Subcomponent:**      DrvCan\_Mpc5700McanLI@Implementation**First affected version:**      1.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
The compiler generates the following warning:

Compiling file: ../../external/BSW/Can/Can.c

../../external/BSW/Can/Can.c: In function 'CanBasicCanMsgReceived':

../../external/BSW/Can/Can.c:1745:16: warning: cast discards '\_\_attribute\_\_((noreturn))'  
qualifier from pointer target type [-Wcast-qual]../../external/BSW/Can/Can.c:1750:10: warning: cast discards '\_\_attribute\_\_((noreturn))'  
qualifier from pointer target type [-Wcast-qual]../../external/BSW/Can/Can.c:1780:55: warning: cast discards '\_\_attribute\_\_((noreturn))'  
qualifier from pointer target type [-Wcast-qual]

When does this happen:

-----  
The warning is issued by the compiler during compilation of the code in case the configuration is  
as described below.

In which configuration does this happen:

-----  
GNU compiler and -Wcast-qual compiler option is used**Resolution Description:**

Workaround:

-----  
Omit gcc command option -Wcast-qual.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

**ESCAN00065891      Compiler warning: cast increases required alignment of target type****Component@Subcomponent:**      DrvCan\_Mpc5700McanLI@Implementation**First affected version:**          1.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
Compiler generates the following warning:

Compiling file: ../../external/BSW/Can/Can.c  
../../external/BSW/Can/Can.c: In function 'CanBasicCanMsgReceived':  
../../external/BSW/Can/Can.c:1745:16: warning: cast increases required alignment of target type [-Wcast-align]  
../../external/BSW/Can/Can.c:1750:10: warning: cast increases required alignment of target type [-Wcast-align]  
../../external/BSW/Can/Can.c:1752:29: warning: cast increases required alignment of target type [-Wcast-align]  
../../external/BSW/Can/Can.c:1758:30: warning: cast increases required alignment of target type [-Wcast-align]

When does this happen:

-----  
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
GNU compiler and -Wcast-align compiler option is used**Resolution Description:**

Workaround:

-----  
Omit gcc command option -Wcast-align

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

## ESCAN00067159 Compiler warning: cast truncates constant value

**Component@Subcomponent:** MemService\_AsrNvM@Implementation

**First affected version:** 3.08.01

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

>..\..\bsw\nvm\nvm\_crc.c(229) : warning C4310: cast truncates constant value

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

CANoeEmu + VS2008

It depends on definition of uint16\_least: Warning occurs only if uint16\_least is not of type int.

Hint:

The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed, because the cast confirms and enforces this behavior (i.e. the value SHALL be truncated, if necessary).  
Additionally: Why uint16\_least is not (unsigned) int? -> this data type fulfills all requirements on a 16 bit unsigned value...

### Resolution Description:

Workaround:

No workaround necessary.

Resolution:

The described issue is corrected by modification of all affected work-products.

**ESCAN00067161      Compiler warning: conditional expression is constant****Component@Subcomponent:**      Il\_AsrComCfg5@Implementation**First affected version:**          1.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
Compiler warns for 'conditional expression is constant'.

When does this happen:

-----  
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
In all configurations with activated optimization "Optimize Const Arrays 2 Define".

Hint:

-----  
The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed due to existence of a sufficient workaround.**Resolution Description:**

Workaround:

-----  
De-activate /MICROSAR/Com/ComGeneral/ComOptimizeConstArrays2Define

Resolution:

-----  
The described issue is not planned to be corrected.

ESCAN00067237 Compiler warning: large type was implicitly cast to small type	
<b>Component@Subcomponent:</b>	If_AsrIfCan@Implementation
<b>First affected version:</b>	5.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compiler warns that a implicitly cast to a small type could occur.	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
All configurations. The issue occurs with a Renesas compiler for M16C but could happen with every other compiler.	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available. No impact on runtime.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	



**ESCAN00068402      Compiler warning: conditional expression or part of it is always true/false****Component@Subcomponent:**      DrvTrans\_Tja1043CandioAsr@Implementation**First affected version:**          2.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----

- Compiler warns for "condition is always true": This may happen depending on configuration, i.e. assert checks

in function CanTrcv\_30\_Tja1043\_GetOpMode following code is available

```
returnVal = E_OK;
```

```
CanTrcv_LeaveCritical();
```

```
if (returnVal == E_OK) /* PRQA S 3355,3358 */ /* MD_CanTrcv_30_Tja1043_13.7 */  
{
```

this issues following compiler warning:

warning (dcc:1606): conditional expression or part of it is always true/false

When does this happen:

-----

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----

All configurations.

**Resolution Description:**

Workaround:

-----

The code works as intended. The warning is uncritical and can be ignored.

Resolution:

-----

The described issue is corrected by modification of all affected work-products.

## ESCAN00068434 Compiler warning: conditional expression or part of it is always true/false

**Component@Subcomponent:** DrvCan\_\_coreAsr@Implementation

**First affected version:** 4.00.00

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

-----

- Compiler warns for "condition is always true": This may happen depending on configuration, i.e. assert checks

in function Can\_SetControllerMode following code is available

```
...
transitionRequest = kCanRequested;

CanMicroModeRestore();
}
if ( transitionRequest == CAN_NOT_OK ) /* PRQA S 3355,3356,3358,3359 */ /* MD_Can_13.7 */
{ /* PRQA S 3201 */ /* MD_Can_3201 */
    retval = CAN_NOT_OK;
    transitionDone = CAN_NOT_OK; /* at least one HW channel is not in new state (CAN_MSR40: poll later) */
}
..
```

this issues following compiler warning:

if ( transitionRequest == CAN\_NOT\_OK ) - warning (dcc:1606): conditional expression or part of it is always true/false

When does this happen:

-----

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----

All configurations.  
but not for all Platform implementations (hw always return OK for state transition)

### Resolution Description:

Workaround:

-----

Ignore warning

**ESCAN00068435      Compiler warning: narrowing or signed-to-unsigned type conversion found: unsigned int to unsigned char****Component@Subcomponent:**      MemService\_AsrNvM@Implementation**First affected version:**      3.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----

- Compiler warns for narrowing or signed-to-unsigned type conversion found: unsigned int to unsigned char

Warning occurs in following function:

FUNC(void, NVM\_PRIVATE\_CODE) NvM\_QueueInit(void)

```
...  
NvM_JobQueue_at[index].PrevEntry = index - 1u;
```

When does this happen:

-----

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----

It happens in all configurations

Hint:

-----

The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed due to MISRA 2004 - implicit conversion is allowed in this case. Additionally, it is obvious that actually no narrowing occurs (even a compiler could be capable of detection). Result of expression is always in range of [0,254].

**Resolution Description:**

Workaround:

-----

Just ignore warning.

Resolution:

-----

The described issue is corrected by modification of all affected work-products.

ESCAN00068872      Compiler warning: the order of volatile accesses is undefined in this statement	
<b>Component@Subcomponent:</b>	DrvCan__coreAsr@Implementation
<b>First affected version:</b>	3.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms): ----- Compiler issues warning messages like this: undefined behavior: the order of volatile accesses is undefined in this statement	
When does this happen: ----- The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen: ----- Rx Queue is enabled	
<b>Resolution Description:</b>	
Workaround: ----- Ignore Warning	
Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00074793 Compiler warning: Condition is always constant	
<b>Component@Subcomponent:</b>	Diag_Asr4Dem@Implementation
<b>First affected version:</b>	4.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compiler warning 'Condition is always constant'	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
Configurations without DTCs	
AND	
Precompile configuration	
<b>Resolution Description:</b>	
Workaround:	
-----	
The warning can be ignored	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00076827 Compiler warning: Prototypes for Sector Info not present	
<b>Component@Subcomponent:</b>	Cp_AsrXcp@GenTool_GeneratorMsr
<b>First affected version:</b>	2.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
When "Processor and Sector Info" is activated the compiler issues a warning because there are not prototypes for the generated Sector Info constants.	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
When "Processor and Sector Info" is used.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Activate "General Info" configuration option	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

**ESCAN00078543      Compiler warning: statement is unreachable when Calibration is deactivated****Component@Subcomponent:** Cp\_AsrXcp@Implementation**First affected version:** 1.30.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
The following compiler warnings happen, when the Option "Calibration enabled" is not active:

```
"../../../../external/BSW/Xcp/XcpProf.c", line 3267: warning #111-D: statement is
unreachable
break;
^
```

```
"../../../../external/BSW/Xcp/XcpProf.c", line 3300: warning #111-D: statement is
unreachable
break;
```

When does this happen:

-----  
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

```
--quit_after_warnings
```

In which configuration does this happen:

-----  
When Calibration is deactivated and compiler option above is active.**Resolution Description:**

Workaround:

-----  
No workaround available.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

<b>ESCAN00081459      Compiler warning: function "ApplCanTimerLoop" was declared but never referenced</b>	
<b>Component@Subcomponent:</b>	DrvCan__coreAsr@Implementation
<b>First affected version:</b>	4.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
compiler warning: function "ApplCanTimerLoop" was declared but never referenced	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
In all configurations where feature SLeep/Wakeup is not enabled. And no other transition needs this hardware transition loop.	
Hint:	
-----	
The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed due to compiler will remove this function so no effect in code size will occur.	
And the code complexity will increase significant to fix this problem by pre-processor switches	
<b>Resolution Description:</b>	
Workaround:	
-----	
Ignore Warning	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	



## ESCAN00086596 Compiler warning: used wrong Memory class qualifier in several functions

**Component@Subcomponent:** Gw\_AsrPduRCfg5@Implementation

**First affected version:** 6.00.00

**Fixed in versions:** 6.00.01

### Problem Description:

What happens (symptoms):

-----  
- Compiler warns qualifier does not exist in the following functions:

PduR\_GwIf\_Transmit\_Multi()  
PduR\_GwIf\_TriggerTransmit\_Multi()  
PduR\_GwIf\_TxConfirmation\_Multi()  
PduR\_GwIf\_CancelTransmit\_Multi()

If the qualifier is used to define the memory section the PduR use the Can Interface section for all PduR\_GwIf\_xxx\_Multi() functions.

When does this happen:

-----  
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
In any N:1 communication Interface routing is configuration.  
AND  
no Can Interface exists in this configuration.

The PduR\_cfg.h contains the following defines:

```
PDUR_TRANSMITIDXOFTXIF2LOMULTI STD_ON
OR
PDUR_IFTRIGGERTRANSMITFCTPTRIDXOFTXIF2LOMULTI STD_ON
OR
PDUR_IFTXCONFIRMATIONIDXOFTXIF2LOMULTI STD_ON
OR
PDUR_CANCELRECEIVEFCTPTR AND PDUR_TXIF2LOMULTI STD_ON
OR
PDUR_TRANSMITIDXOFTXIF2LOMULTI STD_ON
```

### Resolution Description:

Workaround:

-----  
No workaround available.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00086650 Compiler warning: pointless comparison of unsigned integer with zero	
<b>Component@Subcomponent:</b>	SysService_AsrCsm@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The generic range check may produce a compiler warning if the CSM_OFFSET_* of a specific service is zero as the range check will compare "uint16 >= 0" which is always TRUE.	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
Every configuration with some compiler.	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

**ESCAN00087235      Compiler warning: variable "IErrorId" was declared but never referenced****Component@Subcomponent:**      Tp\_Asr4TpCan@Implementation**First affected version:**          2.01.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----  
"../../../../external/BSW/CanTp/CanTp.c", line 3868: warning #550-D: variable "IErrorId" was set but never used  
uint8 IErrorId = CANTP\_E\_NO\_ERROR;  
^

"../../../../external/BSW/CanTp/CanTp.c", line 3909: warning #177-D: variable "IErrorId" was declared but never referenced  
uint8 IErrorId = CANTP\_E\_NO\_ERROR;  
^

"../../../../external/BSW/CanTp/CanTp.c", line 4258: warning #550-D: variable "IErrorId" was set but never used  
uint8 IErrorId = CANTP\_E\_NO\_ERROR;  
^

"../../../../external/BSW/CanTp/CanTp.c", line 4361: warning #550-D: variable "IErrorId" was set but never used  
uint8 IErrorId = CANTP\_E\_NO\_ERROR;  
^

"../../../../external/BSW/CanTp/CanTp.c", line 4493: warning #177-D: variable "IErrorId" was declared but never referenced  
uint8 IErrorId = CANTP\_E\_NO\_ERROR;  
^

When does this happen:

-----  
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
If development error detection is disabled (CANTP\_DEV\_ERROR\_DETECT == STD\_OFF)  
and no dummy statement is used (CANTP\_USE\_DUMMY\_STATEMENT == STD\_OFF)

Hint:

-----  
The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed because a dummy statement exists to avoid this warning (CW\_003)

**Resolution Description:**

<b>ESCAN00087235      Compiler warning: variable "IErrorId" was declared but never referenced</b>	
Workaround: ----- Enable dummy statements	
Resolution: ----- The described issue is corrected by modification of all affected work-products.	
<b>ESCAN00087501      Compiler warning: "signed/unsigned mismatch" due to missing cast in 0:N or 1:N indirections</b>	
<b>Component@Subcomponent:</b>	CommonAsr_ComStackLib@GenTool_GeneratorMsr
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	8.01.00
<b>Problem Description:</b>	
What happens (symptoms): ----- "Signed/unsigned mismatch" compiler warning due to missing cast for the subtracted indirection length. The length macro of a 0:N or 1:N indirection calculates the length through endIndex - startIndex. This subtraction can be interpreted by the compiler as a signed value without a explicit unsigned cast.	
When does this happen: ----- The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen: ----- any configuration using 0:N or 1:N Indirections with the length member AND the indirection configuration class is PRE-COMPILE	
<b>Resolution Description:</b>	
Workaround: ----- Perform a cast in your embedded code.	
Resolution: ----- The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00087536      Compiler warning: 'function' : conversion from 'const &lt;SomeType&gt;' to '&lt;AnotherType&gt;', possible loss of data</b>	
<b>Component@Subcomponent:</b>	CommonAsr_ComStackLib@GenTool_GeneratorMsr
<b>First affected version:</b>	7.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms): ----- Compiler warns for possible loss of data in the module source code: 'function' : conversion from 'const <SomeType>' to '<AnotherType>', possible loss of data  When does this happen: ----- The warning is issued by the compiler during compilation of the code in case the configuration is as described below.  In which configuration does this happen: ----- The module is in the configuration variant postbuild loadable or postbuild loadable selectable AND indirections are modelled in the code generator pointing from the configuration class is POSTBUILD to a destination in the configuration class PRE-COMPILE or LINK.	
<b>Resolution Description:</b>	
Workaround: ----- Add a type cast if in the embedded source code to avoid the warning.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00088061</b>	<b>BswM_Lcfg.c: warning: 'function' : conversion from 'const BswM_ImmediateUserStartIdxOfModeReqeustMappingType' to 'BswM_SizeOfImmediateUserType', possible loss of data</b>
<b>Component@Subcomponent:</b>	SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
<b>First affected version:</b>	7.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
BswM_Lcfg.c: warning: 'function' : conversion from 'const BswM_ImmediateUserStartIdxOfModeReqeustMappingType' to 'BswM_SizeOfImmediateUserType', possible loss of data	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
All	
<b>Resolution Description:</b>	

ESCAN00088362      Compiler warning: "cast truncates constant value" with signed data	
<b>Component@Subcomponent:</b>	CommonAsr_ComStackLib@GenTool_GeneratorMsr
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	8.01.00
<b>Problem Description:</b>	
What happens (symptoms): ----- Compiler warns for "cast truncates constant value" due to cast of subtracted signed data.  When does this happen: ----- The warning is issued by the compiler during compilation of the code in case the configuration is as described below.  In which configuration does this happen: ----- your component generator generates signed data in the configuration class precompile AND your component generator implementation returns in isReduceConstantData2Define() true AND your component generator implementation returns in getDataDeduplicationStrategy() != EDataDeduplicationStrategy.NONE	
<b>Resolution Description:</b>	
Workaround: ----- If the values for isReduceConstantData2Define() and getDataDeduplicationStrategy() are user configurable, you have a workaround else not.  Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00089241 Compiler warning: multiple warnings	
<b>Component@Subcomponent:</b>	SysService_CryptoCv@Impl_actCLib
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
<ul style="list-style-type: none"> <li>- Compiler warns for possible loss of data: Check if cast is missing and if there is really a data loss due to an implicit/explicit cast on the target platform</li> <li>- Compiler warns for ambiguous code, parentheses recommended.</li> </ul>	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
Always.	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	



ESCAN00089425 Compiler warning: missing braces around initializer	
<b>Component@Subcomponent:</b>	SysService_CryptoCv@Impl_ESLib
<b>First affected version:</b>	1.01.01
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compiling file: ../../BSW/SecMod/ESLib_version.c	
ctc W542: ["../../BSW/SecMod/ESLib_version.c" 73/4] missing braces around initializer	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
In all configurations.	
<b>Resolution Description:</b>	
Workaround:	
-----	
Since ESLib_version.c is only used for component testing, it can be excluded from the build for integration.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

**ESCAN00089543      Compiler warning: dead assignment to "errorId" eliminated****Component@Subcomponent:** Nm\_Asr4NmIf@Implementation**First affected version:** 7.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

-----

A compiler warning similar to the following one occurs for the compilation of Nm.c:  
dead assignment to "errorId" eliminated

When does this happen:

-----

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----

'Dev Error Detect' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalProperties/NmDevErrorDetect) in the NmGlobalProperties container is turned OFF in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> Nm\_Cfg.h contains #define NM\_DEV\_ERROR\_REPORT STD\_OFF).

Hint:

-----

The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed due to the API pattern that Vector has decided to use: each API that may report development errors shall always have an errorId variable on the stack to which assignments are made - regardless of whether the variable is actually used or not.

**Resolution Description:**

Workaround:

-----

Ignore the warning.

Resolution:

-----

The described issue is corrected by modification of all affected work-products.

## ESCAN00089544 Compiler warning: conversion to 'uint8' from 'int' may alter its value

**Component@Subcomponent:** Nm\_Asr4NmIf@Implementation

**First affected version:** 9.00.00

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

-----  
Compiler warnings similar to the following one occur for the compilation of Nm.c:  
conversion to 'uint8' from 'int' may alter its value

When does this happen:

-----  
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
'Coordinator Support Enabled' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalFeatures/  
NmCoordinatorSupportEnabled) is turned ON in the 'Network Management General' / 'Basic Editor'  
in DaVinci Configurator (-> Nm\_Cfg.h contains #define NM\_COORDINATOR\_SUPPORT\_ENABLED  
STD\_ON)

AND

(  
'Remote Sleep Ind Enabled' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalFeatures/  
NmRemoteSleepIndEnabled) is turned OFF in the 'Network Management General' / 'Basic Editor' in  
DaVinci Configurator (-> Nm\_Cfg.h contains #define NM\_REMOTE\_SLEEP\_IND\_ENABLED  
STD\_OFF)

OR

all coordinated channels have 'Channel Sleep Master' (/MICROSAR/Nm/NmChannelConfig/  
NmChannelSleepMaster) turned ON in the 'Network Management General' / 'Basic Editor' in  
DaVinci Configurator (-> Nm\_Cfg.h contains #define NM\_OPTIMIZE\_ALL\_SLEEP\_MASTER STD\_ON)

OR

all coordinated channels have 'Synchronizing Network' (/MICROSAR/Nm/NmChannelConfig/  
NmSynchronizingNetwork) turned ON in the 'Network Management General' / 'Basic Editor' in  
DaVinci Configurator (-> Nm\_Cfg.h contains #define NM\_OPTIMIZE\_ALL\_SYNC\_CHANNEL  
STD\_ON)  
)

Hint:

-----  
The compiler warning is known and has been analyzed thoroughly for its impact on the code.  
Nevertheless it will not be fixed because there is no risk of an invalid conversion of value to uint8.

### Resolution Description:

Workaround:

-----  
Ignore the warning.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00089619 Compiler warning: last line of file ends without a newline	
<b>Component@Subcomponent:</b>	Diag_Asr4Dem@Implementation
<b>First affected version:</b>	11.00.00
<b>Fixed in versions:</b>	12.00.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compiler warns about missing newline at the end of Dem_Cfg_Macros.h	
"../../../../bsw/dem/Dem_Cfg_Macros.h", line 431: Warning: #1-D: last line of file ends without a newline	
#endif	
^	
"../../../../bsw/dem/Dem_Cfg_Types.h", line 363: Warning: #1-D: last line of file ends without a newline	
#endif	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code	
In which configuration does this happen:	
-----	
all	
<b>Resolution Description:</b>	
Workaround:	
-----	
Ignore the warning	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

**ESCAN00090108      Compiler warning: function "PduR\_Init\_Rpg" was declared but never referenced****Component@Subcomponent:** Gw\_AsrPduRCfg5@Implementation**First affected version:** 5.00.00**Fixed in versions:** 7.02.00**Problem Description:**

What happens (symptoms):

-----  
Compiler warning: function "PduR\_Init\_Rpg" was declared but never referenced

When does this happen:

-----  
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
Any configuration where routing path groups are not being used.

The PduR\_Lcfg.h file contains the following define

#define PDUR\_RPG STD\_OFF

Hint:

-----  
The compiler warning is known and has been analyzed thoroughly for its impact on the code. No impact on the application.**Resolution Description:**

Workaround:

-----  
Define PduR\_Init\_Rpg to an empty statement via PduR user configuration file

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

ESCAN00090113 Compiler Warning: Result of function-call is ignored	
<b>Component@Subcomponent:</b>	SysService_CryptoCv@Impl_ESLib
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compiling file: ../../BSW/SecMod/ESLib_SHA256.c	
../../BSW/SecMod\ESLib_SHA256.c(71): WARNING C1420: Result of function-call is ignored	
../../BSW/SecMod\ESLib_SHA256.c(180): WARNING C1420: Result of function-call is ignored	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
in all configurations	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00090114 Compiler Warning: Assignment in condition	
<b>Component@Subcomponent:</b>	SysService_CryptoCv@Impl_actCLib
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compiling file: ../../BSW/SecMod/actBNReduce.c	
../../BSW/SecMod\actBNReduce.c(117): WARNING C5909: Assignment in condition	
Compiling file: ../../BSW/SecMod/actBigNum.c	
../../BSW/SecMod\actBigNum.c(234): WARNING C5909: Assignment in condition	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
in all configurations	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

## ESCAN00090161 Compiler warning: condition evaluates always to true/false

**Component@Subcomponent:** Ccl\_Asr4ComMCfg5@Implementation

**First affected version:** 7.00.01

**Fixed in versions:**

### Problem Description:

What happens (symptoms):

-----  
Compiler warns for conditional expression being constant

a) in the function ComM\_Init() when checking the generated data. Compiler warns about condition being always false in the following conditions:

if (ComM\_GetWakeupStateOfChannel(ComM\_ChannelIndex) >= COMM\_MAX\_NUMBER\_OF\_STATES)

if (ComM\_GetSizeOfChannel() != ComM\_GetSizeOfChannelPb())

if (ComM\_GetSizeOfPnc() != ComM\_GetSizeOfPncPb())

As secondary effect compiler might warn about unreachable code/statement.

b) in the function ComM\_PncProcessRxSignalEra() compiler warns about condition being always true in

if(ComM\_IsSynchronizedOfPnc(pncIndex))

c) in the functions ComM\_PncSetBitInSignal() and ComM\_PncClearBitInSignal() when checking the generated data. Compiler warns about condition being always true in

if( signalByteIndex < ComM\_GetSizeOfPncSignalValues() )

When does this happen:

-----  
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
a) occurs when COMM\_DEV\_ERROR\_DETECT == STD\_ON

b) occurs when

- 'Pnc Support' is enabled in ComM (/MICROSAR/ComM/ComMGeneral/ComMPncSupport)

AND

- 'Pnc Gateway Enabled' is enabled in ComM (/MICROSAR/ComM/ComMGeneral/ComMPncGatewayEnabled)

AND

- Only one PNC exists (COMM\_ACTIVE\_PNC == 1U, can be found in ComM\_Cfg.h).

c) occurs when 'Pnc Support' is enabled in ComM (/MICROSAR/ComM/ComMGeneral/ComMPncSupport)

Hint:

-----  
The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed because no simple remedy exist.

The warning is caused by an if-statement applied on external configuration data. Configuration data is const for the given compilation context but might be changed at post-build time.

### Resolution Description:



ESCAN00090806 Compiler warning: C4310: cast truncates constant value	
<b>Component@Subcomponent:</b>	Gw_AsrPduRCfg5@Implementation
<b>First affected version:</b>	7.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compiler warns for cast truncates constant value	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
If the uint8_least is of type unsigned char	
The Platform_Types.h contains the following define	
typedef unsigned char uint8_least; /* At least 8 bit */	
Hint:	
-----	
The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed due to ensure that the init value is large enough. A cast to a smaller value is acceptable and has no impact on the application.	
#define PDUR_INVALID_VARARRAYIDX ((uint16)0xFFFF) is cast for unsigned char to 0xFF which is correct.	
<b>Resolution Description:</b>	
Workaround:	
-----	
ignore the warning	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00090831      Compiler warning: integer conversion resulted in a change of sign</b>	
<b>Component@Subcomponent:</b>	Il_AsrComCfg5@Implementation
<b>First affected version:</b>	1.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compiler warns that "integer conversion resulted in a change of sign".	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
If the compiler WindRiver Diab is used. (found with version 5.9.4.2.)	
Hint:	
-----	
The compiler warning is known and has been analyzed thoroughly for its impact on the code.	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00090874</b>		<b>Compiler warning: DEM_CFG_SUPPORT_NVM_POLLING undefined</b>	
<b>Component@Subcomponent:</b>	Diag_Asr4Dem@Implementation		
<b>First affected version:</b>	11.00.00		
<b>Fixed in versions:</b>	12.00.00		
<b>Problem Description:</b>			
What happens (symptoms):			
-----			
Compile warning occurs in Dem_Cbk.h: 'DEM_CFG_SUPPORT_NVM_POLLING' is not defined as a preprocessor macro, replacing with '0' for '#if/#elif'			
When does this happen:			
-----			
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.			
In which configuration does this happen:			
-----			
In all configurations using .c-Files which include Dem_Cbk.h			
MICROSAR4 DEM and MICROSAR NVM are not affected			
<b>Resolution Description:</b>			
Workaround:			
-----			
Define DEM_CFG_SUPPORT_NVM_POLLING manually to STD_OFF OR Include Dem.h before including Dem_Cbk.h			
Resolution:			
-----			
The described issue is corrected by modification of all affected work-products.			

ESCAN00091295 Compiler warning: dead assignment / variable set but not used	
<b>Component@Subcomponent:</b>	Ccl_Asr4ComMCfg5@Implementation
<b>First affected version:</b>	5.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compiler warns about an useless assignment to a local variable. Typically the warnings refer to local variables 'channel', 'errorId', 'Status' or 'User'.	
Example compiler warning strings:	
"Useless assignment to variable 'abc'. Assigned value not used."	
"Removed dead assignment"	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
EcuC Parameter 'Dummy Statement Kind' is set to 'SelfAssignment'. This can be detected in ComM_Cfg.c: #define COMM_DUMMY_STATEMENT(v) (v)=(v)	
Hint:	
-----	
The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed because no simple remedy exist.	
If Dummy Statement is switched off, other compiler warnings might occur e.g. "Unused/unreferenced variable".	
<b>Resolution Description:</b>	

ESCAN00091340 Compiler warning: cast truncates constant value	
<b>Component@Subcomponent:</b>	If_AsrIfCan@Implementation
<b>First affected version:</b>	5.00.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compile warning occurs.	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
If partial network wakeup PDU filtering is active. (canifcfg.h: CANIF_PN_WU_TX_PDU_FILTER == STD_ON)	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available. Issue is checked and not critical.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

ESCAN00091343 Compiler warning: warning C4310: cast truncates constant value	
<b>Component@Subcomponent:</b>	If_AsrIfCan@Implementation
<b>First affected version:</b>	6.09.00
<b>Fixed in versions:</b>	
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Compile warning occurs.	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
If transmit buffer is configured as FIFO and cancel API is supported. (canifcfg.h: CANIF_TRANSMIT_BUFFER_FIFO == STD_ON && CANIF_CANCEL_SUPPORT_API == STD_ON)	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available. Warning was checked, not critical.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

## ESCAN00091547 Compiler warning: condition is always false

**Component@Subcomponent:** Diag\_Asr4Dem@Implementation

**First affected version:** 11.01.00

**Fixed in versions:**

### **Problem Description:**

What happens (symptoms):

-----  
Compiler warns for "condition is always true/false"

Some compiler will also warn because of dead code, resulting from the constant condition

When does this happen:

-----  
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----  
Dem/DemGeneral/DemSafeBswModeEnabled == TRUE

AND

EcuC/EcucGeneral/EcuCSafeBswChecks == TRUE or undefined

Depending on the configuration, optimization can change a configuration table into a constant macro.

This can causes some run-time checks to check for equality of two constants.

### **Resolution Description:**

Workaround:

-----  
The warning can be ignored.

Resolution:

-----  
The described issue is corrected by modification of all affected work-products.

<b>ESCAN00092315</b>		<b>Compiler warning: function "CanLL_WakeUpHandling" was declared but never referenced</b>
<b>Component@Subcomponent:</b>	DrvCan_Mpc5700McanLI@Implementation	
<b>First affected version:</b>	2.00.00	
<b>Fixed in versions:</b>	2.10.00	
<b>Problem Description:</b>		
What happens (symptoms):		
-----		
Compiler warning occurs: "function "CanLL_WakeUpHandling" was declared but never referenced"		
When does this happen:		
-----		
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.		
In which configuration does this happen:		
-----		
If "Sleep /Wake-up Functionality" is activated in the configuration (leading to the definition of C_ENABLE_SLEEP_WAKEUP).		
<b>Resolution Description:</b>		
Workaround:		
-----		
No workaround available.		
Resolution:		
-----		
The described issue is corrected by modification of all affected work-products.		



ESCAN00092713 Preprocessor parse error	
<b>Component@Subcomponent:</b>	DrvCan_Mpc5700McanLI@Implementation
<b>First affected version:</b>	2.07.00
<b>Fixed in versions:</b>	2.10.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
Preprocessor stops with parsing error. E.g. the MCAN can still be active with pending Tx requests although Stop Mode reached is notified.	
When does this happen:	
-----	
At compilation time.	
In which configuration does this happen:	
-----	
Only for CANbedded AND Range Filtering is used (C_ENABLE_RANGE_x is defined).	
<b>Resolution Description:</b>	
Workaround:	
-----	
No workaround available.	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

<b>ESCAN00093058</b>		<b>Compiler warning: conversion from 'PduIdType' to 'PduR_TxMulti2LoStateIterType', possible loss of data</b>
<b>Component@Subcomponent:</b>	Gw_AsrPduRCfg5@Implementation	
<b>First affected version:</b>	7.00.00	
<b>Fixed in versions:</b>		
<b>Problem Description:</b>		
What happens (symptoms):		
-----		
Compiler warning: Conversion from 'PduIdType' to 'PduR_TxMulti2LoStateIterType', possible loss of data		
When does this happen:		
-----		
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.		
In which configuration does this happen:		
-----		
N:1 Tp routing configuration		
The PduR_Lcfg.h file contains the following define:		
#define PDUR_TXMULTI2LOSTATE STD_ON		
<b>Resolution Description:</b>		
Workaround:		
-----		
No workaround available. Missing explicit cast. The warning can be ignored		
Resolution:		
-----		
The described issue is corrected by modification of all affected work-products.		

**ESCAN00093096 Compiler warning: truncating assignment****Component@Subcomponent:** Ccl\_Asr4ComMCfg5@Implementation**First affected version:** 5.00.00**Fixed in versions:** 8.01.00**Problem Description:**

What happens (symptoms):

-----

Compiler warns about possible loss of data in the function ComM\_LimitPncToChannelRouting() for example

ComM.c 1591(190+5) truncating assignment

There is no risk of data loss and the warning can be ignored.

Background:

The expression is like (type) = (type) | (uint8)

The result of logical OR and AND operator has type int according to C standard. The warning is issued because the affected expression implicitly casts the result to (type) if (type) is not int.

There is no risk of data loss because (type) is uint8 or uint16.

When does this happen:

-----

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-----

ComM/ComMGeneral/ComMPncToChannelRoutingLimitationEnabled == true

**Resolution Description:**

Workaround:

-----

No workaround available.

Resolution:

-----

The described issue is corrected by modification of all affected work-products.

<b>ESCAN00093790</b>		<b>Compiler warning: conversion from 'PduIdType' to 'PduR_TxMulti2LoStateIterType', possible loss of data</b>
<b>Component@Subcomponent:</b>	Gw_AsrPduRCfg5@Implementation	
<b>First affected version:</b>	7.00.00	
<b>Fixed in versions:</b>	10.00.00	
<b>Problem Description:</b>		
What happens (symptoms):		
-----		
The external type is larger than the internal type. The internal type is adapted automatically during generation to a suite able type due to optimization reason. If the internal type is smaller than the external type the value of the external type could never be greater than the internal type could hold, because there is a direct dependency between the value range.		
The warning can be ignored the cast is always valid.		
When does this happen:		
-----		
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.		
In which configuration does this happen:		
-----		
If the /MICROSAR/EcuC/EcucPduCollection/PduIdTypeEnum is set to UINT16, but the maximum configured PDU handle is smaller than 255		
<b>Resolution Description:</b>		
Workaround:		
-----		
Solve: ECUC01006 PduIdTypeEnum validation and reduce the type to the suite able type		
Resolution:		
-----		
The described issue is corrected by modification of all affected work-products.		

ESCAN00093792 Compiler warning: conversion from 'PduIdType' to 'PduR_RmSrcRomIterType', possible loss of data	
<b>Component@Subcomponent:</b>	Gw_AsrPduRCfg5@Implementation
<b>First affected version:</b>	9.00.00
<b>Fixed in versions:</b>	10.00.00
<b>Problem Description:</b>	
What happens (symptoms):	
-----	
The external type is larger than the internal type. The internal type is adapted automatically during generation to a suite able type due to optimization reason. If the internal type is smaller than the external type the value of the external type could never be greater than the internal type could hold, because there is a direct dependency between the value range.	
The warning can be ignored the cast is always valid.	
When does this happen:	
-----	
The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	
-----	
If the /MICROSAR/EcuC/EcucPduCollection/PduIdTypeEnum is set to UINT16, but the maximum configured PDU handle is smaller than 255	
<b>Resolution Description:</b>	
Workaround:	
-----	
Solve: ECUC01006 PduIdTypeEnum validation and reduce the type to the suite able type	
Resolution:	
-----	
The described issue is corrected by modification of all affected work-products.	

## 3. New Issues for Information

Issues which should not have an effect on the usage of the license as the issues are relevant for use cases other than those defined in the questionnaire. The list contains issues that have been detected since the last report.

Issues listed in this section are not relevant for the use case that has been documented in the questionnaire provided to Vector. However, the issues may be relevant for other use cases. Also issues that have been accepted or are tolerated by the OEM (as defined in the questionnaire) are reported here.

No issue to be reported.

## 4. Report Legend

Issue Report	
Report Creation Date 2011-02-25	
Index	The ID number identifies the Issue
ESCAN0002257 Headline describes symptoms and consequences of the Issue in one sentence DrvCan baseAsr@GenTool GeneratorGeny	
ESCAN0002257 Headline describes symptoms and consequences of the Issue in one sentence	
Component@Subcomponent: First affected version: Version fixed: Problem Description: What happens (symptoms):	Component@Subcomponent describes the group of workproducts which are composed of the source code, project documentation, User Manual and Generation Tool. The Subcomponent describes the certain affected work-product in which part of the Component the issue appears. e.g. inside of the source code (e.g. Implementation) or inside of the User Manual (e.g. Documentation) or inside of the concerning Generation Tool code.
<p>// to be removed: Describe FROM CUSTOMERS NON TECHNICAL POINT OF VIEW, - which symptoms one will get if this issue occurs? - How can the issue be seen? - if it cannot be seen, how can the customer detect it? - what happens AFTER the issue occurred? - What is the consequence, the implication?</p> <p>Consider the following questions: If the issue is TEMPORARY: Does the issue cause the malfunction once but after that ECU continues to work and probably works correctly? In which situation (ECU reset / wakeup) does the ECU recover? If the issue is PERMANENT: ECU is blocked until Watch-Dog reset. ECU blocked forever and Watch-Dog cannot help.</p> <p>When does this happen:</p> <p>// to be removed: Describe FROM CUSTOMERS NON TECHNICAL POINT OF VIEW, which circumstances, operational situations, API function calls lead to the issue. With this information the customer wants to find out, whether he is affected by this issue or not.</p> <p>Consider the following questions: When (during runtime) does the issue occur and how can the customer find the issue? (1) Always and immediately (2) Only under specific circumstances (describe them) (3) Rarely, very rarely or unlikely Can the probability of occurrence of the issue be estimated?</p> <p>In which configuration does this happen:</p> <p>// to be removed: Describe FROM CUSTOMERS POINT OF VIEW, which configurations of e.g. GenTool, database (attributes), OEM, compiler, components, ... lead to the issue.</p> <p><b>Resolution Description:</b> Workaround: No workaround available.</p> <p>// to be removed: If there is a workaround available, please replace the default text. Describe FROM CUSTOMERS POINT OF VIEW, what has to be done to avoid this issue.</p> <p>Resolution: The described issue is corrected by modification of all affected workproducts.</p> <p>// to be removed: technical resolution: e.g. error is resolved in file "xyz" function "opq"</p>	<p>The First affected Version describes in which version of the Component the Issue appears first and the Version fixed describes the corrected version of the Component in which the Issue does not appear anymore.</p> <p>The Problem description expresses the Issue content, eventually impact, etc. What happens: Symptoms, consequences and/or the detection way is described. When does it happen: Ignition, trigger point of the Issue In which configuration does this happen: Dependencies to a certain functionality or another component</p> <p>The Resolution description describes a workaround, if available and the resolution of the Issue.</p>

## 5. Quality Management Contact

Quality Management  
Productline Embedded Software (PES)

Vector Informatik GmbH  
Ingersheimer Str. 24  
D-70499 Stuttgart

Phone: +49 711 80670-3700  
Fax: +49 711 80670-399  
eMail: [QualityPES@vector.com](mailto:QualityPES@vector.com)