

TEW-827DRU

Firmware version

TEW-827DRU firmware: 2.06B04

Description

TRENDnet TEW-827DRU with firmware up to and including 2.06B04 contains a stack-based buffer overflow in the ssi binary.

The overflow allows an authenticated user to execute arbitrary code by POSTing to apply.cgi via the action wifi_captive_portal_login with a sufficiently long key "REMOTE_ADDR".

Detail

The bug in function: get_mac_from_ip_by_arptable, binary: www/cgi/ssi

The key 'REMOTE_ADDR' pass to sprintf:

```
00426C60      nop
00426C64      addiu   $v0, (aPingSW1DevNull - 0x4C0000) # "ping %s -w 1 > /dev/null"
00426C68      addiu   $v1, $fp, 0x80+var_60
00426C6C      move    $a0, $v1      # s
00426C70      move    $a1, $v0      # format
00426C74      lw      $a2, 0x80+arg_0($fp)
00426C78      la      $v0, sprintf
00426C7C      nop
00426C80      move    $t9, $v0
00426C84      jalr    $t9 ; sprintf
00426C88      nop
00426C8C      lw      $gp, 0x80+var_70($fp)
00426C90      addiu   $v0, $fp, 0x80+var_60
00426C94      move    $a0, $v0      # command
00426C98      la      $v0, system
00426C9C      nop
00426CA0      move    $t9, $v0
00426CA4      jalr    $t9 ; system
```