

		SNO+ Laser Ball PCA Procedures	
Document Number:		Revision Number: 01	
Document Owner: SNO+ Calibration Post-Doc			
Reviewer:			
Name:	Signature	Date	
Authorizer:			
Name:	Signature	Date	

1 Purpose

The calibration of the SNO+ PMTs requires a standardized light source. The standardized light is provided by a dye laser coupled to the laserball which may be deployed into the detector AV.

2 Supporting Procedures

This procedure may be supplemented by documents available from the SNO calibration home page <http://www.sno.phy.queensu.ca/private/calibration/index.html>. These procedures will be reviewed as necessary.

Online Manipulator Documentation Contains online manula for all commands and operations with the manip program running on the calibration computer. This is the reference source for commands done from the manip console.

Manipulator User Manual Contains an overview of the manipulator system and descriptions of sources and some procedures. In particular it describes how to start the manmon program for controlling and monitoring the manipulator.

Manipulator Reference Manual contains technical information on the manipulator.

SNO+ Laser Ball PCA Procedures	Document No:
	Revision No: 01
	Effective Date: 2017-06-14
	Page 2

3 Outline

The outline of the procedure is:

1. Prepare the laser and URM for use (turn on N₂ supply etc).
2. Flush URM2 with N₂ gas to remove O₂ and Rn. (if the cover gas system is in place)
3. Calibrate URM2 central rope.
4. Lower source into glovebox.
5. Connect side ropes to source. (if not single axis mode)
6. Deploy source into detector.
7. Take PCA data.
8. Retract source to glovebox.
9. Remove side ropes. (if not single axis mode)
10. Retract source into source tube above gatevalve.
11. Shutdown laser and gas flow to laser and URM.

4 Procedures

Operator(s):	Date:
--------------	-------

The procedures in this section are intended to be followed sequentially for the PCA calibration except where it is noted that a following procedure can be skipped. Specifically, if the PCA is to be done in *single axis* mode, the side ropes do not need to be attached or detached from the source.

4.1 Prior to PCA

1. Permission for procedure and confirmation of equipment readiness has been received from Head of Calibration Group or the Site Activities Coordinator. Record authorizer name

SNO+ Laser Ball PCA Procedures	Document No:
	Revision No: 01
	Effective Date: 2017-06-14
	Page 3

2. Laserball is mounted in URM2 which is mounted on 10" valve on glovebox.
3. 10" gatevalve is closed and locked.

4.2 Readyng Laser and URM for Operation

4. Verify that the LN₂ dewar in the junction is at least 1/4 full. If not, request that it be swapped out with another dewar. Record liquid level of Dewar,

LN₂ Level:

5. Turn on the N₂ flow to laser from dewar at junction (marked **Gas Use** on dewar).

Note Time:

6. Turn on the pressure build valve (marked **Pressure Builder** on dewar). The pressure builder valve opens a controlled leak on the dewar to maintain the 150 psi pressure head. If the valve is not opened, the gas pressure to the laser will eventually drop below the operating level.
7. Contact the Detector Operator and get permission to enter the DCR. Make sure that the DCR activity bit is set.
8. Turn on light in DCR following standard procedure. (See Detector Operator Manual).
9. If cover gas present: Remove the flush return line on the URM. The presence of the buffer line makes it difficult to measure the O₂ from the URM.
10. If cover gas present: Check that flush inlet line is connected to URM2. If not connect it. Open the valve on the source tube. It may be necessary to valve off other URM's to get sufficient flow.
11. If cover gas present: Set up Gas Board in "bypass mode" for "URM flush" only. If you are using the high pressure feed **do not exceed** 10 psi on the regulator. Bypass mode maximizes the flow to the URM.

SNO+ Laser Ball PCA Procedures	Document No:
	Revision No: 01
	Effective Date: 2017-06-14
	Page 4

12. If cover gas present: Check that the flow meter (located at South-East corner of pipe box) is railed. If not, open needle valve near the flowmeter fully. **Flush should continue until O₂ reading at the rear of the URM is less than 0.8%.** This may take up to an hour depending on when the URM was last flushed.
13. Check that the source clamps are in the OUT position. **Both** knobs have to be in the extreme **OUT** position. **WARNING: If the source is moved with the clamps in the IN position, the source, umbilical, and manipulator may be severely damaged!** The clamps are used to secure the source while the URM is being moved on and off the glovebox.
14. Check the pressure on the air cylinder for the umbilical takeup mechanism. It should be between 45 and 55 psig. **Do not operate the URM if the pressure is below 40 psig.** If the pressure falls below 10 psig at any point (even momentarily) call the OCE .
15. Verify that the 10" gate valve is locked in the closed position. The valve is closed when the handle points towards the pipebox and the slot on the handle stem points AWAY from the source tube.
16. Calibrate the central rope length (see procedure: Central Rope Position Calibration). Record changes in length of central rop and umbilical. The current fiducial mark for URM2 on the 10" gate valve is $z_{mark} = 1559.9$. Note the fiducial mark is written on the source tube.
17. Check that all seals are in place on URM. Including:
 - flush inlet line
 - window on front of URM motorbox
 - window on rear of URM motorbox
 - umbilical feedthrouhg on rear of motorbox
 - view port window cover on source tube
 - window on rear of strecher box
18. Check that you are familiar with the section on operating the laser especially the **Emergency Shutdown Procedure**. Also, be aware that UV absorbing safety glasses **MUST** be worn while the laser is running unless **ALL** covers on the laser are in place.
19. Plug in the powercord to the laser.

SNO+ Laser Ball PCA Procedures	Document No:
	Revision No: 01
	Effective Date: 2017-06-14
	Page 5

20. Check the POWER switch on the laser is to **local**.
21. Check the CONTROL switch on the laser is set to **remote**.
22. Check that the manual shutoff valve on the right of MV5 is open.
23. Check that the manual shutoff valve MV9 is open.
24. Verify that N₂ is flowing through flow gauge FG5 to the laser head. If there is no flow consult an expert. **Running the laser without sufficient N₂ flow causes serious damage to the laser head!**
25. Record observed laser gas pressure and flow values. Note that the expected values listed below may be superseded by ones listed on one or more tags attached to the valves or flow meters. Always use the values found on the tags.

Transducer	Expect	Observed
PG2	110-150 psig	
PG3	90-110 psig	
PT4	100-110 psig	
FG5	≈ 50 (bottom of ball)	
PT6	≈ 90 psig	

PG2, PG3, and FG5 are read off the gas panel on the end of the laser cabinet. PT4 and PT6 are read from the manipulator computer either from the **manmon** laser window or using the commands,

```
n2laser hipressure (for PT4)
n2laser lowpressure (for PT6)
```

Gas must flow through the laser for ≈ 10 min before turning the laser high voltage on.

SNO+ Laser Ball PCA Procedures	Document No:
	Revision No: 01
	Effective Date: 2017-06-14
	Page 6

26. Block the laser light using the command `n2laser block`.
27. Select dyecell 4 (500 nm) by typing `dyelaser cell 4`
28. Check the state of the laser by issuing the command `n2laser monitor`. It will tell you the general state of the laser.
 - Check that all 4 stirrers are on.
 - Check that there is 120V to the laser.
 - Check that the filterwheels do not report any problems.
29. If cover gas present Wait until the O₂ level in the URM is at or below 0.8%.

4.3 Deploying Source from Source Tube Into Glovebox

30. If cover gas present: Verify that the URM is below 0.8% O₂
31. If cover gas present: Check that flush return line is connected to URM2. If not, connect it. It may be necessary to move it from another URM.
32. Turn off DCR lights.
33. If cover gas present: Record the Cover Gas O₂ level.

Cover Gas O ₂ Reading:

34. Verify OWL light monitor is on. Establish communications with person watching the light monitor. Suggestion: Station the person watching the OWL monitor at the monitor station. Then he/she can shout through the wall of the DCR and you don't need to use the phones which slow communications down.
35. Open gate valve (**Slowly!**). Record the time the valve is opened.

Time Gate Valve Opened:

36. Lock gate valve open.

SNO+ Laser Ball PCA Procedures	Document No:
	Revision No: 01
	Effective Date: 2017-06-14
	Page 7

37. With flashlight perform light leak check on URM. In particular check the seal of the source tube window and around the base of the source tube. Also, check around any inspection panel which may have been removed in the recent past.
38. Using the dimmer switch, **slowly** bring up breaker 9 lights in the DCR with a person still watching the OWL monitor.
39. In ORCA, source type is set to **LASERBALL**.
40. ORCA is in a **transitional run**.
41. Verify that **manip_logger** on the calibration computer and logging the **Laserball** source.
42. Check movement of laserball down

console	manip > laserball by 0 0 -5
manmon	in laserball window: set x=0, y=0, z=-5 click on move by

The laserball should move down by 5 cm. The tension on the rope should be 40-60 N. The tension on the umbilical should be 10-30 N.

43. Check that the source offset and orientation is set correctly. At the console type **laserball sourceoffset**. The current laserball has an offset of -64.5 cm. If the reported number is different contact the OCE. For single axis deployment mode the orientation should be 0; i.e. confirm from the console by typing **laserball orientation**. It should return 0. If deployed with sideropes the orientation depends on what direction the slot faces. If in doubt contact the OCE.
44. Deploy source into the glovebox:

console	manip > laserball to 0 0 1380
manmon	in laserball window: set x=0, y=0, z=1380 click on move to

4.4 Deploying Manipulator into Centre of Detector from Glovebox

45. Contact Water Supervisor and advise him/her that the source is being lowered into the AV. The water group maintains a very small differential pressure between the AV water and the cavity water. The volume of the source is enough to disrupt this differential pressure.

SNO+ Laser Ball PCA Procedures	Document No:
	Revision No: 01
	Effective Date: 2017-06-14
	Page 8

46. Check tensions on urm2rope and urm2umbilical. Rope tension should be approximately 30-50 N. Umbilical tension should be between 15-40 N. Note that the tensions are reduced once the sources is submerged.
47. Move laserball to centre of detector.

console	<code>manip > laserball to 0 0 64.5</code>
manmon	in laserball window: set x=0, y=0, z=64.5 click on move to

4.5 Turning on the Laser

48. Verify on the console that the control power on the laser is on:
`n2laser monitor`
All voltages should be on, all stir motors should be ON, both filterwheels should be IDLE, the dye cell motor should be IDLE and gas should be flowing. If not contact OCE.
49. Verify that the N2 gas has been flowing through the laser for ≈ 10 min. Note that the gas flow is turned on and off with the `n2laser poweron/poweroff` commands.
50. Select desired wavelength or dye cell

console	<code>manip > dyelaser cell <0-9></code> or <code>manip > dyelaser wavelength <wavelength></code>
manmon	in laser window: click on button above desired dye cell

51. Set ND=6.0 or higher.

console	<code>manip > n2laser setnd 6.0</code>
manmon	in laser window: \rightarrow Windows \rightarrow Neutral Density Settings click on desired neutral density

The filter wheels are set to a large attenuation when first turning on the laser to prevent a large amount of light being introduced into the detector and overwhelming the data acquisition. Once the laser is on, the rate and intensity can be adjusted to the desired level.

SNO+ Laser Ball PCA Procedures	Document No:
	Revision No: 01
	Effective Date: 2017-06-14
	Page 9

52. Wait for the laser to return status READY

53. Turn on the laser light

console	<code>manip > n2laser start</code>
manmon	in laser window: click on light on

Now wait 90 seconds while the trigger is delayed. Laser will come on at 10 Hz trigger rate.

54. Plug the Laserball Trigger signal into the EXT A input on the MTCD.

4.6 Taking PCA Data

55. **PCA Runs** The exact nature of the PCA runs will vary. The "canonical" run tends to be

(a) Long Low Occupancy Run.

- 500 nm
- The centroid for the raw TAC is usually at 1800.
- 5-8% occupancy (ND setting at 500 nm is approximately 3.5).
- 40 Hz laser trigger rate (or best you can do without buffer overflow).
- Run Type: LASERBALL_PCA
- 10 subruns (2-3 hours)

(b) Short Medium Occupancy Run.

- 500 nm
- The centroid for the raw TAC is usually at 1800.
- 20-25% occupancy (ND setting at 500 nm is approximately 3.0).
- 5-10 Hz laser trigger rate (or best you can do without buffer overflow).
- Run Type: LASERBALL_PCA
- 3 subruns (20 minutes).

The laser can be run up to 45 Hz but the DAQ produces strange results at such rates.

4.7 Turning Off Laser

56. Unplug EXT A at the MTCD.

SNO+ Laser Ball PCA Procedures	Document No:
	Revision No: 01
	Effective Date: 2017-06-14
	Page 10

57. Turn off laser light

console	manip > n2laser stop
manmon	in laser window: click on light off

58. Turn off laser power

console	manip > n2laser poweroff
manmon	in laser window: click on power off

59. Unplug laser power cord from wall outlet The laser is unplugged when it is not intended to be used for extended periods. This is because it has been observed that on several occasions after an unscheduled power outage the laser has come up in a funny state.

4.8 Retracting Manipulator to Glovebox

60. Contact Water Supervisor. Inform him/her that the source is about to be removed from the detector.
61. Retract the laserball from AV into glovebox

console	manip > laserball to 0 0 1300
manmon	in laserball window: in laserball window: click on Position the pivot set x=0, y=0, z=1300 click on move to

62. Retract the laserball to position to disconnect side ropes

console	manip > laserball to 0 0 1380
manmon	in laserball window: in laserball window: click on Position the pivot set x=0, y=0, z=1380 click on move to

When moving the laserball to 1380, it is important to make sure you are moving with respect to the **pivot** and **not** the centre of the source which is 64.5 cm below the pivot. This is especially important if the sideropes are attached!

SNO+ Laser Ball PCA Procedures	Document No:
	Revision No: 01
	Effective Date: 2017-06-14
	Page 11

4.9 Retracting source above gate valve; Side ropes not attached

63. Move laserball to 1530

console	manip > laserball to 0 0 1530
---------	-------------------------------

64. Move laserball to 1540

console	manip > laserball to 0 0 1540
---------	-------------------------------

65. Move laserball to 1550

console	manip > laserball to 0 0 1550
---------	-------------------------------

NOTE:

MINIMUM SAFE HEIGHT TO CLOSE GATEVALVE IS 1535 cm

If unable to get above this height, contact expert.

66. Retrieve the gatevalve key from the DCR lock box.
67. Unlock the gatevalve.
68. Carefully close the gate valve by rotating the handle *clockwise*. *Expect resistance when the handle is about 3/4 of the way to the closed position. This is the normal overcentering of the valve mechanism.* **If resistance is felt before this or if any sounds are heard that might be caused by valve hitting the source, STOP and contact and expert.** Record the time the valve is closed.

Time Gate Valve Closed:

69. Lock the gatevalve in the **CLOSED** position.
70. Return the gatevalve key to the DCR lock box.
71. If cover gas present Record the Cover Gas O₂ level

Cover Gas O ₂ Reading:

SNO+ Laser Ball PCA Procedures	Document No:
	Revision No: 01
	Effective Date: 2017-06-14
	Page 12

72. If cover gas present Close the URM flush valve if the source does not need drying out. *It is desirable to leave a minute flow of N_2 through the URM in order to dry out the source and the umbilical. Contact OCE for instructions.*
73. If cover gas present Turn off the URM flush regulator (if the source does not need drying out).
74. IF the laser is off, turn off gas flow at the LN_2 dewar in the junction:

4.10 After Calibration

75. Source is above the gate valve.
76. Gate valve is closed and locked.
77. Laser is off.
78. Manual shutoff valve to the right of MV5 is closed.
79. Laser power cord is unplugged from wall outlet.
80. High pressure LN_2 dewar is turned off (both **Gas Use** valve and **Pressure Building** valve).
81. Flush return line is disconnected from rear of URM2.
82. Gas board is set up to provide sufficient flow to dry out the inside of the URM.

5 Revision History

Originating Date: 2017-06-14			
Revision No.	Effective Date (YYYY-MM-DD)	Author	Summary of Change
01	2017-06-14	Ryan Bayes	Drafted from SNO Calibration Operators Manual (PCA, Revision 2) with minor revisions and editable blocks added for user notes.