

# ADC Testing

## Setup

Using PCB, a divider network (2x 10k resistors) feeds the ADC. Software samples a single ADC channel every 10ms. For the first test, the relay isn't triggered. This test was run for 10 minutes. For the second test, the relay randomly opens/closes every 0.1 to 1 second. This test was run for 20 minutes.

## Results

From the MCP3008 data sheet, the ADC has a max error of  $\pm 2\text{LSB}$  ( $\pm 1\text{LSB}$  Integral Nonlinearity and  $\pm 1$  Gain error).

Currently, the system has an error of  $\pm 2.5$  and  $\pm 3\text{LSB}$  with no relays and relays triggering.

## Comments/Recommendations



From the plots, there are very few "outliers". On the next PCB revision, a small RC filter will be added to the front of the ADC input. The a more precise reference will be added to the ADC.

My 2 cents on data sheets. It's impossible to achieve the specifications listed on data sheets. They preforms these tests in optimal conditions and not real world conditions. Instead, the focus should be on determining how well the ADC preforms for the task selected. In this case, will the sensor's output be affected with a  $\pm 3\text{LSB}$  or is that insignificant?

## Data

	No Relay Triggered	Relay Triggered
Samples Collected	58910	117815
Mean	510.315922594	510.402037092
Median	510.0	510.0
Min	507	506
Max	512	512
Min/Max Diff	5	6

## No Relays Triggered



## Relays Triggering

