

```

[
  {
    "Error Code": "0046",
    "Module Name": "cSpcs.c",
    "Text Message": "Could not initialize the DDEA board. Replace
the DDEA. This could also be a problem with communication to the DDEA."
  },
  {
    "Error Code": "0047",
    "Module Name": "cSpcsGspmColor.c",
    "Text Message": "SSP is present, but no code compiled for the
Color mode for the SSP. This is a system software problem."
  },
  {
    "Error Code": "0048",
    "Module Name": "cSpcsGspmColor.c",
    "Text Message": "SPM is present, but no code compiled for the
Color mode for the SPM. This is a system software problem."
  },
  {
    "Error Code": "0049",
    "Module Name": "cSpcsGspmDopp.c",
    "Text Message": "SSP is present, but no code compiled for the
Doppler mode for the SSP. This is a system software problem."
  },
  {
    "Error Code": "0050",
    "Module Name": "cSpcsGspmDopp.c",
    "Text Message": "SPM is present, but no code compiled for the
Doppler mode for the SPM. This is a system software problem."
  },
  {
    "Error Code": "0051",
    "Module Name": "cSpcsGspmMisc.c",
    "Text Message": "SSP is present, but no code compiled for the
Miscellaneous support for the SSP. This is a system software problem."
  },
  {
    "Error Code": "0052",
    "Module Name": "cSpcsGspmMisc.c",
    "Text Message": "SPM is present, but no code compiled for the
Miscellaneous support for the SPM. This is a system software problem."
  },
  {
    "Error Code": "0053",
    "Module Name": "cSpcsGspmMode.c",
    "Text Message": "SSP is present, but no code compiled for the
Mmode for the SSP. This is a system software problem."
  },
  {
    "Error Code": "0054",
    "Module Name": "cSpcsGspmMode.c",
    "Text Message": "SPM is present, but no code compiled for the
Mmode for the SPM. This is a system software problem."
  },
  {
    "Error Code": "0055",
    "Module Name": "cSpcsGspmTwod.c",

```

```

        "Text Message": "SSP is present, but no code compiled for the
2D mode for the SSP. This is a system software problem."
    },
    {
        "Error Code": "0056",
        "Module Name": "cSpcsGspmTwod.c",
        "Text Message": "SPM is present, but no code compiled for the
2D mode for the SPM. This is a system software problem."
    },
    {
        "Error Code": "0057",
        "Module Name": "cInit.c",
        "Text Message": "Could not initialize the Front End Sub-System.
No recommendations."
    },
    {
        "Error Code": "0058",
        "Module Name": "bImem.c",
        "Text Message": "Imem failure. Replace the IMEM board. If this
error repeats, it could be a software memory allocation problem."
    },
    {
        "Error Code": "0059",
        "Module Name": "cFecsXdcr.c",
        "Text Message": "The scanhead prom checksum was incorrect.
Replace the bad scanhead. If it repeats, this could be a problem with
the FEC or SHSEL which read the data."
    },
    {
        "Error Code": "0060",
        "Module Name": "cFecsXdcr.c",
        "Text Message": "The scanhead prom checksum was incorrect.
Replace the bad scanhead. If this error repeats, this could be a
communication problem with the FEC or SHSEL which read the data, which
could be a software problem."
    }
]

```