

# **mitsubishi**

**Mitsubishi Industrial Robot**

**SD Series**  
**Tracking Function Manual**









---

**MELFA**  
**BFP-A8664-A**



## Safety Precautions

Always read the following precautions and the separate "Safety Manual" before starting use of the robot to learn the required measures to be taken.

-  **CAUTION** All teaching work must be carried out by an operator who has received special training. (This also applies to maintenance work with the power source turned ON.)  
Enforcement of safety training
-  **CAUTION** For teaching work, prepare a work plan related to the methods and procedures of operating the robot, and to the measures to be taken when an error occurs or when restarting. Carry out work following this plan. (This also applies to maintenance work with the power source turned ON.)  
Preparation of work plan
-  **WARNING** Prepare a device that allows operation to be stopped immediately during teaching work. (This also applies to maintenance work with the power source turned ON.)  
Setting of emergency stop switch
-  **CAUTION** During teaching work, place a sign indicating that teaching work is in progress on the start switch, etc. (This also applies to maintenance work with the power source turned ON.)  
Indication of teaching work in progress
-  **WARNING** Provide a fence or enclosure during operation to prevent contact of the operator and robot.  
Installation of safety fence
-  **CAUTION** Establish a set signaling method to the related operators for starting work, and follow this method.  
Signaling of operation start
-  **CAUTION** As a principle turn the power OFF during maintenance work. Place a sign indicating that maintenance work is in progress on the start switch, etc.  
Indication of maintenance work in progress
-  **CAUTION** Before starting work, inspect the robot, emergency stop switch and other related devices, etc., and confirm that there are no errors.  
Inspection before starting work

The points of the precautions given in the separate "Safety Manual" are given below.  
Refer to the actual "Safety Manual" for details.

- ⚠CAUTION** Use the robot within the environment given in the specifications. Failure to do so could lead to a drop or reliability or faults. (Temperature, humidity, atmosphere, noise environment, etc.)
- ⚠CAUTION** Transport the robot with the designated transportation posture. Transporting the robot in a non-designated posture could lead to personal injuries or faults from dropping.
- ⚠CAUTION** Always use the robot installed on a secure table. Use in an instable posture could lead to positional deviation and vibration.
- ⚠CAUTION** Wire the cable as far away from noise sources as possible. If placed near a noise source, positional deviation or malfunction could occur.
- ⚠CAUTION** Do not apply excessive force on the connector or excessively bend the cable. Failure to observe this could lead to contact defects or wire breakage.
- ⚠CAUTION** Make sure that the workpiece weight, including the hand, does not exceed the rated load or tolerable torque. Exceeding these values could lead to alarms or faults.
- ⚠WARNING** Securely install the hand and tool, and securely grasp the workpiece. Failure to observe this could lead to personal injuries or damage if the object comes off or flies off during operation.
- ⚠WARNING** Securely ground the robot and controller. Failure to observe this could lead to malfunctioning by noise or to electric shock accidents.
- ⚠CAUTION** Indicate the operation state during robot operation. Failure to indicate the state could lead to operators approaching the robot or to incorrect operation.
- ⚠WARNING** When carrying out teaching work in the robot's movement range, always secure the priority right for the robot control. Failure to observe this could lead to personal injuries or damage if the robot is started with external commands.
- ⚠CAUTION** Keep the jog speed as low as possible, and always watch the robot. Failure to do so could lead to interference with the workpiece or peripheral devices.
- ⚠CAUTION** After editing the program, always confirm the operation with step operation before starting automatic operation. Failure to do so could lead to interference with peripheral devices because of programming mistakes, etc.
- ⚠CAUTION** Make sure that if the safety fence entrance door is opened during automatic operation, the door is locked or that the robot will automatically stop. Failure to do so could lead to personal injuries.
- ⚠CAUTION** Never carry out modifications based on personal judgments, or use non-designated maintenance parts.  
Failure to observe this could lead to faults or failures.
- ⚠WARNING** When the robot arm has to be moved by hand from an external area, do not place hands or fingers in the openings. Failure to observe this could lead to hands or fingers catching depending on the posture.

**⚠CAUTION** Do not stop the robot or apply emergency stop by turning the robot controller's main power OFF. If the robot controller main power is turned OFF during automatic operation, the robot accuracy could be adversely affected. Moreover, it may interfere with the peripheral device by drop or move by inertia of the arm.

**⚠CAUTION** Do not turn off the main power to the robot controller while rewriting the internal information of the robot controller such as the program or parameters. If the main power to the robot controller is turned off while in automatic operation or rewriting the program or parameters, the internal information of the robot controller may be damaged.

## Revision history

[illegible]

## ■Preface

Thank you very much for purchasing Mitsubishi Electric Industrial Robot SD series.

The tracking function allows robots to follow workpieces on a conveyer or transport, line up and process the workpieces without having to stop the conveyer. The conveyor tracking function is the standard function in SD series. It can use only by having the parameter "TRMODE" changed into "1."

Please be sure to read this manual carefully and understand the contents thoroughly before starting to use the equipment in order to make full use of the tracking function.

Within this manual, we have tried to describe all ways in which the equipment can be handled, including non-standard operations, to the greatest extent possible. Please avoid handling the equipment in any way not described in this manual.

Note that this manual is written for the following software version.

Ver. P1 or later

- No part of this manual may be reproduced by any means or in any form, without prior consent from Mitsubishi.
- The contents of this manual are subject to change without notice.
- An effort has been made to make full descriptions in this manual. However, if any discrepancies or unclear points are found, please contact your service provider.
- The information contained in this document has been written to be accurate as much as possible. Please interpret that items not described in this document "cannot be performed." or "alarm may occur". Please contact your service provider if you find any doubtful, wrong or skipped point.
- This specifications is original.

Copyright(C) 2009 MITSUBISHI ELECTRIC CORPORATION

# [Contents]

1. Overview .....	1-1
1.1. What is the Tracking Function? .....	1-1
1.2. Applications .....	1-2
2. System Configuration .....	2-3
2.1. Components .....	2-3
2.1.1. Robot controller enclosure products .....	2-3
2.1.2. Devices Provided by Customers .....	2-3
2.2. Example of System Configuration .....	2-5
2.2.1. Configuration Example of Conveyor Tracking Systems .....	2-5
2.2.2. Configuration Example of Vision Tracking Systems .....	2-6
3. Specification .....	3-7
3.1. Tracking Specifications and Restriction matter .....	3-7
4. Operation Procedure .....	4-8
5. Connection of Equipment .....	5-9
5.1. Preparation of Equipment .....	5-9
5.1.1. Connection of Conveyor Encoder .....	5-10
5.1.2. Installation of encoder cable .....	5-11
5.1.3. Connection of Photoelectric Sensor .....	5-13
6. Parameter Setting .....	6-15
6.1. Dedicated Input/Output Parameters .....	6-15
6.2. Operation Parameters .....	6-15
6.3. Tracking Parameter Setting .....	6-16
7. Sample Robot Programs .....	7-17
8. Calibration of Conveyor and Robot Coordinate Systems ("A" program) .....	8-18
9. Calibration of Vision Coordinate and Robot Coordinate Systems ("B" program) .....	9-23
10. Workpiece Recognition and Teaching ("C" program) .....	10-28
10.1. Program for Conveyor Tracking .....	10-28
10.2. Program for Vision Tracking .....	10-32
11. Teaching and Setting of Adjustment Variables ("1" Program) .....	11-38
12. Sensor Monitoring Program ("CM1" Program) .....	12-42
12.1. Program for Conveyor Tracking .....	12-42
12.2. Program for Vision Tracking .....	12-42
13. Automatic Operation .....	13-43
14. Maintenance .....	14-45
14.1. MELFA-BASIC V Instructions .....	14-45
14.1.1. List of Instructions .....	14-45
14.1.2. List of Robot Status Variables .....	14-45
14.1.3. List of Functions .....	14-46
14.1.4. Explanation of Tracking Operation Instructions .....	14-46
14.2. Timing Diagram of Dedicated Input/Output Signals .....	14-53
14.2.1. Robot Program Start Processing .....	14-53
15. Troubleshooting .....	15-54
15.1. Occurrence of Error Numbers in the Range from 9000 to 9999 .....	15-54
15.2. Occurrence of Other Errors .....	15-55
15.3. In such a case (improvement example) .....	15-56
15.3.1. Make adsorption and release of the work speedy .....	15-56
15.3.2. Make movement of the robot speedy. ....	15-56
15.3.3. The robot is too speedy and drops the work. ....	15-56
15.3.4. Circle movement in tracking. ....	15-57
15.3.5. Restore backup data to another controller .....	15-57
16. Appendix .....	16-58
16.1. List of Parameters Related to Tracking .....	16-58
16.2. Expansion serial interface Connector Pin Assignment .....	16-59
16.3. Chart of sample program .....	16-60
16.3.1. Conveyor tracking .....	16-60
16.3.2. Vision Tracking .....	16-66
16.4. Sample Programs .....	16-70
16.4.1. Conveyor Tracking .....	16-70
16.4.2. Vision Tracking .....	16-77





## 1. Overview

### 1.1. What is the Tracking Function?

The tracking function allows a robot to follow workpieces moving on a conveyer. With this function, it becomes possible to transport, line up and process workpieces without having to stop the conveyer. It also eliminates the need for mechanical fixtures and so forth required to fix workpiece positions.

The features of this function are described below.

- 1) It is possible to follow lined-up workpieces moving on a conveyer while working on them (conveyer tracking making use of photoelectronic sensors).
- 2) It is possible to follow workpieces that are not in a line moving on a conveyer while working on them, even in the case of different types of workpieces (vision tracking combined with vision sensors).
- 3) It is possible to follow changes of movement speed due to automatic calculation of conveyer movement speed.
- 4) Tracking function can be easily achieved by using Mitsubishi's robot command MELFA-BASIC V.
- 5) System construction is made easy by use of sample programs.

## 1.2. Applications

Tracking is primarily intended for applications such as the following.

### (1) Transfer of processed food pallets




Figure 1-1 Example of Processed Food Pallet Transfer

### (2) Lining up parts




Figure 1-2 Example of Parts Lineup

### (3) Assembly of small electrical products




Figure 1-3 Example of Small Electrical Products Assembly

## 2. System Configuration

### 2.1. Components

#### 2.1.1. Robot controller enclosure products

The product structure of the tracking functional relation enclosed by the robot controller is shown in the Table 2–1.

**Table 2–1 List of Configuration in the tracking functional-related product**

Product name	Model name	Remark
Tracking function Manual	BFP-A8664	This manual
Sample program	–	Please refer to "7 Sample Robot Programs" for the sample robot program.

#### 2.1.2. Devices Provided by Customers

When configuring the system, the customers must have certain other devices in addition to this product. The table below shows the minimum list of required devices. Note that different devices are required depending on whether conveyer tracking or vision tracking is used. Please refer to "Table 2–2 List of Devices Provided by Customers (Conveyer Tracking)" and "Table 2–3 List of Devices Provided by Customers (Vision Tracking)" for further details.

**Table 2–2 List of Devices Provided by Customers (Conveyer Tracking)**

Table 2-2 List of Devices Provided by Customers (Conveyer Tracking)			
Name of devices to be provided by customers	Model	Quantity	Remark
<b>Robot part</b>			
Teaching pendant	R32TB or R56TB	1	
Hand	—		
Hand sensor	—	(1)	Used to confirm that workpieces are gripped correctly. Provide as necessary.
Solenoid valve set	See the Remark column		Different models are used depending on the robot used. Check the robot version and provide as necessary.
Hand input cable			
Air hand interface	2A-RZ365 or 2A-RZ375		Provide as necessary.
Calibration jig	—		This is a jig with a sharp tip that is attached to the mechanical interface of the robot arm and used for calibration tasks. It is recommended to use the jig if high precision is required.
<b>Conveyer part</b>			
Conveyer (with encoder)	—	1	Encoder(Recommended product): Omron encoder (E6B2-CWZ1X-1000 or -2000) Recommended connector for encoder input terminal: 10120-30000VE plug made by 3M 10320-52F0-008 shell made by 3M Encoder cable. Twisted-pair cable with the shield
Photoelectronic sensor	—		Used to synchronize tracking
5V power supply	—		+5 VDC (±10%) : For the encoder
24V power supply	—		+24 VDC (±10%) : For the Photoelectronic sensor
<b>Personal computer part</b>			
Personal computer	—	1	Please refer to the instruction manual of RT ToolBox2 for the details of the personal computer specifications.
RT ToolBox2 (Personal computer support software)	3D-11C-WINE 3D-12C-WINE		

**Table 2-3 List of Devices Provided by Customers (Vision Tracking)**

Name of devices to be provided by customers	Model	Quantity	Remark
Robot part			
Teaching pendant	R32TB or R56TB	1	
Hand	—		
Hand sensor	—	(1)	Used to confirm that workpieces are gripped correctly. Provide as necessary.
Solenoid valve set	See the Remark column		Different models are used depending on the robot used. Check the robot version and provide as necessary.
Hand input cable			Provide as necessary.
Air hand interface	2A-RZ365 or 2A-RZ375		This is a jig with a sharp tip that is attached to the mechanical interface of the robot arm and used for calibration tasks. It is recommended to use the jig if high precision is required.
Calibration jig	—		
Conveyer part			
Conveyer (with encoder)	—	1	Encoder(Recommended product): Omron encoder (E6B2-CWZ1X-1000 or -2000) Recommended connector for encoder input terminal: 10120-30000VE plug made by 3M 10320-52F0-008 shell made by 3M Encoder cable. Twisted-pair cable with the shield
Photoelectric sensor	—		Used to synchronize tracking
5V power supply	—		+5 VDC (±10%) : For the encoder
24V power supply	—		+24 VDC (±10%) : For the Photoelectric sensor and Vision sensor
Vision sensor part			
Basic network vision sensor set	4D-2CG5xxxx-PKG	1	See the instruction manual of the network vision sensor for details
Lens	—		C-mount lens
Lighting installation	—	(1)	Provide as necessary.
Connection part			
Hub	—	1	
Ethernet cable (straight)	—	2	Between Robot controller and Hub Between Personal computer and Hub
Personal computer part			
Personal computer	—	1	Please refer to the instruction manual of RT ToolBox2 or the instruction of the network vision sensor for details of the personal computer specifications.
RT ToolBox2 (Personal computer support software)	3D-11C-WINE 3D-12C-WINE		Please refer to the instruction manual of RT ToolBox2 for the details of the personal computer specifications.

## 2.2. Example of System Configuration

The following figure shows examples of conveyer tracking systems and vision tracking systems.

### 2.2.1. Configuration Example of Conveyer Tracking Systems

The following figure shows a configuration example of a system that recognizes lined-up workpieces on a conveyer passing a photoelectric sensor and follows the workpieces.




Figure 2-1 Configuration Example of Conveyer Tracking (Top View)




Figure 2-2 Configuration Example of Conveyer Tracking

### 2.2.2. Configuration Example of Vision Tracking Systems

The following figure shows a configuration example of a system that recognizes positions of workpieces that are not lined up on a conveyor with a vision sensor and follows the workpieces.




Figure 2-3 Configuration Example of Vision Tracking (Top View)




Figure 2-4 Configuration Example of Vision Tracking

### 3. Specification

#### 3.1. Tracking Specifications and Restriction matter

"Table 3-1 Tracking Function Specifications" shows the tracking specifications.

Please refer to "Standard Specifications Manual" for the specifications of the robot arm and controller to be used.

**Table 3-1 Tracking Function Specifications**

Item		Specification and Restriction matter
Supported robots		RV-3SD/6SD/12SD series RH-6SDH/12SDH/18SDH series
Applicable robot controller		CR1D/ CR2D/CR3D controller
Robot program language		Load commands dedicated for the tracking function
Conveyer	Movement speed (*1)	Possible to support up to 300 mm/s (When the robot always transport the workpieces) Possible to support up to 500 mm/s when the interval of workpiece is wide. Possible to support two conveyers by one Robot controller.
	Encoder	Output aspect : A, $\bar{A}$ , B, $\bar{B}$ , Z, $\bar{Z}$ Output form : line driver output (*2) Highest response frequency: 100 kHz Resolution(pulse/rotation) : Up to 2000 (4000 and 8000 uncorrespond) Recommended encoder: Omron E6B2-CWZ1X-1000 E6B2-CWZ1X-2000
	Encoder cable	Shielded twisted-pair cable Outside dimension : Maximum $\phi 6$ mm Conductor size: 24AWG (0.2 mm <sup>2</sup> ) Cable length: Up to 25 m
Photoelectronic sensor (*3)		Used to detect workpieces positions in conveyer tracking.
Vision sensor (*4)		Mitsubishi's network vision sensor
Precision at handling position (*5)		Approximately $\pm 2$ mm (when the conveyer speed is approximately 300 mm/s) (Photoelectronic sensor recognition accuracy, vision sensor recognition accuracy, robot repeatability accuracy and so on)

(\*1) The specification values in the table should only be considered guidelines. The actual values depend on the specific operation environment, robot model, hand and other factors.

(\*2) The line driver output is a data transmission circuit in accordance with RS-422A. It enables the long-distance transmission.

(\*3) The output signal of a photoelectronic sensor must be connected to a general input signal (arbitrary) of the robot controller.


(\*4) In the case of vision tracking, please refer to the instruction manual of network vision sensor.

(\*5) The precision with which workpieces can be grabbed is different from the repeatability at normal transportation due to the conveyer speed, sensor sensitivity, vision sensor recognition accuracy and other factors. The value above should only be used as a guideline.



### 4. Operation Procedure

This chapter explains the operation procedure for constructing a conveyer tracking system and a vision tracking system using Mitsubishi Electric industrial robots.



## **5. Connection of Equipment**

This section explains how to connect each of the prepared pieces of equipment.

### **5.1. Preparation of Equipment**

Prepare equipment by referring to “Table 2–2 List of Devices Provided by Customers (Conveyer Tracking)” to construct a conveyer tracking system and “Table 2–3 List of Devices Provided by Customers (Vision Tracking)” to construct a vision tracking system.

### 5.1.1. Connection of Conveyor Encoder

Wiring of the encoder for the conveyors and the encoder cable is shown in the "Figure 5-1 Wiring of the encoder for conveyors and encoder cable" shows the connection between a Expansion serial interface card connector and an encoder. (The cable uses E6B-2-CWZ1X (by OMRON).)

The a maximum of two encoders for the conveyors are connectable as standard specification. A total of 8 signal wires are required for the connection for the power supply (+ and - terminals) and the + and - terminals of the differential encoders' A, B and Z phases. Refer to the instruction manual of the encoders to be used and connect the signal wires correctly. Note that shielded wires (SLD) should be connected to the ground of the controller and system.



## CAUTION

**Be sure to mount ferrite cores on all encoder cables.**

Be sure to mount the ferrite cores on the encoder cables at a position near the robot controller. If ferrite cores are not mounted, the robot may malfunction due to the influence of noise.



## CAUTION

**There is one robot controller connectable with the one encoder.**

If two or more robot controllers are connected to the one encoder, the waveform of the encoder falls and the exact encoder value may be unable to be acquired.




Figure 5-1 Wiring of the encoder for conveyors and encoder cable

Refer to "Table 16-2 Connectors: CNENC Pin Assignment" with pin assignment of connector (CNENC).

### 5.1.2. Installation of encoder cable

The installation method of the encoder cable is shown by controller to be used.

\*CR1D-700 series: "Figure 5-2-1 Installation of encoder cable (CR1D-700 series)"

\*CR2D-700 series: "Figure 5-3-2 Installation of encoder cable (CR2D-700 series)"

\*CR3D-700 series: "Figure 5-4-3 Installation of encoder cable (CR3D-700 series)"

And, the description about the measures against the noise is shown in the figure "Figure 5-5 Example of noise measures of tracking system".

#### (1)CR1D-700 series

Connect the encoder cable to the connector of the [CNENC] display. And, the ground of the cable uses the rear cover.




Figure 5-2-1 Installation of encoder cable (CR1D-700 series)

### (2)CR2D-700 series

Connect the encoder cable to the connector of the [CNENC] display. And, the ground of the cable uses the rear cover.




Figure 5-3-2 Installation of encoder cable (CR2D-700 series)

### (3)CR3D-700 series

Connect the encoder cable to the connector of the [CNENC] display. And, the ground of the cable uses the rear cover.





Figure 5-4-3 Installation of encoder cable (CR3D-700 series)

**(3) Measures against the noise**

The example of noise measures of the tracking system is shown in the following.

Please implement the measures against the noise if needed in the power supply periphery section for the encoders which prepared of the customer.

- 1) Please insert AC line filter (recommendation: MXB-1210-33 \* Densai-Lambda) in the AC input side cable of the power supply for the encoders.
- 2) Please insert the ferrite core (recommendation: E04SR301334 \* SEIWA ELECTRIC MFG.) in the DC output side cable of the power supply for the encoders.
- 3) Please connect the power supply case for the encoders to the installation operator control panel, connect the earth wire to grounding or the case, and insert the ferrite core (recommendation: E04SR301334 \* SEIWA ELECTRIC MFG.).



**Figure 5-5 Example of noise measures of tracking system**

### 5.1.3. Connection of Photoelectric Sensor

If a photoelectric sensor is used for detection of workpieces, connect the output signal of the photoelectric sensor to a general input signal of the robot controller. Any general input signal number of the robot controller can be selected.

In this section, a connection example where the photoelectric sensor signal is connected to the 6th general input signal is shown in "Figure 5-7 Photoelectric Sensor Connection Example (6th General Input Signal is Used)."





Figure 5-6 Photoelectric Sensor Arrangement Example



Note) The external power supply and photoelectric sensor must be prepared

Note) This connection example shows the connection of the source type.

Figure 5-7 Photoelectric Sensor Connection Example (6th General Input Signal is Used)

## 6. Parameter Setting

This chapter explains how to set dedicated input/output signals that play the role of interface between a robot and an external device (e.g., a Programmable Logic Controller) and parameters related to the tracking function. Please refer to “Detailed Explanations of Functions and Operations” for how to set the parameters.

### 6.1. Dedicated Input/Output Parameters

“Table 6–1 List of Dedicated Input/Output Parameters” lists the setting items of dedicated input/output parameters used to operate the robot via instructions from an external device. Set the signal numbers according to your system using the setting values in the table as reference. **It is not necessary to set these parameters if the robot operates by itself, rather than via instructions from an external device.**

**Table 6–1 List of Dedicated Input/Output Parameters**

Input name/output name (parameter name)	Explanation	Setting Example (*1)
Stop/pausing ( <b>STOP</b> ) or ( <b>STOP2</b> )	Input: Stop a program Output: Output program standby status	0 , -1
Servo OFF/servo ON disabled ( <b>SRVOFF</b> )	Input: Turn the servo off Output: Output servo ON disabled status	1 , -1
Error reset/error occurring ( <b>ERRRESET</b> )	Input: Cancel error status Output: Output error status	2 , -1
Start/operating ( <b>START</b> )	Input: Start automatic operation Output: Output program running status	3 , 1
Servo ON/turning servo ON ( <b>SRVON</b> )	Input: Turn the servo on Output: Output servo on status	4 , 0
Operation right/operation right enabled ( <b>IOENA</b> )	Input: Enable/disable operation right of external signal control Output: Output external signal control operation enabled status	5 , -1
Program reset/program selectable ( <b>SLOTINIT</b> )	Input: Initiate a program. The program execution returns to the first step. Output: Output a status where program No. can be changed	10 , -1
General output signal reset ( <b>OUTRESET</b> )	Input: Reset a general output signal	11 , -1
User specification area 1 ( <b>USRAREA</b> )	Output an indication that the robot is in an area specified by a user Set the start number and end number	8 , 8

(\*1) “-1” in the Setting value column means “not set.”

### 6.2. Operation Parameters

“Table 6–2 List of Operation Parameter” lists the setting items of parameters required to operate the robot at the optimal acceleration/deceleration.

**Table 6–2 List of Operation Parameter**

Parameter name	Explanation	Reference value
Optimal acceleration/ deceleration hand data ( <b>HANDDAT1</b> )	Specify hand weight and so on to make settings that allow optimal acceleration/deceleration operations. For example, if the hand weighs 3 kg, changing the weight setting value from 10 kg to 3 kg makes the robot movement faster. (Hand weight (kg), size (mm) X, Y, Z, gravity (mm) X, Y, Z)	(3,0,0,0,0,0) The setting values are different for each robot model. <b>Use these values as reference only.</b>
Optimal acceleration/ deceleration workpiece data ( <b>WRKDAT1</b> )	Specify workpiece weight and so on to make settings that allow optimum acceleration/deceleration operations. If a workpiece is grabbed via the HClose instruction, the acceleration/deceleration becomes slower. If a workpiece is released via the HOpen instruction, acceleration/deceleration becomes faster. (Workpiece weight (kg), size (mm) X, Y, Z, gravity (mm) X, Y, Z)	(1,0,0,0,0,0) The setting values are different for each robot model. <b>Use these values as reference only.</b>



### 6.3. Tracking Parameter Setting

Specify to which channel of a Encoder connector(CNENC) an encoder of a conveyer is connected.  
 “Table 6–3 Tracking Parameter Setting” lists the parameters to be set. Other parameters are shown in “Table 16-1 List of Tracking Parameters”; make settings as required.

**Table 6–3 Tracking Parameter Setting**

Parameter	Parameter name	Number of elements	Explanation	Value set at factory shipping																		
Tracking mode	TRMODE	1 integer	Enable the tracking function Please set it to “1” when you use the tracking function. 0: Disable/1: Enable	0																		
Encoder number allocation	EXTENC	8 integers	<div><div><div>Set connection destinations on the connector for encoder numbers 1 to 8. Parameter elements correspond to encoder number 1, encoder number 2 ... encoder number 8 from the left. In addition, the encoder physics numbers 3-8 are the reservation number for extension. At present, it cannot be used.</div><table><tr><th>Connection channel</th><th>Encoder physics number</th></tr><tr><td>Standard CH1</td><td>1</td></tr><tr><td>Standard CH2</td><td>2</td></tr><tr><td>Slot1 CH1</td><td>3</td></tr><tr><td>Slot1 CH2</td><td>4</td></tr><tr><td>Slot2 CH1</td><td>5</td></tr><tr><td>Slot2 CH2</td><td>6</td></tr><tr><td>Slot3 CH1</td><td>7</td></tr><tr><td>Slot3 CH2</td><td>8</td></tr></table><div>Reservation number for future extension</div></div><div><p>The value of the encoder which wired the channel 1 in case of the standard encoder input connector [CNENC] for the robot controller is equipped with the encoder cable with initial setting,The value of the encoder which wired the channel 2 by the status variable "M_Enc (1)", "M_Enc (3)", "M_Enc (5)", and "M_Enc (7)",It can confirm by the status variable "M_Enc (2)", "M_Enc (4)", "M_Enc (6)", and "M_Enc (8)."</p><p>It is convenient to check the status variable “M_Enc” when determining the setting value of the “EXTENC” parameter. Please refer to "14.1.2 List of Robot Status Variables” for the explanation of state variable “M_Enc”. Please refer to “Detailed Explanations of Functions and Operations” for how to check the status variable</p></div></div>	Connection channel	Encoder physics number	Standard CH1	1	Standard CH2	2	Slot1 CH1	3	Slot1 CH2	4	Slot2 CH1	5	Slot2 CH2	6	Slot3 CH1	7	Slot3 CH2	8	1,2,3,4,1,2,3,4
Connection channel	Encoder physics number																					
Standard CH1	1																					
Standard CH2	2																					
Slot1 CH1	3																					
Slot1 CH2	4																					
Slot2 CH1	5																					
Slot2 CH2	6																					
Slot3 CH1	7																					
Slot3 CH2	8																					
Tracking Workpiece judgement distance	TRCWDST	1 integer	Distance to judge that the same workpiece is being tracked (mm) The sensor reacts many times when the workpiece with the ruggedness passes the sensor. Then, the robot controller judged that one workpiece is two or more pieces. The sensor between values [mm] set to this parameter does not react after turning on the sensor.	5.00																		

## 7. Sample Robot Programs

This chapter explains the structure of the sample robot programs.

Two types of sample robot programs are provided; for conveyer tracking and for vision tracking. Their program structures are shown in “Table 7–1 List of Sample Robot Programs (Conveyer Tracking)” and “Table 7–2 List of Sample Robot Programs (Vision Tracking)” respectively.

Refer to “RT ToolBox2 Robot Total Engineering Support Software Instruction Manual” for how to install programs to the robot controller.

**Table 7–1 List of Sample Robot Programs (Conveyer Tracking)**

Program name	Description	Explanation
<b>A</b>	Conveyer - robot coordinate system calibration program	This program matches the coordinate systems of the conveyer and robot and calculates the amount of robot movement per encoder pulse.
<b>C</b>	Workpiece coordinate system - robot coordinate system matching program	This program calculates the coordinates at which the robot grabs a workpiece based on the coordinates at which a sensor is activated.
<b>1</b>	Operation program	This program handles transporting workpieces while following recognized workpieces. (1) Movement to the robot origin (2) Workpiece suction and transportation operation while following movement
<b>CM1</b>	Workpiece coordinate monitor program	This program monitors encoder values and stores workpiece coordinates.

**Table 7–2 List of Sample Robot Programs (Vision Tracking)**

Program name	Description	Explanation
<b>A</b>	Conveyer - robot coordinate system calibration program	This program matches the coordinate systems of the conveyer and robot and calculates the amount of robot movement per encoder pulse.
<b>B</b>	Vision coordinate system – robot coordinate system calibration program	This program matches the vision coordinate system and the robot coordinate system.
<b>C</b>	Workpiece coordinate system - robot coordinate system matching program	This program calculates the coordinates at which the robot grabs a workpiece based on the coordinates at which a vision sensor has detected the workpiece.
<b>1</b>	Operation program	This program handles transporting workpieces while following recognized workpieces. (1) Movement to the robot origin (2) Workpiece suction and transportation operation while following movement
<b>CM1</b>	Workpiece coordinate monitor program	This program monitors encoder values and stores workpiece coordinates.

## 8. Calibration of Conveyor and Robot Coordinate Systems ("A" program)

This chapter explains the tasks carried out by using "A" program.

**\* "A" program contains operations required for both conveyor tracking and vision tracking.**

Calibration of a conveyor refers to determining the movement direction of the conveyor in the robot coordinate system and the amount of movement of the robot per encoder pulse. This amount of movement is stored in the robot's status variable "P\_EncDIt."


"A" Program performs specified tasks and automatically calculates the amount of movement of the robot per encoder pulse mentioned above.

The procedures of operations specified by "A" program and items to be confirmed after the operations are explained below.


Please refer to "Detailed Explanations of Functions and Operations" for the steps involved in each operation. Please monitor status variable "M\_Enc(1)" to "M\_Enc(8)" before it works, rotate the encoder, and confirm the value changes.

### (1) Operation procedure


- 1) Mount a calibration jig on the mechanical interface of a robot. Connect a personal computer on which RT ToolBox2(option) is installed to the robot controller.
- 2) Set the controller [MODE] switch to "MANUAL". Set the T/B to "ENABLE".




- 3) Press one of the keys (example, [EXE] key) while the <TITLE> screen is displayed. The <MENU> screen will appear.




- 4) Select "1. FILE /EDIT" screen on the <MENU> screen.




- 5) Press the arrow key, combine the cursor with the program name "A" and press the [EXE] key. Display the <program edit> screen.



- 6) Press the [FUNCTION] key, and change the function display




- 7) Press the [F1] (FWD) key and execute step feed. "(1)Encoder No ....." is displayed




- 8) Work according to the comment directions in the robot program.

- 9) Next "" (2) On conveyor both .. Execute step feed to "".



- 10) Repeat (7) - (8) and execute step feed to "End."

- 11) Press the [F2] (JUMP) key and input the step number. Press the [EXE] key. Then returns to first step



- 12) Press the [FUNCTION] key, and change the function display. Press the [F4] (close) key and close the program.





Figure 8-1 Conveyor and Robot Calibration Operation Diagram

### (2) Tasks

1) Set the encoder number to the X coordinates value of position variable: "PE."

(a) Press the function key ([F2]) corresponding to "the change", and display the position edit screen.

<PROGRAM> A 1 ' ## Ver.A1 ##### 2 # tracking robot - conveyor calibra 3 # NAME : A.prg 4 # Create/version : 2006.04.21 A1 DIRECT CHANGE 123 CLOSE		→	<POS> JNT 100% P5 X:+0000.00 A:+0000.00 Y:+0000.00 B:+0000.00 Z:+0000.00 C:+0000.00 L1:+0000.00 L2:+0000.00 FL1:00000007 FL2:00000000 MOVE TEACH 123 Prev Next
--	--	---	--

(b) The [F3] (Prev) key or the [F4] (Next) key is pressed, change the target variable, and display "PE" on the position name.

<POS> JNT 100% PE X:+0000.00 A:+0000.00 Y:+0000.00 B:+0000.00 Z:+0000.00 C:+0000.00 L1:+0000.00 L2:+0000.00 FL1:00000007 FL2:00000000 MOVE TEACH 123 Prev Next
--

(c) X coordinates are selected by the arrow key, press the [CLEAR] key for a long time, and delete the details. Input the encoder number into X coordinates.

<POS> JNT 100% PE X:+0001.00 A:+0000.00 Y:+0000.00 B:+0000.00 Z:+0000.00 C:+0000.00 L1:+0000.00 L2:+0000.00 FL1:00000007 FL2:00000000 MOVE TEACH 123 Prev Next
--

(d) Press the function key ([F2]) corresponding to "the change", and display the command edit screen.

<POS> JNT 100% PE X:+0001.00 A:+0000.00 Y:+0000.00 B:+0000.00 Z:+0000.00 C:+0000.00 L1:+0000.00 L2:+0000.00 FL1:00000007 FL2:00000000 DELETE NAME 123 CHANGE CLOSE	→	<PROGRAM> A 1 ' ## Ver.A1 ##### 2 # tracking robot - conveyor calibra 3 # NAME : A.prg 4 # Create/version : 2006.04.21 A1 DIRECT CHANGE 123 CLOSE
--	---	--

- 2) Attach a marking sticker on the conveyor (a sticker with an X mark is the best choice for the marking sticker).

Drive the conveyor and stop it when the marking sticker comes within the robot movement range.




Figure 8-2 Position of Marking Sticker on Conveyor

- 3) Move the robot to the position right at the center of the marking sticker on the conveyor.  
 \* **With this operation, encoder data and robot position are acquired.**



## CAUTION

### ***Move the robot to an accurate position.***

Be sure to move the robot to the position exactly at the center of the marking sticker because the amount of robot movement per encoder pulse is determined by the robot positions specified for the first and second times. Moreover, pay attention to the robot height as well because this amount of movement includes changes of robot position in the Z axis direction.

- 4) Raise the robot.
- 5) Drive the conveyor and stop at a position where the marking sticker is immediately outside the robot movement range.



### CAUTION

***The marking sticker should be moved for the maximum amount of movement allowed by the robot movement range.***

If the amount of movement is too small, errors in the amount of robot movement per encoder pulse will become large due to the error of the position specified for the robot.

- 6) Move the robot to the position right above the center of the marking sticker on the moved conveyor.  
\* **With this operation, encoder data and robot position are acquired.**
- 7) Raise the robot.
- 8) Perform step operation until "End."  
\* **The amount of robot movement per encoder pulse is calculated based on this operation.**

### (3) Confirmation after operation

Check the value of "P\_EncDlt" using T/B.

\* **This value indicates the movement of each coordinate (mm) of the robot coordinate system, corresponding to the movement of the conveyor per pulse.**

Example) If "0.5" is displayed for the Y coordinate only

This means that if the conveyor moves for 100 pulses, the workpiece moves 50 mm ( $0.5 \times 100 = 50$ ) in the +Y direction in the robot coordinate system.

### (4) When multiple conveyers are used

Carry out the same operations as above when multiple conveyers are used as well, but pay attention to the following points.

Example) When using conveyor 2 (encoder number 2):

- (a) Enter "2" for the encoder number specified for the X coordinate of the position variable "PE" in the program.
- (b) Check the value of "P\_EncDlt(2)" using RT ToolBox2 when confirming the data after operation.

**Refer to "RT ToolBox2 Robot Total Engineering Support Software Instruction Manual" for how to check variable values using RT ToolBox2.**

## 9. Calibration of Vision Coordinate and Robot Coordinate Systems ("B" program)

This chapter explains the tasks carried out by using "B" program.

\* **"B" program only contains operations required when constructing a vision tracking system.**

**These operations are not necessary when constructing a conveyor tracking system.**

Calibration of a vision sensor refers to converting the position of a workpiece recognized by the vision sensor to the corresponding position in the robot coordinate system. This calibration operation is easily performed by the "calibration data creation" function of MELFA-Vision (network vision support software). Refer to "Network Vision Sensor Instruction Manual" for the details of this function.


"B" program performs specified tasks and allows acquiring the workpiece coordinates recognized by the vision sensor in the robot coordinate system (position coordinates of robot movement).

The procedures of operations specified by "B" program and items to be confirmed after the operations are explained below.


Please refer to "Detailed Explanations of Functions and Operations" for the steps involved in each operation.

### (1) Operation procedure


- 1) Open "B" program using T/B.
- 2) Set the controller [MODE] switch to "MANUAL". Set the T/B to "ENABLE".




- 3) Press one of the keys (example, [EXE] key) while the <TITLE> screen is displayed. The <MENU> screen will appear.



- 4) Select "1. FILE /EDIT" screen on the <MENU > screen.




- 5) Press the arrow key, combine the cursor with the program name "B" and press the [EXE] key. Display the <program edit> screen.






- 6) Press the [FUNCTION] key, and change the function display




- 7) Press the [F1] (FWD) key and execute step feed. "(1)Encoder No ....." is displayed




- 8) Work according to the comment directions in the robot program.

- 9) Next "" (2) Vision sensor .. Execute step feed to "".



- 10) Repeat (7) - (8) and execute step feed to "End."

- 11) Press the [F2] (JUMP) key and input the step number. Press the [EXE] key. Then returns to first step



- 12) Press the [FUNCTION] key, and change the function display. Press the [F4] (close) key and close the program.





Figure 9-1 Vision Sensor and Robot Calibration Operation Procedure Diagram

(2) Tasks

- 1) Set the encoder number to the X coordinates value of position variable: "PE."

(a) Press the function key ([F2]) corresponding to "the change", and display the position edit screen.

<pre> &lt;PROGRAM&gt; B 1 '## Ver.A1 ##### 2 '# tracking robot - conveyor calibra 3 '# NAME      : B.prg 4 '# Create/version : 2006.04.21 A1         </pre>		➔	<pre> &lt;POS&gt; JNT 100% P1 X:+0000.00 A:+0000.00 Y:+0000.00 B:+0000.00 Z:+0000.00 C:+0000.00 L1:+0000.00 L2:+0000.00 FL1:00000007 FL2:00000000         </pre>
<div>DIRECT CHANGE 123 CLOSE</div>			<div>MOVE TEACH 123 Prev Next</div>

(b) The [F3] (Prev) key or the [F4] (Next) key is pressed, change the target variable, and display "PE" on the position name.

<pre> &lt;POS&gt; JNT 100% PE X:+0000.00 A:+0000.00 Y:+0000.00 B:+0000.00 Z:+0000.00 C:+0000.00 L1:+0000.00 L2:+0000.00 FL1:00000007 FL2:00000000         </pre>	
<div>MOVE TEACH 123 Prev Next</div>	

(c) X coordinates are selected by the arrow key, press the [CLEAR] key for a long time, and delete the details. Input the encoder number into X coordinates.

<pre> &lt;POS&gt; JNT 100% PE X:+0001.00 A:+0000.00 Y:+0000.00 B:+0000.00 Z:+0000.00 C:+0000.00 L1:+0000.00 L2:+0000.00 FL1:00000007 FL2:00000000         </pre>	
<div>MOVE TEACH 123 Prev Next</div>	

(d) Press the function key ([F2]) corresponding to "the change", and display the command edit screen.

<pre> &lt;POS&gt; JNT 100% PE X:+0001.00 A:+0000.00 Y:+0000.00 B:+0000.00 Z:+0000.00 C:+0000.00 L1:+0000.00 L2:+0000.00 FL1:00000007 FL2:00000000         </pre>	➔	<pre> &lt;PROGRAM&gt; B 1 '## Ver.A1 ##### 2 '# tracking robot - conveyor calibra 3 '# NAME      : B.prg 4 '# Create/version : 2006.04.21 A1         </pre>
<div>DELETE NAME 123 CHANGE CLOSE</div>		<div>DIRECT CHANGE 123 CLOSE</div>

- 2) Start MELFA-Vision and make the vision sensor into the off-line. Select the [live picture] of MELFA-Vision and display the picture which the vision sensor picturized on real time. Refer to "NETWORK VISION SENSOR INSTRUCTION MANUAL " for operation of MELFA-Vision.

- 3) Paste four marking stickers on the conveyer (stickers with X marks are the best choice for the marking stickers).  
Attach these marking stickers within the field of vision of the vision sensor while checking the live images of MELFA-Vision.  
\* With this operation, encoder data is acquired.




Figure 9-2 Pasting Marking Stickers

- 4) Close [Live Mode] of MELFA-Vision and open the Create Calibration Data screen. Click the [Image] button in the [Sensor Reference Point] column and register the positions of the four stickers on [Camera Image].  
\* In MELFA-Vision, in case of the error message "communication is impossible with the robot controller" is displayed, please confirm the setup of the communications server.
- 5) Move the marking stickers within the robot movement range.
- 6) Move the robot to the position right above the first marking sticker on the conveyor.

- 7) Click the [Position] button in the Create Calibration Data screen of MELFA-Vision and acquire the current robot position.
- 8) Move the robot to the position right at the second marking sticker.
- 9) Click the [Position] button in the Create Calibration Data screen and acquire the current robot position.
- 10) Move the robot to the position right at the third marking sticker.
- 11) Click the [Position] button in the Create Calibration Data screen and acquire the current robot position.
- 12) Move the robot to the position right at the fourth marking sticker.
- 13) Click the [Position] button in the Create Calibration Data screen and acquire the current robot position.
- 14) Raise the robot.  
**\* With this operation, encoder data is acquired.**
- 15) Use MELFA-Vision to save the calibration data.  
**\*With this operation, the workpiece coordinates recognized by the vision sensor can be displayed in the robot coordinate system.**

### (3) Confirmation after operation

Check the value of "M\_100()" using T/B.

Enter the **encoder number** in the array element.

Confirm that the differences between the encoder values acquired on the vision sensor side and the encoder values acquired on the robot side are set in "M\_100()."




## CAUTION

***If precision is highly important, use four workpieces instead of marking stickers to specify 4 points at which they are grabbed.***

When marking stickers are used, a vision sensor calculates the robot position on a flat plane immediately above the conveyor. If the workpiece height is large, the robot coordinate values may deviate from the actual workpiece center displayed when the center of the workpiece is recognized.

For this reason, it is recommended to calibrate the robot using workpieces in order to make sure that the robot calculates the coordinates correctly, based on a flat plane immediately above the workpieces.



### 10. Workpiece Recognition and Teaching ("C" program)

This chapter explains the tasks carried out by using "C" program.

\* **"C" program contains operations required for both conveyer tracking and vision tracking, but different operations are performed. Refers to "10.1 Program for Conveyer Tracking" for operations in the case of conveyer tracking and "10.2 Program for Vision Tracking" for operations in the case of vision tracking.**

Please refer to "Detailed Explanations of Functions and Operations" for the steps involved in each operation.


#### 10.1. Program for Conveyer Tracking

In "C" program for conveyer tracking, encoder data at the positions where a sensor is activated and where the robot suction a workpiece is acquired so that the robot can recognize the workpiece coordinates when the sensor is activated at later times.


The operation procedure and items to be confirmed after operation in "C" program for conveyer tracking are explained below.

##### (1) Operation procedure


- 1) Open "C" program using T/B.
- 2) Set the controller [MODE] switch to "MANUAL". Set the T/B to "ENABLE".




- 3) Press one of the keys (example, [EXE] key) while the <TITLE> screen is displayed. The <MENU> screen will appear.




- 4) Select "1. FILE /EDIT" screen on the <MENU > screen.




- 5) Press the arrow key, combine the cursor with the program name "C" and press the [EXE] key. Display the <program edit> screen.



- 6) Press the [FUNCTION] key, and change the function display




- 7) Press the [F1] (FWD) key and execute step feed. "(1)Vision No ....." is displayed




- 8) Work according to the comment directions in the robot program.。

- 9) Next "" (2) Encoder No.. Execute step feed to "".



- 10) Repeat (7) - (8) and execute step feed to "End."

- 11) Press the [F2] (JUMP) key and input the step number. Press the [EXE] key. Then returns to first step



- 12) Press the [FUNCTION] key, and change the function display. Press the [F4] (close) key and close the program.






Figure 10-1 Operation for Matching Workpiece Coordinates and Robot Coordinates

## (2) Tasks

- 1) Enter the model number, encoder number and number of the sensor that monitors the workpieces in the X, Y and Z coordinates of the position variable "PRM1" in the program.

(a) Press the function key ([F2]) corresponding to "the change", and display the position edit screen.

<b>&lt;PROGRAM&gt; C</b>			
1 '## Ver.A1 #####			
2 # tracking robot - conveyor calibra			
3 # NAME : C.prg			
4 # Create/version : 2006.04.21 A1			
<b>DIRECT</b>	<b>CHANGE</b>	123	<b>CLOSE</b>



<b>&lt;POS&gt; JNT 100% PRM2</b>			
X:+0000.00	A:+0000.00		
Y:+0000.00	B:+0000.00		
Z:+0000.00	C:+0000.00		
L1:+0000.00	L2:+0000.00		
FL1:00000007	FL2:00000000		
<b>MOVE</b>	<b>TEACH</b>	123	<b>Prev</b> <b>Next</b>

- (b) The [F3] (Prev) key or the [F4] (Next) key is pressed, change the target variable, and display "PRM1" on the position name.

<b>&lt;POS&gt; JNT 100% PRM1</b>			
X:+0000.00	A:+0000.00		
Y:+0000.00	B:+0000.00		
Z:+0000.00	C:+0000.00		
L1:+0000.00	L2:+0000.00		
FL1:00000007	FL2:00000000		
<b>MOVE</b>	<b>TEACH</b>	123	<b>Prev</b> <b>Next</b>

- (c) X coordinates are selected by the arrow key, press the [CLEAR] key for a long time, and delete the details. Input the model number into X coordinates.

<b>&lt;POS&gt; JNT 100% PRM1</b>			
X:+0001.00	A:+0000.00		
Y:+0000.00	B:+0000.00		
Z:+0000.00	C:+0000.00		
L1:+0000.00	L2:+0000.00		
FL1:00000007	FL2:00000000		
<b>MOVE</b>	<b>TEACH</b>	123	<b>Prev</b> <b>Next</b>

- (d) Y coordinates are selected by the arrow key, press the [CLEAR] key for a long time, and delete the details. Input the encoder number into Y coordinates.


<b>&lt;POS&gt; JNT 100% PRM1</b>			
X:+0001.00	A:+0000.00		
Y:+0001.00	B:+0000.00		
Z:+0000.00	C:+0000.00		
L1:+0000.00	L2:+0000.00		
FL1:00000007	FL2:00000000		
<b>MOVE</b>	<b>TEACH</b>	123	<b>Prev</b> <b>Next</b>

- (e) Z coordinates are selected by the arrow key, press the [CLEAR] key for a long time, and delete the details. Input the number of the sensor that monitors the workpieces into Z coordinates.

<b>&lt;POS&gt; JNT 100% PRM1</b>			
X:+0001.00	A:+0000.00		
Y:+0001.00	B:+0000.00		
Z:+0008.00	C:+0000.00		
L1:+0000.00	L2:+0000.00		
FL1:00000007	FL2:00000000		
<b>MOVE</b>	<b>TEACH</b>	123	<b>Prev</b> <b>Next</b>

- (f) Press the function key ([F2]) corresponding to "the change", and display the command edit screen.

<b>&lt;POS&gt; JNT 100% PRM1</b>			
X:+0001.00	A:+0000.00		
Y:+0001.00	B:+0000.00		
Z:+0008.00	C:+0000.00		
L1:+0000.00	L2:+0000.00		
FL1:00000007	FL2:00000000		
<b>DELETE</b>	<b>NAME</b>	123	<b>CHANGE</b> <b>CLOSE</b>



<b>&lt;PROGRAM&gt; C</b>			
1 '## Ver.A1 #####			
2 # tracking robot - conveyor calibra			
3 # NAME : C.prg			
4 # Create/version : 2006.04.21 A1			
<b>DIRECT</b>	<b>CHANGE</b>	123	<b>CLOSE</b>

- 2) Move a workpiece to the location where the sensor is activated.  
\* **With this operation, encoder data is acquired.**
- 3) Drive the conveyor to move the workpiece within the robot movement range.
- 4) Move the robot to the position where it suctions the workpiece.  
\* **With this operation, encoder data and robot position are acquired.**
- 5) Perform step operation until "End."

- \* **With this operation, the robot is able to calculate the position of a workpiece as soon as the sensor is activated.**

**(3) Confirmation after operation**

Confirm the values of "M\_101()," "P\_100()" and "P\_102()" using T/B.

Enter **encoder numbers** in array elements.

- "M\_101()": Differences between the encoder values acquired at the position of the photoelectric sensor and the encoder values acquired on the robot side.
- "P\_100()": Position at which workpieces are suctioned
- "P\_102()": The value of the variable "PRM1" set in step (1)

Check that each of the values above has been entered correctly.




### 10.2. Program for Vision Tracking


Vision tracking "C" program acquires encoder data at the position where the vision sensor recognizes workpieces and where the robot suction workpieces such that the robot can recognize the work coordinates recognized by the vision sensor. The following explains the operation procedure and items to confirm after operation in vision tracking "C" program.

#### (1) Operation procedure


- 1) Register workpieces to be recognized by a vision sensor and create a vision program.  
Please refer to "Network vision sensor manual" for the method of making the vision program.
- 2) Open "C" program using T/B.
- 3) Set the controller [MODE] switch to "MANUAL". Set the T/B to "ENABLE".




- 4) Press one of the keys (example, [EXE] key) while the <TITLE> screen is displayed. The <MENU> screen will appear.




- 5) Select "1. FILE /EDIT" screen on the <MENU > screen.




- 6) Press the arrow key, combine the cursor with the program name "C" and press the [EXE] key. Display the <program edit> screen.



- 7) Press the [FUNCTION] key, and change the function display




- 8) Press the [F1] (FWD) key and execute step feed. "(1)Vision No ....." is displayed




- 9) Work according to the comment directions in the robot program.

- 10) Next "" (2) Encoder No.. Execute step feed to "".



- 11) Repeat (7) - (8) and execute step feed to "End."

- 12) Press the [F2] (JUMP) key and input the step number. Press the [EXE] key. Then returns to first step



- 13) Press the [FUNCTION] key, and change the function display. Press the [F4] (close) key and close the program.






Figure 10-2 Operation for Matching Workpiece Coordinates and Robot Coordinates

## (2) Tasks

- 1) Enter the model number and encoder number in the X and Y coordinates of the position variable "PRM1" in the program.

- (a) Press the function key ([F2]) corresponding to "the change", and display the position edit screen.

<PROGRAM> C			
1 '## Ver.A1 #####			
2 # tracking robot - conveyor calibra			
3 # NAME : C.prg			
4 # Create/version : 2006.04.21 A1			
DIRECT	CHANGE	123	CLOSE



<POS> JNT 100% P_100(0)			
X:+0000.00	A:+0000.00		
Y:+0000.00	B:+0000.00		
Z:+0000.00	C:+0000.00		
L1:+0000.00	L2:+0000.00		
FL1:00000007	FL2:00000000		
MOVE	TEACH	123	Prev Next

- (b) The [F3] (Prev) key or the [F4] (Next) key is pressed, change the target variable, and display "PRM1" on the position name.

<POS> JNT 100% PRM1			
X:+0000.00	A:+0000.00		
Y:+0000.00	B:+0000.00		
Z:+0000.00	C:+0000.00		
L1:+0000.00	L2:+0000.00		
FL1:00000007	FL2:00000000		
MOVE	TEACH	123	Prev Next

- (c) X coordinates are selected by the arrow key, press the [CLEAR] key for a long time, and delete the details. Input the model number into X coordinates.


<POS> JNT 100% PRM1			
X:+0001.00	A:+0000.00		
Y:+0000.00	B:+0000.00		
Z:+0000.00	C:+0000.00		
L1:+0000.00	L2:+0000.00		
FL1:00000007	FL2:00000000		
MOVE	TEACH	123	Prev Next

- (d) Y coordinates are selected by the arrow key, press the [CLEAR] key for a long time, and delete the details. Input the encoder number into Y coordinates.

<POS> JNT 100% PRM1			
X:+0001.00	A:+0000.00		
Y:+0001.00	B:+0000.00		
Z:+0000.00	C:+0000.00		
L1:+0000.00	L2:+0000.00		
FL1:00000007	FL2:00000000		
MOVE	TEACH	123	Prev Next

- (f) Press the function key ([F2]) corresponding to "the change", and display the command edit screen.

<POS> JNT 100% PRM1			
X:+0001.00	A:+0000.00		
Y:+0001.00	B:+0000.00		
Z:+0000.00	C:+0000.00		
L1:+0000.00	L2:+0000.00		
FL1:00000007	FL2:00000000		
DELETE	NAME	123	CHANGE CLOSE



<PROGRAM> C			
1 '## Ver.A1 #####			
2 # tracking robot - conveyor calibra			
3 # NAME : C.prg			
4 # Create/version : 2006.04.21 A1			
DIRECT	CHANGE	123	CLOSE

- 2) Start MELFA-Vision and place the vision sensor in the offline status. Select [Live Mode] in MELFA-Vision to display images taken by the vision sensor in real-time. Check the images and set the field of vision in the moving direction of the conveyor (mm) and the length of workpieces detected by the vision sensor (length in the moving direction of the conveyor) in the **X and Y** coordinates of the position variable "PRM2" in the program, respectively.

- (a) Open the [Position data Edit] screen.
- (b) Display "PRM2" at the position name.
- (c) Enter the field of vision in the moving direction of the conveyor (mm) in the X coordinate.
- (d) Enter the workpiece length detected by the vision sensor (length in the moving direction of the conveyor (mm)) in the Y coordinate.
- (d) Return to the [Command edit] screen.

- 3) Specify a communication line to be connected with the vision sensor.

(a) Open the [Command edit] screen.

```
<PROGRAM> C
1 '# Ver.A1 #####
2 '# tracking robot - conveyor calibra
3 '# NAME : C.prg
4 '# Create/version : 2006.04.21 A1
EDIT DELETE 123 INSERT TEACH
```

(b) Display the comamnd step shown in the following

```
<PROGRAM> C
11 'COM.No. of communication line
12 CCOM$="COM2"
13 'Program name of Vision
14 CPRG$="TRK. JOB"
EDIT DELETE 123 INSERT TEACH
```

(c) Press [F1] (edit) key and specify the line opened for the robot controller may connect with the vision sensor to the variable "CCOM\$."

example) Open COM3:

```
<PROGRAM> C Edit
12 CCOM$="COM2:"
EDIT DELETE 123 INSERT TEACH
```

```
<PROGRAM> C Edit
12 CCOM$="COM3:"
EDIT DELETE 123 INSERT TEACH
```

(d) Press the [EXE] key and edit is fixed.

```
<PROGRAM> C
11 'COM.No. of communication line
12 CCOM$="COM3"
13 'Program name of Vision
14 CPRG$="TRK. JOB"
EDIT DELETE 123 INSERT TEACH
```



- 4) Specify a vision program to be started.  
In the same way as in step 3), change the vision program name entered after "CPRG\$=" in the program.
- 5) Specify the cell in the program in which the number of recognized workpieces is stored.  
In the same way as in step 3), change the cell storing the number of recognized workpieces entered after "CKOSU\$=" in the program.  
The number of recognized workpieces is displayed in "Job edit" screen "Recognition result cell position" tab of MELFA-Vision.




Figure 10-3 Job Editing Screen(Result Cell Position Tab)

- 6) Specify the starting cell of the area where recognition results are stored in the vision program.  
In the same way as in step 3), change the starting cell of the area storing recognition results entered after "CSTT\$=" in the program.  
The starting cell of the area storing recognition results is displayed in "Job edit" screen "Recognition result cell position" tab of MELFA-Vision.
- 7) Specify the ending cell of the area where recognition results are stored in the vision program.  
In the same way as in step 3), change the ending cell of the area storing recognition results entered after "CEND\$=" in the program.  
The ending cell of the area storing recognition results is displayed in "Job edit" screen "Recognition

result cell position" tab of MELFA-Vision.

- 8) Place a workpiece to be recognized within the area that the vision sensor can recognize.
- 9) Using MELFA-Vision, place the vision sensor in the online status.
- 10) Using T/B, close the opened "C" program once and then run the modified "C" program automatically with the robot controller.

T/B disabled




Set the T/B [ENABLE] switch to "DISABLE".

Controller enabled



Set the controller [MODE] switch to "AUTOMATIC".

Servo ON



Press the [SVO ON] key, the servo will turn ON, and the SVO ON lamp will light.

**Selection of a program number**

Display of a program number



Press the [CHNG DISP] key and display "PROGRAM NO." on the STATUS NUMBER display.

Selection of a program number



Press the [UP] or the [DOWN] key and display program name "C."

**Start of automatic operation**

Start



Press the [START] key.

After automatic operation, "C" program automatically stops and the LED of the [STOP] button is turned on. Open "C" program again with T/B. Press the [F1](FWD) key to display the subsequent operation messages.

**\* With this operation, encoder data and workpiece position recognized by the vision sensor are acquired.**

11) Rotate the conveyer forward and move a workpiece within the vision sensor recognition area into the robot movement range.

12) Move the robot to the position where it is able to suction the workpiece.

**\* With this operation, encoder data and robot position are acquired.**

13) Perform step operation until "End."

**\* With this operation, the robot becomes able to recognize the position of the workpiece recognized by the vision sensor.**

### (3) Confirmation after operation

Check the values of the following variables using T/B.

Enter the model number for the array number.

- Value of "M\_101()": Differences between encoder values when a workpiece is within the vision sensor area and when the workpiece is on the robot side
- Value of "P\_102()": Data in the variable "PRM1" (model number/encoder number)
- Value of "P\_103()": Data in the variable "PRM2" (recognition field of image view/workpiece size)
- Value of "C\_100\$()": COM number
- Value of "C\_101\$()": Vision program name
- Value of "C\_102\$()": Recognized quantity cell
- Value of "C\_103\$()": Recognition area start cell
- Value of "C\_104\$()": Recognition area end cell

Confirm that each of the above values is entered.

## 11. Teaching and Setting of Adjustment Variables ("1" Program)

This chapter explains operations required to run "1" program.

**\* "1" program settings are required for both conveyer tracking and vision tracking.**

"1" program instructs the robot to follow and grab workpieces recognized by a photoelectric sensor or vision sensor and transport the workpieces.

The teaching positions required by "1" program are explained below, along with how to set adjustment variables prepared in the program.

### (1) Teaching

Teach the origin position and transportation destination. The following explains how to perform these operations.

- 1) Open "1" program using T/B.
- 2) Open the [Position data Edit] screen.
- 3) Display "P1" in order to set the robot origin position when the system is started.
- 4) Move the robot to the origin position and teach it the position.
- 5) Display "PPT" in order to set the transportation destination position (the location where workpieces are placed).
- 6) Move the robot to the transportation destination and teach it the position.

### (2) Setting of adjustment variables in the program

The following section explains how to set adjustment variables, which are required at transportation, and details about their setting.

Please refer to separate manual "Detailed Explanations of Functions and Operations" for how to set adjustment variables.

**Table 11-1 List of Adjustment Variables in Programs**

Variable name	Explanation	Setting example
PWK	Set the model number. X = model number (1 to 10)	When you set 1 to the model number: (X, Y, Z, A, B, C) = (+1,+0,+0,+0,+0,+0)
PRI	"1" program and "CM1" program are run simultaneously (multitasking). "1" program moves the robot, and "CM1" program observes the sensor. It is possible to specify which program is processed with a higher priority, rather than performing the same amount of processing at the same time. X = Set the line numbers of "1" program to be performed (1 to 31). Y = Set the line numbers of "CM1" program to be performed (1 to 31).	When you set to run "1" program by one line and run "CM1" program by 10 lines: (X, Y, Z, A, B, C) = (+1,+10,+0,+0,+0,+0)
PUP1	When operating by the adsorption of workpiece, set the height that the robot works. Height sets the amount of elevation (mm) from the position where workpiece is adsorbed. X = Amount of elevation of the position where a robot waits until a workpiece arrives. (mm) Y = Amount of elevation from the workpiece suction position (before suctioning) (mm) Z = Amount of elevation from the workpiece suction position (after suctioning) (mm)  * Since the Y and Z coordinates indicate distances in the Z direction in the tool coordinate system, the sign varies depending on the robot model.	When the following values are set: Amount of elevation of the position where a robot waits until a workpiece arrives : 50 mm Amount of elevation from the workpiece suction position (before suctioning) : -50 mm Amount of elevation from the workpiece suction position (after suctioning) : -50 mm  (X, Y, Z, A, B, C) = (+50,-50,-50,+0,+0,+0)

PUP2	<p>When operating in putting workpiece, set the height that the robot works. Height sets the amount of elevation (mm) from the position where workpiece is adsorbed. Y = Amount of elevation from the workpiece release position (before release). (mm) Z = Amount of elevation from the workpiece release position (after release). (mm) <b>* Since these values are distances in the Z direction of the tool coordinate system, the sign varies depending on the robot model.</b></p>	<p>When the following values are set: Amount of elevation from the workpiece release position (before release) : -50 mm Amount of elevation from the workpiece release position (after release) : -50 mm (X, Y, Z, A, B, C) = (+0,-50,-50,+0,+0,+0)</p>
PAC1	<p>When operating by the adsorption of workpiece, the acceleration and the deceleration when moving to the position on the workpiece are set. X = The acceleration until moving to the position on the workpiece. (1 to 100) (%) Y = The deceleration until moving to the position on the workpiece. (1 to 100) (%) <b>* The value set by X coordinates and Y coordinates of "PAC*" is used for &lt;acceleration ratio(%)&gt; of the Accel instruction and &lt;deceleration ratio(%)&gt;.</b> <b>The value is reduced when the speed of time when the robot vibrates and the robot is fast.</b></p>	<p>When the following values are set: Acceleration until moving to the position on the workpiece. : 100% Deceleration until moving to the position on the workpiece. : 100% (X, Y, Z, A, B, C) = (+100,+100,+0,+0,+0,+0)</p>
PAC2	<p>When operating by the adsorption of workpiece, the acceleration and the deceleration when moving to the workpiece suction position are set. X = The acceleration until moving to the workpiece suction position. (1 to 100) (%) Y = The deceleration until moving to the workpiece suction position. (1 to 100) (%)</p>	<p>When the following values are set: Acceleration until moving to the workpiece suction position. : 10% Deceleration until moving to the workpiece suction position. : 20% (X, Y, Z, A, B, C) =(+10,+20,+0,+0,+0,+0)</p>
PAC3	<p>When operating by the adsorption of workpiece, the acceleration and the deceleration when moving toward the position on the workpiece are set. X = The acceleration until moving to the position on the workpiece. (1 to 100) (%) Y = The deceleration until moving to the position on the workpiece. (1 to 100) (%)</p>	<p>When the following values are set: Acceleration until moving to the position on the workpiece. : 50% Deceleration until moving to the position on the workpiece. : 80% (X, Y, Z, A, B, C) =(+50,+80,+0,+0,+0,+0)</p>
PAC11	<p>When operating by the release of workpiece, the acceleration and the deceleration when moving to the position on the workpiece are set. X = The acceleration until moving to the position release position. (1 to 100) (%) Y = The deceleration until moving to the position release position. (1 to 100) (%)</p>	<p>When the following values are set: Acceleration until moving to the position on the workpiece : 80% Deceleration until moving to the position on the workpiece : 70% (X, Y, Z, A, B, C) =(+80,+70,+0,+0,+0,+0)</p>
PAC12	<p>When operating by the release of workpiece, the acceleration and the deceleration when moving to the workpiece release position are set. X = The acceleration until moving to the workpiece release position. (1 to 100) (%) Y = The deceleration until moving to the workpiece release position. (1 to 100) (%)</p>	<p>When the following values are set: Acceleration until moving to the workpiece release position. : 5% Deceleration until moving to the workpiece release position. : 10% (X, Y, Z, A, B, C) = (+5,+10,+0,+0,+0,+0)</p>



PAC13	<p>When operating by the release of workpiece, the acceleration and the deceleration when moving toward the position on the workpiece are set.</p> <p>X = The acceleration until moving to the position on the workpiece. (1 to 100) (%)</p> <p>Y = The deceleration until moving to the position on the workpiece. (1 to 100) (%)</p>	<p>When the following values are set:</p> <p>Acceleration until moving to the position on the workpiece. : 100%</p> <p>Deceleration until moving to the position on the workpiece. : 100%</p> <p>(X, Y, Z, A, B, C) = (+100,+100,+0,+0,+0,+0)</p>																					
PDLY1	<p>Set the suction time.</p> <p>X: Suction time (s).</p>	<p>When setting 0.5 second for the sucking time:</p> <p>(X, Y, Z, A, B, C) = (+0.5,+0,+0,+0,+0,+0)</p>																					
PDLY2	<p>Set the release time.</p> <p>X: Release time (s).</p>	<p>When setting 0.3 second for the release time:</p> <p>(X, Y, Z, A, B, C) = (+0.3,+0,+0,+0,+0,+0)</p>																					
POFSET	<p>When the adsorption position shifts, the gap can be corrected. Set the correction value.</p> <p><b>* The direction of the correction is a direction of the hand coordinate system. Please decide the correction value after changing the job mode to "Tool", pushing the [+X] key and the [+Y] key, and confirming the operation of the robot.</b></p>																						
PTN	<p>Set the position of the robot and conveyer, and the direction where the workpiece moves.</p> <p>X = The following values. (1 to 6)</p> <table border="1"> <thead> <tr> <th>Setting value</th><th>Conveyer position</th><th>Conveyer direction</th></tr> </thead> <tbody> <tr> <td>1</td><td>Front</td><td>Right to Left</td></tr> <tr> <td>2</td><td>Front</td><td>Left to Right</td></tr> <tr> <td>3</td><td>Left side</td><td>Right to Left</td></tr> <tr> <td>4</td><td>Leftv</td><td>Left to Right</td></tr> <tr> <td>5</td><td>Right side</td><td>Right to Left</td></tr> <tr> <td>6</td><td>Right side</td><td>Left to Right</td></tr> </tbody> </table>	Setting value	Conveyer position	Conveyer direction	1	Front	Right to Left	2	Front	Left to Right	3	Left side	Right to Left	4	Leftv	Left to Right	5	Right side	Right to Left	6	Right side	Left to Right	<p>When a conveyer is placed in front of the robot and the workpiece moves from the left to right: (When in view of the robot)</p> <p>(X, Y, Z, A, B, C) = (+1,+0,+0,+0,+0,+0)</p> <p><b>The relationship between PRNG and PTN is shown in "Figure 11-1 Diagram of Relationship between Adjustment Variables "PRNG" and "PTN" in the Program".</b></p>
Setting value	Conveyer position	Conveyer direction																					
1	Front	Right to Left																					
2	Front	Left to Right																					
3	Left side	Right to Left																					
4	Leftv	Left to Right																					
5	Right side	Right to Left																					
6	Right side	Left to Right																					
PRNG	<p>Set range of motion where the robot judges workpiece to be able to follow.</p> <p>X = The start distance of the range in which the robot can follow a workpiece :(mm)</p> <p>Y = The end distance of the range in which the robot can follow a workpiece :(mm)</p> <p>Z = The distance in which follow is canceled :(mm)</p>	<p><b>The relationship between PRNG and PTN is shown in "Figure 11-1 Diagram of Relationship between Adjustment Variables "PRNG" and "PTN" in the Program".</b></p>																					




Figure 11-1 Diagram of Relationship between Adjustment Variables "PRNG" and "PTN" in the Program

## 12. Sensor Monitoring Program ( “CM1” Program)

This chapter provides an overview of “CM1” program, which is run in parallel, when “1” program is run. Different types of “CM1” programs are used for conveyer tracking and vision tracking, and different processing is performed for them. These programs are explained in the following.

### 12.1. Program for Conveyer Tracking

“CM1” program calculates the workpiece coordinates in the robot coordinate system at the moment where a photoelectric sensor is activated based on the following data acquired with “A” program and “C” program, and then stores the coordinates in the tracking buffer(Storage area to preserve data temporarily).

<Acquired data>

- Amount of robot movement per encoder pulse (P\_EncDlt)
- Difference between the encoder value when a photoelectric sensor is activated and the encoder value when teaching is performed on a robot
- Position at which the robot is taught to grab a workpiece

### 12.2. Program for Vision Tracking

“CM1” program converts the workpiece position recognized by the vision sensor to the corresponding coordinates in the robot coordinate system based on the following data acquired with “A” program, “B” program and “C” program, and then stores the coordinates in the tracking buffer.

<Acquired data>

- Amount of robot movement per encoder pulse(P\_EncDlt)
- Difference between the encoder value when a marking sticker is on the vision sensor side and the encoder value when the marking sticker is on the robot side
- Workpiece position recognized by the vision sensor
- Difference between the encoder value when the vision sensor recognizes a workpiece and the encoder value when teaching on the workpiece position was performed on the robot
- Position at which the robot is taught to grab a workpiece

The timing at which the vision sensor acquires images is calculated such that images of the same workpiece are taken at least once or up to twice by the following data specified in “C” program.

<Data specified in “C” program>

- Field of view in the conveyer movement direction
- Length of workpieces detected by a vision sensor (length in the conveyer movement direction)



### POINT

***“1” program follows workpieces on a conveyer based on the workpiece information stored in the tracking buffer in “C” program.***

“C” program performs processing until the recognized workpiece position is stored in the tracking buffer. The workpiece information stored in the tracking buffer is read by “1” program and the robot follows workpieces on the conveyer based on the information.

## 13. Automatic Operation

This chapter explains how to prepare the robot before starting the system.

### (1) Preparation

- 1) Check that there is no interfering object within the robot movement range.
- 2) Prepare to run the desired program.


T/B disabled



Controller enabled



Servo ON



**Selection of a program number**

Display of a program number



Selection of a program number



Set the T/B [ENABLE] switch to "DISABLE".

Set the controller [MODE] switch to "AUTOMATIC".

Press the [SVO ON] key, the servo will turn ON, and the SVO ON lamp will light.

Press the [CHNG DISP] key and display "PROGRAM NO." on the STATUS NUMBER display.


Press the [UP] or the [DOWN] key and display program name "1."

### (2) Execution

- 1) Be sure that you are ready to press the [Emergency Stop] button of T/B in the case of any unexpected movement of the robot.
- 2) Run the program from the operation panel of the robot controller.

**Start of automatic operation**

Start



Press the [START] key.

### (3) At error occurrence

If the robot moves erroneously, refer to separate manual "Troubleshooting".

### (4) Ending

The robot does not move unless a sensor that monitors workpieces is activated or a vision sensor recognizes a workpiece. Stop the flow of workpieces from the upstream and press the [STOP] button of the operation panel of the robot controller. Confirm that the [STOP] lamp is turned on.

## 14. Maintenance

This chapter explains information required when maintaining the sample programs (robot program language MELFA-BASIC V and dedicated input/output signals).

### 14.1. MELFA-BASIC V Instructions

The lists of instructions, status variables and functions related to tracking operation are shown below. Please refer to the separate manual "Detailed Explanations of Functions and Operations" for further information about MELFA-BASIC V.

#### 14.1.1. List of Instructions

Table 14-1 List of Instructions

Instruction name	Function
TrBase	Specify the workpiece coordinate origin of teaching data and tracking external encoder logic number.
TrClr	Clear the tracking data buffer.
Trk	Declare start and end of the tracking mode.
TrOut	Output signals from a general-purpose output and read the encoder values.
TrRd	Read workpiece data from the tracking data buffer.
TrWrt	Write workpiece data in the tracking data buffer.

#### 14.1.2. List of Robot Status Variables

Table 14-2 List of Robot Status Variables

Variable name	Number of arrays	Function	Attribute (*1)	Data type
M_Enc	number of encoders 1 to 8	External encoder data External encoder data can be rewritten. <b>If this state variable does not set parameter "TRMODE" to "1", the value becomes like "0".</b>	R/W	Double-precision real number
P_EncDlt	number of encoders 1 to 8	Amount of robot movement per encoder pulse <b>*This state variable is made by sample "A" program.</b>	R/W	Position
M_Trbfct	buffer No. 1 to The first argument of parameter [TRBUF]	Number of data items stored in the tracking buffer	R	Integer
P_Cvspd	number of encoders 1 to 8	Conveyer speed (mm, rad/sec)	R	Position
M_EncMax	number of encoders 1 to 8	The maximum value of external encoder data	R	Double-precision real number
M_EncMin	number of encoders 1 to 8	The minimum value of external encoder data	R	Double-precision real number
M_EncSpd	number of encoders 1 to 8	External encoder speed(Unit: pulse/sec)	R	Single-precision real number
M_TrkCQ	mechanism No. 1 to 3	Tracking operation status of specified mechanism 1: Tracking 0: Not tracking	R	Integer

(\*1) R: Only reading is permitted.

R/W: Both reading and writing are permitted.

## 14.1.3. List of Functions

Table 14-3 List of Functions

Function name	Function	Result
Poscq(<position>)	Check whether the specified position is within the movement range. 1: Within the movement range 0: Outside the movement range	Integer
TrWcur(<encoder number>, <position>, <encoder value>)	Obtain the current position of a workpiece.  <number of encoders> 1 to 8	Position
TrPos(<position>)	Acquire the coordinate position of a workpiece being tracked. Trk On P0,P1,1,M1# PC2=TrPos(P2) PC2 above is obtained in the following manner. PC1=P1+P_EncDlt*(M_Enc-M1#) ' The current position of P1 PC2=PC1*(P_Zero/P0*P2)	Position

## 14.1.4. Explanation of Tracking Operation Instructions

The instructions related to tracking operations are explained in details below.

The explanations of instructions are given using the following format.

- [Function] : Describes the function of an instruction.
- [Format] : Describes the entry method of arguments of an instruction.  
  - < > indicate an argument.
  - [ ] indicates that entry can be omitted.
  - indicate that space is required.
- [Term] : Describes meaning, range and so on of an argument.
- [Example] : Presents statement examples.
- [Explanation] : Provides detailed function descriptions and precautions.

**TrBase (tracking base)****[Function]**

Specify the workpiece coordinate system origin during the teaching operation and the encoder logic number of an external encoder used in tracking operation.

**[Format]**

TrBase □ <Reference position data> [ , <Encoder logic number>]
--

**[Term]**

**<Reference position data>** (can be omitted):

Specify the origin position of position data to be followed during the tracking mode.

**<Encoder logic number>** (can be omitted):

This is a logic number indicating the external encoder that performs tracking operation.

1 is set when this argument is omitted.

Setting range: 1 to 8

**[Example]**

1 TrBase P0	' Specify the workpiece coordinate origin at the teaching position.
2 TrRd P1,M1,MKIND	' Read the workpiece position data from the data buffer.
3 Trk On,P1,M1	' Start tracking of a workpiece whose position measured by a sensor is P1 and encoder value at that time is M1.
4 Mvs P2	' Setting the current position of P1 as P1c, make the robot operate while following workpieces with the target position of $P1c \cdot P\_Zero / P0 \cdot P2$ .
5 HClose 1	' Close hand 1.
6 Trk Off	' End the tracking operation.

**[Explanation]**

- Specify the workpiece coordinate system origin during the teaching operation and the logic number of an external encoder used in tracking operation.
- If an encoder logic number is omitted, the previously specified value 1 is set.
- The reference position data and encoder number are set to their initial values until they are specified by the TrBase instruction or the Trk On instruction. The initial value is P\_Zero for the reference position data and 1 for the encoder number.



**TrClr (tracking data clear)****[Function]**

Clears the tracking data buffer.

**[Format]**

TrClr □ [<Buffer number>]
---------------------------

**[Term]**

**<Buffer number>** (cannot be omitted):

Specify the number of a general-purpose output to be output.

Setting range: 1 to 4 (The first argument of parameter [TRBUF])

**[Example]**

1 TrClr 1	' Clear tracking data buffer No. 1.
2 *LOOP	
3 If M_In(8)=0 Then GoTo *LOOP	' Jump to *LOOP if input signal No. 8, to which a photoelectric sensor is connected, is OFF.
4 M1#=M_Enc(1)	' Acquire data of encoder number 1 at the time when input signal No. 8 is turned on and store it in M1#.
5 TrWrt P1, M1#,MK	' Write workpiece position data P1, encoder value M1# at the time an image is acquired and model number MK in the buffer.

**[Explanation]**

- Clear information stored in specified tracking buffer (1 to 4).
- Execute this instruction when initializing a tracking program.

## **Trk (tracking function)**

### [Function]

After Trk On is executed, the robot goes into the tracking mode and operates while following the conveyer operation until Trk Off is executed.

### [Format]

```
Trk □ On[,<Measurement position data>[,<Encoder data>][,<Reference position data>][,<Encoder logic
number>]]]]
Trk □ Off
```

### [Term]

**<Measurement position data>** (can be omitted):

Specify the workpiece position measured by a sensor.

**<Encoder data>** (can be omitted):

Specify a value of an encoder installed on a conveyer when a workpiece is measured.

**<Reference position data>** (can be omitted):

Specify the origin position of position data to be followed during the tracking mode.

If this argument is omitted, the robot follows the conveyer using the position specified by the TrBase instruction as the origin.

The initial value is PZERO.

**<Encoder logic number>** (can be omitted):

This is a logic number indicating the external encoder that performs tracking operation.

1 is set when this argument is omitted.

Setting range: 1 to 8

### [Example]

1 TrBase P0	' Specify the workpiece coordinate origin at the teaching position.
2 TrRd P1,M1,MKIND	' Read the workpiece position data from the data buffer.
3 Trk On,P1,M1	' Start tracking of a workpiece whose position measured by a sensor is P1 and encoder value at that time is M1.
4 Mvs P2	' Setting the current position of P1 as P1c, make the robot operate while following workpieces with the target position of $P1c \cdot P\_Zero / P0 \cdot P2$ (P2 indicates the workpiece grabbing position).
5 HClose 1	' Close hand 1.
6 Trk Off	' End the tracking operation.

### [Explanation]

- Specify the position relative to the position data specified by Trk On as show in line 20 of the statement example for the target position of the movement instruction during tracking operation.
- Lines 30 and 40 of the example above can also be written as follows.  
 3 Trk On,P1,M1,P0  
 4 Mvs P2  
 In this example, P2 in line 40 is regarded as a position relative to P0.
- "P\_Zero/P0" in "P1c\*P\_Zero/P0\*P2" in [Example] can be replaced with INV(P0).

**TrOut (reading tracking output signal and encoder value)****[Function]**

Read a tracking output value specified by a general-purpose output and read the value of an external encoder synchronously with the output.

**[Format]**

TrOut □ <Output number>, <Encoder 1 value read variable> [ , [<Encoder 2 value read variable>  
[ , [<Encoder 3 value read variable>] [ , [<Encoder 4 value read variable>  
[ , [<Encoder 5 value read variable>] [ , [<Encoder 6 value read variable>  
[ , [<Encoder 7 value read variable>] [ , [<Encoder 8 value read variable>] ]]]]]]

**[Term]**

**<Output number>** (cannot be omitted):

Specify the number of a general-purpose output to be output.

**<Encoder n value read variable>** (can be omitted):

Specify a double-precision value variable in which read values of an external encoder are stored.

Note) n is a value in the range from 1 to 8.

**[Example]**

```
1 *LOOP1
2 If M_In(10) <> 1 GoTo *LOOP1 ' Check whether a photoelectronic sensor is activated.
3 TrOut 20, M1#, M2#           ' Output from general-purpose output No. 20 and store the value of
                                ' external encoder No.1 in M1#, and store the value of external encoder
                                ' No.2 in M2# synchronously with the output.

4 *LOOP2
5 If M_In(21) <> 1 GoTo *LOOP2 ' Wait until the signal (general-purpose input No.21) which shows
                                ' acquiring image from the vision sensor is turned on.
6 M_Out(20)=0                  ' Turn off the No.20 general-purpose output.
```

**[Explanation]**

- This instruction is used when triggering the vision sensor that calculates positions of workpieces to be tracked.
- It is possible to know the position where workpiece images are acquired by obtaining the external encoder values synchronously with the output.
- The general-purpose output signal specified <Output number> is maintained. Therefore, please turn off the signal by using the M\_Out state variable when you confirm acquiring of the vision sensor.

**TrRd (reading tracking data)****[Function]**

Read position data for tracking operation, encoder data and so on from the data buffer.

**[Format]**

TrRd □ <Position data> [ , <Encoder data> ] [ , <Model number> ] [ , <Buffer number> ] [ , <Encoder number> ] ] ]
---

**[Term]**

- <Position data>** (cannot be omitted):  
Specify a variable that contains workpiece positions read from the buffer.
- <Encoder data>** (can be omitted):  
Specify a variable that contains encoder values read from the buffer.
- <Model number>** (can be omitted):  
Specify a variable that contains model numbers read from the buffer.
- <Buffer number>** (can be omitted):  
Specify a number of a buffer from which data is read.  
1 is set if the argument is omitted.  
Setting range: 1 to 4(The first argument of parameter [TRBUF])
- <Encoder number>** (can be omitted):  
Specify a variable that contains values of external encoder numbers read from the buffer.

**[Example]**

## (1) Tracking operation program

1 TrBase P0	' Specify the workpiece coordinate origin at the teaching position.
2 TrRd P1,M1,MK	' Read the workpiece position data from the data buffer.
3 Trk On,P1,M1	' Start tracking of a workpiece whose measured position is P1 and encoder value at the time of measurement is M1.
4 Mvs P2	' Setting the current position of P1 as P1c, make the robot operate while following workpieces with the target position of P1c*P_Zero/P0*PW2.
5 HClose 1	' Close hand 1.
6 Trk Off	' End the tracking operation.

## (2) Sensor data reception program

1 *LOOP	
2 If M_In(8)=0 Then GoTo *LOOP	' Jump to *LOOP if input signal No. 8, to which a photoelectric sensor is connected, is OFF.
3 M1#=M_Enc(1)	' Acquire data of encoder number 1 at the time when input signal No. 8 is turned on and store it in M1#.
4 TrWrt P1, M1#,MK	' Write workpiece position data P1, encoder value M1# at the time an image is acquired and model number MK in the buffer.

**[Explanation]**

- Read the workpiece position (robot coordinates), encoder value, model number and encoder number stored by the TrWrt instruction from the specified buffer.
- If the TrRd instruction is executed when no data is stored in the specified buffer, Error 2540(There is no read data) occurs.

**TrWrt (writing tracking data)****[Function]**

Write position data for tracking operation, encoder data and so on in the data buffer.

**[Format]**

TrWrt □ <Position data> [, <Encoder data>] [, [<Model number>] [, [<Buffer number>] [, <Encoder number>]]]
--

**[Term]**

**<Position data>** (cannot be omitted):

Specify the workpiece position measured by a sensor.

**<Encoder data>** (can be omitted):

Specify the value of an encoder mounted on a conveyor at the time a workpiece is measured.

The encoder value acquired in the M\_Enc() state variable and the TrOut instruction is specified usually.

**<Model number>** (can be omitted):

Specify the model number of workpieces.

Setting range: 1 to 65535

**<Buffer number>** (can be omitted):

Specify a data buffer number.

1 is set if the argument is omitted.

Setting range: 1 to 4(The first argument of parameter [TRBUF])

**<Encoder number>** (can be omitted):

Specify an external encoder number.

The same number as the buffer number is set if the argument is omitted.

Setting range: 1 to 8

**[Example]****(1) Tracking operation program**

1 TrBase P0	' Specify the workpiece coordinate origin at the teaching position.
2 TrRd P1,M1,MKIND	' Read the workpiece position data from the data buffer.
3 Trk On,P1,M1	' Start tracking of a workpiece whose measured position is P1 and encoder value at the time of measurement is M1.
4 Mvs P2	' Setting the current position of P1 as P1c, make the robot operate while following workpieces with the target position of P1c*P_Zero/P0*PW2.
5 HClose 1	' Close hand 1.
6 Trk Off	' End the tracking operation.

**(2) Sensor data reception program**

1 *LOOP	
2 If M_In(8)=0 Then GoTo *LOOP	' Jump to +LOOP if input signal No. 8, to which a photoelectric sensor is connected, is OFF.
3 M1#=M_Enc(1)	' Acquire data of encoder number 1 at the time when input signal No. 8 is turned on and store it in M1#.
4 TrWrt P1, M1#,MK	' Write workpiece position data P1, encoder value M1# at the time an image is acquired and model number MK in the buffer.


**[Explanation]**

- This function stores the workpiece position (robot coordinates) at the time when a sensor recognizes a workpiece, encoder value, model number and encoder number in the specified buffer.
- Arguments other than the workpiece position (robot coordinates) can be omitted. If any of the arguments are omitted, the robot operates while following changes of position data.
- Workpieces within the same workpiece judgment distance set in the "TRCWDST" parameter are regarded as the same workpiece. Even if the data is written twice in the buffer with the TrWrt instruction, only one data set is stored in the buffer. For this reason, data for one workpiece only is read with the TrRd instruction even if images of the same workpiece are acquired twice with a vision sensor.

## 14.2. Timing Diagram of Dedicated Input/Output Signals

### 14.2.1. Robot Program Start Processing

The signal timing when a robot program is started from an external device is shown below.



- ① PLC sets "servo ON H" when it detects "turning servo ON L." The robot turns the servo power supply on and sets "turning servo ON H." PLC acknowledges "turning servo ON H" and sets "servo ON L."
- ② PLC sets "program reset H" upon receiving "program selectable L." The robot returns to the beginning of the program and sets "program selectable H" when the program becomes ready to be started. PLC sets "program reset L" when it detects "program selectable H."
- ③ PLC acknowledges "turning servo ON H," "program selectable H" and "operating L" and sets "start H." The robot sets "program selectable L" and "operating H" when it detects "start H." PLC confirms "operating H" and sets "start L."
- ④ If a stop signal is input, the following processing is performed. Upon receiving "stop H" from PLC, the robot sets "operating L."

## 15. Troubleshooting

This section explains causes of error occurrence and actions to be taken.

### 15.1. Occurrence of Error Numbers in the Range from 9000 to 9999

This section describes causes of errors that may occur while starting a program and how to handle them.

**Table 15-1 List of Errors in Sample Programs**

Error number	Error description	Causes and actions
9100	Communication error	<p>[Causes] The network vision sensor and the robot cannot be connected by the "C" program or the robot cannot log on the vision sensor.</p> <p>[Actions] ① Check the Ethernet cable which connects the robot with the network vision sensor.</p>
9101	Encoder number out of range	<p>[Causes] The encoder number specified in "A" program to "C" program is "0" or "9" or larger.</p> <p>[Actions] ① Check the X coordinate of the position variable "PE" in the programs.</p>
9102	Model number out of range	<p>[Causes] The model number specified in "C" program is "0" or "10" or larger.</p> <p>[Actions] ① Check the X coordinate of the position variable "PRM1" in "C" program. ② If there are more than 11 models, change "MWKMAX=10" line in "C" program.</p>
9110	Position accuracy out of range	<p>[Causes] The workpiece position calculated by operations in "A" program to "C" program is very different from the theoretical value.</p> <p>[Actions] ① Check the X and Y coordinates of the position variable "PVTR" in "CM1" program. These values represent the difference from the theoretical value. ② If the difference stored in "PVTR" is large, run "A" program to "C" program again. ③ Check that the X and Y coordinates of the position variable "PCHK" in "CM1" program are not "0." If they are "0," change the difference from the theoretical value to an allowable value.</p>
9199	Program error	<p>[Causes] A return value cannot be created by the *S50WKPOS function of "1" program.</p> <p>[Actions] ① Check the reason why "MY50STS" of the *S50WKPOS function in "1" program does not change from "0".</p>

## 15.2. Occurrence of Other Errors

Table 15-2 List of Tracking relation Errors

Error number	Error description	Causes and actions
2500	Tracking encoder data error	<p>[Causes] The data of the tracking encoder is abnormal. (The amount of the change is 1.9 times or more.)</p> <p>[Actions] ① Check whether the conveyer rotates at a constant speed. ② Check the wiring for the encoder. ③ Check whether the ground lead is connected.</p>
2510	Tracking parameter reverses	<p>[Causes] Tracking parameter[EXCRGMN] and [EXCRGMX] Setting value reverses</p> <p>[Actions] ① Check the value of [ENCRGMX] and [ENCRGMN] parameters.</p>
2520	Tracking parameter is range over	<p>[Causes] The set value is outside the range parameter [TRBUF]. The first argument is 1 to 8, and the second argument is 1 to 64.</p> <p>[Actions] ① Check the value of [TRBUF] parameter.</p>
2530	There is no area where data is written	<p>[Causes] The data of the size or more of the buffer in which the TrWrt command was continuously set to the second argument of parameter [TRBUF] was written.</p> <p>[Actions] ① Check the execution count of the TrWrt command is correct. ② Check the value of the second argument of parameter [TRBUF] is correct. ③ Check that the X and Y coordinates of the position variable "PCHK" in "CM1" program are not "0." If they are "0," change the difference from the theoretical value to an allowable value.</p>
2540	There is no read data	<p>[Causes] The TrRd command was executed in state the data is not written in tracking buffer.</p> <p>[Actions] ① Execute the TrRd command after confirming whether the buffer has the data with the state variable [M_Trbfct]. ② Confirm whether the buffer number specified by the buffer number specified in TrWrt Mende and the TrRd command is in agreement.</p>
2560	Illegal parameter of Tracking	<p>[Causes] The value set as the parameter [EXTENC] is outside the range. The ranges are 1-8.</p> <p>[Actions] ① Confirm the value set as the parameter [EXTENC].</p>
3982	Cannot be used (singular point)	<p>[Causes] The robot tried to pass the significant point while doing the tracking.</p> <p>[Actions] ① Keep away the position of the workpiece which flows on the conveyer from the robot. ② Expand the interval between the robot and the conveyer.</p>

Please refer to separate manual "Troubleshooting".



### 15.3. In such a case (improvement example)

Explain the improvement example, when building the tracking system using the sample robot program.

#### 15.3.1. Make adsorption and release of the work speedy

In the tracking system, adsorption confirmation of the work may be unnecessary. In that case, processing of adsorption and release can be made speedy by the following methods.

(1) Adjust adsorption time and release time.

Adjust the adjustment variable "PDLY1", and the value of X coordinates of "PDLY2" of the program 1. Refer to "Table 11-1 List of Adjustment Variables in Programs" for the adjustment method.

#### 15.3.2. Make movement of the robot speedy.

Adjust the following setting to make movement of the robot speedy.

(1) Adjustment of the optimal acceleration-and-deceleration setting

Set mass, size, and center of gravity of the hand installed in the robot as the parameter "HNDDAT1." And, set mass, size, and center of gravity of the work as the parameter "WRKDAT1."

By this setting, the robot can move with the optimal acceleration and deceleration and speed. Refer to "Table 6-2 List of Operation Parameter" for setting method.

(2) Adjustment of carrying height

By making low distance at adsorption and release of robot, the moving distance decreases and motion time can be shortened as a result. Refer to the adjustment variable of "PUP1" and "PUP2" in the "Table 11-1 List of Adjustment Variables in Programs" for change of rise distance.

#### 15.3.3. The robot is too speedy and drops the work.

Since the robot's acceleration and deceleration are speedy, drop the work, adjustment is necessary. Refer to the adjustment variable of 「PAC1」 to 「PAC3」 and 「PAC11」 to 「PAC13」 in the "Table 11-1 List of Adjustment Variables in Programs" for the adjustment method of the acceleration and deceleration.

#### 15.3.4. Circle movement in tracking.

Screw fastening and decoration on the work, etc are available in the tracking system. Here, explain the example which draws the circle on the basis of the adsorption position.

<Conditions>

\*The adsorption position taught by Program C is the starting point of the circle.

\*The offset from the adsorption position of pass and end position of circle decided as follows.

POF1=(+50,+50,0,0,0,0,0,0)(0,0).....Relative distance to pass position from adsorption position.

POF2=(0,+100,0,0,0,0,0,0)(0,0).....Relative distance to end position from adsorption position

\*Create PGT1 (pass point) and PGT2 (end point) from the relative distance.

\*Use the Mvr command (circle command) and move on the circle of PGT->PGT1 ->PGT2.

The example of program change of the above <conditions> is shown in the following.

Before sample program change		After sample program change	
81	Trk On,PBPOS,MBENC#,PTBASE...	81	Trk On,PBPOS,MBENC#,PTBASE...
82	Mov PGT,PUP1.Y Type 0,0	82	Mov PGT,PUP1.Y Type 0,0
83	Accel PAC2.X,PAC2.Y	83	<b>POF1=(+50,+50,0,0,0,0,0,0)(0,0) '</b>
84	Mvs PGT	84	<b>POF2=(0,+100,0,0,0,0,0,0)(0,0) '</b>
85	HCLOSE 1	85	<b>PGT1=PGT*POF1 'Pass position</b>
		86	<b>PGT2=PGT*POF2 'End position</b>
		87	Accel PAC2.X,PAC2.Y
		88	Mvs PGT
		89	<b>Mvr PGT,PGT1,PGT2 ' Circle movement</b>
		90	HCclose 1

#### 15.3.5. Restore backup data to another controller

The status variable "P\_EncDlt" is not saved in the backup data from tracking system robot controller.

To generate the value of "P\_EncDlt", execute the "P\_EncDlt(MENCNO) =PY10ENC" command of "Program A" by step forward. (Moving distance per one pulse)

## 16. Appendix

This appendix provides a list of parameters related to tracking and describes Expansion serial interface connector pin assignment as well as sample programs for conveyer tracking and vision tracking.


### 16.1. List of Parameters Related to Tracking

**Table 16–1 List of Parameters Related to Tracking**

Parameter	Parameter name	Number of elements	Description	Setting value at factory shipment
Minimum external encoder value	ENCRGMN	8 integers	The minimum external encoder data value (pulse)  The range of the encoder value which can be acquired in state variable "M_Enc" (minimum value side)	0,0,0,0,0,0,0,0
Maximum external encoder value	ENCRGMX	8 integers	The maximum external encoder data value (pulse)  The range of the encoder value which can be acquired in state variable "M_Enc" (maximum value side)	100000000, 100000000, 100000000, 100000000, 100000000, 100000000, 100000000, 100000000
Tracking buffer	TRBUF	2 integers	Number of tracking buffers and their sizes (KB) <Buffer number> Specify the number of buffers where the tracking data is stored. Setting range: 1 to 8 <Buffer size> Specify the size in which the tracking data is preserved. Setting range: 1 to 64	4 , 64
Tracking adjustment coefficient 1	TRADJ1	8 real numbers	Tracking adjustment coefficient 1 Set the amount of delay converted to the conveyer speed. Convert to 100 mm/s. Example) <ul style="list-style-type: none"> <li>If the delay is 2 mm when the conveyer speed is 50 mm/s: Setting value = 4.0 (2 / 50 * 100)</li> <li>If the advance is 1 mm when the conveyer speed is 50 mm/s: Setting value = -2.0 (-1 / 50 * 100)</li> </ul>	0.00, 0.00, 0.00, 0.00, 0.00, 0.00, 0.00, 0.00
Tracking adjustment coefficient 2	TRADJ2	8 real numbers	Tracking adjustment coefficient 2 Modify the conveyer speed to $V_c + \text{TRADJ2} * (V_c - V_p)$ . $V_c$ = Conveyer speed at the current sampling $V_p$ = Conveyer speed at the previous sampling	0.00, 0.00, 0.00, 0.00, 0.00, 0.00, 0.00, 0.00

## 16.2. Expansion serial interface Connector Pin Assignment

“Figure 16–1 Connector Arrangement” shows the connector arrangement and “Table 16–2 Connectors: CNENC Pin Assignment” shows pin assignment of each connector.



Connector: CNENC

**Figure 16–1 Connector Arrangement**

**Table 16–2 Connectors: CNENC Pin Assignment**


Pin NO.	Signal name	Explanation	Input/output	Remark
1A	SG	Control power supply 0 V	GND	
2A	LAH1	+ terminal of differential encoder A-phase signal	Input	CH1
3A	LBH1	+ terminal of differential encoder B-phase signal	Input	
4A	LZH1	+ terminal of differential encoder Z-phase signal	Input	
5A	SG	Control power supply 0 V	GND	
6A	LAH2	+ terminal of differential encoder A-phase signal	Input	CH2
7A	LBH2	+ terminal of differential encoder B-phase signal	Input	
8A	LAH2	+ terminal of differential encoder Z-phase signal	Input	
9A	-	Empty	–	
10A	-	Empty	–	
1B	SG	Control power supply 0 V	GND	
2B	LAL1	- terminal of differential encoder A-phase signal	Input	CH1
3B	LBL1	- terminal of differential encoder B-phase signal	Input	
4B	LZL1	- terminal of differential encoder Z-phase signal	Input	
5B	SG	Control power supply 0 V	GND	
6B	LAL2	- terminal of differential encoder A-phase signal	Input	CH2
7B	LBL2	- terminal of differential encoder B-phase signal	Input	
8B	LZL2	- terminal of differential encoder Z-phase signal	Input	
9B	-	Empty	–	
10B	-	Empty	–	

16.3. Chart of sample program


The chart of the sample program is shown below.

16.3.1. Conveyer tracking




(1) A.prg




## (2) C.prg




## (3) CM1.prg




## (4) 1.prg










### 16.3.2. Vision Tracking


#### (1) A.prg

The same program as the conveyer tracking.


#### (2) B.prg




## (3) C.prg



## (4) CM1.prg





## (5) 1.prg

The same program as the conveyer tracking.

## 16.4. Sample Programs

### 16.4.1. Conveyor Tracking

#### (1) A.Prg

```
1 '### Ver.A2 #####
2 '# Program for calibration between tracking robot and conveyer
3 '# Program type : A.prg
4 '# Date of creation/version : 2006.04.21 A1a
5 '# COPYRIGHT : MITSUBISHI ELECTRIC CORPORATION.
6 '#####
7 '(1) Register an encoder number to the X coordinate of the "PE" variable/
8 'Check the setting value
9   MECMAX=8                                'The maximum encoder number value (for checking)
10  If PE.X<1 Or PE.X>MECMAX Then Error 9101 'Encoder number out of range
11  MENCNO=PE.X                              'Acquire the encoder number
12 '(2) Attach a marking sticker on the conveyer upstream side/
13 '(3) Move the robot to the position right at the center of the attached sticker/
14  MX10EC1#=M_Enc(MENCNO)                   'Acquire encoder data (first time)
15  PX10PS1=P_Zero                           'Set all elements to ZERO
16  PX10PS1=P_Fbc(1)                         'Acquire the current position (first time)
17 '(4) Raise the robot/
18 '(5) Move the sticker in the forward direction of the conveyer/
19 '(6) Move the robot to the position right at the center of the moved sticker/
20  MX10EC2#=M_Enc(MENCNO)                   'Acquire encoder data (second time)
21  PX10PS2=P_Zero                           'Set all elements to ZERO
22  PX10PS2=P_Fbc(1)                         'Acquire the current position (second time)
23 '(7) Raise the robot/
24 '(8) Perform step operation until End/
25  GoSub *S10ENC                             'P_EncDlt calculation processing
26  P_EncDlt(MENCNO)=PY10ENC                 'Store data in P_EncDlt
27 End
28 '
29 '##### Processing for obtaining P_EncDlt #####
30  'MX10EC1: Encoder data 1
31  'MX10EC2: Encoder data 2
32  'PX10PS1: Position 1
33  'PX10PS2: Position 2
34  'PY10ENC: P_EncDlt value
35 *S10ENC
36  M10ED#=MX10EC2#-MX10EC1#
37  If M10ED#>8000000000.0 Then M10ED#=M10ED#-10000000000.0
38  If M10ED#<-8000000000.0 Then M10ED#=M10ED#+10000000000.0
39  PY10ENC.X=(PX10PS2.X-PX10PS1.X)/M10ED#
40  PY10ENC.Y=(PX10PS2.Y-PX10PS1.Y)/M10ED#
41  PY10ENC.Z=(PX10PS2.Z-PX10PS1.Z)/M10ED#
42  PY10ENC.A=(PX10PS2.A-PX10PS1.A)/M10ED#
43  PY10ENC.B=(PX10PS2.B-PX10PS1.B)/M10ED#
44  PY10ENC.C=(PX10PS2.C-PX10PS1.C)/M10ED#
45  PY10ENC.L1=(PX10PS2.L1-PX10PS1.L1)/M10ED#
46  PY10ENC.L2=(PX10PS2.L2-PX10PS1.L2)/M10ED#
47 Return
48 '
49 'This program "computes how much a robot moves per 1 pulse and stores the result in P_EncDlt."
PE=(1.000,0.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
```

```
PX10PS1=(0.000,0.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PX10PS2=(0.000,0.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PY10ENC=(0.000,0.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
```

## (2) C.Prg

```
1 '### Ver.A2 #####
2 '# Conveyer tracking, workpiece suction position registration program
3 '# Program type : C.prg
4 '# Date of creation/version : 2006.04.21 A1a
5 '# COPYRIGHT : MITSUBISHI ELECTRIC CORPORATION.
6 '#####
7 '(1) Register a model number in the X coordinate of the "PRM1" variable/
8 '(2) Register an encoder number in the Y coordinate of the "PRM1" variable/
9 '(3) Register the number of the sensor that monitors workpieces in the Z coordinate of the "PRM1" variable /
10 'Check the conditions set in the "PRM1" variable
11   MWKMAX=10                                'The maximum model number value (for checking)
12   MECMAX=8                                'The maximum encoder number value (for checking)
13   MWKNO=PRM1.X                            'Acquire a model number
14   MENCNO=PRM1.Y                            'Acquire an encoder number
15   If MWKNO<1 Or MWKNO>MWKMAX Then Error 9102 'Model number out of range
16   If MENCNO<1 Or MENCNO>MECMAX Then Error 9101 'Encoder number out of range
17   For M1=1 TO 10                          'Clear the information
18     P_100(M1)=P_Zero                       'A variable that stores workpiece positions
19     P_102(M1)=P_Zero                       'A variable that stores operation conditions
20     M_101#(M1)=0                          'A variable that stores encoder value differences
21   Next M1
22 '(4) Move a workpiece to the position where the photoelectric sensor is activated/
23   ME1#=M_Enc(MENCNO)                      'Acquire encoder data (first time)
24 '(5) Move a workpiece on the conveyer into the robot operation area/
25 '(6) Move the robot to the suction position/
26   ME2#=M_Enc(MENCNO)                      'Acquire encoder data (second time)
27   P_100(MWKNO)=P_Fbc(1)                   'Acquire the workpiece suction position (current position)
28 '(7) Perform step operation until End/
29   MED#=ME2#-ME1#                          'Calculate the difference of the encoder value.
30   If MED# > 800000000.0 Then MED# = MED#-1000000000.0
31   If MED# < -800000000.0 Then MED# = MED#+1000000000.0
32 '
33   M_101#(MWKNO)=MED#                      'Store the amount of encoder movement in a global variable
34   P_102(MWKNO).X=PRM1.Y                   'Store encoder numbers in a global variable
35   P_102(MWKNO).Y=PRM1.Z                   'Store the sensor number in a global variable
36 End
37 '
38 'This program is "the relation between the position at which the sensor is reacted and the position at which
39 'the robot absorbs workpieces.
```



**(3) 1.Prg**

```
1 '### Ver.A2 #####
2 '# Conveyer tracking, robot operation program
3 '# Program type : 1.prg
4 '# Date of creation/version : 2006.04.21 A1a
5 '# : 2008.11.14 A2a
6 '# MITSUBISHI ELECTRIC CORPORATION.
7 '#####
8 '
9 '### Main processing ###
10 *S00MAIN
11   GoSub *S90HOME           'Origin return processing
12   GoSub *S10INIT          'Initialization processing
13 *LOOP
14   GoSub *S20TRGET         'Tracked workpiece takeout processing
15   GoSub *S30WKPUT         'Workpiece placing processing
16   GoTo *LOOP
17 End
18 '
19 '### Initialization processing ###
20 *S10INIT
21 '/// Speed related ///
22   Accel 100,100           'Acceleration/deceleration setting
23   OvrD 100                'Speed setting
24   LOADSET 1,1             'Optimal acceleration/deceleration specification
25   Oadl On                 'Turning optimal acceleration/deceleration ON
26   Cnt 0
27   Clr 1
28   HOpen 1
29 '/// Initial value setting ///
30   TrClr 1                 'Clear tracking buffer 1
31   MWAIT1=0                'Clear workpiece wait flag 1
32 '/// Multitask startup ///
33   M_09#=PWK.X             'Model number specification
34   If M_Run(2)=0 Then      'Confirmation of conveyer 1 multitasking
35     XRun 2,"CM1",1        'Multitasking setting
36     Wait M_RUN(2)=1
37   EndIf
38   Priority PRI.X,1
39   Priority PRI.Y,2
40 Return
41 '
42 '### Tracked workpiece takeout processing ###
43 *S20TRGET
44 '/// Tracking buffer check ///
45 *LBFCHK
46   If M_Trbfct(1)>=1 Then GoTo *LREAD 'If a workpiece exists
47   Mov P1 Type 0,0          'Move to the pull-off location
48   MWAIT1=0
49   GoTo *LBFCHK
50 '/// Workpiece data acquisition ///
51 *LREAD
52   TrRd PBPOS,MBENC#,MBWK%,1,MBENCNO% 'Read data from the tracking buffer
53   GoSub *S40DTSET          'Transportation data setting
54 '/// Workpiece position confirmation ///
55 *LNEXT
56   PX50CUR=TrWcur(MBENCNO%,PBPOS,MBENC#) 'Acquire the current workpiece position
57   MX50ST=PRNG.X            'Start distance of the range where the robot can follow a workpiece
58   MX50ED=PRNG.Y            'End distance of the range where the robot can follow a workpiece
59   MX50PAT=PTN.X            'Conveyer position pattern number
60   GoSub *S50WKPOS          'Workpiece position confirmation processing
61   If MY50STS=3 Then GoTo *LBFCHK 'Already passed. Go to the next workpiece
62   If MY50STS=2 Then GoTo *LTRST 'Operable: start tracking
```

```

63   If MWAIT=1 Then GoTo *LNEXT           'Wait for incoming workpieces
64   '/// To standby position ///
65   PWAIT=P1                             'Change to workpiece wait posture
66   Select PTN.X                         'Conveyer position pattern number
67   Case 1 TO 2                          'When the conveyer is the front of the robot
68       PWAIT.X=PX50CUR.X                'X coordinates of the robot are matched to workpiece.
69   Case 3 TO 6
70       PWAIT.Y=PX50CUR.Y                'Y coordinates of the robot are matched to workpiece.
71   End Select
72   PWAIT.Z=PX50CUR.Z+PUP1.X
73   PWAIT.C=PX50CUR.C
74   Mov PWAIT Type 0,0                   'Move to workpiece wait posture PWAIT
75   MWAIT1=1                             'Set workpiece wait flag
76   GoTo *LNEXT
77   '/// Start tracking operation ///
78   *LTRST
79   Accel PAC1.X,PAC1.Y
80   Cnt 1,0,0
81   Act 1=1                             'Monitor the robot following workpieces too far
82   Trk On,PBPOS,MBENC#,PTBASE,MBENCNO% 'Tracking operation start setting
83   Mov PGT,PUP1.Y Type 0,0              'Move to tracking midair position
84   Accel PAC2.X,PAC2.Y
85   Mvs PGT                             'Move to a suction position
86   HClose 1                             'Turn suction ON
87   Dly PDLY1.X                          'adsorbion confirmation(s)
88   Cnt 1
89   Accel PAC3.X,PAC3.Y
90   Mvs PGT,PUP1.Z                       'Move to tracking midair position
91   Trk Off                              'Tracking operation end setting
92   Act 1=0
93   Accel 100,100
94   MWAIT = 0
95   Return
96   '
97   '### Workpiece placing processing ###
98   *S30WKPUT
99   Accel PAC11.X,PAC11.Y
100  Mov PPT,PUP2.Y                       'Move to over the placement position
101  Accel PAC12.X,PAC12.Y
102  Cnt 1,0,0
103  Mvs PPT                             'Move to the placement position
104  HOpen 1                             'Turn suction OFF
105  Dly PDLY2.X                          'Release confirmation(s)
106  Cnt 1
107  Accel PAC13.X,PAC13.Y
108  Mvs PPT,PUP2.Z                       'Move to over the placement position
109  Accel 100,100
110  Return
111  '
112  '### Transportation data setting processing ###
113  *S40DTSET
114  PTBASE=P_100(PWK.X)                  'Create reference position
115  TrBase PTBASE,MBENCNO%               'Tracking base setting
116  PGT=PTBASE*POFSET                    'Suction position setting
117  GoSub *S46ACSET                       'Interrupt definition
118  Return
119  '
120  '### Interrupt definition processing 1 ###
121  *S46ACSET
122  Select PTN.X                         'Conveyer position pattern number
123  Case 1 'Front right -> left
124      MSTP1=PRNG.Z                     'Following stop distance
125      Def Act 1,P_Fbc(1).Y>MSTP1 GoTo *S91STOP,S 'To *S91STOP if followed far long
126      Break
127  Case 2 'Front left -> right

```

```
128   MSTP1=-PRNG.Z
129   Def Act 1,P_Fbc(1).Y<MSTP1 GoTo *S91STOP,S
130   Break
131   Case 3 'Left side rear -> front
132   Case 5 'Right side rear -> front
133     MSTP1=PRNG.Z
134     Def Act 1,P_Fbc(1).X>MSTP1 GoTo *S91STOP,S
135     Break
136   Case 4 'Left side front -> rear
137   Case 6 'Right side front -> rear
138     MSTP1=-PRNG.Z
139     Def Act 1,P_Fbc(1).X<MSTP1 GoTo *S91STOP,S
140     Break
141   End Select
142 Return
143 '
144 #### Workpiece position confirmation processing ####
145   'PX50CUR:Current workpiece position
146   'MX50ST:Tracking start range
147   'MX50ED:Tracking end range
148   'MX50PAT:Conveyer position pattern number
149   'MY50STS:Result (1: Wait/2: Start tracking/3: Next workpiece)
150 *S50WKPOS
151   MY50STS=0                                'Clear return value
152   Select MX50PAT                            'Conveyer pattern
153   Case 1 'Front right -> left
154     M50STT=-MX50ST                          'The start side has a negative value
155     M50END=MX50ED
156     If Poscq(PX50CUR)=1 And PX50CUR.Y>=M50STT And PX50CUR.Y<=M50END Then
157       MY50STS=2                              'Tracking possible
158     Else 'If tracking not possible
159       If PX50CUR.Y<0 Then MY50STS=1           'Wait
160       If PX50CUR.Y>M50END Then MY50STS=3      'Move onto the next workpiece
161       If Poscq(PX50CUR)=0 And PX50CUR.Y>=M50STT And PX50CUR.Y<=M50END Then
MY50STS=3 'Outside the movement range
162     EndIf
163     Break
164   Case 2 'Front left -> right
165     M50STT=MX50ST
166     M50END=-MX50ED                          'The end side has a negative value
167     If Poscq(PX50CUR)=1 And PX50CUR.Y<=M50STT And PX50CUR.Y>=M50END Then
168       MY50STS=2                              'Tracking possible
169     Else 'If tracking not possible
170       If PX50CUR.Y>0 Then MY50STS=1           'Wait
171       If PX50CUR.Y<0 Then MY50STS=3           'Move onto the next workpiece
172       If Poscq(PX50CUR)=0 And PX50CUR.Y<=M50STT And PX50CUR.Y>=M50END Then
MY50STS=3 'Outside the movement range
173     EndIf
174     Break
175   Case 3 'Left side rear -> front
176   Case 5 'Right side rear -> front
177     M50STT=-MX50ST                          'The start side has a negative value
178     M50END=MX50ED
179     If Poscq(PX50CUR)=1 And PX50CUR.X>=M50STT And PX50CUR.X<=M50END Then
180       MY50STS=2                              'Tracking possible
181     Else 'If tracking not possible
182       If PX50CUR.X<0 Then MY50STS=1           'Wait
183       If PX50CUR.X>0 Then MY50STS=3           'Move onto the next workpiece
184       If Poscq(PX50CUR)=0 And PX50CUR.X>=M50STT And PX50CUR.X<=M50END Then
MY50STS=3 'Outside the movement range
185     EndIf
186     Break
187   Case 4 'Left side front -> rear
188   Case 6 'Right side front -> rear
189     M50STT=MX50ST
```

```

190     M50END=-MX50ED                                'The end side has a negative value
191     If Poscq(PX50CUR)=1 And PX50CUR.X<=M50STT And PX50CUR.X>=M50END Then
192         MY50STS=2                                    'Tracking possible
193     Else 'If tracking not possible
194         If PX50CUR.X>0 Then MY50STS=1                'Wait
195         If PX50CUR.X<0 Then MY50STS=3                'Move onto the next workpiece
196         If Poscq(PX50CUR)=0 And PX50CUR.X<=M50STT And PX50CUR.X>=M50END Then
MY50STS=3 'Outside the movement range
197     EndIf
198     Break
199 End Select
200 If MY50STS=0 Then Error 9199                        'Program modification required
201 Return
202 '
203 '### Origin return processing ###
204 *S90HOME
205     Servo On                                          'Servo ON
206     P90CURR=P_Fbc(1)                                'Acquire the current position
207     If P90CURR.Z<P1.Z Then                          'If the current height is below the origin
208         OvrD 10
209         P90ESC=P90CURR                              'Create an escape position
210         P90ESC.Z=P1.Z
211         Mvs P90ESC                                  'Move to the escape position
212         OvrD 100
213     EndIf
214     Mov P1                                           'Move to the origin
215 Return
216 '
217 '### Tracking interruption processing ###
218 *S91STOP
219     Act 1=0
220     Trk Off
221     HOpen 1                                          'Release suction
222     P91P=P_Fbc(1)                                  'Acquire the current position
223     P91P.Z=P1.Z
224     Mvs P91P Type 0,0                              'Raise
225     Mov P1                                           'Return to the origin once
226     GoTo *LBFCHK
227 '
P1=(0.000,0.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PAC1=(100.000,100.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PAC11=(100.000,100.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PAC12=(100.000,100.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PAC13=(100.000,100.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PAC2=(100.000,100.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PAC3=(100.000,100.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PDLY1=(1.000,0.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PDLY2=(1.000,0.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
POFSET=(0.000,0.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PPT=(0.000,0.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PRI=(1.000,1.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PRNG=(300.000,200.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PTN=(1.000,0.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PUP1=(50.000,-50.000,-70.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PUP2=(0.000,-50.000,-50.000,0.000,0.000,0.000,0.000,0.000)(0,0)
PWK=(1.000,0.000,0.000,0.000,0.000,0.000,0.000,0.000)(0,0)

```

**(4) CM1.Prg**

```
1 '### Ver.A2 #####
2 '# Conveyer tracking, sensor monitoring program
3 '# Program type : CM1.prg
4 '# Date of creation/version : 2006.04.21 A1a
5 '# COPYRIGHT : MITSUBISHI ELECTRIC CORPORATION.
6 '#####
7 '
8 '##### Main processing #####
9 *S00MAIN
10  GoSub *S10DTGET          'Processing for acquiring required data
11 *LOOP
12  GoSub *S20WRITE          'Workpiece position writing processing
13  GoTo *LOOP
14 End
15 '##### Data acquisition processing #####
16 *S10DTGET
17 'Acquire the suction position, amount of encoder movement and encoder number set with program C
18  MWKNO=M_09#              'Acquire model number
19  M10ED#=M_101#(MWKNO)     'Amount of encoder movement
20  MENCNO=P_102(MWKNO).X     'Encoder number
21  MSNS=P_102(MWKNO).Y      'Sensor number
22 'Calculate the workpiece position (X,Y) when the sensor is activated
23  PWPOS=P_100(MWKNO)-P_EncDlt(MENCNO)*M10ED#
24 Return
25 '##### Position data writing processing #####
26 *S20WRITE
27  If M_In(MSNS)=0 Then GoTo *S20WRITE 'Wait for a workpiece to activate the photoelectric sensor
28  MENC#=M_Enc(MENCNO)       'Encoder number
29  TrWrt PWPOS,MENC#,MWKNO,1,MENCNO   'Write data (workpiece position and encoder value) to the
tracking buffer
30 *L20WAIT
31  If M_In(MSNS)=1 Then GoTo *L20WAIT
32 Return
```

## 16.4.2. Vision Tracking

### (1) A.Prg

The same program as the conveyer tracking.

### (2) B.Prg

```

1 '### Ver. A2 #####
2 '# Network vision tracking, calibration between robot and vision sensor
3 '# Program type      : B.prg
4 '# Date of creation  : 2006.04.21 A1a
5 '# COPYRIGHT : MITSUBISHI ELECTRIC CORPORATION.
6 '#####
7 '(1) Register an encoder number to the X coordinate of the "PE" variable/
8 'Check the setting value
9   MECMAX=8                                'The maximum encoder number value (for checking)
10  If PE.X<1 Or PE.X>MECMAX Then Error 9101'Encoder number out of range
11  MENCNO=PE.X                              'Acquire the encoder number
12 '(2) Attach 4 stickers within the vision sensor recognition area/
13 '(3) Check that the sticker positions are correct by looking at vision images/
14 '(4) Make setting for 4 points in the calibration setting screen of MELFA-Vision/
15  ME1#=M_Enc(MENCNO)                      'Acquire encoder data (first time)
16 '(5) Move the stickers forward until they are within the robot operation area/
17 '(6) Move the robot hand to the position right at the center of sticker 1/
18 '(7) Acquire the robot position for the first point with MELFA-Vision/
19 '(8) Move the robot hand to the position right at the center of sticker 2/
20 '(9) Acquire the robot position for the second point with MELFA-Vision/
21 '(10) Move the robot hand to the position right at the center of sticker 3/
22 '(11) Acquire the robot position for the third point with MELFA-Vision/
23 '(12) Move the robot hand to the position right at the center of sticker 4/
24 '(13) Acquire the robot position for the fourth point with MELFA-Vision/
25 '(14) Raise the robot arm/
26  ME2#=M_Enc(MENCNO)                      'Acquire encoder data (second time)
27  MED#=ME1#-ME2#                          'Calculate the difference of the encoder value.
28  If MED# > 800000000.0 Then MED# = MED#-1000000000.0
29  If MED# < -800000000.0 Then MED# = MED#+1000000000.0
30  M_100#(MENCNO)=MED#
31 '(15) Enter a comment describing the calibration data and store it using MELFA-Vision/
32 End
PE=(1.000,0.000,0.000,0.000,0.000,0.000)

```

**(3) C.Prg**

```

1 '### Ver.A2 #####
2 '# Network vision tracking, workpiece suction position registration program
3 '# Program type           : C.prg
4 '# Date of creation/version : 2006.04.21 A1a
5 '# COPYRIGHT : MITSUBISHI ELECTRIC CORPORATION.
6 '#####
7 '(1) Store a model number in the X coordinate of the "PRM1" variable/
8 '(2) Store an encoder number in the Y coordinate of the "PRM1" variable/
9 '(3) Check live images and register the length in the movement direction to the X coordinate of the "PRM2"
variable/
10 '(4) Store the workpiece length in the Y coordinate of the "PRM2" variable/
11 '(5) Enter the COM port number to be opened for communication after "CCOM$=" in the following line/
12   CCOM$="COM2:"      'Set the number of the port to be opened
13 '(6) Enter the vision program name after "CPRG$=" in the following line/
14   CPRG$="TRK.JOB"    'Set the vision program name
15 '(7) Enter the cell in which the recognized quantity is stored after "CKOSU$=" in the following line/
16   CKOSU$="E76"       'Set the cell in which the recognized quantity is stored
17 '(8) Enter the start of the area where recognition results are stored after "CSTT$=" in the following line/
18   CSTT$="J81"        'Set the start cell where recognition result data is stored
19 '(9) Enter the end cell of the area where recognition results are stored after "CEND$=" in the following line/
20   CEND$="L81"        'Set the end cell where recognition result data is stored
21 '(10) Place workpieces to be tracked in locations recognizable by the vision sensor/
22 '(11) Place the vision sensor in the "online" status/
23 '(12) Press [MENU] of T/B to automatically run program C. When the program stops, open it with T/B/
24   MWKNO=PRM1.X       'Acquire the model number
25   MENCNO=PRM1.Y       'Acquire the encoder number
26 'Establish a communication line with the vision sensor via the opened port
27   NvClose             'Close communication line
28   NvOpen CCOM$ AS #1  'Open communication line and log on
29   Wait M_NvOpen(1)=1 'Wait to log on to the vision sensor
30   NVPST #1,CPRG$,CKOSU$,CSTT$,CEND$,0 'Acquire data of one recognized workpiece
31   P_101(MWKNO)=P_NvS1(1) 'Acquire data of the first recognized workpiece
32   ME1#=M_Enc(MENCNO)   'Acquire encoder data 1
33   NvClose #1
34 Hlt
35 '(13) Move a workpiece on the conveyer until it gets within the robot operation area/
36 '(14) Move the robot to the suction position/
37   ME2#=M_Enc(MENCNO)   'Acquire encoder data 2
38   P_100(MWKNO)=P_Fbc(1) 'Acquire position 1
39 '(15) Perform step operation until End/
40   MED#=ME2#-ME1#       'Calculate the amount of encoder movement
41   If MED# > 800000000.0 Then MED# = MED#-1000000000.0
42   If MED# < -800000000.0 Then MED# = MED#+1000000000.0
43   M_101#(MWKNO)=MED#    'Amount of encoder movement
44   P_102(MWKNO)=PRM1      'Encoder number
45   P_103(MWKNO)=PRM2      'Image size and workpiece size
46   C_100$(MWKNO)=CCOM$    'COM port number
47   C_101$(MWKNO)=CPRG$    'Vision program name
48   C_102$(MWKNO)=CKOSU$   'Recognized quantity cell
49   C_103$(MWKNO)=CSTT$    'Start cell
50   C_104$(MWKNO)=CEND$    'End cell
51 End
52 '
53 'This program is "the relation between the workpiece position recognized by the network vision sensor and
54 ' the position at which the robot suctions workpieces.
PRM1=(1.000,1.000,0.000,0.000,0.000,0.000)
PRM2=(170.000,30.000,0.000,0.000,0.000,0.000)

```

**(4) 1.Prg**

The same program as the conveyer tracking.

**(5) CM1.Prg**

```

1 '### Ver.A2 #####
2 '# Conveyer tracking, communication processing between robot and vision sensor
3 '# Program type      : CM1.prg
4 '# Date of creation/version : 2006.04.21 A1a
5 '# COPYRIGHT : MITSUBISHI ELECTRIC CORPORATION.
6 '#####
7   Dim MX(4),MY(4),MT(4)      'X/Y/C/correlation value/model/buffer
8   ""Dim MTR(8)              'Encoder value
9 '
10 '##### Main processing #####
11 *S00MAIN
12   GoSub *S10DTGET           'Data acquisition processing
13   GoSub *S20VSINI           'VS initialization processing
14   GoSub *S30CONST           'Condition setting
15 '
16   MEP# = M_Enc(MENCNO)+MEI#+100
17   GoSub *S70VOPEN           'Vision sensor line open + vision program load processing
18 *L00_00
19   GoSub *S40CHKS            'VS recognition check processing
20   GoTo *L00_00
21 End
22 '
23 '##### Data acquisition processing #####
24 *S10DTGET
25   MWKNO=M_09#              'Model number
26   MENCNO=P_102(MWKNO).Y    'Encoder number
27   MvsL=P_103(MWKNO).X      'VS screen size longitudinal distance
28   MWKL=P_103(MWKNO).Y      'Workpiece size longitudinal distance
29 '
30   PTEACH=P_100(MWKNO)      'Position taught to the robot
31   PVSWRK=P_101(MWKNO)      'Position recognized by VS
32   CCOM$=C_100$(MWKNO)      'COM port number
33   CPRG$=C_101$(MWKNO)      'Vision program name
34   CKOSU$=C_102$(MWKNO)     'Recognized quantity cell
35   CSTT$=C_103$(MWKNO)      'Start cell
36   CEND$=C_104$(MWKNO)      'End cell
37 Return
38 '
39 '##### Opening communication line #####
40 *S70VOPEN
41   NvClose                   'Close communication line
42   NvOpen CCOM$ AS #1        'Open communication line and log on
43   Wait M_NvOpen(1)=1        'Wait for line connection
44   NvLoad #1,CPRG$           'Load the vision program
45 Return
46 '
47 '##### VS initialization processing #####
48 *S20VSINI
49 'Move from the robot coordinate axis to the robot origin when the vision sensor recognizes workpieces
50   MED1#=M_100$(MENCNO)      'Amount of conveyer movement at calibration between vision sensor and
robot
51   PRBORG=P_EncDlt(MENCNO)*MED1# 'Robot origin when the vision sensor recognizes workpieces
52 'Return a workpiece recognized by the vision sensor to the position taught to the robot
53   MED2#=M_101$(MWKNO)      'Amount of conveyer movement from vision sensor recognition to
workpiece teaching
54   PBACK=P_EncDlt(MENCNO)*MED2#
55 'Calculate the position of the workpiece that the vision sensor in the robot area recognized.

```



```

56  PWKPOS=PRBORG+PVSWRK+PBACK      'Workpiece position recognized by the vision sensor into the
robot area
57  PVTR=(P_Zero/PWKPOS)*PTEACH      'Vectors specifying the center of gravity of the vision sensor
and grabbing position
58  If PVTR.X<-PCHK.X Or PVTR.X>PCHK.X Then Error 9110 'The calculation result is greatly different from
the theory value.
59  If PVTR.Y<-PCHK.Y Or PVTR.Y>PCHK.Y Then Error 9110
60 Return
61 '
62 ##### Condition setting #####
63 *S30CONST
64  MDX = P_EncDIt(MENCNO).X          'Amount of movement per pulse (X)
65  MDY = P_EncDIt(MENCNO).Y          'Amount of movement per pulse (Y)
66  MDZ = P_EncDIt(MENCNO).Z          'Amount of movement per pulse (Z)
67  MD = Sqr(MDX^2+MDY^2+MDZ^2)       'Calculation of the amount of movement per pulse
68  MEI# = Abs((MVSL-MWKL)/MD)         'Calculation of imaging start setting value
69 Return
70 '
71 ##### VS recognition check processing #####
72 *S40CHKS
73 *LVSCMD
74 *LWAIT
75  MEC# = M_Enc(MENCNO)
76  MEM# = MEC# - MEP#                'Subtract the previous encoder pulse value from the current position of the
encoder
77  If MEM# > 800000000.0 Then MEM# = MEM# - 1000000000.0
78  If MEM# < -800000000.0 Then MEM# = MEM# + 1000000000.0
79  If Abs(MEM#) > MEI# GoTo *LVSTRG   'Comparison between the amount of encoder movement and the
camera startup setting value
80  Dly 0.01
81  GoTo *LWAIT
82 *LVSTRG
83  MEP# = MEC#                       'Set the encoder pulse current position to the previous value
84  NvTrg #1, 5, MTR1#,MTR2#,MTR3#,MTR4#,MTR5#,MTR6#,MTR7#,MTR8# 'Imaging request +
encoder value acquisition
85 'Acquisition of recognition data
86  If M_NvOpen(1)<>1 Then Error 9100 'Communication error
87  NVIN #1,"",CKOSU$,CSTT$,CEND$,0    'Imaging request
88  MNUM=M_NvNum(1)                    'Acquire the number of workpieces recognized
89  If MNUM=0 Then GoTo *LVSCMD          'If no workpieces are recognized
90  If MNUM>4 Then MNUM=4                'Set the maximum number (4)
91  For M1=1 TO MNUM                    'Repeat for the number of workpieces recognized
92    MX(M1)=P_NvS1(M1).X                'Data acquisition
93    MY(M1)=P_NvS1(M1).Y
94    MT(M1)=P_NvS1(M1).C
95  Next M1
96  GoSub *S60WRDAT                     'Tracking data storage processing
97 Return
98 '
99 ##### Tracking data storage processing #####
100 *S60WRDAT
101  For M1=1 TO MNUM                    'Perform processing for the number of workpieces recognized
102    PSW=P_Zero
103    PSW=PRBORG                         'Virtually move the robot close to the vision sensor
104    PSW.X=PSW.X+MX(M1)                 'Create the grabbing position
105    PSW.Y=PSW.Y+MY(M1)
106    PSW.C=PSW.C+MT(M1)
107    PRW=P_Zero
108    PRW=PSW*PVTR                       'Compensate for the error in the calculation value
109    PRW.FL1=P_100(MWKNO).FL1
110    PRW.FL2=P_100(MWKNO).FL2
111    Select MENCNO
112    Case 1
113      TrWrt PRW, MTR1#, MWKNO,1,MENCNO 'Position, encoder value, model number, buffer number,
encoder number

```

```

1140      Break
1150      Case 2
1160      TrWrt PRW, MTR2#, MWKNO,1,MENCNO 'Position, encoder value, model number, buffer
number, encoder number
1170      Break
1180      Case 3
1190      TrWrt PRW, MTR3#, MWKNO,1,MENCNO 'Position, encoder value, model number, buffer
number, encoder number
1200      Break
1210      Case 4
1220      TrWrt PRW, MTR4#, MWKNO,1,MENCNO 'Position, encoder value, model number, buffer
number, encoder number
1230      Break
1240      Case 5
1250      TrWrt PRW, MTR5#, MWKNO,1,MENCNO 'Position, encoder value, model number, buffer
number, encoder number
1260      Break
1270      Case 6
1280      TrWrt PRW, MTR6#, MWKNO,1,MENCNO 'Position, encoder value, model number, buffer
number, encoder number
1290      Break
1300      Case 7
1310      TrWrt PRW, MTR7#, MWKNO,1,MENCNO 'Position, encoder value, model number, buffer
number, encoder number
1320      Break
1330      Case 8
1340      TrWrt PRW, MTR8#, MWKNO,1,MENCNO 'Position, encoder value, model number, buffer
number, encoder number
1350      Break
1360      End Select
1370      Next M1
1380      Return
PBACK=(-1.369,-702.674,1.957,0.000,0.000,0.000,0.000,0.000)(0,0)
PCHK=(10.000,10.000,0.000,0.000,0.000,0.000,0.000,0.000)
PRBORG=(1.427,732.255,-2.040,0.000,0.000,0.000,0.000,0.000)(0,0)
PRW=(248.142,734.785,43.410,0.000,0.000,-2.783,0.000,0.000)(0,0)
PSW=(249.449,734.948,-2.040,0.000,0.000,0.147,0.000,0.000)(0,0)
PTEACH=(202.341,38.161,45.367,0.000,0.000,-4.612,0.000,0.000)(0,0)
PVSWRK=(203.594,8.701,0.000,0.000,0.000,-1.682,0.000,0.000)(0,0)
PVTR=(-1.307,-0.159,45.450,0.000,0.000,-2.930,0.000,0.000)(0,0)
PWKPOS=(203.652,38.282,-0.082,0.000,0.000,-1.682,0.000,0.000)(0,0)

```





HEAD OFFICE: TOKYO BUILDING, 2-7-3, MARUNOUCHI, CHIYODA-KU, TOKYO 100-8310, JAPAN  
NAGOYA WORKS: 5-1-14, YADA-MINAMI, HIGASHI-KU, NAGOYA 461-8670, JAPAN

Authorised representative:

MITSUBISHI ELECTRIC EUROPE B.V. GERMANY

Gothaer Str. 8, 40880 Ratingen / P.O. Box 1548, 40835 Ratingen, Germany