


# EEUB2 - Homework #3

## - SOLUTIONS -

### PART A (40 pts)

$$1) \omega_{base} = \frac{P}{T_{max}} = \frac{60000}{250} = 240 \text{ rad/sec}$$

$$N_{base} = 2292 \text{ RPM} \quad (5 \text{ pts})$$



(5 pts)

$$3) \text{ For SMPMSM, } T = \frac{3}{2} p_p \lambda_{pm} i_q$$


→ Field is created in D-axis (1 pts)

→ If  $i_q = 0$ , no torque will be produced. (2 pts)

→  $i_d$  is applied in field weakening region. (2 pts)

$$4) T = \frac{3}{2} p_p \cdot \lambda_{pm} i_q \rightarrow \lambda_{pm} = \frac{250}{\frac{3}{2} \cdot 6 \cdot 250} = \frac{1}{9} = 0,11 \text{ Wb.}$$

(5 pts)



→ Because of SVPWM,  $V_{ph} = \frac{V_{dc}}{\sqrt{3}}$

→ Note that  $\omega = \omega_e = 240 \text{ pp} = 1640 \text{ rad/sec}$

$$\Rightarrow \frac{V_{dc}}{\omega_e \cdot \sqrt{3}} = \sqrt{(\lambda_{pm})^2 + (L \cdot i_q)^2}$$


$$L \cdot i_q = 0,1167 \rightarrow L_{max} = 467 \mu H$$

(6 pts)

6)  $T = \frac{P_{max}}{\omega_{max}} = 47,75 \text{ Nm}$

$$T = \frac{3}{2} P_p \lambda_{pm} i_q \rightarrow i_q = 47,75 \text{ A}$$

$$i_d = \sqrt{i_{max}^2 - i_q^2} = \sqrt{250^2 - 47,75^2} = 245,4 \text{ A}$$



$$\frac{V_{dc}}{\sqrt{3} \omega_e} = \sqrt{(\lambda_{pm} - L i_d)^2 + (L \cdot i_q)^2}$$

→ Solve for L, take the positive root  $\Rightarrow L_{min} = 205 \mu H$

(6 pts)

7)  $205 \mu H \leq L \leq 467 \mu H$  (3 pts)

8) Critical parameters for magnetic design (to determine L and I)

→ Amount and grade of magnets

→ Number of turns

→ Orientation of magnets and pop dimensions in the rotor

etc.

(5 pts)

2 of 4

## PART B (30 pts, 5 pts each)

- 1)
  - windings: copper
  - core: eddy & hysteresis
  - magnets: eddy & hysteresis
  - mechanical: friction & windage
- 2) Permittivity and resistance increases with temperature  
 $P_{\text{cu}} \propto I^2 R \rightarrow$  Copper losses increase.
- 3) Refer to the article.
- 4) Eddy and hysteresis, because of continuously changing magnetic field.
- 5) To determine safe operation region, from thermal point of view. To determine appropriate cooling methods.
- 6) If the machine is idle, it still rotates but  $T_e = T_{\text{fric}}$ .  
a)  $T_{\text{load}} = 0$ . Therefore,  $I$  is small. All losses exist but copper losses are small compared to loaded case.

Part C (30 pts, 7.5 pts each)

1) Disadvantages of SL Machines:

- High torque ripple
- High acoustic noise & vibrations
- Low power density
- Unconventional motor drive

2) → High power density

→ High efficiency

→ High motor usage factor

3) Resistivity of copper is lower, it provides higher efficiency.

4) → Reluctance torque

→ Rare earth free or small amount of rare earth magnets are used.

