

# Chapter 20

## SHEET METALWORKING

- Cutting Operations
- Bending Operations
- Drawing
- Other Sheet Metal Forming Operations
- Dies and Presses for Sheet Metal Processes
- Sheet Metal Operations Not Performed on Presses
- Bending of Tube Stock

# Sheet Metalworking Defined

Cutting and forming operations performed on relatively thin sheets of metal

- Thickness of sheet metal = 0.4 mm (1/64 in) to 6 mm (1/4 in)
- Thickness of plate stock > 6 mm
- Operations usually performed as cold working

# Sheet and Plate Metal Products

- Sheet and plate metal parts for consumer and industrial products such as
  - Automobiles and trucks
  - Airplanes
  - Railway cars and locomotives
  - Farm and construction equipment
  - Small and large appliances
  - Office furniture
  - Computers and office equipment

# Advantages of Sheet Metal Parts

- High strength
- Good dimensional accuracy
- Good surface finish
- Relatively low cost
- For large quantities, economical mass production operations are available

# Sheet Metalworking Terminology

1. “Punch-and-die”
  - Tooling to perform cutting, bending, and drawing
2. “Stamping press”
  - Machine tool that performs most sheet metal operations
3. “Stampings”
  - Sheet metal products

# Three Major Categories of Sheet Metal Processes

## 1. Cutting

- Shearing to separate large sheets; or cut part perimeters or make holes in sheets

## 2. Bending

- Straining sheet around a straight axis

## 3. Drawing

- Forming of sheet into convex or concave shapes

# Cutting

Shearing between two sharp cutting edges




Figure 20.1 - Shearing of sheet metal between two cutting edges:

(1) just before the punch contacts work




Figure 20.1 - Shearing of sheet metal between two cutting edges:

(2) punch begins to push into work, causing plastic deformation






Figure 20.1 - Shearing of sheet metal between two cutting edges:

- (3) punch compresses and penetrates into work causing a smooth cut surface




Figure 20.1 - Shearing of sheet metal between two cutting edges:

- (4) fracture is initiated at the opposing cutting edges which separates the sheet

# Shearing, Blanking, and Punching

Three principal operations in pressworking that cut sheet metal:

- Shearing
- Blanking
- Punching

# Shearing

Sheet metal cutting operation along a straight line between two cutting edges

- Typically used to cut large sheets into smaller sections for subsequent operations




Figure 20.3 - Shearing operation:

(a) side view of the shearing operation

(b) front view of power shears equipped with inclined upper cutting blade  
Symbol  $v$  indicates motion



# Blanking and Punching

*Blanking* - sheet metal cutting to separate piece from surrounding stock

- Cut piece is the desired part, called a *blank*



*Punching* - sheet metal cutting similar to blanking except cut piece is scrap, called a *slug*

- Remaining stock is the desired part



Blank (part)

(a)



(b)

Figure 20.4 - (a) Blanking and (b) punching

# Clearance in Sheet Metal Cutting

Distance between the punch and die

- Typical values range between 4% and 8% of stock thickness
  - If too small, fracture lines pass each other, causing double burnishing and larger force
  - If too large, metal is pinched between cutting edges and excessive burr results



# Clearance in Sheet Metal Cutting

- Recommended clearance can be calculated by:

$$c = at$$

where  $c$  = clearance;  $a$  = allowance; and  $t$  = stock thickness

- Allowance  $a$  is determined according to type of metal

# Allowance $a$ for Three Sheet Metal Groups

<u>Metal group</u>	<u><math>a</math></u>
1100S and 5052S aluminum alloys, all tempers	0.045
2024ST and 6061ST aluminum alloys; brass, soft cold rolled steel, soft stainless steel	0.060
Cold rolled steel, half hard; stainless steel, half hard and full hard	0.075

# Punch and Die Sizes for Blanking and Punching

For a round *blank* of diameter  $D_b$ :

Blanking punch diameter =  $D_b - 2c$

Blanking die diameter =  $D_b$

where  $c$  = clearance

For a round *hole* of diameter  $D_h$ :

Hole punch diameter =  $D_h$

Hole die diameter =  $D_h + 2c$

where  $c$  = clearance




Figure 20.6 - Die size determines blank size  $D_b$ ; punch size determines hole size  $D_h$ ;  $c$  = clearance

## Angular Clearance

Purpose: allows slug or blank to drop through die

- Typical values: 0 Straight portion (for resharpening)




Figure 20.7 - Angular clearance

# Cutting Forces

Important for determining press size (tonnage)

$$F = S t L$$

where  $S$  = shear strength of metal;  $t$  = stock thickness, and  $L$  = length of cut edge

## Bending

Straining sheetmetal around a straight axis to take a permanent bend





Figure 20.11 - (a) Bending of sheet metal

Metal on inside of neutral plane is compressed, while metal on outside of neutral plane is stretched



(b)

Figure 20.11 - (b) both compression and tensile elongation of the metal occur in bending



# Types of Sheetmetal Bending

- *V-bending* - performed with a V-shaped die
- *Edge bending* - performed with a wiping die

## V-Bending

- For low production
- Performed on a *press brake*
- V-dies are simple and inexpensive




Figure 20.12 -  
(a) V-bending

## Edge Bending

- For high production
- Pressure pad required
- Dies & Punch




Figure 20.12 - (b) edge bending

# Stretching during Bending

- If bend radius is small relative to stock thickness, metal tends to stretch during bending
- Important to estimate amount of stretching, so that final part length = specified dimension
- Problem: to determine the length of neutral axis of the part before bending

# Bend Allowance Formula

$$BA = 2\pi \frac{A}{360} (R + K_{ba}t)$$

where  $BA$  = bend allowance;  $A$  = bend angle;  
 $R$  = bend radius;  $t$  = stock thickness; and  $K_{ba}$   
is factor to estimate stretching

- If  $R < 2t$ ,  $K_{ba} = 0.33$
- If  $R \geq 2t$ ,  $K_{ba} = 0.50$

# Springback in Bending

*Springback* = increase in included angle of bent part relative to included angle of forming tool after tool is removed

- Reason for springback:
  - When bending pressure is removed, elastic energy remains in bent part, causing it to recover partially toward its original shape




Figure 20.13 - Springback in bending shows itself as a decrease in bend angle and an increase in bend radius: (1) during bending, the work is forced to take the radius  $R_b$  and included angle  $A'_b$  of the bending tool (punch in V-bending), (2) after punch is removed, the work springs back to radius  $R$  and angle  $A'$

# Bending Force

Maximum bending force estimated as follows:

$$F = \frac{K_{bf} TSwt^2}{D}$$

where  $F$  = bending force;  $TS$  = tensile strength of sheet metal;  $w$  = part width in direction of bend axis; and  $t$  = stock thickness. For V- bending,  $K_{bf} = 1.33$ ; for edge bending,  $K_{bf} = 0.33$






Figure 20.14 - Die opening dimension  $D$ : (a) V-die, (b) wiping die


# Drawing

Sheet metal forming to make cup-shaped, box-shaped, or other complex-curved, hollow-shaped parts


- Sheet metal blank is positioned over die cavity and then punch pushes metal into opening
- Products: beverage cans, ammunition shells, automobile body panels

Figure 20.19 -

- (a) Drawing of a cup-shaped part:
- (1) start of operation before punch contacts work
  - (2) near end of stroke



- (b) Corresponding workpart:
- (1) starting blank
  - (2) drawn part



# Clearance in Drawing

- Sides of punch and die separated by a clearance  $c$  given by:

$$c = 1.1 t$$

where  $t$  = stock thickness

- In other words, clearance = about 10% greater than stock thickness

# Drawing Ratio $DR$

Most easily defined for cylindrical shape:

$$DR = \frac{D_b}{D_p}$$

where  $D_b$  = blank diameter; and  $D_p$  = punch diameter

- Indicates severity of a given drawing operation
  - Upper limit = 2.0

# Reduction $r$

- Again, defined for cylindrical shape:

$$r = \frac{D_b - D_p}{D_b}$$

- Value of  $r$  should be less than 0.50

# Thickness-to-Diameter Ratio

Thickness of starting blank divided by blank diameter

Thickness-to-diameter ratio =  $t/D_b$

- Desirable for  $t/D_b$  ratio to be greater than 1%
- As  $t/D_b$  decreases, tendency for wrinkling increases

# Blank Size Determination

- For final dimensions of drawn shape to be correct, starting blank diameter  $D_b$  must be right
- Solve for  $D_b$  by setting starting sheet metal blank volume = final product volume
- To facilitate calculation, assume negligible thinning of part wall



# Shapes other than Cylindrical Cups

- Square or rectangular boxes (as in sinks),
  - Stepped cups,
  - Cones,
  - Cups with spherical rather than flat bases,
  - Irregular curved forms (as in automobile body panels)
- 
- Each of these shapes presents its own unique technical problems in drawing

# Other Sheet Metal Forming on Presses

Other sheet metal forming operations performed on conventional presses

- Operations performed with metal tooling
- Operations performed with flexible rubber tooling

## Ironing

- Makes wall thickness of cylindrical cup more uniform

- Examp

tillery shells





Figure 20.25 - Ironing to achieve a more uniform wall thickness in a drawn cup: (1) start of process; (2) during process


Note thinning and elongation of walls

# Embossing

- Used to create indentations in sheet, such as raised (or indented) lettering or stren



(a)



(b)

Figure 20.26 - Embossing: (a) cross-section of punch and die configuration during pressing; (b) finished part with embossed ribs

# Guerin Process




Figure 20.28 - Guerin process: (1) before and (2) after  
Symbols  $v$  and  $F$  indicate motion and applied force respectively

# Advantages of Guerin Process

- Low tooling cost
- Form block can be made of wood, plastic, or other materials that are easy to shape
- Rubber pad can be used with different form blocks
- Process attractive in small quantity production

# Dies for Sheet Metal Processes

Most pressworking operations performed with conventional *punch-and-die* tooling

- Custom-designed for particular part
- The term *stamping die* sometimes used for high production dies




Figure 20.30 - Components of a punch and die for a blanking operation







Figure 20.31 -

- (a) Progressive die;  
 (b) associated strip development






Figure 20.32 - Components of a typical mechanical drive stamping press

# Types of Stamping Press Frame

- *Gap frame* – configuration of the letter C and often referred to as a *C-frame*
- *Straight-sided frame* – box-like construction for higher tonnage





Figure 20.33 - Gap frame  
press for sheet  
metalworking

(photo courtesy of E. W.  
Bliss Company)

Capacity = 1350 kN (150  
tons)

Figure 20.34 -  
Press brake with  
bed width of  
9.15 m (30 ft)  
and capacity of  
11,200 kN (1250  
tons); two  
workers are  
positioning plate  
stock for  
bending  
(photo courtesy of  
Niagara Machine  
& Tool Works)






Figure 20.35 - Several sheet metal parts produced on a turret press, showing variety of hole shapes possible (photo courtesy of Strippet, Inc.)




Figure 20.36 - Computer numerical control turret press  
(photo courtesy of Strippit, Inc.)



Figure 20.37 -  
Straight-sided frame press  
(photo courtesy Greenerd  
Press & Machine  
Company, Inc.)



# Power and Drive Systems

- Hydraulic presses - use a large piston and cylinder to drive the ram
  - Longer ram stroke than mechanical types
  - Suited to deep drawing
  - Slower than mechanical drives
- Mechanical presses – convert rotation of motor to linear motion of ram
  - High forces at bottom of stroke
  - Suited to blanking and punching

# Sheet Metal Operations Not Performed on Presses

- Stretch forming
- Roll bending and forming
- Spinning
- High-energy-rate forming processes.

# Stretch Forming

Sheet metal is stretched and simultaneously bent to achieve shape change




Figure 20.39 - Stretch forming: (1) start of process; (2) form die is pressed into the work with force  $F_{die}$ , causing it to be stretched and bent over the form.  $F$  = stretching force

# Force Required in Stretch Forming

$$F = LtY_f$$

where  $F$  = stretching force;  $L$  = length of sheet in direction perpendicular to stretching;  $t$  = instantaneous stock thickness; and  $Y_f$  = flow stress of work metal

- Die force  $F_{die}$  can be determined by balancing vertical force components

## Roll Bending

Large metal sheets and plates are formed into curved sections using rolls





Figure 20.40 - Roll bending

# Roll Forming

Continuous bending process in which opposing rolls produce long sections of formed shape

Figure 20.41 - Roll forming of a continuous channel section:

- (1) straight rolls
- (2) partial form
- (3) final form



# Spinning

Metal forming process in which an axially symmetric part is gradually shaped over a rotating mandrel using a rounded tool or roller

- Three types:
  1. Conventional spinning
  2. Shear spinning
  3. Tube spinning




Figure 20.42 - Conventional spinning: (1) setup at start of process; (2) during spinning; and (3) completion of process



# High-Energy-Rate Forming (HERF)

Processes to form metals using large amounts of energy over a very short time

- HERF processes include:
  - Explosive forming
  - Electrohydraulic forming
  - Electromagnetic forming

# Explosive Forming

Use of explosive charge to form sheet (or plate) metal into a die cavity

- Explosive charge causes a shock wave whose energy is transmitted to force part into cavity
- Applications: large parts, typical of aerospace industry




Figure 20.45 - Explosive forming:  
(1) setup, (2) explosive is detonated, and  
(3) shock wave forms part and plume escapes water surface

# Electromagnetic Forming

Sheet metal is deformed by mechanical force of an electromagnetic field induced in workpart by an energized coil

- Presently the most widely used HERF process
- Applications: tubular parts




Figure 20.47 - Electromagnetic forming: (1) setup in which coil is inserted into tubular workpart surrounded by die; (2) formed part