

Chapter 5

Control Charts for Attributes

5-1. Introduction

- Data that can be classified into one of several categories or classifications is known as **attribute** data.
- Classifications such as conforming and nonconforming are commonly used in quality control.
- Another example of attributes data is the count of defects.

5-2. Control Charts for Fraction Nonconforming

- **Fraction nonconforming** is the ratio of the number of nonconforming items in a population to the total number of items in that population.
- Control charts for **fraction nonconforming** are based on the **binomial** distribution.

5-2. Control Charts for Fraction Nonconforming

Recall: A quality characteristic follows a **binomial** distribution if:

1. All trials are independent.
2. Each outcome is either a “success” or “failure”.
3. The probability of success on any trial is given as p .
The probability of a failure is $1-p$.
4. The probability of a success is constant.

5-2. Control Charts for Fraction Nonconforming

- The binomial distribution with parameters $n \neq 0$ and $0 < p < 1$, is given by

$$p(x) = \binom{n}{x} p^x (1-p)^{n-x}$$

- The mean and variance of the binomial distribution are

$$\mu = np \qquad \sigma^2 = np(1-p)$$

5-2. Control Charts for Fraction Nonconforming

Development of the Fraction Nonconforming Control Chart

Assume

- n = number of units of product selected at random.
- D = number of nonconforming units from the sample
- p = probability of selecting a nonconforming unit from the sample.
- Then:

$$P(D = x) = \binom{n}{x} p^x (1 - p)^{n-x}$$

5-2. Control Charts for Fraction Nonconforming

Development of the Fraction Nonconforming Control Chart

- The sample fraction nonconforming is given as

$$\hat{p} = \frac{D}{n}$$

where \hat{p} is a random variable with mean and variance

$$\mu = p \quad \sigma^2 = \frac{p(1-p)}{n}$$

5-2. Control Charts for Fraction Nonconforming

Standard Given

- If a standard value of p is given, then the **control limits** for the fraction nonconforming are

$$UCL = p + 3\sqrt{\frac{p(1-p)}{n}}$$

$$CL = p$$

$$LCL = p - 3\sqrt{\frac{p(1-p)}{n}}$$

5-2. Control Charts for Fraction Nonconforming

No Standard Given

- If no standard value of p is given, then the **control limits** for the fraction nonconforming are

$$UCL = \bar{p} + 3\sqrt{\frac{\bar{p}(1 - \bar{p})}{n}}$$

$$CL = \bar{p}$$

$$LCL = \bar{p} - 3\sqrt{\frac{\bar{p}(1 - \bar{p})}{n}}$$

where

$$\bar{p} = \frac{\sum_{i=1}^m D_i}{mn} = \frac{\sum_{i=1}^m \hat{p}_i}{m}$$

5-2. Control Charts for Fraction Nonconforming

Trial Control Limits

- Control limits that are based on a preliminary set of data can often be referred to as **trial control limits**.
- The quality characteristic is plotted against the trial limits, if any points plot out of control, assignable causes should be investigated and points removed.
- With removal of the points, the limits are then recalculated.

5-2. Control Charts for Fraction Nonconforming

Example

- A process that produces bearing housings is investigated. Ten samples of size 100 are selected.

Sample #	1	2	3	4	5	6	7	8	9	10
# Nonconf.	5	2	3	8	4	1	2	6	3	4

- Is this process operating in statistical control?


5-2. Control Charts for Fraction Nonconforming

Example

$n = 100, m = 10$

Sample #	1	2	3	4	5	6	7	8	9	10
# Nonconf.	5	2	3	8	4	1	2	6	3	4
Fraction Nonconf.	0.05	0.02	0.03	0.08	0.04	0.01	0.02	0.06	0.03	0.04

$$\bar{p} = \frac{\sum_{i=1}^m \hat{p}_i}{m} = 0.038$$



5-2. Control Charts for Fraction Nonconforming

Example

Control Limits are:


$$UCL = 0.038 + 3\sqrt{\frac{0.038(1-0.038)}{100}} = 0.095$$

$$CL = 0.038$$

$$LCL = 0.038 - 3\sqrt{\frac{0.038(1-0.038)}{100}} = -0.02 \rightarrow 0$$

5-2. Control Charts for Fraction Nonconforming

Example



5-2. Control Charts for Fraction Nonconforming

Design of the Fraction Nonconforming Control Chart

- The **sample size** can be determined so that a shift of some specified amount, δ can be *detected* with a stated level of probability (50% chance of detection). If δ is the magnitude of a process shift, then n must satisfy:

$$\delta = L \sqrt{\frac{p(1-p)}{n}}$$

Therefore,

$$n = \left(\frac{L}{\delta} \right)^2 p(1-p)$$

5-2. Control Charts for Fraction Nonconforming

Positive Lower Control Limit

- The sample size n , can be chosen so that the lower control limit would be nonzero:

$$\text{LCL} = p - L \sqrt{\frac{p(1-p)}{n}} > 0$$

and

$$n > \frac{(1-p)}{p} L^2$$

5-2. Control Charts for Fraction Nonconforming

Interpretation of Points on the Control Chart for Fraction Nonconforming

- Care must be exercised in interpreting points that plot *below* the lower control limit.
 - They are frequently caused by errors in the inspection process or improperly calibrated test and inspection equipment.
 - They often do not indicate a real improvement in process quality.

5-2. Control Charts for Fraction Nonconforming

The np control chart

- The actual number of nonconforming can also be charted. Let n = sample size, p = proportion of nonconforming. The control limits are:

$$UCL = np + 3\sqrt{np(1-p)}$$

$$CL = np$$

$$LCL = np - 3\sqrt{np(1-p)}$$

(if a standard, p , is not given, use \bar{p})

5-2.2 Variable Sample Size

- In some applications of the control chart for the fraction nonconforming, the sample is a **100% inspection** of the process output over some period of time.
- Since different numbers of units could be produced in each period, the control chart would then have a **variable sample size**.

5-2.2 Variable Sample Size

Control Limits Based on an Average Sample Size

- Control charts based on the **average sample size** results in an **approximate set of control limits**.
- The average sample size is given by

$$\bar{n} = \frac{\sum_{i=1}^m n_i}{m}$$

- The upper and lower control limits are

$$\bar{p} \pm 3\sqrt{\frac{\bar{p}(1-\bar{p})}{\bar{n}}}$$

5-3. Control Charts for Nonconformities (Defects)

- There are many instances where an item will contain **nonconformities** but the item itself is not classified as **nonconforming**.
- It is often important to construct control charts for the **total number of nonconformities** or the **average number of nonconformities** for a given “area of opportunity”. The inspection unit must be the same for each unit.

5-3. Control Charts for Nonconformities (Defects)

Poisson Distribution

- The number of nonconformities in a given area can be modeled by the Poisson distribution. Let **c** be the parameter for a Poisson distribution, then the mean and variance of the Poisson distribution are equal to the value **c**.
- The probability of obtaining **x** nonconformities on a single inspection unit, when the average number of nonconformities is some constant, **c**, is found using:

$$p(x) = \frac{e^{-c} c^x}{x!}$$

5-3.1 Procedures with Constant Sample Size

c-chart

- Standard Given:

$$UCL = c + 3\sqrt{c}$$

$$CL = c$$

$$LCL = c - 3\sqrt{c}$$

- No Standard Given:

$$UCL = \bar{c} + 3\sqrt{\bar{c}}$$

$$CL = \bar{c}$$

$$LCL = \bar{c} - 3\sqrt{\bar{c}}$$

5-3.1 Procedures with Constant Sample Size

Choice of Sample Size: The u Chart

- If we find c total nonconformities in a sample of n inspection units, then the **average number of nonconformities** per inspection unit is $u = c/n$.
- The control limits for the average number of nonconformities is

$$UCL = \bar{u} + 3\sqrt{\frac{\bar{u}}{n}}$$

$$CL = \bar{u}$$

$$LCL = \bar{u} - 3\sqrt{\frac{\bar{u}}{n}}$$

5-3.2 Procedures with Variable Sample Size

Three Approaches for Control Charts with Variable Sample Size

1. Variable Width Control Limits
2. Control Limits Based on Average Sample Size
3. Standardized Control Chart

5-3.2 Procedures with Variable Sample Size

Control Limits Based on an Average Sample Size

- Control charts based on the **average sample size** results in an **approximate set of control limits**.
- The average sample size is given by

$$\bar{n} = \frac{\sum_{i=1}^m n_i}{m}$$

- The upper and lower control limits are

$$\bar{u} \pm 3\sqrt{\frac{\bar{u}}{\bar{n}}}$$

5-3.3 Demerit Systems

- When **several less severe** or minor defects can occur, we may need some system for classifying nonconformities or defects according to severity; or to weigh various types of defects in some reasonable manner.

5-3.3 Demerit Systems

Demerit Schemes

1. Class A Defects - very serious
 2. Class B Defects - serious
 3. Class C Defects - Moderately serious
 4. Class D Defects - Minor
- Let c_{iA} , c_{iB} , c_{iC} , and c_{iD} represent the number of units in each of the four classes.

5-3.3 Demerit Systems

Demerit Schemes

- The following weights are fairly popular in practice:
 - Class A-100, Class B - 50, Class C – 10, Class D - 1

$$d_i = 100c_{iA} + 50c_{iB} + 10c_{iC} + c_{iD}$$

d_i - the number of demerits in an inspection unit

5-3.3 Demerit Systems

Control Chart Development

- Number of demerits per unit:

$$u_i = \frac{D}{n}$$

where n = number of inspection units

$$D = \sum_{i=1}^n d_i$$

5-3.3 Demerit Systems

Control Chart Development

$$UCL = \bar{u} + 3\hat{\sigma}_u$$

$$CL = \bar{u}$$

$$LCL = \bar{u} - 3\hat{\sigma}_u$$

where $\bar{u} = 100\bar{u}_A + 50\bar{u}_B + 10\bar{u}_C + \bar{u}_D$

and

$$\hat{\sigma}_u = \left[\frac{(100)^2 \bar{u}_A + (50)^2 \bar{u}_B + (10)^2 \bar{u}_C + \bar{u}_D}{n} \right]^{1/2}$$