

# Tutorial 8

DC Machines and AC Machines

# Example 1

A 208-V, 10hp, four pole, 60 Hz, Y-connected induction motor has a full-load slip of 5 percent. What is the synchronous speed of this motor?

# Explanation

$$n_{sync} = \frac{120 f_e}{P} = \frac{120(60)}{4} = 1800 \text{ rpm}$$

## Example 2

- A 3-phase induction motor is wound for 4 poles and is supplied from 50 Hz system. Calculate
  - (i) Synchronous speed
  - (ii) Rotor speed when slip is 4%
  - (iii) rotor frequency when motor runs at 600 rpm.

# Explanation

**Solution. (i)**

$$N_s = 120f/P = 120 \times 50/4 = 1500 \text{ rpm}$$

**(ii)** rotor speed,

$$N = N_s(1-s) = 1500(1-0.04) = \mathbf{1440 \text{ rpm}}$$

**(iii)** when rotor speed is 600 rpm, slip is

$$s = (N_s - N)/N_s = (1500 - 600)/1500 = 0.6$$

rotor current frequency,

$$f' = sf = 0.6 \times 50 = \mathbf{30 \text{ Hz}}$$

## Example 3

- A slip ring induction motor runs at 290 rpm at full load, when connected to 50 Hz supply. Determine the number of poles and slip?

# Explanation

- $N = 290$  rpm
- $N_s$  has somewhere near it ,say 300 rpm
- If  $N_s$  is assumed as 300 rpm then

$$300 = 120 \times 50/P$$

Hence  $P = 20$

$$\begin{aligned} S &= (300-290)/300 \\ &= 3.33\% \end{aligned}$$

## Example 4

- A three phase, 50 Hz, 4 pole slip ring induction motor has a star connected rotor. The full load speed of the motor is 1460 rpm. Determine the synchronous speed and percentage slip.



# Explanation

- (i)  $N_s = 120f/p = 120 \times 50 / 4 = 1500 \text{ rpm};$
- (ii)  $\text{slip} = (N_s - N) / N_s = (1500 - 1460) / 1500 = 0.0266$
- Percentage slip = 2.66 %

# Example 5

- A 4 pole, 3 phase induction motor operates from a supply whose frequency is 50 Hz,  
Calculate
- (i) the speed at which magnetic field of stator is running
- (ii) the speed of the rotor when slip is 0.04

# Explanation

**Solution.** (i) Stator field revolves at synchronous speed, given by

$$N_s = 120f/P = 120 \times 50/4 = \mathbf{1500 \text{ r.p.m.}}$$

(ii) rotor (or motor) speed,  $N = N_s(1-s) = 1500(1-0.04) = \mathbf{1440 \text{ r.p.m.}}$

# Example 6

- The stator of 3 phase induction motor has 3 slots per pole per phase. If supply frequency is 50 Hz, then Calculate
- (i) number of stator pole produced and total number of slots on the stator
- (ii) speed of the rotating stator flux

# Explanation

**Solution. (i)**

$$P = 2n = 2 \times 3 = \mathbf{6 \text{ poles}}$$

Total No. of slots

$$= 3 \text{ slots/pole/phase} \times 6 \text{ poles} \times 3 \text{ phases} = \mathbf{54}$$

**(ii)**

$$N_s = 120 f / P = 120 \times 50 / 6 = \mathbf{1000 \text{ r.p.m.}}$$

# MCQ 1

- A 3-phase 440 V, 50 Hz induction motor has 4% slip. The frequency of rotor e.m.f. will be
  - (a) 200 Hz
  - (b) 50 Hz
  - (c) 2 Hz
  - (d) 0.2 Hz

# Answer

- Ans: c

## MCQ 2

- 5 H.P., 50Hz, 3-phase, 440 V, induction motors are available for the following r.p.m. Which motor will be the costliest ?
- (a) 730 r.p.m.
- (b) 960 r.p.m.
- (c) 1440 r.p.m.
- (d) 2880 r.p.m.



# Answer

- (a) 730 r.p.m.

# Armature winding

There are 2 types of winding

## Lap and Wave winding

### Lap winding

▶  $A = P$

- ▶ The armature windings are divided into no. of sections equal to the no of poles

### Wave winding

▶  $A = 2$

- ▶ It is used in low current output and high voltage.
- ▶ 2 brushes

# Example

- A DC motor takes an armature current of 110 Amp. at 480 volts. The armature circuit resistance is 0.2 ohm. The machine has 6-poles and the armature is lap connected with 864 conductors. The flux per pole is 0.05 Wb. Calculate the speed of DC motor.

# Explanation

**Solution.**  $E_b = 480 - 110 \times 0.2 = 458 \text{ V}$ ,  $\Phi = 0.05 \text{ W}$ ,  $Z = 864$

Now, 
$$E_b = \frac{\Phi Z N}{60} \left( \frac{P}{A} \right) \text{ or } 458 = \frac{0.05 \times 864 \times N}{60} \times \left( \frac{6}{6} \right)$$

$\therefore N = 636 \text{ r.p.m.}$

# Example

- A 250 V, 4 pole wave wound dc series motor has 782 conductors on its armature. It has armature and series field resistance of 0.75ohm. The motor takes a current of 40 Amp. Calculate the speed when flux per pole is 25mWb.

# Explanation

**Solution.**

Now,

$\therefore$

$$E_b = \Phi ZN (P/A)$$

$$E_b = V - I_a R_a = 50 - 40 \times 0.75 = 220 \text{ V}$$

$$220 = 25 \times 10^{-3} \times 782 \times N \times 0.75 = 220 \text{ V}$$