

Models LD - Defender

Title Defender Anti Lock Braking ECU 2007 onwards

Last Modified 28-MAY-2008 11:23

Category Chassis

Symptom 301000 Service Brake System

Issue: Land Rover have received some reports where a replacement Anti Lock Braking System (ABS) Electronic Control Unit (ECU) has been fitted to a vehicle but not programmed to the vehicle using Integrated Diagnostic Solution (IDS)

Cause: If the ABS ECU has not been programmed to the vehicle the ABS amber warning light will not extinguish when the vehicle is driven. The ECU has to go through a learn process before the new

Content ECU flag is released for the light to extinguish.

Action: If a replacement ABS ECU is required, please ensure that IDS is used to programme the ECU using the **T4** side of the application entering the model year as a 2006 vehicle, where the vehicle is a 2007 MY onwards. If the ABS warning light does not extinguish following the programming sequence and road test, check for any fault codes stored and follow the diagnostic path on T4.