

W7500P Errata Sheet


Document History

Ver 1.0.0 (July.11, 2016)	First release (erratum 1) - I2C
Ver 1.0.1 (Dec.08, 2016)	Correct SCL speed
Ver 1.1.0 (Jun.18, 2018)	erratum 2 - Transmission Delay

© 2016 WIZnet Co., Inc. All Rights Reserved.

For more information, visit our website at <http://www.wiznet.co.kr>

Erratum 1

Phenomenon	Receiving repeating data in continuative data transmission causes I2C communication problem.
Condition	 <p>W7500 receives the first repeating data but starts to discards from the 2nd repeating data to next different data in continuative data transmission. It causes data loss.</p>
Solution & Recommendation	<p>To avoid this issue, W7500 uses GPIO instead of I2C. In this case, SCL has limited speed, 100KHz.</p> <p>Example pseudo code:</p> <pre> Function Initialize_I2C () { ... scl_port_num = I2C_PORT(conf->scl); scl_pin_index = I2C_PIN_INDEX(conf->scl); sda_port_num = I2C_PORT(conf->sda); sda_pin_index = I2C_PIN_INDEX(conf->sda); //SCL setting GPIO_InitDef.GPIO_Pin = scl_pin_index; GPIO_InitDef.GPIO_Mode = GPIO_Mode_OUT; if(scl_port_num == 0) { GPIO_Init(GPIOA, &GPIO_InitDef); GPIO_SetBits(GPIOA, scl_pin_index); } ... //SDA setting </pre>

```

GPIO_InitDef.GPIO_Pin = sda_pin_index;
GPIO_InitDef.GPIO_Mode = GPIO_Mode_IN;
if(sda_port_num == 0)
{
    GPIO_Init(GPIOA, &GPIO_InitDef);
    GPIO_ResetBits(GPIOA, sda_pin_index);
}
....
}

/* SCL function */
Function I2C_SCL
{
...
    if(scl_port_num == 0)
    {
        if(data == 1)
            GPIO_SetBits(GPIOA, scl_pin_index);
        else
            GPIO_ResetBits(GPIOA, scl_pin_index);
    }
...
}

/* SDA function */
Function I2C_SDA
{
...
    if(sda_port_num == 0)
    {
        if(data == 1)
            GPIOA->OUTENCLR = sda_pin_index;
        else
            GPIOA->OUTENSET = sda_pin_index;
    }
...

```

```
}
/* START function */
Function I2C_START

void I2C_Start(I2C_ConfigStruct* conf)
{
    I2C_WriteBitSCL(conf, 1);
    I2C_WriteBitSDA(conf, 1);


    I2C_WriteBitSDA(conf, 0);
    I2C_WriteBitSCL(conf, 0);
}
/* STOP function */
Function I2C_STOP

void I2C_Stop(I2C_ConfigStruct* conf)
{
    I2C_WriteBitSCL(conf, 0);
    I2C_WriteBitSDA(conf, 0);

    I2C_WriteBitSCL(conf, 1);
    I2C_WriteBitSDA(conf, 1);
}
.....
```

Erratum 2

Transmission Delay Case

Phenomenon	<p>There are some cases of data transmission delay when W7500P is connected to a particular switch or router. (The router that was used for the below test is "TP_LINK AC750")</p>  <p>As shown above, there are random cases where the ping reply is delayed over 3 seconds and occurs irregularly.</p>
Condition	<p>The cause of this phenomenon is due to NC (Not Connected) pads & the connection problems related to PHY MII signals inside the chip (W7500P is silicon-in-package product and it includes W7500 and Ethernet PHY circuit inside.); By Collision handling due to wrong detection of duplex mode, the transmission packets are delayed.</p>
Solution & Recommendation	<p>In order to resolve this phenomenon, users MUST add the following initialization code.</p> <pre data-bbox="430 1702 1364 1982"> void PHY_Init(void) { #ifdef __W7500P__ // W7500P only // PB_12 *(volatile uint32_t *) (0x41003070) = 0x61; // RXDV: set pull down // PB_05 </pre>

```

*(volatile uint32_t *) (0x41002054) = 0x01;
*(volatile uint32_t *) (0x41003054) = 0x61;

// PB_06
*(volatile uint32_t *) (0x41002058) = 0x01;
*(volatile uint32_t *) (0x41003058) = 0x61;

// PHY reset pin pull-up (PD_06)
*(volatile uint32_t *) (0x410020D8) = 0x01;
*(volatile uint32_t *) (0x410030D8) = 0x02;
*(volatile uint32_t *) (0x45000004) = 0x40;
*(volatile uint32_t *) (0x45000010) = 0x40;

mdio_init(GPIOB, W7500x_MDC, W7500x_MDIO); // MDIO Init
mdio_write(GPIOB, PHYREG_CONTROL, CNTL_RESET); // PHY Reset
#endif
}

```

The DUP pin(pin 15)of W7500Pshows what duplex mode it operates with the switch or router as,The value is as below.

- DUP pin = '1' (HIGH) : Full duplex mode
- DUP pin = '0' (LOW) : Half duplex mode