

Technical Bulletin

Model
6 Cyl.

Group
7

Subject

Passenger Side Airbag Cover

Part Identifier
7016

Number
9501

ATTENTION: Service Manager / Service Technician

Model Affected: **911 Carrera Model Year 1995**

Concern: Noises from the passenger side Airbag covers while driving.

General Information: The two felt strips on the airbag covers on the passenger side of the vehicle have been replaced with three Teflon strips (figure 1) as of July 1, 1994 production from VIN's: 99XSS321420 Coupe
991SS341178 Cabriolet

Due to production reasons a few vehicles built after the above mentioned production date still received the felt strips.




Figure 1

Repair Information: In case of noise complaints from this area, three (3) Teflon strips should be installed on the top cover (figure 2).

Repair Procedure:

- Disconnect battery.
- Remove radio and radio frame.
- Remove Heater/AC vent, Heater/AC control head and frame.
- Remove ashtray.
- Remove kneebare and disconnect wires to the passenger airbag.
- Remove the lower airbag cover (3 bolts).
- Remove the felt strips on the upper airbag cover and install (3) Teflon strips at the dimensions shown in (figure 2). Start with the installation of the Teflon strips on the edge (circled area figure 2).





Figure 2

Technical Bulletin		Model 6 Cyl.	Group 7
Subject Passenger Side Airbag Cover	Part Identifier 7016	Number 9501	

Important:

The Teflon strips must be installed approximately 2mm over the top radius of the upper cover (figure 3).



Repair Procedure:

Reinstall all components in the reverse order.

Literature:

Workshop manual 911 Carrera (993), Volume V

Parts Information:

Teflon Strip Part Number - 928 512 531 02 Quantity (3)

**Warranty Information
(if applicable)**

Damage Code: 7016 18 0002

Labor Operation:	Description	
6868 1500	Install Teflon strips as per Technical Bulletin	160TU

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers. ©1995 Porsche Cars North America, Inc.

Dealership	Service manager _____	Shop foreman _____	Service technician _____	_____	_____	_____
Distribution	Asst. manager _____	Warranty admin. _____	Service technician _____	_____	_____	_____
Routing						

The trademarks Porsche®, Targa®, Carrera®, Tiptronic®, Variocam® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.

©1995 Porsche Cars
North America, Inc.
All rights reserved. Cannot be
reproduced without written permission.
Service & Parts Publications.



SERVICE

Page 2 of 2
January 26, 1995