


Technical Bulletin		Model 6 Cyl.	Group 3
Subject	Tiptronic Transmission Marking With New Hydraulic Unit	Part Identifier 3730	Number 9601

ATTENTION: Service Manager / Service Technician

Models affected: *911 Carrera From Model Year 1995 - on*


General Information: All Tiptronic transmissions produced since February 1995, for 1995 or newer 911 Carrera's are equipped with a new hydraulic unit, part number 943 325 001 02.

Identification: Identification of Tiptronic transmissions with the new hydraulic unit is as follows:



Marked in the area of the arrow with "025" or greater.


NEW TIPTRONIC TRANSMISSION



Marked in the area of the arrow with "S".

REBUILT TIPTRONIC TRANSMISSION

Repair Information: Transmissions with the new hydraulic unit must have the transmission control unit with software version 2525. Tiptronic transmission control units with this version software can be identified by the bar code label on the front of the transmission control unit (see arrow in illustration below).



Technical Bulletin		Model 6 Cyl.	Group 3
Subject Tiptronic Transmission Marking With New Hydraulic Unit		Part Identifier 3730	Number 9601

Repair Information Con't:

If a transmission with the new hydraulic unit or a new hydraulic unit is installed in a vehicle produced before the following VIN's, **the transmission control unit must also be replaced.**

Transmission control unit with software 2525 has been installed as of VINs:

996 SS 342227 CABRIOLET

999 SS 322660 COUPE

When in doubt as to which software version a vehicle has, check the version on the bar code tag on the front of the Tiptronic control unit.

Marking Transmission:

If a new hydraulic unit, part number 943 325 001 02, is installed in a transmission that previously did not have the new hydraulic unit, the transmission should be marked with a "S" in the area shown on page 1 of this bulletin referring to REBUILT TIPTRONIC TRANSMISSION.

Parts Information:

943 325 001 02

943 325 001 01

993 618 115 00

Hydraulic unit

Hydraulic unit (NO LONGER AVAILABLE)

Transmission control unit (MUST HAVE SOFTWARE VERSION 2525)

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

©1996 Porsche Cars North America, Inc.

Dealership
Distribution
Routing

Service Manager _____
Asst. Manager _____

Shop Foreman _____
Warranty Admin. _____

Service Technician _____
Service Technician _____

The trademarks Porsche®, Targa®, Carrera®, Tiptronic®, Varioram® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.