

**Department of Mechanical Engineering
Indian Institute of Technology Kharagpur**

**Mid-Semester Examination February 2014
Machine Tools and Machining (ME30604)**

Full Marks: 60

Duration: 2 hours

3rd Year BTech and Dual Degree Students of ME, MF, IEM and QEDM

All symbols have usual interpretations

Attempt all questions

- 1 (a) *Answers to Q.1(a) – (e) must accompany neat sketch of the cutting tool (relevant to question and numerical data) in top view to earn any credit*

The cutting plane and machine transverse plane of a single point turning tool [2]
coincide. The side rake (γ_x) of this turning tool is -7° . Find out the side cutting edge angle.

- (b) The auxiliary cutting plane and cutting plane of a single point cutting tool make an [2]
angle of 120° . The end cutting edge angle is 15° . Find out the principal cutting edge angle (ϕ).

- (c) The orthogonal plane and machine transverse plane of a single point cutting tool are [2]
at angle of 90° . Find out the back rake (γ_y) if the inclination angle of the main (principal) cutting edge is $+10^\circ$.

- (d) The tool geometry of a single point turning tool is specified as [2]
 $0^\circ -10^\circ 8^\circ 10^\circ 15^\circ 90^\circ 0$ mm in ORS. Find out the angle between cutting plane and machine longitudinal plane.

- (e) The tool geometry of a single point turning tool is specified as [2]
 $0^\circ -10^\circ 8^\circ 10^\circ 15^\circ 90^\circ 0$ mm in ORS. Show the location of master line of the rake surface.

- 2 Draw the sketch to show the following machining operations and write the [2]
generatrix and directrix statements.

- (a) parting off operation in a lathe [2]
(b) facing operation in a lathe [2]
(c) taper turning in a CNC lathe or a centre lathe [2]
(d) boring a hole in a lathe using boring tool [2]

- (e) drilling in a column drilling machine [2]
- 3 (a) Draw the top view of a single point turning tool specified as [8]
 $10^\circ - 10^\circ 8^\circ 10^\circ 15^\circ 75^\circ 0.8$ mm in ORS and also show the relevant angles and features (in ORS) in top and sectional view.
- (b) The longitudinal feed rate is 17 mm/min. The pinion responsible for longitudinal feed in a lathe has 18 teeth and 1.5 module. The apron constant is 50. Determine the rotational speed of the feed rod in rpm. [2]
- 4 (a) The cutting velocity while turning a bar of 200 mm diameter is 100 m/min when the feed rod rotates at 16 rpm. The transmission ratio of the 'Norton Cone -Tumbler drive' and Meander drive are $\frac{1}{2}$ and $\frac{1}{2}$ respectively. Determine the transmission ratio of the change gear quadrant. [4]
- (b) Sketch a speed gear box with 18 speeds along with the prime mover and the spindle. [3]
- (c) The feed gear box is not connected to speed gear box via the shaft carrying the chuck or the spindle. [3]
 It is connected directly to the input shaft of the speed gear box. The spindle speed is 200 rpm and the longitudinal feed is 0.2 mm/rev. Now by changing the gears within the speed gear box the spindle is doubled (i.e made 400 rpm). What would be the new longitudinal feed in mm/rev and mm/min?
- 5 (a) The no of teeth in the gears of a driver and driven shaft pair are 20, 40, 60 and 80, 60, 40, 4 respectively, i.e., in each case the no of teeth in driver and driven gear is 100. Why is it necessary? Under what circumstances $Z_1 + Z_2$ for the same shaft pair can vary?
- (b) The following is a tool designation. Point out the quantity which is in error. 2
 $\lambda_o - \gamma_o - \alpha_o - \gamma_o' - \phi l - \phi - r$
- (c) Name two pairs used for transforming a rotation to another rotation 2
- (d) Name two pairs used for transforming a rotation to a translatory motion. 2
- 6 (a) Using a sketch show how a single gear tooth can be machined using a lathe. 2
- (b) Name any four methods to produce a flat surface 2
- (c) Sketch the feed gear drive (starting from the motor) of a lathe that is powered by an independent motor (not the same motor used to power the speed gear box) using a block diagram. 2
- (d) The feed gear drive of a lathe is equipped with change gear quadrant, Norton cone, meander drive, lead screw and apron. The apron constant is 50. The pitch of the lead screw is 4 mm. Find the possible transmission ratios of the above gear box elements so that a thread with a pitch of 2 mm can be machined for a spindle speed of (i) 200 rpm and (ii) 400 rpm. 4