


# Phase Diagrams & Phase Transformation

## Microstructure - Phases




## Basic Definitions

- **Alloy:** A metallic substance that is composed of two or more elements.
- **Component:** A chemical constituent (element or compound) of an alloy, which may be used to specify its composition.
- **Phase:** A homogeneous portion of a system that has uniform physical and chemical characteristics.
- **Equilibrium:** The state of a system where the phase characteristics remain constant over indefinite time periods.
  - At equilibrium the free energy is a minimum.

## When we combine two elements


- What equilibrium state do we get?
- If we specify...
  - a composition (e.g., wt% Cu - wt% Ni), and
  - a temperature (T)
- then...
  - How many phases do we get?
  - What is the composition of each phase?
  - How much of each phase do we get?



## Phase Diagram

- Three externally controllable parameters that affect phase fraction and composition
  - Temperature
  - Pressure
  - Composition
- Phase diagram is constructed when various combinations of these parameters are plotted against one another

## Unary (One component) phase diagram



## Phase Equilibria: Solubility Limit

### Introduction

- **Solutions** – solid solutions, single phase
- **Mixtures** – more than one phase


- **Solubility Limit:**  
Max concentration for which only a single phase solution occurs.

Question: What is the solubility limit at 20°C?

Answer: **65 wt% sugar.**

If  $C_0 < 65$  wt% sugar: syrup

If  $C_0 > 65$  wt% sugar: syrup + sugar




## Effect of $T$ & Composition ( $C_0$ )

- Changing  $T$  can change # of phases:
- Changing  $C_0$  can change # of phases:

path A to B.  
path B to D.

B (100°C, 70) 1 phase  
D (100°C, 90) 2 phases



## Phase Equilibria


Simple solution system (e.g., Ni-Cu solution)

	Crystal Structure	electroneg	$r$ (nm)
Ni	FCC	1.9	0.1246
Cu	FCC	1.8	0.1278

- Both have the same crystal structure (FCC) and have similar electronegativities and atomic radii (W. Hume – Rothery rules) suggesting high mutual solubility.
- Ni and Cu are totally miscible in all proportions.

## Phase Diagrams

- Indicate phases as function of  $T$ ,  $C_0$ , and  $P$ .
- For this course:
  - binary systems: just 2 components.
  - independent variables:  $T$  and  $C_0$  ( $P = 1$  atm is almost always used).



## Phase Diagrams:

### # and types of phases

- Rule 1: If we know  $T$  and  $C_0$ , then we know:
  - the # and types of phases present.


### Examples:

A (1100°C, 60):

1 phase: α

B (1250°C, 35):

2 phases: L + α



## Phase Diagrams:

### composition of phases

- Rule 2: If we know  $T$  and  $C_0$ , then we know:
  - the composition of each phase.

### Examples:

$C_0 = 35$  wt% Ni

At  $T_A = 1320^\circ\text{C}$ :

Only Liquid (L)

$C_L = C_0 (= 35 \text{ wt\% Ni})$

At  $T_D = 1190^\circ\text{C}$ :

Only Solid (α)


$C_\alpha = C_0 (= 35 \text{ wt\% Ni})$


At  $T_B = 1250^\circ\text{C}$ :

Both α and L

$C_L = C_{\text{liquidus}} (= 32 \text{ wt\% Ni here})$

$C_\alpha = C_{\text{solidus}} (= 43 \text{ wt\% Ni here})$






Intensive variables of the system:

- Temperature of each phase
- Pressure of each phase
- Composition of each phase = Relative concentration of each component in that phase

Temperature of each phase is equal and is equal to the temperature of the system

Pressure of each phase is equal and is equal to the pressure of the system

To completely define the system means: specifying temperature, pressure and relative concentrations of each component in each phase of the system



### Gibbs Phase Rule when Pressure is constant

$$F = C - P + 1$$


If Pressure is fixed at a particular value

Degrees of Freedom

Number of components

Number of phases

Phase diagrams for metals and ceramics are drawn at 1 atm. fixed pressure



### Phase Diagrams: weight fractions of phases

• Rule 3: If we know T and  $C_0$ , then we know:  
--the amount of each phase (given in wt%).

• Examples:

$C_0 = 35 \text{ wt\% Ni}$

At T<sub>A</sub>: Only Liquid (L)  
 $W_L = 100 \text{ wt\%}, W_\alpha = 0$

At T<sub>D</sub>: Only Solid ( $\alpha$ )  
 $W_L = 0, W_\alpha = 100 \text{ wt\%}$

At T<sub>B</sub>: Both  $\alpha$  and L

$W_L = \frac{S}{R + S} = \frac{43 - 35}{43 - 32} = 73 \text{ wt\%}$


$W_\alpha = \frac{R}{R + S} = 27 \text{ wt\%}$

## Phase Diagrams: # and types of phases

- Rule 1: If we know T and  $C_0$ , then we know:  
–the # and types of phases present.

- Examples:


A(1100°C, 60):  
1 phase:  $\alpha$   
B(1250°C, 35):  
2 phases: L +  $\alpha$




## Ex: Cooling in a Cu-Ni Binary

- Phase diagram:  
Cu-Ni system.

- Consider  
 $C_0 = 35 \text{ wt\% Ni}$ .




## Non-equilibrium/ Fast Cooling



## Cored vs Equilibrium Phases

- $C_{\alpha}$  changes as we solidify.
- Cu-Ni case:  
First  $\alpha$  to solidify has  $C_{\alpha} = 46 \text{ wt\% Ni}$ .  
Last  $\alpha$  to solidify has  $C_{\alpha} = 35 \text{ wt\% Ni}$ .
- Fast rate of cooling:  
Cored structure
- Slow rate of cooling:  
Equilibrium structure



## Binary-Eutectic Systems


2 components

has a special composition  
with a min. melting T.

- Ex.: Cu-Ag system
- 3 single phase regions  
(L,  $\alpha$ ,  $\beta$ )

- Limited solubility:  
 $\alpha$ : mostly Cu  
 $\beta$ : mostly Ag
- $T_E$ : No liquid below  $T_E$
- $C_E$ : Min. melting  $T_E$   
composition

- Eutectic transition  
 $L(C_E) \rightleftharpoons \alpha(C_{\alpha E}) + \beta(C_{\beta E})$



## EX: Pb-Sn Eutectic System (1)

- For a 40 wt% Sn-60 wt% Pb alloy at 150°C, find...


- the phases present:  $\alpha + \beta$
- compositions of phases:

$C_0 = 40 \text{ wt\% Sn}$   
 $C_{\alpha} = 11 \text{ wt\% Sn}$   
 $C_{\beta} = 99 \text{ wt\% Sn}$

- the relative amount  
of each phase:

$$W_{\alpha} = \frac{S}{R+S} = \frac{C_{\beta} - C_0}{C_{\beta} - C_{\alpha}} = \frac{99 - 40}{99 - 11} = \frac{59}{88} = 67 \text{ wt\%}$$

$$W_{\beta} = \frac{R}{R+S} = \frac{C_0 - C_{\alpha}}{C_{\beta} - C_{\alpha}} = \frac{40 - 11}{99 - 11} = \frac{29}{88} = 33 \text{ wt\%}$$



## EX: Pb-Sn Eutectic System (2)

- For a 40 wt% Sn-60 wt% Pb alloy at 200°C, find...

--the phases present:  $\alpha + L$

--compositions of phases:

$$C_0 = 40 \text{ wt\% Sn}$$


$$C_\alpha = 17 \text{ wt\% Sn}$$

$$C_L = 46 \text{ wt\% Sn}$$

--the relative amount of each phase:

$$W_\alpha = \frac{C_L - C_0}{C_L - C_\alpha} = \frac{46 - 40}{46 - 17} = \frac{6}{29} = 21 \text{ wt\%}$$

$$W_L = \frac{C_0 - C_\alpha}{C_L - C_\alpha} = \frac{40 - 17}{46 - 17} = \frac{23}{29} = 79 \text{ wt\%}$$




## Microstructures in Eutectic Systems: I

- $C_0 < 2 \text{ wt\% Sn}$

Result:

--at extreme ends  
--polycrystal of  $\alpha$  grains  
i.e., only one solid phase.




## Microstructures in Eutectic Systems: II

- 2 wt% Sn  $< C_0 < 18.3 \text{ wt\% Sn}$

Result:


- Initially liquid +  $\alpha$
- then  $\alpha$  alone
- finally two phases
  - $\alpha$  polycrystal
  - fine  $\beta$ -phase inclusions





## Microstructures in Eutectic Systems: III

- $C_0 = C_E$


Result: Eutectic microstructure (lamellar structure)  
--alternating layers (lamellae) of  $\alpha$  and  $\beta$  crystals.



## Lamellar Eutectic Structure




## Eutectic Phase Diagram



Apply Gibbs Phase Rule


## Microstructures in Eutectic Systems: III

- If the Liquid composition is Eutectic composition
- Result: Eutectic microstructure (lamellar structure) --alternating layers (lamellae) of  $\alpha$  and  $\beta$  crystals.




## Microstructures in Eutectic Systems: IV


- 18.3 wt% Sn <  $C_0$  < 61.9 wt% Sn
- Result:  $\alpha$  crystals and a eutectic microstructure



## Hypoeutectic & Hypereutectic



You can draw Eutectic phase diagram stating from the eutectic reaction



## Other Phase Diagrams

Eutectoid  $\delta \rightleftharpoons \gamma + \epsilon$

$S_1$

$S_2 > \frac{v}{S_3} < S_3$  Eutectoid

Peritectic  $\gamma + L \rightleftharpoons \delta$

$L$

$S_1$

$S_2$

Peritectic


Peritectoid  $\alpha + \gamma \rightleftharpoons \delta$

$S_1$


$S_2$

Peritectoid

## Peritectoid Phase diagram




## Peritectic and Peritectoid Phase Diagrams




## Eutectoid & Peritectic

### Cu-Zn Phase diagram




Eutectic

Eutectoid




Peritectic

Peritectoid




## Intermediate/ Intermetallic Compounds




- Not isomorphous with either of the components of the alloy system
- Congruently melting intermediate phases  $\rightarrow$  Intermetallic phase

Note: intermetallic compound forms a line - not an area - because stoichiometry (i.e. composition) is exact.

## Cu-Zn : Intermediate Phases



## Fe-Cementite Phase Diagram







## Few Principles about Phase Diagrams

1. One phase regions may touch each other only at single points (point of congruent transformation), never along a boundary
2. Adjacent one phase regions are separated from each other by 2 phase regions involving the same 2 phases
3. Three 2 phase regions must originate upon three phase isotherm
4. Two three phase isotherms may be connected by a 2 phase region provided that there are 2 phases which are common to both of the three phase equilibria
5. All boundaries of 2 phase fields must project into 2 phase fields when they join a three phase isotherm


## Fe-Cementite Phase Diagram




## Iron-Carbon (Fe-C) Phase Diagram




## Growth of Pearlite colony



## Hypoeutectoid Steel



## Hypereutectoid Steel






## Class Work/ Class Test

Do it now on your own notebook

For an alloy, Fe-0.40 wt% C at a temperature just below the eutectoid, determine the following

- composition of  $\text{Fe}_3\text{C}$  and ferrite ( $\alpha$ )
- the amount of carbide (cementite) in grams that forms per 100 g of steel
- the amount of pearlite and proeutectoid ferrite ( $\alpha$ )

## Fe-Cementite Phase Diagram



## Phase Equilibria

Solution: a) composition of  $\text{Fe}_3\text{C}$  and ferrite ( $\alpha$ )


- the amount of carbide (cementite) in grams that forms per 100 g of steel

$$\frac{\text{Fe}_3\text{C}}{\text{Fe}_3\text{C} + \alpha} = \frac{C_0 - C_\alpha}{C_{\text{Fe}_3\text{C}} - C_\alpha} \times 100$$

$$= \frac{0.4 - 0.022}{6.7 - 0.022} \times 100 = 5.7\text{g}$$

$$\text{Fe}_3\text{C} = 5.7\text{g}$$

$$\alpha = 94.3\text{g}$$



## Phase Equilibria


- the amount of pearlite and proeutectoid ferrite ( $\alpha$ )

Amount of pearlite = amount of  $\gamma$  just above  $T_E$

$$\frac{\gamma}{\gamma + \alpha} = \frac{C_0 - C_\alpha}{C_\gamma - C_\alpha} \times 100 = 51.2\text{g}$$


$$\text{pearlite} = 51.2\text{g}$$

$$\text{proeutectoid } \alpha = 48.8\text{g}$$




## Recap of μstructure evolution in steel

### Hypoeutectoid Steel



## Recap of μstructure evolution in steel

### Hypereutectoid Steel



# Phase Transformation

**Phase transformations (change of the microstructure)** can be divided into three categories:

- **Diffusion-dependent with no change in phase composition or number of phases present** (e.g. melting, solidification of pure metal, allotropic transformations, recrystallization, etc.)
- **Diffusion-dependent with changes in phase compositions and/or number of phases** (e.g. eutectic or eutectoid transformations)
- **Diffusionless phase transformation** - by cooperative small displacements of all atoms in structure, (e.g. martensitic transformation )


Diffusion-dependent phase transformations can be rather slow and the final structure often depend on the rate of cooling/heating.

### Kinetics of phase transformations

Phase transformations involve change in structure and (for multi-phase systems) composition  $\Rightarrow$  rearrangement and redistribution of atoms via diffusion is required.

The process of phase transformation involves:

- **Nucleation** of the new phase(s) - formation of stable small particles (nuclei) of the new phase(s). Nuclei are often formed at grain boundaries and other defects.
- **Growth** of the new phase(s) at the expense of the original phase(s).




## Nucleation

Nucleation can be

**Heterogeneous** – the new phase appears on the walls of the container, at impurity particles, etc.

**Homogeneous** – solid nuclei spontaneously appear within the undercooled phase.

Let's consider solidification of a liquid phase undercooled below the melting temperature as a simple example of a phase transformation.



### Gibbs free energy in analysis of phase transitions


It is convenient to analyze phase transformations occurring under conditions of constant temperature (T) and pressure (P) by using **Gibbs free energy (G)**.

$G = H - TS$ , where  $H$  is the **enthalpy** and  $S$  is the **entropy**

$H = U + PV$ , where  $U$  is the internal energy

**Gibbs free energy ( $G = H - TS$ ):**  
Equilibrium is trade-off between minimization of enthalpy and maximization of entropy

*A phase transformation occurs spontaneously only when  $G$  decreases in the course of the transformation*



Is the transition from undercooled liquid to a solid spherical particle in the liquid a spontaneous one?

The formation of a solid nucleus leads to a Gibbs free energy change of

$$\Delta G = V_S(G_v^S - G_v^L) + A_{SL}\gamma_{SL} = \frac{4}{3}\pi r^3 \Delta G_v + 4\pi r^2 \gamma_{SL}$$


at  $T < T_m$ ,  $G_v^S < G_v^L$  – solid is the equilibrium phase

$V_s$  is the volume of the solid sphere


 $A^{SL}$  is the solid/liquid interfacial area

$\gamma^{\text{SL}}$  is the solid/liquid interfacial energy

Free energy change per unit volume. Below  $T_m$  it is -ve



## Homogeneous Nucleation & Energy Effects



## Homogeneous nucleation

at  $r=r^*$ ,  $\frac{\partial \Delta G}{\partial r} = 0$

$$\Delta G = V_s (G_v^s - G_v^l) + A_{SL} \gamma_{SL} = \frac{4}{3}\pi r^3 \Delta G_v + 4\pi r^2 \gamma_{SL}$$

$$r^* = \frac{-2\gamma_{SL}}{\Delta G_v} \quad \Delta G^* = \frac{16\pi(\gamma_{SL})^3}{3(\Delta G_v)^2}$$

$$\Delta G_v = \frac{\Delta H_v \Delta T}{T_m} = \frac{L_v \Delta T}{T_m}$$

$$\Delta T = T_m - T = \text{Undercooling}$$

$$\Delta H_v = L_v \text{ is latent heat of solidification}$$

$$\Delta G_v, \Delta H_v = L_v < 0$$


Therefore,

$$r^* = \frac{-2\gamma_{SL}}{\Delta G_v} = \left( \frac{-2\gamma_{SL} T_m}{\Delta H_v} \right) \frac{1}{\Delta T}$$

Both  $r^*$  and  $\Delta G^*$  decrease with increasing undercooling

$$\Delta G^* = \frac{16\pi(\gamma_{SL})^3}{3(\Delta G_v)^2} = \left( \frac{16\pi(\gamma_{SL})^3 T_m^2}{3(\Delta H_v)^2} \right) \frac{1}{(\Delta T)^2}$$

## Homogeneous nucleation




$$r^* = \frac{-2\gamma_{SL}}{\Delta G_v} = \left( \frac{-2\gamma_{SL} T_m}{\Delta H_v} \right) \frac{1}{\Delta T}$$

$$\Delta G^* = \frac{16\pi(\gamma_{SL})^3}{3(\Delta G_v)^2} = \left( \frac{16\pi(\gamma_{SL})^3 T_m^2}{3(\Delta H_v)^2} \right) \frac{1}{(\Delta T)^2}$$

Both  $r^*$  and  $\Delta G^*$  decrease with increasing undercooling

## Homogeneous nucleation in solid

$$\Delta G = V_s \Delta G_v + A_{SL} \gamma_{SL} + V_s \Delta G_{strain} = \frac{4}{3}\pi r^3 (\Delta G_v + \Delta G_{strain}) + 4\pi r^2 \gamma_{SL}$$



$$r^* = \frac{-2\gamma_{SL}}{(\Delta G_v + \Delta G_{strain})}$$

$$\Delta G^* = \frac{16\pi(\gamma_{SL})^3}{3(\Delta G_v + \Delta G_{strain})^2}$$


Both  $r^*$  and  $\Delta G^*$  increase because of strain energy involved in solid state transformation

## Rate of Homogeneous nucleation

There is an energy barrier of  $\Delta G^*$  for formation of a solid nucleus of critical size  $r^*$ . The probability of energy fluctuation of size  $\Delta G^*$  is given by the Arrhenius equation and the rate of homogeneous nucleation is

$$\dot{N} \sim v_d \exp\left(-\frac{\Delta G^*}{kT}\right) \text{ nuclei per m}^3 \text{ per s}$$

where  $v_d$  is the frequency with which atoms from liquid attach to the solid nucleus. The rearrangement of atoms needed for joining the solid nucleus follow the same temperature dependence as the diffusion coefficient:



$$v_d \sim \exp\left(-\frac{Q_d}{kT}\right)$$

$$\text{Therefore: } \dot{N} \sim \exp\left(-\frac{Q_d}{kT}\right) \exp\left(-\frac{\Delta G^*}{kT}\right)$$

$$\Delta G^* \propto \frac{1}{(\Delta T)^2}$$


$$\Delta T = T_m - T$$

$$\text{As } T \downarrow \rightarrow \Delta T \uparrow \rightarrow \Delta G^* \downarrow$$


$$\rightarrow \exp(-\Delta G^*/kT) \uparrow$$

$$\rightarrow v_d \downarrow$$

## Rate of Homogeneous nucleation




## Heterogeneous nucleation



$$\Delta G = V_S \Delta G_v + A_{SL} \gamma_{SL} + A_{SM} \gamma_{SM} - A_{SM} \gamma_{LM}$$


$$\gamma_{SM} - \gamma_{LM} = -\gamma_{SL} \cos \theta$$

## Heterogeneous nucleation



$$\Delta G = V_S \Delta G_v + A_{SL} \gamma_{SL} + A_{SM} \gamma_{SM} - A_{SM} \gamma_{LM}$$

$$\gamma_{SM} - \gamma_{LM} = -\gamma_{SL} \cos \theta$$



$$A_{SM} = \pi y^2 = \pi r^2 \sin^2 \theta$$

$$A_{SL} = 2\pi r^2 (1 - \cos \theta)$$

$$V = \pi \int_{h,0}^R (R^2 - x^2) dx = \frac{\pi R^3}{3} (3R - h)$$



$$V_S = 1/3 \pi h^2 (3R - h) = 1/3 \pi r^2 [1 - \cos \theta]^2 [2R + r \cos \theta] = 1/3 \pi r^3 [1 - \cos \theta]^2 [2 + \cos \theta]$$

$$V_S = \frac{4}{3} \pi r^3 S(\theta)$$

$$S(\theta) = \frac{(2 + \cos \theta)(1 - \cos \theta)^2}{4}$$

$$\Delta G = \left( \frac{4}{3} \pi r^3 \Delta G_v + 4 \pi r^2 \gamma_{SL} \right) S(\theta)$$

## Heterogeneous nucleation




$$\Delta G_{het} = \left\{ \frac{4}{3} \pi r^3 \Delta G_v + 4 \pi r^2 \gamma_{SL} \right\} S(\theta)$$

$$r_{het}^* = \frac{-2 \gamma_{SL}}{\Delta G_v} = r_{hom}^*$$

$$S(\theta) = \frac{(2 + \cos \theta)(1 - \cos \theta)^2}{4}$$

$$\Delta G_{het}^* = \frac{16 \pi \gamma_{SL}^3}{3 \Delta G_v^2} S(\theta) = \Delta G_{hom}^* S(\theta)$$


## Solidification: Nucleation Processes




- **Homogeneous nucleation**
  - nuclei form in the bulk of liquid metal
  - requires supercooling (typically 80-300°C max)
- **Heterogeneous nucleation**
  - Nuclei form on mold wall or inoculants
  - allows solidification with only 0.1-10°C supercooling

## Nucleation rate


$$\text{if } \theta = 10^\circ \quad S(\theta) = (2 + \cos \theta)(1 - \cos \theta)^2 / 4 \approx 10^{-4}$$




heterogeneous nucleation starts at a lower undercooling



## Variation of S(theta) with theta




# Nucleation rate: Homogeneous vs. Heterogeneous



## Growth

Once a stable nucleus of the new phase exceeding the critical size  $r^*$  is formed, it starts to grow. Atomically rough interfaces migrate by continuous growth, whereas atomically flat interfaces migrate by ledge formation and lateral growth.




$$\text{Growth rate} = C \exp(-Q_A/kT) = C \exp(-Q_m/RT)$$

per atom


per mole

## Rate of phase transformations

Total rate of a phase transformation induced by cooling is a product of the nucleation rate and growth rate (diffusion controlled - slows down with T decrease).



## Rate of Phase Transformation



**high T (close to T<sub>m</sub>):** low nucleation and high growth rates  
→ coarse microstructure with large grains


**low T (strong undercooling):** high nucleation and low growth rates  
→ fine structure with small grains

## Rate of phase transformations


To quantitatively describe the rate of a phase transformation, it can be defined as reciprocal of time for transformation to proceed halfway to completion:

$$\text{rate} = 1 / t_{0.5}$$

Plotting the transformation time vs temperature results in a characteristic C-shaped curves:




## Time – Temperature – Transformation (TTT) diagram α → β phase transformation




### Transformations & Undercooling

- Eutectoid transformation (Fe-Fe<sub>3</sub>C system):  $\gamma \Rightarrow \alpha + \text{Fe}_3\text{C}$
- For transformation to occur, must cool to below 727°C



### Isothermal Transformation Diagrams

- 2 solid curves are plotted:
  - one represents the time required at each temperature for the start of the transformation;
  - the other is for transformation completion.
- The dashed curve corresponds to 50% completion.
- The austenite to pearlite transformation will occur only if the alloy is supercooled to below the eutectoid temperature (727°C).
- Time for process to complete depends on the temperature.




Next class onwards Prof. Sumantra Mandal will teach at the same class timings

### Solidification of pure metal:

- Cooling curve
- Concept of supercooling
- Homogeneous and heterogeneous nucleation processes,
- Microstructure of pure metals

### Cooling Curve for pure metal



### Dendritic structure

Development of Thermal Dendrites

- Spherical Nucleus
- The interface becomes unstable
- Primary arms develop in crystallographic directions  $\langle 100 \rangle$  in cubic crystals
- Secondary and tertiary arms develop



