

License Number

CBD1500635

CustomerNexteer Automotive Corporation
Package: FBL Gm SLP6**Maintenance Expiry Date**

2016-02-01

SIP Delivery Date

2017-07-28

SIP Version

06.04.03

SLP

FBL Gm SLP6

Delivery Number

D03

Report Creation Date

2017-07-27

Contact

In case of questions or the need for an update of the basic software delivery, please contact fblsupport@us.vector.com or your Vector contact person.

Table of Contents

1. [Introduction](#)
 - [1.1 Resolving Issues](#)
 - [1.2 Issue Classification](#)
2. [New Issues](#)
 - [2.1 Safety Relevant Issues: 0](#)
 - [2.2 Runtime Issues without Workaround: 0](#)
 - [2.3 Runtime Issues with Workaround: 4](#)
 - [2.4 Not Released Functionality: 0](#)
 - [2.5 Apparent Issues: 11](#)
 - [2.6 Compiler Warnings: 8](#)
3. [New Issues for Information: 0](#)
4. [Report Legend](#)
5. [Quality Management Contact](#)

1. Introduction

1.1 Resolving Issues

Reported issues are not automatically fixed with the next update delivery.

If a reported issue shall be fixed, please contact Vector agree on the issues that can be fixed with upcoming deliveries.

Please note that Vector may fix issues without explicit request.

1.2 Issue Classification

This Issue Report provides issues that have been detected since the last report. The issues have been classified to facilitate the assessment of their impact:

The chapter 'New Issues' lists issues that have been detected since the last report and which could not be excluded based on the use-case defined in the questionnaire. The issues are classified as follows:

- **Safety Related Issues:** Safety related issues have impact on the functional safety of the software module. If this issue interferes with the functional safety concept of the ECU, this module (or module configuration) must not be used for serial production in a safety-related project. The effect of the issue to the ECU functionality and functional safety has to be analyzed by the user as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.
- **Runtime Issues without Workaround:** Runtime issues without a workaround require an update of the software delivery in case the issue affects the ECU overall functionality. The effect of an issue to the ECU functionality has to be analyzed by the customer as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.
- **Runtime Issues with Workaround:** It is not recommended to update a delivery due to a runtime issue with a documented workaround. The effect of an issue to the ECU functionality has to be analyzed by the user as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.
- **Not Released Functionality:** Not released functionalities (BETA) are either complete software modules or features in the software module that have not yet passed a complete development cycle (they are e.g. not or only partly tested). If a BETA issue ticket affects a complete software module, the software module must not be used for serial production. If a BETA issue ticket affects a feature in the software module, the user has to ensure that all BETA features are disabled as indicated for the serial production release of the ECU.
- **Apparent Issues:** Apparent issues are detected immediately when using the software module. If an issue does not show up while working with the software module, the ECU project is not affected by the issue. Apparent issues may or may not have workarounds.
- **Compiler Warnings:** As a service we also provide the known compiler warnings. The occurrence of a compiler warning may depend on the used software module configuration and compiler settings.

The chapter 'New Issues for Information' lists issues that are not relevant for the use-case that has been documented in the questionnaire provided to Vector. The issues may, however, be relevant for other use-cases. Additionally, issues that have been accepted or are tolerated by the OEM (as defined in the questionnaire) are reported here.

2. New Issues

2.1 Safety Relevant Issues

Safety related issues have impact on the functional safety of the software module. If this issue interferes with the functional safety concept of the ECU, this module (or module configuration) must not be used for serial production in a safety-related project.

The effect of the issue to the ECU functionality and functional safety has to be analyzed by the user as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.

No issue to be reported.

2.2 Runtime Issues without Workaround

Runtime issues without a workaround require an update of the software delivery in case the issue affects the ECU overall functionality. The effect of an issue to the ECU functionality has to be analyzed by the customer as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.

No issue to be reported.

2.3 Runtime Issues with Workaround

It is not recommended to update a delivery due to a runtime issue with a documented workaround. The effect of an issue to the ECU functionality has to be analyzed by the user as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.

Index

ESCAN00090572	Wrong documentation for ApplFblCanBusOff() FBL_TechRef_Gm@Doc_TechRef
ESCAN00092116	Long runtime of flash library functions can delay the Rx frame processing FblDrvFlash_Rh850Rv40His@Impl_Base
ESCAN00095101	Tester connection shall not be fixed in default session FblDiag_14229_Gm@Implementation
ESCAN00096082	GB6002 V1.4.2 defines P2* back to 5000ms FBL_Gm_SLP6@Preconfig

ESCAN00090572 Wrong documentation for ApplFblCanBusOff()	
Component@Subcomponent:	FBL_TechRef_Gm@Doc_TechRef
First affected version:	6.00.00
Fixed in versions:	6.03.00
Problem Description:	
What happens (symptoms):	

Bootloader does not recover from bus-off	
When does this happen:	

When bootloader enters bus-off and there is no recover strategy implemented in ApplFblCanBusOff()	
Issue can be caused by wrong information in documentation in the API description of ApplFblCanBusOff().	
"No action is required in order to recover."	
This statement is wrong. The user must implement a recover strategy in ApplFblCanBusOff().	
In which configuration does this happen:	

All	
Resolution Description:	
Workaround:	

Implement bus-off recovery strategy in ApplFblCanBusOff().	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00092116 Long runtime of flash library functions can delay the Rx frame processing	
Component@Subcomponent:	FbIDrvFlash_Rh850Rv40His@Impl_Base
First affected version:	1.06.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- Flash library operations might be very runtime consuming. This might delay the processing of a Rx frame that long, that the corresponding CAN mailbox has already been overwritten with the following Rx frame assigned to the mailbox. The download will abort with a NRC 0x73 (WrongBlockSequenceCounter). When does this happen: ----- During the flash routines of the flash library. In which configuration does this happen: ----- -Usage of pipelined programming/early acknowledge -So far the behavior has only been detected on F1H and F1K derivatives	
Resolution Description: Workaround: ----- Driving the system with a higher clock also speed up the flash operations and reduces their runtime. (verified with R7F7015032+R7F7015874AFP @ 120MHz) Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00095101 Tester connection shall not be fixed in default session	
Component@Subcomponent:	FblDiag_14229_Gm@Implementation
First affected version:	4.01.03
Fixed in versions:	4.03.01
Problem Description: What happens (symptoms): ----- Tester connection is fixed once communication happens in default session. This is unintended, instead tester connection shall stay flexible in default session. When does this happen: ----- When tester communicates with Fbl in default session. In which configuration does this happen: ----- If FBL_DIAG_ENABLE_GM_RESET_TESTER_IN_DEF_SESSION is not set.	
Resolution Description: Workaround: ----- Set this macro (e.g. in MandatoryDeliveryPreconfig.cfg, content generated to fbl_cfg.h): <pre>#define FBL_DIAG_ENABLE_GM_RESET_TESTER_IN_DEF_SESSION</pre> In order to check the configuration is OK: - Before adding the above macro to configuration, verify, that tester is fixed in default session. so e.g. communication is not possible to tester F2 after communicating with tester F3 to the Fbl after reset - After adding the macro, verify communication in default session is possible to different testers	
Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00096082 GB6002 V1.4.2 defines P2* back to 5000ms	
Component@Subcomponent:	FBL_Gm_SLP6@Preconfig
First affected version:	1.03.02
Fixed in versions:	1.05.12
Problem Description:	
What happens (symptoms):	

A) GB6002 versions < V1.3 and GB6002 versions >= V1.4.2 define P2* to 5000	
b) GB6002 versions >= V1.3 and GB6002 versions < V1.4.2 define P2* to 30000	
Some deliveries prepared for V1.4.2 still use intermediate variant b), but should use a)	
When does this happen:	

At configuration time.	
In which configuration does this happen:	

Always	
Resolution Description:	
Workaround:	

GENy based environment:	
- Overwrite FBL_DIAG_TIME_P3MAX within GENy FblDrvCan_XXX -> User Config File loaded file (typically MandatoryDeliveryPreconfig.cfg)	
Da Vinci Configurator based environment:	
- Change the value "Fbl->FblGeneral->P2* Server" in configuration to 5000ms	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

2.4 Not Released Functionality

Not released functionalities (BETA) are either complete software modules or features in the software module that have not yet passed a complete development cycle (they are e.g. not or only partly tested). If a BETA issue ticket affects a complete software module, the software module must not be used for serial production. If a BETA issue ticket affects a feature in the software module, the user has to ensure that all BETA features are disabled as indicated for the serial production release of the ECU.

No issue to be reported.

2.5 Apparent Issues

Apparent issues are detected immediately when using the software module. If an issue does not show up while working with the software module, the ECU project is not affected by the issue. Apparent issues may or may not have workarounds.

Index

ESCAN00078508	[depends on derivative] Illegal flash block table configuration cause unintended block erase FbiDrvFlash_Rh850Rv40His@Impl_Base
ESCAN00081436	Using FlashDriver_SetResetVector() might cause exception FbiDrvFlash_Rh850Rv40His@Impl_Base
ESCAN00086590	Obsolete generated code in WrapNv_cfg.c does not compile SysService_WrapperNv@GenTool_Geny
ESCAN00090094	FbiCanWakeup() does not allow to enable Can clock again FbiDrvCan_Rh850RscanCrx@Implementation
ESCAN00090391	GM: Calibration header cannot be generated in a way, so that all data bytes can be used FbiTool_Hexeditor_Hexview@Application_Exe
ESCAN00091938	Merqinq does not work FbiTool_Hexeditor_Hexview@Application_Exe
ESCAN00094695	Array gRemainderBuffer is not explicit aligned FbiLib_Mem@Implementation
ESCAN00095072	ApplFbiSetModulePresence() Cannot write presence pattern to multiple memory devices with different erased values FbiKbApi@Implementation
ESCAN00095107	Compile error of generated C-structure FbiTool_Hexeditor_Hexview@Application_Exe
ESCAN00095356	Stream output: Erroneous data overflow indicated FbiLib_Mem@Implementation
ESCAN00095625	External Generator errors "BitOrder could not be resolved" GenTool_GenyVcfgNameDecorator@GenTool_Geny

ESCAN00078508 [depends on derivative] Illegal flash block table configuration cause unintended block erase	
Component@Subcomponent:	FbIDrvFlash_Rh850Rv40His@Impl_Base
First affected version:	0.90.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- If the code flash contains gaps where no flash exists and the user configure a flash block in this area, the flash driver will erase the next valid flash block (first block with start address bigger than the illegal configured block). ----- When does this happen: ----- Always and immediately ----- In which configuration does this happen: ----- all configurations, but not all derivatives ----- Note: The gap between user area and extended user area is not relevant. Until now, no known derivative is affected by this issue!	
Resolution Description: Workaround: ----- Well configured flash block table, which corresponds to the real flash block structure. ----- Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00081436	Using FlashDriver_SetResetVector() might cause exception
Component@Subcomponent:	FblDrvFlash_Rh850Rv40His@Impl_Base
First affected version:	1.02.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

When using FlashDriver_SetResetVector() an exception occurs.	
When does this happen:	

When code called from wdTriggerFct (typically FblLookForWatchdog()) is not located in RAM.	
This may apply e.g. to the Communication Wrapper task functions.	
In which configuration does this happen:	

if FLASH_ENABLE_SET_RESETVECTOR_API is enabled.	
Resolution Description:	
Workaround:	

Either manually handle memDrvDeviceActive in the updater or locate any code referenced by	
FblLookForWatchdog() in RAM	
Resolution:	

None.	

ESCAN00086590 Obsolete generated code in WrapNv_cfg.c does not compile	
Component@Subcomponent:	SysService_WrapperNv@GenTool_Geny
First affected version:	1.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Obsolete generated code in WrapNv_cfg.c does not compile, file should no longer be generated.	
When does this happen:	

Always and immediately	
In which configuration does this happen:	

Any configuration	
Resolution Description:	
Workaround:	

The C file is not needed. Do not compile this file and try to link it to your bootloader.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00090094 FblCanWakeup() does not allow to enable Can clock again	
Component@Subcomponent:	FblDrvCan_Rh850RscanCrx@Implementation
First affected version:	1.02.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

After call to FblCanSleep and wakeup call to FblCanWakeUp, no CAN communication is possible any more.	
When does this happen:	

When waking up again via FblCanWakeUp.	
In which configuration does this happen:	

Configurations that support Can low power mode (FBL_ENABLE_SLEEPMODE defined).	
Resolution Description:	

ESCAN00090094 FblCanWakeup() does not allow to enable Can clock again

Workaround:

1. Replace calls to FblCanWakeup() by calls to ApplFblCanWakeup() in user callback context.
2. Add code to ApplFblCanWakeup() to wake up again:

```
void ApplFblCanWakeup( void )
{
    /* Clear error flags */
    Can->ChCtrl[kFblCanChannel].EF &= FblInvert32Bit(kCanEfMask);

    /* Clear rx full pending buffers 0 - 31*/
    Can->CRBRCF[0] = 0;

    /* Set channel reset mode (currently in stop or reset mode) */
    CanLL_ModeReq_Phys(kFblCanChannel,kCanResetMode);
    while ((!CanLL_ModeCheck_Phys(kFblCanChannel,kCanResetMode)))
    {
        ;
    }

    /* Switch to operation mode (and wait till it is reached) */
    CanLL_ModeReq_Phys(kFblCanChannel,kCanOperationMode);

    while (!CanLL_ModeCheck_Phys(kFblCanChannel,kCanOperationModeCheck))
    {
        ;
    }
}
```

3. Define these macros so that they are available within ApplFblCanWakeup():

```
/**< Requests a on a physical channel */
#define CanLL_ModeReq_Phys(pch,mode) (Can->ChCtrl[pch].CR = ((Can->ChCtrl[pch].CR &
kCanModeMask) | (mode)))
#define CanLL_ModeCheck_Phys(pch,mode) ((Can->ChCtrl[pch].SR & kCanModeBits) == ((mode)
& kCanModeBits))
```

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00090391 GM: Calibration header cannot be generated in a way, so that all data bytes can be used**Component@Subcomponent:** FblTool_Hexeditor_Hexview@Application_Exe**First affected version:** 1.05.00**Fixed in versions:** 1.11.00**Problem Description:**

What happens (symptoms):

Wrong calibration headers are generated.

GM SLP5, SLP6 (XML based header generation):

* The calibration file header is placed before the expected (and configured) location, if not more than really necessary bytes (0x14) are left empty.

GM SLP4 (BAT - file based header generation):

* The calibration header overwrites existing data bytes, if not more than really necessary bytes (0x14) are left empty.

When does this happen:

At calibration file header generation time.

Hexview alignment value (through parameter /AD:XX) is chosen according to the (flash) memories write segment size (ALIGN_SEG_SIZE).

This does not happen, if the amount of bytes left empty is high enough. The number is high enough, if it is at minimum the smallest multiple of ALIGN_SEG_SIZE greater equal 14. If less is left empty, the issue occurs.

E.g. the issue occurs:

* if SEG_SIZE = 4 is and only 14 bytes are left empty (16 bytes need to be left empty).

* if SEG_SIZE = 64 is and only 14 bytes are left empty (64 bytes need to be left empty).

In which configuration does this happen:

If the memories write segment size and thus required alignment value is larger 2 (for internal flash this is e.g. flashdrv.h: FLASH_SEGMENT_SIZE).**Resolution Description:**

Workaround:

Leave at minimum the smallest multiple of ALIGN_SEG_SIZE (compare issue description) greater equal 14 empty at start of file.

Resolution:

The described issue is corrected by modification of all affected work-products.

The resolution allows to do correct fill using /GMAL=X feature. However, data bytes are not possible to be correctly aligned.

ESCAN00091938 Merging does not work

Component@Subcomponent: FblTool_Hexeditor_Hexview@Application_Exe

First affected version: 1.05.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Merging two files does not work.

When does this happen:

When merging two files using command line option /MT or /MO without an offset but with a range.

In which configuration does this happen:

In all configuration.

Resolution Description:

Workaround:

Specify an offset of zero.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00094695 Array gRemainderBuffer is not explicit aligned

Component@Subcomponent: FblLib_Mem@Implementation

First affected version: 1.00.00

Fixed in versions: 4.02.01

Problem Description:

What happens (symptoms):

The program flow hit an assertion in FlashDriver_WriteToFlash() (fbl_flio.c). This assertion asserts the correct alignment of the write buffer.

When does this happen:

This happens for example whenever a file with a non-aligned length is to be programmed.

In which configuration does this happen:

Always in the case the compiler/ linker does not align objects the used flash memory.

Resolution Description:

Workaround:

Align variable gRemainderBuffer from fbl_mem.c to a 32-bit boundary.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00095072	ApplFblSetModulePresence() Cannot write presence pattern to multiple memory devices with different erased values
Component@Subcomponent:	FbIKbApi@Implementation
First affected version:	1.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

ApplFblSetModulePresence() errantly returns kFblFailed when it has written a valid presence pattern. Download will be halted.	
When does this happen:	

During the validation of a block of memory down loaded to secondary device type with a different erased value than primary memory	
In which configuration does this happen:	

FBL_ENABLE_PRESENCE_PATTERN AND FBL_ENABLE_MULTIPLE_MEM_DEVICES AND FBL_FLASH_DELETED is a different value than the deleted value of the secondary device driver.	
Resolution Description:	
Workaround:	

ApplFblSetModulePresence() has to be adapted according to the erased code.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00095107 Compile error of generated C-structure**Component@Subcomponent:** FblTool_Hexeditor_Hexview@Application_Exe**First affected version:** 1.05.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

on C-File export Hexview generates

typedef struct _tFblUpdateBlkInfo

{

FBL_ADDR_TYPE blockAddress;

FBL_MEMSIZE_TYPE blockLength;

V_MEMROM0 V_MEMROM1 vuint8 V_MEMROM2 * V_MEMROM1 V_MEMROM2 blockSource;

} tFblUpdateBlkInfo;

this may lead to compiler errors on platforms where V_MEMROM2 is defined to "const" because a const inside a struct is not allowed.

When does this happen:

on C-file export

In which configuration does this happen:

if V_MEMROM2 is defined to "const" and C-File export is used**Resolution Description:**

Workaround:

replace

V_MEMROM0 V_MEMROM1 vuint8 V_MEMROM2 * V_MEMROM1 V_MEMROM2 blockSource;

by

V_MEMROM1 vuint8 V_MEMROM2 V_MEMROM3 * blockSource;

manually

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00095356 Stream output: Erroneous data overflow indicated	
Component@Subcomponent:	FbLib_Mem@Implementation
First affected version:	3.00.00
Fixed in versions:	4.02.01
Problem Description:	
What happens (symptoms):	

Download reports an error, typically NRC 0x71 (TransferDataSuspended). In case of a UDS download sequence this negative response occurs on a TransferData request.	
When does this happen:	

When downloading data which is passed to the stream output processing, e.g. delta download. Additionally the input length has to be larger than the announced output length, which is expected to be produced by the processing operation.	
In which configuration does this happen:	

When all of the following applies:	
<ul style="list-style-type: none"> - Additional run-time checks are enabled (FBL_ENABLE_SYSTEM_CHECK) - Stream output processing is enabled (FBL_MEM_ENABLE_STREAM_OUTPUT) - Processed data length is not enabled (FBL_DISABLE_PROCESSED_DATA_LENGTH) 	
Resolution Description:	
Workaround:	

Any of the following workarounds can be applied:	
<ul style="list-style-type: none"> - Disable additional run-time checks (FBL_DISABLE_SYSTEM_CHECK) - Do not download delta images which are larger than the actual target image 	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00095625 External Generator errors "BitOrder could not be resolved"	
Component@Subcomponent:	GenTool_GenyVcfgNameDecorator@GenTool_Geny
First affected version:	2.16.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

External Generators throw an error like: "BitOrder could not be resolved".	
When does this happen:	

During generation time with external generators like e.g. DrvEep_XXspi01Asr	
In which configuration does this happen:	

In all configurations with external generators that needs the BoardBitOrder Parameter.	
Resolution Description:	
Workaround:	

Create or patch the Board_pre0.arxml (within <SIP>\external\Generators\Components_Boards\Canoemu\bswmd) and add a preconfiguration of the parameter BoardBitOrder with the according value for your platform.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

2.6 Compiler Warnings

As a service we also provide the known compiler warnings. The occurrence of a compiler warning may depend on the used software module configuration and compiler settings.

Index

ESCAN00083332	Compiler warning: Wrong spelling of include SecM_Inc.h in SecM_Par.* SysService_SecModHis@GenTool_Geny
ESCAN00089241	Compiler warning: multiple warnings SysService_CryptoCv@Impl_actCLib
ESCAN00089424	Compiler warning: dead assignment to "returnValue" eliminated SysService_CryptoCv@Impl_ESLib
ESCAN00089425	Compiler warning: missing braces around initializer SysService_CryptoCv@Impl_ESLib
ESCAN00090113	Compiler Warning: Result of function-call is ignored SysService_CryptoCv@Impl_ESLib
ESCAN00090114	Compiler Warning: Assignment in condition SysService_CryptoCv@Impl_actCLib
ESCAN00093014	Compiler warning: ctc W560: possible truncation at implicit conversion to type "unsigned short int" FblDiag_SecHdr_Gm@Implementation
ESCAN00094172	Compiler warning: undefined preprocessor define SysService_WrapperNv@Implementation

ESCAN00083332		Compiler warning: Wrong spelling of include SecM_Inc.h in SecM_Par.*	
Component@Subcomponent:		SysService_SecModHis@GenTool_Geny	
First affected version:		1.03.00	
Fixed in versions:			
Problem Description:			
What happens (symptoms):			

Compiler warns for a differently spelled file name.			
When does this happen:			

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.			
In which configuration does this happen:			

Any configuration that checks the case of includes.			
Resolution Description:			
Workaround:			

If your operating system has case sensitive file names you can create a SecM_inc.h which includes a SecM_Inc.h.			
Resolution:			

The described issue is corrected by modification of all affected work-products.			

ESCAN00089241 Compiler warning: multiple warnings	
Component@Subcomponent:	SysService_CryptoCv@Impl_actCLib
First affected version:	1.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

<ul style="list-style-type: none"> - Compiler warns for possible loss of data: Check if cast is missing and if there is really a data loss due to an implicit/explicit cast on the target platform - Compiler warns for ambiguous code, parentheses recommended. 	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

Always.	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00089424 Compiler warning: dead assignment to "returnValue" eliminated	
Component@Subcomponent:	SysService_CryptoCv@Impl_ESLib
First affected version:	1.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiling file: ../../BSW/SecMod/ESLib_RSA_V15_Ver_SHA256.c	
ctc W588: ["../../BSW/SecMod/ESLib_RSA_V15_Ver_SHA256.c" 193/17] dead assignment to "returnValue" eliminated	
ctc W588: ["../../BSW/SecMod/ESLib_RSA_V15_Ver_SHA256.c" 358/17] dead assignment to "returnValue" eliminated	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

- Signature verification using RSASSA-PKCS1-v1_5 is used	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00089425 Compiler warning: missing braces around initializer	
Component@Subcomponent:	SysService_CryptoCv@Impl_ESLib
First affected version:	1.01.01
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiling file: ../../BSW/SecMod/ESLib_version.c	
ctc W542: ["../../BSW/SecMod/ESLib_version.c" 73/4] missing braces around initializer	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

In all configurations.	
Resolution Description:	
Workaround:	

Since ESLib_version.c is only used for component testing, it can be excluded from the build for integration.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00090113 Compiler Warning: Result of function-call is ignored	
Component@Subcomponent:	SysService_CryptoCv@Impl_ESLib
First affected version:	1.00.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- Compiling file: ../../BSW/SecMod/ESLib_SHA256.c ../../BSW/SecMod\ESLib_SHA256.c(71): WARNING C1420: Result of function-call is ignored ../../BSW/SecMod\ESLib_SHA256.c(180): WARNING C1420: Result of function-call is ignored When does this happen: ----- The warning is issued by the compiler during compilation of the code in case the configuration is as described below. In which configuration does this happen: ----- in all configurations	
Resolution Description: Workaround: ----- No workaround available. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00090114 Compiler Warning: Assignment in condition	
Component@Subcomponent:	SysService_CryptoCv@Impl_actCLib
First affected version:	1.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiling file: ../../BSW/SecMod/actBNReduce.c	
../../BSW/SecMod\actBNReduce.c(117): WARNING C5909: Assignment in condition	
Compiling file: ../../BSW/SecMod/actBigNum.c	
../../BSW/SecMod\actBigNum.c(234): WARNING C5909: Assignment in condition	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

in all configurations	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00093014 Compiler warning: ctc W560: possible truncation at implicit conversion to type "unsigned short int"	
Component@Subcomponent:	FblDiag_SecHdr_Gm@Implementation
First affected version:	2.00.00
Fixed in versions:	3.03.00
Problem Description:	
What happens (symptoms):	

Compiler warning: ctc W560: possible truncation at implicit conversion to type "unsigned short int"	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

in every configuration	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00094172 Compiler warning: undefined preprocessor define	
Component@Subcomponent:	SysService_WrapperNv@Implementation
First affected version:	2.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiler warns for an undefined preprocessor define (FEE_FSS_CONTROL_API).	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

In projects were not the Vector Autosar FEE is used.	
Resolution Description:	
Workaround:	

Add the following line to the config file (WrapNv_Cfg.h):	
#define FEE_FSS_CONTROL_API STD_OFF	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

3. New Issues for Information

Issues which should not have an effect on the usage of the license as the issues are relevant for use cases other than those defined in the questionnaire. The list contains issues that have been detected since the last report.

Issues listed in this section are not relevant for the use case that has been documented in the questionnaire provided to Vector. However, the issues may be relevant for other use cases. Also issues that have been accepted or are tolerated by the OEM (as defined in the questionnaire) are reported here.

No issue to be reported.

4. Report Legend

Issue Report	
Report Creation Date 2011-02-25	
Index	The ID number identifies the Issue
ESCAN0002257 Headline describes symptoms and consequences of the Issue in one sentence DrvCan baseAsr@GenTool_GeneratorGeny	
ESCAN0002257 Headline describes symptoms and consequences of the Issue in one sentence	
Component@Subcomponent: First affected version: Version fixed: Problem Description: What happens (symptoms):	Component@Subcomponent describes the group of workproducts which are composed of the source code, project documentation, User Manual and Generation Tool. The Subcomponent describes the certain affected work-product in which part of the Component the issue appears. e.g. inside of the source code (e.g. Implementation) or inside of the User Manual (e.g. Documentation) or inside of the concerning Generation Tool code.
<p>// to be removed: Describe FROM CUSTOMERS NON TECHNICAL POINT OF VIEW, - which symptoms one will get if this issue occurs? - How can the issue be seen? - if it cannot be seen, how can the customer detect it? - what happens AFTER the issue occurred? - What is the consequence, the implication?</p> <p>Consider the following questions: If the issue is TEMPORARY: Does the issue cause the malfunction once but after that ECU continues to work and probably works correctly? In which situation (ECU reset / wakeup) does the ECU recover? If the issue is PERMANENT: ECU is blocked until Watch-Dog reset. ECU blocked forever and Watch-Dog cannot help.</p> <p>When does this happen:</p> <p>// to be removed: Describe FROM CUSTOMERS NON TECHNICAL POINT OF VIEW, which circumstances, operational situations, API function calls lead to the issue. With this information the customer wants to find out, whether he is affected by this issue or not.</p> <p>Consider the following questions: When (during runtime) does the issue occur and how can the customer find the issue? (1) Always and immediately (2) Only under specific circumstances (describe them) (3) Rarely, very rarely or unlikely Can the probability of occurrence of the issue be estimated?</p> <p>In which configuration does this happen:</p> <p>// to be removed: Describe FROM CUSTOMERS POINT OF VIEW, which configurations of e.g. GenTool, database (attributes), OEM, compiler, components, ... lead to the issue.</p> <p>Resolution Description: Workaround: No workaround available.</p> <p>// to be removed: If there is a workaround available, please replace the default text. Describe FROM CUSTOMERS POINT OF VIEW, what has to be done to avoid this issue.</p> <p>Resolution: The described issue is corrected by modification of all affected workproducts.</p> <p>// to be removed: technical resolution: e.g. error is resolved in file "xyz" function "opq"</p>	<p>The First affected Version describes in which version of the Component the Issue appears first and the Version fixed describes the corrected version of the Component in which the Issue does not appear anymore.</p> <p>The Problem description expresses the Issue content, eventually impact, etc. What happens: Symptoms, consequences and/or the detection way is described. When does it happen: Ignition, trigger point of the Issue In which configuration does this happen: Dependencies to a certain functionality or another component</p> <p>The Resolution description describes a workaround, if available and the resolution of the Issue.</p>

5. Quality Management Contact

Quality Management
Productline Embedded Software (PES)

Vector Informatik GmbH
Ingersheimer Str. 24
D-70499 Stuttgart

Phone: +49 711 80670-3700
Fax: +49 711 80670-399
eMail: QualityPES@vector.com