



Clio II

Type

S/Section

XB0

X

88

## 82 MODIFICATION TO VEHICLE FAULT-FINDING CHARTS

- Engine : XXX Basic Manual : M.R. 337
- Gearbox : XXX Fault-finding Manual

## ERRATUM

In the Fault-finding manual of Workshop Repair Manual M.R. 337, section 88, page 88-24 and in Technical Note 3058A, page 88-2. :

**Programming a second infra-red (plip) key or a replacement key**

- With the ignition off, type **G04\*** and check that bargraph **9LH** is illuminated.
- Switch on the ignition.
- Type **G40\***, then the security code (4-figure code provided by Retainacar for UK Market) and validate by \* (read "**BON**" on the display).
- Switch off the ignition and type command mode **G32\***. The door motors activate.
- Press the remote control (plip) twice; the door motors will be activated once again.

The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed".

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of RENAULT.

