



| | | Type | Sub section |
|--------------------------|--|------|-------------|
| RENAULT All types | | XXX | 29 |

29 SPECIFICATION OF TOOL T.AV 1331 FOR REPLACEMENT OF DRIVESHAFT GAITER COLLAR TOOL

- Engine: XXX
 - Gearbox: XXX
- Basic manual: MR XX Section 29

To refit the driveshaft gaiter collar tool T.Av. 1331 must be used, which cancels and replaces the following tools :

- T.Av. 944
- T.Av. 1244

The kit making up tool T.Av. 1331 allows all left-hand driveshaft gaiter collars to be replaced on the gearbox side.


For information on removing and refitting the driveshaft on these vehicles, and the triaxe component on the shaft, refer to the Workshop Repair Manual for the vehicle (section 29).

DRIVESHAFT


Driveshaft Gaiter Collar


29

Use rings A, B or C depending on the type of gearbox and the diameter of the splined shaft (see table).




98046

| |  | \emptyset (mm) | L (mm) |
|----------|---|---------------------|-----------|
| A | JB JC | 26 | 118 |
| B | PK ADB | 28 | 99,5 |
| C | JB JC | 28 | 118 |



98086



98087

Méthodes - Réparation 0422

DS.1831

DI2904