



---

## 3 Chassis

### 38C

#### ANTI-LOCK BRAKING SYSTEM

ABS BOSCH 8.1

Vdiag No.: 18

Fault finding – Introduction	38C - 2
Fault finding – List and location of components	38C - 3
Fault finding – Role of components	38C - 4
Fault finding – Operating diagram	38C - 5
Fault finding – System operation	38C - 7
Fault finding – Programming	38C - 8
Fault finding – Replacement of components	38C - 9
Fault finding – Fault summary table	38C - 10
Fault finding – Interpretation of faults	38C - 11
Fault finding – Conformity check	38C - 29
Fault finding – Status summary table	38C - 31
Fault finding – Interpretation of statuses	38C - 32
Fault finding – Parameter summary table	38C - 35
Fault finding – Command summary table	38C - 36
Fault finding – Interpretation of commands	38C - 38
Fault finding – Customer complaints	38C - 43
Fault finding – Fault Finding Chart	38C - 44

---

V1

Edition Anglaise

---

"The repair procedures given by the manufacturer in this document are based on the technical specifications current when it was prepared.

All rights reserved by Renault s.a.s.

The procedures may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of Renault s.a.s.

© Renault s.a.s. 2013

### 1. SCOPE OF THIS DOCUMENT

This document presents the fault finding method applicable to all computers with the following specifications:

*Vehicle(s):* **Thalia 2 / Symbol 2, Clio II F 6**

*Function concerned:* **ABS**

*Computer name:* **ABS BOSCH 8.1**

*VDIAG No.:* **18**

### 2. PREREQUISITES FOR FAULT FINDING

#### Documentation type

**Fault finding procedures** (this document):

- Assisted fault finding (integrated into the **diagnostic tool**), Dialogys.

#### Wiring Diagrams:

- Visu-Schéma.

#### Type of diagnostic tools

- CLIP


#### Special tooling required

Special tooling required:
Diagnostic tool
Multimeter

### 3. SAFETY INSTRUCTIONS

Safety rules must be observed during any work on a component to prevent any material damage or personal injury:

- check the battery voltage to avoid incorrect operation of computer functions,
- **it is strictly forbidden to carry out a road test with the diagnostic tool communicating with the computer because the ABS (anti-lock braking system) and EBD (Electronic Braking Distribution) functions are deactivated. Braking pressure is identical on both vehicle axles (risk of a spin under heavy braking).**



0000001010

The anti-lock braking system consists of:

- four wheel speed sensors (1),
- a brake servo assembly (2),
- a brake pedal sensor (3),
- a pump assembly (4) consisting of:
  - a hydraulic pump,
  - a pressure modulation unit (eight solenoid valves),
  - a computer,
  - a pressure sensor.

### Wheel speed sensor:

Gives the speed of each of the vehicle's wheels.


Analysis of the speeds of the right-hand and left-hand wheel allows the turning direction of the vehicle to be deduced.

### Brake lights switch:

Visual indication of the brake pedal position.

It indicates whether the driver is depressing the brake pedal.

## ABS system flowchart



0000001011

1	ABS computer	6	Front wheel speed sensor
2	Brake switch	7	Rear wheel speed sensor
3	After ignition supply	8	Diagnostic socket
4	Permanent supply	9	Vehicle speed signal
5	Earth	10	Fault warning lights on the instrument panel
→	Electric circuit	→	Hydraulic circuit

On this vehicle, the main functions of the ABS are as follows:

- electronic distribution of braking between front and rear by controlling skidding of the rear wheels,
- keeping the wheels from locking by controlling skidding of the four wheels.

The **ABS** prevents the wheels from locking when braking. This function allows the vehicle to be steered under braking and ensures vehicle stability under braking.

### EBD (electronic braking distribution):

The electronic braking distribution unit optimises the brakeforce distribution between the front and rear axles. This function ensures vehicle stability under braking.

### Fault finding warning lights programming

Instrument panel warning light		Meaning
-	ABS	ABS function inoperative.
Brake faults	ABS	Electronic braking regulation and ABS function not working
Brake faults flashing at <b>2 Hz</b>	ABS flashing at <b>2 Hz</b>	ABS computer is in fault finding mode.
-	ABS flashing at <b>8 Hz</b>	Tachometer index or vehicle configuration not programmed.

### SETTINGS

#### VP001: Enter VIN.

This command permits manual entry of the vehicle's VIN into the computer.

Use this command each time the computer is replaced.

The VIN number (VF...) can be found on the manufacturer's plate on the door pillar and on the body panel under the bonnet.

#### Programming procedure:

- connect the **diagnostic tool**,
- refer to the **BOSCH 8.1 ABS** fault finding,
- select parameter **VP001**,
- enter the VIN,
- clear the computer memory using command **RZ001 Fault memory**,
- exit fault finding mode,
- switch off the ignition,
- wait for the end of powerlatch,
- on the identification screen, using **ID010 V.I.N. code**, check that the code being entered has been correctly recognised.

#### VP004: Vehicle parameters.

This command allows you to identify the vehicle on which the computer is installed.

Using **PR063 Vehicle parameters**, check that the parameters have been correctly recognised.

#### VP006: Enter last APV\* operation date.

Whenever the ABS system is worked on in the shop, the date must be entered.

**Select command VP006 on the diagnostic tool.**

Enter the service date using the **diagnostic tool** keypad.

Using **ID020 Read last After-Sales operation date**, check that the date has been entered.

#### VP007: Tachometric index.

This command is used to program the computer memory with the index required to calculate vehicle speed from the speed at which the tyres fitted on the vehicle turn.

**Command VP007 is only used to stop the ABS warning light flashing after the computer has been replaced.**

Using **PR030 Tachometric index**, check that the index has been entered correctly.

APV\*: After-Sales



### Replacing the computer

When replacing the computer, apply the following procedure:

- **switch off the ignition,**
- **disconnect the battery,**
- **replace the computer,**
- **configure the vehicle parameters with command VP004 "Vehicle parameters",**
- **enter the VIN using command VP001 Write VIN,**
- **configure the tachometric index with command VP007 "Tachometric index",**
- **perform a road test followed by a fault reading to confirm that the system is operating correctly.**

Tool fault	Associated DTC	Diagnostic tool title
<b>DF001</b>	50CC	Computer supply
<b>DF006</b>	501F	Front left-hand wheel speed sensor circuit
<b>DF007</b>	503F	Rear left-hand wheel speed sensor circuit
<b>DF017</b>	50C3	Computer
<b>DF020</b>	50C3	Tachometric index programming
<b>DF026</b>	500F	Front right-hand wheel speed sensor circuit
<b>DF027</b>	502F	Rear right-hand wheel speed sensor circuit
<b>DF063</b>	5046	Wheel speed inconsistency

<b>DF001 PRESENT OR STORED</b>	<b><u>COMPUTER SUPPLY VOLTAGE</u></b> 1.DEF: Below minimum threshold 2.DEF: Above maximum threshold 3.DEF: Abnormal voltage
--	--

<b>NOTES</b>	<b>Special notes:</b> The fault is declared <b>present</b> during a road test at a vehicle speed > 6 mph (10 km/h).
	<b>Conditions for applying the fault finding procedure to stored faults:</b> Apply the fault finding procedure if the fault is <b>present</b> or <b>stored</b> .
	Use <b>Wiring Diagrams Technical Note for Thalia 2 / Symbol 2, Clio II F 6</b> .

Check the condition and position of the ABS fuses, **F01 (50A)** and **F10 (25A)** in the engine fuse and relay box, component code **710** (see **MR 423, Mechanical, 81C, Fuses, Fuses: List and location of components**).

Check the condition and position of the ABS fuse **F24 (10 A)** in the passenger compartment fuse box, component code **1016** (see **MR 423 or 430, Mechanical, 81C, Fuses, Fuses: List and location of components**).

Check the **continuity** between fuses **F01** and **F10** and connections **BP14** and **BP8** of the ABS computer connector, component code **721 (for BURSA)** or **118 (for MERCOSUR)** (presence of + **before ignition feed** on the connections).

Check the **continuity** between the passenger compartment fuse **F24** and connection **AP5** of the ABS computer, component code **721 (for BURSA)** or **118 (for MERCOSUR)** (presence of + **after ignition feed** on the connection).

If the connection or connections are faulty and there is a repair procedure (see **Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair**), repair the wiring, otherwise replace it.

Check that the battery terminals are in good condition and properly tightened, component code **107**.

Check the connections on the ABS computer connector, component code **721 (for BURSA)** or **118 (for MERCOSUR)**.

If the connector is faulty and there is a repair method (see **Technical Note 6015A, Repairing electrical wiring, Wiring: Precautions for repair**), repair the connector, otherwise replace the wiring.

Check the **earths** on connections **MAH** of the ABS computer, component code **721 (for BURSA)** or **118 (for MERCOSUR)**.

If the connection or connections are faulty and there is a repair procedure (see **Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair**), repair the wiring, otherwise replace it.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

### DF001 CONTINUED

Clear the computer memory using command **RZ001 Fault memory**, exit fault finding and switch off the ignition. Carry out a new check using the **diagnostic tool**.

If the fault is still present, contact the Techline.

### AFTER REPAIR

Clear the computer memory using command **RZ001 Fault memory**. Carry out a road test followed by another check with the **diagnostic tool**.

<b>DF006 PRESENT OR STORED</b>	<b><u>FRONT LEFT-HAND WHEEL SPEED SENSOR CIRCUIT</u></b> CO.0: Open circuit or short circuit to earth 1.DEF: Magnetic/mechanical target fault
--	---

<b>NOTES</b>	<b>Special notes:</b> The fault is declared <b>present</b> during a road test at a vehicle speed > 6 mph (10 km/h).
	<b>Conditions for applying the fault finding procedure to stored faults:</b> Apply the fault finding procedure if the fault is <b>present</b> or <b>stored</b> .
	Use <b>Wiring Diagrams Technical Note for Thalia 2 / Symbol 2, Clio II F 6</b> .

<b>CO.0</b>	<b>NOTES</b>	<b>Special notes:</b> Command <b>AC013 Wheel speed sensor supply test</b> , must be used only once.
-------------	--------------	--

Check the connection and condition of the connections of the front left-hand wheel speed sensor, component code **153**.

If the connector is faulty and there is a repair method (see **Technical Note 6015A, Repairing electrical wiring, Wiring: Precautions for repair**), repair the connector, otherwise replace the wiring.

Disconnect the sensor, use command **AC013 Wheel speed sensor supply test** and check that pulses of voltage of approximately **12 V** are detected by a multimeter at the sensor connector terminals on the computer side.

**Are the pulses present?**

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

<p><b>DF006</b> <b>CONTINUED 1</b></p>	
<p><b>YES</b></p>	<p>If pulses are detected, the front left-hand wheel speed sensor is defective, replace the sensor.</p>
<p><b>NO</b></p>	<p>Check the connection and condition of the ABS computer connections, component code <b>721 (for BURSA) or 118 (for MERCOSUR)</b>. If the connector is faulty and there is a repair method (see <b>Technical Note 6015A, Repairing electrical wiring, Wiring: Precautions for repair</b>), repair the connector, otherwise replace the wiring. Check and ensure <b>the continuity</b> of the following connections: – <b>4E</b> between components <b>153</b> and <b>721 (for BURSA) or 118 (for MERCOSUR)</b>, – <b>4C</b> between components <b>153</b> and <b>721 (for BURSA) or 118 (for MERCOSUR)</b>. Also check <b>the insulation</b> between these two connections. If the connection or connections are faulty and there is a repair procedure (see <b>Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair</b>), repair the wiring, otherwise replace it. If the fault is still present, contact the Techline.</p>
<p><b>AFTER REPAIR</b></p>	<p>Clear the computer memory using command <b>RZ001 Fault memory</b>. Carry out a road test followed by another check with the <b>diagnostic tool</b>.</p>

DF006  
CONTINUED 2

1.DEF

NOTES

None.

Check the connection and condition of the connections of the front left-hand wheel speed sensor, component code **153**.

If the connector is faulty and there is a repair method (see **Technical Note 6015A, Repairing electrical wiring, Wiring: Precautions for repair**), repair the connector, otherwise replace the wiring.

Visually inspect the condition of the target and sensor (for dirt, metallic contamination, bearing grease, etc.), and clean using compressed air if necessary.

If there is a lot of grease on the target, contact the Techline.

Check that the wheel speed sensor mounting is in good condition (correct clipping).

Check the conformity of the target (condition, number of teeth = **48** or **44** depending on the version) with the specific command **SC001 Check target teeth**.

If the checks are correct:

- clear the computer fault memory using the command **RZ001 Fault memory**,
- exit fault finding mode, switch off the ignition and carry out a road test.

Replace the instrumented bearing if the fault recurs.

If the fault is still present, contact the Techline.

## AFTER REPAIR

Clear the computer memory using command **RZ001 Fault memory**.  
Carry out a road test followed by another check with the **diagnostic tool**.

<b>DF007 PRESENT OR STORED</b>	<u>REAR LEFT-HAND WHEEL SPEED SENSOR CIRCUIT</u> CO.0: Open circuit or short circuit to earth 1.DEF: Magnetic/mechanical target fault
--	---

<b>NOTES</b>	<b>Special notes:</b> The fault is declared <b>present</b> during a road test at a vehicle speed > 6 mph (10 km/h).
	<b>Conditions for applying the fault finding procedure to stored faults:</b> Apply the fault finding procedure if the fault is <b>present</b> or <b>stored</b> .
	Use <b>Wiring Diagrams Technical Note for Thalia 2 / Symbol 2, Clio II F 6</b> .

<b>CO.0</b>	<b>NOTES</b>	<b>Special notes:</b> Command <b>AC013 Wheel speed sensor supply test</b> , must be used only once.
-------------	--------------	--

Check the connection and condition of the connections of the rear left-hand wheel speed sensor, component code **151**.

If the connector is faulty and there is a repair method (see **Technical Note 6015A, Repairing electrical wiring, Wiring: Precautions for repair**), repair the connector, otherwise replace the wiring.

Disconnect the sensor, use command **AC013 Wheel speed sensor supply test** and check that pulses of voltage of approximately **12 V** are detected by a multimeter at the sensor connector terminals on the computer side.

**Are the pulses present?**

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--



<p><b>DF007</b> <b>CONTINUED 1</b></p>	
<p><b>YES</b></p>	<p>If pulses are detected, the rear left-hand wheel speed sensor is defective, replace the sensor.</p>
<p><b>NO</b></p>	<p>Check the connection and condition of the ABS computer connections, component code <b>721 (for BURSA) or 118 (for MERCOSUR)</b>. If the connector is faulty and there is a repair method (see <b>Technical Note 6015A, Repairing electrical wiring, Wiring: Precautions for repair</b>), repair the connector, otherwise replace the wiring. Check the <b>continuity</b> and <b>insulation</b>, and the <b>absence of interference resistance</b> on the following connections: – <b>4G</b> between components <b>151</b> and <b>721 (for BURSA) or 118 (for MERCOSUR)</b>, – <b>4H</b> between components <b>151</b> and <b>721 (for BURSA) or 118 (for MERCOSUR)</b>. If the connection or connections are faulty and there is a repair procedure (see <b>Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair</b>), repair the wiring, otherwise replace it. If the fault is still present, contact the Techline.</p>
<p><b>AFTER REPAIR</b></p>	<p>Clear the computer memory using command <b>RZ001 Fault memory</b>. Carry out a road test followed by another check with the <b>diagnostic tool</b>.</p>

<p><b>DF007</b> <b>CONTINUED 2</b></p>	
--	--

<p><b>1.DEF</b></p>	<p><b>NOTES</b></p>	<p>None.</p>
---------------------	---------------------	--------------

Visually inspect the condition of the target and sensor (for dirt, metallic contamination, bearing grease, etc.), and clean using compressed air if necessary.  
If there is a lot of grease on the target, contact the Techline.  
Check that the wheel speed sensor mounting is in good condition.  
Check the conformity of the target (condition, number of teeth = **48** or **44** depending on the version) with the specific command **SC001 Check target teeth**.

If the checks are correct:  
– clear the computer fault memory using the command **RZ001 Fault memory**,  
– exit fault finding mode, switch off the ignition and carry out a road test.  
Replace the instrumented bearing if the fault recurs.  
If the fault is still present, contact the Techline.

<p><b>AFTER REPAIR</b></p>	<p>Clear the computer memory using command <b>RZ001 Fault memory</b>. Carry out a road test followed by another check with the <b>diagnostic tool</b>.</p>
----------------------------	--

<b>DF017 PRESENT OR STORED</b>	<u>COMPUTER</u> 1.DEF: Supply fault or internal electrical fault 2.DEF: Invalid programming / initialisation
--	--

<b>NOTES</b>	<b>Special notes:</b> The fault is <b>present</b> when the ignition is switched on.
	<b>Conditions for applying the fault finding procedure to stored faults:</b> Apply the fault finding procedure if the fault is <b>present</b> or <b>stored</b> .
	Use <b>Wiring Diagrams Technical Note for Thalia 2 / Symbol 2, Clio II F 6</b> .

<b>1.DEF</b>	<b>NOTES</b>	None.
		<b>Conditions for applying the fault finding procedure to stored faults:</b> Apply the fault finding procedure whether the fault is <b>present</b> or <b>stored</b>

Check the condition and position of ABS power fuses **F01 (50 A)** and **F10 (25 A)**, in the engine compartment connection unit, component code **710** (see **MR 423** or **430, Mechanical, 81C, Fuses, Fuses: List and location of components**).

Check the **continuity** between fuses **F01** and **F10** and connections **BP14** and **BP8** of the computer connector, component code **721 (for BURSA)** or **118 (for MERCOSUR)** (presence of **+** before ignition feed on the connections).

Check that the battery terminals are in good condition and properly tightened, component code **107**.

Check the connections on the ABS computer connector, component code **721 (for BURSA)** or **118 (for MERCOSUR)**.

If the connector is faulty and there is a repair method (see **Technical Note 6015A, Repairing electrical wiring, Wiring: Precautions for repair**), repair the connector, otherwise replace the wiring.

Check the **earths** on connections **MAH** of component **721 (for BURSA)** or **118 (for MERCOSUR)**.

If the connection or connections are faulty and there is a repair procedure (see **Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair**), repair the wiring, otherwise replace it.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

### DF017 CONTINUED

Clear the computer memory using command **RZ001 Fault memory**, exit fault finding and switch off the ignition. Carry out a new check using the **diagnostic tool**.

If the fault is still present, contact the Techline.

2.DEF

**NOTES**

None.

Use command **VP004 Vehicle parameters** on the **fault finding tool** to define the appropriate version for the vehicle type. **You must select the version that corresponds to the vehicle type.** Check that the vehicle parameters are included in the parameter **PR063 Vehicle parameters**.

If the fault is still present, contact the Techline.

### AFTER REPAIR

Clear the computer memory using command **RZ001 Fault memory**. Carry out a road test followed by another check with the **diagnostic tool**.

<p><b>DF020 PRESENT</b></p>	<p><u>TACHOMETRIC INDEX PROGRAMMING</u></p>
<p><b>NOTES</b></p>	<p>None.</p>
<p>The <b>ABS BOSCH 8.1</b> computer with "tachometric function" must have an index value in order to calculate the vehicle speed from the speed at which the tyres turn. Use command <b>VP007 Tachometric index</b> and check that it has been taken into account using parameter <b>PR030 Tachometric index</b>.</p>	
<p>If the fault is still present, contact the Techline.</p>	

<p><b>AFTER REPAIR</b></p>	<p>Clear the computer memory using command <b>RZ001 Fault memory</b>. Carry out a road test followed by another check with the <b>diagnostic tool</b>.</p>
----------------------------	--

<b>DF026 PRESENT OR STORED</b>	<u>FRONT RIGHT-HAND WHEEL SPEED SENSOR CIRCUIT</u> CO.0: Open circuit or short circuit to earth 1.DEF: Magnetic/mechanical target fault
--	---

<b>NOTES</b>	<b>Special notes:</b> The fault is declared <b>present</b> during a road test at a vehicle speed > 6 mph (10 km/h).
	<b>Conditions for applying the fault finding procedure to stored faults:</b> Apply the fault finding procedure if the fault is <b>present</b> or <b>stored</b> .
	Use <b>Wiring Diagrams Technical Note for Thalia 2 / Symbol 2, Clio II F 6</b> .

<b>CO.0</b>	<b>NOTES</b>	<b>Special notes:</b> Command <b>AC013 Wheel speed sensor supply test</b> , must be used only once.
-------------	--------------	--

Check the connection and the condition of the connections of the front right-hand wheel speed sensor, component code **152**. If the connector is faulty and there is a repair method (see **Technical Note 6015A, Repairing electrical wiring, Wiring: Precautions for repair**), repair the connector, otherwise replace the wiring.  
 Disconnect the sensor, use command **AC013 Wheel speed sensor supply test** and check that pulses of voltage of approximately **12 V** are detected by a multimeter at the sensor connector terminals on the computer side.  
**Are the pulses present?**

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

<p><b>DF026</b> <b>CONTINUED 1</b></p>	
<p><b>YES</b></p>	<p>If pulses are detected, the front right-hand wheel speed sensor is defective, replace the sensor.</p>
<p><b>NO</b></p>	<p>Check the connection and condition of the ABS computer connections, component code <b>721 (for BURSA) or 118 (for MERCOSUR)</b>. If the connector is faulty and there is a repair method (see <b>Technical Note 6015A, Repairing electrical wiring, Wiring: Precautions for repair</b>), repair the connector, otherwise replace the wiring.</p> <p>Check and ensure the continuity of the following connections:</p> <ul style="list-style-type: none"> <li>– <b>4M</b> between components <b>152</b> and <b>721 (for BURSA) or 118 (for MERCOSUR)</b>,</li> <li>– <b>4N</b> between components <b>152</b> and <b>721 (for BURSA) or 118 (for MERCOSUR)</b>.</li> </ul> <p>Also check the insulation between these two connections. If the connection or connections are faulty and there is a repair procedure (see <b>Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair</b>), repair the wiring, otherwise replace it. If the fault is still present, contact the Techline.</p>
<p><b>AFTER REPAIR</b></p>	<p>Clear the computer memory using command <b>RZ001 Fault memory</b>. Carry out a road test followed by another check with the <b>diagnostic tool</b>.</p>

<b>DF026 CONTINUED 2</b>	
------------------------------	--

<b>1.DEF</b>	<b>NOTES</b>	None.
--------------	--------------	-------

Visually inspect the condition of the target and sensor (for dirt, metallic contamination, bearing grease, etc.), and clean using compressed air if necessary.

If there is a lot of grease on the target, contact the Techline.

Check that the wheel speed sensor mounting is in good condition (correct clipping).

Check the conformity of the target (condition, number of teeth = **48** or **44** depending on the version) with the specific command **SC001 Check target teeth**.

If the checks are correct:

- clear the computer fault memory using the command **RZ001 Fault memory**,
- exit fault finding mode, switch off the ignition and carry out a road test.

Replace the instrumented bearing if the fault recurs.

If the fault is still present, contact the Techline.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--



<b>DF027 PRESENT OR STORED</b>	<u>REAR RIGHT-HAND WHEEL SPEED SENSOR CIRCUIT</u> CO.0: Open circuit or short circuit to earth 1.DEF: Magnetic/mechanical target fault
--	--

<b>NOTES</b>	<b>Special notes:</b> The fault is declared <b>present</b> during a road test at a vehicle speed > 6 mph (10 km/h).
	<b>Conditions for applying the fault finding procedure to stored faults:</b> Apply the fault finding procedure if the fault is <b>present</b> or <b>stored</b> .
	Use <b>Wiring Diagrams Technical Note for Thalia 2 / Symbol 2, Clio II F 6</b> .

<b>CO.0</b>	<b>NOTES</b>	<b>Special notes:</b> Command <b>AC013</b> Wheel speed sensor supply test, must be used only once.
-------------	--------------	---

Check the connection and the condition of the connections of the rear right-hand wheel speed sensor, component code **150**.

If the connector is faulty and there is a repair method (see **Technical Note 6015A, Repairing electrical wiring, Wiring: Precautions for repair**), repair the connector, otherwise replace the wiring.

Disconnect the sensor, use command **AC013** Wheel speed sensor supply test and check that pulses of voltage of approximately **12 V** are detected by a multimeter at the sensor connector terminals on the computer side.

**Are the pulses present?**

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001</b> Fault memory. Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	---

<p><b>DF027</b> <b>CONTINUED 1</b></p>	
<p><b>YES</b></p>	<p>If pulses are detected, the rear right-hand wheel speed sensor is defective, replace the sensor.</p>
<p><b>NO</b></p>	<p>Check the connection and condition of the ABS computer connections, component code <b>721 (for BURSA) or 118 (for MERCOSUR)</b>. If the connector is faulty and there is a repair method (see <b>Technical Note 6015A, Repairing electrical wiring, Wiring: Precautions for repair</b>), repair the connector, otherwise replace the wiring.</p> <p>Check and ensure the continuity of the following connections: – <b>4S</b> between components <b>150</b> and <b>721 (for BURSA) or 118 (for MERCOSUR)</b>, – <b>4T</b> between components <b>150</b> and <b>721 (for BURSA) or 118 (for MERCOSUR)</b>. Also check the insulation between these two connections. If the connection or connections are faulty and there is a repair procedure (see <b>Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair</b>), repair the wiring, otherwise replace it.</p> <p>If the fault is still present, contact the Techline.</p>
<p><b>AFTER REPAIR</b></p>	<p>Clear the computer memory using command <b>RZ001 Fault memory</b>. Carry out a road test followed by another check with the <b>diagnostic tool</b>.</p>

DF027  
CONTINUED 2

1.DEF

## NOTES

None.

Visually inspect the condition of the target and sensor (for dirt, metallic contamination, bearing grease, etc.), and clean using compressed air if necessary.  
If there is a lot of grease on the target, contact the Techline.  
Check that the wheel speed sensor mounting is in good condition.  
Check the conformity of the target (condition, number of teeth = **48** or **44** depending on the version) with the specific command **SC001 Check target teeth**.

If the checks are correct:

- clear the computer fault memory using the command **RZ001 Fault memory**,
  - exit fault finding mode, switch off the ignition and carry out a road test.
- Replace the instrumented bearing if the fault recurs.

If the fault is still present, contact the Techline.

## AFTER REPAIR

Clear the computer memory using command **RZ001 Fault memory**.  
Carry out a road test followed by another check with the **diagnostic tool**.

<b>DF063 PRESENT OR STORED</b>	<u>WHEEL SPEED CONSISTENCY</u> 1.DEF: Interference
--	---

<b>NOTES</b>	<b>Priorities when dealing with a number of faults:</b> Deal with faults <b>DF006 Front left-hand wheel speed sensor circuit</b> , <b>DF007 Rear left-hand wheel speed sensor circuit</b> , <b>DF026 Front right-hand wheel speed sensor circuit</b> and <b>DF027 Rear right-hand wheel speed sensor circuit</b> first even if they are stored.
	<b>Conditions for applying the fault finding procedure to stored faults:</b> The fault is declared <b>present</b> during a road test.

Check the condition of the braking system (condition of linings, sealing, grating, bleed, etc.).  
 Check the condition of the axles and the conformity and good condition of the tyre mountings.  
 Check how well the wheel speed sensors are fitted (correct clipping).  
 Repair if necessary.

If the fault is still present, contact the Techline.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

**NOTES**Only carry out a conformity check after a **complete check** with the **diagnostic tool**.

Function	Parameter or Status Check or Action	Display and notes	Fault finding
Diagnostic tool dialogue		ABS BOSCH 8.1	See the interpretation of <b>ALP1</b> <b>No dialogue with the ABS computer</b>
Vehicle parameters	<b>PR063:</b> Vehicle parameters	Check that the parameters are consistent with the vehicle on which fault finding is being run.	VP004 Vehicle parameters
Brake pedal not depressed detection	<b>ET017:</b> Brake pedal	<b>Released</b> status confirmed, brake pedal not depressed	<b>In the event of a fault</b> , apply the interpretation of status <b>ET017</b>
Depressed brake pedal detection	<b>ET017:</b> Brake pedal	<b>Depressed</b> status, brake pedal depressed	
Computer supply	<b>PR005:</b> Computer feed voltage	Ensure that the battery voltage is correct (check the charge circuit if necessary)	<b>In the event of a fault</b> , apply the interpretation of fault <b>DF001 Computer supply voltage</b> .
Vehicle speed	<b>PR038:</b> Vehicle speed	Ensure that the vehicle speed is consistent	<b>In the event of a fault</b> , apply the interpretation of fault <b>DF063 Wheel speed consistency</b>

**NOTES**Only carry out a conformity check after a **complete check** with the **diagnostic tool**.

Function	Parameter or Status Check or Action	Display and notes	Fault finding
Wheel speed	<b>PR001:</b> Front right-hand wheel speed	Ensure that the wheel speed is consistent	<b>In the event of a fault</b> , refer to the interpretation of fault <b>DF026 Front right-hand wheel speed sensor circuit</b>
	<b>PR002:</b> Front left-hand wheel speed	Ensure that the wheel speed is consistent	<b>In the event of a fault</b> , refer to the interpretation of fault <b>DF006 Front left-hand wheel speed sensor circuit</b>
	<b>PR003:</b> Rear right-hand wheel speed	Ensure that the wheel speed is consistent	<b>In the event of a fault</b> , refer to the interpretation of fault <b>DF027 Rear right-hand wheel speed sensor circuit</b>
	<b>PR004:</b> Rear left-hand wheel speed	Ensure that the wheel speed is consistent	<b>In the event of a fault</b> , refer to the interpretation of fault <b>DF007 Rear left-hand wheel speed sensor circuit</b>

Tool status	Diagnostic tool title
ET017	Brake pedal

**ET017**

### BRAKE PEDAL

#### NOTES

#### Special notes:

Carry out the checks only if the **depressed** and **released** statuses are not consistent with the pedal position.

Use **Wiring Diagrams Technical Note for Thalia 2 / Symbol 2, Clio II F 6**.

**STATUS "Released" Brake pedal depressed.**

#### If the brake lights are working:

- Check and ensure the continuity of connection 65A between the connector of the brake light switch, component code **160** and the connector of the ABS computer, component code **721 (for BURSA) or 118 (for MERCOSUR)**.

If the connection is faulty and if there is a repair procedure (see **Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair**), repair the wiring, otherwise replace it.

#### If the brake lights are not working:

- Check the condition and fitting of the brake light switch and fuse **F4 (15A)** of the brake lights.
- Remove and test the operation of the brake light switch:

	Continuity <b>between the following connections:</b>	Insulation between the following connections:
Switch pressed (Brake pedal released)	<b>5A and AP10</b>	<b>65A and AP10</b>
Switch released (Brake pedal depressed)	<b>65A and AP10</b>	<b>5A and AP10</b>

#### AFTER REPAIR

Clear the computer memory using command **RZ001 Fault memory**.  
Carry out a road test followed by another check with the **diagnostic tool**.



**ET017**  
**CONTINUED 1**

If the connection or connections are faulty and there is a repair procedure (see **Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair**), repair the wiring, otherwise replace it.

- Replace the switch if necessary.
- Check and ensure the presence of **+ after ignition feed** on connection **AP10** on the brake light switch connector, component code **160**.

If the connection is faulty and if there is a repair procedure (see **Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair**), repair the wiring, otherwise replace it.

**AFTER REPAIR**

Clear the computer memory using command **RZ001 Fault memory**.  
Carry out a road test followed by another check with the **diagnostic tool**.

ET017  
CONTINUED 2**Depressed STATUS: Brake pedal released.**

- Check the condition and fitting of the brake light switch and fuse **F4 (15A)** of the brake lights.
- Remove and test the operation of the brake light switch:

	Continuity <b>between the following connections:</b>	<b>Insulation</b> between the following connections:
Switch depressed (Brake pedal released)	<b>5A and AP10</b>	<b>65A and AP10</b>
Switch released (Brake pedal depressed)	<b>65A and AP10</b>	<b>5A and AP10</b>

If the connection or connections are faulty and there is a repair procedure (see **Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair**), repair the wiring, otherwise replace it.

Check and ensure the **insulation to + 12V** of connection **65A** between the connector of the brake light switch, component code **160** and the connector of the ABS computer, component code **721 (for BURSA) or 118 (for MERCOSUR)**.

If the fault is still present, contact the Techline.

**AFTER REPAIR**

Clear the computer memory using command **RZ001 Fault memory**.  
Carry out a road test followed by another check with the **diagnostic tool**.

# ANTI-LOCK BRAKING SYSTEM

## Fault finding – Parameter summary table

**38C**

Tool Parameter	Diagnostic tool title	Comments
<b>PR001</b>	Front right-hand wheel speed	These parameters indicate the speed in <b>mph (km/h)</b> of each wheel on the vehicle.
<b>PR002</b>	Front left-hand wheel speed	
<b>PR003</b>	Rear right-hand wheel speed	
<b>PR004</b>	Rear left-hand wheel speed	
<b>PR005</b>	Computer feed voltage	This parameter indicates the computer supply voltage in <b>volts</b> .
<b>PR030</b>	Tachometric index	This parameter specifies the tachometric index entered in the computer for the tyres fitted to the vehicle.
<b>PR038</b>	Vehicle speed	This parameter indicates the vehicle speed in <b>mph (km/h)</b> .
<b>PR063</b>	Vehicle parameters	This parameter shows whether the configuration ( <b>VP004 Vehicle parameters</b> ) matches the vehicle undergoing fault finding

# ANTI-LOCK BRAKING SYSTEM

## Fault finding – Command summary table

**38C**

Tool command	Diagnostic tool title	Comments
<b>RZ001</b>	Fault memory	This command is used to clear the faults <b>stored</b> in the computer.
<b>AC003</b>	Front left-hand wheel solenoid valves	See interpretation of command <b>AC003</b> .
<b>AC004</b>	Front right-hand wheel solenoid valves	See interpretation of command <b>AC004</b> .
<b>AC005</b>	Rear left-hand wheel solenoid valves	See interpretation of command <b>AC005</b> .
<b>AC006</b>	Rear right-hand wheel solenoid valves	See interpretation of command <b>AC006</b> .
<b>AC013</b>	Wheel speed sensor supply test	See interpretation of command <b>AC013</b> .
<b>AC016</b>	Pump motor test	See interpretation of command <b>AC016</b> .

# ANTI-LOCK BRAKING SYSTEM

## Fault finding – Command summary table

**38C**

Tool command	Diagnostic tool title	Comments
<b>SC001</b>	Check target teeth	This command tests the condition of the teeth on each wheel. Select the command <b>SC001</b> and follow the instructions. The test result should be equal to <b>48</b> or <b>44 teeth</b> depending on the version.
<b>SC006</b>	Bleed the hydraulic unit and brake circuits.	This command must be used only in the event of abnormal lengthening of brake pedal travel during a road test with ABS regulation (the vehicle must have already been bled using the conventional procedure). Select command <b>SC006</b> and follow the instructions given by <b>the diagnostic tool</b> .

**AC003**  
**AC004**  
**AC005**  
**AC006**

FRONT LEFT-HAND WHEEL SOLENOID VALVES  
FRONT RIGHT-HAND WHEEL SOLENOID VALVES  
REAR LEFT-HAND WHEEL SOLENOID VALVES  
REAR RIGHT-HAND WHEEL SOLENOID VALVES

### NOTES

#### Conditions of use of the command:

Ignition on, engine stopped and vehicle speed zero.

Before running the commands, check that the battery is properly charged (see **80A, Battery, Battery: Customer complaints**).

These commands test the solenoid valves on each wheel.

#### Controlling the wheel solenoid valves to check the hydraulic system

Lift the vehicle in order to be able to check that the wheels turn freely. Keep the brake pedal depressed to prevent the wheel being tested from being turned by hand (do not brake so firmly that full braking power is reached).

Select and confirm the command of the wheel being examined (e.g. Front left-hand wheel solenoid valves, etc.).

Turn the wheel concerned by hand; you should see it go through the locking/unlocking cycles.

### AFTER REPAIR

Clear the computer memory using command **RZ001 Fault memory**.  
Carry out a road test followed by another check with the **diagnostic tool**.

<b>AC013</b>	<u>WHEEL SPEED SENSOR SUPPLY TEST</u>
--------------	---------------------------------------

<b>NOTES</b>	<b>Conditions of use of the command:</b> Ignition on, engine stopped and vehicle speed zero.
	Before running the command, check that the battery is properly charged (see <b>80A, Battery, Battery: Customer complaints</b> ). You must use command <b>AC013</b> once only.

This command is used to check that voltage pulses of approximately **12 V** are detected on the faulty sensor by a **multimeter** on the connector terminals on the computer side, component codes **150, 151, 152, and 153**.  
Select the command **AC013**.

**Note:**

To restart an **AC013 command**, restart then stop the vehicle engine and ensure that the battery is properly charged.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

<b>AC016</b>	<u>PUMP MOTOR TEST</u>
--------------	------------------------

<b>NOTES</b>	<b>Conditions of use of the command:</b> Ignition on, engine stopped and vehicle speed zero.
	Before running the command, check that the battery is properly charged (see <b>80A, Battery, Battery: Customer complaints</b> ).

This command is used to test the pump motor control circuit.  
Select the command **AC016**.  
The motor must run for **5 seconds**.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--



<b>SC001</b>	<u>CHECK THE TARGET TEETH</u>
--------------	-------------------------------

<b>NOTES</b>	<b>Conditions of use of the command:</b> Ignition on, engine stopped and vehicle speed zero.
	Before running the command, check that the battery is properly charged (see <b>80A, Battery, Battery: Customer complaints</b> ).

This command is used to check the number of teeth on the target.  
 Select the command **SC001**.  
 The test result should be equal to **48** or **44 teeth** depending on the version.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

<b>SC006</b>	<u>BLEEDING THE HYDRAULIC UNIT AND BRAKE CIRCUITS</u>
--------------	---

<b>NOTES</b>	<b>Conditions of use of the command:</b> Ignition on, engine stopped and vehicle speed zero.
	Before running the command, check that the battery is properly charged (see <b>80A, Battery, Battery: Customer complaints</b> ).

This command must be used only in the event of abnormal lengthening of brake pedal travel during a road test with ABS regulation (the vehicle must have already been bled using the conventional procedure).  
 Select command **SC006** and follow the instructions given by **the diagnostic tool**.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

### NOTES

Only consult these customer complaints after a **complete check** with the **diagnostic tool**.

### FAULTS DETECTED WHEN BRAKING WITH ABS CONTROL

Locking of one or more wheels	→	ALP2
Pull	→	ALP3
Drift	→	ALP4
Unexpected ABS operation at low speed and with slight pedal pressure	→	ALP5
Unexpected ABS system intervention on a poor road surface	→	ALP6
Unexpected ABS operation when using special equipment (car phone, CB.)	→	ALP7
Extension of brake pedal travel following a regulation phase (with an irregular pedal when entering regulation).	→	ALP8
Spongy pedal	→	ALP9
Brake pedal vibration	→	ALP10
Noise from the pump, pipes or hydraulic unit	→	ALP11

### OTHER CASES


No dialogue with the ABS computer	→	ALP1
-----------------------------------	---	------

<b>ALP1</b>	<b>No dialogue with the ABS computer</b>
-------------	--

<b>NOTES</b>	Use <b>Wiring Diagrams Technical Note for Thalia 2 / Symbol 2, Clio II F 6.</b>
--------------	---

Try to establish dialogue with a computer on another vehicle to check that **the diagnostic tool** is not faulty. If the tool is not causing the fault and dialogue cannot be established with any other computer on the same vehicle, it may be that a faulty computer is disrupting fault finding line **HK**.  
Use a process of successive disconnections to locate this computer.  
Check the battery voltage and carry out the necessary operations to obtain a correct voltage between **9.8 V < X < 16.7 V**.

Check the presence and condition of the ABS fuses on the passenger compartment fuse box, component code **1016, F24 (10A)** and in the engine fuse box, component code **710, F01 (50A)** and **F10 (25A)**, (see **MR 423 Mechanical, 81C, Fuses, Fuses: List and location of components**).  
Check the connection of the ABS computer connector, component code **721 (for BURSA)** or **118 (for MERCOSUR)** and the condition of its connections.  
If the connector is faulty and there is a repair method (see **Technical Note 6015A, Repairing electrical wiring, Wiring: Precautions for repair**), repair the connector, otherwise replace the wiring.  
Check the **earths** on connections **MAH** of component **721 (for BURSA)** or **118 (for MERCOSUR)** (quality, oxidation, tightness of the earth bolt on top of the ABS unit).  
Check that the supply to the computer is correct:  
– **Earth** on connections **MAH** of component **721 (for BURSA)** or **118 (for MERCOSUR)**,  
– **+ before ignition feed** on connections **BP14** and **BP8** of component **721 (for BURSA)** or **118 (for MERCOSUR)**,  
– **+ after ignition feed** on connection **AP5** of component **721 (for BURSA)** or **118 (for MERCOSUR)**.  
  
If the connection or connections are faulty and there is a repair procedure (see **Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair**), repair the wiring, otherwise replace it.  
Check the connection of the diagnostic socket connector, component code **225** and the condition of its connections.  
Check the **continuity** of connection **HL** and **HK** between the computer and the diagnostic socket.  
If the connection is faulty and if there is a repair procedure (see **Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair**), repair the wiring, otherwise replace it.



<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

### ALP1 CONTINUED

A

Check that the diagnostic socket, component code **225** is correctly supplied:

- **+ before ignition feed** on connection **BP10** of component **225**.
- **+ after ignition feed** on connection **AP10** of component **225**.
- **Earth** on connections **M** and **N** of component **225**

If the connection or connections are faulty and there is a repair procedure (see **Technical Note 6015A, Electrical wiring repair, Wiring: Precautions for repair**), repair the wiring, otherwise replace it.

If dialogue has still not been established after these checks, contact the techline.

### AFTER REPAIR

Clear the computer memory using command **RZ001 Fault memory**.  
Carry out a road test followed by another check with the **diagnostic tool**.

<b>ALP2</b>	<b>Locking of one or more wheels</b>
-------------	--------------------------------------

<b>NOTES</b>	Only address this customer complaint after a <b>complete check</b> with the <b>diagnostic tool</b> .
--------------	--

**Reminder:**

Locking of the wheels on a vehicle fitted with ABS or squealing of tyres, interpreted by the customer as locking, could be related to a normal reaction of the system and should not automatically be assumed to be a fault (braking with ABS regulation on a very bad road causes considerable squealing).

However, if the wheel(s) is/are actually locking, lift the vehicle so that you can turn the wheels and check for:

– Possible inversion when connecting the speed sensors.

Use parameters **PR001 Front right-hand wheel speed**, **PR002 Front left-hand wheel speed**, **PR003 Rear right-hand wheel speed** and **PR004 Rear left-hand wheel speed** by turning the relevant wheels and checking the consistency of the results obtained.

If the value measured is zero, rotate the other wheels to confirm an electrical inversion of the sensors and repair the wiring harness.

– Possible inversion of pipes on the hydraulic unit.

Use commands **AC003 Front left-hand wheel solenoid valves**, **AC004 Front right-hand wheel solenoid valves**, **AC005 Rear left-hand wheel solenoid valves** and **AC006 Rear right-hand wheel solenoid valves** while depressing the brake pedal and check for the occurrence of locking/unlocking cycles on the wheel concerned (see **Command summary table**). If the cycles do not occur on the wheel tested (wheel remains locked), check whether they occur on another wheel to confirm reversed pipes.

If the cycles do not occur on one wheel and the pipes have not been inverted, contact the Techline.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

### ALP2 CONTINUED

Check that the wheel speed sensor mounting is in good condition (clipping).  
Visually inspect the condition of the target (clogging, metallic contamination, etc.) and clean with compressed air if necessary.  
Check the condition of the braking system (condition of linings, sealing, grating, bleed, etc.).  
Check the condition of the axles and the conformity and good condition of the tyre mountings.  
If the fault is still present after these checks, contact the Techline.

### AFTER REPAIR

Clear the computer memory using command **RZ001 Fault memory**.  
Carry out a road test followed by another check with the **diagnostic tool**.

**ALP3**

**Pull**

### NOTES

Only address this customer complaint after a **complete check** with the **diagnostic tool**.

Disconnect one wheel speed sensor.

Start the engine and ensure that only the ABS fault warning light comes on. Do not drive the vehicle if the brake fault warning light is also illuminated because the "braking compensator" function is no longer guaranteed.

Carry out a road test with the ABS thus out of order.

**Is the fault still present under these conditions?**

NO  
↓

YES  
↓

Raise the vehicle so that you can rotate the wheels and check:

- whether the speed sensors have been incorrectly connected,
- whether the pipes on the hydraulic unit have been inverted.

For these two tests, consult and apply the procedures defined in **ALP2 Locking of one or several wheels**.

Check the condition and conformity of the ABS targets.

If the fault is still present, contact the Techline.

If the brake pedal travel is relatively long, bleed the brake circuit.

If the travel is normal, check the tyre pressures, the front axle, or for any leaks in the circuit.

### AFTER REPAIR

Clear the computer memory using command **RZ001 Fault memory**.

Carry out a road test followed by another check with the **diagnostic tool**.



**ALP4**

**Drift**

### NOTES

Only address this customer complaint after a **complete check** with the **diagnostic tool**.

Disconnect one wheel speed sensor.

Start the engine and ensure that only the ABS fault warning light comes on. Do not drive the vehicle if the brake fault warning light is also illuminated because the "braking compensator" function is no longer guaranteed.

Carry out a road test with the ABS thus out of order.

**Is the fault still present under these conditions?**

NO  
↓

Normal behaviour linked to the system operation during the regulation phase, mainly on surfaces with uneven grip or which are poorly laid.

YES  
↓

Road holding fault not related to the ABS.  
Check the condition of the brake linings and that they are to specification and check the tyre pressures, the front axle, etc.

### AFTER REPAIR

Clear the computer memory using command **RZ001 Fault memory**.  
Carry out a road test followed by another check with the **diagnostic tool**.

<b>ALP5</b>	<b>Unexpected ABS operation at low speed and slight pedal pressure</b>
-------------	--

<b>NOTES</b>	Only address this customer complaint after a <b>complete check</b> with the <b>diagnostic tool</b> . Warning: ABS control is sensitive to poor traction (icy roads, wet cobblestones, etc.).
--------------	--

It is possible to feel brake pedal vibrations which are associated with the reaction of the system in particular circumstances, such as:

- crossing rumble strips,
- tight cornering with lifting of the inside rear wheel.

These vibrations may be linked to simple brake limiter activation, when the pressure on the rear axle is limited.

If the fault is different, check the speed sensor connectors (micro-breaks).

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

<b>ALP6</b>	<b>Unexpected ABS system intervention on a poor road surface</b>
-------------	--

<b>NOTES</b>	Only address this customer complaint after a <b>complete check</b> with the <b>diagnostic tool</b> .
--------------	--

On poor road surfaces it is normal to feel hesitation and vibrations of the pedal as well grating which is more significant than on good surfaces.  
This gives the impression of a variation in efficiency, but this should be considered normal.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

<b>ALP7</b>	<b>Unexpected ABS operation when using special equipment (car phone, CB, etc.)</b>
-------------	--

<b>NOTES</b>	Only address this customer complaint after a <b>complete check</b> with the <b>diagnostic tool</b> .
--------------	--

Check that the equipment which is causing the fault is approved.  
Check that this equipment has been correctly installed without modification to the original wiring, particularly that of the ABS (unauthorised earth and + **after ignition feed** connections on the ABS).

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

<b>ALP8</b>	<b>Extension of brake pedal travel following a regulation phase (with an irregular pedal when entering regulation).</b>
-------------	---

<b>NOTES</b>	Only address this customer complaint after a <b>complete check</b> with the <b>diagnostic tool</b> .
--------------	--

Air transit from the hydraulic unit regulation channels to the brake circuits.  
Bleed the systems following the recommended procedure in **MR 423** or **430, Mechanical, 30 A, General information, Brake circuit: Bleeding** (use of **diagnostic tool** command modes).  
After the operation, carry out a road test with ABS regulation.

If the fault persists, carry out the above operation again once or twice.  
If the customer complaint is particularly pronounced, and the bleeds have not rectified it, contact the Techline.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

<b>ALP9</b>	<b>Spongy pedal</b>
-------------	---------------------

<b>NOTES</b>	Only address this customer complaint after a <b>complete check</b> with the <b>diagnostic tool</b> .
--------------	--

Air in the brake circuits.  
Carry out a conventional circuit bleed starting with the right-hand rear brake, then the left-hand rear, left-hand front and right-hand front brakes. Repeat the operation if necessary.  
Check the play of the front and rear bearings.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

<b>ALP10</b>	<b>Brake pedal vibration</b>
--------------	------------------------------

<b>NOTES</b>	Only address this customer complaint after a <b>complete check</b> with the <b>diagnostic tool</b> .
--------------	--

Normal reaction of the brake pedal during an ABS regulation phase or pressure limitation on the rear axle (brake limiter function).

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--

<b>ALP11</b>	<b>Noise from the pump, pipes or hydraulic unit</b>
--------------	---

<b>NOTES</b>	Only address this customer complaint after a <b>complete check</b> with the <b>diagnostic tool</b> .
--------------	--

- Vibration of the unit: check the presence and the condition of the unit support insulating rubber mountings.
  - Vibration of pipes: check that all the pipes are securely clipped in their retaining clips and that there is no contact between pipes or between pipes and bodywork.
- To identify the origin of the noise, use the solenoid valve control commands **AC003 Front left-hand wheel solenoid valves**, **AC004 Front right-hand wheel solenoid valves**, **AC005 Rear left-hand wheel solenoid valves** and **AC006 Rear right-hand wheel solenoid valves** while depressing the brake pedal.

<b>AFTER REPAIR</b>	Clear the computer memory using command <b>RZ001 Fault memory</b> . Carry out a road test followed by another check with the <b>diagnostic tool</b> .
---------------------	--