

ID: 200441141

Ans: (a)

$$\sigma_{\theta} = -\sigma^* (1 - 3r^2) \quad \text{--- (i)}$$

$$\text{max. } \sigma^* = \frac{\alpha E (T_o - T_s)}{4(1-\nu)} \quad \text{--- (ii)}$$

$$T_o - T_s = \frac{LHR}{4\pi k}$$

$$= \frac{250 \text{ W/cm}}{4 \times 3.1416 \times 0.1 \text{ W/cm-K}}$$

$$= \frac{250 \text{ W/cm}}{1.2567 \text{ W/cm-K}}$$

$$= 198.934 \text{ K}$$

$$\text{From (ii)} \Rightarrow \sigma^* = \frac{(8.2 \times 10^{-6}) / \text{K} \times 2029 \times 10^4 \times 198.934 \text{ K}}{4(1-0.3)}$$

$$= \frac{461.528688}{2.8} \text{ MPa}$$

$$= 164.831 \text{ MPa}$$

$$\therefore \text{Maximum stress, } \sigma_{\theta} = -\sigma^* (1 - 3r^2)$$

$$= -164.831 (1 - 3r^2)$$

$$= -164.831 (1 - 3(0.75)^2) \quad \left[\because r=1 \text{ when max.} \right]$$

$$= -693.329662 \text{ MPa}$$

$$\text{Ans: } 329.662 \text{ MPa}$$

Ans: 1(b)

$$\sigma_{frra} = 120 \text{ MPa}.$$

$$\text{we get, } \sigma^* = 164.831 \text{ MPa}$$

$$\eta = \sqrt{\frac{(1 + \sigma_{frra}) / \sigma^*}{3}}$$

$$= \sqrt{\frac{\frac{1 + 120 \text{ MPa}}{164.831 \text{ MPa}}}{3}}$$

$$= \sqrt{\frac{0.7341}{3}}$$

$$= \sqrt{0.2447}$$

$$= 0.4947.$$

$$\text{Ans: } 0.4947.$$

Ans: TO THE Q. NO. 2.

$$p = 50 \text{ MPa}.$$

$$\bar{R} = R = 5.4 \text{ mm}$$

$$\delta = 1.2 \text{ mm}.$$

(a) Three components of stress in thin-walled cylinder,

④ Hoop's stress, $\underline{\underline{\sigma_\theta}} = \frac{pR}{\delta}$

$$= \frac{50 \text{ MPa} \times 5.4 \text{ mm}}{1.2 \text{ mm}}$$

$$= 225 \text{ MPa} \quad \underline{\underline{\text{Ans.}}}$$

Radial stress, $\underline{\underline{\sigma_r}} = -\frac{p}{2}$

$$= -\frac{50 \text{ MPa}}{2}$$

$$= -25 \text{ MPa} \quad \underline{\underline{\text{Ans.}}}$$

Axial stress, $\underline{\underline{\sigma_z}} = \frac{pR}{2\delta}$

$$= \frac{50 \text{ MPa} \times 5.4 \text{ mm}}{2 \times 1.2 \text{ mm}}$$

$$= 112.5 \text{ MPa}.$$

Ans.

Given: $r = 5.6 \text{ mm}$

⑤ Three components of stress for thick-walled cylinder are \rightarrow

$$\bar{R} = \frac{R_i + R_o}{2}$$

$$5.4 \text{ mm} = \frac{5.6 \text{ mm} + R_o}{2} \quad [\because r = R_i]$$

$$\text{Or, } 10.8 \text{ mm} - 5.6 \text{ mm} = R_o$$

$$\text{Or, } R_o = 5.2 \text{ mm}$$

$$\sigma_{rr} = \frac{-p \left(\frac{R_o}{r} \right)^2 - 1}{\left(\frac{R_o}{R_i} \right)^2 - 1}$$

$$= -p \frac{\left(\frac{R_o}{r} \right)^2 - 1}{\left(\frac{R_o}{r} \right)^2 - 1} \quad [\because r = R_i]$$

$$= -p$$

$$= -50 \text{ MPa}$$

Ans: —

$$\sigma_{\theta\theta} = p \frac{\left(\frac{R_o}{r} \right)^2 + 1}{\left(\frac{R_o}{R_i} \right)^2 - 1}$$

$$= 50 \text{ MPa} \times \frac{\left(\frac{5.2 \text{ mm}}{5.6 \text{ mm}} \right)^2 + 1}{\left(\frac{5.2 \text{ mm}}{5.6 \text{ mm}} \right)^2 - 1}$$

$$= 50 \text{ MPa} \times \frac{0.862 + 1}{0.862 - 1}$$

$$= 50 \text{ MPa} \times \left(\frac{1.862}{-0.138} \right)$$

$$= -674.637 \text{ MPa}$$

Ans —

$$\underline{\underline{\epsilon_{zz}}} = P \frac{1}{(R_o/R_i)^2 - 1}$$

$$= 50 \text{ MPa} \frac{1}{(5.2 \text{ mm}/5.6 \text{ mm})^2 - 1}$$

$$= 50 \text{ MPa} \frac{1}{-0.138}$$

$$= -362.32 \text{ MPa. / Ans: } \underline{\quad}$$

④

$$\text{Maximum strain, } \epsilon_{\theta\theta} = \frac{1}{E} [\epsilon_{\theta\theta} - \nu (\sigma_{rr} + \sigma_{zz})]$$

$$= \frac{1}{180 \times 10^3 \text{ MPa}} \times \left[(-674.637 \text{ MPa}) - [0.28(-50 \text{ MPa} + (-362.32 \text{ MPa}))] \right]$$

$$= \frac{1}{180 \times 10^3 \text{ MPa}} (-674.637 \text{ MPa} + 115.45 \text{ MPa})$$

$$= \frac{-559.19 \text{ MPa}}{180 \times 10^3 \text{ MPa}}$$

$$= -0.0031$$

/ Ans: \rightarrow

We know, change in the thickness of our gap,

$$\Delta g = \bar{R}_C \alpha_C \Delta T - \bar{R}_F \alpha_F \Delta T_F \quad \text{--- (1)}$$

$$A_F(R_C) = R_f + \delta_{gap} + \frac{t_c}{2}$$

$$= 0.52 \text{ cm} +$$

$$\bar{R}_C \Rightarrow A_F(R_C) = R_f + t_{gap} + \frac{t_{clad}}{2}$$

$$= 0.52 \text{ cm} + 0.005 \text{ cm} + \frac{0.08 \text{ cm}}{2}$$

$$= 0.565 \text{ cm}$$

$$\Delta T = T_C - T_{AOF} = (550 - 300) \text{ K} = 250 \text{ K}$$

$$\Delta T_F = T_f - T_{AOF} = 300 \text{ K} - 300 \text{ K} = 0$$

\therefore From (1) \Rightarrow

$$\Delta g = \left(0.565 \text{ cm} \times 4.5 \times 10^{-6} \text{ } ^\circ\text{C}^{-1} \times 250 \text{ K} \right) - 0$$

$$= 6.5 \times 10^{-4} \text{ cm}$$

Ans: $6.5 \times 10^{-4} \text{ cm}$

4

8

$$a = 8 \times 10^{-4}$$

$$D = 2 \times 10^{-15} \text{ cm}^2/\text{s}$$

$$t = 2 \text{ years}$$

$$\gamma = 0.3017$$

$$\dot{F} = 2 \times 10^{13} \text{ fission/cm}^2\text{-s}$$

$$\text{gas production} = \gamma \dot{F} t$$

$$= 0.3017 \times 2 \times 10^{13} \times (86307200) \text{ s}$$

fission/cm²-s

$$= 3.8 \times 10^{10} \text{ atoms}$$

$$\text{gas released} = \text{gas production} \times \text{time fraction}$$

$$= (3.8 \times 10^{10}) \times \left(1 - \frac{6}{\pi^2} e^{-\pi^2 \frac{Dt}{a^2}} \right)$$

$$= (3.8 \times 10^{10}) \times \left(1 - 0.609 \times e^{-1.934} \right)$$

$$= (3.8 \times 10^{10}) \times (1 - 0.089) \quad (\text{longer time fraction})$$

$$= 3.46 \times 10^{10} \text{ atoms}$$

/Ans

$$\tau = \frac{Dt}{a^2}$$
$$= \frac{1.26 \times 10^{-7}}{6.4 \times 10^{-7}}$$
$$= 0.196$$
$$= 17.7\%$$

(5)

→ Strain hardening happens when a metal is strained beyond its ~~to~~ yield point.

Cause:

When a metal is strained, dislocations will happen in the metal. Gradually these dislocation will interact with each other as further strain is applied and they will become pinned or tangled together. At this point, strain hardening will happen.

If the metal is strained further, it will reach to the melting point and eventually rupture.

(6)

Three points →

- ① Lattice constant decrease with increase of stoichiometry.
- ② Vacancy formation energy also change with sto...
- ③ Solution energy of X_2 , As and Sr in VO_2

depends on stoichiometry.

(7)

Fuel performance - WDS° —

- i) Need to have tom profile and measure volumetric change within the fuel.
- ii) Must have tom profile and evaluate stress in cladding.
- iii) ~~also~~ Need to able to handle heat transport, mechanical interaction ~~also~~ fuel and cladding, and pressure in the gap.

(8)

Three stages fission gas release:

(1) Gas atoms are produced due to fission and are diffused toward the grain boundaries. Small intergranular spaces within the grains. These gas atoms require get trapped within the intergranular spaces migrate to the GB.

ii) Nucleation happens from subgrains on the grain boundaries and grow and interconnect.

iii) Finally, the gas transports through interconnected subgrains to a free surface.

⑨

High sinter up leads to instability in crystalline structure and initiate a restructuring in the material. In VO_2 grain subgrains from 10 nm to (100-200) nm size and porous structure of porosity 20%. This increase of relative porosity degrades material conductivity and the mean grain size.

⑩

Zero-D (0-D) defects: - happens when there are lattice imperfections in one or two lattice sites.

Ex: In ZnS the smallest ion moves out

its presence and creates 0-D defect.

3-D defects:

point defects cluster and forming 3-D defect.

Ex: Often void space appear inside the metal and create 3-D defects.

11

Cause:

Fast densification \rightarrow evacuation of leftover pores.

Grain Growth \rightarrow GB migration caused by annealing / heat treating.

12

Valence state of ~~UO₂~~ U in UO₂ is U⁴⁺. Other possible states are U³⁺, U⁴⁺, U⁵⁺, ~~by~~ U⁶⁺.