

88

ID: 200441141

Ans: (a)

$$\sigma_{\theta} = -\sigma^* (1 - 3r^2) \quad \text{--- (i) } \checkmark$$

$$\text{and, } \sigma^* = \frac{\alpha E (T_o - T_s)}{4(1-\nu)} \quad \text{--- (ii) } \checkmark$$

13/14

$$T_o - T_s = \frac{LHR}{4\pi k}$$

$$= \frac{250 \text{ W/cm}}{4 \times 3.1416 \times 0.1 \text{ W/cm-K}}$$

$$= \frac{250 \text{ W/cm}}{1.2567 \text{ W/cm-K}}$$

$$= 198.934 \text{ K} \quad \checkmark$$

$$\text{From (ii)} \Rightarrow \sigma^* = \frac{(8.2 \times 10^{-6}) / \text{K} \times 2.029 \times 10^4 \times 198.934 \text{ K}}{4(1-0.3)}$$

$$= \frac{461.528688}{2.8} \text{ MPa}$$

$$= 164.831 \text{ MPa} \quad \checkmark$$

$$\therefore \text{Maximum stress, } \sigma_{\theta} = -\sigma^* (1 - 3r^2)$$

$$= -164.831 (1 - 3r^2)$$

$$= -164.831 (1 - 3(0.75)^2) \quad \left[\because r=1 \text{ when max} \right]$$

$$= -693.329662 \text{ MPa}$$

$$\text{Ans: } 329.662 \text{ MPa}$$

Ans: 1(b)

$$\sigma_{frra} = 120 \text{ MPa}.$$

we get, $\sigma^* = 164.831 \text{ MPa}$

$$\eta = \sqrt{\frac{(1 + \sigma_{frra}) / \sigma^*}{3}}$$

slight error

$$= \sqrt{\frac{\frac{1 + 120 \text{ MPa}}{164.831 \text{ MPa}}}{3}}$$

$$= \sqrt{\frac{0.7341}{3}}$$

$$= \sqrt{0.2447}$$

$$= 0.4947.$$

Ans: 0.4947.

Ans: TO THE Q. NO. 2.

$$p = 50 \text{ MPa}.$$

$$\bar{R} = R = 5.4 \text{ mm}$$

$$\delta = 1.2 \text{ mm}.$$

(a) Three components of stress in thin-walled cylinder,

$$\sigma_r = -\sigma^* (1 - 3\eta^2)$$

$$\eta = \sqrt{\frac{\frac{\sigma_r}{\sigma^*} + 1}{3}}$$

④ Hoop's stress, $\underline{\underline{\sigma_\theta}} = \frac{pR}{\delta}$

$$= \frac{50 \text{ MPa} \times 5.4 \text{ mm}}{1.2 \text{ mm}}$$

$$= 225 \text{ MPa} \quad \underline{\underline{\text{Ans:}}} \quad \checkmark$$

11/14

Radial stress, $\underline{\underline{\sigma_r}} = -\frac{p}{2}$

$$= -\frac{50 \text{ MPa}}{2}$$

$$= -25 \text{ MPa} \quad \underline{\underline{\text{Ans:}}} \quad \checkmark$$

Axial stress, $\underline{\underline{\sigma_z}} = \frac{pR}{2\delta}$

$$= \frac{50 \text{ MPa} \times 5.4 \text{ mm}}{2 \times 1.2 \text{ mm}}$$

$$= 112.5 \text{ MPa} \quad \checkmark$$

Ans:Given: $r = 5.6 \text{ mm}$

⑤ Three components of stress for thick-walled cylinder are \rightarrow

$$\bar{R} = \frac{R_i + R_o}{2}$$

$$\bar{R} = 5.4$$

$$5.4 \text{ mm} = \frac{5.6 \text{ mm} + R_o}{2}$$

$$[\because r = R_i]$$

$$R_i = 4.8$$

$$R_o = 6.0$$

$$\text{Or, } 10.8 \text{ mm} - 5.6 \text{ mm} = R_o$$

$$\text{Or, } R_o = 5.2 \text{ mm}$$

$$\sigma_{rr} = \frac{-p \left[\left(\frac{R_o}{r} \right)^2 - 1 \right]}{\left(\frac{R_o}{R_i} \right)^2 - 1}$$

$$\frac{R_o}{r} \neq \frac{R_o}{R_i}$$

$$= -p \frac{\left(\frac{R_o}{r} \right)^2 - 1}{\left(\frac{R_o}{r} \right)^2 - 1} \quad [\because r = R_i]$$

$$= -p$$

$$= -50 \text{ MPa}$$

Ans: —

$$\sigma_{\theta\theta} = p \frac{\left(\frac{R_o}{r} \right)^2 + 1}{\left(\frac{R_o}{R_i} \right)^2 - 1} \quad \checkmark$$

$$= 50 \text{ MPa} \times \frac{\left(\frac{5.2 \text{ mm}}{5.6 \text{ mm}} \right)^2 + 1}{\left(\frac{5.2 \text{ mm}}{5.6 \text{ mm}} \right)^2 - 1}$$

$$= 50 \text{ MPa} \times \frac{0.862 + 1}{0.862 - 1}$$

$$= 50 \text{ MPa} \times \left(\frac{1.862}{-0.138} \right)$$

$$= -674.637 \text{ MPa}$$

Ans —

$$\frac{R_o}{R_i} > 1 \text{ always}$$

$$\underline{\underline{\epsilon_{zz}}} = P \frac{1}{(R_o/R_i)^2 - 1}$$

$$= 50 \text{ MPa} \frac{1}{(5.2 \text{ mm}/5.6 \text{ mm})^2 - 1}$$

$$= 50 \text{ MPa} \frac{1}{-0.138}$$

$$= -362.32 \text{ MPa. / Ans: } \underline{\hspace{1cm}}$$

④

$$\text{Maximum strain, } \epsilon_{\theta\theta} = \frac{1}{E} \left[\epsilon_{\theta\theta} - \nu (\sigma_{rr} + \sigma_{zz}) \right]$$

$$= \frac{1}{180 \times 10^3 \text{ MPa}} \times \left[(-674.637 \text{ MPa}) - [0.28(-50 \text{ MPa} + (-362.32 \text{ MPa})) \epsilon] \right]$$

$$= \frac{1}{180 \times 10^3 \text{ MPa}} (-674.637 \text{ MPa} + 115.45 \text{ MPa})$$

$$= \frac{-559.19 \text{ MPa}}{180 \times 10^3 \text{ MPa}}$$

$$= -0.0031$$

/ Ans: \rightarrow

- negative strain doesn't make sense here

We know, change in the thickness of our gap,

9/16

$$\Delta \delta_g = \bar{R}_C \alpha_C \Delta T - \bar{R}_F \alpha_F \Delta T_F \quad \text{--- (1)}$$

$$A_F(R_C) = R_f + \delta_{gap} + \frac{t_c}{2}$$

$$= 0.52 \text{ cm} +$$

$$\bar{R}_C \equiv A_F(R_C) = R_f + \delta_{gap} + \frac{t_{clad}}{2}$$

$$= 0.52 \text{ cm} + 0.005 \text{ cm} + \frac{0.08 \text{ cm}}{2}$$

$$= 0.565 \text{ cm}$$

$$\bar{T}_C = \frac{T_o - T_i}{2}$$

$$\Delta T = T_C - T_{Aqf} = (550 - 300) \text{ K} = 250 \text{ K}$$

$$\Delta T_F = T_f - T_{Aqf} = 300 \text{ K} - 300 \text{ K} = 0$$

\therefore From (1) \Rightarrow

- need to solve for T_f
given LHR & heat transport

$$\Delta \delta_g = \left(0.565 \text{ cm} \times 4.5 \times 10^{-6} \text{ 1/K} \times 250 \text{ K} \right) - 0$$

$$= 6.5 \times 10^{-4} \text{ cm}$$

$$\text{Ans: } 6.5 \times 10^{-4} \text{ cm}$$

- halfway, but didn't
obtain the temperature
profile to determine
 \bar{T}_C and \bar{T}_F

9/12

4

$$a = 8 \times 10^{-4}$$

$$D = 2 \times 10^{-15} \text{ cm}^2/\text{s}$$

$$t = 2 \text{ years}$$

$$\gamma = 0.3017$$

$$\dot{F} = 2 \times 10^{13} \text{ fission/cm}^2\text{-s}$$

$$\text{gas production} = \gamma \dot{F}$$

$$= 0.3017 \times 2 \times 10^{13} \times (63072000) \text{ fission/cm}^2\text{-s}$$

$$= 3.8 \times 10^{10} \text{ atoms}$$

- Calculator error here...

$$\begin{aligned} \tau &= \frac{Dt}{a^2} \\ &= \frac{1.26 \times 10^{-7}}{6.4 \times 10^{-7}} \\ &= 0.196 \\ &= 17.7\pi^2 \end{aligned}$$

$$\text{gas released} = \text{gas production} \times \text{time fraction}$$

$$= (3.8 \times 10^{10}) \times \left(1 - \frac{6}{\pi^2} e^{-\pi^2 \frac{Dt}{a^2}} \right)$$

$$= (3.8 \times 10^{10}) \times \left(1 - 0.609 \times e^{-1.934} \right)$$

$$= (3.8 \times 10^{10}) \times (1 - 0.089) \quad (\text{longer time fraction})$$

$$= 3.46 \times 10^{10} \text{ atoms}$$

/atoms

= used equation for annealing instead of in-pile gas release

(5)

→ strain hardening happens when a metal is strained beyond its yield point.

8/8

Cause:

When a metal is strained, dislocations will happen in the metal. Gradually these dislocation will interact with each other as further strain is applied and they will become pinned or tangled together. At this point, strain hardening will happen.

If the metal is strained further, it will reach to the melting point and eventually fracture.

(6)

Three points →

6/6

- ① Lattice constant decreases with increase of stoichiometry.
- ② Vacancy formation energy also change with sto.
- ③ Solution energy of X_2 , As and Sr in VO_2

depends on stoichiometry.

(7)

Fuel performance - MDS^a — 6/6

- i) Need to have ~~from~~ precise and measured volumetric change within the fuel.
- ii) Must have ~~from~~ precise and evaluated stress in cladding.
- iii) ~~Need~~ Need to ~~also~~ to handle heat transport, mechanical ~~interaction~~ ~~with~~ fuel and cladding, and pressure in the gap.

(8)

Three stages fission gas release: 9/9

(1) Gas atoms are produced due to fission and are ~~diffused~~ ~~toward~~ the grain boundaries. Small intergranular ~~sinks~~ ~~within~~ the grains. These gas atoms ~~require~~ get trapped within the ~~intergranular~~ ~~sinks~~ migrate to the GB.

ii) Nucleation happens ~~at~~ ^{on} the ~~grains~~ ^{GB} and grow and interconnect.

iii) Finally, the ~~gas~~ ^{gas} transports through interconnected bubbles ~~to~~ ^{to} a free surface.

⑨

High burn up leads to instability in crystalline ~~the~~ structure and initiate a restructuring in the material. In UO_2 grain subdivide from 10mm ~~(100-200)~~ ⁽¹⁰⁰⁻²⁰⁰⁾ mm size and porous structure of porosity 20%. This increase of relative ~~porosity~~ ^{porosity} degrades material conductivity and ~~the~~ ^{the} mean grain size.

- fission gas is retained
- net thermal conductivity is increased

⑩

Zero-D (0-D) defects: - happens when there are lattice imperfections in one or two lattice sites.

Ex: In ZnS the smallest ion moves out

its place and creates \checkmark 0-D effect.

3-D defects: point defects cluster and forming 3-D defect.

Ex: Often void space appear inside the metal and create 3-D defects.

(11)

Cause:

fuel densification \rightarrow evacuation of leftover pores.

\rightarrow reducing free surface area
Grain Growth \rightarrow GB migration

caused by annealing / heat treating.

\rightarrow reduces GB length, reducing free energy

(12)

Valence state of ~~UO₂~~ U in UO₂ is U^{4+} . Other possible states are U^{3+} , U^{4+} , U^{5+} , U^{6+} .