



South Texas Project Electric Generating Station P.O. Box 289 Wadsworth, Texas 77483

March 20, 2014
NOC-AE-14003100
10 CFR 50.73

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555-0001

South Texas Project
Unit 2
Docket No. STN 50-499
Licensee Event Report 2013-004-01
Supplement to LER 2013-004-00: Manual Actuation of Main Steam Isolation Valves that was
Not Part of a Preplanned Sequence During Testing or Reactor Operation

Reference: Letter from G.T. Powell, STPNOC, to NRC Document Control Desk, "Licensee Event Report 2013-004-00 Manual Actuation of Main Steam Isolation Valves that was Not Part of a Preplanned Sequence During Testing or Reactor Operation," February 18, 2014 (ML14069A175)

Pursuant to 10 CFR 50.73(a)(2)(iv)(A), STP Nuclear Operating Company (STPNOC) submits the attached South Texas Project (STP) Unit 2 Licensee Event Report (LER) 2013-004-01 regarding a manual actuation of the Main Steam Isolation Valves (MSIVs) performed to support breaking vacuum in response to failure of the turbine bearing lift pump. This LER is a supplement to LER 2013-004-00.

This event did not have an adverse effect on the health and safety of the public.

There are no commitments in this letter. Corrective actions will be implemented in accordance with the STP Corrective Action Program.

If there are any questions, please contact Wendy Brost at (361) 972-8516, or me at (361) 972-7566.

G. T. Powell
Site Vice President

web

Attachment: Unit 2 LER 2013-004-01

IEZ2
NRR

STI 33840307

cc:

(paper copy)

Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
1600 East Lamar Boulevard
Arlington, TX 76011-4511

Balwant K. Singal
Senior Project Manager
U.S. Nuclear Regulatory Commission
One White Flint North (MS 8 B1)
11555 Rockville Pike
Rockville, MD 20852

NRC Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 289, Mail Code: MN116
Wadsworth, TX 77483

Jim Collins
City of Austin
Electric Utility Department
721 Barton Springs Road
Austin, TX 78704

(electronic copy)

A. H. Gutterman, Esquire
Morgan, Lewis & Bockius LLP

Balwant K. Singal
U. S. Nuclear Regulatory Commission

John Ragan
Chris O'Hara
Jim von Suskil
NRG South Texas LP

Kevin Pollo
Richard Peña
L. D. Blaylock
City Public Service

Peter Nemeth
Crain Caton & James, P.C.

C. Mele
City of Austin

Richard A. Ratliff
Robert Free
Texas Department of State Health Services

(See Page 2 for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollections.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. PAGE
South Texas Unit 2	05000499	1 OF 4

Manual Actuation of Main Steam Isolation Valves that was Not Part of a Preplanned Sequence During Testing or Reactor Operation

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME N/A	DOCKET NUMBER N/A
12	19	2013	2013 - 004 - 01			03	20	2014	FACILITY NAME N/A	DOCKET NUMBER N/A

9. OPERATING MODE	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)			
3	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
10. POWER LEVEL	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

LICENSEE CONTACT	TELEPHONE NUMBER <i>(Include Area Code)</i>
Wendy Brost, Licensing Engineer	361-972-8516

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO		15. EXPECTED SUBMISSION DATE		MONTH	DAY	YEAR

On December 19, 2013, while in Mode 3 preparing the Unit 2 secondary plant for startup, conditions occurred where it became necessary to break vacuum on the main condenser. The Operator closed the Main Steam Isolation Valves (MSIVs) using the Main Steam Isolation Actuation switch due to the urgency to prevent damage to the main turbine.

This action constitutes a valid manual actuation of multiple MSIVs and is therefore reportable under 10 CFR 50.73(a)(2)(iv)(A).

The risk significance of the event is considered to be very small. This event did not result in any offsite release of radioactivity or increase the offsite dose rates, and there were no personal injuries or damage to any safety-related equipment associated with this event.

The cause of the event was unspecific guidance in the off normal procedure for secondary plant stabilization. The failure of the bearing oil lift piping placed the Control Room Staff in a situation that required prompt action to prevent equipment damage, and the Staff made a decision to use the MSI Actuation switch as a result of the unspecific written guidance to ensure MSIVs and Main Steam Isolation Bypass valves (MSIBs) are closed.

The corrective action will be to revise the off normal procedure for secondary plant stabilization to provide specific direction for the switches to use for closing the MSIVs.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEDB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REV NO.	
South Texas Unit 2	05000499	2013	- 004	- 01	2 OF 4

NARRATIVE**I. DESCRIPTION OF EVENT****A. REPORTABLE EVENT CLASSIFICATION**

This event is reportable pursuant to 10 CFR 50.73(a)(2)(iv)(A), any event or condition that resulted in the valid manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B) that was not part of a pre-planned sequence during testing or reactor operation. The listed system is the Main Steam Isolation Valves (MSIVs).

B. PLANT OPERATING CONDITIONS PRIOR TO EVENT

Unit 2 was operating in Mode 3 at 0% power.

C. STATUS OF STRUCTURES, SYSTEMS, AND COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT

There were no structures, systems, or components that were inoperable at the start of the event that contributed to the event.

D. NARRATIVE SUMMARY OF THE EVENT

On December 19, 2013 at approximately 2200 hours, while in Mode 3 preparing the Unit 2 secondary plant for startup, a repeat failure of the non-safety bearing oil lift piping occurred preventing placing the turbine on the turning gear. After approximately 30 minutes with no turbine rotation, efforts to place the Main Turbine back on the turning gear had failed so the associated annunciator response procedure guided the staff to secure main condenser vacuum and turbine gland seal steam to minimize turbine rotor bow.

The notes in the annunciator response procedure state that the procedure used to secure main condenser vacuum and turbine gland seal steam depends on the type of unit shutdown. Normal shutdown would require the use of normal operating procedures and the off-normal procedure for secondary plant stabilization, and its associated Conditional Information Page (CIP) for the "Condenser Unavailable" condition, would be used following a reactor trip.

An additional note in annunciator response procedure states that the main turbine should to be rotated at least 180 degrees every 15 minutes if possible. The situation was considered urgent because 30 minutes had already elapsed while attempting to restore the turning gear.

This situation did not qualify as a normal shutdown nor as a reactor trip, however all crew members agreed that the actions needed to be performed promptly and the CIP for "Condenser Unavailable" was followed. The Unit Supervisor gave the CIP procedural direction to the crew to isolate the Main Steam Lines (MSL). The Reactor Operator repeated the direction back and turned the Main Steam Isolation Actuation switch to close the MSIVs.

The Control Room staff closed all four MSIVs at once using the Main Steam Isolation (MSI) Actuation switch, rather than closing each valve individually, due to the urgency to prevent damage to the main turbine.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
South Texas Unit 2	05000499	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 4
		2013	- 004	- 01	

NARRATIVE

It should be noted that the off-normal procedure states "ENSURE MSIVs and MSIBs are closed", but does not specifically call for the use of the Main Steam Isolation Actuation switch.

By using the Main Steam Isolation Actuation switch instead of the individual valve switches, the main steam valves close signal was processed through the solid state protection system (SSPS), which is an Engineered Safety Feature (ESF) actuation and is reportable.

E. METHOD OF DISCOVERY

The manual actuation of the MSIVs via the SSPS was self-revealing when the action was performed in the Control Room.

II. EVENT-DRIVEN INFORMATION**A. SAFETY SYSTEMS THAT RESPONDED**

The MSIVs closed in response to the manual actuation of the Main Steam Isolation circuitry. No other safety systems were affected by this event.

B. DURATION OF SAFETY SYSTEM INOPERABILITY

No safety systems were inoperable as a result of this event.

C. SAFETY CONSEQUENCES AND IMPLICATIONS OF THE EVENT

The event did not have an adverse effect on the health and safety of the public.

A risk assessment was performed for this event. At the time of the event, the plant was in Mode 3, preparing the Unit 2 secondary plant for startup. The plant had not been critical for almost a month, which means decay heat was low. There was no initiating event or impact to the capability of mitigating systems or other plant equipment to perform required safety functions. Therefore, there is no incremental core damage or large early release risk associated with this event.

III. CAUSE OF THE EVENT

The cause of the event was unspecific guidance in the off normal procedure for secondary plant stabilization.

The urgency in this event was not from a design basis accident but from a need to protect major plant equipment. The failure of the bearing oil lift piping placed the Control Room Staff in a situation that required prompt action to prevent equipment damage, and the Staff made a decision to use the MSI Actuation switch as a result of the unspecific written guidance to ensure MSIVs and Main Steam Isolation Bypass valves (MSIBs) are closed.

IV. CORRECTIVE ACTIONS

The off normal procedure for secondary plant stabilization will be revised to provide specific direction for the switches to use for closing the MSIVs.

V. PREVIOUS SIMILAR EVENTS

There have been no similar reportable events at STP within the last three years that have occurred for the same reason as this event.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REV NO.	
South Texas Unit 2	05000499	2013	- 004	- 01	4 OF 4

NARRATIVE

VI. ADDITIONAL INFORMATION

None