



South Texas Project Electric Generating Station P.O. Box 289 Wadsworth, Texas 77483

October 29, 2009
NOC-AE-09002482
10CFR50.73

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
One White Flint North
11555 Rockville Pike
Rockville, MD 20852-2738

South Texas Project
Unit 2
Docket No. STN 50-499
Revision 1 to Licensee Event Report 2008-002
Loss of Residual Heat Removal and Valid Actuation of Safety Systems

Pursuant to 10 CFR 50.73, the STP Nuclear Operating Company (STPNOC) submits the attached Unit 2 Licensee Event Report 2008-002 to address a valid actuation of some of the safety systems listed in 10 CFR 50.73(a)(2)(iv)(B). The valid actuation resulted in the loss of residual heat removal capability for a brief period of time.

After further consideration, STPNOC determined that the reporting criteria in 10 CFR 50.73(a)(2)(v)(B) are also applicable for an event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to remove residual heat and as such submits the attached revision to the LER. Changes are annotated in the margins. The associated NRC Performance Indicator for Safety System Functional Failures for the fourth quarter of 2008 has been updated accordingly.

This event did not have an adverse effect on the health and safety of the public.

There are no commitments contained in this event report. Resulting corrective actions will be implemented in accordance with the Corrective Action Program.

If there are any questions regarding this submittal, please contact Ken Taplett at (361) 972-8416 or me at (361) 972-7158.

A handwritten signature in black ink, appearing to read "L. W. Peter".

L. W. Peter
Plant General Manager

Attachment: South Texas Unit 2 LER 2008-002, Revision 1

STI: 32561633

IE22
LWR

cc:

(paper copy)

Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
612 East Lamar Blvd, Suite 400
Arlington, Texas 76011-4125

Mohan C. Thadani
Senior Project Manager
U.S. Nuclear Regulatory Commission
One White Flint North (MS 7 D1)
11555 Rockville Pike
Rockville, MD 20852

Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 289, Mail Code: MN116
Wadsworth, TX 77483

C. M. Canady
City of Austin
Electric Utility Department
721 Barton Springs Road
Austin, TX 78704

(electronic copy)

A. H. Gutterman, Esquire
Morgan, Lewis & Bockius LLP

Mohan C. Thadani
U. S. Nuclear Regulatory Commission

Kevin Howell
Catherine Callaway
Jim von Suskil
NRG South Texas LP

Ed Alarcon
J. J. Nesrsta
R. K. Temple
Kevin Pollo
City Public Service

Jon C. Wood
Cox Smith Matthews

C. Mele
City of Austin

Richard A. Ratliff
Texas Department of State Health Services

Alice Rogers
Texas Department of State Health Services

LICENSEE EVENT REPORT (LER)(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME South Texas, Unit 2	2. DOCKET NUMBER 05000499	3. PAGE 1 OF 5
--	-------------------------------------	--------------------------

4. TITLE
Loss of Residual Heat Removal and Valid Actuation of Safety Systems

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
10	25	2008	2008	- 002 -	01	10	29	2009	NA	05000
									FACILITY NAME	DOCKET NUMBER
									NA	05000

9. OPERATING MODE 5	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)									
	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)						
10. POWER LEVEL 0	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)						
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)						
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)						
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)						
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)						
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)						
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER						
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)							
Specify in Abstract below or in NRC Form 366A										

12. LICENSEE CONTACT FOR THIS LER	
NAME Ken Taplett (Licensing Engineer)	TELEPHONE NUMBER (Include Area Code) (361) 972-8416

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED				15. EXPECTED SUBMISSION DATE		MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE)				<input checked="" type="checkbox"/> NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

At 2344 on October 25, 2008, with Unit 2 in Mode 5 during the end of a refueling outage, a valid Safety Injection actuation signal occurred. The actuation resulted in automatic start of all three Engineered Safety Features Diesel Generators, a Containment ventilation isolation, a Containment phase A isolation and tripping of the running Residual Heat Removal pumps.

The actuation was the result of removing a block for the low steam pressure actuation signal during a maintenance activity to replace a circuit card in the Solid State Protection System. The actuation was not part of a pre-planned sequence during testing or reactor operation. The removal of the signal block was unintended. Although the action was unintended, the signal was a valid signal initiated in response to a parameter satisfying the requirements for initiation of the safety function of the system.

There was no discharge of the Emergency Core Cooling System (ECCS) into the Reactor Coolant system because the ECCS pumps had been properly removed from service for the plant condition. Residual heat removal capability was restored within 4 minutes of the actuation.

The causes of the event were: (1) the outage process did not have specific requirements for processing emergent work or evaluating risk impact on plant conditions; (2) the work planning guidance lacked sufficient rigor; and (3) the work package was complex.

Corrective actions include implementing plant procedures to specify requirements for addressing emergent work during outages and assessing the impacts associated with shutdown risk; and revising the Planner's Guide to develop defense-in-depth strategies

This event did not have an adverse effect on the health and safety of the public.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE		
South Texas, Unit 2	05000499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2	OF	5
		2008	002	01			

NARRATIVE

I. DESCRIPTION OF REPORTABLE EVENT

A. REPORTABLE EVENT CLASSIFICATION

This event is reportable pursuant to 10 CFR 50.73(a)(2)(iv)(A) as an event or condition that resulted in a valid automatic actuation of systems listed in paragraph (a)(2)(iv)(B) of this section of 10 CFR 50.73. The actuation was not part of a pre-planned sequence during testing or reactor operation. The actuation resulted in automatic start of all three Engineered Safety Features (ESF) Diesel Generators, a Containment ventilation isolation, a Containment phase A isolation and tripping of the running Residual Heat Removal (RHR) pumps.

This event is also considered reportable pursuant to 10 CFR 50.73(a)(2)(v)(B) as an event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to remove residual heat.

B. PLANT OPERATING CONDITIONS PRIOR TO THE EVENT

At the time of the event, Unit 2 was in MODE 5 with two RHR pumps running.

C. STATUS OF STRUCTURES, SYSTEMS, OR COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT

The Solid State Protection System (SSPS) that initiated the actuation signal was inoperable as planned at the initiation of the event.

D. NARRATIVE SUMMARY OF THE EVENT, INCLUDING DATES AND APPROXIMATE TIMES

At approximately 1600 on October 25, 2008, with Unit 2 in MODE 5 during the end of a refueling outage, a test switch on the SSPS failed to operate as expected during the performance of a surveillance. It was determined that an A416 general logic card had failed. A decision was made to replace the failed circuit card as emergent work to support the outage MODE ascension plan.

The repair was considered to have little risk in the plant condition existing at the time of the event provided the SSPS cabinets were removed from service. No formal risk assessment was conducted. It was decided to combine the surveillance procedure with the maintenance activity to replace the circuit card in the work package instructions.

The preparation of the emergent work package included a turnover from the day shift to the night shift. During the transfer of information, the requirements to have SSPS out of service and actuation trains in a test condition prior to replacing the failed circuit card were not communicated clearly to the on coming shift. The work package was reviewed by an individual who had very limited familiarity with the SSPS. During the process to gain permission to start the work, it was decided that all prerequisites of the surveillance procedure were required. The performance of all the prerequisites placed both logic trains of the SSPS in normal and all actuation trains in operate.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE		
South Texas, Unit 2	05000499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3	OF	5
		2008	002	01			

NARRATIVE

Work start permission was received and the surveillance prerequisite steps were completed. Upon removal of the failed A416 circuit card on October 25, 2008 at 2344 hours, a low steam pressure actuation signal block was removed from the actuation circuitry. This condition provided a valid Safety Injection (SI) actuation signal. The actuation resulted in automatic start of all three Engineered Safety Features (ESF) Diesel Generators, a Containment ventilation isolation, a Containment phase A isolation and tripping of the running Residual Heat Removal (RHR) pumps. The RHR pumps trip because their power supplies are stripped from the ESF electrical buses in response to an SI signal. No safety system that was aligned to actuate in response to the signal failed to actuate.

There was no discharge of the Emergency Core Cooling System (ECCS) into the Reactor Coolant System (RCS). The High Head Safety Injection Pumps were in pull-to-lock as required by the Technical Specifications for this plant MODE. The Low Head Safety Injection pumps were in pull-to-lock to meet the requirements of plant procedures for the plant condition.

It was concluded immediately that the maintenance activity resulted in the SI actuation. The actuation trains were placed in a test condition and the SI actuation signal was reset. The first RHR pump was restarted in approximately four minutes following the tripping of the pump. The second RHR pump was restarted in approximately six minutes following the tripping of the pump. The interruption of RHR flow resulted in a RCS temperature rise of 7°F (i.e. 147°F to 154°F) based on monitoring core exit thermocouple temperatures.

E. THE METHOD OF DISCOVERY OF EACH COMPONENT OR SYSTEM FAILURE, OR PROCEDURAL OR PERSONNEL ERROR

The unintended SI actuation was self-revealing as a result of the performance of the maintenance activity when the failed circuit card was removed from the SSPS.

II. COMPONENT OR SYSTEM FAILURES

A. FAILURE MODE, MECHANISM, AND EFFECTS OF EACH FAILED COMPONENT

This valid actuation of safety systems was not a result of a failed component.

B. CAUSE OF EACH COMPONENT OR SYSTEM FAILURE

Not applicable.

C. SYSTEMS OR SECONDARY FUNCTIONS THAT WERE AFFECTED BY FAILURE OF COMPONENTS WITH MULTIPLE FUNCTIONS

Not applicable.

D. FAILED COMPONENT INFORMATION

Not applicable.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE		
South Texas, Unit 2	05000499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4	OF	5
		2008	002	01			

NARRATIVE

III. ANALYSIS OF THE EVENT

A. SAFETY SYSTEM RESPONSES THAT OCCURRED

Although a valid SI actuation signal was generated and safety systems were unnecessarily challenged, the actuation was not required for the plant condition. Proper performance of the maintenance activity should have resulted in continuing to block the actuation signal. The RHR system was in service. The SI actuation resulted in loss of this system.

B. DURATION OF SAFETY SYSTEM TRAIN INOPERABILITY

The first RHR loop was out of service for approximately four minutes. The second RHR loop was out of service for approximately six minutes.

C. SAFETY CONSEQUENCES AND IMPLICATIONS

The event did not have an adverse affect on the health and safety of the public.

There was no discharge of the ECCS into the RCS.

Residual heat removal capability was lost for a brief period of time. The loss of RHR cooling occurred 21 days after shutdown with the core reloaded for the next operating cycle. The RCS was pressurized and all four steam generators were available for heat removal. Using conservative assumptions based on plant data, sufficient heat removal capability existed to keep the RCS from boiling for 31 hours. A bounding evaluation determined that the Conditional Core Damage Probability for this event was much less than 1E-06.

This event resulted in no personnel injuries, no offsite radiological releases, and no damage to other safety-related equipment.

IV. CAUSE OF THE EVENT

- The outage process did not have specific requirements for processing emergent work or evaluating the associated risk impact on plant conditions.
- Work planning guidance lacked sufficient rigor. Ownership for work package preparation and review was not clearly established. Mitigation strategies were not formalized to ensure that the technical content of the work package was correct. The technical expertise required for a work package review was not specified.
- Combining the surveillance procedure with the maintenance activity to replace the circuit card complicated the work coordination. The increased level of complexity in the work package instructions resulted in the SSPS being in service instead of being removed from service for the circuit card replacement.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE		
South Texas, Unit 2	05000499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5	OF	5
		2008	002	01			

NARRATIVE

V. CORRECTIVE ACTIONS

- Residual heat removal capability was restored.
- Work instructions were revised to configure the SSPS so that the logic cabinets would be out of service and the actuations trains in test to support the A416 circuit card replacement.
- A plant procedure will be implemented to specify requirements for addressing emergent work during outages including requirements for assessing any shutdown risk created by the work activity. The procedure will list roles and responsibilities of key individuals for providing input, review and approval of emergent work packages.
- The Planner's Guide will be revised to include:
 - a. Requirements to avoid using Operations procedures as work instructions to ensure work instructions are kept simple for review of technical requirements pertaining to the performance of the maintenance activity. If Operations procedures are used, the Planners Guide will provide for a formalized process and required technical justification regarding using this approach.
 - b. A defense in depth strategy in work package preparation identifying such attributes as review responsibilities and error mitigation strategies.

VI. PREVIOUS SIMILAR EVENTS

There have been no STPNOC Licensee Event Reports in the past three years regarding the valid automatic actuation of safety systems or loss of residual heat removal.

VI. ADDITIONAL INFORMATION

The 10 CFR 50.72 notification to the Nuclear Regulatory Commission on October 27, 2008, Event Number 44605, stated the removal of the block for the low pressurizer pressure signal initiated the actuation. Upon further review of the event, the removal of the block for the low steam pressure signal, as stated in Section I.D above, initiated the actuation.