



South Texas Project Electric Generating Station P.O. Box 289 Wadsworth, Texas 77483

November 19, 2001
NOC-AE-01001212
File No.: G25
10CFR50.73
STI: 31371127

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555-0001

South Texas Project
Unit 1
Docket No. STN 50-498
Licensee Event Report 01-001
Essential Cooling Water Pump IC Failure Following Maintenance

Pursuant to 10CFR50.73, South Texas Project submits the attached Unit 1 Licensee Event Report 01-001 regarding the failure of Essential Cooling Water Pump IC following maintenance. This event did not have an adverse effect on the health and safety of the public.

Corrective Actions 1 and 2 are the only Licensee commitments in this letter. If there are any questions on this submittal, please contact either J. R. Morris at (361) 972-8652 or me at (361) 972-7849.

A handwritten signature in black ink, appearing to read "E. D. Halpin".

E. D. Halpin
Plant General Manager

Attachment: LER 01-001 (South Texas, Unit 1)

JE22

cc:

Ellis W. Merschhoff
Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, Texas 76011-8064

Mohan C. Thadani
Addressee Only
U. S. Nuclear Regulatory Commission
Project Manager, Mail Stop OWFN/7-D-1
Washington, DC 20555-0001

Cornelius F. O'Keefe
U. S. Nuclear Regulatory Commission
P. O. Box 289, Mail Code MN116
Wadsworth, TX 77483

A. H. Gutterman, Esquire
Morgan, Lewis & Bockius
1800 M. Street, N.W.
Washington, DC 20036-5869

M. T. Hardt/W. C. Gunst
City Public Service
P. O. Box 1771
San Antonio, TX 78296

A. Ramirez/C. M. Canady
City of Austin
Electric Utility Department
721 Barton Springs Road
Austin, TX 78704

Jon C. Wood
Matthews & Branscomb
112 East Pecan, Suite 1100
San Antonio, Texas 78205-3692

Institute of Nuclear Power
Operations - Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957

Richard A. Ratliff
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

R. L. Balcom/D. G. Tees
Reliant Energy, Inc.
P. O. Box 1700
Houston, TX 77251

C. A. Johnson/R. P. Powers
AEP - Central Power and Light Company
P. O. Box 289, Mail Code: N5022
Wadsworth, TX 77483

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555-0001

LICENSEE EVENT REPORT (LER)(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E8), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME
South Texas Unit 1**2. DOCKET NUMBER**
05000 498**3. PAGE**
1 OF 8**4. TITLE**
Failure of Essential Cooling Water Pump 1C Following Maintenance

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
09	24	2001	2001	01	00	11	19	2001	FACILITY NAME	DOCKET NUMBER
										05000
									FACILITY NAME	DOCKET NUMBER
										05000
9. OPERATING MODE		1	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR : (Check all that apply)							
10. POWER LEVEL		094	20.2201(b)		20.2203(a)(3)(ii)		50.73(a)(2)(ii)(B)		50.73(a)(2)(ix)(A)	
			20.2201(d)		20.2203(a)(4)		50.73(a)(2)(iii)		50.73(a)(2)(x)	
			20.2203(a)(1)		50.36(c)(1)(i)(A)		50.73(a)(2)(iv)(A)		73.71(a)(4)	
			20.2203(a)(2)(i)		50.36(c)(1)(ii)(A)		50.73(a)(2)(v)(A)		73.71(a)(5)	
			20.2203(a)(2)(ii)		50.36(c)(2)		50.73(a)(2)(v)(B)		OTHER Specify in Abstract below or in NRC Form 366A	
			20.2203(a)(2)(iii)		50.46(a)(3)(ii)		50.73(a)(2)(v)(C)			
			20.2203(a)(2)(iv)		50.73(a)(2)(i)(A)		50.73(a)(2)(v)(D)			
			20.2203(a)(2)(v)		X 50.73(a)(2)(i)(B)		50.73(a)(2)(vii)			
			20.2203(a)(2)(vi)		50.73(a)(2)(i)(C)		50.73(a)(2)(viii)(A)			
			20.2203(a)(3)(i)		50.73(a)(2)(ii)(A)		50.73(a)(2)(viii)(B)			

12. LICENSEE CONTACT FOR THIS LERNAME
J. R. MorrisTELEPHONE NUMBER (Include Area Code)
361-972-8652**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX
A	BI	PUMP	H127	NO					

14. SUPPLEMENTAL REPORT EXPECTED

YES (If yes, complete EXPECTED SUBMISSION DATE)	X	NO	15. EXPECTED SUBMISSION DATE	MONTH	DAY	YEAR

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On September 17, 2001, Unit 1 was in Mode 1 in coastdown operations in preparation for a refueling outage. A Train C Essential Cooling Water system outage was entered at 0200 hours in order to perform scheduled maintenance. On September 21, 2001, the Train C Essential Cooling Water pump was started in order to perform post-maintenance surveillance testing. The pump ran for approximately 10 minutes with what was thought to be adequate cooling and lubrication water flow. At approximately 2106 hours, the pump was manually stopped when output pressure dropped to zero. The pump was observed to come to an abrupt stop. Subsequent investigation identified that significant damage had occurred to the No. 2 pump bearing, and the lower pump shaft exhibited indications of overheating. The root cause of the pump damage was determined to be foreign material, which caused insufficient cooling/lubricating flow by obstructing the bearing flow orifices. Because pump repair time would exceed the 7-day Allowed Outage Time of Technical Specification 3.7.4, enforcement discretion was requested to permit continued operation of the unit while the pump was repaired. Enforcement discretion was granted on September 23 at 1800 hours. Repair work was completed and on September 26, 2001 at 0905 hours the Train C Essential Cooling Water system and the associated systems it supports were restored to operable status.

Corrective actions include revising operating procedures to contain additional pump stop criteria based on indicated lube water flow, and revising maintenance procedures to add specific foreign material exclusion/cleaning requirements prior to pump reassembly.

This event was reviewed for risk impact and found to be risk insignificant since the conditional core damage probability was approximately 8.24E-7.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
South Texas Unit 1	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2	OF 8
		2001	01	00		

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

DESCRIPTION OF EVENT

Overview - On September 17, 2001, Unit 1 was in Mode 1 in coastdown operations in preparation for a refueling outage. At 0200 hours, the Allowed Outage Time for the Unit 1 Train C Essential Cooling Water pump was entered to begin work to overhaul the pump for corrective maintenance. On September 21, 2001, following the maintenance overhaul, the Train C Essential Cooling Water pump lost discharge pressure during a dynamic fill and vent evolution. The pump ran for approximately 10 minutes with what was thought to be adequate cooling and lubrication water flow. At approximately 2106 hours, the pump was manually stopped when output pressure dropped to zero. The pump was observed to come to an abrupt stop. Subsequent investigation into the loss of discharge pressure identified that the No. 2 pump bearing and associated bearing housing exhibited evidence of severe overheating. Lubricating flow orifices could not be seen due to the extent of the bearing damage and steel wires were found on the inside of the bearing.

Because pump repair work was projected to extend beyond the 7-day Allowed Outage Time for the Train C Essential Cooling Water pump, which would expire on September 24, 2001, at 0200 hours, enforcement discretion was requested to permit repairs to continue without requiring a shutdown of the unit. The Nuclear Regulatory Commission granted enforcement discretion on September 23, 2001, at 1800 hours. Maintenance and testing were completed and the Train C Essential Cooling Water pump was restored to operable status and Technical Specification Limiting Conditions for Operation 3.5.2, 3.5.6, 3.6.2.1, 3.6.2.3, 3.7.3, 3.7.4, 3.7.7, and 3.7.14 were exited on September 26, 2001, at 0905 hours.

Detailed Event Description - The Train C Essential Cooling Water (ECW) pump had been placed on increased frequency testing in May 2001 due to decreased output. Results of the testing confirmed that developed head had degraded from the reference value. On September 17, 2001 work began to overhaul the pump and increase its operating performance. During day shift, the pump was removed from the ECW system, open pipe ends were covered to prevent entrance of foreign materials, and the pump was transported to the Mechanical Maintenance shop. The pump was disassembled on night shift. As part of the planned maintenance, several parts of the pump were taken to the blast yard where they were sandblasted and a Belzona coating applied per an associated design change package. The parts included the outer columns, inner columns (enclosing tubes), diffuser, suction volute, and impeller. Inspection of the pump internals then began as outlined in the maintenance procedure work instructions. This inspection continued through the next three shifts.

During day shift on September 19, 2001, the remaining parts were returned from the blast yard, inspections were completed and parts were readied for reassembly. In order to prepare the upper and lower inner columns (enclosing tubes) for reassembly, the scale buildup on each end's mating surface was removed. A wire cup brush attached to an air grinder was used to remove the scale buildup. The inside of the tubes was not cleaned following completion of the wire brushing. Reassembly of the pump began during the night shift. As part of the check for cleanness of parts, Mechanical Maintenance personnel visually checked the inside of both the upper and lower enclosing tubes, however no foreign material was detected due to the layer of dark-colored uneven scale inside the tubes.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE		
South Texas Unit 1	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3	OF	8
		2001	01	00			

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

DESCRIPTION OF EVENT (continued)

A step to ensure cleanness and condition of parts was a check off in the pump maintenance procedure and was also a signoff step in the work order data package. However, the maintenance procedure did not refer the user to the Control of System Cleanness during Maintenance procedure, which describes cleaning techniques and provides cleanness acceptance criteria.

The work order controlling the pump maintenance contained a reference to the system cleanness requirements and identified the appropriate cleanness class for the ECW system. The reference section of the work order listed the Control of System Cleanness procedure as the source document for the cleanness class. The Control of System Cleanness procedure contains Addenda describing the acceptance criteria for cleanness as well as the cleaning methods to be used by craftsmen.

The Control of System Cleanness during Maintenance procedure also requires the work planner to establish a Maintenance Verification Point (MVP), where appropriate, in the work control document. The MVP heightens awareness for an important task. Although the procedure requires the work planner to insert an MVP for the visual verification of acceptable cleanness for the type of work performed on the ECW pump, MVPs were not established in the work package.

Reassembly of the pump was completed during day shift of September 20, 2001, and the pump was transported back to the Train C system and set in place. On night shift, the motor was set in place and alignment of pump and motor began. The alignment, coupling, and repacking of the pump were completed during day shift of September 21, 2001. The shaft rotated freely by hand and the Equipment Clearance Order was released.

The Train C ECW Pump was started locally from the Train C Switchgear Room for a Post Maintenance Test during night shift on September 21, 2001. This start was being performed in accordance with the ECW system operating procedure, which governs the fill and vent of the system. Pump discharge pressure immediately increased to 65 psig and flow was indicated on system heat exchanger return flow indicators. Local operators, who were at the pump and in the Switchgear Room, reported a good start based on a discharge pressure of about 60 psig, water flow from the Lube Water Filter Common Outlet Vent Valve, adequate seal leakoff coming from the pump packing, good oil level, and stable motor current at approximately 60 amperes.

As required by the fill and vent procedure, Instrumentation & Control (I&C) Technicians were asked to vent the lube water flow and filter differential pressure gauges. After venting, both gauges indicated zero. When this condition was reported to the Control Room, the operator at the pump was requested to recheck pump seal leakoff. The operator and maintenance personnel verified sufficient seal leakoff flow. At that point, the I&C Technicians were again asked to vent the lube water flow and filter differential pressure gauges. Both gauges still read zero after this second venting.

Shortly thereafter, and approximately 10 minutes after pump start, the pump discharge pressure dropped from 63 to 0 psig. A noise was heard in the area of the pump which personnel in the area believed to be the check valve closing. The mechanics noted seal leakoff flow stop. The local operator at the pump requested an immediate shutdown. System flows as indicated on the heat exchanger return flow indicators also were noted to have dropped to zero. The local operator in the

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
South Texas Unit 1	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4	OF 8
		2001	01	00		

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

DESCRIPTION OF EVENT (continued)

Switchgear Room then opened the pump's breaker, and the mechanics observed the pump shaft come to an abrupt stop.

The pump was removed and disassembled on September 22, 2001. It was determined that significant damage had occurred to the Train C ECW pump. Bearing No. 2 was bonded to the pump shaft and the bearing housing of the "spider assembly" was out-of-round due to overheating. The spider assembly is a structural member of the pump casing that maintains the shaft in the centerline of the pump and contains the No. 2 bearing housing. The bearing flow orifices could not be seen due to the extensive bearing damage. The lower pump shaft also exhibited evidence of extreme overheating.

Investigation determined that the wire cup brush, used during pump overhaul, threw filaments during the normal course of use into the inside of the inner columns (enclosing tubes). The wire brush filaments (foreign material) caused insufficient cooling/lubricating flow by blocking or obstructing the bearing flow orifices. The lack of cooling caused significant heating and thermal expansion of the bearing and the shaft which in turn caused the shaft to bind in the shaft casing, ultimately causing the pump shaft to stop.

CAUSE OF EVENT

Root Cause:

The cause of the Train C Essential Cooling Water pump failure following overhaul maintenance was foreign material intrusion. The root cause of the foreign material intrusion was less than adequate implementation of the Foreign Material Exclusion program.

The wire cup brush threw filaments, during the normal course of use, into the inside of the inner columns (enclosing tubes). The wire brush filaments (foreign material) caused insufficient cooling/lubricating flow by blocking or obstructing the bearing flow orifices.

Foreign material prevention activities described in station procedures were not followed. No actions were taken to prevent the filaments from entering the inner columns during cleaning of the mating surfaces. No actions were taken to clean the inside of the inner columns prior to reassembly to remove the wire filaments.

Contributing Causes:

- The work package, pump maintenance procedure, and cleanliness procedure, as implemented during the task, did not provide sufficient controls to prevent the introduction of foreign material.
- The craftsmen did not follow the cleanliness procedure providing direction and control for preventing foreign material from entering plant equipment/systems. The cleanliness procedure was not directly referenced in the pump maintenance procedure and was only listed as a source document in the work order.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE		
South Texas Unit 1	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5	OF	8
		2001	01	00			

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

CAUSE OF EVENT (continued)

- Work planners and Supervisors did not provide Maintenance Verification Points (MVP) in the work instructions to heighten personnel awareness to the cleanliness inspection as required by the cleanliness procedure.
- The performance of the cleanliness inspection was inadequate. The visual inspection, as performed, could not detect the small wire filaments that were masked by the buildup of uneven scale lining the inside of the columns, poor lighting and the long length (10 feet) of the columns.

CORRECTIVE ACTIONS

Remedial:

The pump repairs and return to service testing were completed satisfactorily. The work package included additional precautions, steps, and verifications to ensure adequate component and system cleanliness. The pump bearings were flushed prior to returning the pump to the field. Once the pump was reinstalled in the field additional lubrication water flow testing was performed to ensure the flow path was clear and adequate flow achieved. The Train C Essential Cooling Water pump was declared operable on September 26, 2001, at 0905 hours.

Compensatory:

This event was discussed with all maintenance supervisors. These discussions reinforced the requirement that work packages be reviewed to assure that required Maintenance Verification Points were included. This action was completed on October 5, 2001.

Corrective:

1. Revise the Essential Cooling Water system operating procedure to require an Essential Cooling Water pump to be stopped if the associated lube water flow indicator does not indicate greater than 3.0 gpm flow within 45 seconds after a pump start, including pump starts for Fill and Vent evolutions. This action was completed on October 12, 2001.
2. Revise the ECW pump maintenance procedure to require specific cleaning instructions for the inside of the columns (enclosing tubes) prior to reassembly of the pump, and incorporate Maintenance Verification Points as required by the Control of System Cleanliness during Maintenance procedure. This action will be completed by November 29, 2001, prior to the overhaul of any other ECW pumps.
3. Brief work planners, supervisors, and craftsmen on their responsibilities for cleanliness requirements, inspections, and MVPs as per the requirements of Control of System Cleanliness during Maintenance procedure. This action is to be completed by November 29, 2001.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
South Texas Unit 1	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	6	OF 8
		2001	01	00		

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

CORRECTIVE ACTIONS (continued)

4. Reinforce station expectations for Foreign Material Exclusion practices during formal training. This action is to be completed by April 25, 2002.

ANALYSIS OF EVENT

This event is reportable per 10 CFR 50.73(a)(2)(i)(B) due to exceeding the 7-day Allowed Outage Time of Technical Specification 3.7.4, Essential Cooling Water System. The Nuclear Regulatory Commission granted enforcement discretion for this condition on September 23, 2001 at 1800 hours.

The quantitative change in core damage probability associated with the Essential Cooling Water pump being out of service for up to an additional 5 days was compared to a qualitative assessment of risk associated with a plant shutdown to comply with Technical Specification 3.7.4. The additional 5 days was preferable to the potential consequences associated with a plant shutdown, and there was no increase in radiological risk. This event was reviewed for risk impact and found to be risk insignificant since the conditional core damage probability (CCDP) was approximately $8.24E-7$.

The Allowed Outage Time for the Train C Essential Cooling Water pump expired on September 24, 2001 at 0200 hours. Essential Cooling Water pump 1C repairs continued without shutting down the Unit, which is a condition prohibited by Technical Specification 3.7.4. The Nuclear Regulatory Commission granted enforcement discretion to allow continued plant operation while Train C ECW pump repairs were completed. Enforcement discretion was also granted from the Action Statement shutdown requirements of the Technical Specifications associated with the systems supported by Essential Cooling Water:

- Technical Specification 3.5.2, Emergency Core Cooling Systems
- Technical Specification 3.5.6, Residual Heat Removal System
- Technical Specification 3.6.2.1, Containment Spray System
- Technical Specification 3.6.2.3, Containment Cooling System
- Technical Specification 3.7.3, Component Cooling Water System
- Technical Specification 3.7.7, Control Room Makeup and Cleanup Filtration System
- Technical Specification 3.7.14, Essential Chilled Water

ADDITIONAL INFORMATION

The following compensatory measures were implemented during the period of enforcement discretion:

The following equipment was verified to be operable or functional during the extended allowed outage period:

- The Technical Support Center Diesel Generator (maintenance and/or testing prohibited).
- The Positive Displacement Charging Pump (maintenance and/or testing prohibited).

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
South Texas Unit 1	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	7	OF 8
		2001	01	00		

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

ADDITIONAL INFORMATION (continued)

The following equipment/lineups were verified to be operable or functional during the extended allowed outage period:

- The circuits required by Technical Specification 3.8.1.1.a (circuits between the offsite transmission network and the onsite Class 1E Distribution System).
- The two remaining onsite power sources required by Technical Specification LCO 3.8.1.1.b (standby diesel generators and each separate fuel tank).
- The equipment specified by Technical Specification 3.8.1.1 Action d (All required systems, subsystems, trains, components, and devices that depend on the remaining OPERABLE diesel generator and the steam-driven auxiliary feedwater pump).
- The two supporting Essential Cooling Water loops required by Technical Specification LCO 3.7.4.
- The circuit between the 138KV offsite transmission network, via the Emergency Transformer, and the onsite Class 1E Distribution System.
- The 138KV line from Blessing to STP or the 138KV line from Lane City to Bay City (both must be in service).
- Maintenance activities in the switchyard that could directly cause a Loss of Offsite Power event were prohibited.
- Maintenance activities that could result in an inoperable open containment penetration were prohibited.

Additional Specific Actions Implemented to Address the Train C ECW Pump Failure

- In the event of a Loss of Offsite Power (LOOP), the STP procedure for the loss of any 13.8 kV or 4.16 kV Bus provides the specific steps required to cross-connect the Train C Engineered Safety Features (ESF) bus power to an alternate emergency power source by back-feeding through an ESF transformer to the Emergency Bus. Loading on the ESF Bus is restricted to the 480 VAC ESF Load Centers, one centrifugal charging pump and its associated cubicle cooler, two Class 1E battery chargers and the 25 KVA TMI inverter.
- Instructions have been prepared for Operations personnel to use a permanently installed piping cross-connect that exists between the ECW trains. These instructions detail actions to take in the event of a LOOP that will allow for one ECW pump to supply cooling water to two Standby Diesel Generators (SDGs). Additional instructions state the necessary steps to allow for one ECW pump to supply cooling water to two trains of Essential Chillers. These actions would only be implemented under emergency conditions.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE		
South Texas Unit 1	05000 498	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	8	OF	8
		2001	01	00			

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

ADDITIONAL INFORMATION (continued)

- Surveillance and planned maintenance activities with the potential to cause a reactor/turbine trip or on-site power interruption in both units were suspended to minimize any potential challenge to safety systems.
- The Control Room personnel were briefed on the above compensatory measures, and Control Room Log entries describing these compensatory measures were made.