

# Response Surface Methodology: Central Composite Designs

BIOE 498/598 PJ

Spring 2022


## Last time: The method of steepest ascent

- ▶ Begin with a FF+CP design.




## Last time: The method of steepest ascent

- ▶ Begin with a FF+CP design.
- ▶ Follow path of steepest ascent until the model breaks.




## Last time: The method of steepest ascent

- ▶ Begin with a FF+CP design.
- ▶ Follow path of steepest ascent until the model breaks.
- ▶ New FF+CP; repeat steepest ascent.




## Last time: The method of steepest ascent

- ▶ Begin with a FF+CP design.
- ▶ Follow path of steepest ascent until the model breaks.
- ▶ New FF+CP; repeat steepest ascent.
- ▶ Stop when model detects lack of fit.



## Last time: The method of steepest ascent

- ▶ Begin with a FF+CP design.
- ▶ Follow path of steepest ascent until the model breaks.
- ▶ New FF+CP; repeat steepest ascent.
- ▶ Stop when model detects lack of fit.
- ▶ **Today:** Fitting a model to a curved response surface.




# When is a first order model not good enough?

- ▶ The FF designs used for process improvement are usually augmented by **center points** — repeated runs at the design center  $(0, 0)$ .
- ▶ Center points serve two purposes:
  1. Estimate the *pure error* via the standard deviation of the repeated runs.
  2. Test for *lack of fit* to detect curvature.

# When is a first order model not good enough?


- ▶ The FF designs used for process improvement are usually augmented by **center points** — repeated runs at the design center  $(0,0)$ .
- ▶ Center points serve two purposes:
  1. Estimate the *pure error* via the standard deviation of the repeated runs.
  2. Test for *lack of fit* to detect curvature.






# When is a first order model not good enough?

- ▶ The FF designs used for process improvement are usually augmented by **center points** — repeated runs at the design center  $(0,0)$ .
- ▶ Center points serve two purposes:
  1. Estimate the *pure error* via the standard deviation of the repeated runs.
  2. Test for *lack of fit* to detect curvature.




# When is a first order model not good enough?

- ▶ The FF designs used for process improvement are usually augmented by **center points** — repeated runs at the design center  $(0,0)$ .
- ▶ Center points serve two purposes:
  1. Estimate the *pure error* via the standard deviation of the repeated runs.
  2. Test for *lack of fit* to detect curvature.



no lack of fit



lack of fit

## Testing for lack of fit due to curvature

We want to compare the degree of curvature to the uncertainty (pure error) in our center points. We compare using a sum-of-squares approach.

# Testing for lack of fit due to curvature

We want to compare the degree of curvature to the uncertainty (pure error) in our center points. We compare using a sum-of-squares approach.

1.  $\bar{y}_{\text{center}}$  = mean response of the  $n_{\text{center}}$  center points  
 $\bar{y}_{\text{fact}}$  = mean response of the  $n_{\text{fact}}$  factorial points

## Testing for lack of fit due to curvature

We want to compare the degree of curvature to the uncertainty (pure error) in our center points. We compare using a sum-of-squares approach.

1.  $\bar{y}_{\text{center}}$  = mean response of the  $n_{\text{center}}$  center points  
 $\bar{y}_{\text{fact}}$  = mean response of the  $n_{\text{fact}}$  factorial points

2.

$$SS_{\text{curve}} = \frac{n_{\text{fact}} n_{\text{center}} (\bar{y}_{\text{fact}} - \bar{y}_{\text{center}})^2}{n_{\text{fact}} + n_{\text{center}}}, \quad DF(SS_{\text{curve}}) = 1$$

## Testing for lack of fit due to curvature

We want to compare the degree of curvature to the uncertainty (pure error) in our center points. We compare using a sum-of-squares approach.

1.  $\bar{y}_{\text{center}}$  = mean response of the  $n_{\text{center}}$  center points  
 $\bar{y}_{\text{fact}}$  = mean response of the  $n_{\text{fact}}$  factorial points

2.

$$SS_{\text{curve}} = \frac{n_{\text{fact}} n_{\text{center}} (\bar{y}_{\text{fact}} - \bar{y}_{\text{center}})^2}{n_{\text{fact}} + n_{\text{center}}}, \quad DF(SS_{\text{curve}}) = 1$$

3.

$$SS_{\text{error}} = \sum_{\substack{\text{center} \\ \text{points}}} (y_i - \bar{y}_{\text{center}})^2, \quad DF(SS_{\text{error}}) = n_{\text{center}} - 1$$

# Testing for lack of fit due to curvature

We want to compare the degree of curvature to the uncertainty (pure error) in our center points. We compare using a sum-of-squares approach.

1.  $\bar{y}_{\text{center}}$  = mean response of the  $n_{\text{center}}$  center points  
 $\bar{y}_{\text{fact}}$  = mean response of the  $n_{\text{fact}}$  factorial points

2.

$$SS_{\text{curve}} = \frac{n_{\text{fact}} n_{\text{center}} (\bar{y}_{\text{fact}} - \bar{y}_{\text{center}})^2}{n_{\text{fact}} + n_{\text{center}}}, \quad \text{DF}(SS_{\text{curve}}) = 1$$

3.

$$SS_{\text{error}} = \sum_{\substack{\text{center} \\ \text{points}}} (y_i - \bar{y}_{\text{center}})^2, \quad \text{DF}(SS_{\text{error}}) = n_{\text{center}} - 1$$

4.

$$F_{\text{curve}} = \frac{SS_{\text{curve}}/\text{DF}(SS_{\text{curve}})}{SS_{\text{error}}/\text{DF}(SS_{\text{error}})}$$

## Example: Testing for curvature (Myers 2009)

temp	time	yield
—	—	39.3
—	+	40.0
+	—	40.9
+	+	41.5
0	0	40.3
0	0	40.5
0	0	40.7
0	0	40.2
0	0	40.6



## Example: Testing for curvature (Myers 2009)

1.  $\bar{y}_{\text{fact}} = (39.3 + 40.0 + 40.9 + 41.5)/4 = 40.425$   
 $\bar{y}_{\text{center}} = (40.3 + 40.5 + 40.7 + 40.2 + 40.6)/5 = 40.46$

temp	time	yield
—	—	39.3
—	+	40.0
+	—	40.9
+	+	41.5
0	0	40.3
0	0	40.5
0	0	40.7
0	0	40.2
0	0	40.6

## Example: Testing for curvature (Myers 2009)

1.  $\bar{y}_{\text{fact}} = (39.3 + 40.0 + 40.9 + 41.5)/4 = 40.425$   
 $\bar{y}_{\text{center}} = (40.3 + 40.5 + 40.7 + 40.2 + 40.6)/5 = 40.46$

2.

$$SS_{\text{curve}} = \frac{4 \times 5 \times (40.425 - 40.46)^2}{4 + 5} = 0.0026$$

temp	time	yield
—	—	39.3
—	+	40.0
+	—	40.9
+	+	41.5
0	0	40.3
0	0	40.5
0	0	40.7
0	0	40.2
0	0	40.6

## Example: Testing for curvature (Myers 2009)

1.  $\bar{y}_{\text{fact}} = (39.3 + 40.0 + 40.9 + 41.5)/4 = 40.425$   
 $\bar{y}_{\text{center}} = (40.3 + 40.5 + 40.7 + 40.2 + 40.6)/5 = 40.46$

2.

$$SS_{\text{curve}} = \frac{4 \times 5 \times (40.425 - 40.46)^2}{4 + 5} = 0.0026$$

3.

$$SS_{\text{error}} = (40.3 - 40.46)^2 + \cdots + (40.6 - 40.46)^2 \\ = 0.172$$

temp	time	yield
—	—	39.3
—	+	40.0
+	—	40.9
+	+	41.5
0	0	40.3
0	0	40.5
0	0	40.7
0	0	40.2
0	0	40.6

## Example: Testing for curvature (Myers 2009)

1.  $\bar{y}_{\text{fact}} = (39.3 + 40.0 + 40.9 + 41.5)/4 = 40.425$   
 $\bar{y}_{\text{center}} = (40.3 + 40.5 + 40.7 + 40.2 + 40.6)/5 = 40.46$

2.

$$SS_{\text{curve}} = \frac{4 \times 5 \times (40.425 - 40.46)^2}{4 + 5} = 0.0026$$

3.

$$SS_{\text{error}} = (40.3 - 40.46)^2 + \cdots + (40.6 - 40.46)^2 \\ = 0.172$$

4.

$$F_{\text{curve}} = \frac{0.0026/1}{0.172/(5-1)} = 0.0605$$

temp	time	yield
—	—	39.3
—	+	40.0
+	—	40.9
+	+	41.5
0	0	40.3
0	0	40.5
0	0	40.7
0	0	40.2
0	0	40.6

## Example: Testing for curvature (Myers 2009)

1.  $\bar{y}_{\text{fact}} = (39.3 + 40.0 + 40.9 + 41.5)/4 = 40.425$   
 $\bar{y}_{\text{center}} = (40.3 + 40.5 + 40.7 + 40.2 + 40.6)/5 = 40.46$

2.

$$SS_{\text{curve}} = \frac{4 \times 5 \times (40.425 - 40.46)^2}{4 + 5} = 0.0026$$

3.

$$SS_{\text{error}} = (40.3 - 40.46)^2 + \dots + (40.6 - 40.46)^2 \\ = 0.172$$

4.

$$F_{\text{curve}} = \frac{0.0026/1}{0.172/(5 - 1)} = 0.0605$$

temp	time	yield
—	—	39.3
—	+	40.0
+	—	40.9
+	+	41.5
0	0	40.3
0	0	40.5
0	0	40.7
0	0	40.2
0	0	40.6

`pf(0.0605, 1, 4, lower.tail=FALSE)`  $\rightarrow p < 0.818$ .

# The steepest ascent method

1. Run a FF design augmented with replicated center points.

# The steepest ascent method

1. Run a FF design augmented with replicated center points.
2. Fit a first order model and check for lack of fit.
  - ▶ If significant lack of fit, switch to Response Surface Methodology.

# The steepest ascent method

1. Run a FF design augmented with replicated center points.
2. Fit a first order model and check for lack of fit.
  - ▶ If significant lack of fit, switch to Response Surface Methodology.
3. Perform runs along the steepest ascent path until the response diminishes.



# The steepest ascent method

1. Run a FF design augmented with replicated center points.
2. Fit a first order model and check for lack of fit.
  - ▶ If significant lack of fit, switch to Response Surface Methodology.
3. Perform runs along the steepest ascent path until the response diminishes.
4. Go to (1) and repeat using the location of maximum response as the new center point.

# The steepest ascent method

1. Run a FF design augmented with replicated center points.
2. Fit a first order model and check for lack of fit.
  - ▶ If significant lack of fit, switch to Response Surface Methodology.
3. Perform runs along the steepest ascent path until the response diminishes.
4. Go to (1) and repeat using the location of maximum response as the new center point.
5. Switch to a **curved** model and *Response Surface Methodology* (RSM).

# Fitting models with curvature

- ▶ We need two things to model a curved response surfaces:
  1. A model that is flexible enough to curve.
  2. Data that can detect the curvature.

# Fitting models with curvature

- ▶ We need two things to model a curved response surfaces:
  1. A model that is flexible enough to curve.
  2. Data that can detect the curvature.
- ▶ The optimal operating conditions correspond to a maximum in the response surface.
- ▶ We need models that can contain maxima.

# Fitting models with curvature

- ▶ We need two things to model a curved response surfaces:
  1. A model that is flexible enough to curve.
  2. Data that can detect the curvature.
- ▶ The optimal operating conditions correspond to a maximum in the response surface.
- ▶ We need models that can contain maxima.
- ▶ FO + TWI models are curved, but are rarely bounded.

# Fitting models with curvature

- ▶ We need two things to model a curved response surfaces:
  1. A model that is flexible enough to curve.
  2. Data that can detect the curvature.
- ▶ The optimal operating conditions correspond to a maximum in the response surface.
- ▶ We need models that can contain maxima.
- ▶ FO + TWI models are curved, but are rarely bounded.

$$y = 20 + 3.6x_1 - 1.8x_2 - 0.6x_1x_2$$

Set  $x_2 = 0$ , then  $y \rightarrow \infty$  as  $x_1 \rightarrow \infty$ .

# Nonlinear response surfaces

- ▶ The *true* model for any system is a general nonlinear function

$$y = f(x_1, x_2, \dots, x_k)$$

# Nonlinear response surfaces

- ▶ The *true* model for any system is a general nonlinear function

$$y = f(x_1, x_2, \dots, x_k)$$

- ▶ If you know  $f$  for your system, congrats! Fit its parameters with regression and use it.



# Nonlinear response surfaces

- ▶ The *true* model for any system is a general nonlinear function

$$y = f(x_1, x_2, \dots, x_k)$$

- ▶ If you know  $f$  for your system, congrats! Fit its parameters with regression and use it.
- ▶ Usually we don't know  $f$ , so we approximate it with a simpler function.

# Nonlinear response surfaces

- ▶ The *true* model for any system is a general nonlinear function

$$y = f(x_1, x_2, \dots, x_k)$$

- ▶ If you know  $f$  for your system, congrats! Fit its parameters with regression and use it.
- ▶ Usually we don't know  $f$ , so we approximate it with a simpler function.
- ▶ **We are not claiming that  $f$  is a particular shape.** Rather, we claim that an approximation is “good enough” over our domain of interest.

## Approximating $f$ with a general quadratic

Let's find the second-order Taylor series of  $f(x_1, x_2)$  centered at zero:

$$f(x_1, x_2) \approx f|_0 + \left. \frac{\partial f}{\partial x_1} \right|_0 x_1 + \left. \frac{\partial f}{\partial x_2} \right|_0 x_2 + \frac{1}{2} \left. \frac{\partial^2 f}{\partial x_1^2} \right|_0 x_1^2 + \frac{1}{2} \left. \frac{\partial^2 f}{\partial x_2^2} \right|_0 x_2^2 + \frac{1}{2} \left. \frac{\partial^2 f}{\partial x_1 \partial x_2} \right|_0 x_1 x_2$$

## Approximating $f$ with a general quadratic

Let's find the second-order Taylor series of  $f(x_1, x_2)$  centered at zero:

$$f(x_1, x_2) \approx \underbrace{f|_0}_{\beta_0} + \underbrace{\frac{\partial f}{\partial x_1} \Big|_0}_{\beta_1} x_1 + \underbrace{\frac{\partial f}{\partial x_2} \Big|_0}_{\beta_2} x_2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_1^2} \Big|_0}_{\beta_{11}} x_1^2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_2^2} \Big|_0}_{\beta_{22}} x_2^2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_1 \partial x_2} \Big|_0}_{\beta_{12}} x_1 x_2$$

- The function  $f$  and its derivatives are unknown, so we fit the parameters  $\beta$  with a linear model.

## Approximating $f$ with a general quadratic

Let's find the second-order Taylor series of  $f(x_1, x_2)$  centered at zero:

$$f(x_1, x_2) \approx \underbrace{f|_0}_{\beta_0} + \underbrace{\frac{\partial f}{\partial x_1} \Big|_0}_{\beta_1} x_1 + \underbrace{\frac{\partial f}{\partial x_2} \Big|_0}_{\beta_2} x_2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_1^2} \Big|_0}_{\beta_{11}} x_1^2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_2^2} \Big|_0}_{\beta_{22}} x_2^2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_1 \partial x_2} \Big|_0}_{\beta_{12}} x_1 x_2$$

$$f(x_1, x_2) \approx \beta_0 + \beta_1 x_1 + \beta_2 x_2 + \beta_{11} x_1^2 + \beta_{22} x_2^2 + \beta_{12} x_1 x_2$$

- The function  $f$  and its derivatives are unknown, so we fit the parameters  $\beta$  with a linear model.

## Approximating $f$ with a general quadratic

Let's find the second-order Taylor series of  $f(x_1, x_2)$  centered at zero:

$$f(x_1, x_2) \approx \underbrace{f|_0}_{\beta_0} + \underbrace{\frac{\partial f}{\partial x_1} \Big|_0}_{\beta_1} x_1 + \underbrace{\frac{\partial f}{\partial x_2} \Big|_0}_{\beta_2} x_2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_1^2} \Big|_0}_{\beta_{11}} x_1^2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_2^2} \Big|_0}_{\beta_{22}} x_2^2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_1 \partial x_2} \Big|_0}_{\beta_{12}} x_1 x_2$$

$$f(x_1, x_2) \approx \underbrace{\beta_0 + \beta_1 x_1 + \beta_2 x_2}_{\text{FO}} + \underbrace{\beta_{11} x_1^2 + \beta_{22} x_2^2}_{\text{PQ}} + \underbrace{\beta_{12} x_1 x_2}_{\text{TWI}}$$

SO

- The function  $f$  and its derivatives are unknown, so we fit the parameters  $\beta$  with a linear model.

## Approximating $f$ with a general quadratic

Let's find the second-order Taylor series of  $f(x_1, x_2)$  centered at zero:

$$f(x_1, x_2) \approx \underbrace{f|_0}_{\beta_0} + \underbrace{\frac{\partial f}{\partial x_1} \Big|_0}_{\beta_1} x_1 + \underbrace{\frac{\partial f}{\partial x_2} \Big|_0}_{\beta_2} x_2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_1^2} \Big|_0}_{\beta_{11}} x_1^2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_2^2} \Big|_0}_{\beta_{22}} x_2^2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_1 \partial x_2} \Big|_0}_{\beta_{12}} x_1 x_2$$

$$f(x_1, x_2) \approx \underbrace{\beta_0 + \beta_1 x_1 + \beta_2 x_2}_{\text{FO}} + \underbrace{\beta_{11} x_1^2 + \beta_{22} x_2^2}_{\text{PQ}} + \underbrace{\beta_{12} x_1 x_2}_{\text{TWI}}$$

SO

- ▶ The function  $f$  and its derivatives are unknown, so we fit the parameters  $\beta$  with a linear model.
- ▶ In general we will have  $k$  factors and the quadratic approximation will be

$$y = \beta_0 + \sum_{i=1}^k \beta_i x_i + \sum_{i=1}^k \beta_{ii} x_i^2 + \sum_{j=1}^k \sum_{i=1}^{j-1} \beta_{ij} x_i x_j.$$

## Approximating $f$ with a general quadratic

Let's find the second-order Taylor series of  $f(x_1, x_2)$  centered at zero:

$$f(x_1, x_2) \approx \underbrace{f|_0}_{\beta_0} + \underbrace{\frac{\partial f}{\partial x_1}|_0}_{\beta_1} x_1 + \underbrace{\frac{\partial f}{\partial x_2}|_0}_{\beta_2} x_2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_1^2}|_0}_{\beta_{11}} x_1^2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_2^2}|_0}_{\beta_{22}} x_2^2 + \underbrace{\frac{1}{2} \frac{\partial^2 f}{\partial x_1 \partial x_2}|_0}_{\beta_{12}} x_1 x_2$$

$$f(x_1, x_2) \approx \underbrace{\beta_0 + \beta_1 x_1 + \beta_2 x_2}_{\text{FO}} + \underbrace{\beta_{11} x_1^2 + \beta_{22} x_2^2}_{\text{PQ}} + \underbrace{\beta_{12} x_1 x_2}_{\text{TWI}}$$

SO

- ▶ The function  $f$  and its derivatives are unknown, so we fit the parameters  $\beta$  with a linear model.
- ▶ In general we will have  $k$  factors and the quadratic approximation will be

$$y = \beta_0 + \sum_{i=1}^k \beta_i x_i + \sum_{i=1}^k \beta_{ii} x_i^2 + \sum_{j=1}^k \sum_{i=1}^{j-1} \beta_{ij} x_i x_j.$$

- ▶ This model has  $1 + 2k + k(k-1)/2$  parameters, so RSM designs must have at least this many runs.





# The Central Composite Design (CCD)


- ▶ A factorial or FF design can estimate FO and TWI terms.
- ▶ Estimating curvature requires points beyond the factorial corners.
- ▶ One popular option is the **Central Composite Design**.

# The Central Composite Design (CCD)

- ▶ A factorial or FF design can estimate FO and TWI terms.
- ▶ Estimating curvature requires points beyond the factorial corners.
- ▶ One popular option is the **Central Composite Design**.




## Parts of the CCD




- Factorial points alone estimates the FO and TWI terms. The core must be Resolution V or higher.

## Parts of the CCD




- ▶ Factorial points alone estimates the FO and TWI terms. The core must be Resolution V or higher.
- ▶ Axial points allow estimation of the PQ terms. Without axial points we could only estimate the sum of all PQ terms.

## Parts of the CCD




- ▶ Factorial points alone estimates the FO and TWI terms. The core must be Resolution V or higher.
- ▶ Axial points allow estimation of the PQ terms. Without axial points we could only estimate the sum of all PQ terms.
- ▶ CCDs have a pair of axial runs for each factor:

## Parts of the CCD




- ▶ Factorial points alone estimates the FO and TWI terms. The core must be Resolution V or higher.
- ▶ Axial points allow estimation of the PQ terms. Without axial points we could only estimate the sum of all PQ terms.
- ▶ CCDs have a pair of axial runs for each factor:
  - ▶ One factor is set to  $\pm\alpha$

## Parts of the CCD



- ▶ Factorial points alone estimates the FO and TWI terms. The core must be Resolution V or higher.
- ▶ Axial points allow estimation of the PQ terms. Without axial points we could only estimate the sum of all PQ terms.
- ▶ CCDs have a pair of axial runs for each factor:
  - ▶ One factor is set to  $\pm\alpha$
  - ▶ All other factors are set to 0.


## Parts of the CCD



- ▶ Factorial points alone estimates the FO and TWI terms. The core must be Resolution V or higher.
- ▶ Axial points allow estimation of the PQ terms. Without axial points we could only estimate the sum of all PQ terms.
- ▶ CCDs have a pair of axial runs for each factor:
  - ▶ One factor is set to  $\pm\alpha$
  - ▶ All other factors are set to 0.
- ▶ Center points estimate pure error and help (some) with PQ terms.




# Parts of the CCD




- ▶ Factorial points alone estimates the FO and TWI terms. The core must be Resolution V or higher.
- ▶ Axial points allow estimation of the PQ terms. Without axial points we could only estimate the sum of all PQ terms.
- ▶ CCDs have a pair of axial runs for each factor:
  - ▶ One factor is set to  $\pm\alpha$
  - ▶ All other factors are set to 0.
- ▶ Center points estimate pure error and help (some) with PQ terms.
- ▶ To build a CCD you need to decide:

# Parts of the CCD




- ▶ Factorial points alone estimates the FO and TWI terms. The core must be Resolution V or higher.
- ▶ Axial points allow estimation of the PQ terms. Without axial points we could only estimate the sum of all PQ terms.
- ▶ CCDs have a pair of axial runs for each factor:
  - ▶ One factor is set to  $\pm\alpha$
  - ▶ All other factors are set to 0.
- ▶ Center points estimate pure error and help (some) with PQ terms.
- ▶ To build a CCD you need to decide:
  1. The size of the FF core

# Parts of the CCD



- ▶ Factorial points alone estimates the FO and TWI terms. The core must be Resolution V or higher.
- ▶ Axial points allow estimation of the PQ terms. Without axial points we could only estimate the sum of all PQ terms.
- ▶ CCDs have a pair of axial runs for each factor:
  - ▶ One factor is set to  $\pm\alpha$
  - ▶ All other factors are set to 0.
- ▶ Center points estimate pure error and help (some) with PQ terms.
- ▶ To build a CCD you need to decide:
  1. The size of the FF core
  2. The number of center runs

# Parts of the CCD




- ▶ Factorial points alone estimates the FO and TWI terms. The core must be Resolution V or higher.
- ▶ Axial points allow estimation of the PQ terms. Without axial points we could only estimate the sum of all PQ terms.
- ▶ CCDs have a pair of axial runs for each factor:
  - ▶ One factor is set to  $\pm\alpha$
  - ▶ All other factors are set to 0.
- ▶ Center points estimate pure error and help (some) with PQ terms.
- ▶ To build a CCD you need to decide:
  1. The size of the FF core
  2. The number of center runs
  3. The value of  $\alpha$

# Uniform precision

- ▶ A model has **uniform precision** if the variance at design radius 1 is the same as at the center.


# Uniform precision

- ▶ A model has **uniform precision** if the variance at design radius 1 is the same as at the center.



# Uniform precision

- ▶ A model has **uniform precision** if the variance at design radius 1 is the same as at the center.



- ▶ Choosing the correct number of center points in a CCD ensures uniform precision.

# Rotatable designs

- ▶ Models are most precise at the center of the design.



# Rotatable designs

- ▶ Models are most precise at the center of the design.
- ▶ Ideally, the change in precision should be independent of the *direction* we move away from the center.

# Rotatable designs

- ▶ Models are most precise at the center of the design.
- ▶ Ideally, the change in precision should be independent of the *direction* we move away from the center.




FIG. 2. Variance contours for some 2 dimensional designs

Image from Box and Hunter 1957.

# Rotatable designs

- ▶ Models are most precise at the center of the design.
- ▶ Ideally, the change in precision should be independent of the *direction* we move away from the center.




FIG. 2. Variance contours for some 2 dimensional designs

Image from Box and Hunter 1957.

- ▶ Designs where the variance only depends on the radius are called **rotatable designs**.

# Rotatable designs

- ▶ Models are most precise at the center of the design.
- ▶ Ideally, the change in precision should be independent of the *direction* we move away from the center.




FIG. 2. Variance contours for some 2 dimensional designs

Image from Box and Hunter 1957.

- ▶ Designs where the variance only depends on the radius are called **rotatable designs**.
- ▶ A CCD with  $F$  factorial points is rotatable when  $\alpha = \sqrt[4]{F}$ .

## Rotatable, uniform precision CCDs

factors ( $k$ )	2	3	4	5	5 - 1	6
factorial points	4	8	16	32	16	64
axial points	4	6	8	10	10	12
center points	5	6	7	10	6	15
axial distance ( $\alpha$ )	1.414	1.682	2.000	2.378	2.000	2.828

factors ( $k$ )	6 - 1	7	7 - 1	8	8 - 1	8 - 2
factorial points	32	128	64	256	128	64
axial points	12	14	14	16	16	16
center points	9	21	14	28	20	13
axial distance ( $\alpha$ )	2.378	3.364	2.828	4.000	3.364	2.828

## Factor levels in a CCD

Each factor in the CCD will be set at five levels:

$$-\alpha \quad -1 \quad 0 \quad 1 \quad \alpha$$

## Factor levels in a CCD

Each factor in the CCD will be set at five levels:

$$-\alpha \quad -1 \quad 0 \quad 1 \quad \alpha$$

Unlike a 2-level design, the coded units in a CCD have meaning!

## Coding the CCD

Let's say we're designing a combination screening of three drugs. The absolute widest concentration range we can use for drug A is  $[-3.2, 1.0]$  on a  $\log_{10}$ - $\mu\text{M}$  scale. What are the five levels assuming a full-factorial CCD?



## Coding the CCD

Let's say we're designing a combination screening of three drugs. The absolute widest concentration range we can use for drug A is  $[-3.2, 1.0]$  on a  $\log_{10}$ - $\mu\text{M}$  scale. What are the five levels assuming a full-factorial CCD?

$$F = 2^3 = 8 \Rightarrow \alpha = \sqrt[4]{8} = 1.68$$

# Coding the CCD

Let's say we're designing a combination screening of three drugs. The absolute widest concentration range we can use for drug A is  $[-3.2, 1.0]$  on a  $\log_{10}$ - $\mu\text{M}$  scale. What are the five levels assuming a full-factorial CCD?

$$F = 2^3 = 8 \Rightarrow \alpha = \sqrt[4]{8} = 1.68$$

$$\begin{aligned} A &= \text{center}(A) + \frac{\text{range}(A)}{2\alpha}[\text{code}] \\ &= -1.1 + \frac{1 - (-3.2)}{2(1.68)}[\text{code}] \end{aligned}$$

## Coding the CCD

Let's say we're designing a combination screening of three drugs. The absolute widest concentration range we can use for drug A is  $[-3.2, 1.0]$  on a  $\log_{10}$ - $\mu\text{M}$  scale. What are the five levels assuming a full-factorial CCD?

$$F = 2^3 = 8 \Rightarrow \alpha = \sqrt[4]{8} = 1.68$$

$$\begin{aligned} A &= \text{center}(A) + \frac{\text{range}(A)}{2\alpha}[\text{code}] \\ &= -1.1 + \frac{1 - (-3.2)}{2(1.68)}[\text{code}] \end{aligned}$$

code:	$-\alpha$	$-1$	$0$	$1$	$\alpha$
$\log_{10}$ - $\mu\text{M}$ :	$-3.2$	$-2.4$	$-1.1$	$0.2$	$1.0$