





# ZQM UMA(14")

## Intel Bay Trail-M Platform Block Diagram

PCB 6L STACK UP



LAYER 1 : TOP  
LAYER 2 : SVCC  
LAYER 3 : IN1(High)  
LAYER 4 : IN2(Low)  
LAYER 5 : SGND  
LAYER 6 : BOT









20140114:change R139 from 10K to 200K for power leakage issue
























Address A2H




M\_B\_DQ[63:0] (3)

2.48A



(3) M\_B\_DRAMRST#

(11) +SMDDR\_VREF\_DQ

(11) +SMDDR\_VREF\_DIMM





## For EMI RESERVE



Place these Caps near So-Dimm1

0.1uF/10uF 4pcs on each side of connector






Quanta Computer Inc.


PROJECT : ZQM

Size Document Number  
DDR3 DIMM1-STD(5.2H)

Date: Wednesday, April 02, 2014 Sheet 12 of 34




Touch Panel level shift










EMU_LID	Touch Pad Function
H	OK
L	No Function


HDMI Conn.

EMI (EMC)







## KEYBOARD (KBC)



<EMI>




## INTERNAL KEYBOARD STRIP SET (KBC)




UnStuff



## KB\_BL LED (KBL)



## CRT









# USB HUB


17



# HOLE(OTH)



# USB DB CONNECTOR




**Quanta Computer Inc.**

**PROJECT : ZQM**


Size	Document Number	Rev
	<b>USB BOARD CONN</b>	C3C
Date:	Wednesday, April 02, 2014	Sheet 17 of 34




## Codec(ADO)




## Codec PWR 5V(ADO)




### Codec PWR 1.5V(ADO)




## Internal Speaker




## Grounding circuit(ADO)




### D-Mic (MIC)




### HEADPHONE/MIC/LINE combo




## Mute(ADO)



## Level shift







### CARD READER CONNECTOR (CRD)



#### Share Pin

SP1	SD_D7	MS_INS#	xD_RDY
SP2	SD_D6	MS_INS#	xD_CS#
SP3	SD_D5	MS_INS#	xD_CS#
SP4	SD_D4	MS_INS#	xD_CS#
SP5	SD_D1	MS_CLK	xD_D6
SP6	SD_D0	MS_D7	xD_D5
SP7	SD_CLK	MS_D3	xD_D4
SP8	SD_CMD	MS_D5	xD_D3
SP9	SD_D3	MS_D2	xD_D2
SP10	SD_D2	MS_D1	xD_D1
SP11	MS_BS	xD_CLE	
SP12	SD_WP	MS_D1	xD_WP#
SP13	SD_CD#	MS_D5	xD_ALE
SP14	MS_D4	xD_D0	
SP15	MS_D0	xD_D1	
SP16	MS_D0	xD_CD#	


### SD/MMC CARD READER (CRD)




vendor suggest change to 91 ohm when use GL834L-04, PN is CS09092FB15




2014/03/03  
1. This resistor is for bead solution to reduce signal voltage in GL834L-03.  
2. We modified SD signal driving ability from GL834L-03 to GL834L-04  
and change solution from bead to resistor  
3. Then this resistor maybe make some USB-C card  
compatibility fail in GL834L-04, so must remove this resistor.






**TPM (TPM)**






G547E2P81U: Enable: Low Active /2.5A



Quanta confidential




**EC 985LB1(KBC)**  
**1.8V interface**




985LB1 Pin88


20130606 Colay with 985L




23




## SM BUS PU(KBC)




20130709 leakage issue for EC SMBus +3V\_S5  
(Pull high +3V at page 12)



**SPI NOR FLASH**



**HWPG(KBC)**




<20130722>Change power from +3V to +3V S5 for power sequence issue




### SM BUS ARRANGEMENT TABLE

SM Bus 1	Battery
SM Bus 2	PCH
SM Bus 3	GPU



# Bay Trail-M S4/S5 to S0 (Power Up) Sequence


24






C3 test change to show

+5 Volt +/- 5%  
Continue current: 5.5A  
Peak current: 7.3A  
OCP minimum: A



ZQM C3 test change to short pad


**+1.8V Volt +/- 5%**  
**Countinue current:0.08A**  
**Peak current:0.11A**  
**OCF minimum:A**



**PROJECT : W03Z**  
**Quanta Computer Inc.**



Size Custom	Document Number <b>+1.8VPCU</b>	Rev C3C
Date: Wednesday, April 02, 2014	Sheet 27 of 34	

+1.0V Volt +/- 5%  
 Countinue current:2.3A  
 Peak current:3.1A  
 OCP minimum:A



2013/09/09 LDO for 1.35V

ZQM C3 test change to short pad







**Quanta Computer Inc.**  
**PROJECT : ZQM**

Size	Document Number	Rev
	<b>+1.05V/1.5V</b>	C3C
Date:	Wednesday, April 02, 2014	Sheet 29 of 34




20130617 Change +1.05V to +1.0V


20M C3 test change to short pad




ZQM C3 test change to short pad



Q3 test change to short pad





Need fine tune  
for thermal protect point  
Note placement position

**Temp = 84C**

**For EC control thermal protection (output 3.3V)**

Model	Date	CHANGE LIST
ZQM REV:A ZQM REV:B		1. FIRST RELEASED
	12/12	Change SPK connector,power FFC connector,LED footprint Change audio jack PN change audio RST circuit back to previous version and reserve D31,R185 and Q21
	12/16	Delete PC171 for power space not enough issue.
ZQM REV:C	12/18	SWAP CN14, Del Hole17 change Hole27 footprint change Hole5,Hole7,Hole25,Hole29 footprint stuff R175,R182,R186,R189 of HDMI for EMI stuff C228 for AudioI for EMI
	01/10	reserve 3V_S5 for touch pad power for Acer request to design design power add 3VSUS circuit for touch pad to use
	01/14	change R139 from 10K to 200K and del R12 for 3V power leakage issue change R115 from 47K to 10K for S5_ON signal, for PUL power enable level issue.
	01/16	change D11 PN to BCBAT54CZ13, footprint to sot323 213-2 1-1 3-2n7002w for small package and cost down change R461,R462 from 4.7K to 2.2K for intel document suggestion for 400KHz pull high signal. add Nuvoton TPM NPCT650 to colay with SLB9655
	01/17	change CN9 footprint to mipci-800055fb052gx00pl-52p-smt for SMT request change PUL1 footprint to qfn32-4x4-4-33p-is195812hrz-smt for SMT request change USB hub RESET pin from R/C to PLTRST#, because +3V_S5 power will keep even power off system in AC mode change R145 from 10K to 200K and del R149 to prevent the voltage of Q13 pin 1 is too low to turn on 2N7002K issue for PCH_EDP_BLON
	01/20	reserve power control circuit by EC card reade for Acer's request reserve power control signal of EC GPIO 52 for card reade for Acer's request modify U5 power to main level
	01/21	del power jumper change PU7 and PU8 PN to AL008068000 change R282 to 619 ohm for USB eye diagram.
	01/23	change card reader RESET from PLTRST# to R/C for S3 resume issue by jack's suggestion
	02/05	change R469 and R471 from 33 ohm to 220 ohm for ME request change U10 to Rev 4 and change R252-R257 from bead to 91 ohm for vendor's suggestion. update function code.
	02/07	reserve R175,R182,R186,R189 of HDMI for SDA HDMI fail.
	02/13	change PUL.2 from SUSON to TP_POWER_ON change PQ28.1 from +3VSUS to +TPVDD change all +3VSUS to +TPVDD.(TP and TPM) use EC GPIO50 to control TP power for Acer's request reserve +3VPCU for LED1.2 for leakage issue
	02/18	change 0 ohm to short pad SWAP R233 and L16, R285 and L19 by vendor's suggestion.
	02/19	change L16 and L19 footprint to 0402 size
	02/24	reserve GPIO34 as PCH_EDP_BLON for EC checking backlight on timing
	02/25	add hole 30 and del hole 21 for ME request
ZQM REV:Ramp	02/27	change LED PN from BEB00028ZA0 to BEB00011ZA5 for Vf issue. change R469 and R471 from 220 ohm to 330 ohm for test result change R470 and R472 from 220 ohm to 680 ohm for test result
	03/03	remove R261 for this register maybe make some UHS-I card compatibility fail in GL834L-04, so must remove this resister. remove U5 and R80 for Nuvoton PAE Mark said that TPM doesn't SERIRQ.
	03/04	change C316-C321 to 1.6pF by vendor's suggestion.(don't large than 2.7P)
	03/04	reserve C706 for PTP touch pad sometimes will auto resume from S3.
	03/06	change R469 and R471 from 330 ohm to 680 ohm for test result change R470 and R472 from 680 ohm to 820 ohm for test result
	03/12	change Q16 to PJA138K
	03/18	reserve 3V_S5 power for TP to use.
	03/20	change SLEEVE R and RING2 R from ADOGND to GND for ESD issue. del all USB signal choke and change to short pad.
	03/21	change PR102 and PR121 from short pad to 0 ohm for power drop issue.
	03/24	Delete 1.35VSUS short jumper JP11

 <b>Quanta Computer Inc.</b>		DOC NO.	PROJECT MODEL : ZQM	APPROVED BY:		DATE:
PROJECT : ZQM						
Change list		PART NUMBER:		DRAWING BY:		REVISION:
Date: Wednesday, April 09, 2014						