

# 1769 CompactLogix Packaged Controllers, Revision 18

Catalog Numbers 1769-L23E-QB1B, 1769-L23E-QBFC1B,  
1769-L23-QBFC1B

Topic	Page
About This Publication	2
Compatible Versions of Software	2
Before You Begin	3
Enhancements	4
Corrected Anomalies	6
Known Anomalies	13
Restrictions	14
Install the Controller Revision	16
Additional Memory Requirements	17
Additional Resources	20

---

**IMPORTANT**

Before updating your controller, we strongly recommend that you review information pertinent to previous major firmware revisions. For example, when updating from revision 17.x to 18.x, view information for revision 17 in this publication:

- CompactLogix Controllers, Revision 17 Release Notes, publication [1769-RN012](#)

Firmware release notes contain material for all minor revisions subsequent to each major revision. If your controller, for example, is at revision 17.03, and not the last minor revision, 17.05, you should view all of the information for revision 17.03...17.05 before updating to revision 18.x.

Release notes are available at:  
<http://rockwellautomation.com/literature>.

---

## About This Publication

This publication describes enhancements, anomalies (known and corrected), and restrictions for the 1769 CompactLogix packaged controllers, revision 18.

### Controllers and Revisions

Cat. No.	Major and Minor Revision No.
1769-L23E-QB1B	18.11
1769-L23E-QBFC1B	
1769-L23-QBFC1B	

## Compatible Versions of Software

To use firmware revision 18.11, the following minimum software versions are required.

Software	Required Version
RSLink Classic software	2.56 (CPR 9, SR2)
RSLink Enterprise software	5.21(CPR 9, SR2)
RSLogix 5000 programming software	18.00 (CPR 9, SR2)
RSNetWorx for ControlNet software	10.00 (CPR 9, SR2)
RSNetWorx for DeviceNet software	
RSNetWorx for EtherNet/IP software	

## Before You Begin

Consider this information before upgrading your packaged controller firmware.

### Avoid Interrupting the Firmware Upgrade

---

**IMPORTANT**

When upgrading your packaged controller firmware, it is **extremely** important to allow the upgrade to complete without interruption.

If you interrupt the firmware upgrade either in the software or by disturbing the physical media, you may render the packaged controller inoperable.

During an upgrade of the CompactLogix firmware, the ControlFlash utility displays various progress dialog boxes. The progress dialog boxes contain these status statements:

- Transmitting block...
- Polling for power-up...

It is crucial that you do not interrupt the firmware upgrade while these progress statements display. Once the Update Status dialog box indicates that the firmware upgrade is complete, you may adjust your controller's network connection, make changes using controller-related software, or cycle controller power.

For more information about upgrading your CompactLogix packaged controller firmware, see information posted at <http://www.rockwellautomation.com/knowledgebase/>.

---

### Avoid a Loss of Communication During the Firmware Upgrade

---

**IMPORTANT**

Loss of communication or power during a controller firmware flash upgrade may result in the controller's rejection of the new firmware. If the controller firmware upgrade fails due to those conditions described, the following corrective actions may be required:

- Cycle controller power with the battery disconnected for 2...3 minutes, then successfully complete the flash upgrade.
  - If a nonrecoverable fault occurs, then return the controller for factory repair.
-

## System Preparations Required Before Upgrading

The following preliminary action is required before upgrading your packaged controller firmware.

If	Then
Your controller is connected to a DH-485 network	Disconnect it from the DH-485 network before you update the firmware of the controller. If you update the firmware of a controller while it is connected to a DH-485 network, communication on the network may stop.

## Enhancements

These enhancements are available when firmware revision 18.11 is used with RSLogix 5000 software, version 18.

### Enhancements with Firmware Revision 18.11

Enhancement	Description
RPI of Individual 1769 I/O Modules Is Configurable	With firmware revision 18.11, each 1769 I/O module on a CompactBus can be configured with its own RPI. With previous revisions, all of the 1769 I/O modules on a CompactBus had to use the same RPI.
Controllers Round RPI to Nearest Whole Value	With firmware revision 18.11, the 1769 CompactLogix controllers round decimal values to whole integers. For example, if you specify the RPI to be 2.5 ms, the controller rounds the RPI value down to 2.0 ms. With previous revisions, the control used the exact RPI value entered, even if it was a decimal, as the RPI for all the I/O modules on the CompactBus.
Unicast I/O with EtherNet/IP Networks	You can configure a Logix5000 controller to communicate with other EtherNet/IP devices via Unicast communication. Unicast communication allows for direct point-to-point communication between two devices on a network. Unicast communication is useful when data does not need to be shared between multiple target devices. Support for Unicast communication is limited to standard I/O.
DF1 Radio Modem Broadcast Support	DF1 Radio Modem support has been expanded to include broadcast capability. The DF1 Radio Modem functionality was initially provided with version 16. With this expansion to include broadcast capabilities, you can configure a master or slave device to broadcast messages to all other stations in one instance.
High-integrity Add-On Instructions	<p>With high-integrity Add-On Instructions, you can generate a unique signature ID based on the content of your instruction. This signature can be used to identify changes to the code, revision, data structures, and documentation associated with an Add-On Instruction.</p> <p>You can generate the signature by using the Add-On Instruction Definition dialog box. In addition, you can access the signature information programmatically for auditing purposes and transport Add-On Instructions between Logix controllers without impacting the signature.</p> <p>For more information about high-integrity Add-On Instruction signatures, see the Add-On Instruction Programming Manual, publication <a href="#">1756-PM010</a>.</p>
Active Step Maintained During SFC Online Edit	Online edits to SFC routines do not always result in the SFC being reset to the initial step. Edits that alter the logic structure of the chart are the only edits that cause the SFC to reset to the initial step.

**Enhancements with Firmware Revision 18.11**

Enhancement	Description
Data Access Control	<p>Two new tag attributes are available: the External Access and Constant attributes. The External Access attribute defines how an external application (that is, an application outside of RSLogix 5000 software or your application code), such as an HMI, historian, or OPC data server, can access a tag. Options you can configure for the External Access attribute include:</p> <ul style="list-style-type: none"> <li>• Read/Write</li> <li>• Read Only</li> <li>• None</li> </ul> <p>The Constant attribute is used to keep the tag from being altered by the controller program or by specified users of RSLogix 5000 software. To keep the program from altering the tag, check the Constant attribute in the Tag Properties dialog box or in the Tag Editor.</p> <p>For complete functionality of the Data Access Control enhancements, you must use the software revisions listed in Compatible Versions of Software on <a href="#">page 2</a>.</p> <p>For more information about tag data access attributes, see the Logix5000 Controllers I/O and Tag Data Programming Manual, publication <a href="#">1756-PM004</a>.</p>
RPI Limitations and Negotiated Default for Multicast	<p>An RPI limit can be set for produced/consumed tags in applications where multicast communication connections are used. When this option is configured, a producing controller verifies that the RPI of incoming connections are within the produced tag settings. If the consuming tag's RPI falls outside the configured range, a producing controller will reject the incoming RPI and may provide an RPI (default) to the consuming controller. This feature is not available with safety produced/consumed tags.</p> <p>For more information about RPI Limitations see the Produced and Consumed Tags Programming Manual, publication <a href="#">1756-PM011</a>.</p>
Attributes of Add-On Instructions Available	<p>You can configure GSV and SSV instructions to obtain attributes of Add-On Instructions. This enhancement provides that capability to program the controller to access Add-On Instruction definitions.</p> <p>For more information about the Add-On Instruction attributes, see the Add-On Instructions Programming Manual, publication <a href="#">1756-PM010</a>.</p> <p>Lgx00105714, Lgx00095246</p>
False Execution Time of Add-On Instructions Improved	<p>With previous revisions, the false execution time of an Add-On Instruction was dependent on the number of parameters (input, output, and inout) configured for the instruction. The more parameters configured, the longer the false execution time of the Add-On Instruction.</p> <p>With revision 18.11, the false execution time of an Add-On Instruction is now constant if a scan false routine is not created. To determine the false execution time of Add-On Instructions based on your controller, reference the values published in the Logix5000 Controllers Execution Time and Memory Use Reference Manual, publication <a href="#">1756-RM087</a>.</p> <p>Lgx00101630, Lgx00091647, Lgx00085092</p>

## Corrected Anomalies

These anomalies have been corrected with firmware revision 18.11.

### Anomalies Corrected with Firmware Revision 18.11

Catalog No.	Description
1769-L23E-QB1B, 1769-L23E-QBFC1B	<p>Use of the controller within Ethernet connection limits, but at or near maximum limits, may result in No Buffer Memory, error code 0x301.</p> <p>If you are upgrading from an earlier firmware revision, and have previously used your controller at, or very near, the maximum Ethernet connection limits with produced/consumed tags, upgrading to firmware revision 17 may cause you to experience over-connection limit errors.</p> <p>This anomaly will only be experienced if your configured RPI rates are not binary multiples of 2 ms. This is because the CompactLogix controllers round the RPI down to the nearest binary multiple to make connections (for example, setting an RPI of 100 ms results in the controller sending data at 64 ms).</p> <p>With firmware revision 18.11, use of the controller at or near maximum limits does <b>not</b> result in a No Buffer Memory error.</p> <p>Lgx00087882</p>
1769-L23-QBFC1, 1769-L23E-QB1B, 1769-L23E-QBFC1B	<p>After clearing a fault due to a missing I/O modules and cycling power to the CompactLogix controller, the program is lost from controller memory and no fault is logged.</p> <p>With firmware revision 18.11, cycling power after clearing a fault for missing I/O modules does not result in the program being lost from controller memory.</p> <p>Lgx000101634, Lgx00092026</p> <p>Forcing the I/O status word is unsuccessful.</p> <p>When you attempt to force the input status word, the force is unsuccessful though RSLogix 5000 software indicates the force is enabled.</p> <p>With firmware revision 18.11, forces are applied as expected.</p> <p>Lgx00086933</p> <p>If you attempt to change the RPI of I/O modules in the I/O configuration tree while in Run or Program mode, the new RPI is not applied. Instead the RPI remains at the interval set when the program was downloaded. To work around this issue and implement the new RPI, you have to Inhibit and Uninhibit the connection or cycle power to the controller.</p> <p>With firmware revision 18.11, attempting to edit the RPI of I/O while in Run or Program mode (online) is successful without further intervention.</p> <p>Lgx00101628, Lgx00089942</p>

**Anomalies Corrected with Firmware Revision 18.11**

<b>Catalog No.</b>	<b>Description</b>
1769-L23-QBFC1, 1769-L23E-QB1B, 1769-L23E-QBFC1B	<p>Deleting program tags while online is successful, even though they are being referenced by RSLinx software and should not be deleted.</p> <p>RSLogix 5000 software and Logix5000 controller firmware provide the ability to delete program tags while online with the controller. As a precaution, the firmware checks the tag to verify that is not in use (that is, the tag is not being scanned or referenced) by RSLinx Classic or Enterprise software. If the tag is being used by RSLinx software, the deletion is not allowed and an error dialog box indicates "Failed to delete tag".</p> <p>However, with certain tags, the deletion is always allowed - even if the tag is being used by RSLinx software. Tag types that are always deleted, even if being used by RSLinx software, include:</p> <ul style="list-style-type: none"> <li>• Motion Axis</li> <li>• Motion Group</li> <li>• Digital Alarm</li> <li>• Analog Alarm</li> <li>• Message</li> </ul> <p>With firmware revision 18.11, tags being used by RSLinx software cannot be deleted while online with the controller.</p> <p>Lgx00086136, Lgx00085678</p>
	<p>SSV class name SerialPort, attribute PendingComDriverID, does not set.</p> <p>With revision 18.11, attempts to use a SSV instruction to set the SerialPort class, PendingComDriverID attribute, are successful.</p> <p>Lgx00073954</p>
	<p>Using an SSV instruction to set a task priority of 0 results in unexpected execution times.</p> <p>If you use a SSV instruction to set a task's priority at 0 (by using the class name Task, attribute Priority), abnormal task execution times result. This is because tasks cannot have a priority of 0 (permissible priority values are 1...15).</p> <p>With firmware revision 18.11, you cannot set a task priority to 0 using an SSV instruction. Attempting to set a task priority to 0 via the SSV instruction results in a minor fault.</p> <p>Lgx00105709, Lgx00076850</p>
	<p>Setting the Read/Write Buffer size parameter before enabling the Echo Mode does not result in a message echo.</p> <p>In the User Protocol tab of the Controller Properties dialog box, if the Read/Write Buffer size is specified before Echo Mode is checked, the message echo does not execute.</p> <p>For the message echo to execute, first check Echo Mode, then specify the Read/Write Buffer size.</p> <p>With firmware revision 18.11, you can specify the Read/Write Buffer size and set the Echo Mode in any order to achieve a message echo.</p> <p>Lgx00087052, Lgx00087176</p>

**Anomalies Corrected with Firmware Revision 18.11**

Catalog No.	Description
1769-L23-QBFC1, 1769-L23E-QB1B, 1769-L23E-QBFC1B	<p data-bbox="370 329 943 357">RMPS instruction in a continuous task does not countdown.</p> <p data-bbox="370 394 1446 516">If a RMPS instruction is used in a continuous task and a Soak Time value greater than 1024 minutes is specified, the countdown (SoakTimeLeft) does not countdown and the RMPS instruction appears to stop executing. This anomaly does not occur if the RMPS is used in a periodic task or the continuous task program is run in SoftLogix 5800 or RSEmulator 5000 software.</p> <p data-bbox="370 554 716 581">To workaround this anomaly, either:</p> <ul data-bbox="381 619 1159 688" style="list-style-type: none"> <li>• use multiple soaks to achieve your total soak times greater than 1024 minutes.</li> <li>• use the RMPS in periodic task that has a Period on 10 ms or greater.</li> </ul> <p data-bbox="370 726 1442 783">This anomaly has been resolved with firmware revision 18.11. You can use an RMPS instruction in a continuous task with a Soak Time value greater than 1024 minutes.</p> <p data-bbox="370 821 737 848">Lgx00100678, Lgx00085036, Lgx00083654</p> <hr/> <p data-bbox="370 863 1463 919">The controller log has been updated so that completing a partial import while online, or adding I/O online no longer is identified as 'Partial Import Online or Add I/O Online modified controller'.</p> <p data-bbox="370 957 1365 1050">Instead, the completion of a partial import while online or adding I/O while online is indicated by a 'Transaction Commit' entry in the controller log. Other transactions that are conducted may also cause a 'Transaction Commit' entry to be logged in the controller log. These transactions include the following:</p> <ul data-bbox="381 1066 1360 1436" style="list-style-type: none"> <li>• Completing an SFC edit while online that does not result in a reset of the Sequential Function Chart.</li> <li>• Accepting any pending edits to the routine.</li> <li>• Creating a tag.</li> <li>• Creating a module or editing module properties.</li> <li>• Deleting components.</li> <li>• Modifying tag properties.</li> <li>• Conducting a partial import online.</li> <li>• Copying, pasting, or cutting any tag or program elements.</li> <li>• Moving tags between collections.</li> </ul> <p data-bbox="370 1474 639 1501">Lgx00098523, Lgx00094306</p>



**Anomalies Corrected with Firmware Revision 18.11**

<b>Catalog No.</b>	<b>Description</b>
1769-L23-QBFC1, 1769-L23E-QB1B, 1769-L23E-QBFC1B	<p>The Modular Multivariable Control (MMC) instruction may not use the second or third control variable (CV) parameters to achieve the process variable (PV) setpoint when certain limits are specified for the CV.</p> <p>In applications where the MMC function block is used to control one PV through manipulation of up to three CVs, only the first CV is manipulated by the instruction if the CVxEUMax, CVEUMin, CVxHLimit, and CVxLLimit input parameters for the first CV are set at conflicting values. These input parameters conflict when the CVxHLimit or CVxLLimit keeps the CV clamped at a value inside the range specified with the CVxEUMax and CVxEUMin parameters. If the CV does not extend outside the CVxEUMax and CVxEUMin parameters, the second and third CVs of the MMC instruction are not used to manipulate the PV.</p> <p>With firmware revision 18.11, the second and third CVs of the MMC instruction are manipulated, even if the first CV is within the range indicated by CVxHLimit and CVxLLimit.</p> <p>Lgx00100721, Lgx00091924</p>
	<p>Setting the WallClockTime to an invalid value by using an SSV instruction results in a Major Nonrecoverable Fault (MNRf).</p> <p>With firmware revision 18.11, if a WallClockTime object's DateTime attribute is invalid, a minor fault results.</p> <p>Lgx00101632, Lgx00097459</p>
	<p>Attempts to use the FIND instruction to search a large string of characters results in a Major Recoverable Fault (MRF).</p> <p>If you attempt to use the ASCII FIND instruction to search a source-data string of 32,767 characters, or more, a major fault Type 4 Code 51 results.</p> <p>With firmware revision 18.11, the FIND instruction can successfully search a source-data string as large as 65,535 characters, the largest amount of characters that can be used in a string.</p> <p>Lgx00101633, Lgx00094007</p>
	<p>Use of an STOD instruction and a program upgrade from revision 16 to revision 17 results in the program-scan time increasing.</p> <p>When an STOD is used in an application that has been upgraded from revision 16 to revision 17, the program scan time dramatically increases due to an anomaly correction made to the STOD instruction in revision 17.</p> <p>With revision 18.11, the program-scan time returns to the time observed with version 16.</p> <p>Lgx000102979, Lgx00095528</p>


**Anomalies Corrected with Firmware Revision 18.11**

Catalog No.	Description
1769-L23-QBFC1, 1769-L23E-QB1B, 1769-L23E-QBFC1B	<p>Completing a partial import of a project developed and run on a SoftLogix controller causes a Major Nonrecoverable Fault (MNRF) if certain instructions are used in the program.</p> <p>A Major Nonrecoverable Fault occurs on the controller when a program is developed and run on a SoftLogix controller, and then a partial import online is completed to a Logix5000 controller while the Logix5000 controller is in Run mode (online). A Major Nonrecoverable Fault occurs if the imported project contains these instructions:</p> <ul style="list-style-type: none"> <li>• Coordinated Control (CC)</li> <li>• Internal Model Control (IMC)</li> <li>• Modular Multivariable Control (MMC)</li> </ul> <p>The MNRF occurs after the partial import is completed and the edits to the program are finalized.</p> <p>Lgx00103561, Lgx00102966</p>
	<p>Use of an FFU instruction in a SFC program results in a Major Nonrecoverable Fault (MNRF) when the last scan of the SFC is configured to Auto Reset.</p> <p>With firmware revision 18.11, this anomaly has been corrected.</p> <p>Lgx000103551, Lgx00096621</p>
	<p>When certain values are converted from a floating-point number to an integer, the Carry Status flag (S:C) is not set as expected for the value being converted.</p> <p>With firmware revision 18.11, the Carry Status flag is set when the conversion results in the generation of a carry-out of the most significant bit.</p> <p>Lgx00105710, Lgx00074175</p>
	<p>A Digital Alarm (ALMD) configured to trigger when the input condition of the alarm is false, does not trigger if the alarm condition is false when you conduct a download or return to run mode.</p> <p>When the Condition parameter of the ALMD instruction is not set (that is, Input = 0) <b>and</b> either the program has recently been downloaded to the controller, or the controller has been changed from Run to Program and back to Run mode, the alarm is not activated (that is, the InAlarm bit is not set).</p> <p>These behaviors may result, depending on your application:</p> <ul style="list-style-type: none"> <li>• Programming designed to respond to the activated alarm is not executed.</li> <li>• Messages designed to be indicated at the operator station in response to the activated alarm are not indicated.</li> <li>• The alarm's history log does not indicate that the alarm was activated.</li> </ul> <p>If you choose not upgrade to this revision, you must toggle the Condition parameter from set (that is, Input = 1) to not set (that is, Input = 0) to activate the alarm.</p> <p>If your Condition parameter is set, then the alarm activates as expected after a download or change to the controller mode.</p> <p>Lgx000104437, Lgx00102840</p>

**Anomalies Corrected with Firmware Revision 18.11**

Catalog No.	Description
1769-L23-QBFC1, 1769-L23E-QB1B, 1769-L23E-QBFC1B	<p>When an invalid Process Variable (PV) value, for example a positive infinity (INF) or not a number (NaN), is used by the Proportional Integral Derivative (PID) instruction, the PID instruction becomes stuck and control of the PV is lost.</p> <p>To reset the instruction and recover control, you have to access the .Data array of the PID instruction and clear any values that are invalid. The PID instruction would then begin to control the PV.</p> <p>With firmware revision 18.11, the instruction recognizes the invalid input value. It ignores the invalid value and the output of the PID instruction will not change. When developing your application, verify that the value passed into the PID instruction is valid.</p> <p>Lgx00105712, Lgx00082890</p>
	<p>Depending on the structure of your program, if your service communication is interrupted for longer than 300 ms (as determined by the System Overhead Time Slice setting) and a connection is in the process of closing, a major nonrecoverable fault (MNRF) may result. The connection that is closing could be a connection used for I/O, a message instruction, a forward open, and so on.</p> <p>With firmware revision 18.11, a connection in the process of closing during a service communication interrupt of &gt;300 ms occurs does not cause a major nonrecoverable fault (MNRF).</p> <p>Lgx00103549, Lgx00098734</p>
	<p>When an SFC Reset (SFR) instruction that is executed specifies a target step that is not the initial step, and the step is anywhere below (but outside) a simultaneous branch, the chart will no longer execute. The chart will remain in the step it was reset to, and attempts to progress via a Transition, Force, or Step Through are unsuccessful.</p> <p>To begin executing the chart again, you must execute an SFR instruction to the initial step or to a step above the first simultaneous branch.</p> <p>With firmware revision 18.11, when an SFC is reset to a specified step the transitions occur as expected.</p> <p>Lgx00099968, Lgx00099132</p>

### Anomalies Corrected with Firmware Revision 18.11

Catalog No.	Description
1769-L23-QBFC1, 1769-L23E-QB1B, 1769-L23E-QBFC1B	<p>Fault handlers can be defined at the controller and program scope levels. These fault handlers are typically used to handle major recoverable faults that can occur during runtime execution of an application due to programming errors. A typical example of this would be handling indirect addressing that has gone out of range; <code>MyTag[index]</code>, where <code>index</code> is larger than the size of the array.</p> <p>Faults can also be handled by the controller during pre-scan of the controller program on the transition to Run mode. Again, for example, the handling of indirect addressing that has gone out of range.</p> <p>There is an anomaly when these methods attempt to handle a fault.</p> <p>These are the possible ways the anomaly can manifest itself:</p> <ul style="list-style-type: none"> <li>• The controller will experience a major non-recoverable fault. I/O goes to their configured safe state, and the user application is cleared from memory. At this point, a Code 1 Type 60 or 61 major recoverable fault will be logged in the controller. This requires you to redownload the application.</li> <li>• Tag data corruption.</li> <li>• Online saving or uploading failures.</li> <li>• Anomalous program execution.</li> </ul> <p>For example, if a rung is being scanned false and there is an instruction that has false execution, the fault handler executes so the remainder of the rung will scan true. In the example below, the OTE instruction has an index out of range. After returning from the fault handler, the ADD instruction will execute, even though the rung input conditions are false.</p>  <p>Lgx00105703, Lgx00100144, Lgx00101800, Lgx00102339, and Lgx00104782</p>

## Known Anomalies

These anomalies have been identified with firmware revision 18.

### Known Anomalies with Firmware Revision 18.11

Catalog No.	Description
1769-L23E-QB1B, 1769-L23-QB1BFC, 1769-L23E-QB1BFC	<p>PI function block appears to stop executing as the output does not change and no instruction faults are logged.</p> <p>If the PI instruction is being used in Linear mode, this floating-point equation is used to calculate the ITerm.</p> $Kp \times Wld \times \frac{WldInput + WldInput_{n-1}}{2} \times DeltaT + ITerm_{n-1}$ <p>Due to the use of the single-precision floating point values, it may be possible, depending on the values of WLD and KP, for the ITerm value to be small enough, less than 0.0000001, to be lost when adding to the ITerm<sub>n-1</sub>.</p> <p>For more information regarding the PI instruction, see the Logix5000 Controllers Process Control and Drives Instructions User Manual, publication <a href="#">1756-RM006</a>.</p> <p>Lgx00070832</p>
	<p>Changes made to the Buffer Timeout value for FactoryTalk Alarm subscribers do not take effect until the existing buffer has been deleted.</p> <p>The FactoryTalk alarm buffer (stored in Logix controller memory) is designed to persist through power cycles. If you change the Buffer Timeout value (via the Communication Setup dialog in FactoryTalk View SE), the controller does not use the new timeout value until the existing buffer is deleted and then recreated. To force recreation of this buffer, you can either:</p> <ul style="list-style-type: none"> <li>• Redownload the project to the controller</li> <li>• Disconnect the FactoryTalk Alarm subscriber and leave it disconnected until the existing timeout expires.</li> </ul> <p>Lgx00069461</p>
	<p>Unsuccessful MSG execution results in subsequent unsuccessful messages in master/slave controller configurations.</p> <p>When a DF-1 serial connection is used between a master and slave controller, a MSG instruction is not successfully executed and an in-polling sequence error occurs if the master station address is not listed in the poll node list. However, with this anomaly, after the in-polling sequence error, subsequent MSG instructions are also unsuccessful.</p> <p>To workaround this anomaly, change the master controller's station address to a different value or re-execute the unsuccessful MSG instruction in Master Transmit mode and use the Between Station Polls parameter.</p> <p>Lgx00083882, Lgx00082610</p>

## Restrictions

These restrictions exist for 1768 CompactLogix controllers at revision 18.11.

### Restrictions with Firmware Revision 18

Cat. No.	Description				
1769-L23E-QB1B, 1769-L23-QB1BFC, 1769-L23E-QB1BFC	The end cap must be attached to the CompactLogix system before you upgrade the controller or I/O module.				
	Use RSLinx Classic software, version 2.56, and RSLinx Enterprise software, version 5.21, or later, for best results with the new External Access tag attributes provided with RSLogix 5000 software, version 18, and controller firmware revision 18.11.				
	Using earlier versions of RSLinx Classic and RSLinx Enterprise software may result in anomalous behavior from the data servers with the External Access options Read Only and None.				
	For more information about tag data access attributes, see the Logix5000 Controllers I/O and Tag Data Programming Manual, publication <a href="#">1756-PM004</a> .				
	Lgx00103263				
	Enabling the time synchronization feature of a CompactLogix controller results in the controller becoming the local master. It does not result in controller becoming synchronized with other wall clock times in the system.				
	If a 1769 I/O fault occurs, you must cycle power to the CompactLogix controller after clearing the major fault. I/O communication is not restored until after the power cycle. You should never use the fault handling routine to clear local I/O faults. You should clear local I/O faults manually on a per case basis, and then the controller should be power cycled.				
	With RSLogix 5000 software, version 18, and controller firmware revision 18.11, the Fault/Program states for Compact I/O modules are not supported and cannot be configured using the Module Configuration dialog box.				
	Since the CompactLogix system does not provide support for local modules to use the alternate outputs, do not configure the attributes or tags listed below. These tags are still created when you add the I/O modules to the configuration.				
<b>Attribute Tags to Avoid</b>					
<table> <tr> <th>For Digital Output Modules</th><th>For Analog Output Modules</th></tr> <tr> <td> <ul style="list-style-type: none"> <li>ProgToFaultEn</li> <li>ProgMode</li> <li>ProgValue</li> <li>FaultMode</li> <li>FaultValue</li> </ul> </td><td> <ul style="list-style-type: none"> <li>CHxProgToFaultEn</li> <li>CHxProgMode</li> <li>CHxFaultMode</li> <li>Where CHx = the channel number</li> </ul> </td></tr> </table>		For Digital Output Modules	For Analog Output Modules	<ul style="list-style-type: none"> <li>ProgToFaultEn</li> <li>ProgMode</li> <li>ProgValue</li> <li>FaultMode</li> <li>FaultValue</li> </ul>	<ul style="list-style-type: none"> <li>CHxProgToFaultEn</li> <li>CHxProgMode</li> <li>CHxFaultMode</li> <li>Where CHx = the channel number</li> </ul>
For Digital Output Modules	For Analog Output Modules				
<ul style="list-style-type: none"> <li>ProgToFaultEn</li> <li>ProgMode</li> <li>ProgValue</li> <li>FaultMode</li> <li>FaultValue</li> </ul>	<ul style="list-style-type: none"> <li>CHxProgToFaultEn</li> <li>CHxProgMode</li> <li>CHxFaultMode</li> <li>Where CHx = the channel number</li> </ul>				

**Restrictions with Firmware Revision 18**

Cat. No.	Description
1769-L23-QBFC1, 1769-L23E-QB1B, 1769-L23E-QBFC1B	<p>Tasks are the basic scheduling mechanism for executing a program and are created as part of the project and program creation process. In addition to other internal tasks, the CompactLogix controllers have an internal task to provide communication with the 1769 I/O modules. This task executes periodically at the Requested Packet Interval (RPI) selected in the properties of the CompactBus. If the task has not completed before it is time to execute again, a task overlap occurs. This task overlap causes the packaged controller to declare a minor fault of Type = 6 (Task Overlap), Code = 4 (VA task).</p> <p>You can use various strategies to resolve minor faults due to task watchdog timeout and/or task overlap. For more information, see RSLogix 5000 Online Help 'Identifying and Managing Tasks'. In the case of a minor fault caused by VA task overlap, increase the RPI until the overlap no longer occurs.</p>
1769-L23-QBFC1B	<p>With a 1769-L23-QBFC1B packaged controller, you cannot bridge from one serial port to the other. However, you can bridge from either serial port to DeviceNet network via the 1769-SDN scanner.</p>

## Install the Controller Revision

To install the latest CompactLogix controllers revision, go to <http://support.rockwellautomation.com/ControlFlash> to download your revision. Then use the ControlFlash utility to upgrade your packaged controller.

Alternatively, if you have installed RSLogix 5000 software, version 17, and related firmware, you may not need to complete the tasks described. The AutoFlash feature of RSLogix 5000 software, version 17, detects if your packaged controller firmware needs upgraded upon a program download to the packaged controller. If a firmware upgrade is necessary, AutoFlash will initiate an update.

After you have completed your firmware upgrade, you should complete these steps to verify that the upgrade was successful.

1. Cycle power to the packaged controller.
2. Go online with the packaged controller and view packaged controller properties.
3. Verify that the firmware revision listed matches the firmware to which you intended to upgrade.
4. If the packaged controller's firmware is not correct, initiate another firmware upgrade.

For more information about errors when completing a ControlFlash upgrade, see the ControlFlash Firmware Upgrade Kit Quick Start, publication [1756-QS105](#).




## Additional Memory Requirements

This firmware revision may require more memory than previous revisions (for example, 10.x, 11.x). To estimate additional memory requirements for your application, you can either use the memory estimation tool provided with RSLogix 5000 software or the tables provided in these release notes.

### Use the Estimate Tool

To estimate the amount of memory required by your application, convert the project to the controller revision desired and use the Estimate tool available in the Memory tab of the Controller Properties.



## Estimate Based on Application Components

If you do not have the desired version of RSLogix 5000 software, use this table to estimate the additional memory that your project may require.

If you are upgrading your system through multiple firmware revisions, add all components your application uses for each of the revisions you upgrade through. For example, if you are upgrading from revision 15.x to revision 18.x, total your application components for revisions 15.x to 16.x, 16.x to 17.x, and 17.x to 18.x.

### Additional Memory Requirements per Application Component

If you upgrade from revision (add all that apply)	Then add the following memory requirements to your project		Which comes from this type of memory	
	Component	Increase/Decrease Per Instance	I/O	Data and Logic
17.x to 18.x	Program	+ 8 bytes		✓
	Equipment Phase	+ 20 bytes		✓
	Add-On Instruction	+ 12 bytes		✓
	Each tag	+ 4 bytes		✓
	In addition, if you use a tag of the types listed below, increase the memory as indicated for each instance:			
	Produced tag	+ 36 bytes + (24 bytes • number of consumers)	✓	
	Consumed tag	+ 24 bytes	✓	
	Data Access Control	+ 4 bytes per symbol		✓
	Tag that uses ALARM_ANALOG data type	- 20 bytes		✓
	Tag that uses ALARM_DIGITAL data type	+ 28 bytes		✓
	Tag that uses MOTION_GROUP data type	+ 76		✓
	Tag that uses AXIS_SERVO_DRIVE or AXIS_GENERIC_DRIVE data type	+ 786 bytes		✓
	Tag that uses AXIS data type other than AXIS_SERVO_DRIVE or AXIS_GENERIC_DRIVE	+ 818 bytes		✓
	Tag that uses COORDINATE_SYSTEM data type with no transform dimensions	+ 40 bytes		✓
	Tag that uses COORDINATE_SYSTEM data type with transform dimensions	+ 100 bytes		✓
	Module input connection	+ 20 bytes		✓
	Module output connection	+ 24 bytes		✓
	Safety controller	- 8 bytes		✓
	Safety partner	- 8 bytes		✓

**Additional Memory Requirements per Application Component**

If you upgrade from revision (add all that apply)	Then add the following memory requirements to your project		Which comes from this type of memory	
	Component	Increase/Decrease Per Instance	I/O	Data and Logic
17.x to 18.x	For each controller (> 1K bytes change):			
	1756-L6x, 1756-L6xS, 1756-L63XT	+ 16728 bytes		✓
	1768-L4x, 1768-L4xS	+ 14448 bytes		✓
	1769-L2x	+ 35084 bytes	✓	
	1769-L31	+ 14740 bytes	✓	
	1769-L32C, 1756-L35CR	+ 35400 bytes	✓	
	1769-L32E, 1756-L35E	+ 35036 bytes	✓	
	1789-L10, 1789-L30, 1789-L60	+ 4992	✓	
	PowerFlex 700S 2	+ 55340 bytes	✓	

## Additional Resources

These resources contain additional information related to the CompactLogix packaged controllers.

Resource	Description
CompactLogix Controllers, Revision 17 Release Notes, publication <a href="#">1769-RN012</a>	Describes anomalies and restrictions specific to revision 17 of the CompactLogix packaged controllers.
CompactLogix Packaged Controllers Quick Start and User Manual, publication <a href="#">IASIMP-QS010</a>	Provides procedures for using your CompactLogix packaged controller as well as additional reference information.
CompactLogix Controllers Selection Guide, publication <a href="#">1769-SG001</a>	Provides specifications and other information related to the selection of CompactLogix controllers.
Add-On Instruction Programming Manual, publication <a href="#">1756-PM010</a>	Explains Add-On Instructions and related features.
GuardLogix Controller Systems User Manual, publication <a href="#">1756-RM093</a>	Provides information specific to the use of GuardLogix controllers and safety program elements.
Logix5000 Controllers I/O and Tag Data Programming Manual, publication <a href="#">1756-PM004</a>	Explains I/O and tag data. It also includes information about using the Data Access Control and External Access features.
Produced and Consumed Tags Programming Manual, publication <a href="#">1756-PM011</a>	Explains produced and consumed tags and includes information about RPI Limitations and Negotiated Default features.
Compact I/O Selection Guide, publication <a href="#">1769-SG002</a>	Provides information about calculating the number of expansion I/O that can be used with your packaged controller.
Rockwell Automation Technical Support Knowledgebase, <a href="http://www.rockwellautomation.com/knowledgebase/">http://www.rockwellautomation.com/knowledgebase/</a>	Contains technical notes and other information related to upgrading your packaged controller's firmware.
CompactLogix Packaged Controllers Installation Instructions, publication <a href="#">1769-IN082</a>	Contains complete instructions for installing your CompactLogix packaged controller.
ControlFlash Firmware Upgrade Kit Quick Start, publication <a href="#">1756-QS105</a>	Contains informations about firmware upgrades, installation instructions, and error messages.

You can view or download Rockwell Automation publications at <http://rockwellautomation.com/literature>. To order paper copies of technical documentation, contact your local Rockwell Automation distributor or sales representative.

Tech Notes and other resources are available at the Technical Support Knowledgebase, <http://www.rockwellautomation.com/knowledgebase>.

## **Notes:**

# Rockwell Automation Support

Rockwell Automation provides technical information on the Web to assist you in using its products. At <http://support.rockwellautomation.com>, you can find technical manuals, a knowledge base of FAQs, technical and application notes, sample code and links to software service packs, and a MySupport feature that you can customize to make the best use of these tools.

For an additional level of technical phone support for installation, configuration, and troubleshooting, we offer TechConnect support programs. For more information, contact your local distributor or Rockwell Automation representative, or visit <http://support.rockwellautomation.com>.

## Installation Assistance

If you experience a problem within the first 24 hours of installation, please review the information that's contained in this manual. You can also contact a special Customer Support number for initial help in getting your product up and running.

United States	1.440.646.3434 Monday – Friday, 8 a.m. – 5 p.m. EST
Outside United States	Please contact your local Rockwell Automation representative for any technical support issues.

## New Product Satisfaction Return

Rockwell Automation tests all of its products to ensure that they are fully operational when shipped from the manufacturing facility. However, if your product is not functioning and needs to be returned, follow these procedures.

United States	Contact your distributor. You must provide a Customer Support case number (call the phone number above to obtain one) to your distributor in order to complete the return process.
Outside United States	Please contact your local Rockwell Automation representative for the return procedure.

Allen-Bradley, Compact I/O, CompactLogix, GuardLogix, RSLinx Classic, RSLinx Enterprise, RSLogix 5000, RSNetWorx for EtherNet/IP, RSNetWorx for ControlNet, RSNetWorx for DeviceNet, Kinetix, PowerFlex, RSLinx Classic, RSLinx Enterprise, RSLogix 5000, Rockwell Automation, Rockwell Software, and TechConnect are trademarks of Rockwell Automation, Inc.

Trademarks not belonging to Rockwell Automation are property of their respective companies.

**[www.rockwellautomation.com](http://www.rockwellautomation.com)**

### Power, Control and Information Solutions Headquarters

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444

Europe/Middle East/Africa: Rockwell Automation, Vorstlaan/Boulevard du Souverain 36, 1170 Brussels, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640

Asia Pacific: Rockwell Automation, Level 14, Core F, Cyberport 3, 100 Cyberport Road, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846

Publication 1769-RN013A-EN-P - February 2010

PN-59119

Copyright © 2010 Rockwell Automation, Inc. All rights reserved. Printed in the U.S.A.