



CompactLogix 5370 L1 Controllers, Revision 20

Catalog Numbers 1769-L16ER-BB1B, 1769-L18ER-BB1B, 1769-L18ERM-BB1B

Topic	Page
Compatible Software Versions	2
Before You Begin	2
Enhancements	3
Corrected Anomalies	4
Known Anomalies	5
Restrictions	9
Install the Controller Revision	10
Additional Resources	10

About This Publication

This publication describes enhancements, known anomalies, and restrictions for CompactLogix[™] 5370 L1 controllers, firmware revisions 20.012 and 20.011.

Information that has been added or changed since the last revision of this publication is indicated by a change bar as shown to the side of this paragraph. In addition to information specific to the most recent firmware revision, the information from previous minor revisions is retained in these release notes.

We strongly recommend that you review the information provided regarding previous firmware revisions. We recommend that you do so because, if you are upgrading your firmware through multiple previous revisions, all of the information specific to all of the revisions is applicable.

If you need to upgrade your 1769-L18ER-BB1B controller from revision 20.011...20.012, all of the information specific to revisions 20.011 and 20.012 is applicable.



Compatible Software Versions

To use firmware revision 20.012, these minimum software versions are required.

Table 1 - Compatible Software Versions

Software	Required Software Version, Min.
Compare Tool	3.20.02
ControlFLASH™	11.00.00
FactoryTalk® AssetCentre	4.00.00 (CPR 9, SR3)
FactoryTalk Services Platform	2.50.00 (CPR 9, SR5)
FactoryTalk Activation	3.50.00 (CPR 9, SR5)
RSLinX® Classic	2.59.01 (CPR 9, SR5)
RSLinX Enterprise	5.50.04 (CPR 9, SR5)
RSLogix™ 5000	20.01.00 (CPR 9, SR5)
RSNetWorx™ for DeviceNet	11.00.00 (CPR 9, SR5)
RSNetWorx for EtherNet/IP	

For system requirements, go to

<http://www.rockwellautomation.com/rockwellsoftware/design/rslogix5000/sysreq.html>.

Before You Begin

Before you upgrade your firmware, consider the following.



IMPORTANT

Loss of communication or power during a controller firmware upgrade can result in the controller rejecting the new firmware. Upon the rejection of new firmware, the controller reverts to the out-of-the-box firmware revision:

- If the controller firmware upgrade fails and the OK status indicator flashes red, take these corrective actions:
 - Cycle controller power and attempt the firmware upgrade again.
 - If, after attempting another upgrade, the controller's OK status indicator continues to flash red, cycle power and attempt another firmware upgrade.
 - If repeated attempts to upgrade the controller firmware continue to result in the OK status indicator flashing red, contact Rockwell Automation® Technical Support.
- If the controller firmware upgrade fails and the OK status indicator is solid red, contact Rockwell Automation Technical Support.

These preliminary actions are required before using your controller.

Table 2 - Before You Begin

If	Then						
You are updating a controller	Before you begin updating your controller, check the status of your Secure Digital (SD) card.						
	<table><tr><th>If your SD card is</th><th>Then</th></tr><tr><td>Unlocked</td><td>You can successfully upgrade the firmware to the intended revision.</td></tr><tr><td>Locked and the Load Image option is set to On Power Up</td><td><p>You should complete these steps before beginning the upgrade:</p><ul style="list-style-type: none">• Unlock the SD card.• Change the Load Image option to User Initiated.<p>If the card is locked when you attempt to upgrade the firmware, the upgrade fails and the controller reverts to the firmware revision already stored on the SD card.</p></td></tr></table>	If your SD card is	Then	Unlocked	You can successfully upgrade the firmware to the intended revision.	Locked and the Load Image option is set to On Power Up	<p>You should complete these steps before beginning the upgrade:</p> <ul style="list-style-type: none">• Unlock the SD card.• Change the Load Image option to User Initiated. <p>If the card is locked when you attempt to upgrade the firmware, the upgrade fails and the controller reverts to the firmware revision already stored on the SD card.</p>
	If your SD card is	Then					
	Unlocked	You can successfully upgrade the firmware to the intended revision.					
Locked and the Load Image option is set to On Power Up	<p>You should complete these steps before beginning the upgrade:</p> <ul style="list-style-type: none">• Unlock the SD card.• Change the Load Image option to User Initiated. <p>If the card is locked when you attempt to upgrade the firmware, the upgrade fails and the controller reverts to the firmware revision already stored on the SD card.</p>						
Unlocked Position							
Locked Position							

Enhancements

These enhancements are available when firmware revision 20.011 is used with RSLogix 5000 software, version 20.00.00 or later.

Table 3 - Enhancements with Firmware Revision 20.011

Cat. No.	Description
1769-L16ER-BB1B, 1769-L18ER-BB1B, 1769-L18ERM-BB1B	<p>Automatic Device Configuration for Drives</p> <p>This feature supports the automatic device replacement functionality for drives. This makes it easier to perform quick, efficient drive replacement without requiring any laptop, software, or user intervention aside from wiring in the new drive and setting a network address. Previously, device configuration data for PowerFlex® drives was kept in the ACD file and had to be manually managed via the AOP of the device. Now, when a module is replaced, the controller will automatically send it to the configuration data. Always supported by SERCOS and Integrated Motion on an EtherNet/IP network drives. Version 20 extends ADC support to the PowerFlex 755 drives.</p>
	<p>Electronic Data Sheet AOP</p> <p>This feature allows select devices that have properly configured EDS sheets to integrate directly with Logix without the need for a device profile. This improves the flexibility of the Integrated Architecture™ by providing a richer integrated experience to more devices.</p>
	<p>Finding/Adding Devices to the Logix Tree</p> <p>Enhancements to the Select Module dialog box make it easier to use and find devices. The Select Module dialog box now shows all registered devices. It also includes new string and category filters, a wildcard search, and a favorites list.</p>
	<p>Security</p> <p>To enhance system and device-level security in systems that use our products, Rockwell Automation prescribes validated, defense-in-depth measures and design practices to enhance system and device-level security. For the latest information on security solutions and enhancements, visit http://www.rockwellautomation.com/solutions/security.</p>

Table 3 - Enhancements with Firmware Revision 20.011

Cat. No.	Description
1769-L16ER-BB1B, 1769-L18ER-BB1B, 1769-L18ERM-BB1B	<p>Security Authority Binding By checking the Require Matching Security Authority ID for Authentication and Authorization checkbox, you can bind the project file to a specific instance of the FactoryTalk Security directory. This lets you to verify the identity of the FactoryTalk Security directory that was used to authenticate and authorize users of a secured project file or secured controller. Once this is assigned, the project file or the controller containing the project file cannot be accessed by any users unless they are authenticated by this specific FactoryTalk Security directory. For more information, see the FactoryTalk Security System Configuration Guide, publication FTSEC-QS001.</p> <p>Change Detection When online with a controller, a 64-bit integer is displayed in the Audit Value dialog box. This Audit Value changes every time an event listed in the Changes To Detect configuration dialog box occurs. By inspecting this value, you can quickly determine if the behavior of a controller has been modified since the last time it was inspected. The Change Detection Audit Value is also exposed as a predefined tag by RSLinx Enterprise software for use in HMI displays or other applications. Additionally, it is included in every entry of the Controller Log.</p>

Corrected Anomalies

These anomalies have been corrected with firmware revision 20.012.

Table 4 - Corrected Anomalies with Firmware Revision 20.012

Cat. No.	Description
1769-L16ER-BB1B, 1769-L18ER-BB1B, 1769-L18ERM-BB1B	<p>CORRECTED: Safe State Values out does not work for 1794-IE4X0E2, 1794-0E12, and 1794-0E8H modules.</p> <p>IMPORTANT: This is an RSLogix 5000 software anomaly that requires version 20.01.00 software for the correction (PSA 2012-02-006). Lgx00126967, Lgx00126968, Lgx00127022</p>
1769-L18ERM-BB1B	<p>CORRECTED: A program with coordinated motion using the Merge All parameter set at low velocity can cause the controller to generate unintended motion. Lgx00124761, Lgx00119183</p> <p>CORRECTED: Overshooting of an MCLM instruction while using an MCCD instruction can occur. In an application, the AccOverrideFactor cannot be changed, but an open list of path segments is processed. Lgx00124758, Lgx00124134</p>

Known Anomalies

These anomalies have been identified with firmware revisions 20.012 and 20.011.

Table 5 - Known Anomalies with Firmware Revisions 20.012 and 20.011

Cat. No.	Description
1769-L16ER-BB1B, 1769-L18ER-BB1B, 1769-L18ERM-BB1B	<p>When using the Automatic Device Configuration (ADC) feature, the Logix controller 'owns' the configuration in the drive. Do not use the HIM or other external tools, such as DriveExplorer, to change drive parameters. Doing so may cause a sequence of events to occur that results in the connection between the controller and the drive to be dropped, and causes the controller to not be able to re-establish the connection. Consider using the Write Mask function (drive Parameter 888 - [Write Mask Cfg]) to prevent tools connected to ports other than the Embedded EtherNet/IP port from writing to the drive.</p> <p style="text-align: right;">Lgx00129012, Lgx00129165</p>
	<p>When the following conditions exist in your CompactLogix 5370 L1 control system, the controller may log a major recoverable fault, Type 2/Code 23:</p> <ul style="list-style-type: none"> The control system includes remote POINT I/O™ modules over an EtherNet/IP network. Any of the POINT I/O modules are configured to Major Fault On Controller if Connection Fails While in Run Mode. A power cycle occurs on the controller. <p>To work around this anomaly, do not configure any remote POINT I/O modules over an EtherNet/IP network to Major Fault On Controller if Connection Fails While in Run Mode.</p> <p style="text-align: right;">Lgx00129095, Lgx00129057</p>
	<p>When using a 1747-AENTR SLC™ 500 EtherNet/IP Adapter and more than five modules in a remote SLC chassis connected to your CompactLogix 5370 L1 controller, the second download of a project to your controller causes the controller to lose communication with the remote SLC chassis. After losing communication with the remote SLC chassis, you also cannot communicate with the controller via the USB nor Ethernet port. You must disconnect the Ethernet cable from the 1747-AENTR adapter.</p> <p>After the Ethernet cable is disconnected from the 1747-AENTR adapter, you can re-establish communication to the controller. However, the controller contains no program at that point.</p> <p>You must re-download the program to the controller and then reconnect the Ethernet cable to the 1747-AENTR adapter to resume normal operations.</p> <p style="text-align: right;">Lgx00128819, Lgx00127668</p>
	<p>PI function block appears to stop executing as the output does not change and no instruction faults are logged.</p> <p>If the PI instruction is being used in Linear mode, this floating-point equation is used to calculate the ITerm.</p> $Kp \times Wld \times \frac{WldInput + WldInput_{n-1}}{2} \times DeltaT + ITerm_{n-1}$ <p>Due to the use of the single-precision floating point values, it may be possible, depending on the values of WLD and KP, for the ITerm value to be small enough, less than 0.0000001, to be lost when adding to the ITerm_{n-1}.</p> <p>For more information regarding the PI instruction, see the Logix5000™ Controllers Process Control and Drives Instructions User Manual, publication 1756-RM006.</p> <p style="text-align: right;">Lgx00070832</p>
	<p>Changes made to the Buffer Timeout value for FactoryTalk Alarms and Events subscribers do not take effect until the existing buffer has been deleted.</p> <p>The FactoryTalk alarm buffer (stored in Logix controller memory) is designed to persist through power cycles. If you change the Buffer Timeout value (via the Communication Setup dialog box in FactoryTalk View SE software), the controller does not use the new timeout value until the existing buffer is deleted and then recreated. To force recreation of this buffer, do one of the following:</p> <ul style="list-style-type: none"> Redownload the project to the controller. Disconnect the FactoryTalk Alarms and Events subscriber and leave it disconnected until the existing timeout expires. <p style="text-align: right;">Lgx00069461</p>
	<p>The MinDurationPRE and MinDurationACC members of ALARM_ANALOG and ALARM_DIGITAL tags are defined as DINT (signed double integer) but they are treated as UDINT (unsigned double integer) by Logix firmware. This causes negative values of the tag members to be handled as large positive numbers when they should be handled as zero.</p> <p style="text-align: right;">Lgx00119996, Lgx00119981</p>
	<p>When you accept edits in LD, ST, and FBD, the controller will log an 'Online Edit' entry in the controller log. Accepting edits in a SFC routine is done by performing a partial import, resulting in a 'Transaction Commit' entry in the controller log.</p> <p>This is confusing because you can select to mask both entries separately. Selecting only Online edits would cause the Audit Value to change only when FBD, ST, and LD edits are made. SFC online edits would change the Audit Value only if the 'Partial Import Online Transaction Completed' bit was set.</p> <p style="text-align: right;">Lgx00122528, Lgx00122622</p>

Table 5 - Known Anomalies with Firmware Revisions 20.012 and 20.011

Cat. No.	Description
1769-L16ER-BB1B, 1769-L18ER-BB1B, 1769-L18ERM-BB1B	<p>In SFCs, when using time-limited actions in steps, if the program stays on a given step for greater than 24 days (2**32 ms) the timer's accumulator (ACC) will roll over and the action body starts to execute again.</p> <p>The time-limited action initializes its timer when it starts (step is first scanned). On subsequent scans, it compares the timers PRE and ACC value. If ACC<PRE, the action body will execute. If ACC >=PRE, it is not executed. When the rollover occurs, the ACC, PRE, and the action body will again execute when it should not.</p> <p style="text-align: right;">Lgx00124689, Lgx00124697</p> <hr/> <p>The controller supports only three active reconfigure messages at a time. If more than three are triggered at a time, they will complete (DN bit will go high), but not all the modules will be reconfigured.</p> <p>For example, if you send five reconfiguration messages at the same time, three reconfigure messages will truly complete (DN bit will go high), and the I/O modules will be reconfigured. The other two reconfigure messages will indicate complete (DN bit will go high), but the I/O modules will not be reconfigured. In this case, the last two should have errored (ER bit), but do not.</p> <p style="text-align: right;">Lgx00125204, Lgx00124996</p> <hr/> <p>When launching RSLogix 5000 software, the Log On to FactoryTalk dialog box can be displayed. This dialog box can be seen when you do not have Administrator privileges on the personal computer and the current user does not exist in the FactoryTalk directory. If you cancel this dialog box, RSLogix 5000 software will not be launched. When the dialog box is displayed, entering the credentials for a user that has Administrator privileges on the personal computer will then allow RSLogix 5000 software to be launched.</p> <p>To avoid seeing this dialog box, you can add the current user or user group to the FactoryTalk directory. Follow these steps to add a user or user group to the FactoryTalk directory.</p> <ol style="list-style-type: none"> 1. Launch the FactoryTalk Administration Console (available from the Start menu). 2. Select the Network directory when prompted. (You may need to provide credentials for a user with Administrator privileges in order to continue.) 3. To allow access for a particular user, navigate to Network\System\Users and Groups\Users, right-click the Users folder and choose New>Windows Linked User. 4. Click Add and provide the domain\logon name for the desired user. (You can click Check Names to verify that the name was found.) 5. To allow access for all authenticated users, navigate to Network\System\Users and Groups\User Groups, right-click the User Groups folder and choose New>Windows Linked User Group. 6. Click Add and type the name of the user group, Authenticated Users. <p>The Log On to FactoryTalk dialog box can also display when using Remote Desktop to connect to the personal computer running RSLogix 5000 software. This is due to FactoryTalk Security not recognizing the computer name. To enable access through Remote Desktop for a specific computer, add the name of the computer initiating the Remote Desktop connection to the Network\System\Computers and Groups\Computers folder in the FactoryTalk Administration Console.</p> <p>To allow all computers to connect, follow these steps.</p> <ol style="list-style-type: none"> 1. Open the FactoryTalk Administration Console and log in to the Network directory by using your domain credentials. 2. Navigate to Network\System\Security Policy. 3. In the Computer Policy Settings section, set Identify terminal server clients using the name to Server Computer. <p>IMPORTANT: If Use single sign-on is set to disable in FactoryTalk software, then the Log On to FactoryTalk dialog box will be displayed each time RSLogix 5000 software is launched and proper user credentials must be entered in order to continue. (By default, 'Use single sign-on' is set to enable.)</p> <p style="text-align: right;">Lgx00124955</p>
1769-L18ERM-BB1B	<p>Under some rare occurrences, if a Motion Axis Move (MAM) instruction with Merge Enabled is activated during the deceleration segment of an active MAM instruction then the new MAM instruction can overshoot its programmed endpoint. The occurrence of the overshoot depends on the following factors:</p> <ul style="list-style-type: none"> • The original MAM instruction's remaining travel distance at the time of the merge and the new MAM instruction's remaining travel distance • The relationship of the decel jerk of the new MAM instruction to the decel jerk of the original MAM instruction • If the original MAM instruction is decelerating <p>Typically, the overshoot does not occur. If either of the following conditions exists, you will avoid the overshoot:</p> <ul style="list-style-type: none"> • The new MAM instruction is programmed with Merge Disabled. If there is no other motion active at the time of the merge, then the Merge Disable results in the same operation as the Merge Enable. • The new MAM instruction has a slightly higher jerk (in units/seconds³) than the original MAM instruction. You should note, though, lower value of jerk in % of time results in higher value of jerk (in units/seconds³). <p style="text-align: right;">Lgx00078822</p> <hr/> <p>If a Motion Group Shutdown Reset (MGSR) instruction is executed while a Motion Group Shutdown (MGSD) is still executing, motion error #7, that is, Shutdown State Error, results.</p> <p>The purpose of an MGSR instruction is to bring an axis group out of the shutdown state. However, when the scenario described in the previous paragraph exists, the MGSR instruction is not executed because the shutdown procedure, initiated by the MGSD instruction, has precedence. Thus, the MGSR instruction generates motion error #7 because the shutdown procedure has not completed. The shutdown procedure must complete before any attempt to reset the shutdown.</p> <p style="text-align: right;">Lgx00095484</p>

Table 5 - Known Anomalies with Firmware Revisions 20.012 and 20.011

Cat. No.	Description
1769-L18ERM-BB1B	<p>This anomaly occurs only in applications that use Integrated Motion on the EtherNet/IP network.</p> <p>With any coordinated move in a system that uses two or more Integrated Motion on the EtherNet/IP network axes, if one axis is disabled by using a Motion Servo Off (MSF) instruction, any remaining Integrated Motion on the EtherNet/IP network axes will generate an Excessive Velocity Error, that is, Drive Error 555.</p> <p style="text-align: right;">Lgx00105360</p>
	<p>This anomaly occurs only in applications that use Integrated Motion on the EtherNet/IP network.</p> <p>When you create a new Integrated Motion on the EtherNet/IP network axis, the default value for Mechanical Brake Delay = 0. If you are using a motor with a brake on this axis and do not change the Mechanical Brake Delay value, the motor will not work properly when you attempt to execute motion.</p> <p>To work around this anomaly, make sure that you set the Mechanical Brake Delay to the appropriate value before executing motion.</p> <p style="text-align: right;">Lgx00113541, Lgx00107169</p>
	<p>This anomaly occurs only in applications that use Integrated Motion on the EtherNet/IP network.</p> <p>Every time there is a Motion Servo Off (MSF) instruction/Motion Servo On (MSO) instruction cycle, the Position Trim value is added to the axis position. This change in axis position causes the axis to move unexpectedly by a distance equal to the Position Trim value.</p> <p style="text-align: right;">Lgx00113540, Lgx00108486</p>
	<p>If your application includes Integrated Motion on an EtherNet/IP network and power is cycled to any of the drives in the project, the controller may experience a major nonrecoverable fault.</p> <p>If your controller experiences a major nonrecoverable fault as a result of this anomaly, that is, power was cycled on a drive, clear the fault and then download the RSLogix 5000 project to the controller again.</p> <p style="text-align: right;">Lgx00126026, Lgx00125266</p>
1769-L16ER-BB1B, 1769-L18ER-BB1B, 1769-L18ERM-BB1B	<p>If the power to the controller is lost when the controller is writing a file to the SD card via a MSG instruction, the access can fail. The result of the failure is that the file or the file allocation table (FAT) can be corrupted on the SD card.</p> <p>Consequently, all future attempts to read from or write to the SD card can also fail.</p> <p>If your program is structured to attempt to access the SD card, it will repeatedly fail and experience a timeout condition on the operation. While these attempts are occurring, the controller does not service other message communication as expected, resulting in slower controller communication performance.</p> <p>IMPORTANT: As long as the corrupted file exists on the SD card, you cannot use the SD card in other controllers. You must first clear all files from the SD card before it can be used again.</p> <p>If you experience this anomaly, complete these steps to attempt to correct it.</p> <ol style="list-style-type: none"> 1. Change your controller to Program mode. 2. Remove the SD card. 3. Delete the corrupted file from the card or format the card. 4. Re-install the SD card. 5. Re-attempt to write the file to the SD card via a MSG instruction. <p>If you complete these steps and the issue persists, contact Rockwell Automation Technical Support.</p> <p>TIP: The life expectancy of flash media is dependent on the number of write cycles that are performed. Flash media controllers use wear leveling but you should avoid frequent writes.</p> <p>Avoiding frequent writes is particularly important when logging data. We recommend that you log data to a buffer in your controller's memory and limit the number of times data is written to removable media.</p> <p style="text-align: right;">Lgx00124850, Lgx00124576</p>
	<p>Your controller can experience a Module RPI Overlap minor fault (Type 03/Code 94) when you perform any of the following actions:</p> <ul style="list-style-type: none"> • Download an RSLogix 5000 project to the controller. Typically, a project download results in this anomaly if the project includes modules with large I/O sizes or high numbers of I/O modules. • While the controller is online, you attempt to change the RPI value for an I/O module. • While the controller is online, you attempt to inhibit and then uninhibit an I/O connection. <p>When your controller experiences a Module RPI Overlap minor fault as a result of these actions, use the Controller Properties dialog box to clear the fault.</p> <p style="text-align: right;">Lgx00125049, Lgx00124926, Lgx00124927</p>
	<p>The controller does not correctly display the active ring supervisor on the Ring Statistics webpage available from the Diagnostics folder.</p> <p>The webpage displays the active ring supervisor IP address in reverse order. For example, an active ring supervisor using an IP address = 192.168.1.4 appears on the Ring Statistics webpage as 4.1.168.192.</p> <p style="text-align: right;">Lgx00125647, Lgx00125517</p>
	<p>The controller's Ethernet port settings, for example, the IP address or Subnet Mask, are always loaded from the SD card regardless of the Load Image parameter configuration on the Nonvolatile Memory Load/Store dialog box.</p> <p style="text-align: right;">Lgx00126022, Lgx00125674</p>

Table 5 - Known Anomalies with Firmware Revisions 20.012 and 20.011

Cat. No.	Description
1769-L16ER-BB1B, 1769-L18ER-BB1B, 1769-L18ERM-BB1B	<p data-bbox="423 329 1469 380">When modifying the controller's Ethernet configuration with RSLogix Classic software, you may experience a Module Configuration Invalid: Parameter error (16#0009).</p> <p data-bbox="423 384 1469 434">This anomaly occurs if you try to apply two network configuration changes without closing the Controller Properties dialog box between the changes.</p> <p data-bbox="423 438 1469 489">To work around this anomaly, close the Controller Properties dialog box after making every Ethernet configuration change in RSLogix Classic software.</p> <p data-bbox="1263 493 1469 518" style="text-align: right;">Lgx00126023, Lgx00125612</p> <hr/> <p data-bbox="423 531 1469 581">In some conditions, an RSLogix 5000 project might not be restored or loaded from an installed SD card at controller powerup despite being configured to do so. This anomaly can occur when these conditions exist at powerup:</p> <ul data-bbox="423 585 1469 758" style="list-style-type: none"> <li data-bbox="423 585 1469 636">• The controller is using firmware revision 1.x. Either of the following conditions result in the controller using firmware revision 1.x: <ul data-bbox="451 619 1469 669" style="list-style-type: none"> <li data-bbox="451 619 1469 636">– You apply power to the controller powerup for the first time after taking it out of the box. <li data-bbox="451 640 1469 669">– A disruption occurs during the process of upgrading controller firmware via the ControlFLASH utility. <li data-bbox="423 682 1469 758">• The RSLogix 5000 project is configured with these parameters: <ul data-bbox="451 707 1469 758" style="list-style-type: none"> <li data-bbox="451 707 1469 732">– Load Image = On Corrupt Memory <li data-bbox="451 737 1469 758">– Load Mode = Remote Run <p data-bbox="423 779 1469 804">You can work around this anomaly by taking either of these actions before attempting to restore the RSLogix 5000 project for an SD card:</p> <ul data-bbox="423 808 1469 879" style="list-style-type: none"> <li data-bbox="423 808 1469 833">• Upgrade the controller firmware revision to revision 20.011 or later. <li data-bbox="423 846 1469 879">• Change the RSLogix 5000 project to Load Image = On Power Up. <p data-bbox="1263 884 1469 909" style="text-align: right;">Lgx00126635, Lgx00125820</p> <hr/> <p data-bbox="423 921 1469 972">Your controller might experience a major nonrecoverable fault if it uses an RSLogix 5000 project that requires most of the controller's available memory and power is cycled to the controller.</p> <p data-bbox="423 976 1469 1026">If the RSLogix 5000 project is so large that fewer than 25,000 bytes of controller memory remain free before power is cycled, the controller might experience this anomaly.</p> <p data-bbox="423 1031 1469 1056">Complete these steps to best determine how much controller memory the project uses.</p> <ol data-bbox="423 1060 1469 1295" style="list-style-type: none"> <li data-bbox="423 1060 1469 1085">1. If your controller is online, go offline. <li data-bbox="423 1089 1469 1115">2. Download the RSLogix 5000 project to the controller. <li data-bbox="423 1119 1469 1190">3. Cycle through all screens on each HMI device used in the application. Often, the inclusion of HMI devices, such as PanelView™ Plus terminals, in the project causes it to use a large portion of the controller's memory. <li data-bbox="423 1194 1469 1220">4. Go online with the controller. <li data-bbox="423 1224 1469 1295">5. Access the Memory tab on the Controller Properties dialog box: <ul data-bbox="451 1228 1469 1295" style="list-style-type: none"> <li data-bbox="451 1228 1469 1253">– If your controller has 25,000 or more bytes of memory free, it should not experience this anomaly. <li data-bbox="451 1257 1469 1295">– If your controller has fewer than 25,000 bytes of memory free, it is more likely to experience this anomaly after the next power cycle on the controller. <p data-bbox="423 1308 1469 1333">If this anomaly occurs, clear the fault and download the project.</p> <p data-bbox="1263 1337 1469 1362" style="text-align: right;">Lgx00127414, Lgx00127450</p> <hr/> <p data-bbox="423 1375 1469 1425">Your controller's domain name, an IP address setting, will not be retained if the name uses 48 characters and power is cycled to the controller. The maximum number of characters available in the domain name field is 48.</p> <p data-bbox="423 1430 1469 1480">Therefore, if you use all of the available characters in the domain name field and power is cycled to the controller, the domain name is not retained.</p> <p data-bbox="423 1484 1469 1509">This anomaly will not occur if the domain name field uses 47 or fewer characters.</p> <p data-bbox="1263 1514 1469 1539" style="text-align: right;">Lgx00126785, Lgx00126981</p> <hr/> <p data-bbox="423 1551 1469 1602">In RSLogix 5000 software, version 20.01.00 or earlier, you can configure the I/O Event Task for your CompactLogix 5370 L1 controller's project. However, the task will never be triggered because the functionality has been disabled in the controller.</p> <p data-bbox="1263 1606 1469 1631" style="text-align: right;">Lgx00126979, Lgx00126927</p>

Restrictions

These restrictions exist with firmware revisions 20.012 and 20.011.

Table 6 - Restrictions with Firmware Revisions 20.012 and 20.011

Cat. No.	Description
1769-L16ER-BB1B, 1769-L18ER-BB1B, 1769-L18ERM-BB1B	<ul style="list-style-type: none"> If you use a CE 6.0 Operating System PanelView Plus terminal in your CompactLogix 5370 L1 control system, you must upgrade to firmware upgrade package 6.10 for the controller to communicate with the terminal. This firmware upgrade file for package 6.10 is available at http://support.rockwellautomation.com/ControlFlash/FUWCom.asp. If you use a CE 4.1 Operating System PanelView Plus terminal in your CompactLogix 5370 L1 control system, you must upgrade to firmware upgrade package 5.10.08 for the new CompactLogix 5370 L1 controller to communicate. The firmware upgrade file is available at http://support.rockwellautomation.com/ControlFlash/FUW.asp. <p>For more information, see KnowledgeBase article #473017 - CompactLogix 5370 Controllers Compatibility with PanelView Plus.</p> <p style="text-align: right;">Lgx00127906</p> <p>These are the Arithmetic State flags anomalies:</p> <ul style="list-style-type: none"> When dealing with Floating point numbers, the controller does not truncate denormalized values or -0.0...0.0. For an integer divide, when the denominator is 0, the S:N and S:Z are not set. For the MOD instruction, the S:V is not set if an overflow occurred during the calculation. <p style="text-align: right;">Lgx00122480</p> <p>The Logix CPU security tool does not work with V20 controllers.</p> <p>The RSLogix 5000 Clock Update tool does not support Windows 7 or Windows Server 2008 operating system.</p> <p>The Totalizer (TOT) instruction may not function properly when a project used with a 1756-L7x controller is converted to be used with a CompactLogix 5370 L1 controller and then downloaded to a CompactLogix 5370 L1 controller. This anomaly can occur under these conditions:</p> <ul style="list-style-type: none"> An RSLogix 5000 project is running on a ControlLogix[®] controller, catalog numbers 1756-L7x, revision 18, with the TOT instruction in Run mode. The project is uploaded and saved to a new file. The new file is changed from the 1756-L7x controller, revision 18, to a CompactLogix 5370 L1 controller, revision 20. The project is downloaded to the new CompactLogix 5370 L1 controller. The project transitions to Run mode. <p>Upon transitioning to Run mode, the TOT instruction's output value is different from the last value generated when the same project was running on the first controller.</p> <p>To reset an invalid Totalizer value, set the ProgResetReq or OperResetReq to move the value of the instruction's Reset input parameter to the instruction's Total output parameter. Repeat this task once more to move the invalid value out of the instruction's OldTotal output parameter.</p> <p style="text-align: right;">Lgx00114767, Lgx00114731</p> <p>If the controller is connected to a computer via a USB cable and the computer is restarted while the cable remains connected, you must disconnect and reconnect the cable between the controller and computer after the computer restart is complete.</p> <p>Failure to disconnect and reconnect the cable results in a failure of the computer to recognize the controller when browsing in RSLinx Classic software.</p> <p style="text-align: right;">Lgx00122143</p>

Install the Controller Revision

Install the Controller Revision To download the latest CompactLogix 5370 L1 controllers firmware revision, go to <http://www.rockwellautomation.com/support/downloads> and select your desired revision. Then, use the ControlFLASH utility to upgrade your controller.

Alternatively, if you have installed RSLogix 5000 software, version 20, and related firmware, you may not need to complete the tasks described. The AutoFlash feature of RSLogix 5000 software detects if your controller firmware needs to be upgraded upon a program download to the controller. If a firmware upgrade is necessary, AutoFlash will initiate an upgrade.

After you have completed your firmware upgrade, complete these steps to verify that the upgrade was successful.

1. Cycle power to the controller.
2. Go online with the controller and view controller properties.
3. Verify that the firmware revision listed matches the firmware to which you intended to upgrade.
4. If the controller's firmware is not correct, initiate another firmware upgrade.

For more information about errors when completing a ControlFLASH upgrade, see the ControlFLASH Firmware Upgrade Kit Quick Start, publication [1756-QS105](#).

Additional Resources

These documents contain additional information concerning related products from Rockwell Automation.

Resource	Description
CompactLogix 5370 Controllers User Manual, publication 1769-UM021	Describes how to install, use and troubleshoot your CompactLogix 5370 controllers
ControlFLASH Firmware Upgrade Kit Quick Start, publication 1756-QS105	Contains informations about firmware upgrades, installation instructions, and error messages

You can view or download publications at <http://www.rockwellautomation.com/literature/>. To order paper copies of technical documentation, contact your local Allen-Bradley® distributor or Rockwell Automation sales representative.

Notes:

Rockwell Automation Support

Rockwell Automation provides technical information on the Web to assist you in using its products.

At <http://www.rockwellautomation.com/support>, you can find technical manuals, technical and application notes, sample code and links to software service packs, and a MySupport feature that you can customize to make the best use of these tools. You can also visit our Knowledgebase at <http://www.rockwellautomation.com/knowledgebase> for FAQs, technical information, support chat and forums, software updates, and to sign up for product notification updates.

For an additional level of technical phone support for installation, configuration, and troubleshooting, we offer TechConnectsm support programs. For more information, contact your local distributor or Rockwell Automation representative, or visit <http://www.rockwellautomation.com/support/>.

Installation Assistance

If you experience a problem within the first 24 hours of installation, review the information that is contained in this manual. You can contact Customer Support for initial help in getting your product up and running.

United States or Canada	1.440.646.3434
Outside United States or Canada	Use the Worldwide Locator at http://www.rockwellautomation.com/support/americas/phone_en.html , or contact your local Rockwell Automation representative.

New Product Satisfaction Return

Rockwell Automation tests all of its products to ensure that they are fully operational when shipped from the manufacturing facility. However, if your product is not functioning and needs to be returned, follow these procedures.

United States	Contact your distributor. You must provide a Customer Support case number (call the phone number above to obtain one) to your distributor to complete the return process.
Outside United States	Please contact your local Rockwell Automation representative for the return procedure.

Documentation Feedback

Your comments will help us serve your documentation needs better. If you have any suggestions on how to improve this document, complete this form, publication [RA-DU002](#), available at <http://www.rockwellautomation.com/literature/>.

Allen-Bradley, CompactLogix, ControlFLASH, ControlLogix, FactoryTalk, Logix5000, PanelView, POINT I/O, Rockwell Software, Rockwell Automation, RSLinx, RSLogix, RSNetworkx, and SLC are trademarks of Rockwell Automation, Inc.

Trademarks not belonging to Rockwell Automation are property of their respective companies.

Rockwell Otomasyon Ticaret A.Ş., Kar Plaza İş Merkezi E Blok Kat:6 34752 İçerenköy, İstanbul, Tel: +90 (216) 5698400

www.rockwellautomation.com

Power, Control and Information Solutions Headquarters

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444

Europe/Middle East/Africa: Rockwell Automation NV, Pegasus Park, De Kleetlaan 12a, 1831 Diegem, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640

Asia Pacific: Rockwell Automation, Level 14, Core F, Cyberport 3, 100 Cyberport Road, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846

Publication 1769-RN023B-EN-P - May 2012

Supersedes Publication 1769-RN023A-EN-P - February 2012

PN-148095

Copyright © 2012 Rockwell Automation, Inc. All rights reserved. Printed in the U.S.A.