

# The Therac 25

## A case study in safety failure


- Radiation therapy machine
- “The most serious computer-related accidents to date”
- People were killed
- Reference:

Nancy Leveson and Clark Turner, “The Investigation of the Therac-25 Accidents”, Computer, 26, 7 (July 1993) pp 18-41.

# Therac 25 Background

- Medical linear accelerator developed by Atomic Energy of Canada, Ltd. in mid-1970s
- Delivers 25 MeV photons or electrons of various energies
- Controlled by PDP-11 minicomputer
- Software responsible for safety
- Software adapted from earlier Therac-6 & Therac 20 systems, which had hardware interlocks for safety

# The Therac 25



# Therac 25 Turntable




Figure B. Upper turntable assembly.

# Therac 25 Turntable

- Electron mode
  - 5-25 MEV
  - Magnets spread beam
  - Ion chamber monitor
- X-ray mode
  - 25 MEV electrons hit target
  - “Beam flattener” attenuates
  - 100x beam current
  - Ion chamber monitor
- Field-light mode
  - No current
  - Mirror & light used to check alignment
  - No ion chamber (since not treating)




Figure B. Upper turntable assembly.

# Therac 25 Turntable

- Computer adjusts turntable position
- Microswitches detect turntable setting
- 3-bit binary code used to encode turntable setting
- Software checks replace hardware interlocks




Figure B. Upper turntable assembly.

# Therac 25 Software Development

- Evolved from Therac 6 system (1972-1976)
- Incorporated some Therac 20 code, as well
- Written in PDP-11 assembler
- Custom operating system
- Little documentation during development
- Minimal unit and software testing
- Q/A testing was 2700 hours of use as integrated system
- Programmer left AECL in 1986, little information available about his background



*"I know this may be an awkward time,  
but do you recall him ever mentioning source code."*



# Therac 25 Software Functions

- Monitors machine status
- Sets up machine for treatment
- Turns beam on and off in response to operator
- Monitors interlocks
- If fault, either prevents treatment start or causes a pause/suspend

# Therac 25 Software Structure

- Critical tasks:
  - Treatment monitor
  - Servo
  - Housekeeping
- Non-critical tasks:
  - Checksum
  - Keyboard
  - Calibration
  - etc.
- Concurrent access to shared memory, “test” and “set” of variables not indivisible, race conditions

# Operator Procedures

- Position patient on table
- Manually set treatment field size and gantry rotation; attach accessories
- Leave room
- Use VT-100 console to enter patient data, dose data, etc.
- (System compares manual settings with system values)
- If “verified”, operator can start machine
- Else must re-enter data

# Operator Screen Layout

PATIENT NAME : TEST		BEAM TYPE: X ENERGY (KøV):		A	1
TREATMENT MODE: FIX				25	
		ACTUAL	PRESCRIBED		
UNIT RATE/MINUTE		0	200		
MONITOR UNITS		50 50	200		
TIME (MIN)		0.27	1.00		
GANTRY ROTATION (DEG)		0.0	0	VERIFIED	
COLLIMATOR ROTATION (DEG)		359.2	359	VERIFIED	
COLLIMATOR X (CM)		14.2	14.3	VERIFIED	
COLLIMATOR Y (CM)		27.2	27.3	VERIFIED	
WEDGE NUMBER		1	1	VERIFIED	
ACCESSORY NUMBER		0	0	VERIFIED	
DATE : 84-OCT-26		SYSTEM: BEAM READY		OP.MODE: TREAT	
TIME : 12:55. 8		TREAT : TREAT PAUSE		X-RAY	
OPR ID: T25VO2-RO3		REASON: OPERATOR		COMMAND:	
				AUTO	
				173777	

Figure A. Operator Interface screen layout.

# Operator Procedures

- **Complaint**

- Re-entering all that data manually is very tedious

- **Response**

- Set things up so that “carriage return” copies previous data for entry
- Series of carriage returns effectively permits fast re-entry of unchanged parts of data

# Operator Procedures

- **Error Conditions**

- “Treatment suspend” requires complete machine reset
- “Treatment pause” can be resumed if operator types “P” at console
- Machine insists on reset after 5 “P”s
- Malfunction messages fairly common & usually do not affect safety

- **Error Messages**

- Cryptic
- Some were of the form “Malfunction NN”

# FDA Comment on Manual

10/1/10 10:10:10

The operator's manual supplied with the machine does not explain nor even address the malfunction codes. The [Maintenance] Manual lists the various malfunction numbers but gives no explanation. The materials provided give *no* indication that these malfunctions could place a patient at risk.

The program does not advise the operator if a situation exists wherein the ion chambers used to monitor the patient are saturated, thus are beyond the measurement limits of the instrument. This software package does not appear to contain a safety system to prevent parameters being entered and intermixed that would result in excessive radiation being delivered to the patient under treatment.

# Accident History

- 11 Therac 25's installed (5 US, 6 Canada)
- Six accidents involving massive overdoses between 1985 and 1987
- Machines recalled in 1987
- Related problems in Therac 20 discovered later but hardware interlocks prevented injuries



# E.g., East Texas, March 1986

- History of 500 patients treated successfully
- Prescribed: 22MeV electrons, 180 rads
- Operator selected x-rays by mistake, used cursor keys to change to electrons
- Machine tripped with “Malfunction 54”
  - Documentation explains this is “dose input 2” error
- Operator proceeded; machine tripped again

# E.g., East Texas, March 1986

- Patient felt something wrong on first jolt, tried to get up
- Video/audio links to room not functioning
- Patient felt jolt on arm while getting up, pounded on door
- Treatment cancelled for day
- Calibration checks seemed normal
- Later found patient had gotten 16,500-25,000 rads over 1 cm square
- Patient eventually died after 5 months

# E.g., East Texas, March 1986

- AECL engineers could not replicate a Malfunction 54
- AECL home office engineer said machine could not overdose patient
- AECL suggested patient got an electric shock
- No grounding problems found
- Machine returned to service April 7, 1986

# East Texas/ April 11, 1986

- Prescription 10 MeV, area 7 x 10 cm
- Operator used cursor keys to change x-rays to electrons, saw “beam ready”, and turned machine on
- Loud noise, shutdown, malfunction 54
- Patient in great pain
- Patient died three weeks later

# East Texas/ April 11, 1986

- Machine taken out of service
- ETCC eventually reproduced malfunction 54
  - Data entry speed critical factor
  - Observed 4000 rad dose
- AECL later measured 25,000 rads
- In lawsuit, earlier “cursor up” problems reported, which AECL believed to have been fixed

# Yakima Valley, January 1987

- Plan: 2 film verification exposures (3 & 4 rads) + 79 rad photon treatment
- Performed two film exposures
- Operator used hand controls to rotate table to field-light position & check alignment
- Operator set machine but forgot to remove film
- Operator turned beam on, machine showed no dose & displayed fleeting message
- Operator proceeded from pause

# Yakima Valley, January 1987

- After another machine pause, operator reentered room.
- Patient complained of burning sensation
- Patient developed severe striped burns
- Patient died in April
- Hospital obtained similar pattern on film by running machine with turntable in field light position

# Responses

- Voluntary Class II recall 8/1/85
- AECL accident report April 15, 1986
- First version of corrective action plan 6/13/86
- Second Yakima overdose 1/17/87
- Fifth (final) corrective action plan 7/21/87
- Interim safety analysis report 1/29/88
- Final safety analysis report 11/3/88



# Tyler Accident Race Condition




Figure 2. Tasks and subroutines in the code blamed for the Tyler accidents.

# Operator Screen Layout

PATIENT NAME : TEST		BEAM TYPE: X ENERGY (KøV):		A	1
TREATMENT MODE: FIX				25	
		ACTUAL	PRESCRIBED		
UNIT RATE/MINUTE		0	200		
MONITOR UNITS		50 50	200		
TIME (MIN)		0.27	1.00		
GANTRY ROTATION (DEG)		0.0	0	VERIFIED	
COLLIMATOR ROTATION (DEG)		359.2	359	VERIFIED	
COLLIMATOR X (CM)		14.2	14.3	VERIFIED	
COLLIMATOR Y (CM)		27.2	27.3	VERIFIED	
WEDGE NUMBER		1	1	VERIFIED	
ACCESSORY NUMBER		0	0	VERIFIED	
DATE : 84-OCT-26		SYSTEM: BEAM READY		OP.MODE: TREAT	
TIME : 12:55. 8		TREAT : TREAT PAUSE		X-RAY	
OPR ID: T25VO2-RO3		REASON: OPERATOR		COMMAND:	
				AUTO	
				173777	

Figure A. Operator Interface screen layout.

# Yakima Accident Race Condition




Figure 4. Yakima software flaw.

# Therac 25 Turntable




Figure B. Upper turntable assembly.

# Corrective Action Plan

- Numerous hardware and software changes
- All interruptions related to dosimetry not continuable
- independent hardware & software shutdowns
- potentiometer on turntable
- hardware interlocks
- “dead man switch” motion enable
- Fix documentation, messages, & user manuals
- etc

# Lessons ( Leveson & Turner)

- Complacency
- Assumption that problem was understood without adequate evidence (“the last bug” fallacy).
- Sole reliance on software for safety
- Systems engineering practices

# Lessons ( Leveson & Turner)

- Documentation key from beginning
- Use established software engineering practices
- Keep designs simple
- Build in software error logging & audit trails
- Extensive software testing and formal analysis at all levels
- Revalidate reused software
- Don't rely only on software for safety
- Do incorporate redundancy
- Pay careful attention to human factors
- Involve users at all phases