

[2020-04-29 01:43:53.092] RdPoESrv rdPoESrv.cc:316 INFO:Number of newly detected RDs: 1  
[2020-04-29 01:43:53.092] RdPoESrv rdPoESrv.cc:317 INFO:Newly detected RdPorts: 8  
[2020-04-29 01:43:53.092] RdEqpCtrl rdEqpCtrl.cc:590 INFO:Setting RD(RdPort:8) as starting  
[2020-04-29 01:43:53.092] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:674 INFO:RdEqp Event Report RdPort:8, RD Connected  
[2020-04-29 01:43:53.092] RdPoESrv rdPoESrv.cc:644 INFO:Power on RdPort 8  
[2020-04-29 01:43:53.096] RdEqpCtrl rdCableSrv.cc:812 INFO:Tx unmuted on RD port 8  
[2020-04-29 01:43:53.096] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:HUNT\_RD\_SERVER transactionId:45  
[2020-04-29 01:43:53.100] XPP\_XCM xcm\_device.c:550 INFO:Opening Device Driver "RDDEV", 7  
[2020-04-29 01:43:53.112] RdClient7 rdLinkConnectionManager.cc:270 INFO:Set MODEM CARRIER\_FREQ to 234 MHz for RdId:7, RdPort:8  
[2020-04-29 01:43:53.112] XPP\_XCM xcm\_device.c:637 INFO:Starting Device Driver "RDDEV", 7  
[2020-04-29 01:43:53.260] rdcisim7 rdcisimServer.cc:44 INFO:\*\*\*\*\* RDCI SIM Forwarder started \*\*\*\*\*  
[2020-04-29 01:43:53.260] rdcisim7 rdcisimServer.cc:45 INFO:RDCI Version Info - Build:36, Date:2019-02-19, Version:R5C, IWD Version:RDCI\_IWD\_J  
[2020-04-29 01:43:54.260] RdClient7 rdBaseMessageHandler.cc:136 INFO:HUNT\_RD\_SERVER\_SIG transaction id 45  
[2020-04-29 01:43:54.260] rdcisim7 rdcisimServer.cc:290 INFO:\*\*\*\*\* Forwarding to PID 0x15000fc for RD7 \*\*\*\*\*  
[2020-04-29 01:43:54.260] rdcisim7 rdcisimServer.cc:323 INFO:\*\*\*\*\* Connecting client PID 0x1000a2 to server PID 0x15000fc for RD7 \*\*\*\*\*  
[2020-04-29 01:43:54.468] RdClient7 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_UTC transactionId:47  
[2020-04-29 01:43:54.588] RdClient7 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:48  
[2020-04-29 01:43:54.688] RdClient7 rdClientBoardBase.cc:165 INFO:sendMsg: type:SUBSCRIBE\_FAULTS transactionId:49  
[2020-04-29 01:43:54.776] RdClient7 rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BOARD\_CAP\_EXCHANGE transactionId:50  
[2020-04-29 01:43:54.884] RdClient7 rdBoardSrv.cc:2053 INFO:Response for RdPort:8 to get Board Capability Req:CFM\_MSG  
[2020-04-29 01:43:55.000] RdClient7 rdSwLoadingSrvBase.cc:538 INFO:Using default load module 'CXC 112 4419/5' from HW PID  
[2020-04-29 01:43:55.000] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 6, handle 1)  
[2020-04-29 01:43:55.004] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 7, handle 1)  
[2020-04-29 01:43:55.004] RdClient7 rdSwLoadingSrvBase.cc:1245 INFO:RD boardOperationalCapability.upgradableDesignDB == 1: RdPort: '8'  
[2020-04-29 01:43:55.004] RdClient7 rdSwLoadingSrvBase.cc:1825 INFO:hwPidCapability.productRevision: R1A  
[2020-04-29 01:43:55.004] RdClient7 rdSwLoadingSrvBase.cc:1477 INFO:Found Match for prodNum KRY 901 390/1, prodNubRev R1A, matching dbProdNum CXC 1124505/1.  
[2020-04-29 01:43:55.004] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 10, handle 1)  
[2020-04-29 01:43:55.004] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 11, handle 1)  
[2020-04-29 01:43:55.004] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 12, handle 1)  
[2020-04-29 01:43:55.004] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 13, handle 1)  
[2020-04-29 01:43:55.004] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 14, handle 1)  
[2020-04-29 01:43:55.004] RdClient7 rdSwLoadingSrvBase.cc:1865 INFO:Add RD DB to loadingData  
[2020-04-29 01:43:55.004] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 6, handle 1)  
[2020-04-29 01:43:55.008] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 7, handle 1)  
[2020-04-29 01:43:55.188] RdClient7 rdSwLoadingSrvBase.cc:1323 INFO:Design DB is not in expected state. (RdPort:8) restartAttempts 0  
[2020-04-29 01:43:55.188] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BRANCH\_CAP transactionId:54  
[2020-04-29 01:43:55.192] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BRANCH\_CAP transactionId:55  
[2020-04-29 01:43:55.408] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:55 INFO:,noCap=11,branchId=A  
[2020-04-29 01:43:55.408] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:222 INFO:capId=1(RDCI\_CAP\_BRANCH\_BAND\_INFO),duplexMode=0(RDCI\_DUPLEX\_MODE\_FDD),band=BandIII  
[2020-04-29 01:43:55.408] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:234  
INFO:capId=2(RDCI\_CAP\_BRANCH\_TX\_FREQUENCY)RfMin=18050000,RfMax=18800000,IfMin=1100000,IfMax=1500000,InvSpectrum=0,StepSize=10,RfTuneMin=18050000,RfTuneMax=18800000,RfTuneCoupled=3,Ibw=400000  
[2020-04-29 01:43:55.408] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:256  
INFO:capId=3(RDCI\_CAP\_BRANCH\_RX\_FREQUENCY)RfMin=17100000,RfMax=17850000,IfMin=400000,IfMax=800000,InvSpectrum=0,StepSize=10,RfTuneMin=17100000,RfTuneMax=17850000,RfTuneCoupled=3,Ibw=400000  
[2020-04-29 01:43:55.412] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:278  
INFO:capId=4(RDCI\_CAP\_BRANCH\_CABLE\_LOSS\_COMP),fskModemOutputPower=-1561,minILThreshold=240,maxILThreshold=4590,catFrequencySelect=1300000  
[2020-04-29 01:43:55.412] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:293 INFO:capId=5(RDCI\_CAP\_BRANCH\_RX\_GAIN),nominalGain=3650,noiseFigure=0  
[2020-04-29 01:43:55.412] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:306 INFO:capId=6(RDCI\_CAP\_BRANCH\_TX\_POWER),txPar=750,txPowerClassUsage=1700  
[2020-04-29 01:43:55.412] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:320 INFO:capId=7(RDCI\_CAP\_BRANCH\_TX\_GAIN\_ADJUST),txGainAdjustHi=0,txGainAdjustLo=-1000  
[2020-04-29 01:43:55.412] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:333 INFO:capId=8(RDCI\_CAP\_BRANCH\_RX\_AGC),rxAgcMode=0,rxAgcDefault=0  
[2020-04-29 01:43:55.412] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:352 INFO:capId=9(RDCI\_CAP\_BRANCH\_TX\_POWER\_MEAS),txPowerMeasMode=2,txMaxPowerBackoff=-10000  
[2020-04-29 01:43:55.412] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:366 INFO:capId=10(RDCI\_CAP\_BRANCH\_CARRIER\_DATA),carrierDataRequired=1,txLoMode=IBW  
[2020-04-29 01:43:55.412] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:387 INFO:capId=11(RDCI\_CAP\_BRANCH\_WCDMA\_DESENSE),desenseGainRebalance=24 dB  
[2020-04-29 01:43:55.644] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:55 INFO:,noCap=11,branchId=B  
[2020-04-29 01:43:55.644] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:222 INFO:capId=1(RDCI\_CAP\_BRANCH\_BAND\_INFO),duplexMode=0(RDCI\_DUPLEX\_MODE\_FDD),band=BandIII  
[2020-04-29 01:43:55.644] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:234  
INFO:capId=2(RDCI\_CAP\_BRANCH\_TX\_FREQUENCY)RfMin=18050000,RfMax=18800000,IfMin=1100000,IfMax=1500000,InvSpectrum=0,StepSize=10,RfTuneMin=18050000,RfTuneMax=18800000,RfTuneCoupled=3,Ibw=400000  
[2020-04-29 01:43:55.644] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:256  
INFO:capId=3(RDCI\_CAP\_BRANCH\_RX\_FREQUENCY)RfMin=17100000,RfMax=17850000,IfMin=400000,IfMax=800000,InvSpectrum=0,StepSize=10,RfTuneMin=17100000,RfTuneMax=17850000,RfTuneCoupled=3,Ibw=400000  
[2020-04-29 01:43:55.644] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:278  
INFO:capId=4(RDCI\_CAP\_BRANCH\_CABLE\_LOSS\_COMP),fskModemOutputPower=-1752,minILThreshold=240,maxILThreshold=4590,catFrequencySelect=1300000  
[2020-04-29 01:43:55.644] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:293 INFO:capId=5(RDCI\_CAP\_BRANCH\_RX\_GAIN),nominalGain=3650,noiseFigure=0  
[2020-04-29 01:43:55.644] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:306 INFO:capId=6(RDCI\_CAP\_BRANCH\_TX\_POWER),txPar=750,txPowerClassUsage=1700  
[2020-04-29 01:43:55.644] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:320 INFO:capId=7(RDCI\_CAP\_BRANCH\_TX\_GAIN\_ADJUST),txGainAdjustHi=0,txGainAdjustLo=-1000  
[2020-04-29 01:43:55.644] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:333 INFO:capId=8(RDCI\_CAP\_BRANCH\_RX\_AGC),rxAgcMode=0,rxAgcDefault=0  
[2020-04-29 01:43:55.644] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:352 INFO:capId=9(RDCI\_CAP\_BRANCH\_TX\_POWER\_MEAS),txPowerMeasMode=2,txMaxPowerBackoff=-10000  
[2020-04-29 01:43:55.644] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:366 INFO:capId=10(RDCI\_CAP\_BRANCH\_CARRIER\_DATA),carrierDataRequired=1,txLoMode=IBW  
[2020-04-29 01:43:55.644] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:387 INFO:capId=11(RDCI\_CAP\_BRANCH\_WCDMA\_DESENSE),desenseGainRebalance=24 dB  
[2020-04-29 01:43:55.656] RdClient7 rdBoardSrv.cc:1807 INFO:send SetTxIfMaxPowerReq with RdPort=8, Br=0, maxPower=-22  
[2020-04-29 01:43:55.656] RdClient7 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_TX\_IF\_MAX\_PWR transactionId:56  
[2020-04-29 01:43:55.656] RdClient7 rdBoardSrv.cc:1807 INFO:send SetTxIfMaxPowerReq with RdPort=8, Br=1, maxPower=-2  
[2020-04-29 01:43:55.656] RdClient7 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_TX\_IF\_MAX\_PWR transactionId:57  
[2020-04-29 01:43:55.840] RdClient7 rdBoardSrv.cc:1832 INFO:Response for RdPort:8 to set TxIfMaxPwrDone:CFM\_MSG  
[2020-04-29 01:43:55.964] RdClient7 rdBoardSrv.cc:1832 INFO:Response for RdPort:8 to set TxIfMaxPwrDone:CFM\_MSG  
[2020-04-29 01:43:55.964] RdClient7 rdBoardSrv.cc:1734 INFO:notifyStartRdDone: 7  
[2020-04-29 01:43:55.964] RdEqpCtrl rdEqpCtrl.cc:399 INFO:StartRdDone with RdPort:8  
[2020-04-29 01:43:55.964] RdEqpCtrl rdCableSrv.cc:495 INFO:Starting Pair Swap Test with RD PORT list: { 8 }  
[2020-04-29 01:43:56.124] RdEqpCtrl rdEqpCtrl.cc:963 INFO:pairSwap test done.  
[2020-04-29 01:43:56.124] RdEqpCtrl rdCableMeasSvSrv.cc:103 INFO:Starting cable IL measurement with RD PORT list: { 8 }  
[2020-04-29 01:43:57.296] RdCableMeasSvSrv rdClientCableMeasurements.cc:213 INFO:A(0mb), B(5482mb), C(226mb) Coefficient was sent to RdPort(8) for branchId(0)  
[2020-04-29 01:43:57.296] RdCableMeasSvSrv rdCableILMeasSv.cc:727 INFO:Stored Rx-IL(2833mb) and Tx-IL(4211mb) for RdPort(8) and branchId(0)  
[2020-04-29 01:43:57.400] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received CFM\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(8) and Branch(A)  
[2020-04-29 01:43:57.452] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received IND\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(8) and Branch(A)  
[2020-04-29 01:43:58.372] RdCableMeasSvSrv rdClientCableMeasurements.cc:213 INFO:A(0mb), B(5291mb), C(218mb) Coefficient was sent to RdPort(8) for branchId(1)  
[2020-04-29 01:43:58.372] RdCableMeasSvSrv rdCableILMeasSv.cc:727 INFO:Stored Rx-IL(2735mb) and Tx-IL(4064mb) for RdPort(8) and branchId(1)  
[2020-04-29 01:43:58.372] RdEqpCtrl rdEqpCtrl.cc:839 INFO:Cable IL Measurement done  
[2020-04-29 01:43:58.372] RdEqpCtrl rdCableSrv.cc:680 INFO:Equalizer for RD port 8 set to ON  
[2020-04-29 01:43:58.376] RdEqpCtrl rdCableSrv.cc:887 INFO:Rx unmuted on RD port 8  
[2020-04-29 01:43:58.376] RdEqpCtrl rdEqpCtrl.cc:860 INFO:Starting AGC test  
[2020-04-29 01:43:58.376] RdEqpCtrl rdEqpCtrl.cc:922 INFO:AGC test done  
[2020-04-29 01:43:58.376] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:81  
[2020-04-29 01:43:58.376] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:2260 INFO:RdEqp Event Report RdPort:8, RD Unlocked  
[2020-04-29 01:43:58.376] RdEqpCtrl rdEqpCtrl.cc:1240 INFO:Processing Set Led Action for RdPort:8; LED type is 0  
[2020-04-29 01:43:58.376] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:82  
[2020-04-29 01:43:58.376] RdEqpFaultCtrl rdActionListUtil.cc:58 INFO:RdEqpEvent:RD Unlocked/RD Locked, RdPort=8 Set LED Action successful;  
[2020-04-29 01:43:58.380] trProc trCdc.c:4799 INFO:INTERNAL RESTART ALL ROT MEAS REQ  
[2020-04-29 01:43:58.380] rdBcProc7 ccieLteInterface.cc:108 INFO:SAR:Published interface: rd08/BcServer(0x17000f8) and RDBCIC7(highestProtocolRev:3(0x3),proto\_basic:0,proto\_spec:3),dispatchPid\_: 0x1000d9  
[2020-04-29 01:43:58.380] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:2260 INFO:RdEqp Event Report RdPort:8, RD Unlocked  
[2020-04-29 01:43:58.380] RdEqpCtrl rdEqpCtrl.cc:1240 INFO:Processing Set Led Action for RdPort:8; LED type is 0  
[2020-04-29 01:43:58.380] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:83  
[2020-04-29 01:43:58.380] RdEqpFaultCtrl rdActionListUtil.cc:58 INFO:RdEqpEvent:RD Unlocked/RD Locked, RdPort=8 Set LED Action successful;  
[2020-04-29 01:43:58.380] rdCbcProc7 ccieLteInterface.cc:113 INFO:SAR:Published interface: rd08/rdCbcServer(0x9000fd) and RDBCIC7(highestProtocolRev:257),dispatchPid\_: 0x1000db  
[2020-04-29 01:43:58.456] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received CFM\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(8) and Branch(B)  
[2020-04-29 01:43:58.512] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received IND\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(8) and Branch(B)  
[2020-04-29 01:44:01.244] RdPoESrv rdPoESrv.cc:709 INFO:Power off RdPort 8  
[2020-04-29 01:44:01.252] RdPoESrv rdPoESrv.cc:430 INFO:RdPort 8: disconnected  
[2020-04-29 01:44:01.252] RdEqpCtrl rdEqpCtrl.cc:605 INFO:Processing PoE disconnect for RdPort:8  
[2020-04-29 01:44:01.252] RdEqpCtrl rdCableSrv.cc:812 INFO:Tx muted on RD port 8  
[2020-04-29 01:44:01.252] RdEqpCtrl rdCableSrv.cc:887 INFO:Rx muted on RD port 8  
[2020-04-29 01:44:01.252] RdEqpCtrl rdCableSrv.cc:680 INFO:Equalizer for RD port 8 set to TERMINATED  
[2020-04-29 01:44:01.252] RdEqpCtrl rdEqpCtrl.cc:664 INFO:Cleaning up all Rd data RdPort:8  
[2020-04-29 01:44:01.252] RdEqpCtrl rdClientBoardBase.cc:93 INFO:RdClientBoardBase::disconnectRd RdId:7, RdPort:8  
[2020-04-29 01:44:01.256] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:661 INFO:RdEqp Fault Report RdPort:8, Fault Id 11 PoEDisconnected, RAISE  
[2020-04-29 01:44:01.256] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:1096 INFO:Begin processing fault PoEDisconnected(11) on RdPort:8  
[2020-04-29 01:44:01.256] RdEqpFaultCtrl rdInternalFaultList.cc:198 INFO:Faults blocked from processing by highest priority fault[0]  
[2020-04-29 01:44:01.256] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:1088 INFO:No more faults to process  
[2020-04-29 01:44:01.256] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:674 INFO:RdEqp Event Report RdPort:8, RD Disconnected  
[2020-04-29 01:44:01.256] rdCbcProc7 rdCbc.cc:240 INFO:Unpublish rd08/rdCbcServer  
[2020-04-29 01:44:01.260] faultManagerProc faultManager.cc:1900 INFO:ABN:Equipment fault, interface:RD\_EQP\_CTRL,method:onFaultRaise,report number:2101,fault type:RDS\_PROBLEM\_PARTIAL,fault slogan:Radio Dot System Problem Partial,fault case:2101,additional info:Disconnected:8;  
[2020-04-29 01:44:01.260] cfhe cfheFaultHandler.cc:217 INFO:ABN:Local fault, faultType:58, interface:10, faultImpact:0x0, 1r:[0 1] (faultCase:2101)  
[2020-04-29 01:44:01.284] XPP\_XCM xcm\_device.c:805 INFO:Stopping Device Driver "RDDEV", 7  
[2020-04-29 01:44:01.292] XPP\_XCM xcm\_device.c:858 INFO:Closing Device Driver "RDDEV", 7  
[2020-04-29 01:44:02.068] RdPoESrv rdPoESrv.cc:316 INFO:Number of newly detected RDs: 1  
[2020-04-29 01:44:02.068] RdPoESrv rdPoESrv.cc:317 INFO:Newly detected RdPorts: 8  
[2020-04-29 01:44:02.068] RdEqpCtrl rdEqpCtrl.cc:590 INFO:Setting RD(RdPort:8) as starting  
[2020-04-29 01:44:02.068] RdEqpFaultCtrl rdInternalFaultList.cc:259 INFO:RD Fault Cease (Cleanup); Fault PoEDisconnected(0) on RdPort:8  
[2020-04-29 01:44:02.068] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:674 INFO:RdEqp Event Report RdPort:8, RD Connected  
[2020-04-29 01:44:02.068] RdPoESrv rdPoESrv.cc:644 INFO:Power on RdPort 8  
[2020-04-29 01:44:02.072] RdEqpCtrl rdCableSrv.cc:812 INFO:Tx unmuted on RD port 8  
[2020-04-29 01:44:02.072] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:HUNT\_RD\_SERVER transactionId:84  
[2020-04-29 01:44:02.076] XPP\_XCM xcm\_device.c:550 INFO:Opening Device Driver "RDDEV", 7  
[2020-04-29 01:44:02.088] RdClient7 rdLinkConnectionManager.cc:270 INFO:Set MODEM CARRIER\_FREQ to 234 MHz for RdId:7, RdPort:8  
[2020-04-29 01:44:02.088] XPP\_XCM xcm\_device.c:637 INFO:Starting Device Driver "RDDEV", 7  
[2020-04-29 01:44:02.092] RdClient7 rdBaseMessageHandler.cc:136 INFO:HUNT\_RD\_SERVER\_SIG transaction id 84  
[2020-04-29 01:44:02.264] RdClient7 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_UTC transactionId:86  
[2020-04-29 01:44:02.356] RdClient7 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:87  
[2020-04-29 01:44:02.452] RdClient7 rdClientBoardBase.cc:165 INFO:sendMsg: type:SUBSCRIBE\_FAULTS transactionId:88  
[2020-04-29 01:44:02.540] RdClient7 rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BOARD\_CAP\_EXCHANGE transactionId:89  
[2020-04-29 01:44:02.680] RdClient7 rdBoardSrv.cc:2053 INFO:Response for RdPort:8 to get Board Capability Req:CFM\_MSG  
[2020-04-29 01:44:02.804] RdClient7 rdSwLoadingSrvBase.cc:538 INFO:Using default load module 'CXC 112 4419/5' from HW PID  
[2020-04-29 01:44:02.804] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 6, handle 1)  
[2020-04-29 01:44:02.804] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 7, handle 1)  
[2020-04-29 01:44:02.804] RdClient7 rdSwLoadingSrvBase.cc:1245 INFO:RD boardOperationalCapability.upgradableDesignDB == 1: RdPort: '8'  
[2020-04-29 01:44:02.804] RdClient7 rdSwLoadingSrvBase.cc:1825 INFO:hwPidCapability.productRevision: R1A

[2020-04-29 01:44:02.804] RdClient7 rdSwLoadingSrvBase.cc:1477 INFO:Found Match for prodNum KRY 901 390/1, prodNubRev R1A, matching dbProdNum CXC 1124505/1.

[2020-04-29 01:44:02.804] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 10, handle 1)

[2020-04-29 01:44:02.808] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 11, handle 1)

[2020-04-29 01:44:02.808] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 12, handle 1)

[2020-04-29 01:44:02.808] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 13, handle 1)

[2020-04-29 01:44:02.808] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 14, handle 1)

[2020-04-29 01:44:02.808] RdClient7 rdSwLoadingSrvBase.cc:1865 INFO:Add RD DB to loadingData

[2020-04-29 01:44:02.808] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 6, handle 1)

[2020-04-29 01:44:02.808] RdClient7 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 7, handle 1)

[2020-04-29 01:44:03.032] RdClient7 rdSwLoadingSrvBase.cc:1323 INFO:Design DB is not in expected state. (RdPort 8) restartAttempts 0

[2020-04-29 01:44:03.032] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BRANCH\_CAP transactionId:93

[2020-04-29 01:44:03.032] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BRANCH\_CAP transactionId:94

[2020-04-29 01:44:03.244] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:55 INFO:,noCap=11,branchId=A

[2020-04-29 01:44:03.244] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:222 INFO:capId=1(RDCI\_CAP\_BRANCH\_BAND\_INFO),duplexMode=0(RDCI\_DUPLEX\_MODE\_FDD),band=BandIII

[2020-04-29 01:44:03.244] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:234

INFO:capId=2(RDCI\_CAP\_BRANCH\_TX\_FREQUENCY)RfMin=18050000,RfMax=18800000,IfMin=1100000,IfMax=1500000,InvSpectrum=0,StepSize=10,RfTuneMin=18050000,RfTuneMax=18800000,RfTuneCoupled=3,Ibw=400000

[2020-04-29 01:44:03.244] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:256

INFO:capId=3(RDCI\_CAP\_BRANCH\_RX\_FREQUENCY)RfMin=17100000,RfMax=17850000,IfMin=400000,IfMax=800000,InvSpectrum=0,StepSize=10,RfTuneMin=17100000,RfTuneMax=17850000,RfTuneCoupled=3,Ibw=400000

[2020-04-29 01:44:03.244] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:278

INFO:capId=4(RDCI\_CAP\_BRANCH\_CABLE\_LOSS\_COMP),fskModemOutputPower=-1561,minILThreshold=240,maxILThreshold=4590,catFrequencySelect=1300000

[2020-04-29 01:44:03.244] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:293 INFO:capId=5(RDCI\_CAP\_BRANCH\_RX\_GAIN),nominalGain=3650,noiseFigure=0

[2020-04-29 01:44:03.244] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:306 INFO:capId=6(RDCI\_CAP\_BRANCH\_TX\_POWER),txPar=750,txPowerClassUsage=1700

[2020-04-29 01:44:03.244] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:320 INFO:capId=7(RDCI\_CAP\_BRANCH\_TX\_GAIN\_ADJUST),txGainAdjustHi=0,txGainAdjustLo=-1000

[2020-04-29 01:44:03.244] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:333 INFO:capId=8(RDCI\_CAP\_BRANCH\_RX\_AGC),rxAgcMode=0,rxAgcDefault=0

[2020-04-29 01:44:03.244] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:352 INFO:capId=9(RDCI\_CAP\_BRANCH\_TX\_POWER\_MEAS),txPowerMeasMode=2,txMaxPowerBackoff=-10000

[2020-04-29 01:44:03.244] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:366 INFO:capId=10(RDCI\_CAP\_BRANCH\_CARRIER\_DATA),carrierDataRequired=1,txLoMode=IBW

[2020-04-29 01:44:03.244] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:387 INFO:capId=11(RDCI\_CAP\_BRANCH\_WCDMA\_DESENSE),desenseGainRebalance=24 dB

[2020-04-29 01:44:03.580] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:55 INFO:,noCap=11,branchId=B

[2020-04-29 01:44:03.580] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:222 INFO:capId=1(RDCI\_CAP\_BRANCH\_BAND\_INFO),duplexMode=0(RDCI\_DUPLEX\_MODE\_FDD),band=BandIII

[2020-04-29 01:44:03.580] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:234

INFO:capId=2(RDCI\_CAP\_BRANCH\_TX\_FREQUENCY)RfMin=18050000,RfMax=18800000,IfMin=1100000,IfMax=1500000,InvSpectrum=0,StepSize=10,RfTuneMin=18050000,RfTuneMax=18800000,RfTuneCoupled=3,Ibw=400000

[2020-04-29 01:44:03.580] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:256

INFO:capId=3(RDCI\_CAP\_BRANCH\_RX\_FREQUENCY)RfMin=17100000,RfMax=17850000,IfMin=400000,IfMax=800000,InvSpectrum=0,StepSize=10,RfTuneMin=17100000,RfTuneMax=17850000,RfTuneCoupled=3,Ibw=400000

[2020-04-29 01:44:03.580] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:278

INFO:capId=4(RDCI\_CAP\_BRANCH\_CABLE\_LOSS\_COMP),fskModemOutputPower=-1752,minILThreshold=240,maxILThreshold=4590,catFrequencySelect=1300000

[2020-04-29 01:44:03.580] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:293 INFO:capId=5(RDCI\_CAP\_BRANCH\_RX\_GAIN),nominalGain=3650,noiseFigure=0

[2020-04-29 01:44:03.580] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:306 INFO:capId=6(RDCI\_CAP\_BRANCH\_TX\_POWER),txPar=750,txPowerClassUsage=1700

[2020-04-29 01:44:03.580] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:320 INFO:capId=7(RDCI\_CAP\_BRANCH\_TX\_GAIN\_ADJUST),txGainAdjustHi=0,txGainAdjustLo=-1000

[2020-04-29 01:44:03.580] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:333 INFO:capId=8(RDCI\_CAP\_BRANCH\_RX\_AGC),rxAgcMode=0,rxAgcDefault=0

[2020-04-29 01:44:03.580] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:352 INFO:capId=9(RDCI\_CAP\_BRANCH\_TX\_POWER\_MEAS),txPowerMeasMode=2,txMaxPowerBackoff=-10000

[2020-04-29 01:44:03.580] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:366 INFO:capId=10(RDCI\_CAP\_BRANCH\_CARRIER\_DATA),carrierDataRequired=1,txLoMode=IBW

[2020-04-29 01:44:03.580] RdClient7 rdBranchCapabilityCfmMessageHandler.cc:387 INFO:capId=11(RDCI\_CAP\_BRANCH\_WCDMA\_DESENSE),desenseGainRebalance=24 dB

[2020-04-29 01:44:03.584] RdClient7 rdBoardSrv.cc:1807 INFO:send SetTxIfMaxPowerReq with RdPort=8, Br=0, maxPower=-22

[2020-04-29 01:44:03.584] RdClient7 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_TX\_IF\_MAX\_PWR transactionId:95

[2020-04-29 01:44:03.584] RdClient7 rdBoardSrv.cc:1807 INFO:send SetTxIfMaxPowerReq with RdPort=8, Br=1, maxPower=-2

[2020-04-29 01:44:03.584] RdClient7 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_TX\_IF\_MAX\_PWR transactionId:96

[2020-04-29 01:44:03.712] RdClient7 rdBoardSrv.cc:1832 INFO:Response for RdPort:8 to set TxIfMaxPwrDone:CFM\_MSG

[2020-04-29 01:44:03.824] RdClient7 rdBoardSrv.cc:1832 INFO:Response for RdPort:8 to set TxIfMaxPwrDone:CFM\_MSG

[2020-04-29 01:44:03.824] RdClient7 rdBoardSrv.cc:1734 INFO:notifyStartRdDone: 7

[2020-04-29 01:44:03.824] RdEqpCtrl rdEqpCtrl.cc:399 INFO:StartRdDone with RdPort:8

[2020-04-29 01:44:03.824] RdEqpCtrl rdCableSrv.cc:495 INFO:Starting Pair Swap Test with RD PORT list: { 8 }

[2020-04-29 01:44:03.948] RdEqpCtrl rdEqpCtrl.cc:963 INFO:pairSwap test done.

[2020-04-29 01:44:03.948] RdEqpCtrl rdCableMeasSvSrv.cc:103 INFO:Starting cable IL measurement with RD PORT list: { 8 }

[2020-04-29 01:44:04.996] RdCableMeasSvSrv rdClientCableMeasurements.cc:213 INFO:A(0mb), B(5482mb), C(226mb) Coefficient was sent to RdPort(8) for branchId(0)

[2020-04-29 01:44:04.996] RdCableMeasSvSrv rdCableILMeasSv.cc:727 INFO:Stored Rx-IL(2833mb) and Tx-IL(4211mb) for RdPort(8) and branchId(0)

[2020-04-29 01:44:05.152] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received CFM\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(8) and Branch(A)

[2020-04-29 01:44:05.204] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received IND\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(8) and Branch(A)

[2020-04-29 01:44:06.224] RdCableMeasSvSrv rdClientCableMeasurements.cc:213 INFO:A(0mb), B(5291mb), C(218mb) Coefficient was sent to RdPort(8) for branchId(1)

[2020-04-29 01:44:06.224] RdCableMeasSvSrv rdCableILMeasSv.cc:727 INFO:Stored Rx-IL(2735mb) and Tx-IL(4064mb) for RdPort(8) and branchId(1)

[2020-04-29 01:44:06.224] RdEqpCtrl rdEqpCtrl.cc:839 INFO:Cable IL Measurement done

[2020-04-29 01:44:06.224] RdEqpCtrl rdCableSrv.cc:680 INFO:Equalizer for RD port 8 set to ON

[2020-04-29 01:44:06.224] RdEqpCtrl rdCableSrv.cc:887 INFO:Rx unmuted on RD port 8

[2020-04-29 01:44:06.224] RdEqpCtrl rdEqpCtrl.cc:860 INFO:Starting AGC test

[2020-04-29 01:44:06.224] RdEqpCtrl rdEqpCtrl.cc:922 INFO:AGC test done

[2020-04-29 01:44:06.224] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:120

[2020-04-29 01:44:06.224] RdEqpFaultCtrl halEventHandler.cc:543 INFO:There is no /groupTempSensorSv in database, use default value 0

[2020-04-29 01:44:06.228] RdEqpFaultCtrl halEventHandler.cc:543 INFO:There is no /groupTempSensorSv in database, use default value 0

[2020-04-29 01:44:06.228] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:2260 INFO:RdEqp Event Report RdPort:8, RD Unlocked

[2020-04-29 01:44:06.228] RdEqpCtrl rdEqpCtrl.cc:1240 INFO:Processing Set Led Action for RdPort:8; LED type is 0

[2020-04-29 01:44:06.228] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:121

[2020-04-29 01:44:06.228] RdEqpFaultCtrl rdActionListUtil.cc:58 INFO:RdEqpEvent:RD Unlocked/RD Locked, RdPort=8 Set LED Action successful;

[2020-04-29 01:44:06.228] trProc trCdc.cc:4799 INFO:INTERNAL RESTART ALL ROT MEAS REQ.

[2020-04-29 01:44:06.228] rdCbcProc7 ccieInterface.cc:113 INFO:SAR:Published interface: rd08/rdCbcServer(0x12000fd) and RDCBCI7(highestProtocolRev:257),dispatchPid: 0x1000db

[2020-04-29 01:44:06.228] rdBcProc7 ccieLteInterface.cc:108 INFO:SAR:Published interface: rd08/BcServer(0x20000f8) and RDBCI7(highestProtocolRev:3(0x3),proto\_basic:0,proto\_spec:3),dispatchPid: 0x1000d9

[2020-04-29 01:44:06.228] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:2260 INFO:RdEqp Event Report RdPort:8, RD Unlocked

[2020-04-29 01:44:06.228] RdEqpCtrl rdEqpCtrl.cc:1240 INFO:Processing Set Led Action for RdPort:8; LED type is 0

[2020-04-29 01:44:06.232] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:122

[2020-04-29 01:44:06.232] RdEqpFaultCtrl rdActionListUtil.cc:58 INFO:RdEqpEvent:RD Unlocked/RD Locked, RdPort=8 Set LED Action successful;

[2020-04-29 01:44:06.232] faultManagerProc faultManager.cc:2468 INFO:ABN:Equipment fault cease,interface:RD\_EQP\_CTRL,method:onFaultCease,report number:2101,additional info:Radio Dot System Problem Partial

[2020-04-29 01:44:06.232] faultManagerProc faultManager.cc:795 INFO:Fault 2102 not found in the fault table

[2020-04-29 01:44:06.348] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received CFM\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(8) and Branch(B)

[2020-04-29 01:44:06.404] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received IND\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(8) and Branch(B)

[2020-04-29 01:44:08.996] RdPoESrv rdPoESrv.cc:709 INFO:Power off RdPort 8

[2020-04-29 01:44:09.004] RdPoESrv rdPoESrv.cc:430 INFO:RdPort 8: disconnected

[2020-04-29 01:44:09.004] RdEqpCtrl rdEqpCtrl.cc:605 INFO:Processing PoE disconnect for RdPort:8

[2020-04-29 01:44:09.004] RdEqpCtrl rdCableSrv.cc:812 INFO:Tx muted on RD port 8

[2020-04-29 01:44:09.008] RdEqpCtrl rdCableSrv.cc:887 INFO:Rx muted on RD port 8

[2020-04-29 01:44:09.008] RdEqpCtrl rdCableSrv.cc:680 INFO:Equalizer for RD port 8 set to TERMINATED

[2020-04-29 01:44:09.008] RdEqpCtrl rdEqpCtrl.cc:664 INFO:Cleaning up all Rd data RdPort:8

[2020-04-29 01:44:09.008] RdEqpCtrl rdClientBoardBase.cc:93 INFO:RdClientBoardBase::disconnectRd RdId:7, RdPort:8

[2020-04-29 01:44:09.008] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:661 INFO:RdEqp Fault Report RdPort:8, Fault Id 11 PoEDisconnected, RAISE

[2020-04-29 01:44:09.008] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:1096 INFO:Begin processing fault PoEDisconnected(11) on RdPort:8

[2020-04-29 01:44:09.008] RdEqpFaultCtrl rdInternalFaultList.cc:198 INFO:Faults blocked from processing by highest priority fault[0]

[2020-04-29 01:44:09.008] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:1088 INFO:No more faults to process

[2020-04-29 01:44:09.008] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:674 INFO:RdEqp Event Report RdPort:8, RD Disconnected

[2020-04-29 01:44:09.008] rdCbcProc7 rdCbc.cc:240 INFO:Unpublish rd08/rdCbcServer

[2020-04-29 01:44:09.012] faultManagerProc faultManager.cc:1900 INFO:ABN:Equipment fault,interface:RD\_EQP\_CTRL,method:onFaultRaise,report number:2101,fault type:RDS\_PROBLEM\_PARTIAL,fault slogan:Radio Dot System Problem Partial,fault case:2101,additional info:Disconnected:8;

[2020-04-29 01:44:09.012] cfhe cfheFaultHandler.cc:217 INFO:ABN:Local fault, faultType:58, interface:10, faultImpact:0x0, lr:[0 1] (faultCase:2101)

[2020-04-29 01:44:09.056] XPP\_XCM xcm\_device.c:805 INFO:Stopping Device Driver "RDDEV", 7

[2020-04-29 01:44:09.064] XPP\_XCM xcm\_device.c:858 INFO:Closing Device Driver "RDDEV", 7

[2020-04-29 01:44:09.580] xpaiSubscriber xpaiSubscriber.cc:133 INFO:Shutting down PA due to board restart

[2020-04-29 01:44:09.580] xpaiSubscriber txChangeCycleBasicHelper.cc:867 INFO:PA shutdown request for branchId 0, blockId 10

[2020-04-29 01:44:09.580] xpaiSubscriber paSrv.cc:622 INFO:paControl Off for PaSrvA for branchId 0, blockId 10: from HAL\_shutdownPA

[2020-04-29 01:44:09.580] xpaiSubscriber rdClientTxRxBranch.cc:170 INFO:No branch enable or disable request sent to RDS

[2020-04-29 01:44:09.580] xpaiSubscriber paSrvIru.cc:151 INFO:PA\_OFF: BranchId 0 SET TO STATUS OFF

[2020-04-29 01:44:09.580] xpaiSubscriber txChangeCycleBasicHelper.cc:867 INFO:PA shutdown request for branchId 1, blockId 10

[2020-04-29 01:44:09.580] xpaiSubscriber paSrv.cc:622 INFO:paControl Off for PaSrvB for branchId 1, blockId 10: from HAL\_shutdownPA

[2020-04-29 01:44:09.580] xpaiSubscriber rdClientTxRxBranch.cc:170 INFO:No branch enable or disable request sent to RDS

[2020-04-29 01:44:09.580] xpaiSubscriber paSrvIru.cc:151 INFO:PA\_OFF: BranchId 1 SET TO STATUS OFF

[2020-04-29 01:44:09.580] XPP\_XMH xmh.c:3609 INFO:Tag XLL\_Restart received. Prevent write or erase of board parameters and user flash.

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 8

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 9

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 10

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 11

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 12

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 13

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 14

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 15

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 0

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 1

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 2

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 3

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 4

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 5

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 6

[2020-04-29 01:44:09.584] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 7

[2020-04-29 01:44:09.584] RdPoESrv rdPoESrv.cc:709 INFO:Power off RdPort 1

[1970-01-01 00:00:00.056] - xpai\_xos.c:287 INFO:XPP (PID=CXC1321797/3\_R40AE), is RUNNING

[1970-01-01 00:00:00.056] - xpai\_xos.c:289 INFO:The XPP with XPAI REVISION: CYB10190-R7G

[1970-01-01 00:00:00.056] - xos.c:3634 INFO:WARP3.5 Flash=FLASH\_SPANSION\_S29GL\_S 64Mb RAM=128Mb HW-id=CXC10115112 HW-rev=R1A000000 OSE Delta PowerPC/BL910356

[1970-01-01 00:00:00.056] - xos.c:3641 INFO:XPP STARTED

[1970-01-01 00:00:00.056] - xos.c:3645 INFO:SYS\_LM\_PID: CXC1321797/3\_R40AE

[1970-01-01 00:00:00.056] - xos.c:3649 INFO:SYS\_LF\_PID: CXP9013268%14\_R78KJ

[1970-01-01 00:00:00.056] - xos.c:3653 INFO:SYS\_RESTART\_CAUSE: ORDERED

[1970-01-01 00:00:00.056] - xos.c:3658 INFO:IBOOT startRestartCause: IBOOT\_SW\_RESET

[1970-01-01 00:00:00.056] - xos.c:3694 INFO:IBOOT PID: CXC1321302/3-R5D

[1970-01-01 00:00:00.056] - xos.c:3695 INFO:XPL PID: CXC1321812/1-R6A

[1970-01-01 00:00:00.056] - xos.c:1855 INFO:SYS\_HW\_PID: KRC 161 444/1

[1970-01-01 00:00:00.056] - xos.c:1855 INFO:SYS\_HW\_REV: R2B

[1970-01-01 00:00:00.056] - xos.c:1855 INFO:SYS\_HW\_NAME: IRU 2242

[1970-01-01 00:00:00.056] - xos.c:1855 INFO:SYS\_HW\_DATE: 20160115

[1970-01-01 00:00:00.056] - xos.c:1855 INFO:SYS\_HW\_SERIAL: D822742997

[1970-01-01 00:00:00.056] - xmh\_flash.c:706 INFO:XMH\_InitFlashDevice: Default board parameter copied to backup

```
[1970-01-01 00:00:00.056] - xdai_xdos.c:155 INFO:The XPP with XDAI REVISION: CYB10191-R4A
[1970-01-01 00:00:00.056] a4ci_startup /repo/ncixp.build/nci/BCP_CNH1606396/xp_bl/xpp_bl/ecb_swu/src/mhp_device.c:663 INFO:1 ports found on 1 primary stations.
[1970-01-01 00:00:00.056] MHP_Device /repo/ncixp.build/nci/BCP_CNH1606396/xp_bl/xpp_bl/ecb_swu/src/mhp_device.c:663 INFO:1 ports found on 1 primary stations.
[1970-01-01 00:00:00.056] MHP_Device /repo/ncixp.build/nci/BCP_CNH1606396/xp_bl/xpp_bl/ecb_swu/src/mhp_device.c:883 INFO:Starting Device Driver "UART750", 1
[1970-01-01 00:00:00.056] MHP_Device /repo/ncixp.build/nci/BCP_CNH1606396/xp_bl/xpp_bl/ecb_swu/src/mhp_device.c:1974 INFO:Initiate MHP Link Status information.
[1970-01-01 00:00:00.056] XPP_XHP_ARM_LM xhp_arm_dev.c:427 INFO:Opening Device Driver "XHP_ARM_XDD_ECP", unit 0
[1970-01-01 00:00:00.056] XPP_XHP_ARM_LM xhp_arm_dev.c:427 INFO:Opening Device Driver "XHP_ARM_XDD_ECP", unit 5
[1970-01-01 00:00:00.056] XPP_XHP_0_0 xhp_arm_dev.c:511 INFO:Starting Device Driver "XHP_ARM_XDD_ECP", unit 0
[1970-01-01 00:00:00.056] XPP_XHP_1_0 xhp_arm_dev.c:511 INFO:Starting Device Driver "XHP_ARM_XDD_ECP", unit 5
[1970-01-01 00:00:00.056] XDP_XDMMI xdmmi.c:1390 INFO:Maintenance button found of type MAIN2.
[1970-01-01 00:00:00.064] main_xos.c:2195 INFO:Application IRU with PID CXC1123669%4R78KJ is started in SUPERVISORY mode
[1970-01-01 00:00:00.064] XPP_XCBC xcbbc.c:4604 INFO:User application started. No XP CBCI-AU server XcbcServer started.
[1970-01-01 00:00:00.156] - xpai_xos.c:287 INFO:IRU (PID=CXC1123669%4R78KJ), is RUNNING
[1970-01-01 00:00:00.156] - xpai_xos.c:289 INFO:The IRU with XPAI REVISION: CYB10190-R7G
[1970-01-01 00:00:00.156] - xdai_xdos.c:155 INFO:The IRU with XDAI REVISION: CYB10191-R4A
[1970-01-01 00:00:00.160] cfhe cfheProc.cc:57 INFO:SAR:CFHE started
[1970-01-01 00:00:00.176] startUp delayHandler.cc:337 INFO:initDelayRunner: DelayRtcBusyWait
[1970-01-01 00:00:00.244] startUp dataBaseLoadSave.cc:679 INFO:HW Data Base loaded.
[1970-01-01 00:00:01.020] XPP_HDR_clk_hdr_clk.c:281 INFO:Estimated clock frequency: 367 MHz
[1970-01-01 00:00:01.852] startUp txEnumsHelper.cc:192 INFO:TxBranchId: Initializing from database.
[1970-01-01 00:00:01.856] startUp commonTypes.cc:723 INFO:BranchId, initFromDatabase!
[1970-01-01 00:00:01.856] startUp txModule.cc:69 INFO:There is no /radioWithMassiveAntennas in database, use default value 0
[1970-01-01 00:00:01.864] maintStateHandler maintStateHandlerProc.cc:43 INFO:There is no /publishTrBci in database, use default value 0
[1970-01-01 00:00:01.880] startUp dataPortDelayMgr.cc:115 INFO:The number of CPRI links 2
[1970-01-01 00:00:02.488] startUp ltu983.cc:248 INFO:Programming LTU as free run
[1970-01-01 00:00:02.580] startUp fpga.cc:101 INFO:key = /trxFpga/hwPID not found
[1970-01-01 00:00:04.176] startUp fpga.cc:171 INFO:FPGA Application (CXC 173 7859/1 R3J01 20190123) is loaded and started.
[1970-01-01 00:00:04.184] startUp deviceIntProcHelper.cc:56 INFO:Added device fpga with trap reg 0x4101 and mask reg 0x4102
[1970-01-01 00:00:04.188] startUp deviceIntProcHelper.cc:462 INFO:Added callback for interrupt bitNo=30
[1970-01-01 00:00:04.188] startUp deviceIntProcHelper.cc:462 INFO:Added callback for interrupt bitNo=28
[1970-01-01 00:00:04.188] startUp deviceIntProcHelper.cc:462 INFO:Added callback for interrupt bitNo=29
[1970-01-01 00:00:04.296] startUp ltuiServer.cc:576 INFO:Create an instance of LtuiServer.
[1970-01-01 00:00:04.316] startUp linkCtrlCpriWarp30.cc:154 INFO:Delaying for 400 ms before starting RICR
[1970-01-01 00:00:04.720] startUp ricrai.c:4406 INFO:HRICR not found!
[1970-01-01 00:00:04.720] HRICR hrirc_config.c:2752 INFO:IRU 2242 detected. Modifying gtx configuration.
[1970-01-01 00:00:04.720] HRICR hrirc_config.c:4990 INFO:HRICR Configuration:device type: WARP35; number of logical ports: 2; number of physical ports: 4; min index slave: 1, max index slave: 2, min index master: 1, max index master: 2, preferred index: -; time allowed for FPGA startup: 0 ms; speed setup method: Non-Xilinx; rbs SFP MMI type: RBS6000_MMI; fpga release number (for alcor): 0; port_based_addition_ecp_config: 2.
[1970-01-01 00:00:04.720] HRICR hrirc_config.c:5006 INFO:HRICR Configuration:cpri_cfgtx_invpair: 0x00000000; cpri_cfgtx_adj_mask: 0xfffffc00; cpri_cfgtx_adj_bits[0]: 0x0c00329b; cpri_cfgtx_adj_bits[1]: 0x0c80329b; cpri_cfgtx_adj_bits[2]: 0x00000000; cpri_cfgtx_adj_bits[3]: 0x00000000; cpri_cfgtx_adj_mask: 0x00000000.
[1970-01-01 00:00:04.720] HRICR hrirc_config.c:5048 INFO:Port configuration for port 0:port type SFP; bus type I2C; parent -1; children 0x00000004; posterity 0x00000004; root_parent 0; master_warp 0; master_on 0; int_vector 0; port_mapping 1; device_base_addr 0xa0000000; port_base_addr 0x00000000; serdes_base_addr 0x00000000; led_base_addr 0x00000000; jb_delay_factor 0; i2c_port 3; i2c_addr 0x51.
[1970-01-01 00:00:04.720] HRICR hrirc_config.c:5081 INFO:Port configuration for port 0:power_enable_conf.port: 2; power_enable_conf.pin: 12; power_enable_conf.direction: 0; cfgtx[0]0x00000000; cfgtx[1]0x00000000; cfgtx[2]0x00000000; cfgtx[3]0x00000000; cfrgx[0]0x00000000; cfrgx[1]0x00000000; cfrgx[2]0x00000000; cfrgx[3]0x00000000; ecp_config[0]0x0f4002d4; ecp_config[1]0x00000000; ecp_config[2]0x00000000; local_cpri_mode:Ericsson Mode.
[1970-01-01 00:00:04.720] HRICR hrirc_config.c:5048 INFO:Port configuration for port 1:port type SFP; bus type I2C; parent -1; children 0x00000008; posterity 0x00000008; root_parent 1; master_warp 0; master_on 0; int_vector 0; port_mapping 0; device_base_addr 0xa0000000; port_base_addr 0x00000000; serdes_base_addr 0x00000000; led_base_addr 0x00000000; jb_delay_factor 0; i2c_port 2; i2c_addr 0x51.
[1970-01-01 00:00:04.720] HRICR hrirc_config.c:5081 INFO:Port configuration for port 1:power_enable_conf.port: 2; power_enable_conf.pin: 10; power_enable_conf.direction: 0; cfgtx[0]0x00000000; cfgtx[1]0x00000000; cfrgx[2]0x00000000; cfrgx[3]0x00000000; cfrgx[0]0x00000000; cfrgx[1]0x00000000; cfrgx[2]0x00000000; cfrgx[3]0x00000000; ecp_config[0]0x0f4002e4; ecp_config[1]0x00000000; ecp_config[2]0x00000000; local_cpri_mode:Ericsson Mode.
[1970-01-01 00:00:04.720] HRICR hrirc_config.c:5048 INFO:Port configuration for port 2:port type WARP35; bus type NA; parent 0; children 0x00000000; posterity 0x00000000; root_parent 0; master_warp 1; master_on 0; int_vector 16; port_mapping 1; device_base_addr 0xa0000000; port_base_addr 0xf400140; serdes_base_addr 0x00001878; led_base_addr 0x00000590; jb_delay_factor 12500; i2c_port 0; i2c_addr 0x00.
[1970-01-01 00:00:04.720] HRICR hrirc_config.c:5081 INFO:Port configuration for port 2:power_enable_conf.port: -1; power_enable_conf.pin: -1; power_enable_conf.direction: -1; cfgtx[0]0x0c00329b; cfrgx[1]0x0c00329b; cfgtx[2]0x0c00329b; cfgtx[3]0x0c00329b; cfrgx[0]0x00000700; cfrgx[1]0x00000700; cfrgx[2]0x00000700; cfrgx[3]0x00000700; ecp_config[0]0x0f4002d4; ecp_config[1]0x0f4002d8; ecp_config[2]0x0f4002dc; local_cpri_mode:Ericsson Mode.
[1970-01-01 00:00:04.720] HRICR hrirc_config.c:5048 INFO:Port configuration for port 3:port type WARP35; bus type NA; parent 1; children 0x00000000; posterity 0x00000000; root_parent 1; master_warp 1; master_on 0; int_vector 15; port_mapping 0; device_base_addr 0xa0000000; port_base_addr 0xf400028; serdes_base_addr 0x00001850; led_base_addr 0x0000058c; jb_delay_factor 12500; i2c_port 0; i2c_addr 0x00.
[1970-01-01 00:00:04.720] HRICR hrirc_config.c:5081 INFO:Port configuration for port 3:power_enable_conf.port: -1; power_enable_conf.pin: -1; power_enable_conf.direction: -1; cfgtx[0]0x0c80329b; cfrgx[1]0x0c80329b; cfgtx[2]0x0c80329b; cfrgx[3]0x0c80329b; cfrgx[0]0x00000700; cfrgx[1]0x00000700; cfrgx[2]0x00000700; cfrgx[3]0x00000700; ecp_config[0]0x0f4002e4; ecp_config[1]0x0f4002e8; ecp_config[2]0x0f4002ec; local_cpri_mode:Ericsson Mode.
[1970-01-01 00:00:05.408] HRICR hrirc.c:8986 INFO:Process HRICR_hw_monitor found.
[1970-01-01 00:00:05.412] startUp hrircrai.c:644 INFO:HRICR CYB10173/9 R13HA is started, processName HRICR
[1970-01-01 00:00:05.412] HRICR hrirc.c:2514 INFO:HRICR conn_state change: RIHI_NOT_CONNECTED->RIHI_CONNECTED
[1970-01-01 00:00:05.412] RICR ricr_config.c:183 INFO:RICR Configuration:no of ports: 2; speed: min index slave: 1, max index slave: 2, min index master: 1 max index master: 2 preferred index: -; Running in application mode
[1970-01-01 00:00:05.412] RICR_fault_handler ricr_common.c:519 INFO:PROCESS RICR_fault_handler started.
[1970-01-01 00:00:05.512] HRICR hrirc.c:5165 INFO:Wrote SFP info for link 0 to HW log
[1970-01-01 00:00:05.512] HRICR hrirc.c:5165 INFO:Wrote SFP info for link 1 to HW log
[1970-01-01 00:00:05.512] RICR_sup_link_0 slave.c:848 INFO:slave_init: link supervisor for link 0 started
[1970-01-01 00:00:05.516] RICR_sup_link_1 slave.c:848 INFO:slave_init: link supervisor for link 1 started
[1970-01-01 00:00:05.520] startUp ricrai.c:4473 INFO:RICR PID:CYB10173/11-R14HA is started, processName RICR
[1970-01-01 00:00:05.520] startUp ricrai.c:627 INFO:added internal ricr subscriber, type 0
[1970-01-01 00:00:05.520] cpriCtrlProc logManager.cc:42 INFO:Receive RICR link status ind:
linkPort: 0x00
hfnSync: 0x00
linkOperational: 0x00
syncBit: 0x00
tAdvance: 0x00000000
refClkPortNo 0 (linkCtrlCpriWarp30.cc:420)
[1970-01-01 00:00:05.520] cpriCtrlProc logManager.cc:42 INFO: No HFNSYNC either (linkCtrlCpriWarp30.cc:447)
[1970-01-01 00:00:05.520] cpriCtrlProc linkCtrlCpriWarp30.cc:508 INFO:m_ricrCpriDetected=0 ltu_locked_on_link=-1 cpriPort[0].linkOperational=0 cpriPort[1].linkOperational=0

[1970-01-01 00:00:05.520] startUp ricrai.c:635 INFO:added internal ricr subscriber, type 5
[1970-01-01 00:00:05.520] cpriCtrlProc logManager.cc:42 INFO:Receive RICR link status ind:
linkPort: 0x01
hfnSync: 0x00
linkOperational: 0x00
syncBit: 0x00
tAdvance: 0x00000000
refClkPortNo 0 (linkCtrlCpriWarp30.cc:420)
[1970-01-01 00:00:05.520] cpriCtrlProc logManager.cc:42 INFO: No HFNSYNC either (linkCtrlCpriWarp30.cc:447)
[1970-01-01 00:00:05.520] cpriCtrlProc linkCtrlCpriWarp30.cc:508 INFO:m_ricrCpriDetected=0 ltu_locked_on_link=-1 cpriPort[1].linkOperational=0 cpriPort[0].linkOperational=0

[1970-01-01 00:00:05.524] cpriCtrlProc linkCtrlCpriBase.cc:118 INFO:Receive RICR link Cascaded ind: cascaded = 0
[1970-01-01 00:00:05.896] startUp channelIf.cc:418 INFO:There is no /radioWithMassiveAntennas in database, use default value 0
[1970-01-01 00:00:09.632] cpriCtrlProc logManager.cc:42 INFO:Receive RICR link status ind:
linkPort: 0x00
hfnSync: 0x01
linkOperational: 0x00
syncBit: 0x01
tAdvance: 0x00000000
refClkPortNo 0 (linkCtrlCpriWarp30.cc:420)
[1970-01-01 00:00:09.632] cpriCtrlProc linkCtrlCpriWarp30.cc:508 INFO:m_ricrCpriDetected=1 ltu_locked_on_link=-1 cpriPort[0].linkOperational=0 cpriPort[1].linkOperational=0

[1970-01-01 00:00:09.632] ltuiServer0 ltu983.cc:279 INFO:Programming LTU to lock
[1970-01-01 00:00:09.632] RICR ltui_if.c:320 INFO:server_status = LTUI_LOCKING
[1970-01-01 00:00:09.632] cpriCtrlProc logManager.cc:42 INFO:Receive RICR link status ind:
linkPort: 0x01
hfnSync: 0x01
linkOperational: 0x00
syncBit: 0x01
tAdvance: 0x00000000
refClkPortNo 0 (linkCtrlCpriWarp30.cc:420)
[1970-01-01 00:00:09.632] cpriCtrlProc linkCtrlCpriWarp30.cc:508 INFO:m_ricrCpriDetected=1 ltu_locked_on_link=-1 cpriPort[1].linkOperational=0 cpriPort[0].linkOperational=0

[1970-01-01 00:00:09.636] ltuiServer0 ltuiServer.cc:418 INFO:LtuState:FREE_RUN->LOCK_IN_PROGRESS
[1970-01-01 00:00:09.636] ltuiServer0 ltuiServer.cc:373 INFO:Lock notification timer started (50 ms)
[1970-01-01 00:00:09.692] ltuiServer0 ltuiServer.cc:253 INFO:LtuState:LOCK_IN_PROGRESS->LOCKED
[1970-01-01 00:00:09.692] RICR ltui_if.c:398 INFO:server_status = LTUI_LOCKED
[1970-01-01 00:00:09.692] ltuiServer0 ltuiServerBase.cc:233 INFO:Ltu lock event notified
[1970-01-01 00:00:09.756] RICR_sup_link_0 slave.c:2272 INFO:slave_main_loop_code: Link 0 up at 2.5 Gbps (SFP, CPRI rev 3)
[1970-01-01 00:00:09.756] RICR_sup_link_1 slave.c:2272 INFO:slave_main_loop_code: Link 1 up at 2.5 Gbps (SFP, CPRI rev 3)
[1970-01-01 00:00:09.756] cpriCtrlProc logManager.cc:42 INFO:Receive RICR link status ind:
linkPort: 0x00
hfnSync: 0x01
linkOperational: 0x01
syncBit: 0x01
tAdvance: 0x00000027
refClkPortNo 0 (linkCtrlCpriWarp30.cc:420)
[1970-01-01 00:00:09.756] cpriCtrlProc halEventHandler.c:543 INFO:There is no /groupTempSensorSv in database, use default value 0
[1970-01-01 00:00:09.756] cpriCtrlProc linkCtrlCpriWarp30.cc:508 INFO:m_ricrCpriDetected=1 ltu_locked_on_link=0 cpriPort[0].linkOperational=1 cpriPort[1].linkOperational=0

[1970-01-01 00:00:09.756] cpriCtrlProc dataPortDelayMgr.cc:359 INFO:setDataPortStateParam, mPreviouslinkState=(0)->linkStatus=(1), tAdv=(39), refClock=(0), portNo=(0), syncBit=(1), smgDiffVec[0]=(0), smgDiffVec[1]=(0), mDllLinkDelayComp=(0), mUllLinkDelayComp=(0)
[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:setTAdvanceUpdate port[0].tAdvanceUpdate:39 (dataPortDelayHandler.cc:298)
[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:Setting data port parameter port[0].tAdvanceDiff:-6 (dataPortDelayHandler.cc:261)
[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:Setting tAdvancedDiff[0] = (-6) (dataPortDelayMgr.cc:903)
[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:Receive RICR link status ind:
linkPort: 0x01
hfnSync: 0x01
linkOperational: 0x01
syncBit: 0x01
tAdvance: 0x00000027
refClkPortNo 0 (linkCtrlCpriWarp30.cc:420)
```



[1970-01-01 00:00:09.760] cpriCtrlProc linkCtrlCpriWarp30.cc:508 INFO:m\_ricrCpriDetected=1 ltu\_locked\_on\_link=0 cpriPort[1].linkOperational=1 cpriPort[0].linkOperational=1

[1970-01-01 00:00:09.760] cpriCtrlProc dataPortDelayMgr.cc:359 INFO:setDataPortStateParam, mPreviouslinkState=(0)->linkStatus=(1), tAdv=(39), refClock=(0), portNo=(1), syncBit=(1), smgDiffVec[0]=(0), smgDiffVec[1]=(0), mDllLinkDelayComp=(0), mUllLinkDelayComp=(0)

[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:setTAdvanceUpdate port[1].tAdvanceUpdate:39 (dataPortDelayHandler.cc:298)

[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:Setting data port parameter port[1].tAdvanceDiff:-6 (dataPortDelayHandler.cc:261)

[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:Setting tAdvanceDiff[1] = (-6) (dataPortDelayMgr.cc:903)

[1970-01-01 00:00:09.788] cpriCtrlProc dataPortDelayMgr.cc:985 INFO:updateSmgOffset: Reference clock was on port(0), cyclesPerFrame=(4915200), cpriORfsDel=(8), cpriIRfsDel=(8), cpriRfsDiff2Bfn0=(2073), cpriRfsDiff2Bfn1=(2073), cpriRfsDiff=(4915199), smgDiffVec[0]=(-307200), smgDiffVec[1]=(307200)

[1970-01-01 00:00:09.788] cpriCtrlProc dataPortDelayMgr.cc:1047 INFO:readRfsDiff: cyclesPerFrame=4915200, cpriRfsDiff=4915199, cpriSwapped=1, value=0 BFN0=2073 BFN1=2073

[1970-01-01 00:00:09.836] cpriCtrlProc linkCtrlCpriWarp35.cc:132 INFO:warp35Delay:5385 [0.1ns], serdesDelay:(244), jbDelay:(1186), hardDelay:(944), RfsDelay:(2848.307292 + 162.760417), FsOffset:(0.000000)

[1970-01-01 00:00:09.836] cpriCtrlProc dataPortDelayMgr.cc:1574 INFO:Detected setting nominal internal BFN delay for the first time. Saving the value nominalInternalBfnDelay=5385

[1970-01-01 00:00:10.060] XPP\_XHP\_0\_0 xhp\_arm\_cm.c:2322 INFO:Connected.

[1970-01-01 00:00:10.060] XPP\_XHP\_0\_0 xhp\_arm\_cm.c:1188 INFO:Connected HDLC address: 3

[1970-01-01 00:00:10.064] XPP\_XHP\_1\_0 xhp\_arm\_cm.c:2322 INFO:Connected.

[1970-01-01 00:00:10.064] XPP\_XHP\_1\_0 xhp\_arm\_cm.c:1188 INFO:Connected HDLC address: 3

[1970-01-01 00:00:11.644] startUp deviceIntProcHelper.cc:56 INFO:Added device warp3 with trap reg 0x54 and mask reg 0x58

[1970-01-01 00:00:11.660] startUp warp3PowerFailure.cc:359 INFO:powerDrop DB parameters: dontRecover = 0, fpgaControl = 0, return48vDelay = 0, doSpikeRecovery = 1, applRestartMethod = 0, ret48RecoveryTimeout = 14

[1970-01-01 00:00:11.660] - warp3PowerFailure.cc:985 INFO:ZI deactivated in FBUF

[1970-01-01 00:00:11.660] - warp3PowerFailure.cc:986 INFO:RUEV:PLD\_ZIOFF 11796432us

[1970-01-01 00:00:12.216] startUp indicatorForwarding.cc:88 INFO:Initialization of mmiReset indicator forwarding complete

[1970-01-01 00:00:12.236] startUp startUp.cc:347 INFO:HW initialization completed

[1970-01-01 00:00:12.236] startUp startUp.cc:351 INFO:RUEV:HW\_INIT 12372557us

[1970-01-01 00:00:12.236] startUp delayHandler.cc:306 INFO:initDelayRunner: DelayFpgaBusyWait

[1970-01-01 00:00:12.236] startUp initFunc.cc:812 INFO:fixPossibleProdDbError

[1970-01-01 00:00:12.240] startUp eqpStartup.cc:140 INFO:EqpStartup initialization start

[1970-01-01 00:00:12.272] faultManagerProc faultManager.cc:2857 INFO:Set event STARTUP\_EVENT to time: 15000[ms], from 0x100070

[1970-01-01 00:00:12.276] startUp rdPoESrv.cc:127 INFO:RJ45 contains Power-On indicating LEDs

[1970-01-01 00:00:12.284] ledProc erciMmi.cc:394 INFO:Vii: 0x00200000

[1970-01-01 00:00:12.284] ledProc erciMmi.cc:394 INFO:Vii: 0x00010000

[1970-01-01 00:00:12.284] ledProc erciMmi.cc:394 INFO:Vii: 0x00000010

[1970-01-01 00:00:12.320] startUp externalAlarmSrv.cc:121 INFO:Number of ports: 2

[1970-01-01 00:00:12.328] startUp rdClient.cc:174 INFO:RDCI Version Info - Build:36, Date:2019-02-19, Version:R5C, IWD Version:RDCI\_IWD\_J

[1970-01-01 00:00:12.364] startUp tddFsmWorkingNotifier.cc:41 INFO:TddFsmWorkingNotifier::subscribeTddFsmWorking()

[1970-01-01 00:00:12.372] faultBranchHandlerProc faultBranchHandler\_proc.cc:65 INFO:No /capFaultReporting param, probably it is not AAS unit

[1970-01-01 00:00:12.380] startUp eqpModule.cc:119 INFO:ExternalAlarmSrvIf Found

[1970-01-01 00:00:12.380] startUp eqpModule.cc:125 INFO:HotSpotSrvIf Found

[1970-01-01 00:00:12.384] startUp eqpStartup.cc:278 INFO:EqpStartup initialization completed successfully

[1970-01-01 00:00:12.384] startUp initFunc.cc:261 INFO:TRx share Module is not started on zero rx radio

[1970-01-01 00:00:12.388] startUp initFunc.cc:299 INFO:There is no /radioWithMassiveAntennas in database, use default value 0

[1970-01-01 00:00:12.500] startUp sbpsSrvPf5.cc:176 INFO:Expansion Blockinterface not found for A

[1970-01-01 00:00:12.508] startUp sbpsSrvPf5.cc:176 INFO:Expansion Blockinterface not found for B

[1970-01-01 00:00:12.572] startUp paSrvPowerLevelIru.cc:91 INFO:powerClassdBm is set to 0

[1970-01-01 00:00:12.576] startUp paSrvPowerLevelIru.cc:91 INFO:powerClassdBm is set to 0

[1970-01-01 00:00:12.576] startUp txBrFaultAdvisor.cc:122 INFO:There is no /radioWithMassiveAntennas in database, use default value 0

[1970-01-01 00:00:12.580] startUp txBrFaultAdvisor.cc:122 INFO:There is no /radioWithMassiveAntennas in database, use default value 0

[1970-01-01 00:00:12.588] startUp txBackoffCtrl.cc:218 INFO:TxBackoffCtrl[TxBackoffCtrlA] locate CavFilterProtectSrv failed

[1970-01-01 00:00:12.592] startUp txBackoffCtrl.cc:218 INFO:TxBackoffCtrl[TxBackoffCtrlB] locate CavFilterProtectSrv failed

[1970-01-01 00:00:12.640] startUp overTempSrvBase.cc:182 INFO:Init of fault suppression map will be done at first temp supervision data request. sensor: RxTemp

[1970-01-01 00:00:12.640] startUp overTempSrvBase.cc:182 INFO:Init of fault suppression map will be done at first temp supervision data request. sensor: TDpa

[1970-01-01 00:00:12.644] startUp txBackoffCtrl.cc:324 INFO:Periodic handling of back-off started for branch: A. period: 5000

[1970-01-01 00:00:12.648] startUp txBackoffCtrl.cc:324 INFO:Periodic handling of back-off started for branch: B. period: 5000

[1970-01-01 00:00:12.652] startUp sbpsSrvPf5.cc:572 INFO:autoGet on key //sbpsCapable returns:0

[1970-01-01 00:00:12.652] startUp sbpsSrvPf5.cc:572 INFO:autoGet on key //sbpsCapable returns:0

[1970-01-01 00:00:12.652] startUp timeoutFilter.cc:507 INFO:Found TimeoutScheduler instance 49215088

[1970-01-01 00:00:12.720] startUp initFunc.cc:349 INFO:Tx::ServiceStartup completed successfully

[1970-01-01 00:00:12.996] startUp rxDesenseService.cc:137 INFO:desenseService A created

[1970-01-01 00:00:13.004] startUp rxDesenseService.cc:137 INFO:desenseService B created

[1970-01-01 00:00:14.608] startUp equalizerComm.cc:152 INFO:Equalizer initialized (numTaps:15, samplFreq:7.68MHz, start-endFreq:-2.50-2.50MHz, numPoints:26)

[1970-01-01 00:00:14.608] startUp ricrai.c:623 INFO:added internal ricr subscriber, type 1

[1970-01-01 00:00:14.608] cpriCtrlProc linkCtrlCpriBase.cc:308 INFO:RICRAI\_UPDATE\_DELAY2\_IND,recToReDelay:0, portNo:0

[1970-01-01 00:00:14.608] cpriCtrlProc warp3ULDelayBlock.cc:143 INFO:Setting bfnTimeDelay: 0, maxBfnTime: 307200

[1970-01-01 00:00:14.608] startUp rxFaultAdvisorBranchCtrl.cc:76 INFO:There is no /radioWithMassiveAntennas in database, use default value 0

[1970-01-01 00:00:14.608] cpriCtrlProc linkCtrlCpriBase.cc:308 INFO:RICRAI\_UPDATE\_DELAY2\_IND,recToReDelay:0, portNo:1

[1970-01-01 00:00:14.612] startUp rxFaultAdvisorBranchCtrl.cc:76 INFO:There is no /radioWithMassiveAntennas in database, use default value 0

[1970-01-01 00:00:14.616] startUp rxLoServiceIruAnalog.cc:79 INFO:Subscription for freqSet successful for branch A

[1970-01-01 00:00:14.616] startUp rxLoServiceIruAnalog.cc:79 INFO:Subscription for freqSet successful for branch B

[1970-01-01 00:00:14.620] startUp rxNcoServiceIru.cc:90 INFO:/rxA/IntermediateFreq/range:39000 80000

[1970-01-01 00:00:14.620] startUp rxNcoServiceIru.cc:90 INFO:/rxB/IntermediateFreq/range:39000 80000

[1970-01-01 00:00:14.740] startUp rxAgcMainServiceDbAccess.cc:1138 INFO:Missing /rxA/aggMainService/narrow or /rx/aggMainService/narrow parameter

[1970-01-01 00:00:14.764] startUp rxAgcMainServiceDbAccess.cc:1138 INFO:Missing /rxB/aggMainService/narrow or /rx/aggMainService/narrow parameter

[1970-01-01 00:00:14.772] startUp rxAgcGainCompensationService.cc:790 INFO:Missing optional DB parameter /ul/aCompGainDefault

[1970-01-01 00:00:14.772] startUp logManager.cc:42 INFO:Missing optional DB parameter /ul/gSupGainCompOffset (rxAgcGainCompensationService.cc:803)

[1970-01-01 00:00:14.780] startUp rxAgcGainCompensationService.cc:790 INFO:Missing optional DB parameter /ul/aCompGainDefault

[1970-01-01 00:00:14.780] startUp logManager.cc:42 INFO:Missing optional DB parameter /ul/gSupGainCompOffset (rxAgcGainCompensationService.cc:803)

[1970-01-01 00:00:14.788] startUp rxDynAgeServiceWxx.cc:226 INFO:AGC dynamic release is enabled

[1970-01-01 00:00:14.796] startUp rxDynAgeServiceWxx.cc:226 INFO:AGC dynamic release is enabled

[1970-01-01 00:00:14.804] startUp timeoutFilter.cc:507 INFO:Found TimeoutScheduler instance 49300352

[1970-01-01 00:00:14.804] startUp rxDiagService.cc:113 INFO:Found TimeoutFilter instance 2f13a48

[1970-01-01 00:00:14.804] startUp rxDiagService.cc:113 INFO:Found TimeoutFilter instance 2f13a48

[1970-01-01 00:00:14.804] startUp rxCbrsMeasServiceIru.cc:73 INFO:Subscription for rxCbrsMeas successful for branch A

[1970-01-01 00:00:14.804] startUp rxCbrsMeasServiceIru.cc:73 INFO:Subscription for rxCbrsMeas successful for branch B

[1970-01-01 00:00:14.824] startUp initFunc.cc:407 INFO:Rx::ServiceStartup completed successfully

[1970-01-01 00:00:14.856] startUp antennaModule.cc:165 INFO:ABN: Failed to connect powerDropService

[1970-01-01 00:00:14.868] startUp ricrai.c:719 INFO:added internal ricr subscriber, type 7

[1970-01-01 00:00:14.872] startUp halEventHandler.cc:193 INFO:No shareLocalFaultId value in database

[1970-01-01 00:00:14.872] startUp crhTpaCarrierList.cc:48 INFO:Number of TxBranches = 2

[1970-01-01 00:00:14.876] startUp crhCarrierCtrl.cc:2817 INFO:Overbooking support is enabled. Overbooking value: 0 mW

[1970-01-01 00:00:14.876] startUp carrierListHandler.cc:89 INFO:Register legacy subscriber: cfhe

[1970-01-01 00:00:14.876] startUp carrierListHandler.cc:89 INFO:Register legacy subscriber: FmEventSubscriber

[1970-01-01 00:00:14.876] startUp carrierListHandler.cc:89 INFO:Register legacy subscriber: rmc

[1970-01-01 00:00:14.880] startUp txModule.cc:1665 INFO:TxModule>>TxModule::subscribeSetFsInfo

[1970-01-01 00:00:14.880] startUp txTimingPhaseCtrl.cc:2259 INFO:TxModule>>TxTimingPhaseCtrl::subscribeFsInfo

[1970-01-01 00:00:14.880] startUp txModule.cc:1665 INFO:TxModule>>TxModule::subscribeSetFsInfo

[1970-01-01 00:00:14.880] startUp txTimingPhaseCtrl.cc:2259 INFO:TxModule>>TxTimingPhaseCtrl::subscribeFsInfo

[1970-01-01 00:00:14.880] startUp txModule.cc:1685 INFO:TxModule>>TxModule::subscribeSetTimingInfo

[1970-01-01 00:00:14.880] startUp txTimingPhaseCtrl.cc:2268 INFO:TxModule>>TxTimingPhaseCtrl::subscribeTimingInfo

[1970-01-01 00:00:14.880] startUp txModule.cc:1685 INFO:TxModule>>TxModule::subscribeSetTimingInfo

[1970-01-01 00:00:14.880] startUp txTimingPhaseCtrl.cc:2268 INFO:TxModule>>TxTimingPhaseCtrl::subscribeTimingInfo

[1970-01-01 00:00:14.880] startUp txBroker.cc:196 INFO:subscribe to LTUI Server

[1970-01-01 00:00:14.880] TxBranchCtrlA txBranchCtrl\_main.cc:322 INFO:RUEV:LTU\_LOCKED 15017420us is locked

[1970-01-01 00:00:14.880] TxBranchCtrlA txChangeCycleFsm.cc:1246 INFO:TX\_CHANGE\_CYCLE\_STATE\_IDLE, doEvaluateBufferedEvents()

[1970-01-01 00:00:14.880] TxBranchCtrlA txBrFaultAdvisor.cc:1377 INFO:handleLtuEvent(LtuModeEventEnumType p\_ltuEvent(1)) m\_ltuLocked(1)

[1970-01-01 00:00:14.880] TxBranchCtrlB txBranchCtrl\_main.cc:322 INFO:RUEV:LTU\_LOCKED 15018025us is locked

[1970-01-01 00:00:14.880] TxBranchCtrlB txChangeCycleFsm.cc:1246 INFO:TX\_CHANGE\_CYCLE\_STATE\_IDLE, doEvaluateBufferedEvents()

[1970-01-01 00:00:14.880] TxBranchCtrlB txBrFaultAdvisor.cc:1377 INFO:handleLtuEvent(LtuModeEventEnumType p\_ltuEvent(1)) m\_ltuLocked(1)

[1970-01-01 00:00:14.880] startUp objectStartUp.cc:112 INFO:objectStartUp completed successfully for resource

[1970-01-01 00:00:14.976] rdsDciProc ccieRdsDcInterface.cc:338 INFO:SAR:Published interface: rdsDcServer(0x1000bb) and RDS-DCI(highestProtocolRev:2),dispatchPid\_: 0x10007c

[1970-01-01 00:00:14.996] bcProc ccieLteInterface.cc:108 INFO:SAR:Published interface: BcServer(0x1000dd) and BCI(highestProtocolRev:3(0x3),proto\_basic:0,proto\_spec:3),dispatchPid\_: 0x100074

[1970-01-01 00:00:14.996] bcProc bcRu.cc:356 INFO:IRU 2242 SW started

[1970-01-01 00:00:14.996] bcProc bcRu.cc:303 INFO:Starting O&M interfaces

[1970-01-01 00:00:15.000] antpServerProc\_antennaModule.cc:1170 INFO:Executing setCurrentMeasurementListener

[1970-01-01 00:00:15.000] antpServerProc\_ccieLteInterface.cc:108 INFO:SAR:Published interface: antpServer(0x1000e0) and ANTPI(highestProtocolRev:4(0x4),proto\_basic:0,proto\_spec:4),dispatchPid\_: 0x1000df

[1970-01-01 00:00:15.116] cbcrProc ccieInterface.cc:113 INFO:SAR:Published interface: XbcServer(0x1000e2) and RRU-CBCI(highestProtocolRev:267),dispatchPid\_: 0x100075

[1970-01-01 00:00:15.468] HRICR\_hw\_monitor sfp\_monitor.c:2369 INFO:SFP fault supervision initialized for port 0

[1970-01-01 00:00:15.792] rdcisim0 rdcisimServer.cc:44 INFO:\*\*\*\*\* RDCI SIM Forwarder started \*\*\*\*\*

[1970-01-01 00:00:15.792] rdcisim0 rdcisimServer.cc:45 INFO:RDCI Version Info - Build:36, Date:2019-02-19, Version:R5C, IWD Version:RDCI\_IWD\_J

[1970-01-01 00:00:15.856] RdPoESrv rdPoESrv.cc:316 INFO:Number of newly detected Rds: 1

[1970-01-01 00:00:15.856] RdPoESrv rdPoESrv.cc:317 INFO:Newly detected RdPorts: 1

[1970-01-01 00:00:15.856] RdEqpCtrl rdEqpCtrl.cc:590 INFO:Setting RD(RdPort:1) as starting

[1970-01-01 00:00:15.856] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:674 INFO:RdEqp Event Report RdPort:1, RD Connected

[1970-01-01 00:00:15.856] RdPoESrv rdPoESrv.cc:644 INFO:Power on RdPort 1

[1970-01-01 00:00:15.864] RdEqpCtrl rdCableSrv.cc:812 INFO:Tx unmuted on RD port 1

[1970-01-01 00:00:15.864] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:HUNT\_RD\_SERVER transactionId:65535

[1970-01-01 00:00:15.864] XPP\_XCM xcm\_device.c:550 INFO:Opening Device Driver "RDDEV", 0

[1970-01-01 00:00:15.876] RdClient0 rdLinkConnectionManager.cc:270 INFO:Set MODEM\_CARRIER\_FREQ to 230 MHz for RdId:0, RdPort:1

[1970-01-01 00:00:15.876] XPP\_XCM xcm\_device.c:637 INFO:Starting Device Driver "RDDEV", 0

[1970-01-01 00:00:16.584] RdClient0 rdBaseMessageHandler.cc:136 INFO:HUNT\_RD\_SERVER\_SIG transaction id 65535

[1970-01-01 00:00:16.584] rdcisim0 rdcisimServer.cc:290 INFO:\*\*\*\*\* Forwarding to PID 0x1000ec for RDO \*\*\*\*\*

[1970-01-01 00:00:16.584] rdcisim0 rdcisimServer.cc:323 INFO:\*\*\*\*\* Connecting client PID 0x10009b to server PID 0x1000ec for RDO \*\*\*\*\*

[1970-01-01 00:00:16.708] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_UTC transactionId:2

[1970-01-01 00:00:16.812] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:3

[1970-01-01 00:00:16.928] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SUBSCRIBE\_FAULTS transactionId:4

[1970-01-01 00:00:17.024] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BOARD\_CAP\_EXCHANGE transactionId:5

[1970-01-01 00:00:17.200] RdClient0 rdBoardSrv.cc:2053 INFO:Response for RdPort:1 to get Board Capability Req:CFM\_MSG

[1970-01-01 00:00:17.312] RdClient0 rdSwLoadingSrvBase.cc:538 INFO:Using default load module 'CXC 112 4419/5' from HW PID

[1970-01-01 00:00:17.312] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 6, handle 1)

[1970-01-01 00:00:17.312] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 7, handle 1)

[1970-01-01 00:00:17.312] RdClient0 rdSwLoadingSrvBase.cc:1245 INFO:RD boardOperationalCapability.upgradableDesignDB == 1: RdPort: '1'

[1970-01-01 00:00:17.312] RdClient0 rdSwLoadingSrvBase.cc:1825 INFO:hwPidCapability.productRevision: R1A

[1970-01-01 00:00:17.316] RdClient0 rdSwLoadingSrvBase.cc:1477 INFO:Found Match for prodNum KRY 901 390/1, prodNubRev R1A, matching dbProdNum CXC 1124505/1.

[1970-01-01 00:00:17.316] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 10, handle 1)

[1970-01-01 00:00:17.316] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 11, handle 1)

[1970-01-01 00:00:17.316] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 12, handle 1)

[1970-01-01 00:00:17.316] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 13, handle 1)  
[1970-01-01 00:00:17.316] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 14, handle 1)  
[1970-01-01 00:00:17.316] RdClient0 rdSwLoadingSrvBase.cc:1865 INFO:Add RD DB to loadingData  
[1970-01-01 00:00:17.316] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 6, handle 1)  
[1970-01-01 00:00:17.316] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 7, handle 1)  
[1970-01-01 00:00:17.544] RdClient0 rdSwLoadingSrvBase.cc:1323 INFO:Design DB is not in expected state. (RdPort 1) restartAttempts 0  
[1970-01-01 00:00:17.544] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BRANCH\_CAP transactionId:9  
[1970-01-01 00:00:17.544] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BRANCH\_CAP transactionId:10  
[1970-01-01 00:00:17.648] TxBackoffCtrlA overTempSrvBase.cc:526 INFO:Subscription for temperatureSvData not done. Sensor: RxTemp  
[1970-01-01 00:00:17.648] TxBackoffCtrlA overTempSrvBase.cc:526 INFO:Subscription for temperatureSvData not done. Sensor: TDpa  
[1970-01-01 00:00:17.648] TxBackoffCtrlA overTempSrvBase.cc:526 INFO:Subscription for temperatureSvData not done. Sensor: TDpa\_A  
[1970-01-01 00:00:17.648] TxBackoffCtrlA overTempSrvBase.cc:526 INFO:Subscription for temperatureSvData not done. Sensor: Tmpa  
[1970-01-01 00:00:17.648] TxBackoffCtrlA overTempSrvBase.cc:526 INFO:Subscription for temperatureSvData not done. Sensor: Tmpa\_A  
[1970-01-01 00:00:17.776] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:55 INFO:,noCap=11,branchId=A  
[1970-01-01 00:00:17.776] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:222 INFO:capId=1(RDCI\_CAP\_BRANCH\_BAND\_INFO),duplexMode=0(RDCI\_DUPLEX\_MODE\_FDD),band=BandIII  
[1970-01-01 00:00:17.776] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:234 INFO:capId=2(RDCI\_CAP\_BRANCH\_TX\_FREQUENCY)RfMin=18050000,RfMax=18800000,IfMin=1100000,IfMax=1500000,InvSpectrum=0,StepSize=10,RfTuneMin=18050000,RfTuneMax=18800000,RfTuneCoupled=3,Ibw=400000  
[1970-01-01 00:00:17.776] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:256 INFO:capId=3(RDCI\_CAP\_BRANCH\_RX\_FREQUENCY)RfMin=17100000,RfMax=17850000,IfMin=400000,IfMax=800000,InvSpectrum=0,StepSize=10,RfTuneMin=17100000,RfTuneMax=17850000,RfTuneCoupled=3,Ibw=400000  
[1970-01-01 00:00:17.776] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:278 INFO:capId=4(RDCI\_CAP\_BRANCH\_CABLE\_LOSS\_COMP),fskModemOutputPower=-1561,minILThreshold=240,maxILThreshold=4590,catFrequencySelect=1300000  
[1970-01-01 00:00:17.776] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:293 INFO:capId=5(RDCI\_CAP\_BRANCH\_RX\_GAIN),nominalGain=3650,noiseFigure=0  
[1970-01-01 00:00:17.776] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:306 INFO:capId=6(RDCI\_CAP\_BRANCH\_TX\_POWER),txPar=750,txPowerClassUsage=1700  
[1970-01-01 00:00:17.776] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:320 INFO:capId=7(RDCI\_CAP\_BRANCH\_TX\_GAIN\_ADJUST),txGainAdjustHi=0,txGainAdjustLo=-1000  
[1970-01-01 00:00:17.776] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:333 INFO:capId=8(RDCI\_CAP\_BRANCH\_RX\_AGC),rxAgcMode=0,rxAgcDefault=0  
[1970-01-01 00:00:17.776] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:352 INFO:capId=9(RDCI\_CAP\_BRANCH\_TX\_POWER\_MEAS),txPowerMeasMode=2,txMaxPowerBackoff=-10000  
[1970-01-01 00:00:17.776] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:366 INFO:capId=10(RDCI\_CAP\_BRANCH\_CARRIER\_DATA),carrierDataRequired=1,txLoMode=IBW  
[1970-01-01 00:00:17.776] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:387 INFO:capId=11(RDCI\_CAP\_BRANCH\_WCDMA\_DESENSE),desenseGainRebalance=24 dB  
[1970-01-01 00:00:18.044] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:55 INFO:,noCap=11,branchId=B  
[1970-01-01 00:00:18.044] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:222 INFO:capId=1(RDCI\_CAP\_BRANCH\_BAND\_INFO),duplexMode=0(RDCI\_DUPLEX\_MODE\_FDD),band=BandIII  
[1970-01-01 00:00:18.044] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:234 INFO:capId=2(RDCI\_CAP\_BRANCH\_TX\_FREQUENCY)RfMin=18050000,RfMax=18800000,IfMin=1100000,IfMax=1500000,InvSpectrum=0,StepSize=10,RfTuneMin=18050000,RfTuneMax=18800000,RfTuneCoupled=3,Ibw=400000  
[1970-01-01 00:00:18.044] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:256 INFO:capId=3(RDCI\_CAP\_BRANCH\_RX\_FREQUENCY)RfMin=17100000,RfMax=17850000,IfMin=400000,IfMax=800000,InvSpectrum=0,StepSize=10,RfTuneMin=17100000,RfTuneMax=17850000,RfTuneCoupled=3,Ibw=400000  
[1970-01-01 00:00:18.044] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:278 INFO:capId=4(RDCI\_CAP\_BRANCH\_CABLE\_LOSS\_COMP),fskModemOutputPower=-1752,minILThreshold=240,maxILThreshold=4590,catFrequencySelect=1300000  
[1970-01-01 00:00:18.044] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:293 INFO:capId=5(RDCI\_CAP\_BRANCH\_RX\_GAIN),nominalGain=3650,noiseFigure=0  
[1970-01-01 00:00:18.044] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:306 INFO:capId=6(RDCI\_CAP\_BRANCH\_TX\_POWER),txPar=750,txPowerClassUsage=1700  
[1970-01-01 00:00:18.044] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:320 INFO:capId=7(RDCI\_CAP\_BRANCH\_TX\_GAIN\_ADJUST),txGainAdjustHi=0,txGainAdjustLo=-1000  
[1970-01-01 00:00:18.044] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:333 INFO:capId=8(RDCI\_CAP\_BRANCH\_RX\_AGC),rxAgcMode=0,rxAgcDefault=0  
[1970-01-01 00:00:18.044] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:352 INFO:capId=9(RDCI\_CAP\_BRANCH\_TX\_POWER\_MEAS),txPowerMeasMode=2,txMaxPowerBackoff=-10000  
[1970-01-01 00:00:18.044] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:366 INFO:capId=10(RDCI\_CAP\_BRANCH\_CARRIER\_DATA),carrierDataRequired=1,txLoMode=IBW  
[1970-01-01 00:00:18.044] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:387 INFO:capId=11(RDCI\_CAP\_BRANCH\_WCDMA\_DESENSE),desenseGainRebalance=24 dB  
[1970-01-01 00:00:18.048] RdClient0 rdModel.cc:1083 INFO:Consolidated RdId is 0  
[1970-01-01 00:00:18.048] RdClient0 rdBoardSrv.cc:1924 INFO:Requesting Time Delay values from RdId:0, RdPort:1  
[1970-01-01 00:00:18.048] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:TX\_TIME\_DELAY transactionId:11  
[1970-01-01 00:00:18.048] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:TX\_TIME\_DELAY transactionId:12  
[1970-01-01 00:00:18.048] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:RX\_TIME\_DELAY transactionId:13  
[1970-01-01 00:00:18.048] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:RX\_TIME\_DELAY transactionId:14  
[1970-01-01 00:00:18.056] RdClient0 paSrvPowerLevelIru.cc:121 INFO:powerClassDbm is set to 1700  
[1970-01-01 00:00:18.076] RdClient0 paSrvPowerLevelIru.cc:121 INFO:powerClassDbm is set to 1700  
[1970-01-01 00:00:18.176] RdClient0 rdTxTimeDelayCfmMessageHandler.cc:68 INFO:branch 0 delayRefPath=0  
[1970-01-01 00:00:18.260] RdClient0 rdTxTimeDelayCfmMessageHandler.cc:68 INFO:branch 1 delayRefPath=0  
[1970-01-01 00:00:18.468] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/dl/rf\_bA/delayReference=0  
[1970-01-01 00:00:18.468] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/dl/rf\_bA/delayFreqCompTable\_x=1  
[1970-01-01 00:00:18.468] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/dl/rf\_bA/delayFreqCompTable\_y=1  
[1970-01-01 00:00:18.468] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/dl/rf\_bB/delayReference=0  
[1970-01-01 00:00:18.472] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/dl/rf\_bB/delayFreqCompTable\_x=1  
[1970-01-01 00:00:18.472] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/dl/rf\_bB/delayFreqCompTable\_y=1  
[1970-01-01 00:00:18.472] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/ul/rf\_bA/delayReference=0  
[1970-01-01 00:00:18.472] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/ul/rf\_bA/delayFreqCompTable\_x=1  
[1970-01-01 00:00:18.476] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/ul/rf\_bA/delayFreqCompTable\_y=1  
[1970-01-01 00:00:18.476] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/ul/rf\_bB/delayReference=0  
[1970-01-01 00:00:18.476] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/ul/rf\_bB/delayFreqCompTable\_x=1  
[1970-01-01 00:00:18.476] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/ul/rf\_bB/delayFreqCompTable\_y=1  
[1970-01-01 00:00:18.476] RdClient0 rdBoardSrv.cc:1807 INFO:send SetTxIfMaxPowerReq with RdPort=1, Br=0, maxPower=-4  
[1970-01-01 00:00:18.480] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_TX\_IF\_MAX\_PWR transactionId:15  
[1970-01-01 00:00:18.480] RdClient0 rdBoardSrv.cc:1807 INFO:send SetTxIfMaxPowerReq with RdPort=1, Br=1, maxPower=15  
[1970-01-01 00:00:18.480] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_TX\_IF\_MAX\_PWR transactionId:16  
[1970-01-01 00:00:18.600] RdClient0 rdBoardSrv.cc:1832 INFO:Response for RdPort:1 to set TxIfMaxPwrDone:CFM\_MSG  
[1970-01-01 00:00:18.700] RdClient0 rdBoardSrv.cc:1832 INFO:Response for RdPort:1 to set TxIfMaxPwrDone:CFM\_MSG  
[1970-01-01 00:00:18.700] RdClient0 rdBoardSrv.cc:1734 INFO:notifyStartRdDone: 0  
[1970-01-01 00:00:18.700] RdEqpCtrl rdEqpCtrl.cc:399 INFO:StartRdDone with RdPort:1  
[1970-01-01 00:00:18.700] RdEqpCtrl rdCableSrv.cc:495 INFO:Starting Pair Swap Test with RD PORT list: { 1 }  
[1970-01-01 00:00:18.832] RdEqpCtrl rdEqpCtrl.cc:963 INFO:pairSwap test done.  
[1970-01-01 00:00:18.832] RdEqpCtrl rdCableMeasSvSrv.cc:103 INFO:Starting cable IL measurement with RD PORT list: { 1 }  
[1970-01-01 00:00:19.852] RdCableMeasSvSrv rdClientCableMeasurements.cc:213 INFO:A(0mb), B(5479mb), C(224mb) Coefficient was sent to RdPort(1) for branchId(0)  
[1970-01-01 00:00:19.852] RdCableMeasSvSrv rdCableILMeasSv.cc:727 INFO:Stored Rx-IL(2856mb) and Tx-IL(4245mb) for RdPort(1) and branchId(0)  
[1970-01-01 00:00:19.972] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received CFM\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(1) and Branch(A)  
[1970-01-01 00:00:20.912] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received IND\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(1) and Branch(A)  
[1970-01-01 00:00:20.976] RdClient0 rdcActiveObject.cc:243 INFO:RD Procedure timer expired for rdId:0 timerId:41 transactionId:29  
[1970-01-01 00:00:20.976] RdCableMeasSvSrv rdCableILMeasSv.cc:1215 INFO:ABN: Received TIME\_OUT response for IL\_RSSI\_MEAS\_REQ for RdPort(1) and branchId(1)  
[1970-01-01 00:00:20.976] RdEqpCtrl rdEqpCtrl.cc:839 INFO:Cable IL Measurement done  
[1970-01-01 00:00:20.976] RdEqpCtrl rdCableSrv.cc:680 INFO:Equalizer for RD port 1 set to ON  
[1970-01-01 00:00:20.976] RdEqpCtrl rdCableSrv.cc:887 INFO:Rx unmuted on RD port 1  
[1970-01-01 00:00:20.976] RdEqpCtrl rdEqpCtrl.cc:860 INFO:Starting AGC test  
[1970-01-01 00:00:20.976] RdEqpCtrl rdEqpCtrl.cc:922 INFO:AGC test done  
[1970-01-01 00:00:20.976] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:30  
[1970-01-01 00:00:20.980] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:2260 INFO:RdEqp Event Report RdPort:1, RD Unlocked  
[1970-01-01 00:00:20.980] RdEqpCtrl rdEqpCtrl.cc:1240 INFO:Processing Set Led Action for RdPort:1; LED type is 0  
[1970-01-01 00:00:20.980] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:31  
[1970-01-01 00:00:20.980] RdEqpFaultCtrl rdActionListUtil.cc:58 INFO:RdEqpEvent:RD Unlocked/RD Locked, RdPort=1 Set LED Action successful;  
[1970-01-01 00:00:20.980] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:661 INFO:RdEqp Fault Report RdPort:1, Fault Id 20 RdMessageTimeout, RAISE  
[1970-01-01 00:00:20.980] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:1096 INFO:Begin processing fault RdMessageTimeout(20) on RdPort:1  
[1970-01-01 00:00:20.980] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:1146 INFO:Performing action Power Reset Action on RdId:0, RdPort:1 for Fault RdMessageTimeout(20)  
[1970-01-01 00:00:20.980] rdBcProc0 ccieLteInterface.cc:108 INFO:SAR:Published interface: rd01/BcServer(0x5000ee) and RDBCIO(highestProtocolRev:3(0x3),proto\_basic:0,proto\_spec:3),dispatchPid\_: 0x1000bd  
[1970-01-01 00:00:20.980] rdCbcProc0 ccieInterface.cc:113 INFO:SAR:Published interface: rd01/rdCbcServer(0x5000ef) and RDCBCIO(highestProtocolRev:257),dispatchPid\_: 0x1000bf  
[1970-01-01 00:00:21.044] RdClient0 rdClientTransactionRegister.cc:99 INFO:Could not find RdClient transaction ID:29.  
[1970-01-01 00:00:21.044] RdClient0 rdBaseMessageHandler.cc:147 INFO:Could not get the transaction info  
[1970-01-01 00:00:21.048] trDcProc ccieLteInterface.cc:108 INFO:SAR:Published interface: radioTrDcServer(0x1000f0) and TR-DCI(highestProtocolRev:65548(0x1000c),proto\_basic:1,proto\_spec:12),dispatchPid\_: 0x1000de  
[1970-01-01 00:00:21.164] almProc ccieInterface.cc:113 INFO:SAR:Published interface: almServer(0x1000f1) and ALM-CDCI(highestProtocolRev:3),dispatchPid\_: 0x1000e8  
[1970-01-01 00:00:21.172] trProc ccieInterface.cc:113 INFO:SAR:Published interface: TRX\_CDCI\_FT(0x1000f2) and TR-CDCI(highestProtocolRev:43),dispatchPid\_: 0x1000e3  
[1970-01-01 00:00:21.240] tpaProc ccieInterface.cc:113 INFO:SAR:Published interface: tpaCdcServer(0x1000f3) and TPA-CDCI(highestProtocolRev:302),dispatchPid\_: 0x1000e7  
[1970-01-01 00:00:21.248] rotProc ccieInterface.cc:113 INFO:SAR:Published interface: rotIdcServer(0x1000f4) and ROT-IDCI(highestProtocolRev:65535),dispatchPid\_: 0x1000e4  
[1970-01-01 00:00:21.252] aiProc ccieInterface.cc:113 INFO:SAR:Published interface: aiServer(0x1000f5) and AI-CDCI(highestProtocolRev:302),dispatchPid\_: 0x1000e6  
[1970-01-01 00:00:21.252] dpclProc ccieInterface.cc:113 INFO:SAR:Published interface: dpclServer(0x1000f6) and DPCL-CDCI(highestProtocolRev:11),dispatchPid\_: 0x1000e5  
[1970-01-01 00:00:21.256] upmiProc upmiServer.cc:113 INFO:Radio doesn't have current and voltage sensors  
[1970-01-01 00:00:21.256] upmiProc upmiServer.cc:116 INFO:PowerConsumptionMeasSrv is not supported on this radio  
[1970-01-01 00:00:21.256] upmiProc upmiServer.cc:214 INFO:SAR:Published interface: RBS\_IW\_UPMI(0x1000f7) and UPMI(highestProtocolRev:1)  
[1970-01-01 00:00:23.424] RdEqpCtrl rdLogCmd.cc:513 INFO:No data from RD (empty log?)  
[1970-01-01 00:00:23.424] RdEqpCtrl rdLogCmd.cc:550 INFO:(Done RdId:0, RdPort:1)  
  
[1970-01-01 00:00:23.424] RdEqpCtrl rdEqpCtrl.cc:1167 INFO:Processing Power cycle for RdPort:1  
[1970-01-01 00:00:23.424] RdEqpCtrl rdCableSrv.cc:887 INFO:Rx muted on RD port 1  
[1970-01-01 00:00:23.424] RdEqpCtrl rdCableSrv.cc:680 INFO:Equalizer for RD port 1 set to TERMINATED  
[1970-01-01 00:00:23.424] RdEqpCtrl rdEqpCtrl.cc:683 INFO:Cleanup Rd data except Hw Pid RdPort:1  
[1970-01-01 00:00:23.424] RdEqpCtrl rdClientBoardBase.cc:93 INFO:RdClientBoardBase::disconnectRd RdId:0, RdPort:1  
[1970-01-01 00:00:23.452] XPP\_XCM xcm\_device.c:805 INFO:Stopping Device Driver "RDDEV", 0  
[1970-01-01 00:00:23.460] XPP\_XCM xcm\_device.c:858 INFO:Closing Device Driver "RDDEV", 0  
[1970-01-01 00:00:23.460] RdPoESrv rdPoESrv.cc:709 INFO:Power off RdPort 1  
[1970-01-01 00:00:23.460] RdEqpFaultCtrl rdActionListUtil.cc:58 INFO:RdEqpFault:SwError(RdMessageTimeout), RdPort=1 Power Reset Action successful;  
[1970-01-01 00:00:23.464] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:2260 INFO:RdEqp Event Report RdPort:1, RD Unlocked  
[1970-01-01 00:00:23.464] RdEqpCtrl rdEqpCtrl.cc:1228 INFO:ABN: RD not present rdId (0)  
[1970-01-01 00:00:23.464] RdEqpFaultCtrl rdActionListUtil.cc:58 INFO:RdEqpEvent:RD Unlocked/RD Locked, RdPort=1 Set LED Action not executed;  
[1970-01-01 00:00:23.612] RdPoESrv rdPoESrv.cc:316 INFO:Number of newly detected Rds: 1  
[1970-01-01 00:00:23.612] RdPoESrv rdPoESrv.cc:317 INFO:Newly detected RdPorts: 1  
[1970-01-01 00:00:23.612] RdEqpCtrl rdEqpCtrl.cc:590 INFO:Setting RD(RdPort:1) as starting  
[1970-01-01 00:00:23.612] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:2260 INFO:RdEqp Event Report RdPort:1, RD Connected  
[1970-01-01 00:00:23.612] RdPoESrv rdPoESrv.cc:644 INFO:Power on RdPort 1  
[1970-01-01 00:00:23.616] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:HUNT\_RD\_SERVER transactionId:33  
[1970-01-01 00:00:23.616] XPP\_XCM xcm\_device.c:550 INFO:Opening Device Driver "RDDEV", 0  
[1970-01-01 00:00:23.632] RdClient0 rdLinkConnectionManager.cc:270 INFO:Set MODEM CARRIER\_FREQ to 230 MHz for RdId:0, RdPort:1  
[1970-01-01 00:00:23.632] XPP\_XCM xcm\_device.c:637 INFO:Starting Device Driver "RDDEV", 0  
[1970-01-01 00:00:23.636] RdClient0 rdBaseMessageHandler.cc:136 INFO:HUNT\_RD\_SERVER\_SIG transaction id 33  
[1970-01-01 00:00:23.740] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_UTC transactionId:35  
[1970-01-01 00:00:23.876] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:36  
[1970-01-01 00:00:23.960] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SUSCRIBE\_FAULTS transactionId:37  
[1970-01-01 00:00:24.112] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BOARD\_CAP\_EXCHANGE transactionId:38  
[1970-01-01 00:00:24.308] RdClient0 rdBoardSrv.cc:2053 INFO:Response for RdPort:1 to get Board Capability Req:CFM\_MSG  
[1970-01-01 00:00:24.440] RdClient0 rdSwLoadingSrvBase.cc:538 INFO:Using default load module 'CXC 112 4419/5' from HW PID  
[1970-01-01 00:00:24.440] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 6, handle 1)  
[1970-01-01 00:00:24.440] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 7, handle 1)  
[1970-01-01 00:00:24.440] RdClient0 rdSwLoadingSrvBase.cc:1245 INFO:RD boardOperationalCapability.upgradableDesignDB == 1: RdPort: '1'  
[1970-01-01 00:00:24.440] RdClient0 rdSwLoadingSrvBase.cc:1825 INFO:hwPidCapability.productRevision: R1A



[1970-01-01 00:00:24.444] RdClient0 rdSwLoadingSrvBase.cc:1477 INFO:Found Match for prodNum KRY 901 390/1, prodNubRev R1A, matching dbProdNum CXC 1124505/1.

[1970-01-01 00:00:24.444] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 10, handle 1)

[1970-01-01 00:00:24.448] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 11, handle 1)

[1970-01-01 00:00:24.448] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 12, handle 1)

[1970-01-01 00:00:24.448] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 13, handle 1)

[1970-01-01 00:00:24.452] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 14, handle 1)

[1970-01-01 00:00:24.452] RdClient0 rdSwLoadingSrvBase.cc:1865 INFO:Add RD DB to loadingData

[1970-01-01 00:00:24.452] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 6, handle 1)

[1970-01-01 00:00:24.456] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 7, handle 1)

[1970-01-01 00:00:24.668] RdClient0 rdSwLoadingSrvBase.cc:1323 INFO:Design DB is not in expected state. (RdPort 1) restartAttempts 0

[1970-01-01 00:00:24.668] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BRANCH\_CAP transactionId:42

[1970-01-01 00:00:24.668] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BRANCH\_CAP transactionId:43

[1970-01-01 00:00:24.876] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:55 INFO:,noCap=11,branchId=A

[1970-01-01 00:00:24.876] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:222 INFO:capId=1(RDCI\_CAP\_BRANCH\_BAND\_INFO),duplexMode=0(RDCI\_DUPLEX\_MODE\_FDD),band=BandIII

[1970-01-01 00:00:24.876] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:234

INFO:capId=2(RDCI\_CAP\_BRANCH\_TX\_FREQUENCY)RfMin=18050000,RfMax=18800000,IfMin=1100000,IfMax=1500000,InvSpectrum=0,StepSize=10,RfTuneMin=18050000,RfTuneMax=18800000,RfTuneCoupled=3,Ibw=400000

[1970-01-01 00:00:24.876] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:256

INFO:capId=3(RDCI\_CAP\_BRANCH\_RX\_FREQUENCY)RfMin=17100000,RfMax=17850000,IfMin=400000,IfMax=800000,InvSpectrum=0,StepSize=10,RfTuneMin=17100000,RfTuneMax=17850000,RfTuneCoupled=3,Ibw=400000

[1970-01-01 00:00:24.876] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:278

INFO:capId=4(RDCI\_CAP\_BRANCH\_CABLE\_LOSS\_COMP),fskModemOutputPower=-1561,minILThreshold=240,maxILThreshold=4590,catFrequencySelect=1300000

[1970-01-01 00:00:24.876] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:293 INFO:capId=5(RDCI\_CAP\_BRANCH\_RX\_GAIN),nominalGain=3650,noiseFigure=0

[1970-01-01 00:00:24.876] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:306 INFO:capId=6(RDCI\_CAP\_BRANCH\_TX\_POWER),txPar=750,txPowerClassUsage=1700

[1970-01-01 00:00:24.876] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:320 INFO:capId=7(RDCI\_CAP\_BRANCH\_TX\_GAIN\_ADJUST),txGainAdjustHi=0,txGainAdjustLo=-1000

[1970-01-01 00:00:24.876] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:333 INFO:capId=8(RDCI\_CAP\_BRANCH\_RX\_AGC),rxAgcMode=0,rxAgcDefault=0

[1970-01-01 00:00:24.876] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:352 INFO:capId=9(RDCI\_CAP\_BRANCH\_TX\_POWER\_MEAS),txPowerMeasMode=2,txMaxPowerBackoff=-10000

[1970-01-01 00:00:24.876] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:366 INFO:capId=10(RDCI\_CAP\_BRANCH\_CARRIER\_DATA),carrierDataRequired=1,txLoMode=IBW

[1970-01-01 00:00:24.876] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:387 INFO:capId=11(RDCI\_CAP\_BRANCH\_WCDMA\_DESENSE),desenseGainRebalance=24 dB

[1970-01-01 00:00:25.212] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:55 INFO:,noCap=11,branchId=B

[1970-01-01 00:00:25.212] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:222 INFO:capId=1(RDCI\_CAP\_BRANCH\_BAND\_INFO),duplexMode=0(RDCI\_DUPLEX\_MODE\_FDD),band=BandIII

[1970-01-01 00:00:25.212] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:234

INFO:capId=2(RDCI\_CAP\_BRANCH\_TX\_FREQUENCY)RfMin=18050000,RfMax=18800000,IfMin=1100000,IfMax=1500000,InvSpectrum=0,StepSize=10,RfTuneMin=18050000,RfTuneMax=18800000,RfTuneCoupled=3,Ibw=400000

[1970-01-01 00:00:25.212] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:256

INFO:capId=3(RDCI\_CAP\_BRANCH\_RX\_FREQUENCY)RfMin=17100000,RfMax=17850000,IfMin=400000,IfMax=800000,InvSpectrum=0,StepSize=10,RfTuneMin=17100000,RfTuneMax=17850000,RfTuneCoupled=3,Ibw=400000

[1970-01-01 00:00:25.212] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:278

INFO:capId=4(RDCI\_CAP\_BRANCH\_CABLE\_LOSS\_COMP),fskModemOutputPower=-1752,minILThreshold=240,maxILThreshold=4590,catFrequencySelect=1300000

[1970-01-01 00:00:25.212] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:293 INFO:capId=5(RDCI\_CAP\_BRANCH\_RX\_GAIN),nominalGain=3650,noiseFigure=0

[1970-01-01 00:00:25.212] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:306 INFO:capId=6(RDCI\_CAP\_BRANCH\_TX\_POWER),txPar=750,txPowerClassUsage=1700

[1970-01-01 00:00:25.212] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:320 INFO:capId=7(RDCI\_CAP\_BRANCH\_TX\_GAIN\_ADJUST),txGainAdjustHi=0,txGainAdjustLo=-1000

[1970-01-01 00:00:25.212] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:333 INFO:capId=8(RDCI\_CAP\_BRANCH\_RX\_AGC),rxAgcMode=0,rxAgcDefault=0

[1970-01-01 00:00:25.212] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:352 INFO:capId=9(RDCI\_CAP\_BRANCH\_TX\_POWER\_MEAS),txPowerMeasMode=2,txMaxPowerBackoff=-10000

[1970-01-01 00:00:25.212] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:366 INFO:capId=10(RDCI\_CAP\_BRANCH\_CARRIER\_DATA),carrierDataRequired=1,txLoMode=IBW

[1970-01-01 00:00:25.212] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:387 INFO:capId=11(RDCI\_CAP\_BRANCH\_WCDMA\_DESENSE),desenseGainRebalance=24 dB

[1970-01-01 00:00:25.216] RdClient0 rdBoardSrv.cc:1807 INFO:send SetTxIfMaxPowerReq with RdPort=1, Br=0, maxPower=-4

[1970-01-01 00:00:25.216] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_TX\_IF\_MAX\_PWR transactionId:44

[1970-01-01 00:00:25.220] RdClient0 rdBoardSrv.cc:1807 INFO:send SetTxIfMaxPowerReq with RdPort=1, Br=1, maxPower=15

[1970-01-01 00:00:25.220] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_TX\_IF\_MAX\_PWR transactionId:45

[1970-01-01 00:00:25.348] RdClient0 rdBoardSrv.cc:1832 INFO:Response for RdPort:1 to set TxIfMaxPwrDone:CFM\_MSG

[1970-01-01 00:00:25.460] RdClient0 rdBoardSrv.cc:1832 INFO:Response for RdPort:1 to set TxIfMaxPwrDone:CFM\_MSG

[1970-01-01 00:00:25.460] RdClient0 rdBoardSrv.cc:1734 INFO:notifyStartRdDone: 0

[1970-01-01 00:00:25.460] RdEqpCtrl rdEqpCtrl.cc:399 INFO:StartRdDone with RdPort:1

[1970-01-01 00:00:25.464] RdEqpCtrl rdCableSrv.cc:495 INFO:Starting Pair Swap Test with RD PORT list: { 1 }

[1970-01-01 00:00:25.556] RdEqpCtrl rdEqpCtrl.cc:963 INFO:pairSwap test done.

[1970-01-01 00:00:25.556] RdEqpCtrl rdCableMeasSvSrv.cc:103 INFO:Starting cable IL measurement with RD PORT list: { 1 }

[1970-01-01 00:00:26.544] RdCableMeasSvSrv rdClientCableMeasurements.cc:213 INFO:A(0mb), B(5479mb), C(224mb) Coefficient was sent to RdPort(1) for branchId(0)

[1970-01-01 00:00:26.544] RdCableMeasSvSrv rdCableILMeasSv.cc:727 INFO:Stored Rx-IL(2856mb) and Tx-IL(4245mb) for RdPort(1) and branchId(0)

[1970-01-01 00:00:26.632] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received CFM MSG response for SET\_IL\_GAIN\_REQ from RdPort(1) and Branch(A)

[1970-01-01 00:00:26.680] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received IND MSG response for SET\_IL\_GAIN\_REQ from RdPort(1) and Branch(A)

[1970-01-01 00:00:27.012] - xhp cmd2.c:575 INFO:Enable debug port! You can login now!

[1970-01-01 00:00:27.276] faultManagerProc faultManager.cc:2907 INFO:RUEV:STARTUP\_END 27412105us

[1970-01-01 00:00:28.932] RdCableMeasSvSrv rdClientCableMeasurements.cc:213 INFO:A(0mb), B(5295mb), C(216mb) Coefficient was sent to RdPort(1) for branchId(1)

[1970-01-01 00:00:28.932] RdCableMeasSvSrv rdCableILMeasSv.cc:727 INFO:Stored Rx-IL(2760mb) and Tx-IL(4102mb) for RdPort(1) and branchId(1)

[1970-01-01 00:00:28.932] RdEqpCtrl rdEqpCtrl.cc:839 INFO:Cable IL Measurement done

[1970-01-01 00:00:28.932] RdEqpCtrl rdCableSrv.cc:680 INFO:Equalizer for RD port 1 set to ON

[1970-01-01 00:00:28.932] RdEqpCtrl rdCableSrv.cc:887 INFO:Rx unmuted on RD port 1

[1970-01-01 00:00:28.932] RdEqpCtrl rdEqpCtrl.cc:860 INFO:Starting AGC test

[1970-01-01 00:00:28.932] RdEqpCtrl rdEqpCtrl.cc:922 INFO:AGC test done

[1970-01-01 00:00:28.932] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:69

[1970-01-01 00:00:28.936] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:2260 INFO:RdEqp Event Report RdPort:1, RD Unlocked

[1970-01-01 00:00:28.936] RdEqpCtrl rdEqpCtrl.cc:1240 INFO:Processing Set Led Action for RdPort:1; LED type is 0

[1970-01-01 00:00:28.936] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:70

[1970-01-01 00:00:28.936] RdEqpFaultCtrl rdActionListUtil.cc:58 INFO:RdEqpEvent:RD Unlocked/RD Locked, RdPort=1 Set LED Action successful;

[1970-01-01 00:00:28.936] trProc trCdc.cc:4799 INFO:INTERNAL RESTART ALL ROT MEAS REQ.

[1970-01-01 00:00:29.052] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received CFM MSG response for SET\_IL\_GAIN\_REQ from RdPort(1) and Branch(B)

[1970-01-01 00:00:29.100] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received IND MSG response for SET\_IL\_GAIN\_REQ from RdPort(1) and Branch(B)