

[2020-05-04 04:43:48.312] RdPoESrv rdPoESrv.cc:709 INFO:Power off RdPort 8  
[2020-05-04 04:43:48.320] RdPoESrv rdPoESrv.cc:430 INFO:RdPort 8: disconnected  
[2020-05-04 04:43:48.320] RdEqpCtrl rdEqpCtrl.cc:605 INFO:Processing PoE disconnect for RdPort:8  
[2020-05-04 04:43:48.320] RdEqpCtrl rdCableSrv.cc:812 INFO:Tx muted on RD port 8  
[2020-05-04 04:43:48.320] RdEqpCtrl rdCableSrv.cc:887 INFO:Rx muted on RD port 8  
[2020-05-04 04:43:48.320] RdEqpCtrl rdCableSrv.cc:680 INFO:Equalizer for RD port 8 set to TERMINATED  
[2020-05-04 04:43:48.320] RdEqpCtrl rdEqpCtrl.cc:664 INFO:Cleaning up all Rd data RdPort:8  
[2020-05-04 04:43:48.320] RdEqpCtrl rdClientBoardBase.cc:93 INFO:RdClientBoardBase::disconnectRd RdId:7, RdPort:8  
[2020-05-04 04:43:48.324] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:661 INFO:RdEqp Fault Report RdPort:8, Fault Id 11 PoEDisconnected, RAISE  
[2020-05-04 04:43:48.324] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:1096 INFO:Begin processing fault PoEDisconnected(11) on RdPort:8  
[2020-05-04 04:43:48.324] RdEqpFaultCtrl rdInternalFaultList.cc:198 INFO:Faults blocked from processing by highest priority fault[0]  
[2020-05-04 04:43:48.324] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:1088 INFO:No more faults to process  
[2020-05-04 04:43:48.324] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:674 INFO:RdEqp Event Report RdPort:8, RD Disconnected  
[2020-05-04 04:43:48.324] rdCbcProc7 rdCbc.cc:240 INFO:Unpublish rd08/rdCbcServer  
[2020-05-04 04:43:48.328] faultManagerProc faultManager.cc:1900 INFO:ABN:Equipment fault, interface:RD\_EQP\_CTRL,method:onFaultRaise,report number:2101,fault type:RDS\_PROBLEM\_PARTIAL,fault slogan:Radio Dot System  
Problem Partial,fault case:2101,additional info:Disconnected:8;  
[2020-05-04 04:43:48.328] cfhe cfheFaultHandler.cc:217 INFO:ABN:Local fault, faultType:58, interface:10, faultImpact:0x0, lr:[0 1] (faultCase:2101)  
[2020-05-04 04:43:48.352] XPP\_XCM xcm\_device.c:805 INFO:Stopping Device Driver "RDDEV", 7  
[2020-05-04 04:43:48.360] XPP\_XCM xcm\_device.c:858 INFO:Closing Device Driver "RDDEV", 7  
[2020-05-04 04:43:48.704] xpaiSubscriber xpaiSubscriber.cc:133 INFO:Shutting down PA due to board restart  
[2020-05-04 04:43:48.708] xpaiSubscriber txChangeCycleBasicHelper.cc:867 INFO:PA shutdown request for branchId 0, blockId 10  
[2020-05-04 04:43:48.708] xpaiSubscriber paSrv.cc:622 INFO:paControl Off for PaSrvA for branchId 0, blockId 10: from HAL\_shutdownPA  
[2020-05-04 04:43:48.708] xpaiSubscriber rdClientTxRxBranch.cc:170 INFO:No branch enable or disable request sent to RDS  
[2020-05-04 04:43:48.708] xpaiSubscriber paSrvIru.cc:151 INFO:PA\_OFF: BranchId 0 SET TO STATUS OFF  
[2020-05-04 04:43:48.708] xpaiSubscriber txChangeCycleBasicHelper.cc:867 INFO:PA shutdown request for branchId 1, blockId 10  
[2020-05-04 04:43:48.708] xpaiSubscriber paSrv.cc:622 INFO:paControl Off for PaSrvB for branchId 1, blockId 10: from HAL\_shutdownPA  
[2020-05-04 04:43:48.708] xpaiSubscriber rdClientTxRxBranch.cc:170 INFO:No branch enable or disable request sent to RDS  
[2020-05-04 04:43:48.708] xpaiSubscriber paSrvIru.cc:151 INFO:PA\_OFF: BranchId 1 SET TO STATUS OFF  
[2020-05-04 04:43:48.708] XPP\_XMH xmh.c:3609 INFO:Tag XLL\_Restart received. Prevent write or erase of board parameters and user flash.  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 8  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 9  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 10  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 11  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 12  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 13  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 14  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 15  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 0  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 1  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 2  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 3  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 4  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 5  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 6  
[2020-05-04 04:43:48.712] xpaiSubscriber warp3ComUICpriCtrlBlock.cc:220 INFO:disableLink, fb 7  
[2020-05-04 04:43:48.712] RdPoESrv rdPoESrv.cc:709 INFO:Power off RdPort 1  
[1970-01-01 00:00:00.056] - xpai\_xos.c:287 INFO:XPP (PID=CXC1321797/3\_R40AE), is RUNNING  
[1970-01-01 00:00:00.056] - xpai\_xos.c:289 INFO:The XPP with XPAI REVISION: CYB10190-R7G  
[1970-01-01 00:00:00.056] - xos.c:3634 INFO:WARP3.5 Flash=FLASH\_SPANSION\_S29GL\_S 64Mb RAM=128Mb HW-id=CXC10115112 HW-rev=RIA000000 OSE Delta PowerPC/BL910356  
[1970-01-01 00:00:00.056] - xos.c:3641 INFO:XPP STARTED  
[1970-01-01 00:00:00.056] - xos.c:3645 INFO:SYS\_LM\_PID: CXC1321797/3\_R40AE  
[1970-01-01 00:00:00.056] - xos.c:3649 INFO:SYS\_LF\_PID: CXP9013268%14 8689be9  
[1970-01-01 00:00:00.056] - xos.c:3653 INFO:SYS\_RESTART\_CAUSE: ORDERED  
[1970-01-01 00:00:00.056] - xos.c:3658 INFO:IBOOT startRestartCause: IBOOT\_SW\_RESET  
[1970-01-01 00:00:00.056] - xos.c:3694 INFO:IBOOT PID: CXC1321302/3-R5D  
[1970-01-01 00:00:00.056] - xos.c:3695 INFO:XPL PID: CXC1321812/1-R6A  
[1970-01-01 00:00:00.056] - xos.c:1855 INFO:SYS\_HW\_PID: KRC 161 444/1  
[1970-01-01 00:00:00.056] - xos.c:1855 INFO:SYS\_HW\_REV: R2B  
[1970-01-01 00:00:00.056] - xos.c:1855 INFO:SYS\_HW\_NAME: IRU 2242  
[1970-01-01 00:00:00.056] - xos.c:1855 INFO:SYS\_HW\_DATE: 20160115  
[1970-01-01 00:00:00.056] - xos.c:1855 INFO:SYS\_HW\_SERIAL: D822742997  
[1970-01-01 00:00:00.056] - xdai\_xdos.c:155 INFO:The XPP with XDAI REVISION: CYB10191-R4A  
[1970-01-01 00:00:00.056] - a4ci\_startup /repo/ncixp.build/nci/BCP\_CNH1606396/xp\_bl/xpp\_bl/ecb\_swu/src/mhp\_device.c:663 INFO:1 ports found on 1 primary stations.  
[1970-01-01 00:00:00.056] MHP\_Device /repo/ncixp.build/nci/BCP\_CNH1606396/xp\_bl/xpp\_bl/ecb\_swu/src/mhp\_device.c:663 INFO:1 ports found on 1 primary stations.  
[1970-01-01 00:00:00.056] MHP\_Device /repo/ncixp.build/nci/BCP\_CNH1606396/xp\_bl/xpp\_bl/ecb\_swu/src/mhp\_device.c:883 INFO:Starting Device Driver "UART750", 1  
[1970-01-01 00:00:00.056] MHP\_Device /repo/ncixp.build/nci/BCP\_CNH1606396/xp\_bl/xpp\_bl/ecb\_swu/src/mhp\_device.c:1974 INFO:Initiate MHP Link Status information.  
[1970-01-01 00:00:00.056] XPP\_XHP\_ARM\_LM xhp\_arm\_dev.c:427 INFO:Opening Device Driver "XHP\_ARM\_XDD\_ECP", unit 0  
[1970-01-01 00:00:00.056] XPP\_XHP\_ARM\_LM xhp\_arm\_dev.c:427 INFO:Opening Device Driver "XHP\_ARM\_XDD\_ECP", unit 5  
[1970-01-01 00:00:00.056] XPP\_XHP\_0\_0 xhp\_arm\_dev.c:511 INFO:Starting Device Driver "XHP\_ARM\_XDD\_ECP", unit 0  
[1970-01-01 00:00:00.056] XPP\_XHP\_1\_0 xhp\_arm\_dev.c:511 INFO:Starting Device Driver "XHP\_ARM\_XDD\_ECP", unit 5  
[1970-01-01 00:00:00.056] XDP\_XDMM1 xdmml.c:1390 INFO:Maintenance button found of type MAIN2.  
[1970-01-01 00:00:00.064] main xos.c:2195 INFO:Application IRU with PID CXC1123669%48689be9 is started in SUPERVISORY mode  
[1970-01-01 00:00:00.064] XPP\_XCBC xcbc.c:4604 INFO:User application started. No XP CBCI-AU server XcbcServer started.  
[1970-01-01 00:00:00.156] - xpai\_xos.c:287 INFO:IRU (PID=CXC1123669%48689be9), is RUNNING  
[1970-01-01 00:00:00.156] - xpai\_xos.c:289 INFO:The IRU with XPAI REVISION: CYB10190-R7G  
[1970-01-01 00:00:00.156] - xdai\_xdos.c:155 INFO:The IRU with XDAI REVISION: CYB10191-R4A  
[1970-01-01 00:00:00.160] cfhe cfheProc.cc:57 INFO:SAR:CFHE started  
[1970-01-01 00:00:00.176] startUp delayHandler.cc:337 INFO:initDelayRunner: DelayRtcBusyWait  
[1970-01-01 00:00:00.244] startUp dataBaseLoadSave.cc:679 INFO:HW Data Base loaded.  
[1970-01-01 00:00:01.020] XPP\_HDR\_clk\_hdr\_clk.c:281 INFO:Estimated clock frequency: 368 MHz  
[1970-01-01 00:00:01.864] startUp txEnumsHelper.cc:192 INFO:TxBranchId: Initializing from database.  
[1970-01-01 00:00:01.868] startUp commonTypes.cc:723 INFO:BranchId, initFromDatabase!  
[1970-01-01 00:00:01.868] startUp txModule.cc:69 INFO:There is no /radioWithMassiveAntennas in database, use default value 0  
[1970-01-01 00:00:01.888] startUp dataPortDelayMgr.cc:115 INFO:The number of CPRI links 2  
[1970-01-01 00:00:01.964] maintStateHandler maintStateHandlerProc.cc:43 INFO:There is no /publishTrBci in database, use default value 0  
[1970-01-01 00:00:02.504] startUp ltu983.cc:248 INFO:Programming LTU as free run  
[1970-01-01 00:00:02.596] startUp fpga.c:101 INFO:key = /trxFpga/hwPID not found  
[1970-01-01 00:00:04.188] startUp fpga.c:171 INFO:FPGA Application (CXC 173 7859/1 R3J01 20190123) is loaded and started.  
[1970-01-01 00:00:04.196] startUp deviceIntProcHelper.cc:56 INFO:Added device fpga with trap reg 0x4101 and mask reg 0x4102  
[1970-01-01 00:00:04.204] startUp deviceIntProcHelper.cc:462 INFO:Added callback for interrupt bitNo=30  
[1970-01-01 00:00:04.204] startUp deviceIntProcHelper.cc:462 INFO:Added callback for interrupt bitNo=28  
[1970-01-01 00:00:04.204] startUp deviceIntProcHelper.cc:462 INFO:Added callback for interrupt bitNo=29  
[1970-01-01 00:00:04.312] startUp ltuiServer.cc:576 INFO:Create an instance of LtuiServer.  
[1970-01-01 00:00:04.328] startUp linkCtrlCpriWarp30.cc:154 INFO:Delaying for 400 ms before starting RICR  
[1970-01-01 00:00:04.732] startUp ricrai.c:4406 INFO:HRICR not found!  
[1970-01-01 00:00:04.736] HRICR hrircr\_config.c:2752 INFO:IRU 2242 detected. Modifying gtx configuration.  
[1970-01-01 00:00:04.736] HRICR hrircr\_config.c:4990 INFO:HRICR Configuration:device type: WARP35; number of logical ports: 2; number of physical ports: 4; min index slave: 1, max index slave: 2, min index master: 1, max index master: 2, preferred index: -; time allowed for FPGA startup: 0 ms; speed setup method: Non-Xilinx; rbs SFP MMI type: RBS6000\_MMI; fpga release number (for alcor): 0; port\_based\_addition\_ecp\_config: 2.  
[1970-01-01 00:00:04.736] HRICR hrircr\_config.c:5006 INFO:HRICR Configuration:cpri\_cfgtx\_invpair: 0x00000000; cpri\_cfgtx\_adj\_mask: 0xfffffc00; cpri\_cfgtx\_adj\_bits[0]: 0x0c00329b; cpri\_cfgtx\_adj\_bits[1]: 0x0c80329b; cpri\_cfgtx\_adj\_bits[2]: 0x00000000; cpri\_cfgtx\_adj\_bits[3]: 0x00000000; cpri\_cfgtx\_adj\_mask: 0x00000000.  
[1970-01-01 00:00:04.736] HRICR hrircr\_config.c:5048 INFO:Port configuration for port 0:port type SFP; bus type I2C; parent -1; children 0x00000004; posterity 0x00000004; root\_parent 0; master\_warp 0; master\_on 0; int\_vector 0; port\_mapping 1; device\_base\_addr 0xa0000000; port\_base\_addr 0x00000000; serdes\_base\_addr 0x00000000; led\_base\_addr 0x00000000; jb\_delay\_factor 0; i2c\_port 3; i2c\_addr 0x51.  
[1970-01-01 00:00:04.736] HRICR hrircr\_config.c:5081 INFO:Port configuration for port 0:power\_enable\_conf.port: 2; power\_enable\_conf.pin: 12; power\_enable\_conf.direction: 0; cfgtx[0]0x00000000; cfgtx[1]0x00000000; cfgtx[2]0x00000000; cfgtx[3]0x00000000; cfrgx[0]0x00000000; cfrgx[1]0x00000000; cfrgx[2]0x00000000; cfrgx[3]0x00000000; ecp\_config[0]0x0f4002d4; ecp\_config[1]0x00000000; ecp\_config[2]0x00000000; local\_cpri\_mode:Ericsson Mode.  
[1970-01-01 00:00:04.736] HRICR hrircr\_config.c:5048 INFO:Port configuration for port 1:port type SFP; bus type I2C; parent -1; children 0x00000008; posterity 0x00000008; root\_parent 1; master\_warp 0; master\_on 0; int\_vector 0; port\_mapping 0; device\_base\_addr 0xa0000000; port\_base\_addr 0x00000000; serdes\_base\_addr 0x00000000; jb\_delay\_factor 0; i2c\_port 2; i2c\_addr 0x51.  
[1970-01-01 00:00:04.736] HRICR hrircr\_config.c:5081 INFO:Port configuration for port 1:power\_enable\_conf.port: 2; power\_enable\_conf.pin: 10; power\_enable\_conf.direction: 0; cfgtx[0]0x00000000; cfgtx[1]0x00000000; cfgtx[2]0x00000000; cfgtx[3]0x00000000; cfrgx[0]0x00000000; cfrgx[1]0x00000000; cfrgx[2]0x00000000; cfrgx[3]0x00000000; ecp\_config[0]0x0f4002e4; ecp\_config[1]0x00000000; ecp\_config[2]0x00000000; local\_cpri\_mode:Ericsson Mode.  
[1970-01-01 00:00:04.736] HRICR hrircr\_config.c:5048 INFO:Port configuration for port 2:port type WARP35; bus type NA; parent 0; children 0x00000000; posterity 0x00000000; root\_parent 0; master\_warp 1; master\_on 0; int\_vector 16; port\_mapping 1; device\_base\_addr 0xa0000000; port\_base\_addr 0x0f400140; serdes\_base\_addr 0x00001878; led\_base\_addr 0x00000590; jb\_delay\_factor 12500; i2c\_port 0; i2c\_addr 0x00.  
[1970-01-01 00:00:04.736] HRICR hrircr\_config.c:5081 INFO:Port configuration for port 2:power\_enable\_conf.port: -1; power\_enable\_conf.pin: -1; power\_enable\_conf.direction: -1; cfgtx[0]0x0c00329b; cfgtx[1]0x0c00329b; cfgtx[2]0x0c00329b; cfgtx[3]0x0c00329b; cfrgx[0]0x00000700; cfrgx[1]0x00000700; cfrgx[2]0x00000700; cfrgx[3]0x00000700; ecp\_config[0]0x0f4002d4; ecp\_config[1]0x0f4002d8;  
[1970-01-01 00:00:04.736] HRICR hrircr\_config.c:5048 INFO:Port configuration for port 3:port type WARP35; bus type NA; parent 1; children 0x00000000; posterity 0x00000000; root\_parent 1; master\_warp 1; master\_on 0; int\_vector 15; port\_mapping 0; device\_base\_addr 0xa0000000; port\_base\_addr 0x0f400028; serdes\_base\_addr 0x00001850; led\_base\_addr 0x0000058c; jb\_delay\_factor 12500; i2c\_port 0; i2c\_addr 0x00.  
[1970-01-01 00:00:04.736] HRICR hrircr\_config.c:5081 INFO:Port configuration for port 3:power\_enable\_conf.port: -1; power\_enable\_conf.pin: -1; power\_enable\_conf.direction: -1; cfgtx[0]0x0c80329b; cfgtx[1]0x0c80329b; cfgtx[2]0x0c80329b; cfgtx[3]0x0c80329b; cfrgx[0]0x00000700; cfrgx[1]0x00000700; cfrgx[2]0x00000700; cfrgx[3]0x00000700; ecp\_config[0]0x0f4002e4; ecp\_config[1]0x0f4002e8;  
[1970-01-01 00:00:04.736] HRICR hrircr\_config.c:5081 INFO:Port configuration for port 3:power\_enable\_conf.port: -1; power\_enable\_conf.pin: -1; power\_enable\_conf.direction: -1; cfgtx[0]0x0c80329b; cfgtx[1]0x0c80329b; cfgtx[2]0x0c80329b; cfgtx[3]0x0c80329b; cfrgx[0]0x00000700; cfrgx[1]0x00000700; cfrgx[2]0x00000700; cfrgx[3]0x00000700; ecp\_config[0]0x0f4002e4; ecp\_config[1]0x0f4002e8;  
[1970-01-01 00:00:05.424] HRICR hrircr.c:8986 INFO:Process HRICR\_hw\_monitor found.  
[1970-01-01 00:00:05.428] startUp ricrai.c:644 INFO:HRICR CYB10173/9 R13HA is started, processName HRICR  
[1970-01-01 00:00:05.428] HRICR hrircr.c:2514 INFO:HRICR conn\_state change: RIHI\_NOT\_CONNECTED->RIHI\_CONNECTED  
[1970-01-01 00:00:05.428] RICR ricr\_config.c:183 INFO:RICR Configuration:no of ports: 2; speed: min index slave: 1, max index slave: 2, min index master: 1 max index master: 2 preferred index: -; Running in application mode  
[1970-01-01 00:00:05.428] RICR\_fault\_handler ricr\_common.c:519 INFO:PROCESS RICR\_fault\_handler started.  
[1970-01-01 00:00:05.524] HRICR hrircr.c:5165 INFO:Wrote SFP info for link 0 to HW log  
[1970-01-01 00:00:05.524] HRICR hrircr.c:5165 INFO:Wrote SFP info for link 1 to HW log  
[1970-01-01 00:00:05.528] RICR\_sup\_link\_0 slave.c:848 INFO:slave\_init: link supervisor for link 0 started  
[1970-01-01 00:00:05.528] RICR\_sup\_link\_1 slave.c:848 INFO:slave\_init: link supervisor for link 1 started  
[1970-01-01 00:00:05.532] startUp ricrai.c:4473 INFO:RICR PID:CYB10173/11-R14HA is started, processName RICR  
[1970-01-01 00:00:05.532] startUp ricrai.c:627 INFO:added internal ricr subscriber, type 0  
[1970-01-01 00:00:05.532] cpriCtrlProc logManager.cc:42 INFO:Receive RICR link status ind:  
linkPort: 0x00  
hfnSync: 0x00  
linkOperational: 0x00  
syncBit: 0x00  
tAdvance: 0x00000000  
refClkPortNo 0 (linkCtrlCpriWarp30.cc:420)  
[1970-01-01 00:00:05.532] cpriCtrlProc logManager.cc:42 INFO: No HFNSYNC either (linkCtrlCpriWarp30.cc:447)  
[1970-01-01 00:00:05.532] cpriCtrlProc linkCtrlCpriWarp30.cc:508 INFO:m\_ricrCpriDetected=0 ltu\_locked\_on\_link=-1 cpriPort[0].linkOperational=0 cpriPort[1].linkOperational=0  
  
[1970-01-01 00:00:05.532] startUp ricrai.c:635 INFO:added internal ricr subscriber, type 5

```
[1970-01-01 00:00:05.536] cpriCtrlProc logManager.cc:42 INFO:Receive RICR link status ind:
    linkPort:      0x01
    hfnSync:       0x00
    linkOperational: 0x00
    syncBit:       0x00
    tAdvance:      0x00000000
    refClkPortNo   0 (linkCtrlCpriWarp30.cc:420)
[1970-01-01 00:00:05.536] cpriCtrlProc logManager.cc:42 INFO:   No HFNSYNC either (linkCtrlCpriWarp30.cc:447)
[1970-01-01 00:00:05.536] cpriCtrlProc linkCtrlCpriWarp30.cc:508 INFO:m_ricrCpriDetected=0 ltu_locked_on_link=-1 cpriPort[1].linkOperational=0 cpriPort[0].linkOperational=0

[1970-01-01 00:00:05.536] cpriCtrlProc linkCtrlCpriBase.cc:118 INFO:Receive RICR link Cascaded ind: cascaded = 0
[1970-01-01 00:00:05.912] startUp channelIf.cc:418 INFO:There is no /radioWithMassiveAntennas in database, use default value 0
[1970-01-01 00:00:09.632] cpriCtrlProc logManager.cc:42 INFO:Receive RICR link status ind:
    linkPort:      0x00
    hfnSync:       0x01
    linkOperational: 0x00
    syncBit:       0x01
    tAdvance:      0x00000000
    refClkPortNo   0 (linkCtrlCpriWarp30.cc:420)
[1970-01-01 00:00:09.632] cpriCtrlProc linkCtrlCpriWarp30.cc:508 INFO:m_ricrCpriDetected=1 ltu_locked_on_link=-1 cpriPort[0].linkOperational=0 cpriPort[1].linkOperational=0

[1970-01-01 00:00:09.636] ltuServer0 ltu983.cc:279 INFO:Programming LTU to lock
[1970-01-01 00:00:09.636] RICR ltui_if.c:320 INFO:server_status = LTUI_LOCKING
[1970-01-01 00:00:09.636] cpriCtrlProc logManager.cc:42 INFO:Receive RICR link status ind:
    linkPort:      0x01
    hfnSync:       0x01
    linkOperational: 0x00
    syncBit:       0x01
    tAdvance:      0x00000000
    refClkPortNo   0 (linkCtrlCpriWarp30.cc:420)
[1970-01-01 00:00:09.636] cpriCtrlProc linkCtrlCpriWarp30.cc:508 INFO:m_ricrCpriDetected=1 ltu_locked_on_link=-1 cpriPort[1].linkOperational=0 cpriPort[0].linkOperational=0

[1970-01-01 00:00:09.636] ltuServer0 ltuiServer.cc:418 INFO:LtuState:FREE_RUN->LOCK_IN_PROGRESS
[1970-01-01 00:00:09.636] ltuServer0 ltuiServer.cc:373 INFO:Lock notification timer started (50 ms)
[1970-01-01 00:00:09.692] ltuServer0 ltuiServer.cc:253 INFO:LtuState:LOCK_IN_PROGRESS->LOCKED
[1970-01-01 00:00:09.692] RICR ltui_if.c:398 INFO:server_status = LTUI_LOCKED
[1970-01-01 00:00:09.692] ltuServer0 ltuiServerBase.cc:233 INFO:Ltu lock event notified
[1970-01-01 00:00:09.756] RICR_sup_link_0 slave.c:2272 INFO:slave_main_loop_code: Link 0 up at 2.5 Gbps (SFP, CPRI rev 3)
[1970-01-01 00:00:09.756] RICR_sup_link_1 slave.c:2272 INFO:slave_main_loop_code: Link 1 up at 2.5 Gbps (SFP, CPRI rev 3)
[1970-01-01 00:00:09.756] cpriCtrlProc logManager.cc:42 INFO:Receive RICR link status ind:
    linkPort:      0x00
    hfnSync:       0x01
    linkOperational: 0x01
    syncBit:       0x01
    tAdvance:      0x00000027
    refClkPortNo   0 (linkCtrlCpriWarp30.cc:420)
[1970-01-01 00:00:09.756] cpriCtrlProc halEventHandler.cc:543 INFO:There is no /groupTempSensorSv in database, use default value 0
[1970-01-01 00:00:09.756] cpriCtrlProc linkCtrlCpriWarp30.cc:508 INFO:m_ricrCpriDetected=1 ltu_locked_on_link=0 cpriPort[0].linkOperational=1 cpriPort[1].linkOperational=0

[1970-01-01 00:00:09.756] cpriCtrlProc dataPortDelayMgr.cc:359 INFO:setDataPortStateParam, mPreviouslinkState=(0)->linkStatus=(1), tAdv=(39), refClock=(0), portNo=(0), syncBit=(1), smgDiffVec[0]=(0),
smgDiffVec[1]=(0), mDllLinkDelayComp=(0), mUllLinkDelayComp=(0)
[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:setTAdvanceUpdate port[0].tAdvanceUpdate:39 (dataPortDelayHandler.cc:298)
[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:Setting data port parameter port[0].tAdvanceDiff:-6 (dataPortDelayHandler.cc:261)
[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:Setting tAdvanceDiff[0] = (-6) (dataPortDelayMgr.cc:903)
[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:Receive RICR link status ind:
    linkPort:      0x01
    hfnSync:       0x01
    linkOperational: 0x01
    syncBit:       0x01
    tAdvance:      0x00000027
    refClkPortNo   0 (linkCtrlCpriWarp30.cc:420)
[1970-01-01 00:00:09.760] cpriCtrlProc linkCtrlCpriWarp30.cc:508 INFO:m_ricrCpriDetected=1 ltu_locked_on_link=0 cpriPort[1].linkOperational=1 cpriPort[0].linkOperational=1

[1970-01-01 00:00:09.760] cpriCtrlProc dataPortDelayMgr.cc:359 INFO:setDataPortStateParam, mPreviouslinkState=(0)->linkStatus=(1), tAdv=(39), refClock=(0), portNo=(1), syncBit=(1), smgDiffVec[0]=(0),
smgDiffVec[1]=(0), mDllLinkDelayComp=(0), mUllLinkDelayComp=(0)
[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:setTAdvanceUpdate port[1].tAdvanceUpdate:39 (dataPortDelayHandler.cc:298)
[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:Setting data port parameter port[1].tAdvanceDiff:-6 (dataPortDelayHandler.cc:261)
[1970-01-01 00:00:09.760] cpriCtrlProc logManager.cc:42 INFO:Setting tAdvanceDiff[1] = (-6) (dataPortDelayMgr.cc:903)
[1970-01-01 00:00:09.788] cpriCtrlProc dataPortDelayMgr.cc:985 INFO:updateSmgOffset: Reference clock was on port(0), cyclesPerFrame=(4915200), cpri0RfsDel=(12), cpri1RfsDel=(12), cpriRfsDiff2Bfn0=(2260),
cpriRfsDiff2Bfn1=(2260), cpriRfsDiff=(4915199), smgDiffVec[0]=(-307200), smgDiffVec[1]=(307200)
[1970-01-01 00:00:09.788] cpriCtrlProc dataPortDelayMgr.cc:1047 INFO:readRfsDiff: cyclesPerFrame=4915200, cpriRfsDiff=4915199, cpriSwapped=1, value=0 BFN0=2260 BFN1=2260
[1970-01-01 00:00:09.836] cpriCtrlProc linkCtrlCpriWarp35.cc:132 INFO:warp35Delay:5548 [0.lns], serdesDelay:(285), jbDelay:(1186), hardDelay:(985), RfsDelay:(2848.307292 + 244.140625), Fsoffset:(0.000000)
[1970-01-01 00:00:09.836] cpriCtrlProc dataPortDelayMgr.cc:1574 INFO:Detected setting nominal BFN delay for the first time. Saving the value nominalInternalBfnDelay=5548
[1970-01-01 00:00:09.884] XPP_XHP_0_0 xhp_arm_cm.c:2322 INFO:Connected.
[1970-01-01 00:00:09.884] XPP_XHP_0_0 xhp_arm_cm.c:1188 INFO:Connected HDLC address: 3
[1970-01-01 00:00:09.908] XPP_XHP_1_0 xhp_arm_cm.c:2322 INFO:Connected.
[1970-01-01 00:00:09.908] XPP_XHP_1_0 xhp_arm_cm.c:1188 INFO:Connected HDLC address: 3
[1970-01-01 00:00:09.908] XPP_XHP_1_0 xhp_arm_cm.c:1188 INFO:Connected HDLC address: 3
[1970-01-01 00:00:11.628] startUp deviceIntProcHelper.cc:56 INFO:Added device warp3 with trap reg 0x54 and mask reg 0x58
[1970-01-01 00:00:11.644] startUp warp3PowerFailure.cc:359 INFO:powerDrop DB parameters: dontRecover = 0, fpgaControl = 0, return48vDelay = 0, doSpikeRecovery = 1, applRestartMethod = 0, ret48RecoveryTimeout = 14
[1970-01-01 00:00:11.644] - warp3PowerFailure.cc:985 INFO:ZI deactivated in FBUF
[1970-01-01 00:00:11.644] - warp3PowerFailure.cc:986 INFO:RUEV:PLD_Z10FF 11782320us
[1970-01-01 00:00:12.200] startUp indicatorForwarding.cc:88 INFO:Initialization of mmiReset indicator forwarding complete
[1970-01-01 00:00:12.216] startUp startUp.cc:347 INFO:HW initialization completed
[1970-01-01 00:00:12.216] startUp startUp.cc:351 INFO:RUEV:HW_INIT 12354557us
[1970-01-01 00:00:12.220] startUp delayHandler.cc:306 INFO:initDelayRunner: DelayFpgaBusyWait
[1970-01-01 00:00:12.220] startUp initFunc.cc:812 INFO:fixPossibleProdDbError
[1970-01-01 00:00:12.220] startUp eqpStartup.cc:140 INFO:EqpStartup initialization start
[1970-01-01 00:00:12.252] startUp rdPoESrv.cc:127 INFO:RJ45 contains Power-On indicating LEDs
[1970-01-01 00:00:12.272] faultManagerProc faultManager.cc:2857 INFO:Set event STARTUP_EVENT to time: 15000[ms], from 0x100070
[1970-01-01 00:00:12.276] ledProc erciMmi.cc:394 INFO:Vii: 0x00200000
[1970-01-01 00:00:12.276] ledProc erciMmi.cc:394 INFO:Vii: 0x00010000
[1970-01-01 00:00:12.276] ledProc erciMmi.cc:394 INFO:Vii: 0x00000010
[1970-01-01 00:00:12.304] startUp externalAlarmSrv.cc:121 INFO:Number of ports: 2
[1970-01-01 00:00:12.308] startUp rdClient.cc:174 INFO:RDCI Version Info - Build:36, Date:2019-02-19, Version:R5C, IWD Version:RDCI_IWD_J
[1970-01-01 00:00:12.344] startUp tddFsmWorkingNotifier.cc:41 INFO:TddFsmWorkingNotifier::subscribeTddFsmWorking()
[1970-01-01 00:00:12.348] startUp rdSwImageXPAIFFile.cc:205 TRACE1:Found SwCompatibilityList.xml file in LMC.<SwCompatibilityList>
    <LmcList>
        <ProdNbr>CXC 1124490/1</ProdNbr>
        <Rev>R2B</Rev>
        <HwList>
            <ListItem>
                <ProdNbr>KRY 901 378/1</ProdNbr>
                <StartRev>PIA</StartRev>
                <StopRev>RIE</StopRev>
            </ListItem>
        </HwList>
    </LmcList>
    </LmcList>
    <LmcList>
        <ProdNbr>CXC 1124490/2</ProdNbr>
        <Rev>R2B</Rev>
        <HwList>
            <ListItem>
                <ProdNbr>KRY 901 378/1</ProdNbr>
                <StartRev>PIA</StartRev>
            </ListItem>
        </HwList>
    </LmcList>
[1970-01-01 00:00:12.360] startUp eqpModule.cc:119 INFO:ExternalAlarmSrvIf Found
[1970-01-01 00:00:12.360] startUp eqpModule.cc:125 INFO:HotSpotSrvIf Found
[1970-01-01 00:00:12.368] startUp eqpStartup.cc:278 INFO:EqpStartup initialization completed successfully
[1970-01-01 00:00:12.368] startUp initFunc.cc:261 INFO:TRx share Module is not started on zero rx radio
[1970-01-01 00:00:12.368] startUp initFunc.cc:299 INFO:There is no /radioWithMassiveAntennas in database, use default value 0
[1970-01-01 00:00:12.372] faultBranchHandlerProc faultBranchHandlerProc.cc:65 INFO:No /capFaultReporting param, probably it is not AAS unit
[1970-01-01 00:00:12.484] startUp sbpsSrvPf5.cc:176 INFO:Expansion Blockinterface not found for A
[1970-01-01 00:00:12.488] startUp sbpsSrvPf5.cc:176 INFO:Expansion Blockinterface not found for B
[1970-01-01 00:00:12.552] startUp paSrvPowerLevellru.cc:91 INFO:powerClassdBm is set to 0
[1970-01-01 00:00:12.556] startUp paSrvPowerLevellru.cc:91 INFO:powerClassdBm is set to 0
[1970-01-01 00:00:12.560] startUp txBrFaultAdvisor.cc:122 INFO:There is no /radioWithMassiveAntennas in database, use default value 0
[1970-01-01 00:00:12.560] startUp txBrFaultAdvisor.cc:122 INFO:There is no /radioWithMassiveAntennas in database, use default value 0
[1970-01-01 00:00:12.572] startUp txBackoffCtrl.cc:218 INFO:TxBackoffCtrl[TxBackoffCtrlA] locate CavFilterProtectSrv failed
[1970-01-01 00:00:12.572] startUp txBackoffCtrl.cc:218 INFO:TxBackoffCtrl[TxBackoffCtrlB] locate CavFilterProtectSrv failed
[1970-01-01 00:00:12.616] startUp overTempSrvBase.cc:182 INFO:Init of fault suppression map will be done at first temp supervision data request. sensor: RxTemp
[1970-01-01 00:00:12.616] startUp overTempSrvBase.cc:182 INFO:Init of fault suppression map will be done at first temp supervision data request. sensor: TDpa
[1970-01-01 00:00:12.624] startUp txBackoffCtrl.cc:324 INFO:Periodic handling of back-off started for branch: A. period: 5000
[1970-01-01 00:00:12.628] startUp txBackoffCtrl.cc:324 INFO:Periodic handling of back-off started for branch: B. period: 5000
[1970-01-01 00:00:12.632] startUp sbpsSrvPf5.cc:572 INFO:autoGet on key //sbpsCapable returns:0
[1970-01-01 00:00:12.632] startUp sbpsSrvPf5.cc:572 INFO:autoGet on key //sbpsCapable returns:0
[1970-01-01 00:00:12.632] startUp timeoutFilter.cc:507 INFO:Found TimeoutScheduler instance 49243560
[1970-01-01 00:00:12.700] startUp initFunc.cc:349 INFO:Tx::ServiceStartup completed successfully
[1970-01-01 00:00:12.972] startUp rxDesenseService.cc:137 INFO:desenseService A created
[1970-01-01 00:00:12.984] startUp rxDesenseService.cc:137 INFO:desenseService B created
[1970-01-01 00:00:14.576] startUp equalizerComm.cc:152 INFO:Equalizer initialized (numTaps:15, samplFreq:7.68MHz, start-endFreq:-2.50-2.50MHz, numPoints:26)
[1970-01-01 00:00:14.576] startUp ricrai.cc:623 INFO:added internal ricr subscriber, type 1
[1970-01-01 00:00:14.576] cpriCtrlProc linkCtrlCpriBase.cc:308 INFO:RICRAI_UPDATE_DELAY2_IND,recToReDelay:0, portNo:0
[1970-01-01 00:00:14.576] cpriCtrlProc warp3U1DelayBlock.cc:143 INFO:Setting bfnTimeDelay: 0, maxBfnTime: 307200
[1970-01-01 00:00:14.576] startUp rxFaultAdvisorBranchCtrl.cc:76 INFO:There is no /radioWithMassiveAntennas in database, use default value 0
[1970-01-01 00:00:14.576] cpriCtrlProc linkCtrlCpriBase.cc:308 INFO:RICRAI_UPDATE_DELAY2_IND,recToReDelay:0, portNo:1
```

[1970-01-01 00:00:14.580] startUp rxFaultAdvisorBranchCtrl.cc:76 INFO:There is no /radioWithMassiveAntennas in database, use default value 0

[1970-01-01 00:00:14.584] startUp rxLoServiceIruAnalog.cc:79 INFO:Subscription for freqSet successful for branch A

[1970-01-01 00:00:14.584] startUp rxLoServiceIruAnalog.cc:79 INFO:Subscription for freqSet successful for branch B

[1970-01-01 00:00:14.584] startUp rxNcoServiceIru.cc:90 INFO:/rxA/IntermediateFreq/range:39000 80000

[1970-01-01 00:00:14.588] startUp rxNcoServiceIru.cc:90 INFO:/rxB/IntermediateFreq/range:39000 80000

[1970-01-01 00:00:14.704] startUp rxAgcMainServiceDbAccess.cc:1138 INFO:Missing /rxA/AgcMainService/narrow or /rx/AgcMainService/narrow parameter

[1970-01-01 00:00:14.728] startUp rxAgcMainServiceDbAccess.cc:1138 INFO:Missing /rxB/AgcMainService/narrow or /rx/AgcMainService/narrow parameter

[1970-01-01 00:00:14.736] startUp rxAgcGainCompensationService.cc:790 INFO:Missing optional DB parameter /ul/aCompGainDefault

[1970-01-01 00:00:14.736] startUp logManager.cc:42 INFO:Missing optional DB parameter /ul/gSupGainCompOffset (rxAgcGainCompensationService.cc:803)

[1970-01-01 00:00:14.744] startUp rxAgcGainCompensationService.cc:790 INFO:Missing optional DB parameter /ul/aCompGainDefault

[1970-01-01 00:00:14.744] startUp logManager.cc:42 INFO:Missing optional DB parameter /ul/gSupGainCompOffset (rxAgcGainCompensationService.cc:803)

[1970-01-01 00:00:14.752] startUp rxDynAgcServiceWxx.cc:226 INFO:AGC dynamic release is enabled

[1970-01-01 00:00:14.760] startUp rxDynAgcServiceWxx.cc:226 INFO:AGC dynamic release is enabled

[1970-01-01 00:00:14.768] startUp timeoutFilter.cc:507 INFO:Found TimeoutScheduler instance 49283352

[1970-01-01 00:00:14.768] startUp rxDiagService.cc:113 INFO:Found TimeoutFilter instance 2flaal0

[1970-01-01 00:00:14.768] startUp rxDiagService.cc:113 INFO:Found TimeoutFilter instance 2flaal0

[1970-01-01 00:00:14.768] startUp rxCbrsMeasServiceIru.cc:73 INFO:Subscription for rxCbrsMeas successful for branch A

[1970-01-01 00:00:14.768] startUp rxCbrsMeasServiceIru.cc:73 INFO:Subscription for rxCbrsMeas successful for branch B

[1970-01-01 00:00:14.788] startUp initFunc.cc:407 INFO:Rx::ServiceStartUp completed successfully

[1970-01-01 00:00:14.820] startUp antennaModule.cc:165 INFO:ABN: Failed to connect powerDropService

[1970-01-01 00:00:14.832] startUp ricrai.c:719 INFO:added internal ricr subscriber, type 7

[1970-01-01 00:00:14.836] startUp halEventHandler.cc:193 INFO:No shareLocalFaultId value in database

[1970-01-01 00:00:14.840] startUp crhTpaCarrierList.cc:48 INFO:Number of TxBranches = 2

[1970-01-01 00:00:14.840] startUp crhCarrierCtrl.cc:2817 INFO:Overbooking support is enabled. Overbooking value: 0 mW

[1970-01-01 00:00:14.840] startUp carrierListHandler.cc:89 INFO:Register legacy subscriber: cfhe

[1970-01-01 00:00:14.840] startUp carrierListHandler.cc:89 INFO:Register legacy subscriber: FmEventSubscriber

[1970-01-01 00:00:14.844] startUp carrierListHandler.cc:89 INFO:Register legacy subscriber: rmc

[1970-01-01 00:00:14.844] startUp txModule.cc:1665 INFO:TxModule>>TxModule::subscribeSetFsInfo

[1970-01-01 00:00:14.844] startUp txTimingPhaseCtrl.cc:2259 INFO:TxModule>>TxTimingPhaseCtrl::subscribeFsInfo

[1970-01-01 00:00:14.844] startUp txModule.cc:1665 INFO:TxModule>>TxModule::subscribeSetFsInfo

[1970-01-01 00:00:14.844] startUp txTimingPhaseCtrl.cc:2259 INFO:TxModule>>TxTimingPhaseCtrl::subscribeFsInfo

[1970-01-01 00:00:14.844] startUp txModule.cc:1685 INFO:TxModule>>TxModule::subscribeSetTimingInfo

[1970-01-01 00:00:14.844] startUp txTimingPhaseCtrl.cc:2268 INFO:TxModule>>TxTimingPhaseCtrl::subscribeTimingInfo

[1970-01-01 00:00:14.844] startUp txModule.cc:1685 INFO:TxModule>>TxModule::subscribeSetTimingInfo

[1970-01-01 00:00:14.844] startUp txTimingPhaseCtrl.cc:2268 INFO:TxModule>>TxTimingPhaseCtrl::subscribeTimingInfo

[1970-01-01 00:00:14.844] startUp txBroker.cc:196 INFO:subscribe to LTUI Server

[1970-01-01 00:00:14.844] TxBranchCtrlA txBranchCtrl\_main.cc:322 INFO:RUEV:LTU\_LOCKED 14982328us is locked

[1970-01-01 00:00:14.844] TxBranchCtrlA txChangeCycleFsm.cc:1246 INFO:TX\_CHANGE\_CYCLE\_STATE\_IDLE, doEvaluateBufferedEvents()

[1970-01-01 00:00:14.844] TxBranchCtrlA txBrFaultAdvisor.cc:1377 INFO:handleLtuEvent(LtuModeEventEnumType p\_ltuEvent(1)) m\_ltuLocked(1)

[1970-01-01 00:00:14.844] TxBranchCtrlB txBranchCtrl\_main.cc:322 INFO:RUEV:LTU\_LOCKED 14982910us is locked

[1970-01-01 00:00:14.844] TxBranchCtrlB txChangeCycleFsm.cc:1246 INFO:TX\_CHANGE\_CYCLE\_STATE\_IDLE, doEvaluateBufferedEvents()

[1970-01-01 00:00:14.844] TxBranchCtrlB txBrFaultAdvisor.cc:1377 INFO:handleLtuEvent(LtuModeEventEnumType p\_ltuEvent(1)) m\_ltuLocked(1)

[1970-01-01 00:00:14.848] startUp objectStartUp.cc:112 INFO:objectStartUp completed successfully for resource

[1970-01-01 00:00:14.952] rdsDciProc ccieRdsDcInterface.cc:338 INFO:SAR:Published interface: rdsDcServer(0x1000bb) and RDS-DCI(highestProtocolRev:2),dispatchPid\_: 0x10007c

[1970-01-01 00:00:14.968] bcProc ccieLteInterface.cc:108 INFO:SAR:Published interface: BcServer(0x1000dd) and BCI(highestProtocolRev:3(0x3),proto\_basic:0,proto\_spec:3),dispatchPid\_: 0x100074

[1970-01-01 00:00:14.968] bcProc bcRu.cc:356 INFO:IRU 2242 SW started

[1970-01-01 00:00:14.968] bcProc bcRu.cc:303 INFO:Starting O&M interfaces

[1970-01-01 00:00:14.976] antpServerProc\_ antennaModule.cc:1170 INFO:Executing setCurrentMeasurementListener

[1970-01-01 00:00:14.976] antpServerProc\_ ccieLteInterface.cc:108 INFO:SAR:Published interface: antpServer(0x1000e0) and ANTPI(highestProtocolRev:4(0x4),proto\_basic:0,proto\_spec:4),dispatchPid\_: 0x1000df

[1970-01-01 00:00:15.084] chcRuProc ccieInterface.cc:113 INFO:SAR:Published interface: XhcBcServer(0x1000e2) and RRU-CBCI(highestProtocolRev:267),dispatchPid\_: 0x100075

[1970-01-01 00:00:15.480] HRICR\_hw\_monitor sfp\_monitor.c:2369 INFO:SFP fault supervision initialized for port 0

[1970-01-01 00:00:15.736] rdcisim0 rdcisimServer.cc:44 INFO:\*\*\*\*\* RDCI SIM Forwarder started \*\*\*\*\*

[1970-01-01 00:00:15.736] rdcisim0 rdcisimServer.cc:45 INFO:RDCI Version Info - Build:36, Date:2019-02-19, Version:R5C, IWD Version:RDCI\_IWD\_J

[1970-01-01 00:00:15.836] RdPoESrv rdPoESrv.cc:316 INFO:Number of newly detected Rds: 1

[1970-01-01 00:00:15.836] RdPoESrv rdPoESrv.cc:317 INFO:Newly detected RdPorts: 1

[1970-01-01 00:00:15.836] RdEqpCtrl rdEqpCtrl.cc:590 INFO:Setting RD(RdPort:1) as starting

[1970-01-01 00:00:15.840] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:674 INFO:RdEqp Event Report RdPort:1, RD Connected

[1970-01-01 00:00:15.840] RdPoESrv rdPoESrv.cc:644 INFO:Power on RdPort 1

[1970-01-01 00:00:15.908] RdEqpCtrl rdCableSrv.cc:812 INFO:Tx unmuted on RD port 1

[1970-01-01 00:00:15.912] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:HUNT\_RD\_SERVER transactionId:65535

[1970-01-01 00:00:15.912] XPP\_XCM xcm\_device.c:550 INFO:Opening Device Driver "RDDEV", 0

[1970-01-01 00:00:15.924] RdClient0 rdLinkConnectionManager.cc:270 INFO:Set MODEM CARRIER\_FREQ to 230 MHz for RdId:0, RdPort:1

[1970-01-01 00:00:15.924] XPP\_XCM xcm\_device.c:637 INFO:Starting Device Driver "RDDEV", 0

[1970-01-01 00:00:16.976] RdClient0 rdBaseMessageHandler.cc:136 INFO:HUNT\_RD\_SERVER\_SIG transaction id 65535

[1970-01-01 00:00:16.976] rdcisim0 rdcisimServer.cc:290 INFO:\*\*\*\* Forwarding to PID 0x1000ec for RD0 \*\*\*\*

[1970-01-01 00:00:16.976] rdcisim0 rdcisimServer.cc:323 INFO:\*\*\*\* Connecting client PID 0x10009b to server PID 0x1000ec for RD0 \*\*\*\*

[1970-01-01 00:00:17.096] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_UTC transactionId:2

[1970-01-01 00:00:17.156] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:3

[1970-01-01 00:00:17.228] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SUBSCRIBE\_FAULTS transactionId:4

[1970-01-01 00:00:17.304] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BOARD\_CAP\_EXCHANGE transactionId:5

[1970-01-01 00:00:17.392] RdClient0 rdBoardSrv.cc:2053 INFO:Response for RdPort:1 to get Board Capability Req:CFM\_MSG

[1970-01-01 00:00:17.476] RdClient0 rdSwLoadingSrvBase.cc:270 TRACE1:Received GET\_HW\_PID callback

[1970-01-01 00:00:17.476] RdClient0 rdSwLoadingSrvBase.cc:538 INFO:Using default load module 'CXC 112 4419/5' from HW PID

[1970-01-01 00:00:17.476] RdClient0 rdSwImage.cc:297 TRACE1:Looking for RdImage with loadId: 'CXC 112 4419/5'

[1970-01-01 00:00:17.476] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 6, handle 1)

[1970-01-01 00:00:17.476] RdClient0 rdSwImage.cc:370 TRACE1:Comparing loadId(CXC 112 4419/5) softwareName(CXC 112 4419/2)

[1970-01-01 00:00:17.476] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 7, handle 1)

[1970-01-01 00:00:17.476] RdClient0 rdSwImage.cc:370 TRACE1:Comparing loadId(CXC 112 4419/5) softwareName(CXC 112 4419/5)

[1970-01-01 00:00:17.476] RdClient0 rdSwImage.cc:407 TRACE1: Found match in LMC/Rootfs with 'CXC 112 4419/5' rev 'R2U200'

[1970-01-01 00:00:17.476] RdClient0 rdSwImage.cc:243 TRACE1:Revision found ' CXC 112 4419/5'

[1970-01-01 00:00:17.476] RdClient0 rdSwLoadingSrvBase.cc:1245 INFO:RD boardOperationalCapability.upgradableDesignDB == 1: RdPort: '1'

[1970-01-01 00:00:17.476] RdClient0 rdSwLoadingSrvBase.cc:1825 INFO:hwPidCapability.productRevision: R1A

[1970-01-01 00:00:17.476] RdClient0 rdSwLoadingSrvBase.cc:1477 INFO:Found Match for prodNum KRY 901 390/1, prodNubRev R1A, matching dbProdNum CXC 1124505/1.

[1970-01-01 00:00:17.476] RdClient0 rdSwImage.cc:297 TRACE1:Looking for RdImage with loadId: 'CXC 1124505/1'

[1970-01-01 00:00:17.480] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 10, handle 1)

[1970-01-01 00:00:17.480] RdClient0 rdSwImage.cc:370 TRACE1:Comparing loadId(CXC 1124505/1) softwareName(CXC 1124490/1)

[1970-01-01 00:00:17.480] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 11, handle 1)

[1970-01-01 00:00:17.480] RdClient0 rdSwImage.cc:370 TRACE1:Comparing loadId(CXC 1124505/1) softwareName(CXC 1124490/2)

[1970-01-01 00:00:17.480] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 12, handle 1)

[1970-01-01 00:00:17.480] RdClient0 rdSwImage.cc:370 TRACE1:Comparing loadId(CXC 1124505/1) softwareName(CXC 1124497/1)

[1970-01-01 00:00:17.480] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 13, handle 1)

[1970-01-01 00:00:17.480] RdClient0 rdSwImage.cc:370 TRACE1:Comparing loadId(CXC 1124505/1) softwareName(CXC 1124504/1)

[1970-01-01 00:00:17.480] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 14, handle 1)

[1970-01-01 00:00:17.480] RdClient0 rdSwImage.cc:370 TRACE1:Comparing loadId(CXC 1124505/1) softwareName(CXC 1124505/1)

[1970-01-01 00:00:17.480] RdClient0 rdSwImage.cc:392 TRACE1:Comparing rev(R1F) with rdImageHeader->r\_state(R1F)

[1970-01-01 00:00:17.480] RdClient0 rdSwImage.cc:407 TRACE1: Found match in LMC/Rootfs with 'CXC 1124505/1' rev 'R1F'

[1970-01-01 00:00:17.480] RdClient0 rdSwImage.cc:243 TRACE1:Revision found ' RIF CXC 1124505/1'

[1970-01-01 00:00:17.480] RdClient0 rdSwLoadingSrvBase.cc:1865 INFO:Add RD DB to loadingData

[1970-01-01 00:00:17.480] RdClient0 rdSwLoadingSrvBase.cc:778 TRACE1:Initializing RD image of type 'APP' (load module: CXC 112 4419/5).

[1970-01-01 00:00:17.480] RdClient0 rdSwImage.cc:297 TRACE1:Looking for RdImage with loadId: 'CXC 112 4419/5'

[1970-01-01 00:00:17.480] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 6, handle 1)

[1970-01-01 00:00:17.480] RdClient0 rdSwImage.cc:370 TRACE1:Comparing loadId(CXC 112 4419/5) softwareName(CXC 112 4419/2)

[1970-01-01 00:00:17.480] RdClient0 rdSwImageXPAIFile.cc:165 INFO:imageFileOpen Index 7, handle 1)

[1970-01-01 00:00:17.480] RdClient0 rdSwImage.cc:370 TRACE1:Comparing loadId(CXC 112 4419/5) softwareName(CXC 112 4419/5)

[1970-01-01 00:00:17.480] RdClient0 rdSwImage.cc:407 TRACE1: Found match in LMC/Rootfs with 'CXC 112 4419/5' rev 'R2U200'

[1970-01-01 00:00:17.484] RdClient0 rdSwLoadingSrvBase.cc:811 TRACE1:Sending RD\_LOAD\_LMC\_INIT with load module name 'CXC 112 4419/5\_R2U200'

[1970-01-01 00:00:17.552] RdClient0 rdSwLoadingSrvBase.cc:366 TRACE1:Received LOAD\_LMC\_INIT callback

[1970-01-01 00:00:17.620] RdClient0 rdSwLoadingSrvBase.cc:434 TRACE1:Received LOAD\_LMC\_END callback

[1970-01-01 00:00:17.620] RdClient0 rdSwLoadingSrvBase.cc:965 TRACE1:legacy behaviour, SWApp is Running for (RdPort: 1).

[1970-01-01 00:00:17.620] RdClient0 rdSwLoadingSrvBase.cc:1323 INFO:Design DB is not in expected state. (RdPort 1) restartAttempts 0

[1970-01-01 00:00:17.620] RdClient0 rdSwLoadingSrvBase.cc:191 TRACE1:Setting currentSwLoading index to 0

[1970-01-01 00:00:17.620] RdClient0 rdSwLoadingSrvBase.cc:1070 TRACE1:SW loading check completed for RdPort:1

[1970-01-01 00:00:17.620] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BRANCH\_CAP transactionId:9

[1970-01-01 00:00:17.620] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:GET\_BRANCH\_CAP transactionId:10

[1970-01-01 00:00:17.628] TxBackoffCtrlA overTempSrvBase.cc:526 INFO:Subscription for temperatureSvData not done. Sensor: RxTemp

[1970-01-01 00:00:17.628] TxBackoffCtrlA overTempSrvBase.cc:526 INFO:Subscription for temperatureSvData not done. Sensor: TDpa

[1970-01-01 00:00:17.628] TxBackoffCtrlA overTempSrvBase.cc:526 INFO:Subscription for temperatureSvData not done. Sensor: TDpa\_A

[1970-01-01 00:00:17.628] TxBackoffCtrlA overTempSrvBase.cc:526 INFO:Subscription for temperatureSvData not done. Sensor: Tmpa

[1970-01-01 00:00:17.628] TxBackoffCtrlA overTempSrvBase.cc:526 INFO:Subscription for temperatureSvData not done. Sensor: Tmpa\_A

[1970-01-01 00:00:17.800] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:55 INFO:capId=10(RDCI\_CAP\_BRANCH\_CARRIER\_DATA),carrierDataRequired=1,txLoMode=IBW

[1970-01-01 00:00:17.800] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:222 INFO:capId=1(RDCI\_CAP\_BRANCH\_BAND\_INFO),duplexMode=0(RDCI\_DUPLEX\_MODE\_FDD),band=BandIII

[1970-01-01 00:00:17.804] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:234

INFO:capId=2(RDCI\_CAP\_BRANCH\_TX\_FREQUENCY)RfMin=18050000,RfMax=18800000,IfMin=1100000,IfMax=1500000,InvSpectrum=0,StepSize=10,RfTuneMin=18050000,RfTuneMax=18800000,RfTuneCoupled=3,Ibw=400000

[1970-01-01 00:00:17.804] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:256

INFO:capId=3(RDCI\_CAP\_BRANCH\_RX\_FREQUENCY)RfMin=17100000,RfMax=17850000,IfMin=400000,IfMax=800000,InvSpectrum=0,StepSize=10,RfTuneMin=17100000,RfTuneMax=17850000,RfTuneCoupled=3,Ibw=400000

[1970-01-01 00:00:17.804] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:278

INFO:capId=4(RDCI\_CAP\_BRANCH\_CABLE\_LOSS\_COMP),fskModemOutputPower=-1561,minILThreshold=240,maxILThreshold=4590,catFrequencySelect=1300000

[1970-01-01 00:00:17.804] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:293 INFO:capId=5(RDCI\_CAP\_BRANCH\_RX\_GAIN),nominalGain=3650,noiseFigure=0

[1970-01-01 00:00:17.804] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:306 INFO:capId=6(RDCI\_CAP\_BRANCH\_TX\_POWER),txPar=750,txPowerClassUsage=1700

[1970-01-01 00:00:17.804] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:320 INFO:capId=7(RDCI\_CAP\_BRANCH\_TX\_GAIN\_ADJUST),txGainAdjustHi=0,txGainAdjustLo=-1000

[1970-01-01 00:00:17.804] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:333 INFO:capId=8(RDCI\_CAP\_BRANCH\_RX\_AGC),rxAgcMode=0,rxAgcDefault=0

[1970-01-01 00:00:17.804] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:352 INFO:capId=9(RDCI\_CAP\_BRANCH\_TX\_POWER\_MEAS),txPowerMeasMode=2,txMaxPowerBackoff=-10000

[1970-01-01 00:00:17.804] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:366 INFO:capId=10(RDCI\_CAP\_BRANCH\_CARRIER\_DATA),carrierDataRequired=1,txLoMode=IBW

[1970-01-01 00:00:17.804] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:387 INFO:capId=11(RDCI\_CAP\_BRANCH\_WCDMA\_DESENSE),desenseGainRebalance=24 dB

[1970-01-01 00:00:17.976] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:55 INFO:,noCap=11,branchId=B

[1970-01-01 00:00:17.976] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:222 INFO:capId=1(RDCI\_CAP\_BRANCH\_BAND\_INFO),duplexMode=0(RDCI\_DUPLEX\_MODE\_FDD),band=BandIII

[1970-01-01 00:00:17.976] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:234

INFO:capId=2(RDCI\_CAP\_BRANCH\_TX\_FREQUENCY)RfMin=18050000,RfMax=18800000,IfMin=1100000,IfMax=1500000,InvSpectrum=0,StepSize=10,RfTuneMin=18050000,RfTuneMax=18800000,RfTuneCoupled=3,Ibw=400000

[1970-01-01 00:00:17.976] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:256

INFO:capId=3(RDCI\_CAP\_BRANCH\_RX\_FREQUENCY)RfMin=17100000,RfMax=17850000,IfMin=400000,IfMax=800000,InvSpectrum=0,StepSize=10,RfTuneMin=17100000,RfTuneMax=17850000,RfTuneCoupled=3,Ibw=400000

[1970-01-01 00:00:17.976] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:278

INFO:capId=4(RDCI\_CAP\_BRANCH\_CABLE\_LOSS\_COMP),fskModemOutputPower=-1752,minILThreshold=240,maxILThreshold=4590,catFrequencySelect=1300000

[1970-01-01 00:00:17.976] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:293 INFO:capId=5(RDCI\_CAP\_BRANCH\_RX\_GAIN),nominalGain=3650,noiseFigure=0

[1970-01-01 00:00:17.976] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:306 INFO:capId=6(RDCI\_CAP\_BRANCH\_TX\_POWER),txPar=750,txPowerClassUsage=1700

[1970-01-01 00:00:17.976] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:320 INFO:capId=7(RDCI\_CAP\_BRANCH\_TX\_GAIN\_ADJUST), txGainAdjustHi=0, txGainAdjustLo=-1000

[1970-01-01 00:00:17.976] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:333 INFO:capId=8(RDCI\_CAP\_BRANCH\_RX\_AGC), rxAgcMode=0, rxAgcDefault=0

[1970-01-01 00:00:17.976] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:352 INFO:capId=9(RDCI\_CAP\_BRANCH\_TX\_POWER\_MEAS), txPowerMeasMode=2, txMaxPowerBackoff=-10000

[1970-01-01 00:00:17.976] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:366 INFO:capId=10(RDCI\_CAP\_BRANCH\_CARRIER\_DATA), carrierDataRequired=1, txLoMode=IBW

[1970-01-01 00:00:17.976] RdClient0 rdBranchCapabilityCfmMessageHandler.cc:387 INFO:capId=11(RDCI\_CAP\_BRANCH\_WCDMA\_DESENSE), desenseGainRebalance=24 dB

[1970-01-01 00:00:17.976] RdClient0 rdModel.cc:1083 INFO:Consolidated RdId is 0

[1970-01-01 00:00:17.976] RdClient0 rdBoardSrv.cc:1924 INFO:Requesting Time Delay values from RdId:0, RdPort:1

[1970-01-01 00:00:17.976] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:TX\_TIME\_DELAY transactionId:11

[1970-01-01 00:00:17.976] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:TX\_TIME\_DELAY transactionId:12

[1970-01-01 00:00:17.976] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:RX\_TIME\_DELAY transactionId:13

[1970-01-01 00:00:17.976] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:RX\_TIME\_DELAY transactionId:14

[1970-01-01 00:00:17.984] RdClient0 paSrvPowerLevelIru.cc:121 INFO:powerClassdBm is set to 1700

[1970-01-01 00:00:18.008] RdClient0 paSrvPowerLevelIru.cc:121 INFO:powerClassdBm is set to 1700

[1970-01-01 00:00:18.080] RdClient0 rdTxTimeDelayCfmMessageHandler.cc:68 INFO:branch 0 delayRefPath=0

[1970-01-01 00:00:18.144] RdClient0 rdTxTimeDelayCfmMessageHandler.cc:68 INFO:branch 1 delayRefPath=0

[1970-01-01 00:00:18.312] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/dl/rf\_bA/delayReference=0

[1970-01-01 00:00:18.312] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/dl/rf\_bA/delayFreqCompTable\_x=1

[1970-01-01 00:00:18.312] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/dl/rf\_bA/delayFreqCompTable\_y=1

[1970-01-01 00:00:18.312] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/dl/rf\_bB/delayReference=0

[1970-01-01 00:00:18.316] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/dl/rf\_bB/delayFreqCompTable\_x=1

[1970-01-01 00:00:18.316] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/dl/rf\_bB/delayFreqCompTable\_y=1

[1970-01-01 00:00:18.316] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/ul/rf\_bA/delayReference=0

[1970-01-01 00:00:18.316] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/ul/rf\_bA/delayFreqCompTable\_x=1

[1970-01-01 00:00:18.320] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/ul/rf\_bA/delayFreqCompTable\_y=1

[1970-01-01 00:00:18.320] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/ul/rf\_bB/delayReference=0

[1970-01-01 00:00:18.320] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/ul/rf\_bB/delayFreqCompTable\_x=1

[1970-01-01 00:00:18.320] RdClient0 rdBoardSrv.cc:2914 INFO:Created new DB key: /59x/BandIII/ul/rf\_bB/delayFreqCompTable\_y=1

[1970-01-01 00:00:18.320] RdClient0 rdBoardSrv.cc:1807 INFO:send SetTxIfMaxPowerReq with RdPort=1, Br=0, maxPower=-4

[1970-01-01 00:00:18.324] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_TX\_IF\_MAX\_PWR transactionId:15

[1970-01-01 00:00:18.324] RdClient0 rdBoardSrv.cc:1807 INFO:send SetTxIfMaxPowerReq with RdPort=1, Br=1, maxPower=15

[1970-01-01 00:00:18.324] RdClient0 rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_TX\_IF\_MAX\_PWR transactionId:16

[1970-01-01 00:00:18.380] RdClient0 rdBoardSrv.cc:1832 INFO:Response for RdPort:1 to set TxIfMaxPwrDone:CFM\_MSG

[1970-01-01 00:00:18.460] RdClient0 rdBoardSrv.cc:1832 INFO:Response for RdPort:1 to set TxIfMaxPwrDone:CFM\_MSG

[1970-01-01 00:00:18.460] RdClient0 rdBoardSrv.cc:1734 INFO:notifyStartRdDone: 0

[1970-01-01 00:00:18.460] RdEqpCtrl rdEqpCtrl.cc:399 INFO:StartRdDone with RdPort:1

[1970-01-01 00:00:18.460] RdCableSrv.cc:495 INFO:Starting Pair Swap Test with RD PORT list: { 1 }

[1970-01-01 00:00:18.532] RdClient0 rdSwLoadingSrvBase.cc:270 TRACE1:Received GET\_HW\_PID callback

[1970-01-01 00:00:18.532] RdEqpCtrl rdEqpCtrl.cc:963 INFO:pairSwap test done.

[1970-01-01 00:00:18.536] RdEqpCtrl rdCableMeasSvSrv.cc:103 INFO:Starting cable IL measurement with RD PORT list: { 1 }

[1970-01-01 00:00:19.152] RdCableMeasSvSrv rdClientCableMeasurements.cc:213 INFO:A(0mb), B(5480mb), C(224mb) Coefficient was sent to RdPort(1) for branchId(0)

[1970-01-01 00:00:19.152] RdCableMeasSvSrv rdCableILMeasSv.cc:727 INFO:Stored Rx-IL(2857mb) and Tx-IL(4246mb) for RdPort(1) and branchId(0)

[1970-01-01 00:00:19.204] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received CFM\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(1) and Branch(A)

[1970-01-01 00:00:19.240] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received IND\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(1) and Branch(A)

[1970-01-01 00:00:19.828] RdCableMeasSvSrv rdClientCableMeasurements.cc:213 INFO:A(0mb), B(5296mb), C(216mb) Coefficient was sent to RdPort(1) for branchId(1)

[1970-01-01 00:00:19.832] RdCableMeasSvSrv rdCableILMeasSv.cc:727 INFO:Stored Rx-IL(2761mb) and Tx-IL(4103mb) for RdPort(1) and branchId(1)

[1970-01-01 00:00:19.832] RdEqpCtrl rdEqpCtrl.cc:839 INFO:Cable IL Measurement done

[1970-01-01 00:00:19.832] RdEqpCtrl rdCableSrv.cc:680 INFO:Equalizer for RD port 1 set to ON

[1970-01-01 00:00:19.832] RdEqpCtrl rdCableSrv.cc:887 INFO:Rx unmuted on RD port 1

[1970-01-01 00:00:19.832] RdEqpCtrl rdEqpCtrl.cc:860 INFO:Starting AGC test

[1970-01-01 00:00:19.832] RdEqpCtrl rdEqpCtrl.cc:922 INFO:AGC test done

[1970-01-01 00:00:19.832] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:40

[1970-01-01 00:00:19.832] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:2260 INFO:RdEqp Event Report RdPort:1, RD Unlocked

[1970-01-01 00:00:19.832] RdEqpCtrl rdEqpCtrl.cc:1240 INFO:Processing Set Led Action for RdPort:1; LED type is 0

[1970-01-01 00:00:19.832] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:41

[1970-01-01 00:00:19.832] RdEqpFaultCtrl rdActionListUtil.cc:58 INFO:RdEqpEvent:RD Unlocked/RD Locked, RdPort=1 Set LED Action successful;

[1970-01-01 00:00:19.836] rdBcProc0 ccieLteInterface.cc:108 INFO:SAR:Published interface: rd01/BcServer(0x3000ee) and RDBCIO(highestProtocolRev:3(0x3),proto\_basic:0,proto\_spec:3),dispatchPid\_: 0x1000bd

[1970-01-01 00:00:19.836] RdEqpFaultCtrl rdEqpFaultCtrlBase.cc:2260 INFO:RdEqp Event Report RdPort:1, RD Unlocked

[1970-01-01 00:00:19.836] RdEqpCtrl rdEqpCtrl.cc:1240 INFO:Processing Set Led Action for RdPort:1; LED type is 0

[1970-01-01 00:00:19.836] RdEqpCtrl rdClientBoardBase.cc:165 INFO:sendMsg: type:SET\_VISUAL\_INDICATION transactionId:42

[1970-01-01 00:00:19.836] RdEqpFaultCtrl rdActionListUtil.cc:58 INFO:RdEqpEvent:RD Unlocked/RD Locked, RdPort=1 Set LED Action successful;

[1970-01-01 00:00:19.836] rdCbcProc0 ccieInterface.cc:113 INFO:SAR:Published interface: rd01/rdCbcServer(0x3000ef) and RDCBCIO(highestProtocolRev:257),dispatchPid\_: 0x1000bf

[1970-01-01 00:00:19.884] trDcProc ccieLteInterface.cc:108 INFO:SAR:Published interface: radioTrDcServer(0x1000f0) and TR-DCI(highestProtocolRev:65548(0x1000c),proto\_basic:1,proto\_spec:12),dispatchPid\_: 0x1000de

[1970-01-01 00:00:19.916] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received CFM\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(1) and Branch(B)

[1970-01-01 00:00:19.956] RdCableMeasSvSrv rdCableILMeasSv.cc:1250 INFO:Received IND\_MSG response for SET\_IL\_GAIN\_REQ from RdPort(1) and Branch(B)

[1970-01-01 00:00:20.112] tpaProc ccieInterface.cc:113 INFO:SAR:Published interface: tpaCdcIsServer(0x2000f2) and TPA-CDCI(highestProtocolRev:302),dispatchPid\_: 0x1000e7

[1970-01-01 00:00:20.180] almProc ccieInterface.cc:113 INFO:SAR:Published interface: almServer(0x2000f1) and ALM-CDCI(highestProtocolRev:3),dispatchPid\_: 0x1000e8

[1970-01-01 00:00:20.188] trProc ccieInterface.cc:113 INFO:SAR:Published interface: TRX\_CDCI\_FT(0x1000f3) and TR-CDCI(highestProtocolRev:43),dispatchPid\_: 0x1000e3

[1970-01-01 00:00:20.192] dpclProc ccieInterface.cc:113 INFO:SAR:Published interface: dpclServer(0x1000f4) and DPCL-CDCI(highestProtocolRev:11),dispatchPid\_: 0x1000e5

[1970-01-01 00:00:20.200] upmiProc upmiServer.cc:113 INFO:Radio doesn't have current and voltage sensors

[1970-01-01 00:00:20.200] upmiProc upmiServer.cc:116 INFO:PowerConsumptionMeasSrv is not supported on this radio

[1970-01-01 00:00:20.200] upmiProc upmiServer.cc:214 INFO:SAR:Published interface: RBS\_IW\_UPMI(0x1000f5) and UPMI(highestProtocolRev:1)

[1970-01-01 00:00:20.296] rotProc ccieInterface.cc:113 INFO:SAR:Published interface: rotIdcServer(0x2000f7) and ROT-IDCI(highestProtocolRev:65535),dispatchPid\_: 0x1000e4

[1970-01-01 00:00:20.304] aiProc ccieInterface.cc:113 INFO:SAR:Published interface: aiServer(0x2000f6) and AI-CDCI(highestProtocolRev:302),dispatchPid\_: 0x1000e6

[1970-01-01 00:00:24.020] - xhp\_cmd2.c:575 INFO:Enable debug port! You can login now!