

Electrical Machines

Galina Demidova

Assoc. Prof.

demidova@itmo.ru

Dmitry Lukichev


Assoc. Prof.

lukichev@itmo.ru


Alexander Mamatov

Assist. Prof.

amamatov@itmo.ru




Geometry of the magnetic circuit, featuring soft iron (red); a coil (blue); and an AlNiCo-like material (green). The AlNiCo bar is initially nonmagnetic, then magnetized because of an applied current to the coil and demagnetized because of the extraction from the magnetic circuit (arrow).






- ✓ The AlNiCo component starts from a nonmagnetized state and magnetizes because of an applied current to the coil
- ✓ The AlNiCo component is magnetized because of the current of Step 1 and keeps most of its magnetization, even when the coil current is removed
- ✓ The magnetized AlNiCo component gets partially demagnetized when extracted from the core
- ✓ The demagnetized AlNiCo component is brought back in the magnetic circuit, essentially keeping the low magnetic remanent flux from when it was out of the magnetic circuit

H [kA/m]	B [T]
-50 (coercive magnetic field, H _c)	0
-48	0.5
-47	0.7
-46	0.85
-44	0.96
-40	1.03
-35	1.08
-30	1.11
-20	1.155
-10	1.187
0	1.2 (Remanent flux, Br)






Horizontal component of magnetic flux density
in the center of the AlNiCo during the four-step
process






The axial and radial direction are represented by z and r -axes respectively. The magnetization direction of the permanent magnets is shown as black arrows.





Hysteresis loss



$$u_0(t) = U_{0m} \cos \omega t$$

the magnetic flux in core

$$u_0(t) = -e_0(t) = \frac{d\Psi(t)}{dt} = w \frac{d\Phi_0(t)}{dt} = U_{0m} \cos \omega t$$

\Downarrow

$$\Phi_0(t) = \frac{1}{w} \int u_0(t) dt = \frac{U_{0m}}{w} \int \cos \omega t dt = \frac{U_{0m}}{w\omega} \sin \omega t = \Phi_{0m} \sin \omega t$$

crest value emf

$$E_{0m} = U_{0m} = w\omega\Phi_{0m} = w2\pi f\Phi_{0m}$$


root-mean-square value emf

$$E_0 = U_0 = E_{0m} / \sqrt{2} = 4,44wf\Phi_{0m}$$



For the ideal solenoid


$$\Phi_{0m} = \frac{U_0}{4,44wf}$$



Voltage and magnetic flux

The magnetic flux in core

$$\varphi_0 = \arccos\left(\frac{P_0}{U_0 I_{0\vartheta}}\right) < \pi/2$$



$$P_0 = U_0 I_{0a}$$




$$I_{0a} = I_0 \sin \delta = I_0 \cos \varphi_0$$

$$I_{0p} = I_0 \cos \delta = I_0 \sin \varphi_0$$



$$Q_0 = U_0 I_{0p}$$



Hysteresis loss

$$P_{\Gamma} = \eta f B_m^n V$$

η – the core coefficient (depending on material);




f – frequency;

V – core dimension;

B_m – maximum flux density ;

$1,0 < n < 2,0$ – coefficient depending on material and flux density

Eddy current losses



Whirling currents losses

$$P_e = \xi d^2 f^2 B_m^2 V$$


ξ – coefficient depending on conductivity core;

$d \ll b$ – plate core thickness;

f – frequency of magnetic reversals per second (Hz);

V – core dimension;

B_m – maximum flux density



$$P_1 = I^2 R_1 > P_2 = (I/n)^2 R_2 \Rightarrow P_1 / P_2 \approx n^2 \Big|_{R_1 \approx R_2}$$

Thank you!

www.itmo.ru