



| Student # | Name | Signature |
|-----------|------|-----------|
| | | |

| | | |
|--------|--------|-------|
| Q1 40% | Q2 60% | Total |
| | | |

Do not use any reference other than the approved printouts.
Write your name on all answer sheets. Good Luck

A digital combinational lock is designed as shown in the concept design of Figure 1. The keypad module, buzzer (alarm), and the door lock relay modules and their connections to the EDU-PIA are shown in Figure 2.




Figure 1: Digital Combinational Lock Concept

Figure 2: Keypad, Buzzer, Relay modules

During the system tests, it was observed that the buzzer (alarm) is continuously ON, while no key is pressed. The problem is narrowed down to the READKEY subroutine as shown below.

READKEY
REW
Note that after SOLD B is not applied to the port.

KUR E 01111100 ; set carry bit
YUK B %1111 1110 ; apply low to K0
YAZ B PIAPORT
YUK A <PIAPORT>
VE A,\$78
KAR A,\$78
DEE SCAN ; if all rows 1, no key is pressed
YAZ A, ROW ; contains row info
YAZ B, COL ; contains column info
ALT KEY ; branches to KEY subroutine to process ROW and COL info.
DÖN

SCAN
KURE 01111100
SOLD B
KAR B,\$77
DEE READKEY
DAL REW

③ E=1
01111110 11111101
④ VE B,\$7F ⇒ B=01111101
⑤ 01110111 KAR B,\$77

③ scan K1 and K2
VE B,\$7F
KAR B,\$77

①) The problem is K7 is always 1 in this code. Modified as above to fix. Also REW is in the vraypline.
Note: There are multiple solutions. This is what I thought of.

Q1[40pts] Examine the design and the code, and identify the reason of the continuously running alarm. Propose and implement a solution for this problem. Explain your solution. Modify or re-write the READKEY subroutine to fix the problem without changing the hardware.

Q2[60pts] During further tests of the system, it was observed that the keypad erroneously accepts the same key entry multiple times. For example, if user presses Key 5 once, the computer reads multiple 5,5,5,5... mistakenly.

Propose and implement a solution for this problem. Explain your solution. Modify the hardware and software to fix this problem. Write the necessary codes (subroutines etc...) to fix the problem. Indicate the changes in the status/control register, if any. Indicate the changes in hardware connections, if any.

Q2) see the AND Gate in Figure 2
It is connected to the RDY
input. When a key is pressed,
the output of AND (RDY Input)
transitions from 1 \rightarrow 0. This
should generate an interrupt to
scan the columns.

PIA conditioning = 00000010

Set the interrupt vector address
to the READKEY.

NOTE: There are other ways to solve this.

Such as software to detect if the key
is released. It is OK, but risky.

Setting a time delay between keystrokes is
not user friendly. Checking if the consecutive keys are the
same does not work. The code can actually be 5,5,5,5