

# Coordinator (CO) Sequence of Events

## 1. Setup Phase

- Initialize pins, I2C, and serial.
- Set `relayPin` and `fanPin` to OFF.
- Attach interrupt on D2 (`wdAlertPin`) for emergency signal from Watchdog (WD).
- At end of `setup()`, set `coReadyPin` (D6) HIGH to notify WD that CO is ready.

## 2. Serial Command Handling

- `start`:
  - Sets `testRunning = true`
  - Sets `pwmValue = 0`
  - Turns relay ON (load connected)
- `stop`:
  - Stops test
  - Turns relay OFF, fan ON
  - Waits 60 sec, then fan OFF

## 3. Main Loop

- If `emergencyShutdown == true`:
  - Turn relay OFF, fan ON
  - Continue logging sensor data
- If test is running:
  - Sends Vgs PWM to controller
  - Reads Vbus, Vshunt, current, temp
  - Logs all data over serial
  - Increments PWM until max
  - Delays between steps

## 4. Auto-Shutdown (CO-controlled)

- If `current_mA` exceeds limit (e.g., 5000 mA):
  - Same shutdown sequence
  - Continues logging

## 5. Emergency Shutdown (WD-triggered)

- If WD sets D4 HIGH (CO sees rising edge on D2):
  - CO disables load, enables fan
  - Continues logging for diagnostics