

DESIGN OF INDUCTION MOTOR


Construction of Induction Motor

The AC induction motor comprises two electromagnetic parts:

- Stationary part called the stator
- Rotating part called the rotor

The stator and the rotor are each made up of

- An electric circuit, usually made of insulated copper or aluminium winding, to carry current
- A magnetic circuit, usually made from laminated silicon steel, to carry magnetic flux



Stator

The stator is the outer stationary part of the motor, which consists of:

- The outer cylindrical frame of the motor or yoke, which is made either of welded sheet steel, cast iron or cast aluminium alloy.
- The magnetic path, which comprises a set of slotted steel laminations called stator core pressed into the cylindrical space inside the outer frame. The magnetic path is laminated to reduce eddy currents, reducing losses and heating.
- A set of insulated electrical windings, which are placed inside the slots of the laminated stator. The cross-sectional area of these windings must be large enough for the power rating of the motor. For a 3-phase motor, 3 sets of windings are required, one for each phase connected in either star or delta.



Stator laminations



stator core with smooth yoke



Stator with ribbed yoke

Rotor

Rotor is the rotating part of the induction motor. The rotor also consists of a set of slotted silicon steel laminations pressed together to form of a cylindrical magnetic circuit and the electrical circuit. The electrical circuit of the rotor is of the following nature

Squirrel cage rotor consists of a set of copper or aluminium bars installed into the slots, which are connected to an end-ring at each end of the rotor. The construction of this type of rotor along with windings resembles a ‘squirrel cage’. Aluminium rotor bars are usually die-cast into the rotor slots, which results in a very rugged construction. Even though the aluminium rotor bars are in direct contact with the steel laminations, practically all the rotor current flows through the aluminium bars and not in the lamination



Squirrel cage rotor




Slip ring rotor

Wound rotor consists of three sets of insulated windings with connections brought out to three slip rings mounted on one end of the shaft. The external connections to the rotor are made through brushes onto the slip rings. Due to the presence of slip rings such type of motors are called slip ring motors.

Some more parts to complete the constructional details of an induction motor, are:

- Two end-flanges to support the two bearings, one at the driving-end and the other at the non driving-end, where the driving end will have the shaft extension.
- Two sets of bearings to support the rotating shaft,
- Steel shaft for transmitting the mechanical power to the load.
- Cooling fan located at the non driving end to provide forced cooling for the stator and rotor
- Terminal box on top of the yoke or on side to receive the external electrical connections

Cut sectional view of the induction motor




Introduction to Design

The main purpose of designing an induction motor is to obtain the complete physical dimensions of all the parts of the machine as mentioned below to satisfy the customer specifications. The following design details are required.

1. The main dimensions of the stator.
- 2 Details of stator windings.
3. Design details of rotor and its windings
4. Performance characteristics.

Main Dimensions: The armature diameter (stator bore) D and armature core length L are known as the main dimensions of a rotating machine.



Main dimensions D and L

Total Loadings:

Total Magnetic Loading : the total flux around the armature (or stator) periphery at the air gap is called the total magnetic loading.

$$\text{total magnetic loading} = p\phi$$

Total Electric Loading: the total number of ampere conductors around the armature (or stator) periphery is called the total electric loading.

$$\text{total electric loading} = I_z Z$$

Specific Loadings:

Specific Magnetic Loading : the average flux density over the air gap of a machine is known as specific magnetic loading.

specific magnetic loading

$$B_{av} = \frac{\text{total flux around the air gap}}{\text{area of flux path at the air gap}} = \frac{p\phi}{\pi DL}$$

Specific Electric Loading: the number of armature (or stator) ampere conductors per meter of armature (or stator) periphery at the air gap is known as specific electric loading.

specific electric loading

$$ac = \frac{\text{total armature ampere conductors}}{\text{armature periphery at air gap}} = \frac{I_z Z}{\pi D}$$

Output Equation

Let

V_{ph} = phase voltage ;

I_{ph} = phase current

Z_{ph} = no of conductors/phase;

T_{ph} = no of turns/phase

N_s = Synchronous speed in rpm;

n_s = synchronous speed in rps

p = no of poles ;

a_c = Specific electric loading

Φ = air gap flux/pole;

B_{av} = Average flux density

K_w = winding factor ;

η = efficiency

D = Diameter of the stator;

L = Gross core length

C_o = Output coefficient;

$\cos \phi$ = power factor

Consider ‘m’ phase machine, with usual notations
 Output Q in kW = Input \times efficiency

$$\text{Input to motor} = m V_{ph} I_{ph} \cos \varphi \quad * 10^{-3} \text{ kW}$$

For a 3- ϕ machine ‘m’ = 3

$$\text{Input to 3- } \phi \text{ motor} = 3 V_{ph} I_{ph} \cos \varphi \quad * 10^{-3} \text{ kW}$$

$$\begin{aligned} \text{Assuming } V_{ph} &= E_{ph}, \quad V_{ph} = E_{ph} = 4.44 f \Phi T_{ph} K_w \\ &= 2.22 f \Phi Z_{ph} K_w \end{aligned}$$

$$f = P N_s / 120 = P^* n_s / 2$$

$$\text{Output} = 3 \times 2.22 \times P n_s / 2 \times \Phi Z_{ph} K_w I_{ph} \eta \cos \Phi \times 10^{-3} \text{ kW}$$

$$\text{Output} = 1.11 \times P \Phi \times 3 I_{ph} Z_{ph} \times n_s K_w \eta \cos \Phi \times 10^{-3} \text{ kW}$$

$$P\Phi = B_{av} \pi D L, \text{ and } 3I_{ph} Z_{ph} / \pi D = ac$$

$$\text{Output to motor} = 1.11 * B_{av} \pi D L * \pi D ac * n_s K_w \eta \cos \varphi * 10^{-3} \text{ kW}$$

$$Q = (1.11 \pi^2 B_{av} ac K_w \eta \cos \varphi * 10^{-3}) D^2 L n_s \text{ kW}$$

$$Q = (11 B_{av} ac K_w \eta \cos \varphi * 10^{-3}) D^2 L n_s \text{ kW}$$

$$\text{Therefore Output } Q = C_o D^2 L n_s \text{ kW}$$

$$\text{where } C_o = (11 B_{av} ac K_w \eta \cos \varphi * 10^{-3}) = \text{Output coefficient}$$

Choice of Specific Loadings

Specific Magnetic loading or Air gap flux density

- i. Power factor: poor power factor for high flux density in air gap
- ii. Iron loss: iron losses increase with increase in flux density
- iii. Overload capacity: overload capacity increase with increase in flux density

Limitations :

Flux density in teeth < 1.8 Tesla

Flux density in core $1.3 - 1.5$ Tesla

Advantages of Higher value of B_{av}

- Size of the machine reduced
- Cost of the machine decreases
- Overload capacity increases

For 50 Hz machine the value of B_{av} lies between $0.35 - 0.6$ Tesla.

Specific electric loading or ampere conductors per meter

- i. *Copper loss and temperature rise*: a large value of *ac* gives higher copper losses and large temp. rise
- ii. *Voltage*: for high voltage machine value of *ac* should be small
- iii. *Overload capacity*: overload capacity decreased with high value of *ac*.

The value of *ac* depends upon the size of the motor, voltage of stator winding, type of ventilation and overload capacity desired.

It varies between 5000 – 45000 ampere conductors per meter.

Separation of D and L

The output equation gives the relation between D^2L and output of the machine. To separate D and L for this product a relation has to be assumed. Following are the various design considerations based on which a suitable ratio between gross length and pole pitch (L/τ) assumed.

- a) To obtain minimum over all cost 1.5 to 2.0*
- b) To obtain good efficiency 1.4 to 1.6*
- c) To obtain good over all design 1.0 to 1.1*
- d) To obtain good power factor 1.0 to 1.3*

Power factor plays a very important role in the performance of induction motors. Hence to obtain the best power factor the following relation will be usually assumed for separation of D and L.

Pole pitch/ Core length = 0.18/pole pitch

or $(\pi D/p) / L = 0.18 / (\pi D/p)$

i.e $D = 0.135 P \sqrt{L}$

where D and L are in meter.

Peripheral Speed

The obtained values of D and L have to satisfy the condition imposed on the value of peripheral speed.

For the normal design of induction motors the calculated diameter of the motor should be such that the peripheral speed must be below 30 m/s. In case of specially designed rotor the peripheral speed can be 60 m/s.

Stator Design

Stator slots: in general two types of stator slots are employed in induction motors viz, open slots and semi closed slots. Operating performance of the induction motors depends upon the shape of the slots

(i) Open slots: In this type of slots the slot opening will be equal to that of the width of the slots. In such type of slots, assembly and repair of winding are easy. However such slots will lead to higher air gap contraction factor and hence poor power factor.

(ii) Semi closed slots: In such type of slots, slot opening is much smaller than the width of the slot. Hence in this type of slots assembly of windings is more difficult and takes more time compared to open slots and hence it is costlier. However the air gap characteristics are better compared to open type slots.

(iii) Tapered slots: In this type of slots also, opening will be much smaller than the slot width. However the slot width will be varying from top of the slot to bottom of the slot with minimum width at the bottom.

Selection of number of stator slots:

Number of stator slots must be properly selected at the design stage as such this number affects the weight, cost and operating characteristics of the motor. As there are no rules for selecting the number of stator slots, the advantages and disadvantages of selecting higher number slots help to serve as guidelines in the selection. Following are the advantages and disadvantages of selecting higher number of slots.

Advantages :

- (i) Reduced leakage reactance.
- (ii) Reduced tooth pulsation losses.
- (iii) Higher over load capacity.

Disadvantages:

- (i) Increased cost
- (ii) Increased weight
- (iii) Increased magnetizing current
- (iv) Increased iron losses
- (v) Poor cooling
- (vi) Increased temperature rise
- (vii) Reduction in efficiency

The number of slots/pole/phase should not be less than 2 otherwise the leakage reactance becomes high. The number of slots should be selected to give an integral number of slots per pole per phase. The stator slot pitch at the air gap surface should be between 1.5 to 2.5 cm.

Stator slot pitch at the air gap surface = $\tau_{ss} = \pi D / S_{ss}$ where S_{ss} is the number of stator slots

Turns per phase :

EMF equation of an induction motor is given by

$$E_{ph} = 4.44f\Phi T_{ph} K_w$$

Hence turns per phase can be obtained from emf equation

$$T_{ph} = E_{ph} / 4.44f \Phi_m K_w$$

Generally the induced emf can be assumed to be equal to the applied voltage per phase

$$\text{Flux/pole, } \Phi_m = B_{av} * \pi DL/p = B_{av} \tau L, \quad (\tau = \pi D/p)$$

winding factor K_w may be assumed as 0.955 for full pitch distributed winding unless otherwise specified.

Number of conductors /phase, $Z_{ph} = 2 \times T_{ph}$, and hence Total number of stator conductors $Z = 6 * T_{ph}$ and conductors/slot $Z_s = Z/S_s$ or $6 * T_{ph}/S_s$

Conductor cross section:

Area of cross section of stator conductors can be estimated from the stator current per phase and suitably assumed value of current density for the stator windings.

Sectional area of the stator conductor $a_s = I_s / \delta_s$ where δ_s is the current density in stator windings

Stator current per phase $I_s = Q / (3V_{ph} \cos\phi)$

A suitable value of current density has to be assumed considering the advantages and disadvantages.

Advantages of higher value of current density:

- (i) reduction in cross section
- (ii) reduction in weight
- (iii) reduction in cost

Disadvantages of higher value of current density:

- (i) increase in resistance
- (ii) increase in cu loss
- (iii) increase in temperature rise
- (iv) reduction in efficiency

Higher value is assumed for low voltage machines and small machines. Usual value of current density for stator windings is 3 to 5 amps/mm².

Area of stator slot: Slot area is occupied by the conductors and the insulation. Out of which almost more than 25 % is the insulation. Once the number of conductors per slot is decided, approximate area of the slot can be estimated.

Slot space factor = Copper area in the slot / Area of each slot

This slot space factor so obtained will be between 0.25 and 0.4.

Depth of stator core : The flux density in the stator core lie between 1.2 to 1.4 Tesla. The flux passing through the stator core is half of the flux per pole.

Flux in the stator core section $\Phi_c = \frac{1}{2} \Phi$

flux density in the stator core $= B_{cs}$


Area of stator core $A_c = \Phi_c / 2B_{cs}$

Also, area of stator core $A_c = L_i * d_{cs}$

Hence, depth of the core (d_{cs}) $= A_c / L_i = \Phi_c / 2B_{cs} * L_i$

Outer diameter of the stator core

$$\begin{aligned} D_o &= D + 2(\text{depth of stator slots} + \text{depth of core}) \\ &= D + 2 d_{ss} + 2 d_{cs} \end{aligned}$$



Length of the mean Turn:

Length of the mean turn is calculated using formula

$$L_{mt} = 2L + 2.3 \tau + 0.24$$

where L is the gross length of the stator and τ is pole pitch in meter.

Rotor Design


There are two types of rotor construction. One is the squirrel cage rotor and the other is the slip ring rotor. Most of the induction motor are squirrel cage type. These are having the advantage of rugged and simple in construction and comparatively cheaper. However they have the disadvantage of lower starting torque. In this type, the rotor consists of bars of copper or aluminium accommodated in rotor slots. In case slip ring induction motors the rotor complex in construction and costlier with the advantage that they have the better starting torque. This type of rotor consists of star connected distributed three phase windings.

Length of Air-gap

Between stator and rotor is the air gap which is a very critical part. The performance parameters of the motor like magnetizing current, power factor, over load capacity, cooling and noise are affected by length of the air gap.

Power Factor:- the mmf required to send the flux through air gap is proportional to the product of flux density and length of air gap.

fig shows phasor diagrams of an induction motor with two different air gap lengths. With increase in air gap length magnetizing mmf increases and hence greater the magnetizing current. Therefore, the phase angle between applied voltage and stator current will increase which gives low power factor.



Overload Capacity:- overload capacity of induction motor is the ratio of maximum output to rated output and the maximum output is obtained from circle diagram. The diameter of circle diagram is V_s/X_s where X_s is reactance of motor. The length of air gap affects the leakage reactance. If the length of air gap is large, the leakage flux is reduced, hence reduced value of leakage reactance. With decrease in the value of leakage reactance the diameter of circle diagram increases and hence the overload capacity increases.

Pulsation loss:- the tooth pulsation losses, which is produced due to variation in reactance of the air gap, is reduced with large air gap.

Cooling:- the large air gap provide better facilities for cooling at the gap surfaces due to the cylindrical surfaces of stator and rotor are separated by large distance.

Noise:- noise in induction motor reduced with increase in air gap length due to reduction in leakage flux which is the cause of noise.

Hence length of the air gap is selected considering the advantages and disadvantages of larger air gap length.

Advantages:

- (i) Increased overload capacity
- (ii) Increased cooling
- (iii) Reduced unbalanced magnetic pull
- (iv) Reduced in tooth pulsation
- (v) Reduced noise

Disadvantages

- (i) Increased Magnetising current
- (ii) Reduced power factor

Magnetising current and power factor being very important parameters in deciding the performance of induction motors, the induction motors are designed for optimum value of air gap or minimum air gap possible. Hence in designing the length of the air gap following empirical formula is employed.

Air gap length $l_g = 0.2 + 2\sqrt{DL}$ mm

Design of Squirrel Cage Rotor

Number of slots: Proper numbers of rotor slots are to be selected in relation to number of stator slots otherwise undesirable effects will be found at the starting of the motor. Cogging and Crawling are the two phenomena which are observed due to wrong combination of number of rotor and stator slots. In addition, induction motor may develop unpredictable hooks and cusps in torque speed characteristics or the motor may run with lot of noise.

Crawling: The rotating magnetic field produced in the air gap will be usually nonsinusoidal and generally contains odd harmonics of the order 3rd, 5th and 7th. The third harmonic flux will produce the three times the magnetic poles compared to that of the fundamental. Similarly the 5th and 7th harmonics will produce the poles five and seven times the fundamental respectively. The presence of harmonics in the flux wave affects the torque speed characteristics. The motor with presence of 7th harmonics is to have a tendency to run the motor at one seventh of its normal speed.

Cogging: In some cases where in the number of rotor slots are not proper in relation to number of stator slots the machine refuses to run and remains stationary. Under such conditions there will be a locking tendency between the rotor and stator. Such a phenomenon is called cogging.

Hence in order to avoid such bad effects a proper number of rotor slots are to be selected in relation to number of stator slots. In addition rotor slots will be skewed by one slot pitch to minimize the tendency of cogging, torque defects like synchronous hooks and cusps and noisy operation while running. Effect of skewing will slightly increase the rotor resistance and increases the starting torque. However this will increase the leakage reactance and hence reduces the starting current and power factor.

Selection of number of rotor slots: The number of rotor slots may be selected using the following guide lines.

- (i) To avoid cogging and crawling: (a) $S_s \neq S_r$ (b) $S_s - S_r \neq 3P$
- (ii) To avoid synchronous hooks and cusps in torque speed characteristics $S_s - S_r \neq P, 2P, 5P$.
- (iii) To noisy operation $S_s - S_r \neq 1, 2, (P \pm 1), (P \pm 2)$

Rotor Bar Current: Bar current in the rotor of a squirrel cage induction motor may be determined by comparing the mmf developed in rotor and stator. The stator mmf is about 15% higher because of the magnetizing mmf.

Rotor mmf = 0.85 (stator mmf)

Number of rotor bars = $N_b = S_r$ = number of rotor slots

Rotor bar current = I_b

Rotor mmf = $I_b \cdot S_r / 2$

Stator mmf = $3 \cdot I_s \cdot T_s$

Thus $I_b \cdot S_r / 2 = 0.85 (3 \cdot I_s \cdot T_s)$ or $I_b = 0.85 * (6 * I_s * T_s / S_r)$

Cross sectional area of Rotor bar: Sectional area of the rotor conductor can be calculated by rotor bar current and assumed value of current density for rotor bars. As a guide line the rotor bar current density can be assumed between 4 to 7 amp/mm² .

Hence sectional area of the rotor bars can be calculated as

$$a_b = I_b / \delta_b \text{ mm}^2$$

Shape and Size of the Rotor slots: Generally semi-closed slots or closed slots with very small or narrow openings are employed for the rotor slots. In case of fully closed slots the rotor bars are force fit into the slots from the sides of the rotor.

The rotors with closed slots are giving performance to the motor in the following way. (i) As the rotor slot is closed the rotor surface is smooth at the air gap and hence the motor draws lower magnetizing current. (ii) reduced noise as the air gap characteristics are better (iii) increased leakage reactance and (iv) reduced starting current. (v) Over load capacity is reduced (vi) Undesirable and complex air gap characteristics. From the above it can be concluded that semi-closed slots are more suitable and hence are employed in rotors.

Copper loss in rotor bars: Knowing the length of the rotor bars and resistance of the rotor bars c_u losses in the rotor bars can be calculated.

Length of rotor bar $l_b = L + \text{allowance for skewing}$

Rotor bar resistance $= 0.021 \times l_b / a_b$

Copper loss in rotor bars $= I_b^2 \times r_b \times \text{number of rotor bars.}$

End Ring Current: All the rotor bars are short circuited by connecting them to the end rings at both the end rings. As the rotor is a short circuited, there will be current flow because of induced emf in the rotor bars. The distribution of current and end rings are as shown in Fig. Considering the bars under one pole pitch, half of the number of bars and the end ring carry the current in one direction and the other half in the opposite direction. Thus the maximum end ring current may be taken as the sum of the average current in half of the number of bars under one pole.

Maximum end ring current $I_{e(max)}$
 = (Number of bars over half a pole pitch) $I_b(av)$

$$= S_r / 2P * [2/\pi * I_{b(max)}]$$

$$= (S_r * I_{b(max)}) / \pi P$$

rms value of bar current $I_b = I_{b(max)} / \sqrt{2}$

$$I_{e(max)} = (S_r * I_b * \sqrt{2}) / \pi P$$

rms value of end ring current $I_e = I_{e(max)} / \sqrt{2}$

$$I_e = (S_r * I_b) / \pi P$$

Area of end ring: Knowing the end ring


current and assuming suitable value for the

current density in the end rings cross section

for the end ring can be calculated. Current density in the end ring may be assume as 4.5 to 7.5 amp/mm².

Area of each end ring $A_e = I_e / \delta_e \text{ mm}^2$

$A_e = t_e * d_e$ where t_e = thickness of end ring and d_e = depth of end ring



Design of wound Rotor

These are the types of induction motors where in rotor also carries distributed star connected 3 phase winding. At one end of the rotor there are three slip rings mounted on the shaft. Three ends of the winding are connected to the slip rings. External resistances can be connected to these slip rings at starting, which will be inserted in series with the windings which will help in increasing the torque at starting. Such type of induction motors are employed where high starting torque is required.

Number of rotor slots: The number of rotor slots should never be equal to number of stator slots. Generally for wound rotor motors a suitable value is assumed for number of rotor slots per pole per phase, and then total number of rotor slots are calculated. So selected number of slots should be such that tooth width must satisfy the flux density limitation. Semi-closed slots are used for rotor slots.

Number of rotor Turns: The voltage between the slip rings on open circuit must be limited to safety values. In general the voltage between the slip rings for low and medium voltage machines must be limited to 400 volts. For motors with higher voltage ratings and large size motors this voltage must be limited to 1000 volts. Based on the assumed voltage between the slip rings comparing the induced voltage ratio in stator and rotor, the number of turns on rotor winding can be calculated.

$$\text{Voltage ratio } E_r / E_s = (K_{wr} \times T_r) / (K_{ws} \times T_s)$$

$$\text{Hence rotor turns per phase } T_r = (E_r / E_s) (K_{ws} / K_{wr}) T_s$$

E_r = open circuit rotor voltage/phase

E_s = stator voltage /phase

K_{ws} = winding factor for stator

K_{wr} = winding factor for rotor

T_s = Number of stator turns/phase

Rotor Current and conductor section

Assuming rotor mmf = 0.85* stator mmf

$$2 \times 3 \times I_r \cdot T_r = (0.85) 2 \times 3 \times I_s \cdot T_s$$

Rotor current per phase $I_r = (0.85) I_s \cdot T_s / T_r$

Rotor conductor area $A_r = I_r / \delta_r$

The current density could be taken as 3 to 5 A/mm²

Rotor Teeth The flux density in the rotor teeth does not exceed about 1.7 wb/m². The maximum flux density for rotor teeth occurs at their root as their section is minimum there.

Minimum width of rotor teeth $W_{ir(\min)} = \Phi_m / (1.7 \cdot (S_r/p)) \cdot L_i$

Minimum width actually provided should be larger than the value given by above equation.

W_{ir} = rotor slot pitch at the root – rotor slot width = $((D_r - 2d_{sr})/S_r) - W_{sr}$

d_{sr} = depth of rotor slot and W_{sr} = width of rotor slot

Rotor Core

The flux density in the rotor core is generally equal to stator core density.

Depth of rotor core $d_{cr} = \Phi_m / (2 * B_{cr} * L_i)$

B_{cr} = flux density in the rotor core

Inside diameter of rotor lamination

$$D_i = D_r - 2(d_{sr} + d_{cr})$$

Operating Characteristics

No load current: The no load current of an induction motor has two components magnetizing component, I_m and iron loss component, I_w .

Thus the no load current $I_0 = \sqrt{(I_m)^2 + (I_w)^2}$ amps

Magnetising current: Magnetising current of an induction motor is responsible for producing the required amount of flux in the different parts of the machine. Hence this current can be calculated from all the magnetic circuit of the machine. The ampere turns for all the magnetic circuit such as stator core, stator teeth, air gap, rotor core and rotor teeth gives the total ampere turns required for the magnetic circuit. Based on the total ampere turns of the magnetic circuit the magnetizing current can be calculated as

Mmf for air gap

$$B_{g60} = 1.36 B_{av}$$

$$\text{Mmf for air gap } At_g = 800000 B_{g60} K_g L_g$$

Mmf for stator teeth: value of mmf for teeth is found out by finding flux density at a section $1/3$ height of tooth from narrow end.

$$B_{ts1/3} = \Phi_m / (S_s/p) * L_i * W_{ts1/3}$$

Calculation of mmf for teeth is based upon B_{ts60} ; $B_{ts60} = 1.36 B_{ts1/3}$

$$W_{ts1/3} = (\pi (D + 2d_{ss}/3)/S_s) - W_{ss}$$

Mmf per meter at_s for stator teeth is found from B-at curve

$$\text{Mmf required for stator teeth } At_s = at_s \times d_{ss}$$

Mmf for rotor teeth: Flux density in rotor teeth at $1/3$ height from narrow end.

$$B_{tr1/3} = \Phi_m / (S_r/p) * L_i * W_{tr1/3}$$

$$W_{tr1/3} = (\pi (D_r - 2d_{sr}/3)/S_r) - W_{sr}$$

$$B_{tr60} = 1.36 B_{tr1/3}$$

Mmf per meter at_s for rotor teeth is found from B-at curve

$$\text{Mmf required for stator teeth } At_{tr} = at_{tr} \times d_{sr}$$

Mmf for stator core:

Magnetising current $I_m = P \cdot AT_{60} / (2.34 k_w T_{ph})$

where p – no of pairs of poles, AT_{30} – Total ampere turns of the magnetic circuit at 60° from the centre of the pole, T_{ph} – Number of stator turns per phase.

Iron loss component of current: This component of current is responsible for supplying the iron losses in the magnetic circuit. Hence this component can be calculated from no load losses and applied voltage.

Iron loss component of current $I_w = \text{Total no load losses} / (3 \times \text{phase voltage})$

No load Power Factor: No load power factor of an induction motor is very poor. As the load on the machine increases the power factor improves. No load power factor can be calculated knowing the components of no load current.

No load power factor $\cos\phi_0 = I_w / I_0$

Dispersion Coefficient:

Power factor is an important factor in designing of induction motor.

Power factor depends upon two factors:

- i) Magnetizing current :a large value of the magnetizing current indicates poor power factor
- ii) Ideal short circuit current (I_{sc}): it is defined as the current drawn by the motor at standstill neglecting its resistance. A large value of ideal short circuit current will be drawn for small value of leakage reactance giving good power factor.

Dispersion coefficient defined as the ratio of magnetizing current to ideal short circuit current.

Thus dispersion coefficient, $\sigma = I_m/I_{sci}$

$$\begin{aligned} &= I_m / (E_s / X_s) \\ &= I_m \cdot X_s / E_s \end{aligned} \qquad I_{sci} = E_s / X_s$$

For small values of I_m and X_s dispersion coefficient is small and power factor is good. Thus for a small value of dispersion coefficient power factor is good, where as for large value of dispersion coefficient power factor is poor.

Magnetizing current $I_m = P \cdot AT_{60} / (2.34 k_w T_{ph})$

Where AT_{60} is the total mmf consumed by flux path, out of which a large part is consumed by air gap length.

$$AT \text{ air gap} = 800000 * 1.36 * B_{av} l'_g$$

$$I_m \propto P * B_{av} l'_g / K_{ws} \cdot T_s$$

$$I_{sci} = E_s / X_s$$

$$E_s \propto f \Phi_m T_s K_{ws} \alpha f B_{av} \frac{\pi D L}{P} T_s K_{ws} \quad X_s \propto f T_s^2 L \left(\frac{\lambda}{P q_s} \right)$$

$$I_{sci} \propto \frac{B_{av} D K_{ws} q_s}{T_s \lambda}$$

$$\text{thus dispersion coefficient } \sigma = \frac{I_m}{I_{sci}} \propto \frac{P l'_g \lambda}{D K_{ws}^2 q_s}$$

From equation , machine a given L and D, the dispersion coefficient is large for grater number of poles, consequently making power factor poor. Thud slow speed machine have poor power factor.

Effect of dispersion coefficient on induction motor characteristics:

1. Effect on maximum power factor:

As shown in circle diagram

OA=magnetizing current

OB=ideal short circuit current


Dispersion coefficient:

$$\sigma = OA/OB$$

$$\text{maximum power factor} = \cos \phi_{\min} = \frac{DC}{OC} = \frac{AB/2}{OB - AB/2} = \frac{AB}{2OB - AB}$$

For maximum power factor OD is tangent to the circle and

$$\angle ODC = 90^\circ \quad \frac{OB - OA}{OB + OA} = \frac{1 - OA/OB}{1 + OA/OB} = \frac{1 - \sigma}{1 + \sigma}$$



For $\sigma = 0.05$, maximum p.f. = 0.905

For $\sigma = 0.10$, maximum p.f. = 0.818

Hence there is a large decrease in maximum p.f. when the dispersion coefficient increases.

2. *Effect on overload capacity:*

Assuming, an induction motor is designed to have maximum pf at full load, its corresponding output will be DE. The maximum output will be corresponding to FC

$$\begin{aligned}\text{overload capacity} &= \frac{\text{maximum power output}}{\text{full load output}} = \frac{FC}{DE} = \frac{AC}{DC \sin \phi_{\min}} \\ &= \frac{1}{\sin \phi_{\min}} = \frac{1}{\sqrt{1 - (\cos \phi_{\min})^2}} = \frac{1}{\sqrt{1 - \left(\frac{1 - \sigma}{1 + \sigma}\right)^2}} = \frac{1 + \sigma}{2\sqrt{\sigma}}\end{aligned}$$

For $\sigma = 0.05$ overload capacity = 2.348

For $\sigma = 0.10$ overload capacity = 1.740

Hence overload capacity decreases with increase in dispersion coeff.