

CS 4910

Project: Blacktop

TPS Report

2/24/2020

Team:	Skyler Sheler	skyler.j.sheler@wmich.edu	(616) 438-3527
	Erron Johnson	erron.d.johnson@wmich.edu	(269) 547-8933
	Allin Kahrl	f.allin.kahrl@wmich.edu	(207) 522-4859
	Tyler Henniges	tyler.m.henniges@wmich.edu	(269) 330-4229
Client:	WMU Computer Club	colin.c.macreery@wmich.edu	(269) 276-3106
Contact:	Colin MacCreery	colin.c.macreery@wmich.edu	(269) 276-3106
Project Lead	Allin Kahrl	f.allin.kahrl@wmich.edu	(207) 522-4859

Task	Who will complete	Time	Risk 1-10	% complete	Actual time	review
T1	SS	1 hour	1	100%	1 hour	AK TH EJ
T2	SS AK TH EJ	5 hours	3	100%	20 hours	AK TH EJ
T3	SS AK TH EJ	10 hours	3	100%	TBD	TBD
T4	SS AK TH EJ	10 hours	6	75%	TBD	TBD
T5	AK	5 hours	4	25%	TBD	TBD
T6	SS	10 hours	5	100%	10 hours	AK EJ TH
T7	SS AK	5 hours	1	60%	TBD	TBD
T8	EJ TH	1 hour	1	100%	1 hour	SS AK
T9	EJ TH	7 hours	1	100%	7 hours	SS AK
T10	SS AK	3 hours	5	50%	TBD	TBD
T11	TH	4 hours	2	100%	4 hours	TBD

T1: Write the requested deliverables for the week

Write the TPS Report and Stories for the week

- T2: Test the board to see if it can handle all of the peripherals being turned on at once
The maximum current load of the board must be determined, and if turning on all peripherals exceeds that load a failsafe must be developed to prevent the board from breaking.
- T3: Finish breadboarding a prototype board.
The components will have to be socketed into a breadboard and tested for full functionality. This is currently the largest portion of the project to overcome and time specifications will have to be further analyzed.
- T4: Develop drivers using SPI to interface with the on-board EEPROM
Drivers must be developed using a serial peripheral interface to transfer data from the main board to the on-board EEPROM
- T5: Create revision 3 boards after testing the revision 1 and 2 boards.
- T6: Begin Soldering the revision 1 and 2 boards.
Both revision 1 and 2 have been completed, there are minor errors that need to be accounted for.
- T7: Refine the preliminary powerpoint presentation to reflect desired improvements listed by the class
- T8: Fix revision 1 board
A solder bridge and an error in the traces was found in the rev1 board. This will need to be corrected for rev 3 as it is probably present in rev 2. Bodge wire was used to accomplish this
- T9 write a test program for the rev1 board
- T10: Probe the current rev1 and rev2 boards for why the potentiometer does not work.
- T11: Write an additional test program to test the boards.