

- ① A 3ϕ , 10HP, 208V, 6 pole, 60Hz wound-rotor induction machine has a stator to rotor turns ratio of 1:0.5, where both stator and rotor phases are wye-connected. The stator is connected to a 3ϕ , 208V, 60Hz source. The motor runs @ 1140 rpm.
- V_{in} \rightarrow s_s \rightarrow n_m

A) OPERATING SLIP.

$$n_s = \frac{120 f_s}{P} = \frac{120(60)}{6} = 1200 \text{ rpm}$$

$$\Rightarrow s = 1 - \frac{n_m}{n_s} = 1 - \frac{1140}{1200} = \boxed{0.05 \text{ operating slip}}$$

B) PER PHASE ROTOR VOLTAGE (MAG. & FREQ.)

$E_{r,s}$: induced rotor voltage @ slip

E_r : induced rotor voltage

$$\rightarrow E_{r,s} = s E_r = s \frac{E_s}{a} = s \frac{V_{in}}{a\sqrt{3}}$$

(From WYE) $\rightarrow \frac{V_{in}}{\sqrt{3}} = E_s$: "induced" stator voltage.

$$E_{r,s} = \frac{(0.05)(208)}{2\sqrt{3}} = \boxed{3.0V}$$

$$a = \frac{1}{0.5} = 2$$

FREQ

$$\Rightarrow f_r = s f_s = (0.05)(60 \text{ Hz}) = \boxed{3 \text{ Hz}}$$

C) RPM OF ROTOR FIELD w.r.t ROTOR & w.r.t STATOR.

$$\text{ROTOR FIELD w.r.t ROTOR is SLIP RPM} = s n_s = 0.05(1200 \text{ rpm}) = \boxed{60 \text{ rpm}}$$

$$\text{ROTOR FIELD w.r.t STATOR is } \underbrace{(1-s)n_s}_{n_m} + \underbrace{s n_s}_{\text{slip rpm}} = n_s = \boxed{1200 \text{ rpm}}$$

- ② A 3ϕ , 460V, 60Hz, 20kW induction machine draws 25A at a power factor of 0.9 lagging when connected to a 3ϕ , 460V, 60Hz supply. The core loss is 900W, stator copper loss is 1100W, rotor copper loss is 550W, and friction and windage loss is 300W. Calculate:


A] AIR GAP POWER

From the diagram, $P_{ag} = P_{in} - P_{core} - P_{s,cu}$

$$P_{st} = \sqrt{3} V_L I_L \cdot pf = 3 \cdot \left(\frac{V_L}{\sqrt{3}} \right) I_{phase} \cdot pf$$

$$\hookrightarrow P_{in} = \sqrt{3} (460)(25)(0.9) = 17926.7 \text{ W}$$

$$\Rightarrow P_{ag} = 17926.7 - 900 - 1100 = \boxed{15926.7 \text{ W}}$$



* the airgap power is what is left from the input stage for the rotor to convert to mechanical power.

B] MECHANICAL POWER

The mechanical power we get will be the airgap power the rotor receives minus the copper loss in the rotor. No core losses given in rotor.

$$P_{mech} = P_{ag} - P_{r,cu} = 15926.7 - 550 = \boxed{15376.7 \text{ W}}$$

C] OUTPUT HORSEPOWER

$$P_{out} = P_{mech} - P_{f,w} = 15376.7 - 300 = 15076.7 \text{ W}$$

$$\Rightarrow \frac{15076.7 \text{ W}}{1} \left(\frac{1 \text{ HP}}{746 \text{ W}} \right) = \boxed{20.2 \text{ HP}}$$

$P_{f,w}$: friction & windage loss

D] EFFICIENCY

The efficiency can be calculated between P_{out} & P_{in} .

$$\eta = \frac{P_{out}}{P_{in}} \times 100\% = \frac{15076.7}{17926.7} \times 100\% = \boxed{84.1\% \text{ efficient}}$$

- ③ A 3 ϕ , 10Hp, 460V, 60Hz, 4-pole induction motor runs at 1730 rpm at full-load. The stator copper loss is 200W and the windage & friction loss is 320W. Determine:

$$n_m = 1730 \text{ rpm}$$

$$n_s = \frac{120f}{P} = \frac{120(60 \text{ Hz})}{4} = 1800 \text{ rpm}$$

First we need to find slip s .

$$\Rightarrow s = 1 - \frac{n_m}{n_s} = 1 - \frac{1730}{1800} = 0.0389$$

$$\text{Next, } P_{out} = 10 \text{ Hp} = 10 \text{ Hp} \left(\frac{746 \text{ W}}{1 \text{ Hp}} \right) = 7460 \text{ W}$$

$$\Rightarrow P_{out} = P_{mech} - P_{fw} \Rightarrow P_{mech} = P_{out} + P_{fw} = 7460 + 320 = \boxed{7780 \text{ W}}$$

B AIR GAP POWER

$$P_{ag} = \frac{P_{mech}}{1-s} = \frac{7780}{1-0.0389} = \boxed{8094.9 \text{ W}}$$

C ROTOR COPPER LOSS

$$P_{r,w} = s P_{ag} = 0.0389(8094.9) = \boxed{314.9 \text{ W}} \quad * \text{ also could do } P_{r,w} = P_{ag} - P_{mech}$$

D INPUT POWER

No stator copper loss given $\therefore P_{in} = P_{ag} + P_{r,w}$

$$P_{in} = 8094.9 + 200 = \boxed{8294.9 \text{ W}}$$

E EFFICIENCY

$$\eta = \frac{P_{out}}{P_{in}} \times 100\% = \frac{7460}{8294.9} \times 100\% = \boxed{89.9\% \text{ efficient}}$$

⑦ Test results for 3 ϕ , 230V, 60Hz, 6.5A, 500W induction machine

Blocked rotor: 44V, 60Hz, 2.5A, 1250W

No-load: 208V, 60Hz, 6.5A, 500W

The average resistance measured by a DC Bridge b/w two stator terminals is 0.54Ω \rightarrow Since 2 stator phases $R_1 = \frac{0.54\Omega}{2} = 0.27\Omega$

A NO-LOAD ROTATIONAL LOSS

$$P_{rot} = P_{NL} - 3I_1^2 R_1 = 500 - 3(6.5)^2(0.27) = \boxed{465.8W}$$

B IEEE EA. CKT.

We already know $R_1 = \frac{0.54\Omega}{2} = 0.27\Omega$ phase voltage

Z_{NL}

$$P_{NL} = \frac{P_m}{3I_1^2} = \frac{500}{3(6.5)^2} = 3.94\Omega, \quad Z_{NL} = \frac{V_1}{I_1} = \frac{208}{\sqrt{3}6.5} = 18.5\Omega$$

$$X_{NL} = \sqrt{Z_{NL}^2 - R_{NL}^2} = \sqrt{18.5^2 - 3.94^2} = j18.1\Omega$$

$\uparrow = X_1 + X_m$


Z_{BL}

$$s=1, \quad R_{BL} = \frac{P_{BL}}{3I_{BL}^2} = \frac{1250}{3(2.5)^2} = 0.667\Omega \quad \text{where } R_2' = R_{BL} - R_1 = 0.667 - 0.27 = 0.397\Omega$$

$$Z_{BL} = \frac{V_1}{I_1} = \frac{44}{\sqrt{3} \cdot 2.5} = 1.016\Omega \rightarrow X_{BL} = \sqrt{1.016^2 - 0.667^2} = j0.766\Omega$$

$$X_{BL} = X_1 + X_2' \therefore X_1 = X_2' = \frac{X_{BL}}{2} = \frac{0.766}{2} = j0.383\Omega$$

$$\Rightarrow X_m = X_{NL} - X_1 = 18.1 - 0.383 = j17.7\Omega$$



C OUTPUT HP @ s=0.1

$$\frac{R_2'}{s} = \frac{0.383}{0.1} = 3.83\Omega \Rightarrow Z_1 = R_1 + jX_1 + X_m \parallel \left(\frac{R_2'}{s} + jX_2' \right) = 0.27 + j0.383 + \frac{j17.7(3.83 + j0.383)}{j17.7 + 3.83 + j0.383}$$

$$= 4.07 \angle 21.7^\circ \Omega$$

$$\Rightarrow I_1 = \frac{V_1}{\sqrt{3} Z_1} = \frac{208}{\sqrt{3}(4.07 \angle 21.7^\circ)} = 29.5 \angle -21.7^\circ A$$

$$\Rightarrow P_h = \sqrt{3}(208)(29.5) \cos(-21.7^\circ) = 9874.69$$

$$P_{ag} = P_h - 3I_1^2 R_1 = 9874.7 - 3(29.5)^2(0.27) = 9169.8W$$

$$P_{mech} = (1-s)P_{ag} = (0.9)(9169.8) = 8252.8W$$

$$P_{out} = P_{mech} - P_{rot, loss}$$

$$= 8252.8 - 465.8$$

$$= \boxed{7787W = 10.4HP}$$