

## SECTION 2 TABLES OF COMMAND CODES

### 1. List of G Codes

| Code                                   | Group | Functions  | Optional |
|--|-------|--|----------|
| G00 *3<br>G01 *3<br>G02<br>G03         | 1     | Positioning<br>Linear interpolation<br>Circular interpolation-Helical cutting (CW)<br>Circular interpolation-Helical cutting (CCW) |          |
| G04 *2                                 | 2     | Dwell  |          |
| G05<br>G06<br>G07<br>G08               |       |  |          |
| G09 *2                                 | 18    | Exact stop   |          |
| G10 *1<br>G11                          | 3     | Cancel of G11<br>Parallel and rotation shift of coordinate system  | ○        |
| G12<br>G13                             |       |  |          |
| G14                                    |       | Axis name designation/cancel   | ○        |
| G15<br>G16 *2                          | 4     | Selection of work coordinate system (Modal)<br>Selection of work coordinate system (One-shot)                                      | ○        |
| G17 *3<br>G18 *2<br>G19 *2             | 5     | Plane selection: XY<br>Plane selection: ZX<br>Plane selection: YZ  |          |
| G20 *2<br>G21 *2                       | 15    | Inch input confirmation<br>Metric input confirmation   | ○        |
| G22 *3<br>G23 *3                       | 6     | Programmable travel limit ON<br>Programmable travel limit cancel   | ○        |
| G24<br>G25<br>G26<br>G27<br>G28<br>G29 |       |  |          |

\*1 Has already been set when power supply is turned on.

\*2 Effective in a specified block.

\*3 May be set by an initial condition parameter.

(cont'd)

| Code  | Group | Functions   | Optional |
|---|-------|---|----------|
| G30 *2  | 16    | Positioning to home position  |          |
| G31 *2  | 17    | Skip function   | ○        |
| G32<br>G33<br>G34<br>G35<br>G36<br>G37<br>G38       |       |   |          |
| G40 *1<br>G41<br>G42                                | 7     | Cutter radius compensation cancel<br>Cutter radius compensation, left<br>Cutter Radius compensation, right  |          |
| G43 *1<br>G44                                       | 8     | Three dimensional compensation cancel<br>Three dimensional compensation ON  | ○        |
| G45<br>G46<br>G47<br>G48<br>G49                     |       |   |          |
| G50 *1<br>G51                                       | 9     | Enlargement and reduction of geometry cancel<br>Enlargement and reduction of geometry ON  | ○        |
| G52   |       |   |          |
| G53 *3<br>G54<br>G55<br>G56 *3<br>G57<br>G58<br>G59 | 10    | Tool length offset cancel<br>Tool length offset, X-axis<br>Tool length offset, Y-axis<br>Tool length offset, Y-axis<br>Tool length offset, 4th-axis<br>Tool length offset, 5th-axis<br>Tool length offset, 6th-axis |          |
| G60   | 1     | One-directional positioning   |          |
| G61   | 14    | Exact stop mode   |          |

\*1 Has already been set when power supply is turned on.

\*2 Effective in a specified block.

\*3 May be set by an initial condition parameter.

(cont'd)

| Code   | Group | Functions  | Optional |
|--------|-------|--|----------|
| G62    | 19    | Programmable mirror image function               | ○        |
| G63    |       |  |          |
| G64 *1 | 14    | Cutting mode                                     | ○        |
| G65    |       |  |          |
| G66    |       |  |          |
| G67    |       |  |          |
| G68    | 24    | Cancel of G68                                    | ○        |
| G69    |       | Setting of 3-D coordinate system conversion      |          |
| G70    |       |  |          |
| G71    | 11    | Fixed cycle, Designation of return level for M53 |          |
| G72    |       |  |          |
| G73    | 11    | Fixed cycle, High speed drilling cycle           |          |
| G74    |       | Fixed cycle, Reverse tapping                     |          |
| G75    |       |  |          |
| G76    | 11    | Fixed cycle, Fine boring                         |          |
| G77    |       |  |          |
| G78    |       |  |          |
| G79    |       |  |          |
| G80 *1 | 11    | Fixed cycle, Mode cancel                         |          |
| G81    |       | Fixed cycle, Drill/spot boring                   |          |
| G82    |       | Fixed cycle, Drill/counter boring                |          |
| G83    |       | Fixed cycle, Deep-hole drilling cycle            |          |
| G84    |       | Fixed cycle, Tapping                             |          |
| G85    |       | Fixed cycle, Boring                              |          |
| G86    |       | Fixed cycle, Boring                              |          |
| G87    |       | Fixed cycle, Back boring                         |          |
| G88    |       |  |          |
| G89    | 11    | Fixed cycle, Boring                              |          |
| G90 *3 | 12    | Absolute dimensioning                            |          |
| G91 *3 |       | Incremental dimensioning                         |          |

\*1 Has already been set when power supply is turned on.

\*2 Effective in a specified block.

\*3 May be set by an initial condition parameter.

## SECTION 2 TABLES OF COMMAND CODES

(cont'd)

| Code   | Group | Functions  | Optional |
|--------|-------|--|----------|
| G92    | 20    | Setting of work coordinate system                            |          |
| G93    |       |  |          |
| G94 *3 | 13    | Feed per min   |          |
| G95 *3 |       | Feed per rev   |          |
| G96    |       |  |          |
| G97    |       |  |          |
| G98    |       |  |          |
| G99    |       |  |          |
| G172   | 0     | 3-D arc nearest path   |          |
| G173   | 0     | 3-D arc farthest path  |          |
| G174   | 77    | Cylinder side-face machining OFF                             |          |
| G175   | 77    | Cylinder side-face machining ON                              |          |
| G176   | 71    | F-code and S-code ignore CANCEL                              |          |
| G177   | 71    | F-code and S-code ignore                                     |          |
| G178   | 0     | Threading fixed cycle in the No. 1 axis direction in a plane |          |
| G179   | 0     | Threading fixed cycle in the No. 2 axis direction in a plane |          |
| G180   | 64    | Attachment rotation compensation CANCEL                      |          |
| G181   | 64    | Attachment rotation compensation facing FRONT                |          |
| G182   | 64    | Attachment rotation compensation facing LEFT                 |          |
| G183   | 64    | Attachment rotation compensation facing REAR                 |          |
| G184   | 64    | Attachment rotation compensation facing RIGHT                |          |
| G185   | 64    | Attachment rotation compensation facing DOWN                 |          |
| G186   | 65    | Tolerance control mode CANCEL                                |          |
| G187   | 65    | Tolerance control mode ON                                    |          |
| G188   | 69    | No. 2 tool length offset CANCEL                              |          |
| G189   | 69    | No. 2 tool length offset ON                                  |          |
| G190   | 39    | Constant G90 mode (absolute) processing                      |          |
| G191   | 25    | Manual shift amount CANCEL                                   |          |
| G192   | 67    | Top face detection fixed cycle mode CANCEL                   |          |
| G193   | 67    | Top face detection fixed cycle mode ON                       |          |
| G194   | 68    | Fixed cycle mode with breakage detection CANCEL              |          |
| G195   | 68    | Fixed cycle mode with breakage detection ON                  |          |
| G196   | 26    | Block call at each sub-program ON                            |          |
| G197   | 26    | Block call at each sub-program CANCEL                        |          |

(cont'd)

| Code | Group | Functions   | Optional |
|------|-------|---|----------|
| G198 | 70    | Threading compound fixed cycle in the No. 1 axis direction in a plane |          |
| G199 | 70    | Threading compound fixed cycle in the No. 2 axis direction in a plane |          |
| G256 | 78    | 3-D arc projection surface selection                                  |          |
| G274 | 10    | Fixed cycle synchronous tapping reverse tapping cycle                 | ○        |
| G284 | 10    | Fixed cycle synchronous tapping tapping cycle                         | ○        |

\*1 Has already been set when power supply is turned on.

\*2 Effective in a specified block.

\*3 May be set by an initial condition parameter.

## 2. List of Mnemonic Codes

| Code   | Group | Contents  | Optional |
|--------|-------|---|----------|
| NOEX   | 34    | Specification of the sequence not executed  |          |
| CALL   | 27    | Subprogram, Simple call   |          |
| RTS    |       | Subprogram, End code  |          |
| MODIN  |       | Subprogram, Call after positioning mode ON  |          |
| MODOUT |       | Subprogram, Call after positioning mode OFF   |          |
| GOTO   | 28    | Branch command, Unconditional jump  |          |
| IF     |       | Branch command, Conditional jump (6 kinds)  |          |
| RTMCR  |       | Macro processing end code (used only in system)                                       |          |
| RTMDI  |       | MDI processing end code (used only in system)   |          |
| OMIT   | 29    | Coordinate calculation function, Omit   | ○        |
| RSTRT  |       | Coordinate calculation function, Restart  |          |
| LAA    | 30    | Coordinate calculation function, Line at angle  | ○        |
| ARC    |       | Coordinate calculation function, Arc  |          |
| GRDX   |       | Coordinate calculation function, Grid X   |          |
| GRDY   |       | Coordinate calculation function, Grid Y   |          |
| DGRDX  |       | Coordinate calculation function, Double grid X  |          |
| DGRDY  |       | Coordinate calculation function, Double grid Y  |          |
| SQRX   |       | Coordinate calculation function, Square X   |          |
| SQRY   |       | Coordinate calculation function, Square Y   |          |
| BHC    |       | Coordinate calculation function, Bolt hole circle                                     |          |
| FMILR  | 31    | Area machining, Face milling (Rough)  | ○        |
| FMILF  |       | Area machining, Face milling (Finish)   |          |
| PMIL   |       | Area machining, Pocket milling (Zigzag)   |          |
| PMILR  |       | Area machining, Pocket milling (Spiral)   |          |
| RMILO  |       | Area machining, Round milling (Out)   |          |
| RMILI  |       | Area machining, Round milling (In)  |          |
| MSG    | 35    | Message display   | ○        |
| NMSG   |       | Restoring original display  |          |
| NCYL   | 36    | Fixed cycle, No cycle movement  |          |
| COPY   | 39    | Copy, initial value of local coordinate system for parallel shift or rotation         | ○        |
| COPYE  |       | Copy end, Incremental value for parallel shift or rotation of local coordinate system |          |
| CHFC   |       | Arbitrary-angle chamfering  | ○        |
| CHFR   |       | Arbitrary-angle chamfering (rounding)   |          |

### 3. List of M Codes

| Code | Group | Function Element                                      | Against Axis Movement | Modal/ One-shot | Remarks                                | Optional          |
|------|-------|---|-----------------------|-----------------|--|-------------------|
| M00  | 1     | Program stop  | After                 | one-shot        |  |                   |
| M01  |       | Optional stop   | After                 | one-shot        |  |                   |
| M02  | 18    | End of program  | After                 | one-shot        |  |                   |
| M30  |       | End of tape   | After                 | one-shot        |  |                   |
| M03  | 2     | Spindle CW  | At the same time      | modal           |  |                   |
| M04  |       | Spindle CCW   | At the same time      | modal           |  |                   |
| M05  |       | Spindle stop  | After                 | modal           |  |                   |
| M19  |       | Spindle orientation                                   | After                 | modal           |  |                   |
| M06  | 3     | Vertical spindle tool change                          | After                 | one-shot        |  |                   |
| M77  |       | Horizontal spindle tool change                        | After                 | one-shot        |  |                   |
| M07  | 8     | Oil mist coolant ON                                   | At the same time      | modal           |  | ○                 |
| M08  | 10    | Coolant pump ON                                       | At the same time      | modal           |  | ○                 |
| M09  | 24    | Coolant system OFF (M07, 08, 12, 50, 51, 59, 120 OFF) | After                 | modal           |  | ○                 |
| M10  | 30    | A-axis clamp  | After                 | modal           |  | ○                 |
| M11  |       | A-axis unclamp  | After                 | modal           |  |                   |
| M12  | 22    | Chip air blow ON                                      | At the same time      | modal           |  | ○                 |
| M15  | 5     | Rotary index table CW (4th-axis)                      | At the same time      | modal           |  |                   |
| M16  |       | Rotary index table CCW (4th-axis)                     | At the same time      | modal           |  |                   |
| M17  | 7     | Swivel head index CCW                                 | At the same time      | one-shot        | Effective for only the first M73 - M76 |                   |
| M20  | 31    | B-axis clamp  | After                 | modal           |  | ○                 |
| M21  |       | B-axis unclamp  | After                 | modal           |  | (Except for MC-H) |
| M22  | 32    | Y-axis clamp  | After                 | modal           |  |                   |
| M23  |       | Y-axis unclamp  | After                 | modal           |  |                   |
| M24  | 33    | Z-axis clamp  | After                 | modal           |  |                   |
| M25  |       | Z-axis unclamp  | After                 | modal           |  |                   |
| M26  | 35    | C-axis clamp  | After                 | modal           |  | ○                 |
| M27  |       | C-axis unclamp  | After                 | modal           |  |                   |
| M32  | 38    | Splash guard door close                               | At the same time      | modal           |  | ○                 |
| M33  |       | Splash guard door open                                | At the same time      | modal           |  |                   |

## SECTION 2 TABLES OF COMMAND CODES

(cont'd)

| Code | Group | Function Element                             | Against Axis Movement | Modal/ One-shot | Remarks  | Optional |
|------|-------|--|-----------------------|-----------------|--|----------|
| M40  | 11    | High/middle-high/middle-low/low range        | At the same time      | modal           | Spindle gears are automatically determined by RPM command. |          |
| M41  |       | High/middle-high/middle-low range            | At the same time      | modal           |  |          |
| M42  |       | High/middle-high range                       | At the same time      | modal           |  |          |
| M43  |       | High range                                   | At the same time      | modal           |  |          |
| M44  |       | AAC (F) next attachment clear                | At the same time      | one-shot        | F: Floor type<br>T: Table type                             | ○        |
| M45  |       | AAC (F) change preparation                   | At the same time      | one-shot        |  |          |
| M46  |       | AAC (F) no next attachment                   | At the same time      | one-shot        |  |          |
| M47  |       | AAC (T) no next attachment                   | At the same time      | one-shot        |  |          |
| M48  |       | AAC (T) next attachment clear                | At the same time      | one-shot        |  |          |
| M49  |       | AAC (T) change preparation                   | At the same time      | one-shot        |  |          |
| M50  | 23    | Through-the-tool coolant, low pressure ON    | At the same time      | modal           |  | ○        |
| M51  |       | Through-the-tool coolant, high pressure ON   | At the same time      | modal           |  |          |
| M52  | 12    | Return level in fixed cycle: upper limit     | At the same time      | one-shot        |  |          |
| M53  | 13    | Return level in fixed cycle: specified level | At the same time      | modal           |  |          |
| M54  |       | Return level in fixed cycle: R level         | At the same time      | modal           |  |          |
| M57  | 34    | W-axis clamp                                 | After                 | modal           |  | ○        |
| M58  |       | W-axis unclamp                               | After                 | modal           |  |          |
| M59  | 25    | Chip air blow ON                             | At the same time      | modal           |  | ○        |
| M60  | 4     | Pallet change cycle                          | After                 | one-shot        |  | ○        |
| M62  |       | Vertical spindle tool change preparation     | After                 | modal           |  | ○        |
| M68  |       | Vertical spindle tool clamp                  | After                 | modal           |  |          |
| M69  |       | Vertical spindle tool unclamp                | After                 | modal           |  |          |
| M63  | 21    | No next tool in automatic tool change cycle  | At the same time      | one-shot        |  |          |
| M64  |       | Next tool return cycle                       | At the same time      | one-shot        |  |          |
| M65  |       | ATC ready                                    | At the same time      | one-shot        |  |          |



(cont'd)

| Code | Group | Function Element  | Against Axis Movement | Modal/ One-shot | Remarks                      | Optional |
|------|-------|---|-----------------------|-----------------|------------------------------|----------|
| M66  | 14    | Continuous tool change between vertical and horizontal spindle (same tool)      | At the same time      | one-shot        |                              |          |
| M67  |       | Continuous tool change between vertical and horizontal spindle (different tool) | At the same time      | one-shot        |                              |          |
| M70  | 3     | Manual tool change  | After                 | one-shot        |                              | ○        |
| M71  |       | Attachment manual tool change   | After                 | one-shot        |                              | ○        |
| M72  |       | Horizontal spindle tool change preparation                                      | After                 | modal           |                              |          |
| M78  |       | Horizontal spindle tool clamp   | After                 | modal           |                              |          |
| M79  |       | Horizontal spindle tool unclamp   | After                 | modal           |                              |          |
| M73  | 15    | Swivel head, front position   | After                 | one-shot        |                              | ○        |
| M74  |       | Swivel head, left position  | After                 | one-shot        |                              |          |
| M75  |       | Swivel head, back position  | After                 | one-shot        |                              |          |
| M76  |       | Swivel head, right position   | After                 | one-shot        |                              |          |
| M81  | 27    | Automatic W-axis positioning 1  | After                 | one-shot        |                              | ○        |
| M82  |       | Automatic W-axis positioning 2  | After                 | one-shot        |                              |          |
| M83  |       | Automatic W-axis positioning 3  | After                 | one-shot        |                              |          |
| M84  |       | Automatic W-axis positioning 4  | After                 | one-shot        |                              |          |
| M85  |       | Automatic W-axis positioning 5  | After                 | one-shot        |                              |          |
| M87  |       | Oil mist/Air blow ON  | At the same time      | one-shot        | Effective for M90, 91 and 98 | ○        |
| M88  |       | Dust collector ON   | At the same time      | modal           |                              | ○        |
| M89  |       | Dust collector OFF  | At the same time      | modal           |                              |          |
| M90  |       | Vertical spindle oil mist cycle mode ON   | At the same time      | modal           |                              |          |
| M98  |       | Horizontal spindle oil mist cycle mode ON                                       | At the same time      | modal           |                              |          |
| M91  |       | Tap-drill hole chip air blow cycle mode ON                                      | At the same time      | modal           | Turned OFF by M09            | ○        |

## SECTION 2 TABLES OF COMMAND CODES

(cont'd)

| Code | Group | Function Element                                | Against Axis Movement | Modal/ One-shot | Remarks | Optional |
|------|-------|---|-----------------------|-----------------|---------|----------|
| M101 | 4     | Pallet selection 1                              | After                 | one-shot        |         | ○        |
| M102 |       | Pallet selection 2                              | After                 | one-shot        |         |          |
| M103 |       | Pallet selection 3                              | After                 | one-shot        |         |          |
| M104 |       | Pallet selection 4                              | After                 | one-shot        |         |          |
| M105 |       | Pallet selection 5                              | After                 | one-shot        |         |          |
| M106 |       | Pallet selection 6                              | After                 | one-shot        |         |          |
| M107 |       | Pallet selection 7                              | After                 | one-shot        |         |          |
| M108 |       | Pallet selection 8                              | After                 | one-shot        |         |          |
| M109 |       | Pallet selection 9                              | After                 | one-shot        |         |          |
| M110 |       | Pallet selection 10                             | After                 | one-shot        |         |          |
| M111 |       | Pallet selection 11                             | After                 | one-shot        |         |          |
| M112 |       | Pallet selection 12                             | After                 | one-shot        |         |          |
| M115 | 6     | 5th axis-rotary table forward                   | At the same time      | modal           |         | ○        |
| M116 |       | 5th axis-rotary table reverse                   | At the same time      | modal           |         |          |
| M118 |       | Spindle orientation (reverse)                   | After                 | modal           |         |          |
| M119 |       | Spindle orientation (reverse/forward)           | After                 | modal           |         |          |
| M120 |       | Shower coolant ON                               | At the same time      | modal           |         | ○        |
| M130 | 9     | Spindle rotation condition for cutting feed OFF | At the same time      | modal           |         |          |
| M131 |       | Spindle rotation condition for cutting feed ON  | At the same time      | modal           |         |          |
| M132 | 37    | Single block ineffective                        | At the same time      | modal           |         |          |
| M133 |       | Single block effective                          | At the same time      | modal           |         |          |
| M134 | 16    | Spindle speed override ineffective              | At the same time      | modal           |         |          |
| M135 |       | Spindle speed override effective                | At the same time      | modal           |         |          |
| M136 | 17    | Feedrate override ineffective                   | At the same time      | modal           |         |          |
| M137 |       | Feedrate override effective                     | At the same time      | modal           |         |          |
| M138 | 36    | Dry run ineffective                             | At the same time      | modal           |         |          |
| M139 |       | Dry run effective                               | At the same time      | modal           |         |          |
| M140 | 39    | Slide hold ineffective                          | At the same time      | modal           |         |          |
| M141 |       | Slide hold effective                            | At the same time      | modal           |         |          |

## SECTION 2 TABLES OF COMMAND CODES

(cont'd)

| Code | Group | Function Element                               | Against Axis Movement | Modal/One-shot | Remarks                                  | Optional |
|------|-------|--|-----------------------|----------------|--|----------|
| M142 |       | Spindle overload detection ineffective         | At the same time      | modal          |  | ○        |
| M143 |       | Spindle overload detection effective           | At the same time      | modal          |  |          |
| M144 | 19    | Touch sensor advance                           | After                 | modal          |  | ○        |
| M145 |       | Touch sensor retraction                        | After                 | modal          |  |          |
| M150 | 28    | Coolant group specification-vertical spindle   | At the same time      | modal          |  | ○        |
| M151 |       | Coolant group specification-horizontal spindle | At the same time      | modal          |  |          |
| M152 |       | Coolant group specification-3rd group          | At the same time      | modal          |  |          |
| M153 |       | Coolant group specification-4th group          | At the same time      | modal          |  |          |
| M154 | 20    | Sensor air blow OFF                            | After                 | modal          |  | ○        |
| M155 |       | Sensor air blow ON                             | At the same time      | modal          |  |          |
| M157 |       | AAC (2 st.) no next tool                       | After                 | one-shot       |  | ○        |
| M158 |       | AAC (2 st.) next tool clear                    | After                 | one-shot       |  |          |
| M159 |       | AAC (2 st.) attachment preparation             | After                 | one-shot       |  |          |
| M160 | 4     | Pallet loading command at PPC ON               |                       |                |  | ○        |
| M161 |       | Pallet unloading command at PPC ON             |                       |                |  |          |
| M163 |       | Long tool-no next tool                         | At the same time      | one-shot       |  | ○        |
| M165 |       | Long tool-tool change preparation              | At the same time      | one-shot       | Safety cover specification for next tool |          |

## SECTION 2 TABLES OF COMMAND CODES

(cont'd)

| Code | Group | Function Element                          | Against Axis Movement | Modal/ One-shot | Remarks  | Optional |
|------|-------|---|-----------------------|-----------------|--|----------|
| M172 | 3     | Long tool-tool change-command             | After                 | one-shot        |  | ○        |
| M166 |       | ATC active tool return mode specification | At the same time      | one-shot        |  | ○        |
| M170 | 3     | AAC (F) attachment change                 | After                 | one-shot        | F: Floor type<br>T: Table type                           | ○        |
| M171 |       | AAC (T) attachment change                 | After                 | one-shot        |  |          |
| M173 |       | AAC (2 st.) attachment change command     | After                 | one-shot        |  |          |
| M176 |       | Dust collection mode-sir blow             | At the same time      | one-shot        |  | ○        |
| M178 | 4     | Dust collection mode-ON                   | At the same time      | modal           |  | ○        |
| M179 |       | Dust collection mode-OFF                  | At the same time      | modal           |  |          |
| M177 | 3     | Angular attachment tool change            | After                 | one-shot        | AT-ATC   | ○        |
| M181 | 38    | External M signal                         | At the same time      | one-shot        |  | ○        |
| M182 |       | External M signal                         | At the same time      | one-shot        |  |          |
| M183 |       | External M signal                         | At the same time      | one-shot        |  |          |
| M184 |       | External M signal                         | At the same time      | one-shot        |  |          |
| M185 |       | External M signal                         | At the same time      | one-shot        |  |          |
| M186 |       | External M signal                         | At the same time      | one-shot        |  | ○        |
| M187 |       | External M signal                         | At the same time      | one-shot        |  |          |
| M188 |       | External M signal                         | At the same time      | one-shot        |  |          |
| M190 |       | Automatic W-axis positioning 1            | After                 | one-shot        | For automatic W-axis positioning 10 points specification | ○        |
| M191 |       | Automatic W-axis positioning 2            | After                 | one-shot        |  |          |
| M192 |       | Automatic W-axis positioning 3            | After                 | one-shot        |  |          |
| M193 |       | Automatic W-axis positioning 4            | After                 | one-shot        |  |          |
| M194 |       | Automatic W-axis positioning 5            | After                 | one-shot        |  |          |
| M195 |       | Automatic W-axis positioning 6            | After                 | one-shot        |  |          |
| M196 |       | Automatic W-axis positioning 7            | After                 | one-shot        |  |          |
| M197 |       | Automatic W-axis positioning 8            | After                 | one-shot        |  |          |
| M198 |       | Automatic W-axis positioning 9            | After                 | one-shot        |  |          |
| M199 |       | Automatic W-axis positioning 10           | After                 | one-shot        |  |          |

(cont'd)

| Code | Group | Function Element  | Against Axis Movement | Modal/ One-shot | Remarks | Optional |
|------|-------|---|-----------------------|-----------------|---------|----------|
| M234 | 50    | Synchronized tapping gear selection range command (gear determined according to available spindle speeds in each gear range)    |                       |                 |         |          |
| M235 | 50    | Synchronized tapping gear selection range command (spindle speeds in the 1st gear range are covered by 2nd gear range)          |                       |                 |         |          |
| M236 | 50    | Synchronized tapping gear selection range command (spindle speeds in the 1st and 2nd gear ranges are covered by 3rd gear range) |                       |                 |         |          |
| M237 | 50    | Synchronized tapping gear selection range command (entire speeds are covered by 4th gear range)                                 |                       |                 |         |          |
| M238 | 39    | Soft override DISABLED  |                       |                 |         |          |
| M239 | 39    | Soft override ENABLED   |                       |                 |         |          |
| M292 | 44    | Threading fixed cycle chamfering ON   |                       |                 |         | ○        |
| M293 | 44    | Threading fixed cycle chamfering OFF  |                       |                 |         | ○        |
| M294 | 43    | Compound fixed cycle cutting pattern 1  |                       |                 |         | ○        |
| M295 | 43    | Compound fixed cycle cutting pattern 2  |                       |                 |         | ○        |
| M296 | 43    | Compound fixed cycle cutting pattern 3  |                       |                 |         | ○        |
| M323 | 2     | MC500/600H APC/ATC simultaneous operating M-code  |                       |                 |         |          |
| M326 | 51    | Synchronized tapping torque monitoring DISABLED   |                       |                 |         |          |
| M327 | 51    | Synchronized tapping torque monitoring ENABLED  |                       |                 |         |          |
| M331 | 56    | 6th axis rotary table FORWARD   |                       |                 |         |          |
| M332 | 56    | 6th axis rotary table REVERSE   |                       |                 |         |          |
| M396 | 49    | Synchronized tapping 1-speed gear indexing  |                       |                 |         |          |