

6th Generation Intel® Processor Family

Specification Update

Supporting 6th Generation Intel® Core™ Processor Families based on the H-Processor, S-Processor and Intel® Pentium® Processor

Supporting Intel® Xeon® Processor E3-1500 v5 Product Families based on the H-Platform

Supporting 6th Generation Intel® Core™ Processor Families based on Y-Processor Line, U-Processor Line, Intel® Pentium® Processor, and Intel® Celeron™ Processor

March 2021



You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or visit www.intel.com/design/literature.htm.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration. No product or component can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

No product or component can be absolutely secure.

Intel, Intel Core, Xeon, Pentium, Celeron, Intel Speedstep, and the Intel logo, are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others.

© Intel Corporation



Contents

Revision History	4
Preface	6
Summary Tables of Changes	8
Identification Information	21
Errata..	29
Specification Changes	86
Specification Clarifications.....	87
Documentation Changes	88



Revision History

Revision	Description	Date
001	Initial release	July 2015
002	Updated Errata Chapter	August 2015
003	<ul style="list-style-type: none"> Title and Subtitle Changes Updated Processor lines Y/U/S/H S-SPECs Updated Table 7, H-Processor Line Errata Added: SKL054, SKL055, SKL056, SKL057, SKL058, SKL059, SKL060, SKL061, SKL062, SKL063, SKL064, SKL065, SKL066, SKL067, SKL068, SKL069, SKL070, SKL071, SKL072, SKL073, SKL074, SKL075, SKL076, SKL077, SKL078, SKL079, SKL080, SKL081, SKL082, SKL083, SKL084, SKL085, SKL086, SKL087, SKL088, SKL089, SKL090, SKL091, SKL093, SKL094, SKL095, SKL096, SKL097 	January 2016
004	<ul style="list-style-type: none"> Updated Table 1, Errata Summary Table. Updated Table 5, U-Processor Updated Table 7, H-Processor Errata Added: SKL099, SKL100, SKL103, SKL104, SKL105 	March 2016
005	<ul style="list-style-type: none"> Updated Table 1, Errata Summary Table. Modified Table column headings. Added Table Notes 4 and 5 Updated Tables 4, 5, 6, 7 Updated Table 6 to add 6th Generation Intel® processor I7-6660U SKU 	March 2016
006	<ul style="list-style-type: none"> Minor updates for clarity Errata Added: SKL106–SKL111 	May 2016
007	Updated Table 7, H-Processor Line	May 2016
008	<ul style="list-style-type: none"> Updated Table 1. Errata Summary Errata Added: SKL112 – SKL132 	September 2016
009	Errata Added: SKL133 – SKL141	January 2017
010	Errata <ul style="list-style-type: none"> Removed SKL054 Added: SKL142 – SKL150 	April 2017
011	Errata <ul style="list-style-type: none"> Added: SKL151 	June 2017
012	<ul style="list-style-type: none"> Updated link in Related Documents Updated Table 1. Errata Summary Errata: <ul style="list-style-type: none"> Updated SKL013 and SKL090 Removed SKL143. Duplicate of erratum SKL139 Added: SKL158 and SKL159 	November 2017



013	Errata: <ul style="list-style-type: none">- Updated SKL026- Added: SKL160 – SKL171	July 2018
014	Errata <ul style="list-style-type: none">- Updated erratum SKL035, SKL050 and SKL062- Replaced erratum SKL023 with 2 errata: SKL172 and SKL173- Added new errata SKL174 and 175	September 2018
015	Errata <ul style="list-style-type: none">- Added erratum SKL176	October 2018
016	Errata: <ul style="list-style-type: none">- Added erratum SKL177	November 2018
017	Errata: <ul style="list-style-type: none">- Updated erratum SKL178	January 2019
018	Errata: <ul style="list-style-type: none">- Updated erratum SKL179	February 2019
019	Errata: <ul style="list-style-type: none">- Updated erratum SKL 180 and SKL 181	April 2019
020	Errata: <ul style="list-style-type: none">- Added erratum SKL 182 and SKL 183	June 2019
021	Errata: <ul style="list-style-type: none">- Added erratum SKL 184- Updated erratum SKL036	August 2019
022	Errata: <ul style="list-style-type: none">- Added erratum SKL 185 and SKL186	September 2019
023	Errata: <ul style="list-style-type: none">- Added erratum SKL 187 and SKL188	November 2019
024	Errata: <ul style="list-style-type: none">- Added erratum SKL 189 and SKL190	January 2020
025	Errata: <ul style="list-style-type: none">- Added erratum SKL 191 - SKL 195	July 2020
026	Errata: <ul style="list-style-type: none">- Added erratum SKL 196 - SKL 197	November 2020
027	Errata: <ul style="list-style-type: none">- Removed erratum SKL 197	December 2020
028	Errata: <ul style="list-style-type: none">- Added erratum SKL 198	March 2021



Preface

This document is an update to the specifications contained in the documents listed in the following Affected Documents/Related Documents table. It is a compilation of device and document errata and specification clarifications and changes, and is intended for hardware system manufacturers and for software developers of applications, operating system, and tools.

Information types defined in the Nomenclature section of this document are consolidated into this update document and are no longer published in other documents. This document may also contain information that has not been previously published.

Affected Documents

Document Title	Document Number/Location
6 th Generation Intel® Processor Datasheet for S-Platforms, Volume 1 of 2	332687
6 th Generation Intel® Processor Datasheet for S-Platforms, Volume 2 of 2	332688
6 th Generation Intel® Processor Datasheet for H-Platforms, Volume 1 of 2	332986
6 th Generation Intel® Processor Datasheet for H-Platforms, Volume 2 of 2	332987
6 th Generation Intel® Processor Datasheet for U/Y Platforms, Volume 1 of 2	332990
6 th Generation Intel® Processor Datasheet for U/Y Platforms, Volume 2 of 2	332991

Related Documents

Document Title	Document Number/Location
AP-485, Intel® Processor Identification and the CPUID Instruction	http://www.intel.com/design/processor/applnots/241618.htm
Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 1: Basic Architecture Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2A: Instruction Set Reference Manual A-M Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2B: Instruction Set Reference Manual N-Z Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3B: System Programming Guide Intel® 64 and IA-32 Intel Architecture Optimization Reference Manual	https://software.intel.com/en-us/articles/intel-sdm



Document Title	Document Number/Location
<i>Intel® 64 and IA-32 Architectures Software Developer's Manual Documentation Changes</i>	http://www.intel.com/content/www/us/en/processors/architectures-software-developer-manuals.html
<i>Intel® Virtualization Technology Specification for Directed I/O Architecture Specification</i>	D51397-008/ https://www.intel.com/content/dam/www/public/us/en/documents/product-specifications/vt-directed-io-spec.pdf
<i>ACPI Specifications</i>	http://www.acpi.info

Nomenclature

Errata are design defects or errors. Errata may cause the processor's behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

Specification Changes are modifications to the current published specifications. These changes will be incorporated in the next release of the specifications.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.

Documentation Changes include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.

Note: Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, and so on).



Summary Tables of Changes

The following table indicates the Specification Changes, Errata, Specification Clarifications or Documentation Changes, which apply to the listed processor stepping. Intel intends to fix some of the errata in a future stepping of the component, and to account for the other outstanding issues through documentation or Specification Changes as noted. This table uses the following notations:

Codes Used in Summary Table

Stepping

X: Erratum, Specification Change, or Clarification that applies to this stepping.

(No mark) or (Blank Box): This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

Status

Doc: Document change or update that will be implemented.

Plan Fix: This erratum may be fixed in a future stepping of the product.

Fixed: This erratum has been previously fixed.

No Fix: There are no plans to fix this erratum.

Row

Shaded: This item is either new or modified from the previous version of the document.



Table 1. Errata Summary Table

Number	Processor Line / Stepping							Status	Title
	Y	U		H		S			
	D-1	D-1	K-1	N-0	R-0	R-0	S-0		
SKL001	X	X	X	X	X	X	X	No Fix	Reported Memory Type May Not Be Used to Access the VMCS and Referenced Data Structures
SKL002	X	X	X	X	X	X	X	No Fix	Instruction Fetch May Cause Machine Check if Page Size and Memory Type Was Changed Without Invalidation
SKL003	X	X	X	X	X	X	X	No Fix	Execution of VAESIMC or VAESKEYGENASSIST With An Illegal Value for VEX.vvvv May Produce a #NM Exception
SKL004	X	X	X	X	X	X	X	No Fix	The Corrected Error Count Overflow Bit in IA32_MC0_STATUS is Not Updated When The UC Bit is Set
SKL005	X	X	X	X	X	X	X	No Fix	VM Exit May Set IA32_EFER.NXE When IA32_MISC_ENABLE Bit 34 is Set to 1
SKL006	X	X	X	X	X	X	X	No Fix	SMRAM State-Save Area Above the 4GB Boundary May Cause Unpredictable System Behavior
SKL007	X	X	X	X	X	X	X	No Fix	x87 FPU Exception (#MF) May be Signaled Earlier Than Expected
SKL008	X	X	X	X	X	X	X	No Fix	Incorrect FROM_IP Value For an RTM Abort in BTM or BTS May be Observed
SKL009	X	X	X	X	X	X	X	No Fix	DR6 Register May Contain an Incorrect Value When a MOV to SS or POP SS Instruction is Followed by an XBEGIN Instruction
SKL010	X	X	X	X	X	X	X	No Fix	Opcode Bytes F3 0F BC May Execute As TZCNT Even When TZCNT Not Enumerated by CPUID
SKL011				X	X	X	X	No Fix	PCIe* Root-port Initiated Compliance State Transmitter Equalization Settings May be Incorrect
SKL012	X	X	X	X	X	X	X	No Fix	The SMSW Instruction May Execute Within an Enclave
SKL013	X	X	X	X	X	X	X	No Fix	PEBS Record After a WRMSR to IA32_BIOS_UPDT_TRIG May be Incorrect
SKL014	X	X	X	X	X	X	X	No Fix	Intel® PT TIP.PGD May Not Have Target IP Payload
SKL015	X	X	X	X	X	X	X	No Fix	Operand-Size Override Prefix Causes 64-bit Operand Form of MOVBE Instruction to Cause a #UD



Number	Processor Line / Stepping							Status	Title
	Y	U		H		S			
	D-1	D-1	K-1	N-0	R-0	R-0	S-0		
SKL016	X	X	X	X	X	X	X	No Fix	Execution of FXSAVE or FXRSTOR With the VEX Prefix May Produce a #NM Exception
SKL017	X	X	X	X	X	X	X	No Fix	WRMSR May Not Clear The Sticky Count Overflow Bit in The IA32_MCI_STATUS_MSRs' Corrected Error Count Field
SKL018	X	X	X	X	X	X	X	No Fix	PEBS Eventing IP Field May be Incorrect After Not-Taken Branch
SKL019	X	X	X	X	X	X	X	No Fix	Debug Exceptions May Be Lost or Misreported Following WRMSR to IA32_BIOS_UPDT_TRIG
SKL020				X	X	X	X	No Fix	Attempts to Retrain a PCIe* Link May be Ignored
SKL021	X	X	X	X	X	X	X	No Fix	Intel® Processor Trace PSB+ Packets May Contain Unexpected Packets
SKL022	X	X	X	X	X	X	X	No Fix	An APIC Timer Interrupt During Core C6 Entry May be Lost
SKL023	X	X	X	X	X	X	X	No Fix	Replaced by 2 errata: SKL172 and SKL173
SKL024	X	X	X	X	X	X	X	No Fix	VM Entry That Clears TraceEn May Generate a FUP
SKL025			X					No Fix	EDRAM Corrected Error Events May Not be Properly Logged After a Warm Reset
SKL026	X	X	X	X	X	X	X	No Fix	Performance Monitor Event For Outstanding Offcore Requests May be Incorrect
SKL027	X	X	X	X	X	X	X	No Fix	Machine Check or Shutdown May Occur When Using The Peci RdIAMS Command
SKL028	X	X	X	X	X	X	X	No Fix	ENCLU[EGETKEY] Ignores KEYREQUEST.MISC_MASK
SKL029	X	X	X	X	X	X	X	No Fix	POPCNT Instruction May Take Longer to Execute Than Expected
SKL030	X	X	X	X	X	X	X	No Fix	ENCLU[EREPORT] May Cause a #GP When TARGETINFO.MISCSELECT is Non-Zero
SKL031	X	X	X	X	X	X	X	No Fix	A VMX Transition Attempting to Load a Non-Existent MSR May Result in a Shutdown
SKL032	X	X	X	X	X	X	X	No Fix	Transitions Out of 64-bit Mode May Lead to an Incorrect FDP And FIP
SKL033	X	X	X	X	X	X	X	No Fix	Intel® PT FUP May be Dropped After OVF



Number	Processor Line / Stepping							Status	Title
	Y	U		H		S			
	D-1	D-1	K-1	N-0	R-0	R-0	S-0		
SKL034	X	X	X	X	X	X	X	No Fix	ENCLS[ECREATE] Causes #GP if Enclave Base Address is Not Canonical
SKL035	X	X	X	X	X	X	X	No Fix	Data Breakpoint May Not be Detected on a REP MOVSB
SKL036	X	X	X	X	X	X	X	No Fix	Graphics VTd Hardware May Cache Invalid Entries
SKL037				X	X	X	X	No Fix	PCIe* and DMI Links With Lane Polarity Inversion May Result in Link Failure
SKL038				X	X	X	X	Fixed	PCIe* Expansion ROM Base Address Register May be Incorrect
SKL039				X	X	X	X	No Fix	PCIe* Perform Equalization May Lead to Link Failure
SKL040				X	X	X	X	No Fix	Two DIMMs Per Channel 2133 MHz DDR4 SODIMM Daisy-Chain Systems With Different Vendors May Hang
SKL041	X	X	X	X	X	X	X	No Fix	ENCLS[EINIT] Instruction May Unexpectedly #GP
SKL042	X	X	X	X	X	X	X	No Fix	Intel® PT OVF Packet May be Lost if Immediately Preceding a TraceStop
SKL043	X	X	X	X	X	X	X	No Fix	Detecting an Intel® PT Stopped or Error Condition Within an Intel® TSX Region May Result in a System Hang
SKL044	X	X	X	X	X	X	X	No Fix	WRMSR to IA32 BIOS UPDT TRIG May be Counted as Multiple Instructions
SKL045	X	X	X	X	X	X	X	No Fix	The x87 FIP May be Incorrect
SKL046	X	X	X	X	X	X	X	No Fix	Branch Instructions May Initialize MPX Bound Registers Incorrectly
SKL047	X	X	X	X	X	X	X	No Fix	Writing a Non-Canonical Value to an LBR MSR Does Not Signal a #GP When Intel® PT is Enabled
SKL048	X	X	X	X	X	X	X	No Fix	Processor May Run Intel® AVX Code Much Slower Than Expected
SKL049	X	X	X	X	X	X	X	No Fix	Intel® PT Buffer Overflow May Result in Incorrect Packets
SKL050	X	X	X	X	X	X	X	No Fix	Intel® PT PSB+ Packets May be Omitted on a C6 Transition
SKL051	X	X	X	X	X	X	X	No Fix	IA32 PERF GLOBAL STATUS.TRACE TOP A PMI Bit Cannot be Set by Software
SKL052 ¹	X	X	X	X	X	X	X	No Fix	CPUID Incorrectly Reports Bit Manipulation Instructions Support



Number	Processor Line / Stepping							Status	Title
	Y	U		H		S			
	D-1	D-1	K-1	N-0	R-0	R-0	S-0		
SKL053 ²	X	X	X	X	X	X	X	No Fix	Intel® Turbo Boost Technology May be Incorrectly Reported as Supported on Intel® Core™ i3 U/H/S, Select Intel® Mobile Pentium®, Intel® Mobile Celeron®, Select Intel® Pentium® G4xxx and Intel® Celeron® G3xxx Processors
SKL054	X	X	X	X	X	X	X	No Fix	N/A. Erratum has been removed
SKL055	X	X	X	X	X	X	X	No Fix	Use of Prefetch Instructions May Lead to a Violation of Memory Ordering
SKL056	X	X	X	X	X	X	X	No Fix	CS Limit Violation May Not be Detected
SKL057	X	X	X	X	X	X	X	No Fix	Last Level Cache Performance Monitoring Events May Be Inaccurate
SKL058	X	X	X	X	X	X	X	No Fix	#GP Occurs Rather Than #DB on Code Page Split Inside an Intel® SGX Enclave
SKL059	X	X	X	X	X	X	X	No Fix	Execution of VAESENCLAST Instruction May Produce a #NM Exception Instead of a #UD Exception
SKL060	X	X	X	X	X	X	X	No Fix	Intel® SGX Enclave Accesses to the APIC-Access Page May Cause APIC-Access VM Exits
SKL061	X	X	X	X	X	X	X	No Fix	CR3 Filtering Does Not Compare Bits [11:5] of CR3 and IA32_RTIT_CR3_MATCH in PAE Paging Mode
SKL062	X	X	X	X	X	X	X	No Fix	Intel® PT PacketEn Change on C-state Wake May Not Generate a TIP Packet
SKL063	X	X	X	X	X	X	X	No Fix	Graphics Configuration May Not be Correctly Restored After a Package C8 Exit
SKL064	X	X	X	X	X	X	X	No Fix	x87 FDP Value May be Saved Incorrectly
SKL065	X	X	X	X	X	X	X	No Fix	PECI Frequency Limited to 1 MHz
SKL066	X	X	X	X	X	X	X	No Fix	Processor Graphics IOMMU Unit May Not Mask DMA Remapping Faults
SKL067 ³				X	X	X	X	No Fix	Processor With Intel® SGX Support May Hang During S3 Wake or Power-On Reset
SKL068	X	X	X	X	X	X	X	No Fix	Audio Glitches May Occur After Reset or S3/S4 Exit
SKL069	X	X	X	X	X	X	X	No Fix	Intel® PT CYCThresh Value of 13 is Not Supported



Number	Processor Line / Stepping							Status	Title
	Y	U		H		S			
	D-1	D-1	K-1	N-0	R-0	R-0	S-0		
SKL070	X	X	X	X	X	X	X	No Fix	Exx. Intel® PT May Drop Some Timing Packets After Entering Thread
SKL071	X	X	X	X	X	X	X	No Fix	Underflow and Denormal Conditions During a VDPPS Instruction With YMM Operands May Not Produce The Expected Results
SKL072	X	X	X	X	X	X	X	No Fix	IA Core Ratio Change Coincident With Outstanding Read to the DE May Cause a System Hang
SKL073	X	X	X	X	X	X	X	No Fix	Enabling VMX-Preemption Timer Blocks HDC Operation
SKL074	X	X	X	X	X	X	X	No Fix	Certain Processors May be Configured With an Incorrect TDP
SKL075	X	X	X	X	X	X	X	No Fix	Display Flicker May Occur When Both VT-d And FBC Are Enabled
SKL076	X	X	X	X	X	X	X	No Fix	System May Hang When Using Intel® TXT And Memory That Supports Address Mirroring
SKL077	X	X	X	X	X	X	X	No Fix	System May Hang or Reset During Processor Package C9 Exit
SKL078	X	X	X	X	X	X	X	No Fix	Integrated Audio Codec May Not be Detected
SKL079	X	X	X	X	X	X	X	No Fix	MOVNTDQA From WC Memory May Pass Earlier MFENCE Instructions
SKL080	X	X	X	X	X	X	X	No Fix	APIC Timer Interrupt May be Delivered Early
SKL081			X					No Fix	Processors That Support EDRAM May Not Initialize Properly
SKL082	X	X	X	X	X	X	X	No Fix	Processor May Hang or Cause Unpredictable System Behavior
SKL083	X	X	X					No Fix	The Processor May Fail to Properly Exit Package C6 or Deeper
SKL084	X	X	X	X	X	X	X	No Fix	Certain Processors May Report Incorrect DID2
SKL085	X	X	X	X	X	X	X	No Fix	System May Hang When Entering S3/S4/S5 State
SKL086	X	X	X	X	X	X	X	No Fix	Display Flickering May be Observed with Specific eDP Panels
SKL087	X	X	X	X	X	X	X	No Fix	x87 FPU Data Pointer Updated Only for Instructions That Incur Unmasked Exceptions



Number	Processor Line / Stepping							Status	Title
	Y	U		H		S			
	D-1	D-1	K-1	N-0	R-0	R-0	S-0		
SKL088	X	X	X	X	X	X	X	No Fix	Incorrect Branch Predicted Bit in BTS/BTM Branch Records
SKL089	X	X	X	X	X	X	X	No Fix	MACHINE_CLEARS.MEMORY ORDERING Performance Monitoring Event May Undercount
SKL090	X	X	X	X	X	X	X	No Fix	CTR_FRZ May Not Freeze Some Counters
SKL091	X	X	X	X	X	X	X	No Fix	Instructions And Branches Retired Performance Monitoring Events May Overcount
SKL092									Deleted – Please refer to SKL057
SKL093	X	X	X	X	X	X	X	No Fix	REP MOVSB May Not Operate Correctly With EPT Enabled
SKL094	X	X	X	X	X	X	X	No Fix	Ring Frequency Changes May Cause a Machine Check And System Hang
SKL095	X	X	X	X	X	X	X	No Fix	Some OFFCORE_RESPONSE Performance Monitoring Events May Over Count
SKL096	X	X	X	X	X	X	X	No Fix	Using BIOS to Disable Cores May Lead to a System Hang
SKL097	X	X	X	X	X	X	X	No Fix	#GP After RSM May Push Incorrect RFLAGS Value When Intel® PT is Enabled
SKL098									Deleted - Please refer to SKL005S
SKL099	X	X	X	X	X	X	X	No Fix	Access to SGX EPC Page in BLOCKED State is Not Reported as an SGX-Induced Page Fault
SKL100	X	X	X	X	X	X	X	No Fix	MTF VM Exit on XBEGIN Instruction May Save State Incorrectly
SKL101				X				No Fix	PCIe* Atomic Operations May Lead to Unpredictable System Behavior
SKL102				X				No Fix	Instructions That Cause #NM May Lead to Hang
SKL103			X	X				No Fix	Enabling S3 on Processors With EDRAM May Cause Unpredictable System Behavior
SKL104	X	X	X	X	X	X	X	No Fix	PEBS Record May Be Generated After Being Disabled
SKL105	X	X	X	X	X	X	X	No Fix	Software Using Intel® TSX May Result in Unpredictable System Behavior
SKL106	X	X	X	X	X	X	X	No Fix	Package-C6 Exit Latency May be Higher Than Expected Leading to Display Flicker



Number	Processor Line / Stepping							Status	Title
	Y	U		H		S			
	D-1	D-1	K-1	N-0	R-0	R-0	S-0		
SKL107			X	X				No Fix	EDRAM May Cause Unpredictable System Behavior
SKL109	X	X	X	X	X	X	X	No Fix	Enabling Package C8 State or Deeper May Lead to Display Flicker or a System Hang
SKL110			X	X				No Fix	System May Hang When EDRAM is Enabled And DDR is Operating at 1600 MHz
SKL111	X	X	X	X	X	X	X	No Fix	DR6.B0-B3 May Not Report All Breakpoints Matched When a MOV/POP SS is Followed by a Store or an MMX Instruction
SKL112	X	X	X	X	X	X	X	No Fix	Package C3 Exit Latency May be Longer Than Expected Leading to Display Flicker
SKL113	X	X	X	X	X	X	X	No Fix	Processor DDR VREF Signals May Briefly Exceed JEDEC Spec When Entering S3 State
SKL114	X	X	X	X	X	X	X	No Fix	Complex Interactions With Internal Graphics May Impact Processor Responsiveness
SKL115	X	X	X	X	X	X	X	No Fix	#GP on Segment Selector Descriptor that Straddles Canonical Boundary May Not Provide Correct Exception Error Code
SKL116				X	X			No Fix	After a Package C10 Sleep State Exit, a Subsequent C8/C9 Exit May Cause System Hang
SKL117	X	X	X	X	X	X	X	No Fix	Performance Monitoring Counters May Undercount When Using CPL Filtering
SKL118	X	X	X	X	X	X	X	No Fix	Memory Controller CKE Signal May Not be Expected Value When Executing Boundary Scan EXTEST Command
SKL119	X	X	X	X	X	X	X	No Fix	Certain Non-Canonical IA32_BNDCFGS Values Will Not Cause VM-Entry Failures
SKL120	X	X	X	X	X	X	X	No Fix	PEBS Eventing IP Field May Be Incorrect Under Certain Conditions
SKL121	X	X	X	X	X	X	X	No Fix	Executing a 256-Bit AVX Instruction May Cause Unpredictable Behavior
SKL122	X	X	X	X	X	X	X	No Fix	HWP's Guaranteed Performance Updated Only on Configurable TDP Changes
SKL123	X	X	X	X	X	X	X	No Fix	Core and/or Ring Frequency May be Briefly Lower Than Expected After BIOS Completes
SKL124	X	X	X	X	X	X	X	No Fix	RF May be Incorrectly Set in The EFLAGS That is Saved on a Fault in PEBS or BTS



Number	Processor Line / Stepping							Status	Title
	Y	U		H		S			
	D-1	D-1	K-1	N-0	R-0	R-0	S-0		
SKL125	X	X	X	X	X	X	X	No Fix	Intel® PT ToPA PMI Does Not Freeze Performance Monitoring Counters
SKL126	X	X	X	X	X	X	X	No Fix	HWP's Maximum Performance Value is Reset to 0xFF
SKL127	X	X	X	X	X	X	X	No Fix	HWP's Guaranteed Performance and Relevant Status/Interrupt May be Updated More Than Once Per Second
SKL128	X	X	X	X	X	X	X	No Fix	Some Memory Performance Monitoring Events May Produce Incorrect Results When Filtering on Either OS or USR Modes
SKL129	X	X	X	X	X	X	X	No Fix	HWP May Generate Thermal Interrupt While Not Enabled
SKL130	X	X	X	X	X	X	X	No Fix	Camera Device Does Not Issue an MSI When INTx is Enabled
SKL131	X	X	X	X	X	X	X	No Fix	An x87 Store Instruction Which Pends #PE May Lead to Unexpected Behavior When EPT A/D is Enabled.
SKL132				X				No Fix	System Hang or Machine Check May Occur When eDRAM Enabled
SKL133	X	X	X	X	X	X	X	No Fix	RING PERF LIMIT REASONS May be Incorrect
SKL134	X	X	X	X	X	X	X	No Fix	BNDLDX And BNDSTX May Not Signal #GP on Non-Canonical Bound Directory Access
SKL135						X	X	No Fix	DDR4 DTS Temperature Reading May be Inaccurate
SKL136	X	X	X	X	X	X	X	No Fix	Performance Monitoring Load Latency Events May Be Inaccurate For Gather Instructions
SKL137	X	X	X	X	X	X	X	No Fix	N/A. Erratum has been removed
SKL138	X	X	X					No Fix	N/A. Erratum has been removed
SKL139	X	X	X	X	X	X	X	No Fix	Some Bits in MSR_MISC_PWR_MGMT May be Updated on Writing Illegal Values to This MSR
SKL140	X	X	X	X	X	X	X	No Fix	Violations of Intel® Software Guard Extensions (Intel® SGX) Access-Control Requirements Produce #GP Instead of #PF
SKL141	X	X	X	X	X	X	X	No Fix	IA32_RTIT_CR3_MATCH MSR Bits[11:5] Are Treated As Reserved



Number	Processor Line / Stepping							Status	Title
	Y	U		H		S			
	D-1	D-1	K-1	N-0	R-0	R-0	S-0		
SKL142	X	X	X	X	X	X	X	No Fix	APIC Timer Interrupt May Not be Generated at The Correct Time In TSC-Deadline Mode
SKL143	-	-	-	-	-	-	-	-	Removed. Duplicate of Erratum SKL139
SKL144	X	X	X					No Fix	Unpredictable System Behavior May Occur When System Agent Enhanced Intel® Speedstep® is Enabled
SKL145	X	X	X	X	X	X	X	No Fix	Processor May Hang Under Complex Scenarios
SKL146	X	X	X	X	X	X	X	No Fix	The Intel PT CR3 Filter is Not Re-evaluated on VM Entry
SKL147	X	X	X	X	X	X	X	No Fix	Display Slowness May be Observed Under Certain Display Commands Scenario
SKL148	X	X	X	X	X	X	X	No Fix	CPUID TLB Associativity Information is Inaccurate
SKL149	X	X	X	X	X	X	X	No Fix	Processor Graphics May Render Incorrectly or May Hang Following Warm Reset With Package C8 Disabled
SKL150	X	X	X	X	X	X	X	No Fix	Short Loops Which Use AH/BH/CH/DH Registers May Cause Unpredictable System Behavior
SKL151	X	X	X	X	X	X	X	No Fix	Processor Graphics May Render Incorrectly or May Hang Following Warm Reset With Package C8 Disabled
SKL152	X	X	X	X	X	X	X	No Fix	Unpredictable System Behavior May Occur in DDR4 Multi-Rank System
SKL153	X	X	X	X	X	X	X	No Fix	Processor May Hang on Complex Sequence of Conditions
SKL154	X	X	X	X	X	X	X	No Fix	Intel® SGX Vulnerability May Impact Enclave Security
SKL155	X	X	X	X	X	X	X	No Fix	MOVNTDQA From WC Memory May Pass Earlier Locked Instructions
SKL156	X	X	X	X	X	X	X	No Fix	Spurious Corrected Errors May be Reported
SKL157	X	X	X	X	X	X	X	No Fix	Masked Bytes in a Vector Masked Store Instructions May Cause Write Back of a Cache Line
SKL158	X	X	X	X	X	X	X	No Fix	WRMSR to IA32 BIOS_UPDT_TRIG Concurrent With an SMX_SENTER/SEXIT May Result in a System Hang
SKL159	X	X	X	X	X	X	X	No Fix	Use of VMASKMOV to Store When Using EPT May Fail



Number	Processor Line / Stepping							Status	Title
	Y	U		H		S			
	D-1	D-1	K-1	N-0	R-0	R-0	S-0		
SKL160	X	X	X	X	X	X	X	No Fix	Writing Non-Zero Values to Read Only Fields in IA32_THERM_STATUS MSR May #GP
SKL161	X	X	X	X	X	X	X	No Fix	Precise Performance Monitoring May Generate Redundant PEBS Records
SKL162	X	X	X	X	X	X	X	No Fix	SGX ENCLS[EINIT] May Not Signal an Error For an Incorrectly Formatted SIGSTRUCT Input
SKL163	X	X	X	X	X	X	X	No Fix	Branch Instruction Address May be Incorrectly Reported on TSX Abort When Using MPX
SKL164	X	X	X	X	X	X	X	No Fix	Setting Performance Monitoring IA32_PERF_GLOBAL_STATUS_SET MSR Bit 63 May Not #GP
SKL165	X	X	X	X	X	X	X	No Fix	Hitting a Code Breakpoint Inside a SGX Debug Enclave May Cause The Processor to Hang
SKL166	X	X	X	X	X	X	X	No Fix	Performance Monitoring ASCI Status Bit May be Inaccurate
SKL167	X	X	X	X	X	X	X	No Fix	Processor May Hang When Executing Code In an HLE Transaction
SKL168	X	X	X	X	X	X	X	No Fix	Intel® PT CYC Packets Can be Dropped When Immediately Preceding PSB
SKL169	X	X	X	X	X	X	X	No Fix	Intel® PT VM-entry Indication Depends on The Incorrect VMCS Control Field
SKL170	X	X	X	X	X	X	X	No Fix	VCVTPS2PH To Memory May Update MXCSR in The Case of a Fault on The Store
SKL171	X	X	X	X	X	X	X	No Fix	Intel® PT May Drop All Packets After an Internal Buffer Overflow
SKL172	X	X	X	X	X	X	X	No Fix	Intel® PT ToPA Tables Read From Non-Cacheable Memory During an Intel® TSX Transaction May Lead to Processor Hang
SKL173	X	X	X	X	X	X	X	No Fix	Performing an XACQUIRE to an Intel® PT ToPA Table May Lead to Processor Hang
SKL174	X	X	X	X	X	X	X	No Fix	ZMM/YMM Registers May Contain Incorrect Values
SKL175	X	X	X	X	X	X	X	No Fix	Intel® PT CYC Packet Can be Dropped When Immediately Preceding PSB
SKL176	X	X	X	X	X	X	X	No Fix	When Virtualization Exceptions are Enabled, EPT Violations May Generate Erroneous Virtualization Exceptions



Number	Processor Line / Stepping							Status	Title
	Y	U		H		S			
	D-1	D-1	K-1	N-0	R-0	R-0	S-0		
SKL177	X	X	X	X	X	X	X	No Fix	System May Hang With Multiple Pending Posted Writes When Using Direct MMIO Write Access Model
SKL178	X	X	X	X	X	X	X	No Fix	Using Intel® TSX Instructions May Lead to Unpredictable System Behavior.
SKL179	X	X	X	X	X	X	X	No Fix	Performance Monitoring General Purpose Counter 3 May Contain Unexpected Values
SKL180	X	X	X	X	X	X	X	No Fix	Unexpected Uncorrected Machine Check Errors May Be Reported
SKL181	X	X	X	X	X	X	X	No Fix	Intel® PT Trace May Drop Second Byte of CYC Packet
SKL182	X	X	X	X	X	X	X	No Fix	Executing Some Instructions May Cause Unpredictable Behavior
SKL183	X	X	X	X	X	X	X	No Fix	A Pending Fixed Interrupt May Be Dispatched Before an Interrupt of The Same Priority Completes
SKL184	X	X	X	X	X	X	X	No Fix	Incorrect Execution of Internal Branch Instructions May Lead to Unpredictable System Behavior
SKL185	X	X	X	X	X	X	X	Plan Fix	Processor May Behave Unpredictably on Complex Sequence of Conditions Which Involve Branches That Cross 64 Byte Boundaries
SKL186	X	X	X	X	X	X	X	No Fix	A PMI That Freezes LBRs Can Cause a Duplicate Entry in TOS
SKL187	X	X	X	X	X	X	X	No Fix	SGX Key Confidentiality May be Compromised
SKL188	X	X	X	X	X	X	X	No Fix	Unexpected Page Faults in Guest Virtualization Environment
SKL189	X	X	X	X	X	X	X	No Fix	System May Hang Under Complex Conditions
SKL190	X	X	X	X	X	X	X	No Fix	Instruction Fetch May Cause Machine Check if Page Size Was Changed Without Invalidation
SKL191				X	X	X	X	No Fix	PEG PCIe Link May Fail to Link When Resuming From PKG-C8
SKL192				X	X	X	X	No Fix	Incorrect ECC Errors Reporting Following Entry to PKG-C7
SKL193	X	X	X	X	X	X	X	No Fix	PMU MSR UNC PERF FIXED_CTR is Cleared After Pkg C7 or Deeper



Number	Processor Line / Stepping							Status	Title
	Y	U		H		S			
	D-1	D-1	K-1	N-0	R-0	R-0	S-0		
SKL194	X	X	X	X	X	X	X	No Fix	Performance Monitoring General Counter 2 May Have Invalid Value Written When TSX Is Enabled
SKL195	X	X	X	X	X	X	X	No Fix	Display VT-d TLB invalidation during disabling of VTd Translations May Cause Display Corruption or Flickering
SKL 196	X	X	X	X	X	X	X	No Fix	Processor May Hang if Warm Reset Triggers During BIOS Initialization
SKL 197	X	X	X	X	X	X	X	No Fix	Erratum has been removed
SKL198	X	X	X	X	X	X	X	No Fix	MD_CLEAR Operations May Not Properly Overwrite All Buffers
Notes: 1. Affects 6th Generation Intel® Pentium® processor family and Intel® Celeron® processor family. 2. Affects 6th Generation Intel® Core™ i3 U/H/S, Intel® Pentium®, Intel® Celeron®, Intel® Pentium® G4xxx and Intel® Celeron® G3xxx Processors. 3. Affects 6th Generation Intel® Core™ i7 & i5 Desktop and Intel® Xeon® E3-1200 v5 Family Processors. 4. Processor line and Stepping information: – Y-Processor Line stepping: D-1 (Mobile) – U-Processor Line stepping: D-1 (Mobile) / K-1 (Mobile) – H-Processor Line stepping: N-0 (Mobile / Desktop)/ R-0 (Mobile / Desktop) – S-Processor Line stepping: R-0 (Desktop) / S-0 (Desktop)									



Identification Information

Component Identification via Programming Interface

The processor stepping can be identified by the following register contents:

Table 2. Y/U-Processor Lines Component Identification

Reserved	Extended Family	Extended Model	Reserved	Processor Type	Family Code	Model Number	Stepping ID
31:28	27:20	19:16	15:14	13:12	11:8	7:4	3:0
	0000000b	0100b		00b	0110b	1110b	xxxxb

Table 3. H/S-Processor Lines Component Identification

Reserved	Extended Family	Extended Model	Reserved	Processor Type	Family Code	Model Number	Stepping ID
31:28	27:20	19:16	15:14	13:12	11:8	7:4	3:0
	0000000b	0101b		00b	0110b	1110b	xxxxb

NOTES:


1. The Extended Family, Bits [27:20] are used in conjunction with the Family Code, specified in Bits[11:8], to indicate whether the processor belongs to the Intel386™, Intel486™, Pentium®, Pentium 4, or Intel® Core™ processor family.
2. The Extended Model, Bits [19:16] in conjunction with the Model Number, specified in Bits [7:4], are used to identify the model of the processor within the processor's family.
3. The Family Code corresponds to Bits [11:8] of the EDX register after RESET, Bits [11:8] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the generation field of the Device ID register accessible through Boundary Scan.
4. The Model Number corresponds to Bits [7:4] of the EDX register after RESET, Bits [7:4] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the model field of the Device ID register accessible through Boundary Scan.
5. The Stepping ID in Bits [3:0] indicates the revision number of that model. See Table 1 for the processor stepping ID number in the CPUID information.
6. When EAX is initialized to a value of '1', the CPUID instruction returns the Extended Family, Extended Model, Processor Type, Family Code, Model Number and Stepping ID value in the EAX register. Note that the EDX processor signature value after reset is equivalent to the processor signature output value in the EAX register.

Cache and TLB descriptor parameters are provided in the EAX, EBX, ECX, and EDX registers after the CPUID instruction is executed with a 2 in the EAX register.



Component Marking Information

Figure 1. Y-Processor Line BGA Top-Side Markings



Pin Count: 1515 Package Size: 20 mm x 16.5 mm

Production (SSPEC):


GRP1LINE1: FPOxxxxxSSPEC
 GRP2LINE1 (G2L1): Intel logo
 GRP3LINE1 (G3L1): {eX}

Table 4. Y-Processor Line

S-Spec #	Processor Number	Step-ping	Cache Size (MB)	Func-tional Core	Processor Graphics Cores	Processor Graphics Freq. (MHz)	Processor Graphics Turbo Freq. (MHz)	DDR3L Mem. (MHz)	LPDDR3 Mem. (MHz)	Core Freq. (MHz)	Turbo 1 Core Freq. Rate (MHz)	Thermal Design Power (W)	Slot / Socket Type
SR2ER	Pentium 4405Y	D-1	2	2	2	300	800	1600	1866	1500	1500	6	BGA1515
SR2EN	m3-6Y30	D-1	4	2	2	300	850	1600	1866	900	2200	4.5	BGA1515
SR2EM	m5-6Y54	D-1	4	2	2	300	900	1600	1866	1100	2700	4.5	BGA1515
SR2EH	m7-6Y75	D-1	4	2	2	300	1000	1600	1866	1200	3100	4.5	BGA1515
SR2EG	m5-6Y57	D-1	4	2	2	300	900	1600	1866	1100	2800	4.5	BGA1515



Figure 2. U-Processor Line BGA Top-Side Markings



Pin Count: 1356 Package Size: 42 mm x 24 mm

Sample (SSPEC):

GRP1LINE1: FPOxxxxxQxxx
 GRP2LINE1 (G2L1): {eX}
 GRP3LINE1 (G3L1): Intel logo


Table 5. U-Processor Line

S-Spec #	Processor Number	Stepping	Cache Size (MB)	Functional Core	Processor Graphics Cores	Processor Graphics Freq. (MHz)	Processor Graphics Turbo Freq. (MHz)	DDR3L Mem. (MHz)	DDR4 Mem. (MHz)	LPDDR3 Mem. (MHz)	Core Freq. (MHz)	Turbo 1 Core Freq. Rate (MHz)	Thermal Design Power (W)	Slot / Socket Type
SR2F0	i5-6300U	D-1	3	2	2	300	1000	1600	2133	1866	2400	3000	15	BGA1356
SR2F1	i7-6600U	D-1	4	2	2	300	1050	1600	2133	1866	2600	3400	15	BGA1356
SR2EY	i5-6200U	D-1	3	2	2	300	1000	1600	2133	1866	2300	2800	15	BGA1356
SR2EZ	i7-6500U	D-1	4	2	2	300	1050	1600	2133	1866	2500	3100	15	BGA1356
SR2EX	Pentium 4405U	D-1	2	2	1	300	950	1600	2133	1866	2100	2100	15	BGA1356
SR2EV	Celeron 3855U	D-1	2	2	1	300	900	1600	2133	1866	1600	1600	15	BGA1356
SR2EW	Celeron 3955U	D-1	2	2	1	300	900	1600	2133	1866	2000	2000	15	BGA1356
SR2EU	i3-6100U	D-1	3	2	2	300	1000	1600	2133	1866	2300	2300	15	BGA1356
SR2JB	i7-6560U	K-1	4	2	3	300	1050	1600	2133	1866	2200	3200	15	BGA1356
SR2JC	i5-6260U	K-1	4	2	3	300	950	1600	2133	1866	1800	2900	15	BGA1356



S-Spec #	Processor Number	Stepping	Cache Size (MB)	Functional Core	Processor Graphics Cores	Processor Graphics Freq. (MHz)	Processor Graphics Turbo Freq. (MHz)	DDR3L Mem. (MHz)	DDR4 Mem. (MHz)	LPDDR3 Mem. (MHz)	Core Freq. (MHz)	Turbo 1 Core Freq. Rate (MHz)	Thermal Design Power (W)	Slot / Socket Type
SR2JF	I3-6167U	K-1	3	2	3	300	1000	1600	2133	1866	2700	2700	28	BGA1356
SR2JH	I7-6567U	K-1	4	2	3	300	1100	1600	2133	1866	3300	3600	28	BGA1356
SR2JJ	I5-6287U	K-1	4	2	3	300	1100	1600	2133	1866	3100	3500	28	BGA1356
SR2JK	I5-6267U	K-1	4	2	3	300	1050	1600	2133	1866	2900	3300	28	BGA1356
SR2JM	I5-6360U	K-1	4	2	3	300	1000	1600	2133	1866	2000	3100	15	BGA1356
SR2KA	I7-6650U	K-1	4	2	3	300	1050	1600	2133	1866	2200	3400	15	BGA1356
SR2JL	I7-6660U	K-1	4	2	3	300	1050	1600	2133	1866	2400	3400	15	BGA1356

Figure 3. S-Processor Line LGA Top-Side Markings



Pin Count: 1151 Package Size: 37.5 mm x 37.5 mm

Sample (SSPEC):

GRP1LINE1: Intel logo
 GRP1LINE2: BRAND
 GRP1LINE3: PROC#
 GRP1LINE4: SSPEC SPEED
 GRP1LINE5: {FPO} {eX}



Table 6. S-Processor Line

S-Spec #	Processor Number	Step-ping	Cache Size (MB)	Func-tional Core	Processor Graphics Cores	Processor Graphics Freq. (MHz)	Processor Graphics Turbo Freq. (MHz)	DDR4 Mem. (MHz)	DDR3L Mem. (MHz)	Core Freq. (MHz)	Turbo 1 Core Freq. Rate (MHz)	Thermal Design Power (W)	Slot / Socket Type
SR2BR ¹	i7-6700K	R-0	8	4	2	350	1150	2133	1600	4000	4200	91	LGA1151
SR2BS ¹	i5-6400T	R-0	6	4	2	350	950	2133	1600	2200	2800	35	LGA1151
SR2BT ¹	i7-6700	R-0	8	4	2	350	1150	2133	1600	3400	4000	65	LGA1151
SR2BU ¹	i7-6700T	R-0	8	4	2	350	1100	2133	1600	2800	3600	35	LGA1151
SR2BV ¹	i5-6600K	R-0	6	4	2	350	1150	2133	1600	3500	3900	91	LGA1151
SR2BW ¹	i5-6600	R-0	6	4	2	350	1150	2133	1600	3300	3900	65	LGA1151
SR2BX ¹	i5-6500	R-0	6	4	2	350	1050	2133	1600	3200	3600	65	LGA1151
SR2BY ¹	i5-6400	R-0	6	4	2	350	950	2133	1600	2700	3300	65	LGA1151
SR2BZ ¹	i5-6500T	R-0	6	4	2	350	1100	2133	1600	2500	3100	35	LGA1151
SR2C0 ¹	i5-6600T	R-0	6	4	2	350	1100	2133	1600	2700	3500	35	LGA1151
SR2L0	I7-6700K	R-0	8	4	2	350	1150	2133	1600	4000	4100	95	LGA1151
SR2L1	I5-6400T	R-0	6	4	2	350	950	2133	1600	2200	2800	35	LGA1151
SR2L2	I7-6700	R-0	8	4	2	350	1150	2133	1600	3400	4000	65	LGA1151
SR2L3	I7-6700T	R-0	8	4	2	350	1100	2133	1600	2800	3600	35	LGA1151
SR2L4	I5-6600K	R-0	6	4	2	350	1150	2133	1600	3500	3900	95	LGA1151
SR2L5	I5-6600	R-0	6	4	2	350	1150	2133	1600	3300	3900	65	LGA1151
SR2L6	I5-6500	R-0	6	4	2	350	1050	2133	1600	3200	3600	65	LGA1151
SR2L7	I5-6400	R-0	6	4	2	350	950	2133	1600	2700	3300	65	LGA1151
SR2L8	I5-6500T	R-0	6	4	2	350	1100	2133	1600	2500	3100	35	LGA1151
SR2L9	I5-6600T	R-0	6	4	2	350	1100	2133	1600	2700	3500	35	LGA1151
SR2H9	i3-6320	S-0	4	2	2	350	1150	2133	1600	3900	N/A	51	LGA1151
SR2HA	i3-6300	S-0	4	2	2	350	1150	2133	1600	3800	N/A	51	LGA1151
SR2HG	i3-6100	S-0	3	2	2	350	1050	2133	1600	3700	N/A	51	LGA1151
SR2HM	G4520	S-0	3	2	2	350	1050	2133	1600	3600	N/A	51	LGA1151
SR2HJ	G4500	S-0	3	2	2	350	1050	2133	1600	3500	N/A	51	LGA1151
SR2DC	Pentium G4400	R-0	3	4	2	350	1000	2133	1600	3300	N/A	65	LGA1151
SR2HD	i3-6300T	S-0	4	2	2	350	950	2133	1600	3300	N/A	35	LGA1151
SR2HE	i3-6100T	S-0	3	2	2	350	950	2133	1600	3200	N/A	35	LGA1151
SR2HS	G4500T	S-0	3	2	2	350	950	2133	1600	3000	N/A	35	LGA1151




S-Spec #	Processor Number	Step-ping	Cache Size (MB)	Func-tional Core	Processor Graphics Cores	Processor Graphics Freq. (MHz)	Processor Graphics Turbo Freq. (MHz)	DDR4 Mem. (MHz)	DDR3L Mem. (MHz)	Core Freq. (MHz)	Turbo 1 Core Freq. Rate (MHz)	Thermal Design Power (W)	Slot / Socket Type
SR2HC	I3-6320T	S-0	4	2	2	350	950	2133	1600	3400	N/A	35	LGA1151
SR2HQ	G4400T	S-0	3	2	1	350	950	2133	1600	2900	N/A	35	LGA1151
SR2HK	Pentium G4400	S-0	3	2	1	350	1000	2133	1600	3300	N/A	65	LGA1151
SR2HT	Celeron G3900T	S-0	2	2	1	350	950	2133	1600	2600	N/A	35	LGA1151
SR2HV	Celeron G3900	S-0	2	2	1	350	950	2133	1600	2800	N/A	65	LGA1151
SR2HX	Celeron G3920	S-0	2	2	1	350	950	2133	1600	2900	N/A	65	LGA1151

NOTES:

- The following S-Spec is affected by erratum SKL067 which is being addressed by Product Change Notification (PCN) #114074.
- Intel is initiating new S-Spec and MM numbers for 6th Generation Intel® Core™ i7 & i5 desktop and the Intel® Xeon® E3-1200 v5 family processors for a minor manufacturing configuration change to allow customers to enable Intel® Software Guard Extensions (Intel® SGX) when using these processors.
 - The stepping will not change for these processors; it remains R-0.
 - The CPUID Processor Signature will not change for these processors; it remains 0x506E3.
 - Die size and package will not change for these processors.
 - Link to SKL-S 4+2 PCN #114074 (Product Change Notification) for new S-Specs: <http://qdm.intel.com/dm/i.aspx/5A160770-FC47-47A0-BF8A-062540456F0A/PCN114074-00.pdf>



Figure 4. H-Processor Line BGA Top-Side Markings



Pin Count: 1440 Package Size: 42 mm x 28 mm

Production (SSPEC):

GRP1LINE1 (G1L1): {eX}
 GRP2LINE1: FPOxxxxxSSPEC
 GRP3LINE1 (G3L1): Intel logo

Table 7. H-Processor Line

S-Spec #	Processor Number	Step- ping	Cache Size (MB)	Function al Core	Process or Graphic s Cores	Processor Graphics Freq. (MHz)	Processor Graphics Turbo Freq. (MHz)	DDR3L Mem. (MHz)	DDR4 Mem. (MHz)	LPDDR3 Mem. (MHz)	Core Freq. (MHz)	Turbo 1 Core Freq. Rate (MHz)	Thermal Design Power (W)	Slot / Socket Type
SR2FM	E3-1535MV5	R-0	8	4	2	350	1050	1600	2133	1866	2900	3800	45	BGA1440
SR2FT	i7-6920HQ	R-0	8	4	2	350	1050	1600	2133	1866	2900	3800	45	BGA1440
SR2FN	E3-1505MV5	R-0	8	4	2	350	1050	1600	2133	1866	2800	3700	45	BGA1440
SR2FU	i7-6820HQ	R-0	8	4	2	350	1050	1600	2133	1866	2700	3600	45	BGA1440
SR2FL	i7-6820HK	R-0	8	4	2	350	1050	1600	2133	1866	2700	3600	45	BGA1440
SR2FQ	i7-6700HQ	R-0	6	4	2	350	1050	1600	2133	1866	2600	3500	45	BGA1440
SR2FS	i5-6440HQ	R-0	6	4	2	350	950	1600	2133	1866	2600	3500	45	BGA1440
SR2FP	i5-6300HQ	R-0	6	4	2	350	950	1600	2133	1866	2300	3200	45	BGA1440
SR2FR	i3-6100H	R-0	3	2	2	350	900	1600	2133	1866	2700	2700	35	BGA1440
SR2QT	E3-1515MV5	N-0	8	4	4	350	1000	1600	2133	1866	2800	3700	45	BGA1440



S-Spec #	Processor Number	Stepping	Cache Size (MB)	Functional Core	Processor or Graphics Cores	Processor Graphics Freq. (MHz)	Processor Graphics Turbo Freq. (MHz)	DDR3L Mem. (MHz)	DDR4 Mem. (MHz)	LPDDR3 Mem. (MHz)	Core Freq. (MHz)	Turbo 1 Core Freq. Rate (MHz)	Thermal Design Power (W)	Slot / Socket Type
SR2QU	E3-1545MV5	N-0	8	4	4	350	1050	1600	2133	1866	2900	3800	45	BGA1440
SR2QV	E3-1575MV5	N-0	8	4	4	350	1100	1600	2133	1866	3000	3900	45	BGA1440
SR2R8	E3-1565LV5	N-0	8	4	4	350	1050	1600	2133	1866	2500	3500	35	BGA1440
SR2R9	E3-1585LV5	N-0	8	4	4	350	1150	1600	2133	1866	3000	3700	45	BGA1440
SR2RB	E3-1585V5	N-0	8	4	4	350	1150	1600	2133	1866	3500	3900	65	BGA1440
SR2TT	E3-1578V5	N-0	8	4	4	700	1000	1600	2133	1866	2000	3400	45	BGA1440
SR2TU	E3-1558LV5	N-0	8	4	3	650	1000	1600	2133	1866	1900	3300	45	BGA1440
SR2QW	i7-6970HQ	N-0	8	4	4	350	1050	1600	2133	1866	2800	3700	45	BGA1440
SR2QX	i7-6870HQ	N-0	8	4	4	350	1000	1600	2133	1866	2700	3600	45	BGA1440
SR2QY	i7-6770HQ	N-0	6	4	4	350	950	1600	2133	1866	2600	3500	45	BGA1440
SR2QZ	I5-6350HQ	N-0	6	4	4	350	900	1600	2133	1866	2300	3200	45	BGA1440



Errata

SKL001	Reported Memory Type May Not Be Used to Access the VMCS and Referenced Data Structures
Problem	Bits 53:50 of the IA32_VMX_BASIC MSR report the memory type that the processor uses to access the VMCS and data structures referenced by pointers in the VMCS. Due to this erratum, a VMX access to the VMCS or referenced data structures will instead use the memory type that the MTRRs (memory-type range registers) specify for the physical address of the access.
Implication	Bits 53:50 of the IA32_VMX_BASIC MSR report that the WB (write-back) memory type will be used but the processor may use a different memory type.
Workaround	Software should ensure that the VMCS and referenced data structures are located at physical addresses that are mapped to WB memory type by the MTRRs.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL002	Instruction Fetch May Cause Machine Check if Page Size and Memory Type Was Changed Without Invalidation
Problem	This erratum may cause a machine-check error (IA32_MCI_STATUS.MCACOD=0150H) on the fetch of an instruction that crosses a 4-KByte address boundary. It applies only if (1) the 4-KByte linear region on which the instruction begins is originally translated using a 4-KByte page with the WB memory type; (2) the paging structures are later modified so that linear region is translated using a large page (2-MByte, 4-MByte, or 1-GByte) with the UC memory type; and (3) the instruction fetch occurs after the paging-structure modification but before software invalidates any TLB entries for the linear region.
Implication	Due to this erratum an unexpected machine check with error code 0150H may occur, possibly resulting in a shutdown. Intel has not observed this erratum with any commercially available software.
Workaround	Software should not write to a paging-structure entry in a way that would change, for any linear address, both the page size and the memory type. It can instead use the following algorithm: first clear the P flag in the relevant paging-structure entry (e.g., PDE); then invalidate any translations for the affected linear addresses; and then modify the relevant paging-structure entry to set the P flag and establish the new page size and memory type.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL003	Execution of VAESIMC or VAESKEYGENASSIST With An Illegal Value for VEX.vvvv May Produce a #NM Exception
Problem	The VAESIMC and VAESKEYGENASSIST instructions should produce a #UD (Invalid-Opcode) exception if the value of the vvvv field in the VEX prefix is not 1111b. Due to this erratum, if CR0.TS is "1", the processor may instead produce a #NM (Device-Not-Available) exception.
Implication	Due to this erratum, some undefined instruction encodings may produce a #NM instead of a #UD exception.
Workaround	Software should always set the vvvv field of the VEX prefix to 1111b for instances of the VAESIMC and VAESKEYGENASSIST instructions.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL004	The Corrected Error Count Overflow Bit in IA32_MC0_STATUS is Not Updated When The UC Bit is Set
Problem	After a UC (uncorrected) error is logged in the IA32_MC0_STATUS MSR (401H), corrected errors will continue to be counted in the lower 14 bits (bits 51:38) of the Corrected Error Count. Due to this erratum, the sticky count overflow bit (bit 52) of the Corrected Error Count will not get updated when the UC bit (bit 61) is set to 1.
Implication	The Corrected Error Count Overflow indication will be lost if the overflow occurs after an uncorrectable error has been logged.
Workaround	None identified
Status	For the stepping's affected, see the Summary Table of Changes.

SKL005	VM Exit May Set IA32_EFER.NXE When IA32_MISC_ENABLE Bit 34 is Set to 1
Problem	When "XD Bit Disable" in the IA32_MISC_ENABLE MSR (1A0H) bit 34 is set to 1, it should not be possible to enable the "execute disable" feature by setting IA32_EFER.NXE. Due to this erratum, a VM exit that occurs with the 1-setting of the "load IA32_EFER" VM-exit control may set IA32_EFER.NXE even if IA32_MISC_ENABLE bit 34 is set to 1. This erratum can occur only if IA32_MISC_ENABLE bit 34 was set by guest software in VMX non-root operation.
Implication	Software in VMX root operation may execute with the "execute disable" feature enabled despite the fact that the feature should be disabled by the IA32_MISC_ENABLE MSR. Intel has not observed this erratum with any commercially available software.
Workaround	A virtual-machine monitor should not allow guest software to write to the IA32_MISC_ENABLE MSR
Status	For the stepping's affected, see the Summary Table of Changes.



SKL006	SMRAM State-Save Area Above the 4GB Boundary May Cause Unpredictable System Behavior
Problem	If BIOS uses the RSM instruction to load the SMBASE register with a value that would cause any part of the SMRAM state-save area to have an address above 4-GBytes, subsequent transitions into and out of SMM (system-management mode) might save and restore processor state from incorrect addresses.
Implication	This erratum may cause unpredictable system behavior. Intel has not observed this erratum with any commercially available system.
Workaround	Ensure that the SMRAM state-save area is located entirely below the 4GB address boundary.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL007	x87 FPU Exception (#MF) May be Signaled Earlier Than Expected
Problem	x87 instructions that trigger #MF normally service interrupts before the #MF. Due to this erratum, if an instruction that triggers #MF is executing when an Enhanced Intel SpeedStep® Technology transitions, an Intel® Turbo Boost Technology transitions, or a Thermal Monitor event occurs, the #MF may be taken before pending interrupts are serviced.
Implication	Software may observe #MF being signaled before pending interrupts are serviced.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL008	Incorrect FROM_IP Value For an RTM Abort in BTM or BTS May be Observed
Problem	During RTM (Restricted Transactional Memory) operation when branch tracing is enabled using BTM (Branch Trace Message) or BTS (Branch Trace Store), the incorrect EIP value (From_IP pointer) may be observed for an RTM abort.
Implication	Due to this erratum, the From_IP pointer may be the same as that of the immediately preceding taken branch.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL009	DR6 Register May Contain an Incorrect Value When a MOV to SS or POP SS Instruction is Followed by an XBEGIN Instruction
Problem	If XBEGIN is executed immediately after an execution of MOV to SS or POP SS, a transactional abort occurs and the logical processor restarts execution from the fallback instruction address. If execution of the instruction at that address causes a debug exception, bits [3:0] of the DR6 register may contain an incorrect value.
Implication	When the instruction at the fallback instruction address causes a debug exception, DR6 may report a breakpoint that was not triggered by that instruction, or it may fail to report a breakpoint that was triggered by the instruction.
Workaround	Avoid following a MOV SS or POP SS instruction immediately with an XBEGIN instruction.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL010	Opcode Bytes F3 0F BC May Execute As TZCNT Even When TZCNT Not Enumerated by CPUID
Problem	If CPUID.(EAX=07H, ECX=0):EBX.BMI1 (bit 3) is 1 then opcode bytes F3 0F BC should be interpreted as TZCNT otherwise they will be interpreted as REP BSF. Due to this erratum, opcode bytes F3 0F BC may execute as TZCNT even if CPUID.(EAX=07H, ECX=0):EBX.BMI1 (bit 3) is 0.
Implication	Software that expects REP prefix before a BSF instruction to be ignored may not operate correctly since there are cases in which BSF and TZCNT differ with regard to the flags that are set and how the destination operand is established.
Workaround	Software should use the opcode bytes F3 0F BC only if CPUID.(EAX=07H, ECX=0):EBX.BMI1 (bit 3) is 1 and only if the functionality of TZCNT (and not BSF) is desired.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL011	PCIe* Root-port Initiated Compliance State Transmitter Equalization Settings May be Incorrect
Problem	If the processor is directed to enter PCIe Polling.Compliance at 5.0 GT/s or 8.0 GT/s transfer rates, it should use the Link Control 2 Compliance Preset/De-emphasis field (bits [15:12]) to determine the correct de-emphasis level. Due to this erratum, when the processor is directed to enter Polling.Compliance from 2.5 GT/s transfer rate, it retains 2.5 GT/s de-emphasis values.
Implication	The processor may operate in Polling.Compliance mode with an incorrect transmitter de-emphasis level.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL012	The SMSW Instruction May Execute Within an Enclave
Problem	The SMSW instruction is illegal within an SGX (Software Guard Extensions) enclave, and an attempt to execute it within an enclave should result in a #UD (invalid-opcode exception). Due to this erratum, the instruction executes normally within an enclave and does not cause a #UD.
Implication	The SMSW instruction provides access to CR0 bits 15:0 and will provide that information inside an enclave. These bits include NE, ET, TS, EM, MP and PE.
Workaround	None identified. If SMSW execution inside an enclave is unacceptable, system software should not enable SGX.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL013	PEBS Record After a WRMSR to IA32_BIOS_UPDT_TRIG May be Incorrect
Problem	A PEBS record generated by a WRMSR to IA32_BIOS_UPDT_TRIG MSR (79H) may have an incorrect value in the Eventing EIP field if an instruction prefix was used on the WRMSR.
Implication	The Eventing EIP field of the generated PEBS record may be incorrect. Intel has not observed this erratum with any commercially available software.
Workaround	Instruction prefixes have no architecturally-defined function for the WRMSR instruction; instruction prefixes should not be used with the WRMSR instruction.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL014	Intel® PT TIP.PGD May Not Have Target IP Payload
Problem	When Intel PT (Intel Processor Trace) is enabled and a direct unconditional branch clears IA32_RTIT_STATUS.FilterEn (MSR 571H, bit 0), due to this erratum, the resulting TIP.PGD (Target IP Packet, Packet Generation Disable) may not have an IP payload with the target IP.
Implication	It may not be possible to tell which instruction in the flow caused the TIP.PGD using only the information in trace packets when this erratum occurs.
Workaround	The Intel PT trace decoder can compare direct unconditional branch targets in the source with the FilterEn address range(s) to determine which branch cleared FilterEn.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL015	Operand-Size Override Prefix Causes 64-bit Operand Form of MOVBE Instruction to Cause a #UD
Problem	Execution of a 64 bit operand MOVBE instruction with an operand-size override instruction prefix (66H) may incorrectly cause an invalid-opcode exception (#UD).
Implication	A MOVBE instruction with both REX.W=1 and a 66H prefix will unexpectedly cause an #UD (invalid-opcode exception). Intel has not observed this erratum with any commercially available software.
Workaround	Do not use a 66H instruction prefix with a 64-bit operand MOVBE instruction.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL016	Execution of FXSAVE or FXRSTOR With the VEX Prefix May Produce a #NM Exception
Problem	Attempt to use FXSAVE or FXRSTOR with a VEX prefix should produce a #UD (Invalid-Opcode) exception. If either the TS or EM flag bits in CR0 are set, a #NM (device-not-available) exception will be raised instead of #UD exception.
Implication	Due to this erratum a #NM exception may be signaled instead of a #UD exception on an FXSAVE or an FXRSTOR with a VEX prefix.
Workaround	Software should not use FXSAVE or FXRSTOR with the VEX prefix.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL017	WRMSR May Not Clear The Sticky Count Overflow Bit in The IA32_MCI_STATUS MSRs' Corrected Error Count Field
Problem	The sticky count overflow bit is the most significant bit (bit 52) of the Corrected Error Count Field (bits[52:38]) in IA32_MCI_STATUS MSRs. Once set, the sticky count overflow bit may not be cleared by a WRMSR instruction. When this occurs, that bit can only be cleared by power-on reset.
Implication	Software that uses the Corrected Error Count field and expects to be able to clear the sticky count overflow bit may misinterpret the number of corrected errors when the sticky count overflow bit is set. This erratum does not affect threshold-based CMCI (Corrected Machine Check Error Interrupt) signaling.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL018	PEBS Eventing IP Field May be Incorrect After Not-Taken Branch
Problem	When a PEBS (Precise-Event-Based-Sampling) record is logged immediately after a not-taken conditional branch (Jcc instruction), the Eventing IP field should contain the address of the first byte of the Jcc instruction. Due to this erratum, it may instead contain the address of the instruction preceding the Jcc instruction.
Implication	Performance monitoring software using PEBS may incorrectly attribute PEBS events that occur on a Jcc to the preceding instruction.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL019	Debug Exceptions May Be Lost or Misreported Following WRMSR to IA32_BIOS_UPDT_TRIG
Problem	If the WRMSR instruction writes to the IA32_BIOS_UPDT_TRIG MSR (79H) immediately after an execution of MOV SS or POP SS that generated a debug exception, the processor may fail to deliver the debug exception or, if it does, the DR6 register contents may not correctly reflect the causes of the debug exception.
Implication	Debugging software may fail to operate properly if a debug exception is lost or does not report complete information.
Workaround	Software should avoid using WRMSR instruction immediately after executing MOV SS or POP SS
Status	For the stepping's affected, see the Summary Table of Changes.

SKL020	Attempts to Retrain a PCIe* Link May be Ignored
Problem	A PCIe link should retrain when Retrain Link (bit 5) in the Link Control register (Bus 0; Device 1; Functions 0, 1, 2; Offset 0xB0) is set. Due to this erratum, if the link is in the L1 state, it may ignore the retrain request.
Implication	The PCIe link may not behave as expected.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL021	Intel® Processor Trace PSB+ Packets May Contain Unexpected Packets
Problem	Some Intel Processor Trace packets should be issued only between TIP.PGE (Target IP Packet.Packet Generation Enable) and TIP.PGD (Target IP Packet.Packet Generation Disable) packets. Due to this erratum, when a TIP.PGE packet is generated it may be preceded by a PSB+ (Packet Stream Boundary) that incorrectly includes FUP (Flow Update Packet) and MODE.Exec packets.
Implication	Due to this erratum, FUP and MODE.Exec may be generated unexpectedly.
Workaround	Decoders should ignore FUP and MODE.Exec packets that are not between TIP.PGE and TIP.PGD packets.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL022	An APIC Timer Interrupt During Core C6 Entry May be Lost
Problem	Due to this erratum, an APIC timer interrupt coincident with the core entering C6 state may be lost rather than held for servicing later.
Implication	A lost APIC timer interrupt may lead to missed deadlines or a system hang.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL023	Placing an Intel® PT ToPA in Non-WB Memory or Writing It Within a Transactional Region May Lead to System Instability
SKL023	N/A. Erratum has been removed.

SKL024	VM Entry That Clears TraceEn May Generate a FUP
Problem	If VM entry clears Intel® PT (Intel Processor Trace) IA32_RTIT_CTL.TraceEn (MSR 570H, bit 0) while PacketEn is 1 then a FUP (Flow Update Packet) will precede the TIP.PGD (Target IP Packet, Packet Generation Disable). VM entry can clear TraceEn if the VM-entry MSR-load area includes an entry for the IA32_RTIT_CTL MSR.
Implication	When this erratum occurs, an unexpected FUP may be generated that creates the appearance of an asynchronous event taking place immediately before or during the VM entry.
Workaround	The Intel PT trace decoder may opt to ignore any FUP whose IP matches that of a VM entry instruction.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL025	EDRAM Corrected Error Events May Not be Properly Logged After a Warm Reset
Problem	After a warm reset, an EDRAM corrected error may not be logged correctly until the associated machine check register is initialized. This erratum may affect IA32_MC8_STATUS or IA32_MC10_STATUS.
Implication	The EDRAM corrected error information may be lost when this erratum occurs.
Workaround	Data from the affected machine check registers should be read and the registers initialized as soon as practical after a warm reset.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL026	Performance Monitor Event For Outstanding Offcore Requests May be Incorrect
Problem	The performance monitor event OFFCORE_REQUESTS_OUTSTANDING (Event 60H, any Umask Value) should count the number of offcore outstanding transactions each cycle. Due to this erratum, the counts may be higher or lower than expected.
Implication	The performance monitor event OFFCORE_REQUESTS_OUTSTANDING may reflect an incorrect count.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL027	Processor Instability May Occur When Using The PECI RdIAMSRR Command
Problem	Under certain circumstances, reading a machine check register using the PECI (Platform Environmental Control Interface) RdIAMSRR command may result in a machine check, processor hang or shutdown.
Implication	Machine check, hang or shutdown may be observed when using the PECI RdIAMSRR command.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL028	ENCLU[EGETKEY] Ignores KEYREQUEST.MISCMASK
Problem	The Intel® SGX (Software Guard Extensions) ENCLU[EGETKEY] instruction ignores the MISCMASK field in KEYREQUEST structure when computing a provisioning key, a provisioning seal key, or a seal key.
Implication	ENCLU[EGETKEY] will return the same key in response to two requests that differ only in the value of KEYREQUEST.MISCMASK. Intel has not observed this erratum with any commercially available software.
Workaround	When executing the ENCLU[EGETKEY] instruction, software should ensure the bits set in KEYREQUEST.MISCMASK are a subset of the bits set in the current SECS's MISCSELECT field.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL029	POPCNT Instruction May Take Longer to Execute Than Expected
Problem	POPCNT instruction execution with a 32 or 64 bit operand may be delayed until previous non-dependent instructions have executed.
Implication	Software using the POPCNT instruction may experience lower performance than expected.
Workaround	None identified
Status	For the stepping's affected, see the Summary Table of Changes.

SKL030	ENCLU[EREPORTR] May Cause a #GP When TARGETINFO.MISCSELECT is Non-Zero
Problem	The Intel® SGX (Software Guard extensions) ENCLU[EREPORTR] instruction may cause a #GP (general protection fault) if any bit is set in TARGETINFO structure's MISCSELECT field.
Implication	This erratum may cause unexpected general-protection exceptions inside enclaves.
Workaround	When executing the ENCLU[EREPORTR] instruction, software should ensure the bits set in TARGETINFO.MISCSELECT are a subset of the bits set in the current SECS's MISCSELECT field.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL031	A VMX Transition Attempting to Load a Non-Existent MSR May Result in a Shutdown
Problem	A VMX transition may result in a shutdown (without generating a machine-check event) if a non-existent MSR is included in the associated MSR-load area. When such a shutdown occurs, a machine check error will be logged with IA32_MCI_STATUS.MCACOD (bits [15:0]) of 406H, but the processor does not issue the special shutdown cycle. A hardware reset must be used to restart the processor.
Implication	Due to this erratum, the hypervisor may experience an unexpected shutdown.
Workaround	Software should not configure VMX transitions to load non-existent MSRs.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL032	Transitions Out of 64-bit Mode May Lead to an Incorrect FDP And FIP
Problem	A transition from 64-bit mode to compatibility or legacy modes may result in cause a subsequent x87 FPU state save to zeroing bits [63:32] of the FDP (x87 FPU Data Pointer Offset) and the FIP (x87 FPU Instruction Pointer Offset).
Implication	Leaving 64-bit mode may result in incorrect FDP and FIP values when x87 FPU state is saved.
Workaround	None identified. 64-bit software should save x87 FPU state before leaving 64-bit mode if it needs to access the FDP and/or FIP values.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL033	Intel® PT FUP May be Dropped After OVF
Problem	Some Intel PT (Intel Processor Trace) OVF (Overflow) packets may not be followed by a FUP (Flow Update Packet) or TIP.PGE (Target IP Packet, Packet Generation Enable).
Implication	When this erratum occurs, an unexpected packet sequence is generated.
Workaround	When it encounters an OVF without a following FUP or TIP.PGE, the Intel PT trace decoder should scan for the next TIP, TIP.PGE, or PSB+ to resume operation.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL034	ENCLS[ECREATE] Causes #GP if Enclave Base Address is Not Canonical
Problem	The ENCLS[ECREATE] instruction uses an SECS (SGX enclave control structure) referenced by the SRCPAGE pointer in the PAGEINFO structure, which is referenced by the RBX register. Due to this erratum, the instruction causes a #GP (general-protection fault) if the SECS attributes indicate that the enclave should operate in 64-bit mode and the enclave base linear address in the SECS is not canonical.
Implication	System software will incur a general-protection fault if it mistakenly programs the SECS with a non-canonical address. Intel has not observed this erratum with any commercially available software.
Workaround	System software should always specify a canonical address as the base address of the 64-bit mode enclave.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL035	Data Breakpoint May Not be Detected on a REP MOVS
Problem	A REP MOVS instruction that causes an exception or a VM exit may not detect a data breakpoint that occurred on an earlier memory access of that REP MOVS instruction.
Implication	A debugger may miss a data read/write access if it is done by a REP MOVS instruction
Workaround	Software that relies on data breakpoint for correct execution should disable fast-strings (bit 0 in IA32_MISC_ENABLE MSR).
Status	For the steppings affected, see the Summary Table of Changes.

SKL036	Graphics VTd Hardware May Cache Invalid Entries
Problem	The processor's graphics IOMMU (I/O Memory Management Unit) may cache invalid VTd context entries. This violates the VTd specification for HW Caching Mode where hardware implementations of this architecture must not cache invalid entries.
Implication	Due to this erratum, unpredictable system behavior and/or a system hang may occur.
Workaround	Software should flush the Gfx VTd context cache after any update of context table entries.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL037	PCIe* and DMI Links With Lane Polarity Inversion May Result in Link Failure
Problem	The processor's PCIe and DMI links may fail after exiting Package C7 or deeper if the platform requires the link to utilize lane polarity inversion.
Implication	Due to this erratum, the processor cannot support lane polarity inversion on the PCIe or DMI links when Package C7 or deeper is enabled.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL038	PCIe* Expansion ROM Base Address Register May be Incorrect
Problem	After PCIe 8.0 GT/s Link Equalization on a root port (Bus 0; Device 1; Function 0, 1, 2) has completed, the Expansion ROM Base Address Register (Offset 38H) may be incorrect.
Implication	Software that uses this BAR may behave unexpectedly. Intel has not observed this erratum with any commercially available software.
Workaround	It is possible for the BIOS to contain a partial workaround for this erratum. Software should wait at least 5ms following link equalization before accessing these Expansion ROM Base Address Register.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL039	PCIe* Perform Equalization May Lead to Link Failure
Problem	Due to this erratum, when a processor PCIe port operating at 8.0 GT/s is directed to redo equalization, either via software or from the link partner, incorrect coefficients may be conveyed during Equalization Phase 3.
Implication	If the link partner accepts the incorrect coefficients, the link may become unstable. Note this affects 8.0 GT/s only.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL040	Two DIMMs Per Channel 2133 MHz DDR4 SODIMM Daisy-Chain Systems With Different Vendors May Hang
Problem	When, on a single memory channel with 2133 MHz DDR4 SODIMMs, mixing different vendors or mixing single rank and dual rank DIMMs, may lead to a higher rate of correctable errors or system hangs.
Implication	Due to this erratum, reported correctable error counts may increase or system may hang.
Workaround	Use a single vendor for and do not mix single rank and dual rank 2133 MHz DDR4 SODIMM.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL041	ENCLS[EINIT] Instruction May Unexpectedly #GP
Problem	When using Intel® SGX (Software Guard Extensions), the ENCLS[EINIT] instruction will incorrectly cause a #GP (general protection fault) if the MISCSELECT field of the SIGSTRUCT structure is not zero.
Implication	This erratum may cause an unexpected #GP, but only if software has set bits in the MISCSELECT field in SIGSTRUCT structure that do not correspond to extended features that can be written to the MISC region of the SSA (State Save Area). Intel has not observed this erratum with any commercially available software.
Workaround	When executing the ENCLS[EINIT] instruction, software should only set bits in the MISCSELECT field in the SIGSTRUCT structure that are enumerated as 1 by CPUID.(EAX=12H,ECX=0):EBX (the bit vector of extended features that can be written to the MISC region of the SSA).
Status	For the stepping's affected, see the Summary Table of Changes.



SKL042	Intel® PT OVF Packet May be Lost if Immediately Preceding a TraceStop
Problem	If an Intel PT (Intel® Processor Trace) internal buffer overflow occurs immediately before software executes a taken branch or event that enters an Intel PT TraceStop region, the OVF (Overflow) packet may be lost.
Implication	The trace decoder will not see the OVF packet, nor any subsequent packets (e.g., TraceStop) that were lost due to overflow.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL043	Detecting an Intel® PT Stopped or Error Condition Within an Intel® TSX Region May Result in a System Hang
Problem	While executing within an Intel TSX (Intel® Transactional Synchronization Extensions) transactional region with Intel PT (Intel® Processor Trace) enabled and an event occurs that causes either the Error bit (bit 4) or Stopped bit (bit 5) in the IA32_RTIT_STATUS MSR (0571H) to be set then, due to this erratum, the system may hang.
Implication	A system hang may occur when Intel PT and Intel TSX are used together.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL044	WRMSR to IA32_BIOS_UPDT_TRIG May be Counted as Multiple Instructions
Problem	When software loads a microcode update by writing to MSR IA32_BIOS_UPDT_TRIG (79H) on multiple logical processors in parallel, a logical processor may, due to this erratum, count the WRMSR instruction as multiple instruction-retired events.
Implication	Performance monitoring with the instruction-retired event may over count by up to four extra events per instance of WRMSR which targets the IA32_BIOS_UPDT_TRIG register.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL045	The x87 FIP May be Incorrect
Problem	The x87 FPU should update the x87 FIP (FPU instruction pointer) for every non-control x87 instruction executed. Due to this erratum, the FIP is valid only if the last non-control FP instruction had an unmasked exception.
Implication	When this erratum occurs, an instruction that saves FIP (e.g., FSTENV) may save an incorrect value. Software that depends on the FIP value for x87 non-control instructions without unmasked exceptions may not operate as expected.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL046	Branch Instructions May Initialize MPX Bound Registers Incorrectly
Problem	Depending on the current Intel® MPX (Memory Protection Extensions) configuration, execution of certain branch instructions (near CALL, near RET, near JMP, and Jcc instructions) without a BND prefix (F2H) initialize the MPX bound registers. Due to this erratum, execution of such a branch instruction on a user-mode page may not use the MPX configuration register appropriate to the current privilege level (BNDCFGU for CPL 3 or BNDCFGS otherwise) for determining whether to initialize the bound registers; it may thus initialize the bound registers when it should not, or fail to initialize them when it should.
Implication	After a branch instruction on a user-mode page has executed, a #BR (bound-range) exception may occur when it should not have or a #BR may not occur when one should have.
Workaround	If supervisor software is not expected to execute instructions on user-mode pages, software can avoid this erratum by setting CR4.SMEP [bit 20] to enable supervisor-mode execution prevention (SMEP). If SMEP is not available or if supervisor software is expected to execute instructions on user-mode pages, no workaround is identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL047	Writing a Non-Canonical Value to an LBR MSR Does Not Signal a #GP When Intel® PT is Enabled
Problem	If Intel PT (Intel Processor Trace) is enabled, WRMSR will not cause a general-protection exception (#GP) on an attempt to write a non-canonical value to any of the following MSRs: MSR_LASTBRANCH_{0 - 31}_FROM_IP (680H – 69FH) MSR_LASTBRANCH_{0 - 31}_TO_IP (6C0H – 6DFH) MSR_LASTBRANCH_FROM_IP (1DBH) MSR_LASTBRANCH_TO_IP (1DCH) MSR_LASTINT_FROM_IP (1DDH) MSR_LASTINT_TO_IP (1DEH) Instead the same behavior will occur as if a canonical value had been written. Specifically, the WRMSR will be dropped and the MSR value will not be changed.
Implication	Due to this erratum, an expected #GP may not be signaled.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL048	Processor May Run Intel® AVX Code Much Slower Than Expected
Problem	After a C6 state exit, the execution rate of AVX instructions may be reduced.
Implication	Applications using AVX instructions may run slower than expected.
Workaround	It is possible for the BIOS to contain a workaround
Status	For the stepping's affected, see the Summary Table of Changes.



SKL049	Intel® PT Buffer Overflow May Result in Incorrect Packets
Problem	Under complex micro-architectural conditions, an Intel PT (Processor Trace) OVF (Overflow) packet may be issued after the first byte of a multi-byte CYC (Cycle Count) packet, instead of any remaining bytes of the CYC.
Implication	When this erratum occurs, the splicing of the CYC and OVF packets may prevent the Intel PT decoder from recognizing the overflow. The Intel PT decoder may then encounter subsequent packets that are not consistent with expected behavior.
Workaround	None Identified. The decoder may be able to recognize that this erratum has occurred when a two-byte CYC packet is followed by a single-byte CYC, where the latter 2 bytes are 0xf302, and where the CYC packets are followed by a FUP (Flow Update Packet) and a PSB+ (Packet Stream Boundary+). It should then treat the two CYC packets as indicating an overflow.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL050	Intel® PT PSB+ Packets May be Omitted on a C6 Transition
Problem	An Intel PT (Processor Trace) PSB+ (Packet Stream Boundary+) set of packets may not be generated as expected when IA32_RTIT_STATUS.PacketByteCnt[48:32] (MSR 0x571) reaches the PSB threshold and a logical processor C6 entry occurs within the following one KByte of trace output.
Implication	After a logical processor enters C6, Intel PT output may be missing PSB+ sets of packets.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL051	IA32_PERF_GLOBAL_STATUS.TRACE_TOPA_PMI Bit Cannot be Set by Software
Problem	A WRMSR that attempts to set Trace_ToPA_PMI (bit 55) in the IA32_PERF_GLOBAL_STATUS MSR (38EH) by writing a '1' to bit 55 in the IA32_PERF_GLOBAL_STATUS_SET (MSR (391H) will cause a #GP fault.
Implication	Software cannot set the Trace_ToPA_PMI bit.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL052	CPUID Incorrectly Reports Bit Manipulation Instructions Support
Problem	Executing CPUID with EAX = 7 and ECX = 0 may return EBX with bits [3] and [8] set, incorrectly indicating the presence of BMI1 and BMI2 instruction set extensions.
Implication	Attempting to use instructions from the BMI1 or BMI2 instruction set extensions will result in a #UD exception.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL053	Intel® Turbo Boost Technology May be Incorrectly Reported as Supported on Intel® Core™ i3 U/H/S, Select Intel® Mobile Pentium®, Intel® Mobile Celeron®, Select Intel® Pentium® G4xxx and Intel® Celeron® G3xxx Processors
Problem	These processors may incorrectly report support for Intel® Turbo Boost Technology via CPUID.06H.EAX bit 1.
Implication	The CPUID instruction may report Turbo Boost Technology as supported even though the processor does not permit operation above the Base Frequency.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL054	N/A. Erratum has been removed.
---------------	---------------------------------------

SKL055	Use of Prefetch Instructions May Lead to a Violation of Memory Ordering
Problem	Under certain micro architectural conditions, execution of a PREFETCHH instruction or a PREFETCHW instruction may cause a load from the prefetched cache line to appear to execute before an earlier load from another cache line.
Implication	Software that relies on loads executing in program order may not operate correctly.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL056	CS Limit Violation May Not be Detected
Problem	A CS (code segment) limit reduction may not be properly applied.
Implication	Instructions may be executed beyond the CS limit. Intel has not observed this erratum to impact the operation of any commercially available software.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL057	Last Level Cache Performance Monitoring Events May be Inaccurate
Problem	The performance monitoring events LONGEST_LAT_CACHE.REFERENCE (Event 2EH; Umask 4FH) and LONGEST_LAT_CACHE.MISS (Event 2EH; Umask 41H) count requests that reference or miss in the last level cache. However, due to this erratum, the count may be incorrect.
Implication	LONGEST_LAT_CACHE events may be incorrect.
Workaround	None identified. Software may use the following OFFCORE_REQUESTS model-specific sub events that provide related performance monitoring data: DEMAND_DATA_RD, DEMAND_CODE_RD, DEMAND_RFO, ALL_DATA_RD, L3_MISS_DEMAND_DATA_RD, ALL_REQUESTS.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL058	#GP Occurs Rather Than #DB on Code Page Split Inside an Intel® SGX Enclave
Problem	When executing within an Intel® SGX (Software Guard Extensions) enclave, a #GP (general-protection exception) may be delivered instead of a #DB (debug exception) when an instruction breakpoint is detected. This occurs when the instruction to be executed spans two pages, the second of which has an entry in the EPCM (enclave page cache map) that is not valid.
Implication	Debugging software may not be invoked when an instruction breakpoint is detected.
Workaround	Software should ensure that all pages containing enclave instructions have valid EPCM entries.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL059	Execution of VAESENCLAST Instruction May Produce a #NM Exception Instead of a #UD Exception
Problem	Execution of VAESENCLAST with VEX.L= 1 should signal a #UD (Invalid Opcode) exception, however, due to the erratum, a #NM (Device Not Available) exception may be signaled.
Implication	As a result of this erratum, an operating system may restore AVX and other state unnecessarily.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL060	Intel® SGX Enclave Accesses to the APIC-Access Page May Cause APIC-Access VM Exits
Problem	In VMX non-root operation, Intel SGX (Software Guard Extensions) enclaves accesses to the APIC-access page may cause APIC-access VM exits instead of page faults.
Implication	A VMM (virtual-machine monitor) may receive a VM exit due to an access that should have caused a page fault, which would be handled by the guest OS (operating system).
Workaround	A VMM avoids this erratum if it does not map any part of the EPC (Enclave Page Cache) to the guest's APIC-access address; an operating system avoids this erratum if it does not attempt indirect enclave accesses to the APIC.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL061	CR3 Filtering Does Not Compare Bits [11:5] of CR3 and IA32_RTIT_CR3_MATCH in PAE Paging Mode
Problem	In PAE paging mode, the CR3[11:5] are used to locate the page-directory-pointer table. Due to this erratum, those bits of CR3 are not compared to IA32_RTIT_CR3_MATCH (MSR 572H) when IA32_RTIT_CTL.CR3Filter (MSR 570H, bit 7) is set.
Implication	If multiple page-directory-pointer tables are co-located within a 4KB region, CR3 filtering will not be able to distinguish between them so additional processes may be traced.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL062	Intel® PT PacketEn Change on C-state Wake May Not Generate a TIP Packet
Problem	A TIP.PGE (Target IP, Packet Generation Enabled) or TIP.PGD (Target IP, Packet Generation Disabled) packet may not be generated if Intel PT (Processor Trace) PacketEn changes after IA32_RTIT_STATUS.FilterEn (MSR 571H, bit 0) is re-evaluated on wakeup from C6 or deeper sleep state.
Implication	When code enters or exits an IP filter region without a taken branch, tracing may begin or cease without proper indication in the trace output. This may affect trace decoder behavior.
Workaround	None identified. A trace decoder will need to skip ahead to the next TIP or FUP packet to determine the current IP.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL063	Graphics Configuration May Not be Correctly Restored After a Package C8 Exit
Problem	The processor should ensure internal graphics configuration is restored during a Package C8 or deeper exit event. Due to this erratum, some internal graphics configurations may not be correctly restored.
Implication	When this erratum occurs, a graphics driver restart may lead to system instability. Such a restart may occur when upgrading the graphics driver.
Workaround	It is possible for the BIOS to contain a workaround for this erratum
Status	For the stepping's affected, see the Summary Table of Changes.

SKL064	x87 FDP Value May be Saved Incorrectly
Problem	Execution of the FSAVE, FNSAVE, FSTENV, or FNSTENV instructions in real-address mode or virtual-8086 mode may save an incorrect value for the x87 FDP (FPU data pointer). This erratum does not apply if the last non-control x87 instruction had an unmasked exception.
Implication	Software operating in real-address mode or virtual-8086 mode that depends on the FDP value for non-control x87 instructions without unmasked exceptions may not operate properly.
Workaround	None identified. Software should use the FDP value saved by the listed instructions only when the most recent non-control x87 instruction incurred an unmasked exception.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL065	PECI Frequency Limited to 1 MHz
Problem	The PECI (Platform Environmental Control Interface) 3.1 specification's operating frequency range is 0.2 MHz to 2 MHz. Due to this erratum, PECI may be unreliable when operated above 1 MHz.
Implication	Platforms attempting to run PECI above 1 MHz may not behave as expected.
Workaround	None identified. Platforms should limit PECI operating frequency to 1 MHz.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL066	Processor Graphics IOMMU Unit May Not Mask DMA Remapping Faults
Problem	Intel® Virtualization Technology for Directed I/O specification specifies setting the FPD (Fault Processing Disable) field in the context (or extended-context) entry of IOMMU to mask recording of qualified DMA remapping faults for DMA requests processed through that context entry. Due to this erratum, the IOMMU unit for Processor Graphics device may record DMA remapping faults from Processor Graphics device (Bus: 0; Device: 2; Function: 0) even when the FPD field is set to 1.
Implication	Software may continue to observe DMA remapping faults recorded in the IOMMU Fault Recording Register even after setting the FPD field.
Workaround	None identified. Software may mask the fault reporting event by setting the IM (Interrupt Mask) field in the IOMMU Fault Event Control register (Offset 038H in GFXVTBAR).
Status	For the stepping's affected, see the Summary Table of Changes.

SKL067	Processor With Intel® SGX Support May Hang During S3 Wake or Power-On Reset
Problem	Processors that support Intel® SGX (Intel Software Guard Extensions) may experience hangs when waking from S3 (Standby) system sleep state or during a power-on reset. This erratum may occur even if the Intel SGX feature is not enabled.
Implication	Due to this erratum, the system may not wake after entering standby sleep state or may not start up after a power-on reset
Workaround	It is possible for the BIOS to contain a workaround for this erratum. For systems that do not power gate Vcc Sustain, if the workaround detects this erratum, support for Intel SGX will be removed until platform power is disconnected and reapplied.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL068	Audio Glitches May Occur After Reset or S3/S4 Exit
Problem	After a reset or S3/S4 exit the processor may operate at a lower than expected frequency.
Implication	When this erratum occurs, the processor may be unable to adequately support audio playback resulting in several seconds of audio glitches.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL069	Intel® PT CYCThresh Value of 13 is Not Supported
Problem	Intel PT (Intel® Processor Trace) CYC (Cycle Count) threshold is configured through CYCThresh field in bits [22:19] of IA32_RTIT_CTL MSR (570H). A value of 13 is advertised as supported by CPUID (leaf 14H, sub-leaf 1H). Due to this erratum, if CYCThresh is set to 13 then the CYC threshold will be 0 cycles instead of 4096 (2 ¹³ -1) cycles.
Implication	CYC packets may be issued in higher rate than expected if threshold value of 13 is used.
Workaround	None identified. Software should not use value of 13 for CYC threshold.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL070	Exx. Intel® PT May Drop Some Timing Packets After Entering Thread
Problem	Intel PT (Intel® Processor Trace) may temporarily stop sending MTC (Mini Time Counter) and CYC (Cycle) packets after entering thread C3 state. MTC and CYC packets may be missing in up to 1KB of trace output after entering thread C3.
Implication	Some Intel PT timing packets may temporarily not be sent after thread C3 is entered.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL071	Underflow and Denormal Conditions During a VDPSS Instruction With YMM Operands May Not Produce The Expected Results
Problem	A VDPSS (Vector Dot Product of Packed Single Precision Floating-Point Values) instruction operating on YMM registers with denormal operand(s) or experiencing an underflow may not produce the expected result if the exception is masked in the MXCSR. This may also happen when intermediate multiply results have underflow conditions.
Implication	VDPSS with YMM registers may not produce the expected result.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL072	IA Core Ratio Change Coincident With Outstanding Read to the DE May Cause a System Hang
Problem	An outstanding read from an IA core to the DE (Display Engine) that is coincident with an IA core ratio change may result in a system hang.
Implication	Due to this erratum, the system may hang.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL073	Enabling VMX-Preemption Timer Blocks HDC Operation
Problem	HDC (Hardware Duty Cycling) will not put the physical package into the forced idle state while any logical processor is in VMX non-root operation and the "activate VMX-preemption timer" VM-execution control is 1.
Implication	HDC will not provide the desired power reduction when the VMX-preemption timer is active in VMX non-root operation.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL074	Certain Processors May be Configured With an Incorrect TDP
Problem	Certain processors should be configured with a TDP (Thermal Design Power) limit of 54 or 51 watts. Due to this erratum, these processors may be incorrectly configured at 65 W TDP. The following processors are affected by this erratum: Intel® Core™ i3 Processor Series, Celeron® and Pentium® (Dual-Core With GT1/GT2). A processor that reports a value of 0x208 in TDP_POWER_OF_SKU field in MSR PACKAGE_POWER_SKU (MSR 614H [14:0]) are affected by this erratum.
Implication	Processors affected by this erratum may spend more time in turbo and thus may experience unexpected thermal throttling events.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL075	Display Flicker May Occur When Both VT-d And FBC Are Enabled
Problem	Display flickering may occur when both FBC (Frame Buffer Compression) and VT-d (Intel® Virtualization Technology for Directed I/O) are enabled and in use by the display controller.
Implication	Due to this erratum, display flickering may be observed.
Workaround	It is possible for Intel® Graphics Driver 15.40.11.4312 or later to contain a workaround for this erratum. This workaround will disable FBC.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL076	System May Hang When Using Intel® TXT And Memory That Supports Address Mirroring
Problem	Within platforms that utilize memory that supports address mirroring, processors that utilize Intel TXT (Intel Trusted Execution Technology) measured launch environment may fail to boot and hang.
Implication	Due to this erratum, system may hang.
Workaround	A BIOS workaround has been identified. Please refer to TXT BIOS ACM 1.3 or later and release notes.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL077	System May Hang or Reset During Processor Package C9 Exit
Problem	Under a complex set of conditions, during a processor Package C9 exit, display artifacts may be seen, the processor may hang, or the processor may incur a machine check exception with an Internal Unclassified error reported in IA32_MCi_STATUS with MCACOD (bits[15:0]) equal to 0x402 and MSCOD (31:16)] equal to 0x94yy (where y can be any value).
Implication	Display artifacts may be seen or the system may log a machine check error and reset or hang when resuming from C9.
Workaround	It is possible for the BIOS and Intel® Graphics Driver 15.40.11.4312 or later to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL078	Integrated Audio Codec May Not be Detected
Problem	Integrated Audio Codec may lose power when LPSP (Low-Power Single Pipe) mode is enabled for an eDP* (embedded DisplayPort) or HDMI ports. Platforms with Intel® SST (Intel® Smart Sound Technology) enabled are not affected.
Implication	The Audio Bus driver may attempt to do enumeration of Codecs when eDP or HDMI port enters LPSP mode, due to this erratum, the Integrated Audio Codec will not be detected and audio maybe be lost.
Workaround	Intel® Graphics Driver 15.40.11.4312 or later will prevent the Integrated Audio Codec from losing power when LPSP mode is enabled.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL079	MOVNTDQA From WC Memory May Pass Earlier MFENCE Instructions
Problem	An execution of MOVNTDQA or VMOVNTDQA that loads from WC (write combining) memory may appear to pass an earlier execution of the MFENCE instruction.
Implication	When this erratum occurs, an execution of MOVNTDQA or VMOVNTDQA may appear to execute before memory operations that precede the earlier MFENCE instruction. Software that uses MFENCE to order subsequent executions of the MOVNTDQA instructions may not operate properly.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL080	APIC Timer Interrupt or Timed MWAIT Wake May Occur Early
Problem	When the APIC timer is configured to TSC Deadline Mode, a timer interrupt may occur before the expected deadline if any of IA32_TSC_DEADLINE MSR (6E0H) bits [63:56] are set. Additionally, a Timed MWAIT with EDX bits [31:24] set may wake early and may set EAX[1] to report that the MWAIT timer caused the wake event.
Implication	A timer interrupt may be delivered earlier than specified by the IA32_TSC_DEADLINE MSR or a Timed MWAIT may wake earlier than its specified deadline.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL081	Processors That Support EDRAM May Not Initialize Properly
Problem	During platform initialization, the processor's eDRAM interface may fail to complete its training and configuration sequence.
Implication	When this erratum occurs, a processor that supports eDRAM may not initialize properly.
Workaround	It is possible for BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL082	Processor May Hang or Cause Unpredictable System Behavior
Problem	Under complex microarchitecture conditions, processor may hang with an internal timeout error (MCACOD 0400H) logged into IA32_MCI_STATUS or cause unpredictable system behavior
Implication	When this issue occurs, the system may cause unpredictable system behavior
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL083	The Processor May Fail to Properly Exit Package C6 or Deeper
Problem	When the processor exits Package C6 or deeper, it may hang, generate a machine check exception with an Internal Unclassified error reported in IA32_MCI_STATUS with MCACOD (bits[15:0]) equal to 0x402 and MSCOD (31:16)] equal to 0x94yy (where y can be any value), or exhibit unpredictable system behavior.
Implication	Due to this erratum, unpredictable system behavior may occur.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL084	Certain Processors May Report Incorrect DID2
Problem	The U-processor with GT3 and TDP of 28W may report an incorrect value of 1926H in DID2 (Processor Graphics Device ID) (Bus 0, Device 2, Function 0; offset 2h; bits [15:0]) register. This value should be 1927H.
Implication	Software that decodes DID2 values may not function as expected.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL085	System May Hang When Entering S3/S4/S5 State
Problem	When entering S3/S4/S5 state, it may hang and generate a machine check with an Internal Unclassified error reported in IA32_MCI_STATUS with MCACOD (bits[15:0]) equal to 0x402 and MSCOD (31:16)] equal to 0x77yy (where y can be any value).
Implication	Due to this erratum a system hang may occur.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL086	Display Flickering May be Observed with Specific eDP Panels
Problem	The processor may incorrectly configure transmitter buffer characteristics if the associated eDP panel requests VESA equalization preset 3, 5, 6, or 8.
Implication	Display flickering or display loss maybe observed.
Workaround	Intel® Graphics Driver version 15.40.12.4326 or later contains a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL087	x87 FPU Data Pointer Updated Only For Instructions That Incur Unmasked Exceptions
Problem	The x87 FPU data pointer points to the data (operand) for the last x87 non-control instruction executed, unless CPUID.(EAX=07H,ECX=0H):EBX.FDP_EXCPTN_ONLY[bit 6] is 1, in which case it points to the operand for the last x87 non-control instruction that incurred an unmasked x87 exception. Due to this erratum, x87 FPU data pointer behaves as if the FDP_EXCPTN_ONLY flag is 1 even when that bit is 0.
Implication	If the most recent x87 non-control instruction did not incur an unmasked x87 exception, software that then examines the x87 FPU data pointer will see an incorrect value. Intel has not observed this erratum with any commercially available software.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL088	Incorrect Branch Predicted Bit in BTS/BTM Branch Records
Problem	BTS (Branch Trace Store) and BTM (Branch Trace Message) send branch records to the Debug Store management area and system bus respectively. The Branch Predicted bit (bit 4 of eighth byte in BTS/BTM records) should report whether the most recent branch was predicted correctly. Due to this erratum, the Branch Predicted bit may be incorrect.
Implication	BTS and BTM cannot be used to determine the accuracy of branch prediction.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL089	MACHINE_CLEAR.S.MEMORY_ORDERING Performance Monitoring Event May Undercount
Problem	The performance monitoring event MACHINE_CLEAR.S.MEMORY_ORDERING (Event C3H; Umask 02H) counts the number of machines clears caused by memory ordering conflicts. However due to this erratum, this event may undercount for VGATHER*/VPGATHER* instructions of four or more elements.
Implication	MACHINE_CLEAR.S.MEMORY_ORDERING performance monitoring event may undercount.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL090	CTR_FRZ May Not Freeze Some Counters
Problem	IA32_PERF_GLOBAL_STATUS.CTR_FRZ (MSR 38EH, bit 59) is set when either (1) IA32_DEBUGCTL.FREEZE_PERFMON_ON_PMI (MSR 1D9H, bit 12) is set and a PMI is triggered, or (2) software sets bit 59 of IA32_PERF_GLOBAL_STATUS_SET (MSR 391H). When set, CTR_FRZ should stop all core performance monitoring counters from counting. However, due to this erratum, IA32_PMC4-7 (MSR C5-C8H) may not stop counting. IA32_PMC4-7 are only available when a processor core is not shared by two logical processors.
Implication	General performance monitoring counters 4-7 may not freeze when IA32_PERF_GLOBAL_STATUS.CTR_FRZ is set.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL091	Instructions And Branches Retired Performance Monitoring Events May Overcount
Problem	<p>The performance monitoring events INST_RETIRED (Event C0H; any Umask value) and BR_INST_RETIRED (Event C4H; any Umask value) count instructions retired and branches retired, respectively. However, due to this erratum, these events may overcount in certain conditions when:</p> <ul style="list-style-type: none">- Executing VMASKMOV* instructions with at least one masked vector element- Executing REP MOVS or REP STOS with Fast Strings enabled (IA32_MISC_ENABLES MSR (1A0H), bit 0 set)- An MPX #BR exception occurred on BNDLDX/BNDSTX instructions and the BR_INST_RETIRED (Event C4H; Umask is 00H or 04H) is used.
Implication	INST_RETIRED and BR_INST_RETIRED performance monitoring events may overcount.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL092	Deleted – Please refer to SKL057
---------------	---

SKL093	REP MOVS May Not Operate Correctly With EPT Enabled
Problem	Execution of REP MOVS may incorrectly change [R/E]CX, [R/E]SI, and/or [R/E]DI register values during instruction execution. This erratum occurs only if the execution would set an accessed or dirty flag in a paging structure to which EPT does not allow writes.
Implication	Incorrect changes to RCX, RSI, and/or RDI may lead to a block-copy operation with an unexpected length, an unexpected source location, and/or an unexpected destination location.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL094	Ring Frequency Changes May Cause a Machine Check And System Hang
Problem	Ring frequency changes may lead to a system hang with the processor logging a machine check in IA32_MCI_STATUS where the MCACOD (bits[15:0]) value is 0x0402 and the MSCOD (bits[31:16]) value is 0x77yy (yy is any 8-bit value).
Implication	When this erratum occurs, the system will log a machine check and hang. Power management activity, including system power state changes, can result in ring frequency changes that may trigger this erratum.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL095	Some OFFCORE_RESPONSE Performance Monitoring Events May Overcount
Problem	The performance monitoring events OFFCORE_RESPONSE (Events B7H and BBH) should count off-core responses matching the request-response configuration specified in MSR_OFFCORE_RSP_0 and MSR_OFFCORE_RSP_1 (1A6H and 1A7H, respectively) for core-originated requests. However, due to this erratum, DMND_RFO (bit 1), DMND_IFETCH (bit 2) and OTHER (bit 15) request types may overcount.
Implication	Some OFFCORE_RESPONSE events may overcount.
Workaround	None identified. Software may use the following model-specific events that provide related performance monitoring data: OFFCORE_REQUESTS (all sub-events), L2_TRANS.L2_WB and L2_RQSTS.PF_MISS.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL096	Using BIOS to Disable Cores May Lead to a System Hang
Problem	Using the BIOS hardware core disable facility may cause the processor to hang when it attempts to enter or exit Package C6.
Implication	When this erratum occurs, attempting to enter or exit Package C6 state will hang the system.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL097	Instructions Fetch #GP After RSM During Inter® PT May Push Incorrect RFLAGS Value on Stack
Problem	If Intel PT (Processor Trace) is enabled, a #GP (General Protection Fault) caused by the instruction fetch immediately following execution of an RSM instruction may push an incorrect value for RFLAGS onto the stack.
Implication	Software that relies on RFLAGS value pushed on the stack under the conditions described may not work properly.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL098	Deleted - Please refer to SKL005S
---------------	--



SKL099	Access to SGX EPC Page in BLOCKED State is Not Reported as an SGX-Induced Page Fault
Problem	If a page fault results from attempting to access a page in the SGX (Intel® Software Guard Extensions) EPC (Enclave Page Cache) that is in the BLOCKED state, the processor does not set bit 15 of the error code and thus fails to indicate that the page fault was SGX-induced.
Implication	Due to this erratum, software may not recognize these page faults as being SGX-induced.
Workaround	Before using the EBLOCK instruction to marking a page as BLOCKED, software should use paging to mark the page not present.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL100	MTF VM Exit on XBEGIN Instruction May Save State Incorrectly
Problem	Execution of an XBEGIN instruction while the monitor trap flag VM-execution control is 1 will be immediately followed by an MTF VM exit. If advanced debugging of RTM transactional regions has been enabled, the VM exit will erroneously save as instruction pointer the address of the XBEGIN instruction instead of the fallback instruction address specified by the XBEGIN instruction. In addition, it will erroneously set bit 16 of the pending-debug-exceptions field in the VMCS indicating that a debug exception or a breakpoint exception occurred.
Implication	Software using the monitor trap flag to debug or trace transactional regions may not operate properly. Intel has not observed this erratum with any commercially available software.
Workaround	None identified
Status	For the stepping's affected, see the Summary Table of Changes.

SKL101	PCIe* Atomic Operations May Lead to Unpredictable System Behavior
Problem	Processors with eDRAM do not support PCIe Atomic Operations. Due to this erratum, processors with eDRAM incorrectly advertise support for PCIe Atomic Operations in DCAP2 CSRs (Bus 0; Device 1; Function 0,1,2; Offset 0xC4), bits[9:7].
Implication	Use of PCIe Atomic Operations may lead to unpredictable system behavior.
Workaround	It is possible for the BIOS to contain a workaround for this erratum
Status	For the stepping's affected, see the Summary Table of Changes.



SKL102	Instructions That Cause #NM May Lead to Hang
Problem	An x87 FPU instruction or AESNI instruction executed while CR0.TS[bit 3]=1 should cause an #NM (device not available) exception. Due to this erratum, executing such instructions when Intel Hyper-Threading Technology is enabled may result in a hang with an internal timeout error (MCACOD 0400H) logged into IA32_MCI_STATUS bits [15:0].
Implication	When this erratum occurs, the system will experience a fatal machine check. Intel has not observed this erratum with any commercially available software.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL103	Enabling S3 on Processors With EDRAM May Cause Unpredictable System Behavior
Problem	Entering S3 when EDRAM is enabled may lead to unpredictable system behavior.
Implication	When this erratum occurs, the system may exhibit unpredictable system behavior.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL104	PEBS Record May Be Generated After Being Disabled
Problem	A performance monitoring counter may generate a PEBS (Precise Event Based Sampling) record after disabling PEBS or the performance monitoring counter by clearing the corresponding enable bit in IA32_PEBS_ENABLE MSR (3F1H) or IA32_PERF_GLOBAL_CTRL MSR (38FH).
Implication	A PEBS record generated after a VMX transition will store into memory according to the post-transition DS (Debug Store) configuration. These stores may be unexpected if PEBS is not enabled following the transition.
Workaround	It is possible for the BIOS to contain a workaround for this erratum. A software workaround is possible through disallowing PEBS during VMX non-root operation and disabling PEBS prior to VM entry.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL105	Software Using Intel® TSX May Result in Unpredictable System Behavior
Problem	Under a complex set of internal timing conditions and system events, software using the Intel TSX (Transactional Synchronization Extensions) instructions may result in unpredictable system behavior.
Implication	This erratum may result in unpredictable system behavior.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL106	Package-C6 Exit Latency May be Higher Than Expected Leading to Display Flicker
Problem	Package-C6 exit latency may be higher than expected.
Implication	Due to this erratum, the display may flicker or other Isochronous devices may be affected.
Workaround	It is possible for the BIOS to contain a workaround for this erratum
Status	For the stepping's affected, see the Summary Table of Changes.

SKL107	EDRAM May Cause Unpredictable System Behavior
Problem	EDRAM, under certain low-power conditions, may lead to unpredictable behavior.
Implication	When this erratum occurs, the system will behave unpredictably
Workaround	It is possible for the BIOS to contain a workaround for this erratum
Status	For the stepping's affected, see the Summary Table of Changes.

SKL108	PCIe* Port Does Not Support DLL Link Activity Reporting
Problem	The PCIe Base specification requires DLL (Data Link Layer) Link Activity Reporting when 8 GT/s link speed is supported. Due to this erratum, link activity reporting is not supported
Implication	Due to this erratum, PCIe port does not support DLL Link Activity Reporting when 8 GT/s is supported.
Workaround	None identified
Status	For the stepping's affected, see the Summary Table of Changes.

SKL109	Enabling Package C8 State or Deeper May Lead to Display Flicker or a System Hang
Problem	Under certain conditions, when Package C8 state or deeper is enabled, display flickering may be observed and/or the system may hang.
Implication	When this erratum occurs, the display may flicker and/or the system may hang.
Workaround	It is possible for the BIOS to contain a workaround for this erratum
Status	For the stepping's affected, see the Summary Table of Changes.



SKL110	System May Hang When EDRAM is Enabled And DDR is Operating at 1600 MHz
Problem	When EDRAM is enabled and the DDR operating frequency is 1600 MHz, a system hang may occur
Implication	When this erratum occurs, the system may hang.
Workaround	It is possible for the BIOS to contain a workaround for this erratum
Status	For the stepping's affected, see the Summary Table of Changes.

SKL111	DR6.B0-B3 May Not Report All Breakpoints Matched When a MOV/POP SS is Followed by a Store or an MMX Instruction
Problem	Normally, data breakpoints match that occur on a MOV SS, r/m or POP SS will not cause a debug exception immediately after MOV/POP SS but will be delayed until the instruction boundary following the next instruction is reached. After the debug exception occurs, DR6.B0-B3 bits will contain information about data breakpoints matched during the MOV/POP SS as well as breakpoints detected by the following instruction. Due to this erratum, DR6.B0-B3 bits may not contain information about data breakpoints matched during the MOV/POP SS when the following instruction is either an MMX instruction that uses a memory addressing mode with an index or a store instruction.
Implication	When this erratum occurs, DR6 may not contain information about all breakpoints matched. This erratum will not be observed under the recommended usage of the MOV SS, r/m or POP SS instructions (i.e., following them only with an instruction that writes (E/R)SP).
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL112	Package C3 Exit Latency May be Longer Than Expected Leading to Display Flicker
Problem	Package C3 exit latency may be longer than expected.
Implication	When this erratum occurs on a system with multiple high-resolution displays, the displays may flicker
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL113	Processor DDR VREF Signals May Briefly Exceed JEDEC Spec When Entering S3 State
Problem	Voltage glitch of up to 200mV on the VREF signal lasting for about 1mS may be observed when entering System S3 state. This violates the JEDEC DDR specifications.
Implication	Intel has not observed this erratum to impact the operation of any commercially available system.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL114	Complex Interactions With Internal Graphics May Impact Processor Responsiveness
Problem	Under complex conditions associated with the use of internal graphics, the processor may exceed the MAX_LAT CSR values (PCI configuration space, offset 03FH, bits[7:0]).
Implication	When this erratum occurs, the processor responsiveness is affected. Intel has not observed this erratum with any commercially available software.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL115	#GP on Segment Selector Descriptor that Straddles Canonical Boundary May Not Provide Correct Exception Error Code
Problem	During a #GP (General Protection Exception), the processor pushes an error code on to the exception handler's stack. If the segment selector descriptor straddles the canonical boundary, the error code pushed onto the stack may be incorrect.
Implication	An incorrect error code may be pushed onto the stack. Intel has not observed this erratum with any commercially available software.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL116	After a Package C10 Sleep State Exit, a Subsequent C8/C9 Exit May Cause System Hang
Problem	If Package C10 sleep state has been entered and exited, a later Package C8/C9 sleep state entrance/exit may cause the system to hang.
Implication	When this erratum occurs, the system hangs.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL117	Performance Monitoring Counters May Undercount When Using CPL Filtering
Problem	Performance Monitoring counters configured to count only OS or only USR events by setting exactly one of bits 16 or 17 in IA32_PERFVTSELx MSRs (186H-18DH) may not count for a brief period during the transition to a new CPL.
Implication	A measurement of ring transitions (using the edge-detect bit 18 in IA32_PERFVTSELx) may undercount, such as CPL_CYCLES.RING0_TRANS (Event 5CH, Umask 01H). Additionally, the sum of an OS-only event and a USR-only event may not exactly equal an event counting both OS and USR. Intel has not observed any other software-visible impact.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL118	Memory Controller CKE Signal May Not be Expected Value When Executing Boundary Scan EXTEST Command
Problem	If RESET# is asserted while EXTEST command is run, the CKE signal will always be observed as a low value instead of toggling as the BCSAN pattern is shifted.
Implication	Due to this erratum, the CKE signal may be observed low during the EXTEST Command.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL119	Certain Non-Canonical IA32_BNDCFGS Values Will Not Cause VM-Entry Failures
Problem	If the VM-entry controls Load IA32_BNDCFGS field (bit 16) is 1, VM-entry should fail when the value of the guest IA32_BNDCFGS field in the VMCS is not canonical (that is, when bits 63:47 are not identical). Due to this erratum, VM-entry does not fail if bits 63:48 are identical but differ from bit 47. In this case, VM-entry loads the IA32_BNDCFGS MSR with a value in which bits 63:48 are identical to the value of bit 47 in the VMCS field.
Implication	If the value of the guest IA32_BNDCFGS field in the VMCS is not canonical, VM-entry may load the IA32_BNDCFGS MSR with a value different from that of the VMCS field.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL120	PEBS EventingIP Field May Be Incorrect Under Certain Conditions
Problem	The EventingIP field in the PEBS (Processor Event-Based Sampling) record reports the address of the instruction that triggered the PEBS event. Under certain complex microarchitectural conditions, the EventingIP field may be incorrect
Implication	When this erratum occurs, performance monitoring software may not attribute the PEBS events to the correct instruction.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL121	Executing a 256-Bit AVX Instruction May Cause Unpredictable Behavior
Problem	Under complex micro-architectural conditions, executing a 256 AVX bit instruction may result in unpredictable system behavior.
Implication	When this erratum occurs, the system may behave unpredictably
Workaround	It is possible for the BIOS to contain a workaround for this erratum
Status	For the stepping's affected, see the Summary Table of Changes.

SKL122	HWP's Guaranteed_Performance Updated Only on Configurable TDP Changes
Problem	According to HWP (Hardware P-states) specification, the Guaranteed_Performance field (bits[15:8]) in the IA32_HWP_CAPABILITIES MSR (771H) should be updated as a result of changes in the configuration of TDP, RAPL (Running Average Power Limit) and other platform tuning options that may have dynamic effects on the actual guaranteed performance support level. Due to this erratum, the processor will update the Guaranteed_Performance field only as a result of Configurable TDP dynamic changes
Implication	Software may read a stale value of the Guaranteed_Performance field.
Workaround	None identified
Status	For the stepping's affected, see the Summary Table of Changes.

SKL123	Core and/or Ring Frequency May be Briefly Lower Than Expected After BIOS Completes
Problem	Due to this erratum, the core and ring frequencies may be lower than expected for up to several seconds after BIOS completes
Implication	Processing immediately after BIOS completes may take longer than expected. The erratum does not cause any functional failures.
Workaround	It is possible for the BIOS to contain a workaround for this erratum
Status	For the stepping's affected, see the Summary Table of Changes.



SKL124	RF May be Incorrectly Set in The EFLAGS That is Saved on a Fault in PEBS or BTS
Problem	After a fault due to a failed PEBS (Processor Event Based Sampling) or BTS (Branch Trace Store) address translation, the RF (resume flag) may be incorrectly set in the EFLAGS image that is saved.
Implication	When this erratum occurs, a code breakpoint on the instruction following the return from handling the fault will not be detected. This erratum only happens when the user does not prevent faults on PEBS or BTS.
Workaround	Software should always prevent faults on PEBS or BTS.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL125	Intel® PT ToPA PMI Does Not Freeze Performance Monitoring Counters
Problem	Due to this erratum, if IA32_DEBUGCTL.FREEZE_PERFMON_ON_PMI (MSR 1D9H, bit 12) is set to 1 when Intel PT (Processor Trace) triggers a ToPA (Table of Physical Addresses) PMI (PerfMon Interrupt), performance monitoring counters are not frozen as expected.
Implication	Performance monitoring counters will continue to count for events that occur during PMI handler execution.
Workaround	PMI handler software can programmatically stop performance monitoring counters upon entry.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL126	HWP's Maximum_Performance Value is Reset to 0xFF
Problem	According to HWP (Hardware P-states) specification, the reset value of the Maximum_Performance field (bits [15:8]) in IA32_HWP_REQUEST MSR (774h) should be set to the value of IA32_HWP_CAPABILITIES MSR (771H) Highest_Performance field (bits[7:0]) after reset. Due to this erratum, the reset value of Maximum_Performance is always set to 0xFF.
Implication	Software may see an unexpected value in Maximum Performance field. Hardware clipping will prevent invalid performance states.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL127	HWP's Guaranteed_Performance and Relevant Status/Interrupt May be Updated More Than Once Per Second
Problem	According to HWP (Hardware P-states) specification, the Guaranteed_Performance field (bits[15:8]) in the IA32_HWP_CAPABILITIES MSR (771H) and the Guaranteed_Performance_Change (bit 0) bit in IA32_HWP_STATUS MSR (777H) should not be changed more than once per second nor should the thermal interrupt associated with the change to these fields be signaled more than once per second. Due to this erratum, the processor may change these fields and generate the associated interrupt more than once per second.
Implication	HWP interrupt rate due to Guaranteed_Performance field change can be higher than specified
Workaround	Clearing the Guaranteed_Performance_Change status bit no more than once per second will ensure that interrupts are not generated at too fast a rate.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL128	Some Memory Performance Monitoring Events May Produce Incorrect Results When Filtering on Either OS or USR Modes
Problem	<p>The memory at-retirement performance monitoring events (listed below) may produce incorrect results when a performance counter is configured in OS-only or USR-only modes (bits 17 or 16 in IA32_PERFVTSELx MSR). Counters with both OS and USR bits set are not affected by this erratum.</p> <p>The list of affected memory at-retirement events is as follows:</p> <p>MEM_INST_RETIRED.STLB_MISS_LOADS event D0H, umask 11H MEM_INST_RETIRED.STLB_MISS_STORES event D0H, umask 12H MEM_INST_RETIRED.LOCK_LOADS event D0H, umask 21H MEM_INST_RETIRED.SPLIT_LOADS event D0H, umask 41H MEM_INST_RETIRED.SPLIT_STORES event D0H, umask 42H MEM_LOAD_RETIRED.L2_HIT event D1H, umask 02H MEM_LOAD_RETIRED.L3_HIT event D1H, umask 04H MEM_LOAD_RETIRED.L4_HIT event D1H, umask 80H MEM_LOAD_RETIRED.L1_MISS event D1H, umask 08H MEM_LOAD_RETIRED.L2_MISS event D1H, umask 10H MEM_LOAD_RETIRED.L3_MISS event D1H, umask 20H MEM_LOAD_RETIRED.FB_HIT event D1H, umask 40H MEM_LOAD_L3_HIT_RETIRED.XSNP_MISS event D2H, umask 01H MEM_LOAD_L3_HIT_RETIRED.XSNP_HIT event D2H, umask 02H MEM_LOAD_L3_HIT_RETIRED.XSNP_HITM event D2H, umask 04H MEM_LOAD_L3_HIT_RETIRED.XSNP_NONE event D2H, umask 08H</p>
Implication	The listed performance monitoring events may produce incorrect results including PEBS records generated at an incorrect point
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL129	HWP May Generate Thermal Interrupt While Not Enabled
Problem	Due to this erratum, the conditions for HWP (Hardware P-states) to generate a thermal interrupt on a logical processor may generate thermal interrupts on both logical processors of that core.
Implication	If two logical processors of a core have different configurations of HWP (e.g. only enabled on one), an unexpected thermal interrupt may occur on one logical processor due to the HWP settings of the other logical processor.
Workaround	Software should configure HWP consistently on all logical processors of a core.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL130	Camera Device Does Not Issue an MSI When INTx is Enabled
Problem	When both MSI (Message Signaled Interrupts) and legacy INTx are enabled by the camera device, INTx is asserted rather than issuing the MSI, in violation of the PCI Local Bus Specification.
Implication	Due to this erratum, camera device interrupts can be lost leading to device failure.
Workaround	The camera device must disable legacy INTx by setting bit 10 of PCICMD (Bus 0; Device 5; Function 0; Offset 04H) before MSI is enabled
Status	For the stepping's affected, see the Summary Table of Changes.

SKL131	An x87 Store Instruction Which Pends #PE May Lead to Unexpected Behavior When EPT A/D is Enabled.
Problem	An x87 store instruction which causes a #PE (Precision Exception) to be pended and updates an EPT (Extended Page Tables) A/D bit may lead to unexpected behavior.
Implication	The VMM may experience unexpected x87 fault or a machine check exception with the value of 0x150 in IA32_MC0_STATUS.MCACOD (bits [15:0] in MSR 401H)
Workaround	It is possible for the BIOS to contain a workaround for this erratum
Status	For the stepping's affected, see the Summary Table of Changes.

SKL132	System Hang or Machine Check May Occur When eDRAM Enabled
Problem	A machine check exception may occur with an error reported in IA32_MC10_STATUS or may experience system hang at high temperatures
Implication	When this erratum occurs, the system will generate a machine check error or result in a system hang.
Workaround	It is possible for the BIOS to contain a workaround for this erratum
Status	For the stepping's affected, see the Summary Table of Changes.



SKL133	RING_PERF_LIMIT_REASONS May be Incorrect
Problem	Under certain conditions, RING_PERF_LIMIT_REASONS (MSR 6B1H) may incorrectly assert the OTHER status bit (bit 8) as well as the OTHER log bit (bit 24).
Implication	When this erratum occurs, software using this register will incorrectly report clipping because of the OTHER reason.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL134	BNDLDX And BNDSTX May Not Signal #GP on Non-Canonical Bound Directory Access
Problem	BNDLDX and BNDSTX instructions access the bound's directory and table to load or store bounds. These accesses should signal #GP (general protection exception) when the address is not canonical (i.e. bits 48 to 63 are not the sign extension of bit 47). Due to this erratum, #GP may not be generated by the processor when a non-canonical address is used by BNDLDX or BNDSTX for their bound directory memory access
Implication	Intel has not observed this erratum with any commercially available software.
Workaround	Software should use canonical addresses for bound directory accesses.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL135	DTS Temperature Reading May be Inaccurate on DDR4 systems
Problem	The temperature reported by the DTS (Digital Thermal Sensor) on DDR4 systems may vary from the actual temperature by +5°C to -15°C rather than the specified $\pm 5^\circ\text{C}$.
Implication	When this erratum occurs, CPU throttling may occur later than expected. Intel has not observed this erratum to have any impact on system.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL136	Performance Monitoring Load Latency Events May Be Inaccurate For Gather Instructions
Problem	The performance monitoring events MEM_TRANS_RETIRED.LOAD_LATENCY_* (Event CDH; UMask 01H; any latency) count load instructions whose latency exceed a predefined threshold, where the loads are randomly selected using the load latency facility (an extension of PEBS). However due to this erratum, these events may count incorrectly for VGATHER*/VPGATHER* instructions
Implication	The Load Latency Performance Monitoring events may be Inaccurate for Gather instructions
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL137	N/A. Erratum has been removed.
---------------	---------------------------------------

SKL138	N/A. Erratum has been removed.
---------------	---------------------------------------

SKL139	Some Bits in MSR_MISC_PWR_MGMT May be Updated on Writing Illegal Values to This MSR
Problem	Attempts to write illegal values to MSR_MISC_PWR_MGMT (MSR 0x1AA) result in #GP (General Protection Fault) and should not change the MSR value. Due to this erratum, some bits in the MSR may be updated on writing an illegal value
Implication	Certain fields may be updated with allowed values when writing illegal values to MSR_MISC_PWR_MGMT. Such writes will always result in #GP as expected.
Workaround	None identified. Software should not attempt to write illegal values to this MSR.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL140	Violations of Intel® Software Guard Extensions (Intel® SGX) Access-Control Requirements Produce #GP Instead of #PF
Problem	Intel® Software Guard Extensions (Intel® SGX) define new access-control requirements on memory accesses. A violation of any of these requirements causes a page fault (#PF) that sets bit 15 (SGX) in the page-fault error code. Due to this erratum, these violations instead cause general-protection exceptions (#GP).
Implication	Software resuming from system sleep states S3 or S4 and relying on receiving a page fault from the above enclave accesses may not operate properly.
Workaround	Software can monitor #GP faults to detect that an enclave has been destroyed and needs to be rebuilt after resuming from S3 or S4
Status	For the stepping's affected, see the Summary Table of Changes.

SKL141	IA32_RTIT_CR3_MATCH MSR Bits[11:5] Are Treated As Reserved
Problem	Due to this erratum, bits[11:5] in IA32_RTIT_CR3_MATCH (MSR 572H) are reserved; an MSR writes that attempts to set that field to a non-zero value will result in a #GP fault.
Implication	The inability to write the identified bit field does not affect the functioning of Intel® PT (Intel® Processor Trace) operation because, as described in erratum SKL061, the bit field that is the subject of this erratum is not used during Intel PT CR3 filtering.
Workaround	Ensure that bits 11:5 of the value written to IA32_RTIT_CR3_MATCH are zero, including cases where the selected page-directory-pointer-table base address has non-zero bits in this range.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL142	APIC Timer Interrupt May Not be Generated at The Correct Time In TSC-Deadline Mode
Problem	After writing to the IA32_TSC_ADJUST MSR (3BH), any subsequent write to the IA32_TSC_DEADLINE MSR (6E0H) may incorrectly process the desired deadline. When this erratum occurs, the resulting timer interrupt may be generated at the incorrect time.
Implication	When the local APIC (Advanced Programmable Interrupt Controller) timer is configured for TSC-Deadline mode, a timer interrupt may be generated much earlier than expected or much later than expected. Intel has not observed this erratum with most commercially available software.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL143	Removed. Duplicate of Errata SKL139
---------------	--

SKL144	Unpredictable System Behavior May Occur When System Agent Enhanced Intel® Speedstep® is Enabled
Problem	Under complex system conditions, System Agent Enhanced Intel® Speedstep® may result in unpredictable system behavior.
Implication	When this erratum occurs, the system may behave unpredictably.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL145	Processor May Hang Under Complex Scenarios
Problem	Under complex micro-architectural conditions, the processor may hang with an internal timeout error (MCACOD 0400H) logged into IA32_MCi_STATUS.
Implication	This erratum results in a processor hang.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL146	The Intel PT CR3 Filter is Not Re-evaluated on VM Entry
Problem	On a VMRESUME or VMLAUNCH with both TraceEn[0] and CR3Filter[7] in IA32_RTIT_CTL (MSR 0570H) set to 1 both before the VM Entry and after, the new value of CR3 is not compared with IA32_RTIT_CR3_MATCH (MSR 0572H).
Implication	The Intel PT (Processor Trace) CR3 filtering mechanism may continue to generate packets despite a mismatching CR3 value, or may fail to generate packets despite a matching CR3, as a result of an incorrect value of IA32_RTIT_STATUS.ContextEn[1] (MSR 0571H) that results from the failure to re-evaluate the CR3 match on VM entry.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL147	Display Slowness May be Observed Under Certain Display Commands Scenario
Problem	Back-to-back accesses to the VGA register ports (I/O addresses 0x3C2, 0x3CE, 0x3CF) will experience higher than expected latency.
Implication	Due to this erratum, the processor may redraw the screen slowly when in VGA mode.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL148	CPUID TLB Associativity Information is Inaccurate
Problem	CPUID leaf 2 (EAX=02H) TLB information inaccurately reports that the shared 2nd-Level TLB is 6-way set associative (value C3H), although it is 12-way set associative. Other information reported by CPUID leaf 2 is accurate.
Implication	Software that uses CPUID shared 2 nd -level TLB associativity information for value C3H may operate incorrectly. Intel has not observed this erratum to impact the operation of any commercially available software.
Workaround	None identified. Software should ignore the shared 2nd-Level TLB associativity information reported by CPUID for the affected processors.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL149	Processor Graphics May Render Incorrectly or May Hang Following Warm Reset With Package C8 Disabled
Problem	Processor Graphics may not properly restore internal configuration after warm reset when package C8 is disabled.
Implication	Due to this erratum Processor Graphics may render incorrectly or hang on warm reset.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL150	Short Loops Which Use AH/BH/CH/DH Registers May Cause Unpredictable System Behavior
Problem	Under complex micro-architectural conditions, short loops of fewer than 64 instructions that use AH, BH, CH or DH registers as well as their corresponding wider register (e.g. RAX, EAX or AX for AH) may cause unpredictable system behavior. This can only happen when both logical processors on the same physical processor are active.
Implication	Due to this erratum, the system may experience unpredictable system behavior.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL151	Processor Graphics May Render Incorrectly or May Hang Following Warm Reset With Package C8 Disabled
Problem	Processor Graphics may not properly restore internal configuration after warm reset when package C8 is disabled.
Implication	Due to this erratum Processor Graphics may render incorrectly or hang on warm reset.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL152	Unpredictable System Behavior May Occur in DDR4 Multi-Rank System
Problem	Due to incorrect configuration of DDR4 ODT by BIOS, it is possible for a multi-rank system to violate section 4.27 of the DDR4 JEDEC spec revision JESED79-4A.
Implication	Due to this erratum, complex microarchitectural conditions may result in unpredictable system behavior
Workaround	A BIOS workaround has been identified. Please refer to Silicon Initialization version 2.1.0 or later and release notes
Status	For the stepping's affected, see the Summary Table of Changes.

SKL153	Processor May Hang on Complex Sequence of Conditions
Problem	A complex set of architectural and micro-architectural conditions may lead to a processor hang with an internal timeout error (MCACOD 0400H) logged into IA32_MCi_STATUS. When both logical processors in a core are active, this erratum will not occur unless there is no store on one of the logical processors for more than 10 seconds.
Implication	This erratum may result in a processor hang. Intel has not observed this erratum with any commercially available software.
Workaround	None Identified.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL154	Intel® SGX Vulnerability May Impact Enclave Security
Problem	There is a vulnerability that may allow a malicious party to impact the security of an SGX (Intel® Software Guard Extensions) enclave. Exploitation of the vulnerability requires the malicious party to modify BIOS code.
Implication	Malicious Software may be able to modify enclave data or code.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL155	MOVNTDQA From WC Memory May Pass Earlier Locked Instructions
Problem	An execution of (V)MOVNTDQA (streaming load instruction) that loads from WC (write combining) memory may appear to pass an earlier locked instruction to a different cache line
Implication	Software that expects a lock to fence subsequent (V)MOVNTDQA instructions may not operate properly.
Workaround	Software should not rely on a locked instruction to fence subsequent executions of MOVNTDQA. Software should insert an MFENCE instruction if it needs to preserve order between streaming loads and other memory operations.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL156	Spurious Corrected Errors May be Reported
Problem	Due to this erratum, spurious corrected errors may be logged in the IA32_MC0_STATUS MSR (401H) register with the valid field (bit 63) set, the uncorrected error field bit (bit 61) not set, a Model Specific Error Code (bits [31:16]) of 0x0001, and an MCA Error Code (bits [15:0]) of 0x0005. If CMCI is enabled, these spurious corrected errors also signal interrupts.
Implication	When this erratum occurs, software may see an unusually high rate of reported corrected errors. As it is not possible to distinguish between spurious and non-spurious errors, this erratum may interfere with reporting non-spurious corrected errors
Workaround	None Identified
Status	For the stepping's affected, see the Summary Table of Changes.



SKL157	Masked Bytes in a Vector Masked Store Instructions May Cause Write Back of a Cache Line
Problem	Vector masked store instructions to WB (write-back) memory-type that cross cache lines may lead to CPU writing back cached data even for cache lines where all of the bytes are masked
Implication	The processor may generate writes of un-modified data. This can affect MMIO (Memory Mapped IO) or non-coherent agents in the following ways: <ol style="list-style-type: none">1. For MMIO range that is mapped as WB memory type, this erratum may lead to MCE (Machine Check Exception) due to writing back data into the MMIO space. This applies only to cross page vector masked stores where one of the pages is in MMIO range.2. If the CPU cached data is stale, for example in the case of memory written directly by a non-coherent agent (agent that uses non-coherent writes), this erratum may lead to writing back stale cached data even if these bytes are masked
Workaround	Platforms should not map MMIO memory space or non-coherent device memory space as WB memory. If WB is used for MMIO range, software or VMM should not map such MMIO page adjacent to a regular WB page (adjacent on the linear address space, before or after the IO page). Memory that may be written by non-coherent agents should be separated by at least 64 bytes from regular memory used for other purposes (on the linear address space)
Status	For the stepping's affected, see the Summary Table of Changes.

SKL158	WRMSR to IA32_BIOS_UPDT_TRIG Concurrent With an SMX SENTER/SEXIT May Result in a System Hang
Problem	Performing WRMSR to IA32_BIOS_UPDT_TRIG (MSR 79H) on a logical processor while another logical processor is executing an SMX (Safer Mode Extensions) SENTER/SEXIT operation (GETSEC[SENTER] or GETSEC[SEXIT] instruction) may cause the processor to hang.
Implication	When this erratum occurs, the system will hang. Intel has not observed this erratum with any commercially available system.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL159	Use of VMASKMOV to Store When Using EPT May Fail
Problem	Use of VMASKMOV instructions to store data that splits over two pages, when the instruction resides on the first page may cause a hang if EPT (Extended Page Tables) is in use, and the store to the second page requires setting the A/D bits in the EPT entry.
Implication	Due to this erratum, the CPU may hang on the execution of VMASKMOV.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL160	Writing Non-Zero Values to Read Only Fields in IA32_THERM_STATUS MSR May #GP
Problem	IA32_THERM_STATUS MSR (19CH) includes read-only (RO) fields as well as writable fields. Writing a non-zero value to any of the read-only fields may cause a #GP.
Implication	Due to this erratum, software that reads the IA32_THERM_STATUS MSR, modifies some of the writable fields, and attempts to write the MSR back may #GP.
Workaround	Software should clear all read-only fields before writing to this MSR
Status	For the stepping's affected, see the Summary Table of Changes.

SKL161	Precise Performance Monitoring May Generate Redundant PEBS Records
Problem	Processor Event Based Sampling (PEBS) may generate redundant records for a counter overflow when used to profile cycles. This may occur when a precise performance monitoring event is configured on a general counter while setting the Invert and Counter Mask fields in IA32_PERFEVTSELx MSRs (186H - 18DH), and the counter is reloaded with a value smaller than 1000 (through the PEBS-counter-reset field of the DS Buffer Management Area).
Implication	PEBS may generate multiple redundant records, when used to profile cycles in certain conditions.
Workaround	It is recommended for software to forbid the use of the Invert bit in IA32_PERFEVTSELx MSRs or restrict PEBS-counter-reset value to a value of at least 1000.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL162	SGX ENCLS[EINIT] May Not Signal an Error For an Incorrectly Formatted SIGSTRUCT Input
Problem	The ENCLS[EINIT] instruction leaf may not signal an error on a specific combination of SIGSTRUCT values even though the signature does not fully comply with RSA signature specifications
Implication	When this erratum occurs, ENCLS[EINIT] instruction leaf may pass the checks although the SIGSTRUCT signature doesn't fully comply with RSA signature specifications. This erratum doesn't compromise the security of SGX and does not impact normal usage of SGX.
Workaround	None identified. Software is not expected to be impacted by this erratum.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL163	Branch Instruction Address May be Incorrectly Reported on TSX Abort When Using MPX
Problem	When using Intel® Memory Protection Extensions (MPX), an Intel® Transactional Synchronization Extensions (TSX) transaction abort will occur in case of legacy branch (that causes bounds registers INIT) when at least one MPX bounds register was in a NON-INIT state. On such an abort, the branch Instruction address should be reported in the FROM_IP field in the Last Branch Records (LBR), Branch Trace Store (BTS) and Branch Trace Message (BTM) as well as in the Flow Update Packets (FUP) source IP address for Processor Trace (PT). Due to this erratum, the FROM_IP field in LBR/BTS/BTM, as well as the Flow Update Packets (FUP) source IP address that corresponds to the TSX abort, may point to the preceding instruction.
Implication	Software that relies on the accuracy of the FROM_IP field / FUP source IP address and uses TSX may operate incorrectly when MPX is used.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL164	Setting Performance Monitoring IA32_PERF_GLOBAL_STATUS_SET MSR Bit 63 May Not #GP
Problem	Bit 63 of IA32_PERF_GLOBAL_STATUS_SET MSR (391H) is reserved. Due to this erratum, setting the bit will not result in General Protection Fault (#GP).
Implication	Software that attempts to set bit 63 of IA32_PERF_GLOBAL_STATUS_SET MSR does not generate #GP. There are no other system implications to this behavior
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL165	Hitting a Code Breakpoint Inside a SGX Debug Enclave May Cause The Processor to Hang
Problem	Under complex microarchitecture conditions, the processor may hang when hitting a code breakpoint inside an SGX (Intel® Software Guard Extensions) debug enclave. This may happen only after opt-out entry into an SGX debug enclave and when the execution would set the accessed bit (A-bit) in any level of the paging or EPT (extended page table) structures used to map the code page, and when both logical processors on the same physical core are active.
Implication	Due to this erratum, the processor may hang while debugging an SGX debug enclave.
Workaround	None identified.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL166	Performance Monitoring ASCI Status Bit May be Inaccurate
Problem	The ASCI (Anti Side-Channel Interference) field in IA32_PERF_GLOBAL_STATUS (MSR 38EH, bit 60) should be set when the count in any of the configured performance counters (i.e. IA32_PMCx or IA32_FIXED_CTRx) was altered due to direct or indirect operation of Intel® SGX. Due to this erratum, the ASCI bit may not be set properly when IA32_FIXED_CTR0 is used.
Implication	Software that relies on the value of the ASCI bit in IA32_PERF_GLOBAL_STATUS for its operation may not operate correctly when IA32_FIXED_CTR0 is used.
Workaround	None identified
Status	For the stepping's affected, see the Summary Table of Changes.



SKL167	Processor May Hang When Executing Code In an HLE Transaction
Problem	Under certain conditions, if the processor acquires an HLE (Hardware Lock Elision) lock via the XACQUIRE instruction in the Host Physical Address range between 40000000H and 403FFFFFFH, it may hang with an internal timeout error (MCACOD 0400H) logged into IA32_MCI_STATUS.
Implication	Due to this erratum, the processor may hang after acquiring a lock via XACQUIRE.
Workaround	BIOS can reserve the host physical address ranges of 40000000H and 403FFFFFFH (e.g. map it as UC/MMIO). Alternatively, the VMM (Virtual Machine Monitor) can reserve that address range so no guest can use it. In non-virtualized systems, the OS can reserve that memory space.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL168	Intel® PT CYC Packets Can be Dropped When Immediately Preceding PSB
Problem	Due to a rare microarchitectural condition, generation of an Intel® PT (Processor Trace) PSB (Packet Stream Boundary) packet can cause a single CYC (Cycle Count) packet, possibly along with an associated MTC (Mini Time Counter) packet, to be dropped
Implication	An Intel® PT decoder that is using CYCs to track time or frequency will get an improper value due to the lost CYC packet
Workaround	If an Intel® PT decoder is using CYCs and MTCs to track frequency, and either the first MTC following a PSB shows that an MTC was dropped, or the CYC value appears to be 4095 cycles short of what is expected, the CYC value associated with that MTC should not be used. The decoder should wait for the next MTC before measuring frequency again.
Status	For the stepping's affected, see the Summary Table of Changes.

SKL169	Intel® PT VM-entry Indication Depends on The Incorrect VMCS Control Field
Problem	An Intel® Processor Trace PIP (Paging Information Packet), which includes indication of entry into non-root operation, will be generated on VM-entry as long as the "Conceal VMX in Intel® PT" field (bit 19) in Secondary Execution Control register (IA32_VMX_PROCBASED_CTLDS2, MSR 048BH) is clear. This diverges from expected behavior, since this PIP should instead be generated only with a zero value of the "Conceal VMX entries from Intel® PT" field (Bit 17) in the Entry Control register (IA32_VMX_ENTRY_CTLDS MSR 0484H).
Implication	An Intel® PT trace may incorrectly expose entries to non-root operation.
Workaround	A VMM (virtual machine monitor) should always set both the "Conceal VMX entries from Intel® PT" field in the Entry Control register and the "Conceal VMX in Intel® PT" in the Secondary Execution Control register to the same value.
Status	For the stepping's affected, see the Summary Table of Changes.



SKL170	VCVTPS2PH To Memory May Update MXCSR in The Case of a Fault on The Store
Problem	Execution of the VCVTPS2PH instruction with a memory destination may update the MXCSR exceptions flags (bits [5:0]) if the store to memory causes a fault (e.g., #PF) or VM exit. The value written to the MXCSR exceptions flags is what would have been written if there were no fault.
Implication	Software may see exceptions flags set in MXCSR, although the instruction has not successfully completed due to a fault on the memory operation. Intel has not observed this erratum to affect any commercially available software.
Workaround	None identified
Status	For the stepping's affected, see the Summary Table of Changes.

SKL171	Intel® PT May Drop All Packets After an Internal Buffer Overflow
Problem	Due to a rare microarchitectural condition, an Intel® PT (Processor Trace) ToPA (Table of Physical Addresses) entry transition can cause an internal buffer overflow that may result in all trace packets, including the OVF (Overflow) packet, being dropped.
Implication	When this erratum occurs, all trace data will be lost until either PT is disabled and re-enabled via IA32_RTIT_CTL.TraceEn [bit 0] (MSR 0570H) or the processor enters and exits a C6 or deeper C state.
Workaround	None identified
Status	For the stepping's affected, see the Summary Table of Changes.

SKL172	Intel® PT ToPA Tables Read From Non-Cacheable Memory During an Intel® TSX Transaction May Lead to Processor Hang
Problem	If an Intel® PT (Processor Trace) ToPA (Table of Physical Addresses) table is placed in UC (Uncacheable) or USWC (Uncacheable Speculative Write Combining) memory, and a ToPA output region is filled during an Intel® TSX (Transaction Synchronization) transaction, the resulting ToPA table read may cause a processor hang.
Implication	Placing Intel® PT ToPA tables in non-cacheable memory when Intel® TSX is in use may lead to a processor hang.
Workaround	None identified. Intel PT ToPA should reside in WB memory and should not be written within a Transactional Region.
Status	For the steppings affected, see the Summary Table of Changes.



SKL173	Performing an XACQUIRE to an Intel® PT ToPA Table May Lead to Processor Hang
Problem	If an XACQUIRE lock is performed to the address of an Intel® PT (Processor Trace) ToPA (Table of Physical Addresses) table, and that table is later read by the CPU during the HLE (Hardware Lock Elision) transaction, the processor may hang.
Implication	Accessing ToPA tables with XACQUIRE may result in a processor hang.
Workaround	None identified. Software should not access ToPA tables using XACQUIRE. An OS or hypervisor may wish to ensure all application or guest writes to ToPA tables to take page faults or EPT violations.
Status	For the steppings affected, see the Summary Table of Changes.

SKL174	ZMM/YMM Registers May Contain Incorrect Values
Problem	Under complex microarchitectural conditions values stored in ZMM and YMM registers may be incorrect.
Implication	Due to this erratum, YMM and ZMM registers may contain an incorrect value. Intel® has not observed this erratum with any commercially available software.
Workaround	It is possible for BIOS to contain a workaround for this erratum.
Status	For the steppings affected, see the Summary Table of Changes.

SKL175	Intel® PT CYC Packet Can be Dropped When Immediately Preceding PSB
Problem	Due to a rare microarchitectural condition, generation of an Intel® PT (Processor Trace) PSB (Packet Stream Boundary) packet can cause a single CYC (Cycle Count) packet, possibly along with an associated MTC (Mini Time Counter) packet, to be dropped.
Implication	An Intel® PT decoder that is using CYCs to track time or frequency will get an improper value due to the lost CYC packet.
Workaround	If an Intel® PT decoder is using CYCs and MTCs to track frequency, and either the first MTC following a PSB shows that an MTC was dropped, or the CYC value appears to be 4095 cycles short of what is expected, the CYC value associated with that MTC should not be used. The decoder should wait for the next MTC before measuring frequency again.
Status	For the steppings affected, see the Summary Table of Changes.



SKL176	When Virtualization Exceptions are Enabled, EPT Violations May Generate Erroneous Virtualization Exceptions
Problem	An access to a GPA (guest-physical address) may cause an EPT-violation VM exit. When the "EPT-violation #VE" VM-execution control is 1, an EPT violation may cause a #VE (virtualization exception) instead of a VM exit. Due to this erratum, an EPT violation may erroneously cause a #VE when the "suppress #VE" bit is set in the EPT paging-structure entry used to map the GPA being accessed. This erratum does not apply when the "EPT-violation #VE" VM-execution control is 0 or when delivering an event through the IDT. This erratum applies only when the GPA in CR3 is used to access the root of the guest paging-structure hierarchy (or, with PAE paging, when the GPA in a PDPTE is used to access a page directory).
Implication	When using PAE paging mode, an EPT violation that should cause a VMexit in the VMM may instead cause a VE# in the guest. In other paging modes, in addition to delivery of the erroneous #VE, the #VE may itself cause an EPT violation, but this EPT violation will be correctly delivered to the VMM.
Workaround	A VMM may support an interface that guest software can invoke with the VMCALL instruction when it detects an erroneous #VE.
Status	For the steppings affected, see the Summary Table of Changes.

SKL177	System May Hang With Multiple Pending Posted Writes When Using Direct MMIO Write Access Model
Problem	Under complex conditions, if a device fails to consume at least 8 posted writes within 5us and its device driver uses a Direct MMIO write access software model and Enhanced Intel® Speed Step® Technology is enabled, the system may hang with an internal timer error machine check with error code IA32_MCI_STATUS[15:0] = 0x0400. Implication: Due to this erratum, the system may hang. Intel has only observed this erratum to occur with a direct MMIO write access model.
Implication	Due to this erratum, the system may hang. Intel has only observed this erratum to occur with a direct MMIO write access model.
Workaround	None identified.
Status	For the steppings affected, see the Summary Table of Changes.

SKL178	Using Intel® TSX Instructions May Lead to Unpredictable System Behavior
Problem	Under complex microarchitectural conditions, software using Intel® TSX (Transactional Synchronization Extensions) may result in unpredictable system behavior. Intel has only seen this under synthetic testing conditions. Intel is not aware of any commercially available software exhibiting this behavior.
Implication	Due to this erratum, unpredictable system behavior may occur.
Workaround	It is possible for BIOS to contain a workaround for this erratum.
Status	For the steppings affected, see the Summary Table of Changes.



SKL179	Performance Monitoring General Purpose Counter 3 May Contain Unexpected Values
Problem	When Restricted Transactional Memory (RTM) is supported (CPUID.07H.EBX.RTM [bit 11] = 1) and when TSX_FORCE_ABORT=0, Performance Monitor Unit (PMU) general purpose counter 3 (IA32_PMC3, MSR C4H and IA32_A_PMC3, MSR 4C4H) may contain unexpected values. Further, IA32_PREFEVTSEL3 (MSR 189H) and IA32_PERF_GLOBAL_CTRL[3] (MSR 38FH) may contain unexpected configuration values; which may also affect IA32_PERF_GLOBAL_INUSE[3] (MSR 392H).
Implication	Due to this erratum, software that uses PMU general purposes counter 3 may read an unexpected count and configuration.
Workaround	Software can avoid this erratum by writing 1 to bit 0 of TSX_FORCE_ABORT (MSR 10FH) which will cause all Restricted Transactional Memory (RTM) transactions to abort with EAX code 0. TSX_FORCE_ABORT MSR is available when CPUID.07H.EDX[bit 13]=1.
Status	For the steppings affected, see the Summary Table of Changes.

SKL180	Unexpected Uncorrected Machine Check Errors May Be Reported
Problem	In rare micro-architectural conditions, the processor may report unexpected machine check errors. When this erratum occurs, IA32_MC0_STATUS (MSR 401H) will have the valid bit set (bit 63), the uncorrected error bit set (bit 61), a model specific error code of 03H (bits [31:16]) and an MCA error code of 05H (bits [15:0]).
Implication	Due to this erratum, software may observe unexpected machine check exceptions.
Workaround	None identified.
Status	For the steppings affected, see the Summary Table of Changes.

SKL181	Intel® PT Trace May Drop Second Byte of CYC Packet
Problem	Due to a rare microarchitectural condition, the second byte of a 2-byte CYC (Cycle Count) packet may be dropped without an OVF (Overflow) packet.
Implication	A trace decoder may signal a decode error due to the lost trace byte.
Workaround	None identified. A mitigation is available for this erratum. If a decoder encounters a multi-byte CYC packet where the second byte has bit 0 (Ext) set to 1, it should assume that 4095 cycles have passed since the prior CYC packet, and it should ignore the first byte of the CYC and treat the second byte as the start of a new packet.
Status	For the steppings affected, see the Summary Table of Changes.

SKL182	Executing Some Instructions May Cause Unpredictable Behavior
Problem	Under complex micro-architectural conditions, executing an X87, AVX, or integer divide instruction may result in unpredictable system behavior.
Implication	When this erratum occurs, the system may behave unpredictably. Intel has not observed this erratum with any commercially available software.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the steppings affected, see the Summary Table of Changes.



SKL183	A Pending Fixed Interrupt May Be Dispatched Before an Interrupt of The Same Priority Completes
Problem	Resuming from C6 Sleep-State, with Fixed Interrupts of the same priority queued (in the corresponding bits of the IRR and ISR APIC registers), the processor may dispatch the second interrupt (from the IRR bit) before the first interrupt has completed and written to the EOI register, causing the first interrupt to never complete.
Implication	Due to this erratum, Software may behave unexpectedly when an earlier call to an Interrupt Handler routine is overridden with another call (to the same Interrupt Handler) instead of completing its execution.
Workaround	It is possible for the BIOS to contain a workaround for this erratum.
Status	For the steppings affected, see the Summary Table of Changes.

SKL184	Incorrect Execution of Internal Branch Instructions May Lead to Unpredictable System Behavior
Problem	Under complex microarchitecture conditions, incorrect execution of internal branch instructions that span multiple 64 byte boundaries (cross cache line), may result in unpredictable system behavior including unexpected #PF (page faults) or #UD (Invalid Opcode) faults due to incorrect execution of internal branch operations.
Implication	When this erratum occurs, the system may exhibit unpredictable system behavior including unexpected #PF (page faults) or #UD (Invalid Opcode) faults.
Workaround	It is possible for BIOS to contain a workaround for this erratum.
Status	For the steppings affected, see the Summary Table of Changes.

SKL185	Processor May Behave Unpredictably on Complex Sequence of Conditions Which Involve Branches That Cross 64 Byte Boundaries
Problem	Under complex micro-architectural conditions involving branch instructions bytes that span multiple 64 byte boundaries (cross cache line), unpredictable system behavior may occur.
Implication	When this erratum occurs, the system may behave unpredictably.
Workaround	It is possible for BIOS to contain a workaround for this erratum.
Status	For the steppings affected, see the Summary Table of Changes.

SKL186	A PMI That Freezes LBRs Can Cause a Duplicate Entry in TOS
Problem	If a PMI (Performance Monitor Interrupt) is taken while LBRs (Last Branch Records) are enabled and IA32_DEBUGCTL.FREEZE_LBRS_ON_PMI[bit 11]=1 (MSR 01D9H), a taken branch that performs an LBR update near the time of the PMI may instead record a duplicate of the prior entry into the TOS (Top of Stack) entry.
Implication	Software may unexpectedly observe the appearance of back-to-back execution of the same branch.
Workaround	In general, software can ignore the TOS entry if it matches the TOS-1 entry. Note that certain code sequences with no intervening taken branches can legitimately insert a valid duplicate LBR record in the TOS entry.
Status	For the steppings affected, see the Summary Table of Changes.



SKL187	SGX Key Confidentiality May be Compromised
Problem	Under complex micro-architectural conditions, it may be possible for the value of SGX keys to be inferred using speculative execution side channel methods.
Implication	If exposed, such keys could allow an attacker to access SGX enclave data. Processors that do not support Hyper-Threading are not affected by this issue.
Workaround	It is possible for BIOS to contain a workaround for this erratum.
Status	For the steppings affected, see the Summary Table of Changes.

SKL188	Unexpected Page Faults in Guest Virtualization Environment
Problem	Under complex micro-architectural conditions, a virtualized guest could observe unpredictable system behavior.
Implication	When this erratum occurs, systems operating in a virtualization environment may exhibit unexpected page faults (double faults) leading to guest OS shutdown.
Workaround	It is possible for BIOS to contain a workaround for this erratum.
Status	For the steppings affected, see the Summary Table of Changes.

SKL189	System May Hang Under Complex Conditions
Problem	Under complex conditions, insufficient access control in graphics subsystem may lead to a system hang or crash upon a register read.
Implication	When this erratum occurs a system hang or crash may occur.
Workaround	It is possible for a combination of BIOS and a graphics driver to contain a workaround for this erratum.
Status	For the steppings affected, see the Summary Table of Changes.



SKL190	Instruction Fetch May Cause Machine Check if Page Size Was Changed Without Invalidation
Problem	This erratum may cause a machine-check error (IA32_MCI_STATUS.MCACOD=005H with IA32_MCI_STATUS.MSCOD=00FH or IA32_MCI_STATUS.MCACOD=0150H with IA32_MCI_STATUS.MSCOD=00FH) on the fetch of an instruction. It applies only if (1) instruction bytes are fetched from a linear address translated using a 4-Kbyte page and cached in the processor; (2) the paging structures are later modified so that these bytes are translated using a large page (2-Mbyte, 4-Mbyte or 1-GByte) with a different physical address (PA), memory type (PWT, PCD and PAT bits), or User/Supervisor (U/S) bit; and (3) the same instruction is fetched after the paging structure modification but before software invalidates any TLB entries for the linear region.
Implication	Due to this erratum an unexpected machine check with error code 0150H with MSCOD 00FH may occur, possibly resulting in a shutdown. This erratum could also lead to unexpected correctable machine check (IA32_MCI_STATUS.UC=0) with error code 005H with MSCOD 00FH.
Workaround	Software should not write to a paging-structure entry in a way that would change the page size and either the physical address, memory type or User/Supervisor bit. It can instead use one of the following algorithms: first clear the P flag in the relevant paging-structure entry (e.g., PDE); then invalidate any translations for the affected linear addresses; and then modify the relevant paging-structure entry to set the P flag and establish the new page size. An alternative algorithm: first change the physical page attributes (combination of physical address, memory type and User/Supervisor bit) in all 4K pages in the affected linear addresses; then invalidate any translations for the affected linear addresses; and then modify the relevant paging-structure entry to establish the new page size.
Status	For the steppings affected, see the Summary Table of Changes.

SKL191	PEG PCIe Link May Fail to Link When Resuming From PKG-C8
Problem	PEG IO registers may not be restored after resuming from PKG-C8. Alternate problem: The processor's PCIe root port configuration registers may not be properly restored when resuming from PKG-C8.
Implication	PEG PCIe may fail to link when resuming from PKG-C8. Note: PCIe add-in cards that do not support the L2 state do not encounter this issue as they do not allow the platform to enter PKG-C8. <i>Alternate problem:</i> The processor PCIe root port may fail to establish a link when resuming from PKG-C8.
Workaround	A fix for this erratum is available in microcode. Please see Microcode Update Tables in this document.
Status	For the steppings affected, see the Summary Table of Changes.



SKL192	Incorrect ECC Errors Reporting Following Entry to PKG-C7
Problem	The Correctable and Uncorrectable ECC error address reported in ECCERRLOG0/1 (MCHBAR Offset 4048h/404Ch) may be overwritten after a PKG-C7 event.
Implication	DDR Correctable and Uncorrectable ECC errors reported in ECCERRLOG0/1 (MCHBAR Offset 4048h/404Ch) may report an incorrect error address after resuming from PKG-C7.
Workaround	None identified.
Status	For the steppings affected, see the Summary Table of Changes.

SKL193	PMU MSR_UNC_PERF_FIXED_CTR is Cleared After Pkg C7 or Deeper
Problem	The Performance Monitoring Unit Uncore Performance Fixed Counter (MSR_UNC_PERF_FIXED_CTR (MSR 395h)) is cleared after pkg C7 or deeper.
Implication	Due to this erratum, once the system enters pkg C7 or deeper the uncore fixed counter does not reflect the actual count.
Workaround	None identified.
Status	For the steppings affected, see the Summary Table of Changes.

SKL194	Performance Monitoring General Counter 2 May Have Invalid Value Written When TSX Is Enabled
Problem	When Transactional Synchronization Extensions (TSX) is enabled, and there are aborts (HLE or RTM) overlapping with access or manipulation of the IA32_PMC2 general-purpose performance counter (Offset: C3h) it may return invalid value.
Implication	Software may read invalid value from IA32_PMC2.
Workaround	None identified.
Status	For the steppings affected, see the Summary Table of Changes.

SKL195	Display VT-d TLB invalidation during disabling of VTd Translations May Cause Display Corruption or Flickering
Problem	If a hypervisor/VMM has enabled VTd translations for the Gfx IOMMU (TE=1 in VTd specification) and then switches the Gfx IOMMU to disable translations (TE=0) with DMA remapping enabled in the BIOS, the display VTd TLB may be invalidated without waiting for any pending memory requests to complete.
Implication	Due to this erratum, momentary display corruption or flickering may occur during boot.
Workaround	None identified.
Status	For the steppings affected, see the Summary Table of Changes.



SKL196	Processor May Hang if Warm Reset Triggers During BIOS Initialization
Problem	Under complex micro-architectural conditions, when the processor receives a warm reset during BIOS initialization, the processor may hang with a machine check error reported in IA32_MCI_STATUS, with MCACOD (bits [15:0]) value of 0400H, and MSCOD (bits [31:16]) value of 0080H.
Implication	Due to this erratum, the processor may hang. Intel has only observed this erratum in a synthetic test environment.
Workaround	None identified.
Status	For the steppings affected, see the Summary Table of Changes.

SKL197	Erratum has been removed
---------------	---------------------------------

SKL198	MD_CLEAR Operations May Not Properly Overwrite All Buffers
Problem	Problem: On processors that enumerate the MD_CLEAR CPUID bit (CPUID.(EAX=7H,ECX=0):EDX[MD_CLEAR=10]), L1D_FLUSH, RSM, and VERW memory instructions should overwrite affected buffers with constant data. Under complex micro-architectural conditions, these instructions may not overwrite all affected buffers.
Implication	Due to this erratum, the use of MD_CLEAR operations to prevent MDS (Microarchitectural Data Sampling) or TAA (Intel® Transactional Synchronization Extensions Asynchronous Abort) side-channel methods from revealing previously accessed data may not be fully effective.
Workaround	It is possible for BIOS to contain a workaround for this erratum.
Status	For the steppings affected, see the Summary Table of Changes.



Specification Changes

There are no Specification Changes in this revision.

§



Specification Clarifications

There are no specification clarifications in this revision.

§



Documentation Changes

[H,S,U] 6th Generation Intel® Processor Datasheet – Volume 2 of 2 Update
6th Generation Intel® Processor Datasheet Volume 2 of 2 for U/Y-Platforms (Doc# 332991), S-Platforms (Doc# 332688) and H-Platforms (Doc# 332987) are expected to include additional information for Bit Range 3:0 NSPD in the next revision:

Section 6.23: DMI Link Status (LSTS)—Offset 8Ah

Bit Range	Default & Access	Field Name (ID): Description
3:0	1h ROV	NSPD: Negotiated Speed: Indicates negotiated link speed. 1h: 2.5 Gb/s 2h: 5.0 Gb/s 3h: 8.0 Gb/s All other encodings are reserved. The value in this field is undefined when the Link is not up.

[H,S,U] 6th Generation Intel® Processor Datasheet – Volume 2 of 2 Update
6th Generation Intel® Processor Datasheet Volume 2 of 2 for U/Y-Platforms (Doc# 332991), S-Platforms (Doc# 332688) and H-Platforms (Doc# 332987) are expected to be updated in next revision as following:

Section 12.39: Link Control (LCTL) – Offset B0h

Bit Range	Default & Access	Field Name (ID): Description
5	0h WO	RL: Retrain Link: 0b Normal operation. 1b Full Link retraining is initiated by directing the Physical Layer LTSSM from L0, L0s, or L1 states to the Recovery state. This bit always returns 0 when read. This bit is cleared automatically (no need to write a 0)