

High Voltage Diagnostics and Trouble Shooting in MicroBooNE

(The MicroBooNE Collaboration)

(Dated: March 28, 2017)

Abstract

At the end of January, MicroBooNE ramped down it's drift HV system after a series of unusual and worrying behavior on HV monitoring plots. This document presents a summary of the tests performed, diagnostics developed, and a chronological ordering of events. We also include some "lessons learned" that may be useful to future LArTPCs.

10 **I. INTRODUCTION**

11 **II. DESCRIPTION OF MICROBOONE HV SYSTEM**

12 **A. HV Supply**

13 **B. HV Feedthrough**

14 **C. Cathode and Resistor Chain**

15 **D. Anode and Wire Bias**

16 **E. Pickoff Point**

17 **III. SYMPTOMS**

18 As the high voltage issues developed, several symptoms were identified which
19 provided metrics to judge the stability or instability of the system. Several were
20 monitoring variables of the HV system itself, such as the current readback from the
21 Glassman power supply and the voltage of the pickoff point. Others were detected
22 through the readout of the detector, including persistent high frequency (900kHz)
23 noise on some detector channels, and “burst” events, described below.

24 **A. Pickoff Point Instability**

25 The first symptom to be detected during MicroBooNE’s high voltage incident
26 was large, sustained deviations on the pickoff point (see Section II E). Nominally,
27 this point sits at a value of approximately $\frac{5M\Omega}{17.1G\Omega} = 0.029\%$ of the applied voltage by
28 the power supply. As seen in Figure 1, the pickoff point values deviated significantly
29 from the nominal values. In this figure, the band of nominal values is selected as the
30 minimum and maximum of a two week stable period.

31 **B. HV Power Supply Current RMS**

32 As seen in Figure 1 is the calculated current from the back of the high voltage
33 power supply. The power supply outputs and analog voltage from which we derive
34 a current using the following formula:

35 The current shown in the figure demonstrates clear increases in noisiness when the
36 pickoff point deviations occur, indicating that whatever the cause of the problems is,
37 it affects both the HV power supply and the pickoff point simultaneously.

38 Because of the way the monitoring data is archived, we lack precise enough data




Figure 1. Pickoff point deviations over the weekend of Jan 27th. Though the absolute calibration is not correct on the current from the HV power supply, there is clearly a correlation between the pickoff point deviations and noise on the HV power supply.

to calculate an RMS of the calculated current from the back of the power supply, and can make only qualitative comparisons to historical data. We have since implemented archiving of not just the values output by the power supply, but also the noise on those value measurements.

C. TPC Asic LV Current Draw

In coincidence with the large deviations of the pickoff point, MicroBooNE also observed increased current draw on a handful of power supplies for the cold electronics. Figure 2 shows the increased draw on the worst feedthrough, labeled within the detector as “FT1.” High current draws are not unusual, though this incident

48 required multiple power cycles to restore nominal operation. Additionally, the final
 49 power cycle on 1/29/17 just before 14:00 CST occurred after the detector's high volt-
 50 age had been decreased from 70kV to 65kV. After this, the current draw was stable
 51 for some time, though later attempts to ramp up the detector also caused increased
 52 current draw on this feedthrough.




Figure 2. The current for the cold electronics power supply during the same time period as Figure1.

53 The increased current draw is correlated well with a persistant noise state on
 54 the detector electronics. It is thought that the high voltage instability induces a
 55 noise state on the electronics that persists until the electronics are reconfigured or
 56 power cycled, which is why the power cycles in Figure 2 show normal current draw
 57 afterwards, at least temporarily, for 3 of the 4 power cycles shown.

58 Figure 4 shows an event display of the part of the detector impacted by the
 59 persistant noise state. Figure 3 shows a portion of a waveform from this region

60 compared to normal running conditions. The increase in noise is almost exclusively
61 at the 900kHz band, and shows a dramatic increase over the usual noise at 900kHz.

62 Based on the observations of increased noise on the feedthroughs showing in-
63 creased current draw, the symptom of current draw is a secondary symptom of the
64 high voltage instabilities. A high voltage incident (like a “burst” event discussed
65 below) likely induces a bad state in the detector electronics when it overloads the
66 input on the electronics. We saw many incidences of increased current draw on
67 the feedthrough that started after high voltage instabilities, but we never observed
68 increased current draw when the high voltage was not on.

69 **D. “Burst” Events**

70 The last observation of high voltage instability symptoms are the “burst” events,
71 an example of which is shown in Figure ???. In these events, we see high ADC counts
72 on all channels, across all three readout planes, simultaneously. Even wires that are
73 unresponsive see these burst events, as shown in Figure 6.

74 The pulse amplitude after burst event shows a very long return to baseline after
75 the event occurs, seen in both Figures 5 and 6. There are several notable features of
76 these events:

- 77 • **Wire length dependence**
- 78 • **Saturation of channels**
- 79 • **Signal on unresponsive channels**




Figure 3.






Figure 4.

80 IV. DIAGNOSTICS

81 A. (Warm) HV Supply Tests

82 After the weekend of Jan 27th, 2017, MicroBooNE powered down the drift high
 83 voltage supply to investigate. To diagnose the source of the troubling, a large number
 84 of procedures were attempted, described here.






Figure 6. Burst event waveforms from U plane wires. In the top image, the entire waveform is shown, demonstrating the long return to baseline that produces the rainbow appearance in the U plane of Figure 5. In the bottom image is shown the wire response at the incidence of the burst event, as well as the response on an unresponsive channel.

85 1. *Glassman HV Supply replacement*

86 The very first test performed on the system was to replace the high voltage power
87 supply. The system is a a Glassman power supply, described in Section II A. A
88 spare was available and installed, and when the spare supply was powered on no
89 observable difference was detected in the behavior of the system. The spare supply
90 was not ramped to a high voltage initially, since the symptoms were clearly occurring
91 at a relatively low ($<10\text{kV}$) voltage.

92 2. *HV Cable inspection*

93 The next obvious step to search for a hardware failure was in the high voltage
94 cables that bring the high voltage from the Glassman supply, through both filter
95 pots, and into the cryostat high voltage feedthrough. All connections of cable to
96 supply or filters pots were checked, and no obvious defects were found.

97 3. *AC Power Distribution Inspection*

98 Considering that one main symptom of the high voltage instabilities is the high
99 RMS on the current output from the HV power supply, we investigated the AC power
100 distribution to the power supply itself. Using an AC analyzer (“ONEAC ONEView
101 Line Noise Viewing Interface” [1]), we determined that there was no excess noise
102 on the AC input to the high voltage supply than to any other areas of the detector
103 systems.

104 4. *“In air” Test of HV Supply*

105 As a last test of the warm side of the high voltage supply system, we pulled the
106 cable that connects to the cryostat high voltage feedthrough out of the feedthrough,
107 and ramped it to 20kV in air. No symptoms were observed during this test, indicating
108 that the power supply, filter pots, high voltage cables, and AC power distribution
109 were all functioning properly. Based off of this, it was concluded that the warm side
110 of the high voltage supply system was in good health, and the problems with the
111 HV system were downstream of the cryostat’s high voltage feedthrough.

112 **B. V vs. I Tests on cathode**

113 **C. Pickoff Point Measurements**

114 1. *Current-source mode measurements*

115 2. *Measurement of field cage resistance*

116 3. *Voltage-source mode measurements*

117 4. *Measurement of pickoff point resistance*

118 5. *Measurement of field cage resistance*

119 6. *Measurement of burst rate at pickoff point bias*

120 **D. “Burst” Analysis**

121 **E. Cathode Pulse Tests**

122 **V. RESOLUTION**

123 **VI. LESSONS LEARNED**

124 **VII. CONCLUSION**

125 Chronological Timeline

126 [1] ONEAC, “Oneac oneview® line noise viewing interface,” (2017).